



H.F. NODES CONSTRUCTION

#22 Terex TS-14G Scraper

11:25 AM 25/04/2010

HOURS 421

JASON

10:51 AM 18/05/2010

HOURS

SERVICE TECH MYKE

REPLACED THE HINGE ON THE EJECTOR

5:29 PM 17/06/2010

HOURS

SERVICE TECH MIKE LANCE

CHECKED MACHINE OVER

REPAIRED THE HYD LEAKS

3:31 PM 02/07/2010

HOURS 525

SERVICE TECH RANDY

CHECK OUT THE REAR TRANSMISSION

THE CLUTCHS HAD FAILED

ALL THE LINING CAME OFF THE PLATES



H.F. NODES CONSTRUCTION

REPLACED THE TRANSMISSION WITH EXCHANGE FROM GEAR CENTRE

TEST RUN MACHINE

3:20 PM 29/07/2010

HOURS 0 NEXT SERVICE DUE AT 250

SERVICE TECH ROB/MYKE

SERVICED THE ENGINE 15/40

REPLACED OIL AIR AND FUEL FILTERS

REPLACED HOUR METER

8:25 AM 30/08/2010

HOURS 76 NEXT SERVICE DUE AT 250

SERVICE TECH RANDY

CHECKED MACHINE OVER

REPAIRED THE BOWL HEATERS

1:28 PM 16/12/2010

HOURS 292 NEXT SERVICE DUE AT 542

SERVICE TECH DEAN

SERVICED BOTH ENGINES 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

replaced the housing on the front transmisson



12:13 PM 03/01/2011

HOURS 311

SERVICE TECH MURRAY

CHECK OUT THE ENGINE MISS

REMOVED THE CYLINDER HEAD

NO 4 PISTON AND LINER WAS SCORED

AND THE LINER SEALS WERE GONE

REPLACED THE PISTON AND LINERS

INSTALLED ENGINE COOLANT HEATERS

1:40 PM 21/02/2011

HOURS 330 NEXT SERVICE DUE AT 542

SERVICE TECH DEAN

REPLACED THE STARTER ON THE FRONT ENGINE

8:30 AM 22/03/2011

HOURS 378 NEXT SERVICE DUE AT 547

SERVICE TECH RANDY

CHECKOVER

REPLACED OIL AND FILTER REAR TRANS

2:16 PM 30/03/2011



H.F. NODES CONSTRUCTION

HOURS 390 NEXT SERVICE DUE AT 547

SERVICE TECH TRAVIS

REMOVED THE FAILED MUFFLER

INSTALLED MUFFLER OFF OF # 24

4:46 PM 18/04/2011

HOURS 455 NEXT SERVICE DUE AT 549

SERVICE TECH RANDY;

INSTALLED SIX NEW INJECTORS

CHECKED MACHINE OVER

INSTALLED A NEW FUEL PRESSURE REGULATOR

8:38 AM 5/24/2011

HOURS 560 NEXT SERVICE DUE AT 810

SERVICE TECH TRAVIS

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

REPLACED ORING AND LEAKING HOSE

5:19 PM 8/15/2011

HOURS

SERVICE TECH JUSTIN

REPLACED THE THROTTLE CONTROLLER FOR THE FRONT ENGINE



H.F. NODES CONSTRUCTION

2:54 PM 8/24/2011

HOURS

SERVICE TECH MURRAY

CHECK OUT ENGINE BACKFIRE

REPLACED THE STARTER ON THE REAR ENGINE

RUN MACHINE AROUND

FOUND THE FRONT ENGINE CAM SENSOR WAS NOT SHIMMED CORRECTLY

REPLACED NO 5 INJECTOR ON THE REAR ENGINE

REPLACED THE TRANSMISSION GAURD

CHANGED THE POSTION OF THE OPERATORS SEAT

3:38 PM 10/13/2011

HOURS 822 NEXT SERVICE DUE AT 1072

SERVICE TECH TRAVIS

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

9:09 AM 1/17/2012

HOURS 1018 NEXT SERVICE DUE AT 1072

SERVICE TECH CHRIS

CHECKED MACHINE OVER



H.F. NODES CONSTRUCTION

11:18 AM 2/4/2012

HOURS 1141 NEXT SERVICE DUE AT 1391

SERVICE TECH RANDY;

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

9:37 AM 2/5/2012

HOURS 1141 NEXT SERVICE DUE AT 1391

SERVICE TECH RANDY

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

12:41 PM 3/9/2012

HOURS

SERVICE TECH CHRIS

REPLACED THE EJECTOR CYLINDER

7:18 AM 6/21/2012

HOURS 1363 NEXT SERVICE DUE AT 1613

SERVICE TECH RANDY;

CHECKED OUT WHY THE EJECTOR CYLINDER WONT RETURN

REPLACED THE MAIN HYD CONTROL VALVE

REPLACED THE RETURN OIL FILTER IN THE HYD TANK



H.F. NODES CONSTRUCTION

SERVICED THE ENGINES 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

CHANGED OIL IN THE REAR TRANSMISSION

REPLACED THE TRANSMISSION FILTERS

10:47 AM 8/9/2012

HOURS 1566 NEXT SERVICE DUE AT 1613

SERVICE TECH RYAN

CHECKED MACHINEE OVER

FIRE EXT JULT 2012

4:39 PM 10/3/2012

HOURS 1650 NEXT SERVICE DUE AT 1900

SERVICE TECH CHRIS

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT JULY 2012

REPLACED THE MAIN HYD PUMP

INSTALLED BOWL HEATERS

2:02 PM 4/9/2013

HOURS

SERVICE TECH RANDY;



H.F. NODES CONSTRUCTION

CHECKED OUT THE EJECTOR CYLINDER FOR NOT RETURNING

REPLACED THE HYD FILTER SOME SMALL CUTTINGS IN IT

9:57 AM 5/7/2013

HOURS 1811 NEXT SERVICE DUE AT 1900

SERVICE TECH RYAN

CHECKED MACHINE OVER

SENT THE BOWL LIFT CYLINDERS TO BHS

TO GET RESEALED

FIRE EXT JULY 2013

REMOVED THE BOWL HEATERS

5:05 PM 7/30/2013

HOURS 1935 NEXT SERVICE DUE AT 2185

SERVICE TECHS CHRIS AND GORDON

SERVICED ENGINE 15/40

REPLACED OIL FUEL AND AIR FILTERS

11:39 AM 11/1/2013

HOURS 2184 NEXT SERVICE DUE AT 2434

SERVICE TECH GORDON

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS



H.F. NODES CONSTRUCTION

1:02 PM 1/17/2014

HOURS 2275 NEXT SERVICE DUE AT 2434

SERVICE TECH RANDY;

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

REPLACED THE AIR DRYER ASSEMBLY 109991X (UNITED SPRING)

THE REAR TRANSMISSION FAILED

REPLACED WITH NEW ONE FROM THE GEAR CENTRE

REPLACED THE SEAL ON THE INPUT ON THE REAR DIFF

FIRE EXT MAY 2013

REPLACED THE PUMP DRIVE GEAR BOX

4:30 PM 7/6/2014

HOURS 2520 NEXT SERVICE DUE AT 2770

SERVICES TECH CHRIS

SERVICED THE ENGINE 15/40

SERVICED AIR OIL AND FUEL FILTERS

FIRE EXT. MAY 2014

5:08 PM 8/20/2014

HOURS

SERVICE TECH RANDY



H.F. NODES CONSTRUCTION

MACHINE WAS HAULED IN TO THE YARD.

THE OPERATOR SAID THE ENGINE HAD A BAD KNOCK IN IT

REMOVED THE ENGINE IL FILTER.

CUT IT OPEN THERE WAS NO CUTTINGS IN IT.

TRIED TO START THE ENGINE

THE ENGINE HAD NO FUEL

BLEED THE FUEL SYSTEM OUT

THE CHECK VALVE HAD FAILED ON THE FUEL TRANSFER PUMP

REPLACED THE CHECK VALVE, THE ENGINE RUNS GOOD

2:05 PM 9/5/2014

HOURS

SERVICE TECH MYKE

REPAIRED THE BOWL WHERE THE ROUTER BITS BOLT ON

REMOVED ONE APRON CYLINDER AND HAD BHS REBUILD IT

2:39 PM 08/09/2015

HOURS 2895 NEXT SERVICE DUE AT 3145

SERVICE TECH CHRIS

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

REPLACED THE FAN HUB ASSEMBLY

CHECKED THE DIFF OIL



H.F. NODES CONSTRUCTION

GREASED THE DRIVE LINE

FIRE EXT MAY 2015

9:55 AM 25/11/2015

HOURS 3050 NEXT SERVICE DUE AT 3145

SERVICE TECH RYAN

CHECKED MACHINE OVER

FIRE EXT MAY 2015

8:02 AM 01/02/2016

HOURS 3185 NEXT SERVICE DUE AT 3435

SERVICE RYAN

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

CHANGED OIL AND FILTERS IN THE HYD

CHANGED OIL IN THE DIFFS AND GEAR BOX

CHANGED OIL AND FILTERS

IN THE TRANSMISSIONS

CHECKED MACHINE OVER

SWAPPED THE STEERING VALVE WITH THE ONE OUT #24

REPLACED THE REAR ENGINE SEAL

BEARING AND HYD RESEALED THE EJECTOR CYLINDER

REPLACED THE LH STEERING CYLINDER



H.F. NODES CONSTRUCTION

BEARING AND HYD RESEALED THE LH APRON CYLINDER

FIRE EXT MAY 2015

8:43 AM 04/07/2016

HOURS 3188 NEXT SERVICE DUE AT 3435

SERVICE TECH RANDY

REPLACED THE AIR DRYER

11:53 AM 18/07/2016

HOURS NONE BROKEN

CHECK LIST DATE NONE

OPERATORS CHECK LIST

DILLON WALLER

ENCANA 212 RD

11:55 AM 18/07/2016

HOURS 3192

OPERATORS CHECK LIST

DILLON WALLER

NONE OF THE GAUGES WORK

212 ENCANA

5:27 PM 03/08/2016



H.F. NODES CONSTRUCTION

HOURS

SERVICE TECH RANDY

REPLACED THE RIGHT FRONT TIRE WITH USED ONE OUT OF STOCK

12:46 PM 14/08/2016

HOURS

SERVICE TECH RYAN

REPLACED THE THROTTLE PEDAL ASSEMBLY FOR THE REAR ENGINE

4:42 PM 17/08/2016

OPERATORS CHECK LIST

HOURS ?????

OPERATOR DILLION WALLER

LOCATION 4-7

DATED AUG?????

NO COMMENTS

9:20 AM 26/11/2016

HOURS 3464 NEXT SERVICE DUE AT 3714

SERVICE TECH RYAN

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

DROPPED THE EDGES



H.F. NODES CONSTRUCTION

WILL NEED NEW ONES NEXT TIME

5:16 PM 06/12/2016

HOURS

SERVICE TECH GORDON

REPLACED THE CUTTING EDGES

12:56 PM 09/02/2017

HOURS 3482 NEXT SERVICE DUE AT 3714

SERVICE TECH RANDY

CHECKED MACHINE OVER

FIRE EXT APRIL 2016

REPLACED THE CRANK SHAFT SEAL IN THE FRONT ENGINE

INSTALLED A NEW AIR DRYER FILTER

7:09 AM 12/04/2017

HOURS 3593 NEXT SERVICE DUE AT 3714

SERVICE TECH RANDY

CHECKED MACHINE OVER

REPLACED THE BRAKE POT AN THE RIGHT HAND FRONT AND RIGHT REAR

REPAIRED THE OIL LEAK ON THE HYD CONTROL VALVE

REPLACED THE FRONT CRANK SHAFT SEAL

FIRE EXT APRIL 2016



H.F. NODES CONSTRUCTION

REPAIRED THE ALL THE AIR LEAKS

CALIBRATED THE TRANSMISSONS

7:10 AM 08/05/2017

HOURS

SERVICE TECH SLADE

REPLACED THE THROTTLE PEDAL SWITCHS

REPAIRED THE WIRING ON THE SIDE OF THE BOWL

REPLACED THE POOR HYD HOSES

WELD CRACKS IN THE TRANSMISSON GAURD

6:06 AM 21/08/2017

HOURS 3852 NEXT SERVICE DUE AT 4002

SERVICE TECH RANDY

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

9:57 AM 30/05/2018

HOURS 3985 NEXT SERVICE DUE AT 4002

SERVICE TECH RANDY

CHECKED MACHINE OVER

REPLACED THE CUTTING EDGES

FIRE EXT MAY 2018



REPLACED THE UJIONTS ON THE DRIVE SHAFT ENGINE TO TRANSMISSON

12:24 PM 19/08/2019

HOURS 3802 NEXT SERVICE DUE AT 4002

SERVICE TECH SLADE

REPLACED THE OPERATORS SEAT

PART NO M695SC MB

87275C24

INSTALLED A NEW SEAT BELT

8:30 AM 29/08/2019

HOURS 3834 SERVICE DUE AT 4002

SERVICE TECH COLE

REPLACED THE FRONT SEAL AND WEAR SLEEVE ON REAR ENGINE.

8:51 AM 03/09/2019

HOURS 3840 NEXT SERVICE 4002

SERVICE TECH COLE AND AYDEN

REPLACED THE FRONT TRANSMISSON

FLUSHED THE TRANSMISSON COOLER

REPLACED THE FILTER

11:54 AM 20/09/2019



H.F. NODES CONSTRUCTION

HOURS 8903 NEXT SERVICE DUE AT 9153

SERVICE TECH AYDEN

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT JULY 2020

4:21 PM 15/10/2019

HOURS 3911 NEXT SERVICE DUE AT 4002

SERVICE TECH AYDEN

CHECKED THE MACHINE OVER

FOUND THE FAN HUB ON THE REAR ENGINE TO HAVE FAILED

REMOVED THE HOOD AND FAD ASSEMBLY

REMOVED THE HUB AND INSTALLED THE NEW ONE

REPLACED THE FRONT CRANKSHAFT SEAL

REPLACED THE ORINGS ON THE OIL PUMP ON THE FRONT ENGINE

REPLACED THE BELT TENIONER PULLEY

CHANGED OIL AND FILTERS IN THE FRONT AND REAR TRANSMISSON

FIRE EXT JULY 2020

10:59 AM 24/07/2020

HOURS 3953 NEXT SERVICE DUE AT 4002

SERVICE TECH SLADE

CHECKED OUT LOW POWER ON THE REAR ENGINE



H.F. NODES CONSTRUCTION

FOUND NO 1 INJECTOR TO HAVE FAILED

REPLACED IT WITH USED ONE OUT OF #21

CODES ARE GONE

1:30 PM 03/09/2020

HOURS 3972 NEXT SERVICE DUE AT 4222

SERVICE TECH SLADE

CHECKED THE MACHINE OVER

SERVICED BOTH ENGINES, 10W30 OIL

REPLACED AIR OIL AND FUEL FILTERS, CLEANED FUEL SCREENS.

CHECKED OUT THE OIL LEAK ON THE FRONT ENGINE

FOUND THE DOWLS ON THE COVER FOR THE OIL PUMP TO BE PUSHED IN

REPLACED THE OIL AND SEAL

REPAIRED THE DOWLS

REPAIRED THE A/C COMPRESSOR MOUNT

REPIARED THE WIRING FOR THE TACH

RESEAL THE FILL TUBE FOR THE FRONT PUMP DRIVE

WASH THE RADS

RESEAL THE AIR COMPRESSOR MOUNT

REPLACED THE HEATER HOSES

REPAIRED THE BROKEN BELLY PAN BOLTS

WELD CRCKS IN THE EJECTOR

DETENT FOR THE EJECTOR RETURN NOT WORKING



H.F. NODES CONSTRUCTION

7:24 AM 03/11/2020

HOURS 3973 NEXT SERVICE DUE AT 4222

SERVICE TECH SLADE

CHECKED OUT THE OIL LEAK ON THE FRONT OF THE ENGINE

FOUND THE TIMING COVER THATS BOLT TO THE BLOCK WAS LEAKING

REMOVE THE ENGINE

REMOVED THE CYLINDER HEAD

REMOVE THE FRONT COVER AND RESEAL

RESEALED THE HIGH PRESSURE OIL PUMP MOUNT

RESEAL THE AIR COMPRESSOR AND WATER PUMP MOUNT

RE SEAL INJECTORS.

REMOVED THE STEERING CONTROL VALVE UNDER THE CAB

DEASSMBLED

RESEALED THE VALVE

INSTALLED THE VALVE ON THE MACHINE.

REPLACED HYD OIL AND FILTER.

REMOVED THE APRON

GOT BEARING AND HYD TO BUILD NEW PINS AND REPAIRED THE BOSS

INSTALLED NEW BEARINGS

11:09 AM 02/09/2021

HOURS 3987 NEXT SERVICE DUE AT 4222



SERVICE TECH COLE

REMOVED THE FAILED REAR ENGINE

INSTALLED THE REAR ENGINE OUT OF #26

REPLACED THE OUTPUT UJIONT ON THE REAR DRIVE SAHFT

INSTALLED THE SEAT OUT OF 26

SERVICED THE THE REAR ENGINE

WASH OUT THE REAR RADIATOR

BLEW OUT THE FRONT RAD

REPLACED THE FAN AND ALT BELTS ON THE FRONT ENGINE

FIRE EXT JULY 2021

JAYTIN WELD CRACK IN THE DRAFT TUBE WHERE THE ARM IS WELDED ONTO IT

10:45 AM 23/05/2023

HOURS

SERVICE TECH MURRAY

CHECKED THE MACHINE CODES

REPAIRED THE WIRING ON THE SIDE OF THE BOWL

REPLACED THE PLUG FOR THE REAR ENGINE WHERE IT CONNECTS TO THE MACHINE HARNESS

3:50 PM 08/08/2023

HOURS 4258 NEXT SERVICE DUE AT 4558

SERVICE TECH MURRAY

300HR SERVICE 15/40



FIRE EXTINGUISHER AUG 2023

FRONT AND REAR OIL CHANGES 15/40

8:15 AM 04/06/2024

HOURS 4376 NEXT SERVICE DUE AT 4558

SERVICE TECH AYDEN

CHECKED THE MACHINE OVER

BOTH RAD HAVE DIESEL IN THEM

DRAINED AND FLUSHED THE COOLING SYSTEM

REPLACED THE COOLANT FILTERS

FILLED WITH NEW ANTI FREEZE

REPLACED THE UJOINTS ON THE INPUTS FOR

BOTH TRANSMISSIONS

REPLACED THE LEFT REAR WHEEL SEAL

REPLACED BOTH BATTERYYS

RESEALED THE FRONT DIF AND CHANGED OIL

BOWL LIFT CLYINDERS STARTING TO WEEP