



H.F. NODES CONSTRUCTION

#21 Terex TS-14G Scraper

11:24 AM 25/04/2010

HOURS 657 NEXT SERVICE DUE AT 908

CHECKED MACHINE OVER

TRAVIS REPLACED THE STARTER ON THE REAR ENGINE

LANCE REPLACED THE ORING ON THE HIGH PRESSURE PUMP ON THE FRONT ENGINE

8:20 AM 06/06/2010

HOURS 748 NEXT SERVICE DUE AT 908

SERVICE TECH TRAVIS

CHECKED MACHINE OVER

REPLACED REAR CRANK SEAL REAR ENGINE

REPLACED TURBO INLET GASKETS

REPLACED RH STEERING RAM

8:40 AM 19/07/2010

HOURS 903 NEXT SERVICE DUE AT 1153

SERVICE TECH RANDY

SERVICED ENGINE 15/40

REPLACED OIL AIR AND FUEL FILTERS

REPLACED FAN HUB



H.F. NODES CONSTRUCTION

1:45 PM 07/09/2010

HOURS 1118 NEXT SERVICE DUE AT 1368

SERVICE TECH DEAN/rob

CHECKED MACHINE OVER

RECALIBRATE THE TRANSMISSION

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

RESEALED THE LEFT BOWL LIFT CYLINDER

7:36 AM 01/12/2010

HOURS

SERVICE TECH RANDY

CHECKED MACHINE OVER

1:27 PM 16/12/2010

HOURS

SERVICE TECH DEAN

SERVICED THE ENGINES 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

MACHINE WAS SERVICED THE SAME TIME AS #22



H.F. NODES CONSTRUCTION

8:30 AM 29/01/2011

HOUR 5 NEXT SERVICE DUE AT 255

SERVICE TECH RANDY

REPLACED THE HOUR METER

SERVICED THE ENGINES 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

REPAIRED THE BRAKES

REPLACED THE WHEEL SEALS ON ALL FOUR WHEELS

SET WHEEL BEARINGS

REPLACED THE BAD HYD HOSES

TURNED THE CUTTING EDGES

8:30 AM 22/03/2011

HOURS 15 NEXT SERVICE DUE AT 255

SERVICE TECH RANDY

CHECKOVER

8:03 AM 26/04/2011

HOURS 86 NEXT SERVICE DUE AT 255

SERVICE TECH RANDY;

CHECKED MACHINE OVER

REPLACED THE PUMP DRIVE GEAR BOX

INPUT SHAFT BROKE



H.F. NODES CONSTRUCTION

2:23 PM 7/28/2011

HOURS 295 NEXT SERVICE DUE AT 545

SERVICE TECH RANDY;

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

4:56 PM 9/9/2011

HOURS 443 NEXT SERVICE DUE AT 548

SERVICE TECH JOE

CHECKED MACHINE OVER

REPAIRED THE BATTERY CABLE TO THE BACK ENGINE

6:29 AM 9/12/2011

HOURS 458 NEXT SERVICE DUE AT 548

SERVICE TECH JUSTIN

REPLACED THE REAR ENGINE CRANK SHAFT SEAL

2:24 PM 10/7/2011

HOURS 548

SERVICE TECH CHRIS

CHECK MACHINE OVER



H.F. NODES CONSTRUCTION

7:51 AM 12/12/2011

HOURS 763 NEXT SERVICE DUE AT 1013

SERVICE TECH TRAVIS

SERVICED THE ENGINES 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

REPAIRED THE LEAKING HYD HOSES

9:12 AM 1/17/2012

HOURS 868 NEXT SERVICE DUE AT 1013

SERVICE TECH CHRIS

CHECKED MACHINE OVER

REPLACED THE FAN BELT ON THE FRONT ENGINE

INSTALLED NEW BEARINGS IN THE IDLER PULLEY

4:42 PM 7/9/2012

HOURS 1034 NEXT SERVICE DUE AT 1211

SERVICE TECH CAM

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

REPAIRED THE AIR LEAKS

INSTALLED TWO NEW SENSORS FOR THE AIR SYSTEMS

2:47 PM 10/3/2012



H.F. NODES CONSTRUCTION

HOURS 1110 NEXT SERVICE DUE AT 1211

SERVICE TECH CHRIS

CHECKED MACHINE OVER

REPAIRED THE AIR LEAK

REPAIRED THE WIRING ON THE REAR ENGINE

WELD EJECTOR CRACKS

5:09 PM 9/20/2013

HOURS

SERVICE TECH CHRIS

REPLACED THE FUEL TRANSFER PUMP

2:45 PM 9/24/2013

HOURS ???

SERVICE TECH GORDON

CHECKED OUT WHY THE FAN BELT WAS MISSING

FOUND THE FAN HUB HAD SEIZED UP

THE FAN HAD ALSO LOST A FAN BLADE

REPLACED THE FAN HUB ASSEMBLY ON THE REAR ENGINE

REMOVED THE FAN OFF OF #24 REAR ENGINE INSTALLED ONTO #21

11:14 AM 11/2/2013

REPLACED THE THROTTLE PTI SWITCH ON THE FRONT ENGINE



H.F. NODES CONSTRUCTION

8:36 AM 5/16/2014

HOURS 1685 NEXT SERVICE DUE AT 1758

SERVICE TECH RANDY

CHECKED MACHINE OVER

REPLACED THE FRONT TRANSMISSION

TEETH HAD LIFT ON THE PLANETARY DRUMS

INSTALLED REBUILT TRANSMISSION IN THE REAR

5:13 PM 8/20/2014

HOURS 1900 NEXT SERVICE DUE AT 1758

SERVICE TECH RYAN

OPERATOR COMPLAIN OF NO DRIVE IN THE FRONT ENGINE

SERVICE TECH WENT OT JOB SITE AND FOUND THE FRONT DRIVE SHAFT TO

BE NOT TURNING

REMOVED THE PUMP DRIVE

THE FLEX DRIVE PLATE HAD FAILED

REPLACED THE DRIVE PLATE

INSTALLED THE PUMP DRIVE

TEST RUN MACHINE

1:48 PM 9/18/2014

HOURS 1934 NEXT SERVIC DUE AT 2045



H.F. NODES CONSTRUCTION

SERVICE TECH BRAXTON

12:48 PM 19/05/2015

HOURS

SERVICE TECH RANDY

CHECKED MACHINE OVER

FOUND THE STARTER ON THE REAR ENGINE HAD FAILED

SERVICE THE ENGINE S 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

CHANGED THE WATER FILTERS

CHANGED TRANSMISSION OIL FILTERS

REPLACED THE BYPASS SENDER ON THE FRONT TRANSMISSION FILTER HOUSING

10:53 AM 09/09/2015

HOURS 2181 NEXT SERVICE DUE AT 2333

SERVICE TECH GORDON

CHECKED MACHINE OVER

2:39 PM 24/11/2015

HOURS 2349 NEXT SERVICE TECH 2600

SERVICE TECH GORDON

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS



H.F. NODES CONSTRUCTION

GREASED THE DRIVE LINE

REPAIRED THE COOLANT LEAK

6:51 AM 11/03/2016

HOURS 2517 NEXT SERVICE DUE AT 2767

SERVICE TECH RANDY

SERVICED THE ENGINES 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

REPLACED THE REAR TRANSMISSION WITH NO #8

REPLACED THE ENGINE REAR MAIN SEALS

REPLACED THE OIL PAN GASKET ON THE REAR ENGINE

10:50 AM 28/06/2016

HOURS 2526 NEXT SERVICE DUE AT 2767

SERVICE TECH RANDY

REPLACED THE THROTTLE PEDAL ASSEMBLY

ON THE REAR ENGINE (NEW STYLE)

PART NO WIL 351343

TOPPED UP THE A/C

3:33 PM 18/07/2016

HOURS 2551 NEXT SERVICE DUE AT 2767

OPERATORS CHECK LIST



OPERATOR BROCK

GOT TO WIGGLE THE PLUG ON THE FUEL RAIL SENSOR TO START FRONT ENGINE

RANDY AT MACHINE WILL CHECK OUT

2:59 PM 27/07/2016

HOURS 2583 SERVICE TECH RANDY

CHECKED MACHINE OVER

REPLACED THE MAIN AIR LINE FROM COMPRESSOR TO AIR TANK

REPLACED THE LEFT REAR MAXI POT

4:26 PM 29/09/2016

HOURS 2789 NEXT SERVICE DUE AT 3039

SERVICE TECH SLADE

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT APRIL 2016

APRON CABLE BAD

7:25 AM 27/01/2017

HOURS 2943 NEXT SERVICE DUE AT 3039

SERVICE TECH RANDY

REPLACED THE FRONT DRIVE SHAFT

REPAIRED THE SEAT MOUNT



H.F. NODES CONSTRUCTION

FIRE EXT APRIL 2016

REPLACED THE ENGINE AIR FILTERS

10:43 AM 19/04/2017

HOURS 3054 NEXT SERVICE DUE AT 3304

SERVICE TECH RANDY

CHECKED MACHINE OVER

REPLACED THE MAXI POT ON THE RIGHT REAR AXLE

INSTALLED NEW INJECTOR IN THE REAR ENGINE

REPLACED THE FRONT ENGINE WIRING HARNESS

REPLACED THE RIGHT FRONT WHEEL SEAL

3:34 PM 27/04/2017

HOURS 3054 NEXT SERVICE DUE AT 3304

SERVICE TECH SLADE

REPLACED THE THROTTLE SWITCHES

REPAIRED THE WIRING ON THE BOWL

REPAIRED THE WIRING ON THE REAR STARTER

INSTALLED A SOLINIOD ON THE EJECTOR RETURN PILOT VALVE

4:26 PM 16/10/2017

HOURS 3325 NEXT SERVICE DUE AT 3575

SERVICE TECH SLADE



H.F. NODES CONSTRUCTION

SERVICED THE ENGINE S 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT APRIL 2017

1:42 PM 08/12/2017

HOURS 3340 NEXT SERVICE DUE AT 3575

SERVICE TECH SLADE

CHECKE MACHINE OVER

REPLACED THE RADIO POWER INVERTER

REBEARINGED THE REAR OUT PUT DRIVE

REPAIRED THE WIRING FOR THE TRANSMISSON

REPLACED THE AIR PRESSURE SENDER

INSTALLED WEAR PLATES ON THE PUSH BLOCK

INSTALLED NEW SIGHT GLASSES ON THE HYD TANK

FIRE EXT APRIL 2017

REPAIR THE OIL LEAK ON THE REAR TRANSMISSON

8:09 AM 22/08/2019

HOURS 3362 NEXT SERVICE DUE AT 3575

SERVICE TECH SLADE

INSTALLED A NEW OPERATORS SEAT

PART NO 87275C24



H.F. NODES CONSTRUCTION

2:00 PM 26/11/2019

HOURS 3517 NEXT SERVICE DUE AT 3767

SERVICE TECH DENNIS

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL IFLTERS

FIRE EXT

7:49 AM 12/08/2020

HOURS 3529 NEXT SERVICE DUE AT 3769

SERVICE TECH MURRAY

CHECK OUT THE ANTI FREEZE IN THE OIL PAN

REMOVED THE ENGINE

DEASSEMBLED THE ENGINE

FOUND ALL THE LINER SEALS TO BE BAD

FOUND TWO PISTON ANDLINER TO BE SCORED

INSTALLED SIX NEW LINER KITS (GEAR O RAMA)

REUSED OUR HEAD

GOT SIX EXCHANGE INJECTORS FROM GEAR O RAMA

WASHED OUT THE RAD

INSTALLED NEW MAIN AND ROD BEARINGS

INSTALLED A NEW FAN BELT

RPLACED THE FAN HUB WITH ONE THAT WAS REBEARINGED BY BEARING AND HYD

INSATALLED A NEW MUFFLER FROM GEAR O RAMA



REPAIRED THE BROKEN WIRES ON THE REAR ENGINE WIRING HARNESS

FIRE EXT JULY 2020

7:31 AM 02/12/2020

HOURS 3624 NEXT SERVICE DUE AT 3817

SERVICE TECH SLADE

SHIM DRIVE LINE YOKES

CHANGED OIL IN THE PLANETARYS

CHANGED TRANSMISSION OIL AND FILTERS

REPLACED THE AIR DRYER FILTER

REPAIRE TRANSMISSION OIL LEAKS

FIRE EXT DEC 2020

10:25 AM 23/05/2021

HOURS 3654 NEXT SERVICE DUE AT 3817

SERVICE TECH MURRAY

CHECKED THE MACHINE OVER

LEFT BOWL CYLINDER IS LEAKING

RIGHT APRON CYLINDER IS LEAKING

FIRE EXT DEC 2020

11:03 AM 15/07/2021

HOURS 3657 NEXT SERVICE DUE AT 3817



H.F. NODES CONSTRUCTION

SERVICE TECH AYDEN

BLEW OUT THE RADS

REPLACED THE CLAMP ON THE A/A LINE

10:52 AM 25/08/2021

HOURS 3719 NEXT SERVICE DUE AT 3817

SERVICE TECH COLE

CHECKED THE MACHINE OVER

CHANGED OIL IN THE GEAR BOX

REPAIRED THE BROKEN GREASE LINES

REPLACED THE HOSE ON THE SIDE OF THE BOWL

REPAIRED THE EJECTOR KEEPER LOCK PIN

FIRE EXT MAY 2021

6:46 AM 22/10/2021

HOURS 3877 NEXT SERVICE DUE AT 4177

SERVICE TECH AYDEN

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

FILPPED THE EDGES

REPLACED A HOSE ON THE RIGHT HAND STEERING CYLINDER

FIRE EXT MAY 2021



H.F. NODES CONSTRUCTION

10:34 AM 2022-08-17

HOURS 3909 NEXT SERVICE DUE AT 4177

SERVICE TECH ROB

CHECKED THE MACHINE OVER

REPLACED THE STEERING CYLINDERS

REPLACED THE LEFT BOWL LIFT CYLINDER

INSTALLED A USED LIFT PUMP ON THE FRONT ENGINE

SERVICE TECH MURRAY

RECHAREGD THE A/C

7:01 AM 21/07/2023

HOURS 4007 NEXT SERVICE DUE AT 4177

SERVICE TECH MURRAY

FIRE EXTUNGUISHER EXP JULY 2023

INSTALLED NEW BATTERIES

REPLACED WATER PUMP

COMPLETE GREASE JOB

REPLACED PLUG END ON TORQUW LOCK UP SOLENOID

REPLACED RAD WITH ONE FROM WHITE TEREX BUGGY, THIS ONE LEAKS WORSE THAN OLD ONE.
WILL PUT OLD ONE BACK IN ONCE ITS BACK FROM COOL CORE IN GP.

REPLACED OLD TEREX RAD WITH ORIGINAL THAT CAME BACK FROM COOL CORE IN GP, NO LEAKS.
UNIT RUNS GOOD NOW.

2:40 PM 29/08/2023



H.F. NODES CONSTRUCTION

HOURS 4140 NEXT SERVICE DUE AT 4440

SERVICE TECH WES

300HR SERVICE 15/40

FORE EXTINGUISHER JULY 2024

CHANGED SECONDARY AIR FILTER, BLEW OUT PRIMARY

BLEW OUT CAB AIR FILTERS

NO VISIBLE HYDRAULIC LEAKS

APRON CABLE WILL NEED TO BE REPLACED WHEN MACHINE COMES HOME

FRONT ENGINE OIL PAN HAS LEAK NEAR FILL TUBE BUT IS NOT TOO BAD OF A LEAK

8:39 AM 04/06/2024

HOURS 4299 NEXT SERVICE DUE AT 4440

SERVICE TECH AYDEN

CHECKED THE MACHINE OVER

REMOVED BOTH APRON CYLINDERS SENT OUT FOR REPAIR

REPLACED THE BACKUP ALARM

REPLACED THE SPILL KIT

REPALCED THE REAR ENGINE THROTTLE PEDAL

RPLACED THE EJECTOR STOP CABLES

FIRE EXT JULY 2023

11:50 AM 18/06/2024

HOURS 4317 NEXT SERVICE DUE AT 4440



H.F. NODES CONSTRUCTION

SERVICE TECH AYDEN

INSTALLED THE APRON CLYINDERS

TOPPED UP THE HYD OIL

REPLACED THE SEALS FOR THE FRONT ENGINE OIL COOLER