



MAINTENANCE MANAGEMENT SCHEDULED MAINTENANCE

Prime Mover	Make/Model	Kenworth T909 Prime Mover						
	Date of Manufacture	2017						
	Engine/VIN No.	79966508/6F5000000HA458705						
	Registration No.	CM71QE						
SERVICE TYPE	RECOMMENDED KMS	ACTUAL KMS	INTERVAL	DATE	ACCREDITED MAINTENANCE PROVIDER	ADDRESS	JOB OR INVOICE NUMBER	COMMENTS & ADDITIONAL WORK
First service	10,000	14,796	4,796	09/20/2017	Central West Diesel	Forbes	27411	First service
B Service	50,000	72,810	22,810	11/28/2017	Twin City	Wodonga	1426874	B Service, service auto greaser,
C Service	100,000	117,000	17,000	02/05/2018	Central West Diesel	Forbes	29528	C Service, change ad blue filter, replace RHS low beam light,
B Service	150,000	188,674	38,674	05/14/2018	Central West Diesel	Forbes	31017	B Service, wash out radiator
C Service	200,000	233,000	33,000	07/14/2018	Central West Diesel	Forbes	40125	C Service, tighten exhaust bracket, repce batteries, serviced ice pack
B Service	250,000							
C Service	300,000	306,544	73,544	10/24/2018	Central West Diesel	Forbes	41612	C Service, service ice box compressor, replace front engine mounts, replace bottom shock rubbers, replace bearing 2nd axle RHS, replace seal, adjust bearings and brakes, grease nipple front RHS steering joint
B Service	350,000	359,688	9,688	01/09/2019	Glen Artney	Tamworth	39821	B Service, adjust auto greaser, tight shackle bolts, service icepack, grease input shaft and clutch actuator, replace engine mount, replace wheel seal, change diff oils,
C Service	400,000	438,300	38,300	05/03/2019	Glen Artney	Tamworth	42085	C Service, remove & replace a/c fan, replace torque rod bushes front diff, replace 2 red marker lights
B Service	450,000	478,857	28,857	03/24/2020	Glen Artney	Tamworth	47857	B Service, replace broken power steering cap, auto greaser needs replacing, repair RHR, new bush, replace icepack fuel filter
C Service	500,000							
B Service	550,000	546,154	67,297	10/11/2019	Inland Truck Centre	Dubbo	863711	B Service, replace diff oils and filters
C Service	600,000							
B Service	650,000							
A Service	675,000	696,047	149,893	06/25/2020	Ooma	Forbes		A service
C Service	700,000	728,801	28,801	08/31/2020	Glen Artney	Tamworth	50882	C Service, Remove and replace rollers, Adjust brakes and tension wheel to spec. Inspect oil leaks on both sides of second axle Found hub seals leaking, Cleaned all bearings, brakes and hub components, Oiled/repacked bearings and fitted to hubs using new seals. Refitted hubs and carried out bearing adjustment and fitted lock nuts. Refitted axles with new gaskets. Refitted wheels and tensioned nuts. Filled hubs with fresh oil.
B Service	750,000	770,945	20,945	10/30/2020	Brown & Hurley	Coffs Harbour	2039949	B Service, ad blue service, clear faults, replace air dryer filter & silencer, replace cab filter, eaton clutch greasing, engine valve set, diff oil samples, replace drive belts, reline all drive brakes, replace coolant filter, repair grease lines at steer area, rekit horton, replace RHF drive shock
C Service	800,000	833,113	33,113	02/17/2021	Brown & Hurley	Coffs Harbour	2119410	C Service, clean radiator and intercooler, replaced broken R/H bonnet locator mount on bonnet, repair damaged relay for drivin lights, repair wiring behind alternator, lube drivers seat base and track, checked steer shocks (all okay), checked S cam and replaced brake shoes and brake drum, replaced L/H rear blinker assembly, installed new heater tap and topped up coolant, tensioned bellybar bolts, removed diff breathers and cleaned and refitted, resourced harness under bonnet, resecure brake hoses and secure diff breather hose on 3rd axle, replaced yoke nut and seal
B Service	850,000							
C Service	900,000	904,676	71,563	06/23/2021	Brown & Hurley	Coffs Harbour	2217220	C Service, Steer wheel bearings, Replaced failed torque rod bushes, Removed bug deflector and sat on walk plate with bolts, Remove and replace rubbers and broken clamp, Removed and replaced RH and LH side cab mounts, Proceeded to drain coolant. Remove transfer pipe and connection, replaced o'ring, fitted new hose clamp, fitted new governor valve, Replaced ta light, Replaced reverse light on LHS, Replaced light on drivers step, Removed LH H-beam, took pictures then refit, replace both rear swaybars and torque rod bushes, replaced bolts and tensioned up sump bolts, Removed old bonnet mounts as they were broken an cracked and replaced with new one, Removed old governor valve lines that were leaking, cut new lines to length an fitted to truck.
B Service	950,000							
C Service	1,000,000	991,186	86,510	11/11/2021	Brown & Hurley	Yatala	2332433	C Service, REPLACE COMPLETE AIRDRYER, CHECK AIR SUSPENSION, AIRBAGS DROPPING DOWN IN SHORT TIME, COLD COOLANT LEAK RHS OF ENGINE, REPAIR BROKEN GREASE LINE ON BALL JOINT, AFTERTREATMEN LIGHT COMMING ON AT TIMES- NOT USING ADBLUE WHEN LIGHT ON, OIL LEAK AT DIFF PINION
B Service	1,050,000	1,078,433	28,433	07/07/2022	Cummins	South Grafton	9421794 (engine under warranty)	Engine Replacement and clutch
C Service	1,100,000	1,125,673	25,673	08/03/2022	Brown & Hurley	Yatala	2545570	C Service, FRONT DIF INPUT AND TROUGH SHAFT SEALS LEAKING. MOVEMENT IN UNI IN TAIL SHAFT, FLANGE ON EXHAUST PIPE NEAR TURBO BROKEN, ADBLUE TANK HAS MOVED, DRIVERS DOOR HANDLE LOOSE/BROKEN. PARKER LIGHTS ON BULL BAR SHORTENING, DRIVER HAS CUT WIRE ON LH SIDE. LIGHT ON RH TANK STEP AND LH MIRROR NOT WORKING. TRUCK LOOSING AIR WHEN HOLDING FOOT ON BRAKE.
B Service	1,150,000	1,175,371	25,371	11/07/2022	Brown & Hurley	Yatala	2677384	B Service
C Service	1,200,000	1,218,615	18,615	01/30/2023	Twin City	West Wodonga	1712225	C Service - removed and replaced grease nipple, engine tune, replaced jaw kit and turntable, adjust front diff bearing, replace fan, replaced shock absorber bushes
B Service	1,250,000							
C Service	1,300,000							
B Service	1,350,000	1,335,872	117,257	08/30/2023	Brown & Hurley	Yatala	2974926	B Service - Rear diff oil leak, movement in centre bearing, LHS wheel seal leaking, repair broken auto greaser lines
C Service	1,400,000	1,400,000	64,128	02/26/2024	Forbes Truck Alignment	Forbes	2223	C Service - replace tie rod ends, replace jack shaft, replace uni joints in tail shaft
B Service	1,450,000	1,455,549	55,549	05/13/2024	Forbes Truck Alignment	Forbes	2249	B Service - pinion seal, grease and adjust trailers
C Service	1,500,000	1,527,160	71,611	10/08/2024	Forbes Truck Alignment	Forbes	2385	CARRY OUT SERVICE AS PER SERVICE SHEET
B Service	1,550,000	1,579,359	52,199	01/29/2025	Forbes Truck Alignment	Forbes	2603	C Service - SERVICE AIR DRYER,CHECK TYRE PRESSURE,CHANGE POWER STEERING FILTER AND OIL, CHECK BRAKE LININGWEAR/REPAVE/ADJUST IF REQUIRED,CHECK COOLANT LEVEL,AIR FILTERS

C Service	1,600,000	1,630,830	51,471	05/13/2025	Forbes Truck Alignment	Forbes	2790	
B Service	1,650,000							