

MINISTRY OF TRANSPORTATION  
SAFETY INSPECTION REPORT



Vehicle Inspection Certificate Number: MQ50AE37

Start Date / Time: Apr 16, 2025, 3:02 PM

End Date / Time: Apr 25, 2025, 2:59 PM

| VEHICLE/ENGINE INFORMATION | CHASSIS            | ENGINE    |
|----------------------------|--------------------|-----------|
| Plate#: CC51102            | Year: 2013         | Year:     |
| VIN:<br>1FVACXDT8DDBU8301  | Make: FREIGHTLINER | Make:     |
| GVWR(kg): 14968            | Model: M2          | Size (L): |
| Odometer: 673399           | Fleet ID:          |           |

|                          |      |
|--------------------------|------|
| SAFETY INSPECTION RESULT | PASS |
|--------------------------|------|

SAFETY SYSTEM INSPECTION RESULTS

| System Inspected | Result   |
|------------------|----------|
| Suspension       | Repaired |
| Air Brakes       | Repaired |

MANDATORY ITEMS

| Inspection Item                             | Result |
|---|--------|
| <b>Axle 1, Driver Side Tire</b>             |        |
| Tire Tread Depth (mm)                       | 14     |
| Initial Tire Pressure (kPa)                 | 724    |
| <b>Drum Brakes<br/>Bolted/riveted block</b> |        |
| Shoe Lining Thickness (mm)                  | 13     |
| Drum Inside Diameter (mm)                   | 382.91 |
| Within OEM specifications?                  | Yes    |
| <b>S-Cam Drum Brakes</b>                    |        |
| Chamber Type (size)                         | 20     |
| Brake Stroke (mm)                           | 38     |

| Inspection Item                             | Result |
|---|--------|
| <b>Axle 1, Passenger Side Tire</b>          |        |
| Tire Tread Depth (mm)                       | 14     |
| Initial Tire Pressure (kPa)                 | 724    |
| <b>Drum Brakes<br/>Bolted/riveted block</b> |        |
| Shoe Lining Thickness (mm)                  | 13     |
| Drum Inside Diameter (mm)                   | 383.34 |
| Within OEM specifications?                  | Yes    |
| <b>S-Cam Drum Brakes</b>                    |        |
| Chamber Type (size)                         | 20     |
| Brake Stroke (mm)                           | 38     |

| Inspection Item                        | Result  |
|--|---------|
| <b>Axle 2, Driver Side, Inner Tire</b> |         |
| Tire Tread Depth (mm)                  | Over 20 |
| Initial Tire Pressure (kPa)            | 724     |
| <b>Axle 2, Driver Side, Outer Tire</b> |         |
| Tire Tread Depth (mm)                  | Over 20 |
| Initial Tire Pressure (kPa)            | 724     |

| Inspection Item                           | Result  |
|---|---------|
| <b>Axle 2, Passenger Side, Inner Tire</b> |         |
| Tire Tread Depth (mm)                     | Over 20 |
| Initial Tire Pressure (kPa)               | 724     |
| <b>Axle 2, Passenger Side, Outer Tire</b> |         |
| Tire Tread Depth (mm)                     | Over 20 |
| Initial Tire Pressure (kPa)               | 724     |

|   |         |
|---|---------|
| <b>Drum Brakes</b><br><b>Bolted/riveted block</b> |         |
| Shoe Lining Thickness (mm)                        | Over 15 |
| Drum Inside Diameter (mm)                         | 418.27  |
| Within OEM specifications?                        | Yes     |
| <b>S-Cam Drum Brakes</b>                          |         |
| Chamber Type (size)                               | 30LS    |
| Brake Stroke (mm)                                 | 38      |

|   |         |
|---|---------|
| <b>Drum Brakes</b><br><b>Bolted/riveted block</b> |         |
| Shoe Lining Thickness (mm)                        | Over 15 |
| Drum Inside Diameter (mm)                         | 418.55  |
| Within OEM specifications?                        | Yes     |
| <b>S-Cam Drum Brakes</b>                          |         |
| Chamber Type (size)                               | 30LS    |
| Brake Stroke (mm)                                 | 38      |

|   |                                 |
|---|---------------------------------|
| <b>Vehicle Inspection Centre #:</b> 13702 | <b>Technician #:</b> 182678     |
| CENTURY TRUCK AND TRAILER REPAIR INC.     | <b>Name:</b> GURMUKH NIJJAR     |
| 15 WINER ROAD                             | <b>Report Number:</b> 304       |
| PUSLINCH, ON N1H6H9                       | <b>Tablet ID:</b> 3156          |
| 519-835-9761                              | <b>STO ID/Account:</b> 17011406 |
| <b>Software Version:</b> 2024.08.21.1     | <b>Trade Code:</b> 310T         |

Vehicle Inspection Questions? Call the Public Contact Centre 1-833-420-2103 or go to <https://www.ontario.ca/page/driveon-emissions-and-safety-inspection-program>