



Hometown
 11301 98 Avenue
 Grande Prairie, AB T8V 5A5
 (780) 832-2949
 info@hometownngp.ca
 www.facebook.com/
 hometownautomotivegp

Estimate #8390

Created: 06/15/2026
 Payment Term: On Receipt
 Service Writer: Jeff Williams



2010 Ford F-350 Super Duty Lariat
 VIN: 1FTWW3BR3AEB22457
 Mileage: 320,312 km

INSPECTION--PURCHASED FROM RICHIE BROS---ENGINE CONCERN

STARTED TRUCK, RAN TO OPERATING TEMP, ENGINE SHAKE AT IDLE, ON ROAD TEST EXCESSIVE BLACK SMOKE, CODE P0269 CYLINDER 3 CONTRIBUTION , AT IDLE EXCESSIVE BLOW BY WHEN OIL CAP IS REMOVED
 20- CODES STORED AS ACTIVE IN PCM

P1828-P1820 TRANSFER CASE SHIFTING FAULT CODES --FURTHER DIAG NEEDED

SHORT ROAD TEST, SUSPECT NOISE FROM REAR DIFF AND ENGINE CONCERN FROM ROAD TEST ENGINE

PERFORMED RELATIVE COMPRESSION TEST CYLINDER 3 20%LOWER THAN ALL OTHER CYLINDERS SUSPECT BAD PISTON RINGS ON CYLINDER 3 CYLINDERS 5 AND 6 FAIL AT 5 %
 CODE P2291 LOW INJECTOR CONTROL PRESSURE AT CRANKING

CYLINDER 5 MISS FIRE HARD AT IDLE, WHEN INJECTOR TURNED OFF NO CHANGE SUSPECT BAD INJECTOR AS WELL NEW ENGINE WITH INJECTORS NEEDED

REAR DIFFERENTIAL
 PULLED REAR DIFFERENTIAL PLUG, HUGE CHUNKS OF METALS STUCK TO MAGNET AND FLUID IS BLACK--HAVE PIC REAR DIFF WILL NEED TO BE REBUILT

JUST WALK AROUND VISUAL INSPECTION
 FRONT HEAD LIGHT
 FRONT WINDSHIELD
 4 TIRES
 REAR BUMPER ROTTED OUT
 DRIVERS RUNNING BOARD MISSING TOP
 PASSENGER REAR FENDER FLARE COMING OFF
 BOX IS VERY RUSTED UNDERNEATH

Description	Subtotal
Labor: INSPECT	\$202.50
Shop Supplies (15%): \$30.38 GST (5%): \$11.64 Total: \$244.52	

Estimates provided are an approximation of timing and charges to you for the services requested. They are based on the anticipated work to be done. It is possible for unexpected complications to cause some deviation from the original quote. You hereby authorize the repair work described in this estimate to be done along with the procurement of the necessary material(s), including permission to operate the vehicle for on-road testing or inspection. If any additional repairs are required, we will prepare a revised work order providing the cost of additional parts and labor and total revised cost. All parts are new unless specified otherwise.

Deposits are non-refundable. No returns or refunds on special ordered items or electrical parts. There is no warranty for used parts or customer supplied parts.

You agree that we are not responsible for loss or damage to your vehicle, including loss of articles left in the vehicle, including, without limitation, in case of fire, theft, or any other cause(s) beyond our control. We are not responsible for any delays caused by unavailability of parts or delays in delivery of parts by the supplier or transporter.

Totals only include authorized services

Labor	\$202.50
Parts	\$0.00
Subtotal	\$202.50
Shop Supplies	\$30.38
EPA	\$0.00
GST	\$11.64
Grand Total	\$244.52
Paid to Date	(\$0.00)

REMAINING BALANCE \$244.52



Hometown
 11301 98 Avenue
 Grande Prairie, AB T8V 5A5
 (780) 832-2949
 info@hometowngp.ca
 www.facebook.com/
 hometownautomotivegp

Estimate #8390

Created: 06/15/2026
 Payment Term: On Receipt
 Service Writer: Jeff Williams

You have the right to know before authorizing any additional repairs what those repairs will be and what they will cost. If required repairs exceed the authorized estimated amount, we must obtain your approval to perform the repairs. We will keep you informed and perform only repairs authorized by you.

Signature _____

Declined

QUOTE----NEW ENGINE			
TIME ESTIMATE ONLY--CAB OFF REPAIR, EXTRA TIME WILL BE ADDED FOR SIEZED UP OR BROKEN BOLTS			
ENGINE QUOTED IS SERVICE LONG BLOCK--COMES WITH NEW GLOW PLUGS, HIGH PRESSURE FUEL SYSTEM, EXHAUST MANIFOLDS, OIL COOLER			
OIL CHANGE NEW FUEL FILTERS			
WILL USE OLD INTAKE WITH ORIGINAL TWIN TURBO INNER COOLER SYSTEM WILL BE CHECKED FOR LEAKS BEFORE HOOK UP OF NEW ENGINE--FURTHER PARTS AND LAB MAY APPLY			
Description	Price	QTY	Subtotal
Labor: LAB			\$3,750.00
Part: 6.4 ENGINE	\$34,309.10	1	\$34,309.10
Part: OIL FILTER	\$98.48	1	\$98.48
Part: 5W40 SYNTH	\$12.50	14	\$175.00
Part: FUEL FILTERS	\$216.98	1	\$216.98
Part: AC RECHARGE	\$249.95	1	\$249.95
Part: PRESTONE ANTIFREEZE	\$28.91	3	\$86.73
Shop Supplies (15%): \$562.50 GST (5%): \$1,972.44			Total: \$41,421.18

QUOTE----REAR DIFFERENTIAL REBUILD WITH LOCKER			
Description	Price	QTY	Subtotal
Labor: LAB			\$1,500.00
Part: REBUILD KIT WITH LOCKER	\$2,543.56	1	\$2,543.56
Part: 75W-140	\$27.02	3	\$81.06
Shop Supplies (15%): \$225.00 GST (5%): \$217.48			Total: \$4,567.10