

NewGen Projects Ltd.

5301 57 Ave

Grimshaw AB, T0H1W0

P: 780-332-2054

Unit # E205 Machine Hours: 3988 Sept 11/20

Description	Tech	Parts And Discription	Price
Replace 1 carrier rollers			\$ -
- charge engine oil & filter			\$ -
- charge all fuel filters & Teprime			\$ -
- charge all hyd filters			\$ -
- charge oil in final drives			\$ -
- clean cab			\$ -
- wash unit			\$ -
- charge air filters			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

P: 780-332-2054

Grimshaw AB, TOH, 1W0

Unit #

205

Machine Hours:

4291

Nov 7/20

[illegible]

P: 780-332-2054

Grimsshaw AB, TOH 1W0

Unit # 205

Machine Hours:

4550

Dec 19/2020

[illegible]

NewGen Projects Ltd.

5501 57 Ave.

Grimshaw AB, T0H 1W0

Pl. 780-822-2054

Unit #

<205

Machine Hours:

4804

May 12/21

Description	Tech	Parts And Discription	Price
Complete Service			\$
- Planetary oil changed			\$
- Swing oil			\$
- engine oil + filter			\$
- fuel filters			\$
- engine air filters			\$
- Cab filters			\$
- Replace RH mirror			\$
- hydraulic filters			\$
			\$
			\$
			\$

NewGen Projects Ltd.

205

625

mar 3/21

[illegible]

NewGen Projects Ltd.

Nov, 3/21

[illegible]

Wang, J. & Wu, Y. 2005. *Journal of Applied Ecology*, 42, 1033–1038.

E 205

21/12/21

Machine Hours: 5913

Description	Tech	Parts And Discription	Price
Service: change oil / Filter		(1) B7322	
coolant leak & heater hose ✓		(201) O/Hs	
lights ✓ horn ✓ head-operation ✓ wiper blades ✓		(11) washer fluid	
pos-hat ✓ block heater ✓ pump drive ✓ oil drive ✓		(361) coolant	
circle drive ✓ grease ✓			
wiring computer-wiring, needs drive belt			

NewGen Projects Ltd.

Machine Hours: 6438

(1) R61105 O-ring (cooler housing)
(1) R501428 Cooler gasket
(1) R5-2014-S58R Solenoid
relay control

(1) AFI211041 Air pulley
(1) Alternator
(1) 4333 461 accumulator
(2) Air line

(2) L40 4232 LED lights
(1) RE548027 belt tensioner
~~FF 100495 belt~~
~~FF 100495 belt~~

~~(1) If possible get~~

Jordan

502-71

6588

Feb 21/22

Description	Tech	Parts And Discription	Price
- Water pop in Fuel light on, inspected wiring on separator sensor found broken wire			
Idling with a studler			
- Changed Fuel filters			
Found loose Fuel hose, tightened.			
Pop studler was eliminated			


Jordan

508

6584 hrs


5/8/22

[illegible]



Unit # E205 Machine Hours: 6986 Nov 9/22

[illegible]



Jan. 15/23

[illegible]



P.O. Box 650 Grimshaw, AB. T0H 1W0

Unit #

E-205

Machine Hours:

7500

Jan 21/23 Ethken

Description

Tech

Parts & Description

Price

Final drive fluid changed
heavily greased
fluids checked

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$

\$



Unit #

502-7

Machine Hours:

7967

Mar 6/23

[illegible]



Unit #	Machine Hours:		
E-205		7940	Mar 16 / 2023
			Ethen

[illegible]



Quinton April 24/23

P.O. Box 650 Grimshaw, AB. T0H 1W0

Unit # E205 Machine Hours: 8110

Description

Tech

Parts & Description

Price

-	Replace 1 Light			\$
-	Replace 2 way antenna			\$
-	Tighten hose on stick			\$
-	Replace cab filters			\$
-	Replace Air filter			\$
-	Fix couple dents / steps			\$
-	Replace mirror			\$
-	Shim thumb			\$
				\$
				\$
				\$

*New Betco Rails + Segments supplied by
Franklin, Pad swap by Brant - \$13,500 - Rails/Segs
\$1850 - Pad swap



P.O. Box 650, Grimshaw, Alberta T0H 1W0 | P: 780.332.2054


Excavators 225/290/350

Unit # *E 205* Date: *Apr 1 24* Hours: *8110* Signature: *[Signature]*

Service Hours Remaining	<i>180</i>	Wedge Bolts Tight	
Engine Oil Level	<i>/</i>	Fuel Level	
Hyd Oil Level	<i>/</i>	All Pans & Gaurds	<i>/</i>
Fan Belt Condition	<i>/</i>		
Coolant Level	<i>/</i>		
Air Filter Condition	<i>/</i>		
DEF Level		Stock:	
Spare Jug		Whisk Broom	<i>/</i>
Washed	<i>/</i>	Windex	<i>/</i>
Cab Clean	<i>/</i>	Paper Towel	<i>/</i>
Lights Working	<i>/</i>	First Aid	<i>/</i>
Unit #'s & Decals	<i>/</i>	Spill Kit	<i>/</i>
Tooth Condition	<i>/</i>	Fire Extinguisher	
Cutting Edge Condition		Fire Extinguisher Expiry	<i>/</i>
Drain Water Seperator	<i>/</i>	Hammer	<i>/</i>
Check for Leaks/Cracked Hoses	<i>/</i>	Power Bar/Socket	<i>/</i>
Grease all Nipples	<i>/</i>	Track Shovel	<i>/</i>
Track Tension		Pad Bolts & Nuts	

Comments

--



July 13/23

[illegible]



Oct 24/23

[illegible]

P.O. Box 650 Grimshaw, AB, T0H 1W0

Unit # E-205

Machine Hours:

70.53 hrs Nov 23/22

Description	Tech	Parts & Description	Price
R/R Door-window from assy: clean and install glass (* Unlatched In) whole unit MUST be replaced if broken * repair door handle assembly and re-adjust, R/R ballbearing handle		(1) hood latch assy 7361455SH	\$(Val per)
R/R hood Latch assy (original hood)		(1) Screw 4706566 (Hitachi)	\$
R/R Tool box mirror assy.		(1) Door-Glass FYA000015015SH (rear)	\$(Val per)
Needs Tool box mirror, counter weight mirror cracked sand		(1) Ball valve handle	\$
		(1) tube weather	\$
		(1) AT 497535SH mirror Assy.	\$
			\$
			\$
			\$
			\$



P.O. Box 650 Grimshaw, AB. T0H 1W0

Unit#

E-205

Machine Hours

8414

Jan 31/23

Ethan

Description	Tech	Parts & Description	Price
Engine oil + filter	Change - Machine	greased	\$
Fuel filters + water	separated	changed	\$
Hydraulic tank filter	changed		\$
Pilot filter	changed		\$
Inner + outer cab filter	changed		\$
Inner + outer engine oil filter	changed		\$
Final drive oil	changed	75-90	\$
Fluids checked			\$
Far left cab light	Replaced		\$
Cab mirror	Replaced		\$
Fluids checked			\$
Cab unit + foggy CR			\$



P.O. Box 650 Grimshaw, AB. T0H 1W0

Nov 4/24 Ethan

Unit#

50.11

Machine Hours

9884

[illegible]



284 left on service

P.O. Box 650 Grimshaw, AB. T0H 1W0 Quinton Dec 11/24

Unit# E 205 Machine Hours 9986

Description	Tech	Parts & Description	Price
- Drain water from tank	and	filters	\$
- Check fluids			\$
- Add tarp			\$
- Change cab filters			\$
- Change L.H.S. butterfly on boom			\$
- Replace fire ext bracket			\$
- Replace 1 light			\$
- Fill Hyd tank			\$
			\$
			\$
			\$
			\$



P.O. Box 650 Grimshaw, AB. T0H 1W0

Unit# E-205

Feb 21/25


Date:

Machine Hours:

Description

Tech Parts & Description

[illegible]



Note: Date, Signature, Unit Numbers and Equipment Hours are all MANDATORY

Date: Mar 13/25

Location:

500

Signature: _____

Throw out hooks on skidsteers bring inside, then trucks

ON E-205 to move out of Way

Install decals, light bulbs, new hitch + hitch mount on

LT-600

Bring in D-610 for wash



P.O. Box 650 Grimshaw, AB. T0H 1W0

Unit #: F-285

Date: Mar 21/25

Machine Hours:

Technician Signature:

Description

Parts & Description

Replace Replace Both Eng Oil hoses from	
Block to filter head	
Install new tool box	
New Inner tower Eng oil filters	
New Inner tower cab oil filter	
All safety functions work as should	
operator's manual is in cab	
new Idler pulley	
New Oil cap	
New light LH side of boom	
Replace Replace left side hose on boom to	
stick Ram	



Note: Date, Signature, Unit Numbers and Equipment Hours are all MANDATORY

Date: mar 21/25 Location:

Location:

long

Signature:

Bring E-265 into shop
Install new tail box

Refuse both Eng oil links back to filter head



P.O. Box 650 Grimshaw, AB. T0H 1W0

Daily Report

Note: Date, Signature, Unit Numbers and Equipment Hours are all MANDATORY

Date: mar 28/25 Location: Shop

Signature: [Signature]

E-705 check over unit

shop clean up

D-702 post cut Road

NewGen Projects Ltd.

Aug 12/20

Aug 12/20

[illegible]

P.O. Box 650 Grimshaw, AB. T0H 1W0

Unit #: C-205 Date: Apr. 29/25 Machine Hours: 10548

 Technician Signature: 

Description

Parts & Description

- Lights, wiper, Arm bar, Seat belt, Positive air shut off, Master switch with lockout mechanism	
- Switches in cab in decent condition. Replaced safety snap cover for Positive air shut off	
- Fan speed works. A/C working.	
- Replaced A/C belt.	
- Fluids check, topped up hyd oil, coolant, Eng oil + swing drive oil.	
- Changed final drive oils.	
- Horn works	
- Replaced boom cylinder barrel and bushings + pins. Re skinned + greased	
- Painted tool box + lid (replaced lid) replaced latch for lid	
- Replaced All 4 carrier rollers.	
- Tightened tracks.	
- No leaks at this time.	