

W

NewGen Projects Ltd.

Unit #

E200

Machine Hours:

7811

19/12/21

Description	Tech	Parts And Discription	Price
Find coolant leaks ✓ leak at T from pre-heat repaired ✓	Bett	5L coolant	5
check all lights ✓ Rear Rear looking		(2) - 10 o-rings	5
pre-heat working ✓		(5) L hydraulic	5
block heater ✓ not working			5
healer under operation ✓			5
horn ✓			5
lights ✓			5
check all lights			5
hydraulic leaks at swing water: replace (2) o-rings ✓			5
pump drive ✓			5
hydraulic oil ✓			5
main drives ✓			5

NewGen Projects Ltd.

Unit # E-206

12/30/21

Machine Hours: 7815

Description	Tech	Parts And Discription	Price
Check for coolant leak: top off with coolant	But		
pressure test to 15 psi			\$
1.0 hr pulled inspection			\$
covers for visually no			\$
leaks found: saw all			\$
booster line clamps, surge			\$
test pad and hose clamps			\$
Green heat leaking			\$
			\$
			\$
			\$

NewGen Projects Ltd.

6206

8340

Feb 18/22

[illegible]

[The page contains extremely faint, illegible text.]

2026

9119

Aug 31 22

[illegible]

P.O. Box 650 Grimsshaw, AB. T0H 1W0

Unit # E206

Machine Hours:

9448

Nov 17/22

Description	Tech	Parts & Description	Price
Replace bearings and D200	Blaine carter		\$
cone seals on RH Planetary			\$
Complete service including			\$
all air filters			\$
Repair leaky lift Pump			\$
Pressure test coolant system - Good			\$
wash & clean cab			\$
Ice hug - Kyle Richardson			\$
			\$
			\$
			\$

NewGen Projects Ltd.

Unit # E206

Machine Hours: 8741

APR 10/21

Description	Tech	Parts And Discription	Price
Service 1 change oil / Filter, pri, sec, Separate - Fuel Filter, drain tank	(1)	B40063 oil Filter	
Replace SCR & Repair wiring Terminal	(1)	R502513 oil / Filter - positive charge	
Replace door seal	(1)	BF 76100-0 Fuel Filter (Sep)	
Replace hoses in swing house X 5	(1)	BF7950-0 Primary Fuel	
Stick to wrist arm Resealed - Accurate	(1)	BF7949-0 Secondary Fuel	
Change oil in pump drive	(1)	BT 9440 hydraulic (Pilot)	
Change oil in both final	(1)	Fuel oil pressure reduce valve	
Cut off Tee lug	(8)	poils hydraulic 32 AW	
Drain hydraulic tank and re-fill, Rtl fuel oil pressure relief valve	(1)	PA5656 cab air line	
Lost repair: engine head, hydraulic door, fuel hose, pump door	(1)	PA30174 cab air line	
	(1)	RS 5329 inner air eng	
	(1)	RS 4992 outer air eng	

- (1) DT 9557 hydraulic element
- (1) Fuel filter retaining ring

NewGen Projects Ltd.

Unit # €206

Machine Hours:

91048

~~100~~ Aug 19/21

Description	Tech	Parts And Discription	Price
Complete Set of TID Seefors			\$
Manifold Gaskets			\$
Valve Set - had Tattle Techchecked			\$
all Valves Set Proper ✓			\$
wash			\$
			\$
			\$
			\$
			\$
			\$
			\$
Brett & Jordan			\$

P.O. Box 650 Grimshaw, AB. T0H 1W0

Unit#

E-206

Machine Hours

9772hrs

Ex 19.5/23

[illegible]

P.O. Box 650 Grimshaw, AB. T0H 1W0

Unit# E-206

Machine Hours

10 placeholders

Aug. 16/23

[illegible]

P.O. Box 650 Grimshaw, AB. T0H 1W0

Unit#

१०२-३

Machine Hours

10 012hrs

Aug. 16/23

[illegible]



Unit#

E-206

Machine Hours

10 270


Sept. 21/23

[illegible]



Sep 1, 30/11}

[illegible]



10 703

[illegible]

Daily Report

Note: Date, Signature, Unit Numbers and Equipment Hours are all MANDATORY

Date: April 9/2025

Location:

Shop

Signature:

[Signature]

M-47501 - Finish repairs harness

D-607 - Drop stone pans for wash


E-206 - Repair hydraulic leaks

- replace hose on swing door

- Start to fill with oil

- remove & replace wristle seals

- replace hyd lines for molten vegol



Note: Date, Signature, Unit Numbers and Equipment Hours are all MANDATORY

install new skins & grease seals on stock end

Remove & replace hydraulic hose on pump & for thru



Note: Date, Signature, Unit Numbers and Equipment Hours are all MANDATORY

Put new locking pins on loader forks



P.O. Box 650 Grimsshaw, AB. T0H 1W0

Daily Report

Note: Date, Signature, Unit Numbers and Equipment Hours are all MANDATORY

Date:

Location:

Signature:

April 21/19

Shoe

E-206

install hydraulic hoses & o-rings
install dustet
fix metered mixing
run & check for leaks

[illegible]

P.O. Box 650 Grimsshaw, AB. T0H 1W0

Unit #: E-206

Date: Aug 19/25

Machine Hours: 11756

Technician Signature: [Signature]

Description	Parts & Description
Remove Seat and interior Panels, Remove all Hvac components, Recover Freon. Remove Evaporator, Wash out Evaporator	
Re-Install Evaporator, Reinstall all Hvac components, Reinstall all cab plastics all Control modules/mands, Reinstall Seat test	
All Hvac functions, all Seat functions Put in 2lbs of Freon. Ac blowing at 20 celcius	
Fix wiring for lights, All lights work, Replace Solenoid Number 1 in Valve block	