

NewGen Projects Ltd.

5301 57th Ave

Grimshaw, AB T0H 1W0

Phone: (780)332-2054

Work Order

DATE

INVOICE #

E-204

Aug 8/20

Service required/Description of work

Completed

Hours

Parts # & Description

Initials

- Wash Unit
- Check swing drive
- " engine oil
- " hyd level & top off
- Repair hyd return line mount
- Inspect all parts of a/c system, Blow out fan + condenser Best as possible
- Clean cab
- Install all belly pans
- Tighten A/c Belt
- ~~Disassemble~~ Reassemble seat for inspection
- Change oil in Plant gears
- Tag attachments

[illegible]

[illegible]

NewGen Projects Ltd.

E204

15350

Oct 8/21

[illegible]

PLEASE PAY THIS TOTAL ** CONTINUED **		SIGNATURE _____ DATE _____	
TOTAL PARTS TOTAL LABOR MISC. CHARGES SALES TAX	AMOUNT	I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair, or while field testing.	
DESCRIPTION		PAST DUE INTEREST 1.5% PER MONTH (18% ANNUAL), MINIMUM CHARGE OF \$1.50.	
AMOUNT		CORRECTION: ARRIVE ON SITE. UNIT PARKED ON SOME GRAVEL PILES NEAR AN EXCAVATION. FILL IN SERVICE TASK ASSESSMENT. CHECK FOR CODES IN MONITOR (NONE). HOOK UP MPDR. CHECK FOR STORED CODES. ENGINE CONTROLLER HAS 1239-1 FUEL LEAK OR (SUPPLY PUMP OR INJECTION SYSTEM) CONTROL PERFORMANCE & 157-3 COMMON RAIL PRESSURE SENSOR CIRCUIT HIGH INPUT (POSSIBLY FROM WHEN SENSOR WAS RECENTLY CHANGED / NEW PIGTAIL). CLEARED CODES. MONITOR SUPPLY PUMP INLET PRESS / FUEL FLOW RATE / COMMON RAIL PRESSURE. WARM UP UNIT AND FOUND THAT AFTER UNIT WAS QUITE WARM (15-20MIN) AND USING BOOM UP OR ARM IN THE ENGINE WOULD START TO "POP" AND RUN ROUGH FOR A SECOND OR 2.	
TRAVEL CHARGES KEITH 780-835-8526 NM OF WESTLOCK * LABOR * CARBON TAX SURCHARGE * GST/HST * D/R ROUGH ENGINE OPERATION : INTERMITTENT		1,880.00 28.20 1,908.20 95.41 TOTAL	

PURCHASE ORDER NO. E204		PHONE NUMBER 780-332-2054		WORK ORDER NO. 1629379		SEG. 01		DATE OPENED 15OCT21		SALES PRN	
MAKE JD		MODEL 225DLC		SERIAL NO. 1FF225DXJC0502140		EQUIP. NO. E204		METER 15408		AUTHORIZED BY GS / KEITH	

INVOICE DATE 26OCT21		BRANCH 06		INVOICE NO. 1629379	
----------------------	--	-----------	--	---------------------	--



Service
Invoice

Brandt Tractor Ltd.
7301 - 102nd Street
Clairmont, AB
T8X 5A7
(780) 532-3414

Brandt

E204

DATE		SIGNATURE	
X			
I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs hereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sales, repair, or while field testing.			
PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUAL, MINIMUM CHARGE OF \$1.50)			
TOTAL PARTS		TOTAL LABOR	
MISC. CHARGES		SALES TAX	
PLEASE PAY THIS TOTAL		**CONTINUED**	
DESCRIPTION		AMOUNT	
AT THIS TIME THE READINGS FOR FUEL FLOW AND COMMON RAIL WOULD BOUNCE LOW AND BACK UP. AFTER RUNNING FURTHER THE CODE 1239-1 CAME BACK. TALK WITH CUSTOMER / FOREMAN - UNIT HAS HAD WORK DONE EARLIER FOR THIS SAME CODE. TANK HAS BEEN CLEANED, NEW FILTERS, FLOW OUT OF TANK CHECKED. UNIT HAD NEW COMMON RAIL PRESSURE SENSOR TO REPAIR HARD STARTING. ALSO A RAIL RELIEF AND PUMP INLET "VALVE" WAS CHANGED. INSTALL A LOW PRESSURE GAUGE IN THE FINAL FILTER BASE TO CHECK SUPPLY PRESSURE. RAN UNIT FOR 15-20 MIN AND PRESSURE STAYS WITHIN SPEC 3-4 PSI EVEN WITH A LOAD. REVIEW DTAC SOL 97634. DECIDED TO TRY A NEW PUMP. REMOVE AIR INTAKE PIPE. REMOVE SCREWS HOLDING SCV IN. HAD TROUBLE GETTING ONE OUT. ASSEMBLE ENGINE AND RUN FOR 15-20 MIN. NO ISSUE (END OF DAY). OPERATOR RAN WHILE I CLEANED UP TOOLS. SET UP GAUGE TO GO IN LINE BETWEEN FINAL FUEL FILTER AND HIGH PRESSURE PUMP. WARM UNIT UP AND MONITOR PRESSURE AND ALSO PERFORM MPDR RECORDINGS. DECIDED TO CHANGE INJECTORS AS TRANSFER PRESSURE HOLDS AT 2 PSI WHEN CODE IS ACTIVE. CHANGE INJECTORS. TEST. SAME ISSUE. PUT IN DTAC CASE 1757691. WRITE			
DESCRIPTION		AMOUNT	
PURCHASE ORDER NO. 780-332-2054 PHONE NUMBER 1629379 WORK ORDER NO. 150CT21 SEG. 02 DATE OPENED 15408 SALES PRN AUTHORIZED BY GS / KEITH		MAKE JD MODEL 225DLC SERIAL NO. 1FF225DXJCD502140 EQUIP. NO. E204 METER 15408 GS / KEITH	

PAGE	2
SALE TYPE	CHARGE
CUSTOMER NO.	700000820

NEW GEN PROJECTS LTD
BOX 650
*****EM STAT & INVOIC
GRIMSHAW, AB T0H 1W0

SOLD TO:

INVOICE DATE	260CT21
BRANCH	06
INVOICE NO.	1629379

JOHN DEERE



Service Invoice

Brandt Tractor Ltd.
7301 - 102nd Street
Clairmont, AB
T8X 5A7
(780) 532-3414

Brandt

INVOICE DATE	260CT21	BRANCH	06	INVOICE NO.	1629379
--------------	---------	--------	----	-------------	---------

PAGE	3	SALE TYPE	CHARGE	CUSTOMER NO.	70000820
------	---	-----------	--------	--------------	----------

S
H
I
P
I
N
T
O

SOLD TO:

NEW GEN PROJECTS LTD
BOX 650
*****EM STAT & INVOIC
GRIMSHAW, AB 10H 1MO

SOLD TO:

NEW GEN PROJECTS LTD
BOX 650
*****NEW STAT & INVOIC
GRIMSHAW, AB 10H 1W0

Brandt Tractor Ltd.
7301 - 102nd Street
Clairmont, AB
T8X 5A7
(780) 532-3414



Service Invoice



JOHN DEERE

NewGen Projects Ltd.

Unit # E204

15417

Oct 22 / 21

[illegible]

NewGen Projects Ltd.

Unit # F-204

Machine Hours:

April 27, 2022

[illegible]

Handwritten signature

NewGen Projects Ltd.

100

Machine Hours: 15 500 hrs.

May. 19/22

[illegible]

NewGen Projects Ltd.

Unit # E-204

Machine Hours: 15605

Description	Tech	Parts And Discription	Price
Diagnose for poor running condition: Check EGR system		(1) reed valve block	5
R+I from cooler to engine intake: reed valve block has burnt		(2) gaskets replaced.	5
reed valves off 3 of 6 valves. Replace block and gaskets		(1) Cam sensor	5
Service: Change oil/Filts		(1) Fuel return control valve	5
clean out intake tract and fuel lines, pump pickup,		(1) Oil Filtr	5
and return lines. Diagnose for poor HVAC operation;		(1) RH control (stick)	5
seat controls and slides not working, panels not attached		(1) LH control. (stick)	5
R+I+R HVAC, seat base, all inner panels; clean			5
and re-install interior, repair seized rails + slides, repair			5
lumber support + accessories.			5
Codes 1239-1			5

Jordan

11-201

Machine Hours: 15659hrs

Sept. 2/22

[illegible]

Brandt Tractor Ltd.
7301 102nd St.
Clairmont, AB
T8X 5A7
(780)532-3414

Brandt

NEW GEN PROJECTS LTD
BOX 650
EM STAT & INVOICES
GRIMSHAW AB 10H 1W0

GRIMSHAW AB 10H 1WO CA

CA

PAGE		1
CASH	CHG.	OTHER
	X	
ACCOUNT NO.		
700000820		

NEW GEN PROJECTS LTD
KEITH 780-835-8526

KEITH 780-835-8526

[illegible]

Brandt

Brandt Tractor Ltd.
7301 102nd St.
Clairmont, AB
T8X 5A7
(780)532-3414

Parts Invoice



JOHN DEERE

S
L
O
D
T
O

NEW GEN PROJECTS LTD
BOX 650
EM STAT & INVOICES
GRIMSHAW AB T0H 1W0
CA

PAGE	
CASH	1
CHQ.	
OTHER	
ACCOUNT NO.	
70000820	

S
H
I
P
T
O

NEW GEN PROJECTS LTD
KEITH 780-835-8526

GRIMSHAW

SALESMAN	750	ORDER NO.	E204	QUANTITIES	01266165	PHONE	780-332-2054	INVOICE DATE	11OCT23	BIN	14:10	INVOICE NO.	4773091
----------	-----	-----------	------	------------	----------	-------	--------------	--------------	---------	-----	-------	-------------	---------

ORDERED	SHIPPED	QTY	MAKE: JD	MODEL: 225D	SERNO: 502140	LIST	NET	EXTENSIONS	OFFICE USE
---------	---------	-----	----------	-------------	---------------	------	-----	------------	------------

MAKE: JD
MODEL: 225D
SERNO: 502140
LIST 258.79
NET 258.79
EXTENSIONS 1035.16
PC
HRS:
PARTS HOURS: MON-FRI 7AM-6PM
SAT 8AM-4PM
** 24 HOUR EMERGENCY ON CALL PARTS, SERVICE & SALES **
** ALL ELECTRICAL COMPONENTS ARE NON RETURNABLE **
** ALL FABRICATED HYDRAULIC HOSES ARE FINAL SALE **

GST No. 899544779
*
TOTAL GST/HST *

Posted

51.76

AMOUNT

ACCOUNT

DESCRIPTION

PARTS TAXABLE

PARTS NONTAXABLE

MISC TAXABLE

MISC NONTAXABLE

SALES TAX

1086.92

PLEASE PAY THIS TOTAL

SIGNATURE

DATE

TERMS: NET 30 DAYS FROM

DATE OF INVOICE

NO GOODS CAN BE RETURNED WITHOUT OUR PERMISSION. GOODS
RETURNED BY PERMISSION WHICH WERE FURNISHED CORRECTLY
ACCORDING TO ORDER ARE SUBJECT TO A HANDLING CHARGE. NO
CLAIMS ON THIS INVOICE WILL BE CONSIDERED AFTER 30 DAYS OF
RECEIPT OF GOODS.
PAST DUE INTEREST 1 1/2% PER MONTH (18% ANNUUM).

MINIMUM CHARGE OF \$1.50

TITLES TO ALL ITEMS
REMAIN WITH BRANDT
TRACTOR LTD. UNTIL PUR-
CHASE PRICE, INTEREST
AND OTHER CHARGES
ARE FULLY PAID.

CUSTOMER COPY



P.O. Box 650 Grimsshaw, AB. T0H 1W0

Quinton

Feb 1

Unit# E 204

Machine Hours

16486

Description	Tech	Parts & Description	Price
- Replace All 4 injectors			\$
- Change engine oil			\$
- Replace batteries			\$
- Replace 1 round heater vent			\$
- Replace 2 lights			\$
- Replace L.H.S mirror			\$
- Replace blade tilt hoses			\$
- Grease machine			\$
- Check all fluids			\$
			\$
			\$
			\$

* Both lift arms leak

* Ham on top of cylinder leaks



NUMBER: ~~309~~ 215

New Gun.

dkuniga@aao.com

UNIT/SERIAL	JOB DESCRIPTION	HOURS
	Shop / Wap.	

DATE COMPLETED: _____
COMPLETED BY: Dora Kuy



WORK ORDER

Altu Buz.

DARCY KURIGA 780-835-8090 dkuriga@yaoo.com

DATE	UNIT	SERIAL	HOURS/KILOMETERS
August 7	ms-2104		13069 hrs

UNIT/SERIAL	JOB DESCRIPTION	HOURS
	Nampa / Shop	

DATE COMPLETED	DESCRIPTION	JOB TOTAL
MS-2104	- Travel Sails Nippers. - Hooked Hooked up 290 Hot pack to 225. worked good with Different Hot pack. Problem is in 225 Hot pack. - checked valve and Pressure on the pack - motor on the pack for 225 is weak.	41
MS-2104	- Re assemble steering valve. - In sail valve Back on Buggy. - Remove and installed New Hydraulic Pump.	9

DATE COMPLETED: _____

COMPLETED BY: _____

Darcy Kungu

