

 RITCHIE BROS. Diagnostic Report
Auctioneers[®]**2019 Freightliner 106 Medium Duty****Test Information**

Engine	Cummins B6.7 (6.7)
Engine Serial	CMMNS*6B u17D0670000000*74410558
VIN	3ALACYFC9KDLH6332
Driveline	Class 8 4x2
Body	Truck MDHD: Conventional
Test Time	Feb. 3, 2026, 1:51 p.m.
File Length	50.356 s

Usage

Label	Value	Units
Engine Odometer	170,730	mi
Odometer (Instrument Cluster #1)	170,731	mi
Engine Total Hours of Operation	7,947.2	h
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	4	%

Engine On/Off

Engine running

Check Engine Light



Amber Warning Lamp - Warning, but OK to drive

Emissions Deleted/Tampered

No

Faults

<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Active	Engine #1	Aftertreatment 1 Diesel Exhaust Fluid Tank Quality	Abnormal Rate of Change	1
Previous	Brakes - System Controller	Vehicle Deceleration Control	Abnormal Rate of Change	126
Previous	Brakes - System Controller	J1939 Network #1. Primary Vehicle Network	Current Below Normal	33
Previous	Body Controller	Unknown	Data Error	4
Previous	Body Controller	Manufacturer Assignable SPN	Not Responding Properly	126
Previous	Body Controller	Manufacturer Assignable SPN	Data Error	5
Previous	Body Controller	Manufacturer Assignable SPN	Data Error	3
Previous	Body Controller	Source Address 3	Data Error	1
Previous	Body Controller	Manufacturer Assignable SPN	Not Responding Properly	1
Previous	Body Controller	Estimated Percent Fan 2 Speed	Current Below Normal	2
Previous	Body Controller	Cab Dome Light 2	Current Below Normal	1
Previous	Body Controller	Headlamp Low Beam Right #1	Current Below Normal	3
Previous	Body Controller	Turn Signal Switch	Data Error	7
Previous	Body Controller	Windshield Wiper Motor ON/OFF	Not Responding Properly	10
Previous	Body Controller	Manufacturer Assignable SPN	Voltage Below Normal	18
Previous	Body Controller	High-Low Beam Switch	Data Error	7
Previous	Body Controller	Manufacturer Assignable SPN	Not Responding Properly	3
Previous	Headway Controller	Manufacturer Assignable SPN	Special Instruction	8
Previous	Headway Controller	Manufacturer Assignable SPN	Failure	23
Previous	Headway Controller	Manufacturer Assignable SPN	Current Below Normal	1
Previous	Headway Controller	EBS Brake Switch	Data Error	5
Previous	Headway Controller	Brake Pedal Position	Data Error	5
Previous	Headway Controller	Manufacturer Assignable SPN	Voltage Above Normal	9
Previous	Proprietary	Source Address 33	Data Error	126