

Description	Work Done	Completed
Brake Test - Prime Mover	Not required - Vehicle going off site	11/02/2022
60,000km Topset	Not required - Vehicle going off site	11/02/2022
Volvo Prime Mover (A Service)	Not required - Vehicle going off site	11/02/2022
Volvo Prime Mover (D Service)	Not Required	10/19/2022
Volvo Prime Mover (A Service)	Not required	10/11/2022
Volvo Prime Mover (A Service)	Not required	09/19/2022
Volvo Prime Mover (A Service)	Not required	09/19/2022
Replace Final Drive Oil	not required	08/31/2022
Replace Gearbox Oil & Filter	not required	08/31/2022
Replace Diff Oil	not required	08/31/2022
Replace Air Dryer Filter	not required	08/31/2022
WA Mainroads Accreditation Roadworthiness Checklist	Not required	08/06/2022
Volvo Prime Mover (D Service)	not required	07/24/2022
Volvo Prime Mover (A Service)	not required	07/24/2022
Volvo Prime Mover (A Service)	as per b service	07/10/2022
Volvo Prime Mover (A Service)	Not required	08/17/2022
WATER SPRAY STUCK ON	FREE UP STUCK SPRAY	06/06/2022
PTO not disengaging	Check PTO operation/air supply etc. Found switch working normally. Lubricate PTO actuator and test. PTO engages and disengages fine.	06/04/2022
Volvo Prime Mover (A Service)	Service asset as per attached service sheet	06/06/2022
Brake Test - Prime Mover	truck parked up not in use	05/22/2022
60,000km Topset	truck parked up not in use	05/27/2022
Volvo Prime Mover (D Service)	parked up not working	05/10/2022
Volvo Prime Mover (A Service)	Service asset as per attached service sheet	05/03/2022
Volvo Prime Mover (A Service)	Service asset as per attached service sheet	03/23/2022
Replace Final Drive Oil	trucks parked up and not in use	03/15/2022
Replace Gearbox Oil & Filter	trucks parked up and not in use	03/15/2022
Replace Diff Oil	trucks parked up and not in use	03/15/2022
Replace Belt Tensioner & Drive Belts	trucks parked up and not in use	03/15/2022

Replace Air Dryer Filter	trucks parked up and not in use	03/15/2022
Volvo Prime Mover (D Service)	Service asset as per attached service sheet	02/14/2022
carry out tasks	completed	02/24/2022
carry out tasks	completed	02/24/2022
carry out tasks	completed	02/24/2022
carry out tasks	completed	02/24/2022
Volvo Prime Mover (A Service)	Service asset as per attached service sheet	01/17/2022
repaired aircon	repaired aircon	01/13/2022
carry out tasks	completed	02/24/2022
water sprayers	connect rear sprayers to one air line repaired tail light wiring	12/16/2021
no pto	replaced blown pto fuse	12/16/2021
Volvo Prime Mover (A Service)	Service asset as per attached service sheet	01/02/2022
60,000km Topset	carried out top set and service truck is being parked up	11/27/2021
Volvo Prime Mover (D Service)	carried out top set and service truck is being parked up	11/27/2021
Volvo Prime Mover (A Service)	carried out top set and service truck is being parked up	11/27/2021
carry out tasks	completed	02/24/2022
defects	repair l/h head light wiring secure camera to window screen	11/26/2021
VEHICLE SHUTTING DOWN	REPLACED K2 RELAY REPLACED ENGINE OIL AND FILTER	11/23/2021
Inspect for sprayers not working	Inspected sprayers and found broken air lines Replaced broken air lines Tested	11/13/2021
Fan fault	Inspected and found failed idler bearing Replaced idler bearing Replaced engine fan belt Re-wired damaged fan plug	11/17/2021
Will not build air	Removed hot pipe Found carbon build up Removed carbon Refit hot pipe and tested	11/20/2021

01733 - repairs	Battery warning light on Middle sprayer not turning off at all Cab lock alarm on Needs new rear guards fitting l/h sprayer not working Multiple air leaks GPS not working Tablet N/W CAMERA NEED SECURING	12/10/2021
3086 - AC not working	Repaired AC issue	11/04/2021
REPAIR AIR LEAKS DIAGNOSE A/C FAULT	Replaced a/c hose Re-gassed a/c Tested a/c	11/10/2021
WATER PUMP FAULT	DIAGNOSE AND REPAIR PUMP FAULT ROCK STUCK IN PUMP	10/18/2021
HOT HYDRAULICS	CHANGED HYDRAULIC OIL REPLACED HYDRAULIC FILTER HOUSING AND FILTER FLOW TESTED HYDRAULICS CLEANED AND LUBRICATED DIVERTER VALVE	10/14/2021
60,000km Topset	as per service	09/26/2021
60,000km Topset	as per service	09/26/2021
Replace Final Drive Oil	as per service	09/26/2021
Replace Gearbox Oil & Filter	as per service	09/26/2021
Replace Diff Oil	as per service	09/26/2021
Replace Air Dryer Filter	as per service	09/26/2021
Volvo Prime Mover (B Service)	as per service	09/26/2021
On Board Compressor Not Working	Repair wiring to discharge temp switch & tested	08/29/2021
0076 - Hydraulics over heating	Inspect cooling fan issue 1,732,025 km 6,384 hours	09/01/2021
Volvo Prime Mover (A Service)	INSPECTION AND SERVICE CARRY OUT HOSES MOVED SINCE 10 L SERVICE	06/11/2020
Brake Inspections	Carry out brake audit - all ok	04/18/2020
change out headlight bulbs	change out headlight bulbs	03/19/2020

Weld bracket of power steering tank and training on truck	Weld bracket of power steering tank and training on truck	05/25/2020
Inspection,	Pre-inspection for BHP inspection Repaired exhaust clamp due to leak	02/16/2020
CHECK / REPLACE TYRES REQUIRE	Changed all tyres	01/17/2020
Volvo Prime Mover (D Service)	Volvo Prime Mover (D Service) Air bags x5 All tyres changed	01/20/2020
Need fitted cage (?) to go on bottom of suction hose for 8.8 Shed	Not required	02/06/2020
WATER PUMP NOT WORKING	Blockage removed	02/08/2020
LH SUCTION PIPE FEEDING INTO THE TANK - SUSPECT BLOCKED, TRIED TO UNBLOCK BUT UNSUCCESSFUL	Freed up water pump Resealed all joints Tested and all ok	01/06/2020
Not pumping(8-8 shed sump)- weak suction. Oil drips noticed when exiting	Pumping Ok Repaired Oil Leak	12/23/2019
Check ECU connectivity and FMS gateway is open for MTData access	WATER TRUCK TRANSFERRED FROM PICTON TO YAKABINDIE 07.02.20	02/07/2020
LEAKING WATER FROM TANK ON L/H/SIDE,	WATER TRUCK TRANSFERRED FROM PICTON TO YAKABINDIE 07.02.20	02/07/2020
MTDATA NOT WORKING, NO WIFI CONNECTION WHEN TRYING TO LOG IN	EARTH 2 OCEAN REPAIR MTDATA UNIT , NOW TRACKING. REPLACE OLD PA0181 UNIT INTO 171 WITH 171 SIM CARD. MTDATA RECONFIGURED UNIT ALL WORKING OK. (INV: I10595 - QPI-10838)	02/14/2019
Volvo Prime Mover (A Service)	Volvo Prime Mover (A Service) REPLACED MUFFLER & CHROME TIP, REPLACED NUMBER PLATE LIGHT, CHECK / GREASE UP WATER CANNON JET, REPLACED PARK LIGHT RHS, CHECKED BATTERIES ALL GOOD	02/13/2019
WHEELS TO START TO WOBBLE AT 80-90KM ON HIGHWAY	TRUE TRACK CARRIED OUT WHEEL ALIGNMENT (INV: 25315 - QPI-10430)	12/18/2018
PRIME MOVER NO START, JUMP START	JUMP START, CHECKED BATTERY CHARGE LOW. REPLACED BATTERIES 2 X N150	10/04/2018
CREATE WATER HOSE AND CONNECTIONS FOR WATER TRUCK	COLLECT HOSE AND PARTS FROM PRIME INDUST. MAKE WATER HOSE AND CONNECTIONS UP FOR WATER TRUCK TO SUIT TANK AT BERTH 8	07/24/2018

EARTH 2 OCEAN TO REPAIR MTDATA FAULTS	EARTH 2 OCEAN TO REPAIR MTDATA FAULTS - ODOMETER NOT ACCURATE, ENGINE DATA NOT WORKING DUE TO NO VOLVO FMS GATEWAY (INV: 11219 - QPI-8199)	02/22/2018
BENNY CALLED OUT TO CHECK COOLANT LEAK	BENNY CALLED OUT TO CHECK COOLANT LEAK REMOVED / REPLACED WATER PUMP LEAKING, REPLACED COOLANT HEATER HOSE	03/12/2018
DRIVERS SEAT WONT ADJUST SEAT BOTTOM FORWARD	CHECKED DRIVERS SEAT, ALL WORKING IN GOOD ORDER	02/13/2019
CANON LOOSE OUT OF CONROL, ROOF LEAKING INTO CAB, CLUTCH NEEDS ADJUSTING	RESEALED CANON CHECKED / GREASED UP WATER CANNON MECHANISM, CHECKED NOT CONFIRMED LEAKS ON ROOF, TOPPED UP FLUID & CLEAN RESERVOIR	02/13/2019
Volvo Prime Mover (A Service)	Volvo Prime Mover (A Service) REPLACED RH CAB LOCK	01/16/2018
JUMP START, BATTERIES FLAT	JUMP START, BATTERIES FLAT	01/05/2018
VALVES AT BACK LEAKING WATER & AIR WATER CANON LOOSE CHIP IN WINDSCREEN	REMOVE WATER CANON FROM TANK STRIP DOWN & CLEAN ALL GEARS. MODIFY CLAMPS & REASSEMBLE REFIT TO TANK & TEST CHECK VALVES AT REAR & TIGHTEN BOLTS ON LEAKING VALVES WATER CANON CLAMPS TIGHTENED UP, CHECKED VALVES NOT LEAKING AT THIS TIME	01/09/2018
FUEL CAP MISSING DRIVERS SIDE TANK	REPLACED FUEL CAP LHS	12/04/2017
PA0229 LOST FUEL CAP TAKEN FROM 171 PARKED IN YARD	REPLACED FUEL CAP 171	11/08/2017
ALL WATER SPRAYERS & VALVES - LEAKING, WILL NOT TURN OFF	VALVES AT REAR & TIGHTEN BOLTS ON LEAKING VALVES	01/09/2018
CHECK / REPAIR AIR LEAK, WINDSCREEN CHIP & MTDATA SCREEN NOT RECEIVING	REPAIRED AIR LEAK ON WATER VALVE UNIT. CHECKED MTDATA, SHUTDOWN, START UP WORKS OK.	10/24/2017
CHECK / REPAIR FLAT BATTERIES - NO START	CHECKED BATTERIES & CHARGING SYSTEM REPLACED X 2 N120 BATTERIES TO GET TRUCK GOING	09/08/2017
Volvo Prime Mover (B Service)	Volvo Prime Mover (B Service) REPLACED AIR BAG LHF DRIVE. REPAIR HOSE ON WATER BOTTLE. REPLACED STEERING PUMP DOWDY SEALS.	07/06/2017

CLUTCH PEDAL FAULT AS DISCUSSED WITH STEVE WORK REQ. P1011680	CHECKED CLUTCH PEDAL, TESTED OK	07/06/2017
METERING VALVE ON GREASING SYSTEM NEEDS REPLACING ON NEXT SERVICE	REPLACED ALL GREASE METERING VALVES	05/29/2017
CARRY OUT MINE SPEC. FOR TRANSFER TO CRISTAL MINE FOR PA0158 TO COME OUT	CARRIED OUT MINE SPEC	04/24/2017
INSTALL POWER SUPPLY FOR MT DATA	FITTED POWER SUPPLY FOR MT DATA	04/05/2017
MONITOR/CHECK STEERING PUMP LEAKS	REPLACED STEERING PUMP DOWDY SEALS. REPLACED AIR BAG LHF DRIVE. REPAIR HOSE ON WATER BOTTLE.	07/06/2017
Volvo Prime Mover (A Service)	Volvo Prime Mover (A Service) FRONT NUMBER PLATE FADED, VISUAL DISCOLOURATION OF COOLANT RESERVOIR. WATER RESERVOIR IS LEAKING/WATER SLOWLY DRIPPING/CRACK UNDERNEATH. FRONT COVER PANEL BOLT TREAD WORN-OUT R/H/S. MINOR AIR LEAK FRONT WATER SPRAYERVALVE L/H/S	03/10/2017
WATER CART MODS FOR WASHING DOWN TRAILERS	SET UP PIPE WORK TO FILL BULK WATER TANK & TEST SYNCRO ENGINEERING - MODIFY ELBOW FOR WATER PIPES FOR PRESSURISER ADAPTION. INV:1442 QPI-4808	01/25/2017
CENTRE REAR SPRAY NOT WORKING PROPERLY	CHECK THE OPERATION ON THE CENTRE REAR SPRAY & IT IS WORKING WELL	01/25/2017
RIGHT HEADLIGHT NOT WORKING. CAB TILT WARNING ALARM WONT TURN OFF.	REPAIR WIRING TO RH HEADLIGHT AND REPLACED GLOBE. REPLACED RH CAB TILT WARNING SENSOR AND REPAIR THE PLUG.	08/02/2016
CHECK / REPAIR WATER CANON - DOESNT TURN OFF. REPAIR AIR LEAKS - DROPS AIR IDLING.	REMOVE WATER CANON SHUT OFF VALVE. REPAIR & REFIT	06/30/2016
CHECK CAMERA HANGING DOWN. WATER CANON DOESN'T SHUT OFF, ALWAYS ON WHEN PTO ENGAGED.	REFIT CAMERA TO WINDSCREEN. CHECK TOP WATER CANON SYSTEM, NO FAULT FOUND.	05/06/2016
TRUCK MINOR GREASE UP (10,000KM / 30 DAYS)	TRUCK MINOR GREASE UP (10,000KM / 30 DAYS)	01/19/2016
SYNCRO ENG. WELD OUT 90- PIPE / FLANGE	SYNCRO ENG. WELD OUT 90- PIPE / FLANGE (INV: 0659 - QPI-1423)	11/20/2015

CHECK WATER PUMP / HYDRAULIC PRESSURES, REPAIR COOLANT LEAK	CHECK PRESSURES - HYDRAULIC SUPPLY 2300PSI. WATER AT PUMP 250 TO 300 KPA. PUMP RPM 1800RPM AT 1500 ENGINE RPM. REPLACED DAMAGED COVER ON FRONT OF ENGINE THAT WAS LEAKING COOLANT.	11/25/2015
HOSEPRO TO SUPPLY COOLER AND HOSE UP	HOSEPRO TO SUPPLY COOLER AND HOSE UP (INV: 3351 - PO:QPI-1329)	11/05/2015
SYNCRO ENG. TO REPAIR FRONT BUMPER - DAMAGED	SYNCRO ENG. FABRICATED & FIT BULL BAR BRACKETS AND MOUNTING PLATE. (INV: 0665 - PO: QPI-1429)	11/24/2015
NO START & SPRAYERS FAULT	REPLACED BATTERIES FAULT FIND MIDDLE REAR SPRAYER, CLEAN OUT SOLENOID & CUT COMPRESSION SPRING ON VALVE. BLANK ALL HOLES IN TANK & SET UP CORRECT WATER LEVEL FOR DRIVING ON ROAD.	10/26/2015
REAR SPRAYERS & TOP CANON	ADJUSTED HYDRAULICS AND SPRAY COULD NOT GET THE REQUIRED PRESSURE.	11/24/2015
TRUCK & MACHINE TO CARRY OUT WIRING OF LIGHTS ETC.	TRUCK & MACHINE CARRIED OUT WIRING OF WORK LIGHTS, MARKER LIGHTS, REVERSE ALARM & REPAIRED WIRING TO WATER CANON. (INV: 22017 - PO: QPI-1157)	10/22/2015
AUSQUIP TO CARRY OUT WATER TANK CONVERSIONS	AUSQUIP CARRIED OUT WATER TANK CONVERSIONS FROM HINO TO VOLVO. REMOVE TANK & ALL PUMPING GEAR OFF HINO & MODIFY TO 8 WHEELER VOLVO, EXTENDED REAR CHASSIS. FRONT SPRAY BAR TO BE FITTED IN LIEU OF ALI BULL BAR. EXTRA WORK TO FRONT SPRAY BAR / PIPE WORK - RESEAL FITTINGS WIRING UP OF LIGHTS & HYDRAULICS. (INV: 137776 - PO: OPI-1253)	10/21/2015
WATER CANON SEAL LEAKING. HYDRAULIC OIL COOLER RUNNING HOT	RESEAL WATER CANON. RUN WIRES TO SWITCH THE HYDRAULIC COOLER FAN ON WHEN THE PTO IS SWITCHED ON.	11/05/2015
SPRAYERS LEAKING	REPAIR LEAKING SPRAY CONNECTION FROM THE DIAPHRAGM	10/27/2015
WATER CANON NOT WORKING - NO CONTROL OIL PUMP STILL GETTING HOT.	REPLACED PTO PUMP. REMOVED WATER CANON ASSY. REPAIRED, MAKE NEW GEAR KEY, INSTALLED & TESTED.	10/29/2015

REPAIR HYDRAULIC OIL LEAK FIT REVERSE SQUAWKER ALARM	REPAIRED HYDRAULIC OIL LEAK, REPLACED PTO PUMP & REPLACED REVERSE ALARM TO SQUAWKER. OIL COOLER FITTED BY SYNCRO ENG. 04.11.15 & HOSES FITTED BY HOSEPRO 05.11.15	10/27/2015
REMOVE TURNTABLE REMOVE LH FUEL TANK AND RELOCATE FUEL PICK UP HOSES AND FUEL LEVEL WIRING TO THE RHS.	REMOVED TURNTABLE & LH FUEL TANK. RELOCATE FUEL PICK UP HOSES & WIRING TO RHS. DELIVERED PRIME MOVER TO AUSQUIP FOR MODIFICATIONS TO WATER TANK WT0001.	09/16/2015
CHECK / REPAIR DRIVING LIGHT - HELD ON BY TAPE	REPLACED SCREW IN SPOT LIGHT.	09/11/2015
CHECK COOLANT LEAK	ENGINE REPAIRS - REPLACED HEAD GASKET (LEAKING COOLANT RIGHT SIDE REAR) REPLACED CAM BEARINGS, NEW TURBO & EXHAUST HOUSING. FLUSH COOLANT SYSTEM WITH REFRESH & WATER. FINISH WITH COOLANT.	09/11/2015
REPAIR LH HEADLIGHT WIRING	TO FIND FAULT WITH LH HEADLIGHT NOT WORKING. REPAIRED LH HEADLIGHT WIRING	09/03/2015
CHECK OVER FLOW OUT OF TOP TANK - CAP LOOSE. HUB SEALS ON ALL FOUR DRIVES LEAKING	DRAIN HYDRAULIC TANK OVERFILLED, WASH TANK & CHASSIS HUB SEALS NOT LEAKING AT TIME OF CHECK.	08/24/2015
RADIO NOT WORKING - NEED RADIO CODE	RE-ENTERED RADIO CODE	08/19/2015
REPLACE BELTS, BELT TENSIONER & IDLER PULLEY EVERY 100,000KMS	CHECKED BELTS HAVE BEEN REPLACED RECENTLY	08/17/2015
TRUCK MINOR GREASE UP (10,000KM / 30 DAYS)	TRUCK MINOR GREASE UP (10,000KM / 30 DAYS)	08/17/2015
REPAIR RHS HEADLIGHT - NOT WORKING. CHECK WIRING	repair wiring to RH head light	08/14/2015
REPAIR AIR LEAK	MAKE UP QUICK RELEASE AIR COUPLING AND FIT	08/07/2015
ENGINE SYSTEM ERRORS - ENGINE OIL, ELECTRICAL FAULT, DERATE	TRUCK CENTRE REPLACED ENGINE HARNESS. (INV: 7037991 - PO: QPI-503) REPLACED ENGINE OIL LEVEL SENSOR.	08/07/2015
WA MAIN ROADS ACCREDITATION ROADWORTHINESS CHECKLIST	WA MAIN ROADS ACCREDITATION ROADWORTHINESS CHECKLIST	04/29/2015
REPLACE BELTS, BELT TENSIONER & IDLER PULLEY EVERY 100,000KMS	REPLACED FAN HUB, TENSIONERS & BELTS	07/07/2015
TRUCK MAJOR SERVICE - VOLVO SERVICES 100,000KMS	TRUCK MAJOR SERVICE - VOLVO SERVICES 100,000KMS	08/17/2015
replace front eng mount, replace fan hub and belts and tensioners, replace intercooler and trans cooler	replace front eng mount, replace fan hub and belts and tensioners, replace intercooler and trans cooler	07/07/2015

LH tail light windscreen chipped engine derate light fault	replace failed tail light globe repair windscreen stone chips check engine derate fault, no fault found.	07/17/2015
LH indicator failed	REPAIRED LH INDICATOR	06/10/2015
CHECK / REPAIR DERATE FAULT - WARNING ON DASH. SUSPECTED LOW COOLANT. FAULT STILL OCCURRING.	TRUCK CENTRE TO REPAIR SPLIT HOSE PIPE. DELIVERED 05.06.15	06/05/2015
repair lights and bleed clutch	top up and bleed clutch slave cylinder. replace headlight globe.	03/26/2015
TRUCK MINOR GREASE UP (10,000KM / 30 DAYS)	TRUCK MINOR GREASE UP (10,000KM / 30 DAYS)	08/03/2015
CHECK / REPAIR CLUTCH FAULT	BLEED CLUTCH SYSTEM	05/14/2015
NEXT SERVICE - ALL BELTS, TENSIONERS & FAN HUB. TOP SET DUE. RESEAL WIRING LOOM & ROCKER COVER. MANIFOLD GASKETS. POWER WINDOW SWITCH. OIL LEVEL SENSOR.	REPLACED FAN HUB, TENSIONERS & BELTS 07.07.15 replace front eng mount, replace fan hub and belts and tensioners, replace intercooler and trans cooler. REPLACED EPG & ALL EXHAUST GASKETS, NEW FLEX & CLAMPS. INJECTOR SLEEVES REPLACED & TOPSET DONE. REPAIR WIRING TO OIL LEVEL SENSOR. STARTER MOTOR CHECKED OK. NO FAULTS TO POWER STEERING SYSTEM. REPLACED DRIVERS DOOR LATCH. LED LIGHTS FITTED TO REAR.	08/03/2015
CARRY OUT 10,000KM / 30 DAYS GREASE UP	CARRY OUT 10,000KM / 30 DAYS GREASE UP	04/29/2015
CARRY OUT 20,000KM BASIC 'A' SERVICE	CARRIED OUT 20,000KM BASIC 'A' SERVICE - REPLACED HEADER TANK, LOW COOLANT SENSOR & HOSES. COOLANT FILLED WITH NEW. NEW AIR FILTERS FITTED. REPLACED REAR DROP ARM.	04/29/2015
STEER TYRES	KAL TIRES REPLACED TYRES. TRUE TRACK CARRIED OUT WHEEL ALIGNMENT (INV: 20333)	04/29/2015
DIFF OIL LEAKING FROM BREATHER	DRAINED & REFILLED DIFFS. CHECKED DIFF BREATHER OK. CHECKED DIFF LOCK OK. TEST DRIVE OK. DEGREASE DIFF.	04/23/2015
RHR BRAKE LIGHT - NOT WORKING	CHECKED AT TIME OF SERVICE, ALL OK. MUST HAVE BEEN REPAIRED PREVIOUSLY.	08/17/2015
LH MIRROR ANTI FOG WHINE IN STEERING	REPLACED DRIVERS SIDE LOWER MIRROR. REPAIR MIRROR HEATER WIRING PASSENGER SIDE.	08/03/2015
HEADLIGHT RHS	REPAIRED RH HEADLIGHT GLOBE	05/04/2015
ACCREDITATION ROADWORTHY CHECK LIST	COMPLETE FULL ACCREDITATION ROADWORTHY CHECK LIST	04/29/2015

CHECK / REPAIR RH MIRROR - PLASTIC CRACKED. // CHECK / REPAIR START MOTOR - AFTER SHUT DOWN WHEN RESTARTING STARTER MOTOR NO POWER.	REPAIR MIRROR HEATER WIRING PASSENGER SIDE. REPLACED DRIVERS SIDE LOWER MIRROR. NO FAULTS TO POWER STEERING SYSTEM.	08/03/2015
CHECK / REPAIR OIL SENSOR FAULT	REPAIR WIRING TO OIL LEVEL SENSOR.	08/03/2015
CHECK / REPAIR EXHAUST BRAKE - NOT WORKING. // CHECK / REPAIR CRUISE CONTROL - NOT WORKING.	REPLACED EPG & ALL EXHAUST GASKETS, NEW FLEX & CLAMPS. REPLACED FUSE TO CRUISE CONTROL.	08/03/2015
CHECK / REPAIR AIR LINE - LEAKING WHEN BRAKES APPLIED	CHECKED AT TIME OF SERVICE, MUST HAVE BEEN REPAIRED PREVIOUSLY.	08/17/2015
CHECK / REPAIR BATTERY LIGHT - COMING ON DASH. LIGHT FLICKERING. BATTERY CHARGE OVER 30V WARNING.	CHECKED BATTERIES & CHARGE ALL OK.	08/03/2015

