



Vehicle History Detail



Fleet #	PM103
Registration	XB04QH
Make	Mack
Model	Trident
VIN / Chassis #	6FMM12H56ED805139

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
11/07/2025		Registration O-277		1051129277	\$3,852.28
05/07/2025	1,102,370 kms	Brakes R-2319	Internal Workshop		\$0.00
05/07/2025	1,102,370 kms	Steering R-2319 REPLACED STEER TYRES. CHECKED KING PINS AND STEERING COMPONENTS OK	Internal Workshop		\$60.00
05/07/2025	1,102,370 kms	body repairs R-2319 DOOR REPLACED	Internal Workshop		\$240.00
05/07/2025	1,102,370 kms	Mirror R-2319 REPLACED MIRROR ASSY	Internal Workshop		\$120.00
05/07/2025	1,102,370 kms	Suspension R-2319 REPLACED STEER SHOCKS	Internal Workshop		\$645.68
05/07/2025		Electrical R-2319 CHECK SECURE NO COVER REQUIRED	Internal Workshop		\$31.63
05/07/2025	1,102,370 kms	Suspension R-2319 SHOCK RUBBER MISSING CAB HEIGHT ADJUSTER LEAKING. REPAIRED ADJUSTER AND SET RIDE HEIGHT MUD GAURD RUBBER MOUNTS BROKEN. REPLACED RUBBERS	Internal Workshop		\$504.45
11/06/2025	1,141,069 kms	Exhaust System R-2239 REMOVED EXHAUST STACK ASSY AND FABRICATED REPLACEMENT. REFIT WITH NEW ELBOW AND CLAMPS.	Internal Workshop		\$1,405.18
11/06/2025	1,101,469 kms	Brakes R-2239 REMOVED AND REPLACED ALL DRIVE BRAKE SHOES AND BRUMS. REPLACED HUB SEALS.REPLACED RH WHEEL BEARINGS.	Internal Workshop		\$2,637.45
11/06/2025	1,141,069 kms	Electrical R-2239 TEST OK	Internal Workshop		\$0.00
11/06/2025	1,141,069 kms	ELECRICAL R-2239 SUPPLIED AND FITTED LIGHTBAR AND TEST OK	Internal Workshop		\$1,056.61

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
11/06/2025	1,141,069 kms	Air Conditioner R-2239 REMOVED AND REPLACED COMPRESSOR ASSY. REPLACED RD AND TX VALVE. REPLACED	Advanced AutoElectrics		\$1,205.09
11/06/2025	1,141,069 kms	Electrical R-2239 REPLACED AUDIO UNIT AND TEST OK	Internal Workshop		\$60.00
10/06/2025	101,464 kms	ELECRICAL R-2236 REPLACED BLOWER FAN AND RESISTOR AND TEST OK	Internal Workshop		\$502.78
10/06/2025	101,464 kms	C - 180000 S-955 CARRY OUT ANNUAL SERVICE	Internal Workshop		\$588.81
09/12/2024		Hydraulics R-2092	LRF Repairs Pty Ltd		\$1,440.21
21/10/2024	94,284 kms	air filter R-1911 REPLACED AIR FILTERS	Internal Workshop		\$131.93
21/10/2024	94,284 kms	Electrical R-1872 Removed and replaced tail lamps and test operation ok FITTED AIR SUPPLY CONTROLS TO CABIN AND TEST OPERATION OK.	Internal Workshop		\$787.43
14/10/2024	94,284 kms	COI I-171 carried out coi inspection	KnK Vehicle Inspections & Mod Certificates		\$297.00
20 Records				Total:	\$15,566.53