



Vehicle History Detail



Fleet #	PM63
Registration	XB46IA
Make	SCANIA
Model	P114
VIN / Chassis #	XLEP6X40004477745

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
		COI I-266			\$0.00
29/09/2025		INSPECTION R-2427	Internal Workshop		\$4,131.98
11/12/2024		Exhaust System R-2122 REPAIRED EXHAUST AS REQUIRED NEW PARTS REPLACED	Internal Workshop		\$2,204.40
11/12/2024		Driveline R-2123 REPLACED RHR BRAKE BOOSTER REPLACED REAR DRIVE DIFF PINION SEAL AND UNI	Internal Workshop		\$1,718.20
11/12/2024		Cab R-2129 REPLACED CAB RAM	Internal Workshop		\$1,086.62
03/12/2024	1 kms	B - 30000 S-853 FULL B SERVICE AND REPAIRS AIR DRYER SERVICE ALL FILTERS			\$1,193.09
6 Records				Total:	\$10,334.29