

| Description | Work Done | Completed |
|---|--|------------|
| A Service - Trailer Set | Completed | 11/19/2024 |
| Carbon Burn - Prime Mover | Asset Retired - Not Required | 10/03/2024 |
| B Service - Trailer Set | Completed | 10/03/2024 |
| Air Dryer Filter Replacement - Prime Mover | Asset Retired - Not Required | 10/03/2024 |
| B Service - Prime Mover | Asset Retired - Not Required | 10/03/2024 |
| Demobilise for auction | Demobilise for auction 2/10/24 | 10/07/2024 |
| door stop broken and left indicator broken | Completed | 09/16/2024 |
| Change hydraulic hose,change add blue filling pipe set, fixed oil leak front engine injector harness and change rocker arm cover gasket | Change hydraulic hose,change add blue filling pipe set,fixed oil leak front engine injector harness,change rocker arm cover gasket | 08/29/2024 |
| Adblue filler neck broken | Completed | 08/15/2024 |
| A Service - Trailer Set | Completed | 08/28/2024 |
| First Aid Kit Inspection | Completed | 08/28/2024 |
| A Service - Prime Mover | Completed | 08/28/2024 |
| Tyres want rotating | Position 5 moved to position 7 Position 7 moved to position 5 Position 6 moved to position 8 Position 8 moved to position 6 | 08/13/2024 |
| Check electrical faults. Replaced brake pads all drive axle Fit new brake calliper and abs sensor in p6. | Completed | 08/13/2024 |
| Air leak behind cab Seat wont adjust | Found air leak from trailer brake valve Clean nickel residue off of seat rails with cab duster and pop seat forward so it can adjust | 08/06/2024 |
| Adblu cap missing | Completed | 07/11/2024 |
| LHR mudflapand marker signs missing | Replaced mudflap and marker signs | 07/11/2024 |
| Topset - Prime Mover | Completed on C service | 04/15/2024 |
| Diff Oil Replacement - Prime Mover | Completed on C service | 04/15/2024 |
| Gearbox Oil Replacement - Prime Mover | Completed on C service | 04/15/2024 |
| Wiper blades broken | Completed | 07/08/2024 |
| B Service - Trailer Set | Completed | 07/11/2024 |
| B Service - Prime Mover | Completed | 07/11/2024 |

| | | |
|--|---|------------|
| Fire Suppression Systems Inspection | Check Fire Suppression system and Fire extinguishers are operational and stamp for compliance. CARRIED OUT BY WA FIRE PROTECTION | 06/28/2024 |
| Flat tyre | Spare outer tyre fitted to position 6 | 06/20/2024 |
| Flat tyre | Load Ute and travel to site New tyre fitted to position 2 Return to yard and unload Ute | 06/20/2024 |
| Change new cab hydraulic ram and air bag p1 p3 | Change new cab hydraulic ram and change new air bag p1 p3 | 05/30/2024 |
| A Service - Trailer Set | Completd | 05/29/2024 |
| A Service - Prime Mover | Completed 1159116km | 05/29/2024 |
| Hydraulic leak | Completed | 05/13/2024 |
| B Service - Trailer Set | Completed | 04/18/2024 |
| Pulling Power Reduced | Replaced ADD BLUE PUMP Diagnosed addblue System P3 ,4 Replacement Brake Pad Wheels Speed sensor 4 faulty/changed | 05/06/2024 |
| Air Dryer Filter Replacement - Prime Mover | replaced and calibrated | 04/17/2024 |
| Clutch requires replacing | Completed - new clutch fitted | 04/24/2024 |
| Carbon Burn - Prime Mover | completed | 04/17/2024 |
| A Service - Trailer Set | Completed | 05/03/2024 |
| C Service - Prime Mover | completed by Zach | 04/18/2024 |
| coolant leak | Replaced coolant cross over hose secured silicone hose | 04/09/2024 |
| Repair coolant leak and top it up. | Completed | 04/04/2024 |
| Coolant leak | Replaced coolant hose that rubbed through on the steering hose | 04/03/2024 |
| Repair hydraulic leak @ control valve | Repair hydraulic leak @ control valve | 03/25/2024 |
| Change new driver set belt | Change new driver set belt | 03/25/2024 |
| Rear light plug broken | Replaced rear light plug Test Reset right hand indicator trailer fuse on truck Test ok | 03/15/2024 |
| LH second steer axle kin pin needs replacing | checked and lubricated all ok | 03/19/2024 |
| Suspension needs repair | Checked all ok | 03/19/2024 |
| exhaust flex split | Replaced flex | 03/14/2024 |

| | | |
|--|--|------------|
| B Service - Trailer Set | Perform service on trailer set as per assigned surveys on each individual step. Completed by Luke Mader group | 02/06/2024 |
| B Service - Prime Mover | Minor service which includes: Engine oil and filter change, Fuel filter change Completed by Luke Mader group | 02/06/2024 |
| Air Dryer Filter Replacement - Prime Mover | Replaced air dryer and calibrated completed by Lucas Mader group | 01/25/2024 |
| Fan Hub Replacement - Prime Mover | Replaced fan hub and fan completed by Lucas Mader group | 01/25/2024 |
| Air leak rear of cab | Replaced air solenoids at rear of cab completed by Lucas Mader group | 01/25/2024 |
| Fan stuck on | replaced fan and hub completed by Lucas Mader group | 01/25/2024 |
| Truck has derated CWR29514 | Found fuel lines blocked and fuel pick blocked replaced filters and cleaned all lines completed by Lucas Mader group | 01/25/2024 |
| Aircon not working | Checked found evaporator leaking and condenser failed remove and replaced both regas aircon unit check all ok completed by Obrien Electrical | 01/03/2024 |
| Air leak | Found air leak replaced brake booster | 12/27/2023 |
| Fire Suppression Systems Inspection | Check Fire Suppression system and Fire extinguishers are operational and stamp for compliance. CARRIED OUT BY WA FIRE PROTECTION | 12/21/2023 |
| A Service - Trailer Set | Perform service on trailer set as per assigned surveys on each individual step. completed by Luke Mador Group | 12/27/2023 |
| A Service - Prime Mover | Visual inspection of asset and grease. carried Out A/S Ryan | 12/14/2023 |
| Tyres unserviceable | Recapped drive tyres fitted | 12/04/2023 |
| Carbon Burn - Prime Mover | removed pipes cleaned out | 10/09/2023 |
| Engine Bearing Roll - Prime Mover | Not completed | 10/19/2020 |
| Mainshaft & Rear Jack Uni Joints Replacement - Prime Mover | Inspected | 11/25/2019 |
| Brake valve leaking air | replaced foot brake valve | 10/09/2023 |

| | | |
|--|---|------------|
| Water pump leaking | replaced water pump coolant hose and idlers tensioners | 10/09/2023 |
| Change window mechanism assembly rhs | Change window mechanism rhs | 09/19/2023 |
| Change high ride valve and rs value | Change high ride value and RS valve | 09/15/2023 |
| A Service - Prime Mover | Visual inspection of asset and grease. | 09/14/2023 |
| IVMS Faults | Completed upgrade by SAM | 03/11/2024 |
| B Service - Prime Mover | Minor service which includes: C/o C Engine oil and filter change, Fuel filter change, ODR Download from EBS module | 08/04/2023 |
| SCR warning light on | Plug TT. replaced NOX sensor tested ok. | 07/05/2023 |
| P6 Brake calliper Seized | P6 Brake Calliper assembly Replaced And brake pads Brake pad sensor replaced P5 Brake pad replaced | 06/15/2023 |
| Tyres | Spare outer tyre fitted to position 3 | 06/14/2023 |
| A Service - Trailer, No Turntable, Mech Susp, Drum Brakes | Visual inspection of asset and grease.carry out Florentino 10k | 06/14/2023 |
| Driver hit kerb | Spare outer tyre fitted to position 6 | 05/30/2023 |
| A Service - Prime Mover | Visual inspection of asset and grease. | 06/14/2023 |
| A Service - Prime Mover | Visual inspection of asset and grease. | 05/09/2023 |
| Driver request fridge need to removed broken Air system malfunction Mud flap broken Fan Hub tensioner damaged +Fan Belt ALT.&A/C Tensioner +Belt | Replacement Fan hub belt ,Tensioner Assembly (Carried by RS) Replacement AC ,ALT.Tensioner +Belt Chevron 2x + Mud flaps2x Reset the Air Drier Removed Fridge | 04/20/2023 |
| Topset | TOPSET Next serviced | 06/14/2023 |
| C Service - Prime Mover | Major service which includes:carried out Z.H & RS Engine oil and filter change, Fuel filter change, ODR Download from EBS module Diff and Transmission oil change, Adjusting engine valve clearances | 04/20/2023 |

| | | |
|---|---|------------|
| P8 airbag small and big mount leaking P5 stay broken | Replaced 2 airbag Replaced stay Done@ 1143474 kms | 03/17/2023 |
| A Service - Prime Mover | Visual inspection of asset and grease. Done@1143474 kms | 03/17/2023 |
| A Service - Trailer, No Turntable, Mech Susp, Drum Brakes | Visual inspection of asset and grease. CAME IN WITH PRM488 | 03/10/2023 |
| Tyres | X2 new tyres fitted to position 7 and 8 | 02/15/2023 |
| Air Spring Leaking R/H middle & L/H Rear side | Replaced Air Spring big and small basement | 02/15/2023 |
| Tyres unserviceable | New tyres fitted to position 3 and 4 | 02/14/2023 |
| A Service - Prime Mover | Visual inspection of asset and grease.carried out 10k/PRM413-1142220.3km done | 02/15/2023 |
| Auto greaser not working Driver seat cushion rip Work and mirror lights not working | Repair auto greaser Replaced cushion Repair lights. | 01/12/2023 |
| A Service - Prime Mover | Visual inspection of asset and grease. | 01/16/2023 |
| Can't start | Charge air to release the gear | 01/09/2023 |
| B Service - Prime Mover | Service asset as per service sheet. | 01/12/2023 |
| 2nd Steer Link Rod Defective Air Drier over use need to reset Air lines off | Replaced Link Rod Assembly 2nd Steering Use Tech.tool for clear all codes and reset Air drier Secured air lines | 12/09/2022 |
| Tyres | Flip position 3 Position 1 flipped and moved to position 2 Position 2 flipped and moved to position 1 | 12/09/2022 |

| | | |
|--|--|------------|
| HYDRAULIC KIT FITOUT | <p>CARRIED OUT BY HYDRATRANS</p> <p>Fit up - Single end tipper & triple side tipper including standard transmission pneumatic shift PTO, gear pump, 3 position tipping valve, 200L oil tank, electric switches, including wiring harness to IP55 9 bank solenoid box. High pressure hose kit including 1 ¼" ball valves and female pressure coupling, male return coupling, 200 L 68 centistoke hydraulic oil. Testing and commissioning.</p> <p>Fit Up - Add side tipper lid control fit up - Add Gantry Frame 2000mm x 400 x 250 (LWH) Fit Up - Upgrade to pedestal mount control box Supply & fit 2 x 175A anderson plugs 24v on gantry frame</p> | 08/25/2022 |
| A Service - Trailer, No Turntable, Mech Susp, Drum Brakes | Visual inspection of asset and grease.Carry out 10k TSK270 adjustment all brakes | 11/09/2022 |
| A Service - Prime Mover | Visual inspection of asset and grease.carry out 10k | 12/09/2022 |
| B Service - Prime Mover | Minor service which includes: Engine oil and filter change, Fuel filter change, ODR Download from EBS module | 10/13/2022 |
| C Service - Prime Mover | Major service which includes: Engine oil and filter change, Fuel filter change, ODR Download from EBS module Diff and Transmission oil change, <u>Adjusting engine valve clearances</u> | 10/13/2022 |
| Tyres | Spare tyre fitted to position 4 | 10/04/2022 |
| A Service - Trailer, No Turntable, Mech Susp, Drum Brakes | Visual inspection of asset and grease. Carried out by James Jardenil. NOTE: THIS CAME IN WITH PRM488 | 10/05/2022 |
| Battery Replacement | Battery Replacement | 10/05/2022 |
| FMC - MT Data - MDVR Channel State Error - PRM00413 - SWT - QB Southwest Transport Rockingham - 07:56 Tue 27 Sep 22 (AWST) | <p>ATTEND TO MTDATA FAULTS.</p> <p>CHECK DVR AND CAMERAS. REPLACE SD CARD. INSTALL CRADLE CHARGER.</p> <p>CARRIED OUT BY O'BRIEN</p> | 12/08/2022 |

| | | |
|---|--|------------|
| A Service - Prime Mover | Visual inspection of asset and grease.carry out 10k PRM413/116561km | 10/05/2022 |
| FMC - MT Data - MDVR Recording Error - PRM00413 - SWT - QB Southwest Transport Rockingham - 17:00 Tue 06 Sep 22 (AWST) | ATTEND TO MTDATA FAULTS. CHECK DVR AND CAMERAS. REPLACE SD CARD. INSTALL CRADLE CHARGER. CARRIED OUT BY O'BRIEN | 12/08/2022 |
| FMC - MT Data - MDVR Hard Drive State Error - PRM00413 - SWT - QB Southwest Transport Rockingham - 17:00 Tue 06 Sep 22 (AWST) | ATTEND TO MTDATA FAULTS. CHECK DVR AND CAMERAS. REPLACE SD CARD. INSTALL CRADLE CHARGER. CARRIED OUT BY O'BRIEN | 12/08/2022 |
| Set up for BHP site. | Set up the truck to comply in BHP site | 09/01/2022 |
| truck derating | Replaced accelerator switch | 07/21/2022 |
| B Service - Prime Mover | Minor service which includes: Engine oil and filter change, Fuel filter change, ODR Download from EBS module. J.A | 07/05/2022 |
| WA Mainroads Accreditation Roadworthiness Checklist | Complete Mainroads "Accreditation Road Worthiness Checklist" AS PER C SERVICE | 05/05/2022 |
| Mudguard ripped off | Fixed guard | 06/20/2022 |
| Puncture | Travel to site Replace tyre Return to yard | 06/14/2022 |
| Air Compressor Replacement | Air Compressor Replacement @ 1,116,000KMS | 06/02/2022 |
| A Service - Prime Mover | Visual inspection of asset and grease. | 06/08/2022 |
| faulty air compressor | Replaced air compressor and clean all the pipes.refit all the associated parts. | 06/02/2022 |
| exhaust muffler block | Replaced muffler Refit all the associated parts Tested. 1113000km | 05/27/2022 |
| crack exhaust manifold center and broken bolts in no.1 | Replaced exhaust manifold centre Fit new gasket and bolts | 05/18/2022 |
| coolant leak from the radiator. | Replaced radiator and charge air cooler. Refit all the associated parts. Refill coolant and tested. 1113000km | 05/27/2022 |
| Engine can't start | | 05/16/2022 |

| | | |
|---|--|------------|
| hole in the muffler | Repair hole in muffler | 05/06/2022 |
| spotlight not working | Replaced spotlight plug | |
| wiper blade need replacing | Replaced wiper blades | |
| park brake malfunction | Repair wiring harness. | 05/04/2022 |
| Parking lever can't release,driver can't unhook the truck | | 05/02/2022 |
| Parking lever malfunction,driver can't unhook the truck | | 05/02/2022 |
| C Service - Prime Mover | Major service which includes: | 05/05/2022 |
| Transmission lock in gears at CCL weight bridge | Pump air to truck. Start the truck | 04/28/2022 |
| Out of air locked in gear | Fill air and tricked into neutral | 04/28/2022 |
| A Service - Prime Mover | Visual inspection of asset and grease. | 04/20/2022 |
| Flat tyre | Travelled to chememan yard and fit spare tyre to position 8 outer | 04/12/2022 |
| Engine cant start | | 04/12/2022 |
| Battery due to change | | 04/01/2022 |
| B Service - Prime Mover | Minor service which includes: | 03/31/2022 |
| Front drive axle brake pads low | Replaced brake pads and brake calliper piston rubber boots. | 03/10/2022 |
| Wiper blade u/s | Replaced cabin filter | |
| Cabin filter block | Replaced wiper blades | |
| A Service - Prime Mover | Visual inspection of asset and grease. | 03/14/2022 |
| B Service - Prime Mover | Minor service which includes: | 02/07/2022 |
| Air filter bracket broken,left hand front cab shock absorber top bush worn out.mud guard bracket loose. | Replaced bracket,top shock absorber bush and tight up mudguard bracket. | 01/21/2022 |
| A Service - Prime Mover | Visual inspection of asset and grease. | 01/20/2022 |
| Volvo Prime Mover (C Service) | Service asset as per attached service sheet 1X SPARE TYRE P3 REPAIR LHS STEP BRACKET | 12/24/2021 |
| 28164-DRIVER SIDE DOOR CAN'T OPEN INSIDE | FIX THE CABLE | 12/10/2021 |
| CWR2009375 - TRUCK ABS MALFUNCTION, AUXILIARY BRAKES DISABLED | PLUG IN LAPTOP AND INSPECT VEHICLE, FOUND SNAPPED SPEED SENSOR ON P1, REPLACED SPEED SENSOR AND TEST | 11/29/2021 |

| | | |
|---|---|------------|
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet REMOVED RADIATOR & WASH OUT REPLACED CAB RAM HOSE FIT NEW RHS HEADLIGHT SECURE BATTERY CABLE NEAR THE STARTER & MAKE A NEW CABLE FOR THE STARTER MOTOR REPAIR RHS STEP. REINFORCED THE MAIN BRACKET | 12/08/2021 |
| CWR2009370-HEADLIGHT LOW VISIBILITY, OIL LEAK IN CAB | REPLACED HEAD LIGHT REPAIRED CAB LEAK | 12/24/2021 |
| 28152-HEAD LIGHT NOT BRIGHT | REPLACED LHS HEAD LIGHT ASSEMBLY | 11/25/2021 |
| 28104-LH REAR TAIL LIGHT OUT | REPLACED LHR TAIL LIGHT | 11/11/2021 |
| Volvo Prime Mover (C Service) | Service asset as per attached service sheet WELD THE HOLE ON THE MUFFLER NEW TYRES P1 & P2, NEW DRIVES, P1 P3 10X NEW TYRES 3X OIL FILTERS 1X FUEL FILTER | 11/04/2021 |
| 27307-RHS INDICATOR LIGHT ON FRONT NOT WORKING | REPLACED GLOBE | 10/10/2021 |
| 27287-BROKEN DOOR LOCK CABLE | MAKE UP A DOOR LOCK CABLE | 09/28/2021 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet | 09/30/2021 |
| CWR5413-REPLACE DRIVER DOOR LEVER, CAN'T OPEN FROM INSIDE | FOUND CABLE CUT INSIDE | 09/24/2021 |
| 27224-DRIVER SAYS DERATED | CHECKED & NFF | 09/16/2021 |
| Volvo Prime Mover (E Service) | Service asset as per attached service sheet REPLACED CAB REAR SHOCK ABSORBER L/S | 08/26/2021 |
| CWR1137-DRIVER'S WINDOW SCRATCHED, WINDSCREEN CRACKED, SIDE FUEL TANK TREAD PLATE RUSTY, SIDE MIRROR LIGHT BROKEN, SEAT SHAKER FALLING OFF, BULL BAR LED FAULTY, PARK LIGHTS U/S, WATER IN HEADLIGHTS | REPLACED DRIVER SIDE WINDOW REPLACED FUEL TANK STEP FRAME REPAIR L/H MIRROR LIGHT REFIT SEAT SHAKER REPLACED LED PARK LIGHT MODULE WINDSCREEN REPLACED BY TCWA 27/08/21 | 08/26/2021 |
| 26884-BROEKN WIRE, DAMAGED AIR TANK, JACK SHAFT U/S | REPAIR WIRING REPLACED JACK SHAFT FIT ON AIR TANK | 07/26/2021 |
| 26964-PARTS TO INSTALL | MODULATOR INSTALL FIX BENT BRACKETS FOR WING LOOM TIDY AIR LINES UP | 07/26/2021 |

| | | |
|---|--|------------|
| 27107-REPAIRS | FIX MODULATOR, AIR TANK & FLANGE | 07/26/2021 |
| 27042-ASSESS THE DAMAGE FROM THE JACK SHAFT HIT | INSPECT & LIST ALL THE PARTS | 07/19/2021 |
| 26949 - JACK SHAFT UNI JOINT BROKEN | ASSIST THE TOW TRUCK GOING TO WORKSHOP | 07/18/2021 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet FLIP P2 & P3, PR70 | 07/19/2021 |
| 27030 - REAR INNER DRIVE TYRE FLAT | REPLACED FLAT TYRES | 07/12/2021 |
| Volvo Prime Mover (C Service) | Service asset as per attached service sheet ORDERED PARTS STEER RAM CYLINDER REPLACED NOX SENSOR REPLACED (CLEARED CODE) CAB BLOWER AIR DRYER MUFFLER REPLACED | 06/24/2021 |
| 26902 - AIR HOSE SPLIT | PUT A NEW HOSE AND FITTINGS | 06/14/2021 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet WATER PUMP REPLACED | 06/09/2021 |
| 26737 - P8 BRAKE BOOSTER LEAK | CHANGE THE BRAKE BOOSTER | 05/31/2021 |
| 26721 - SEAT BELT DRIVER SIDE STUCK | REPAIR THE SEATBELT | 05/17/2021 |
| Volvo Prime Mover (C Service) | Service asset as per attached service sheet REPLACE WIPER BLADES, DONE BELTS AND T/S, REPLACE COOLANT LINE FITTING | 05/10/2021 |
| 26600-BATTERIES U/S | REPLACED BATTERIES | 04/18/2021 |
| CWR5407-TRUCK READING FUEL PRESSURE LOW, TRUCK SURGING WHEN UNDER LOAD | REPAIR FUEL PRESSURE FAULTS FOUND FUEL PICK UP BLOCKED, CLEANED & TESTED | 04/23/2021 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet 2X NEW TYRES P3 & P4 | 04/23/2021 |
| Volvo Prime Mover (C Service) | Service asset as per attached service sheet NEW DRIVES REPLACED METERING VALVE REPLACED BRAKE PADS 1ST STEER AXLE & 2ND DRIVE AXLE REPLACED DOG BOX SWITCH REPLACED FRONT CAB SHOCK ABSORBER REPLACE TURNTABLE LOCK SPRING 8X NEW TYRES | 04/01/2021 |
| 19717 - STEERING PIPE COME OFF FROM THE FITTINGS | REPLACE BROKEN PIPE, FILL UP STEERING OIL AND TESTED OK | 12/23/2020 |

| | | |
|--|---|------------|
| Volvo Prime Mover (A Service) | NEW P1 & P2, FLIP P3 & P4 | 03/04/2021 |
| 2009363 - air con fan not working, air conditioning non existant, hot inside cab | 890552 km | 01/06/2021 |
| 19740 - air con fan not working | fit new air con fan tested ok | 01/06/2021 |
| 19951 - TURBO BOOST LEAK | 19951 - TURBO BOOST LEAK DIAGNOST AND REPAIR BOOST LEAK FOUND BOTTOM INTER COOLER HOSE ON PROPERLY SEATED FITTED NEW HOSE AND CLAMPS | 02/11/2021 |
| Volvo Prime Mover (E Service) | Service asset as per attached service sheet CHANGE DIFF OIL PARTS USED - 3X OIL FILTER, 1X FUEL FILTER, 1X WATER SEPARATOR, 1X GEAR BOX FILTER, 1X ADD BLUE FILTER, 1X STEERING OIL FILTER, 1X AIR DRYER FILTER, 1X CABIN FILTER, 1X WIPER BLADE, 1X AIR FILTER FILTER CURRENT READING - 910342 | 02/09/2021 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet SECURE L/H WIPER ARM AND LUBE UP ALL THE PIVOTS CURRENT READING - 901069 | 01/22/2021 |
| Volvo Prime Mover (C Service) | Service asset as per attached service sheet SPARE TYRE P3 20K SERVICE CURRENT READING - 886631 | 12/29/2020 |
| Volvo Prime Mover (A Service) | service asset as per attached serviced sheet CHECK TYRES CHANGE STEERING PIPE AND HOSE PARTS USED - 2X STEERING PIPE, 2X HOSE, 2X FITTING CURRENT READING - 874496 | 12/08/2020 |

| | | |
|--|--|------------|
| Volvo Prime Mover (C Service) | Service asset as per attached service sheet CHECK TYRES WELD CRACK INN THE EXHAUST PIPE REPLACE WASHER BOTTLE LEAD & FRONT INDICATOR GLOBE REPLACED L/H 2ND STEER MUD GUARD CURRENT READING - 862457 | 11/19/2020 |
| 2009360 - TRAILER BRAKE WAND NOT WORKING ON STEERING COLLMN PASSENGER SIDE DOOR INSIDE RELEASE HATCH NOT WORKING - WON'T OPEN FROM INSIDE | DIAGNOST EBS REPAIR SUSPECTED ECM FAULTS - TO BE REPAIR AT TCWA. CHANGE THE DOOR HATCH CURRENT - 855989 | 11/03/2020 |
| WA Mainroads Accreditation Roadworthiness Checklist | ACCREDITATION | 11/03/2020 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet CHECK TYRES PARTS USED - 1X LEFT HATCH DOOR CABLE CURRENT READING - 855989 | 11/03/2020 |
| 19288 - OIL FILTER ELBOW LEAKING | 19288 - OIL FILTER ELBOW LEAKING REPLACE ELBOW ON OIL FILTER TUBE REFILL OIL IN PRIME MOVER CURRENT READING - 841742 | 10/08/2020 |
| 19306 - Door latch cable broken | Fit new door latch cable Lubricate door latch mechanism Lubricate window regulator 829947km | 09/04/2020 |
| 19128 - Door handle cable mechanism broken | Pull apart door and assess damage | 09/03/2020 |
| PRM00413 - INVESTIGATE VEHICLE FOR OVER HEATING / REPLACE THERMOSTAT/REPLACE COMPLETE LID/ POSSIBLE CLUTCH, CYLINDER REPLACEMENT | PRM00413 - INVESTIGATE VEHICLE FOR OVER HEATING / REPLACE THERMOSTAT/REPLACE COMPLETE LID/ POSSIBLE CLUTCH, CYLINDER REPLACEMENT - WORK DONE AT TCWA 08/10/20 - IINVOICE #6049634-000002 | 10/08/2020 |
| 19352 - FUEL FILTER HOUSING U/S | 19352 - FUEL FILTER HOUSING U/S REPLACE FUEL FILTER HOUSING CURRENT READING 841742 | 10/07/2020 |

| | | |
|--|---|------------|
| 19282 - STARVING FOR FUEL, SUCKING AIR | 19282 - STARVING FOR FUEL, SUCKING AIR REMOVE FUEL FILTER, FOUND CROSS THREADED AND SUSCKING AIR, TIGHTENED AS MUCH AS CAN TO STOP AIR GETTING IN AND DRIVE BACK TO YARD CURRENT READING - 841739 PARTS USED FILTER HOUSING | 10/07/2020 |
| ATTEND TO AIR CONDITIONER CONNECT GAUGES - CONDENSER,PRESSURE TEST, GAS REGAS OILAND DYE, O RING | ATTEND TO AIR CONDITIONER CONNECT GAUGES - CONDENSER,PRESSURE TEST, GAS REGAS OILAND DYE, O RING WORK DONE BY O'BRIEN ELECTRICS | 08/14/2020 |
| Volvo Prime Mover (C Service) | Service asset as per attached service sheet NEW DRIVES PARTS USED 20K VOLVO SERVICE KIT 32L ENGINE OIL X8 NEW TYRES CURRENT READING - 841736 | 10/06/2020 |
| 2009359 - ENGINE COOLANT HIGH TEMP WARNING FAN MALFUNCTION WARNING RED FLASHING WARNING STOP ENGINE COOLANT TEMPERTURE HIGH | SENT TO TCWA ALAN - REPLACE RADIATOR, REPLACE THERMOSTAT, CHECK AND REPLACE FAN | 09/23/2020 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet FLIP AND PR P3 10 K SERVICE 1 X TYRE PLUG 834153 KM | 09/10/2020 |
| Volvo Prime Mover (C Service) | Service asset as per attached service sheet REPLACE STEERING ARM AND BALL JOINTS | 08/25/2020 |
| 19184 - R/H CAB SKIRT COMING OFF | 19184 - R/H CAB SKIRT COMING OFF SECURE THE SKIRT WITH SCREWS | 08/16/2020 |
| REPLACE WINDSCREEN | REPLACE WINDSCREEN - WORKM DONE BY TCWA 11/08/20 | 08/11/2020 |
| HAND BRAKE ON DASH IS BROKEN | INSPECT FOR BROKEN PARTS - NO BREAKS OR MALFUNCTION - STILL USABLE AND WORKING ONLY PLASTIC TRIM BROKEN | 08/25/2020 |

| | | |
|--|--|------------|
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet fir on park brake switch organise a/c repair - fit on condenser by o'brian electrics | 08/14/2020 |
| CHECK FIRE EXTINGUISHER | CHECK FIRE EXTINGUISHER CHECKED AS PER WO-QBP-027-309 | 07/06/2020 |
| 18940 - Batteries blow up | Remove blown batteries, check all main connections and wiring for shorts Fit new batteries, isolator switch and fire extinguisher | 07/06/2020 |
| TRUCK OVERHEATING | Diagnose faults. Found glitch in the computer. Reset fault and monitor. Didn't happen again | 07/23/2020 |
| Volvo Prime Mover (E Service) | Service asset as per attached service sheet Secure suzi coil Fix steering oil leak fit new olive seal Fit new left hand cab air bag Reset air dryer Make up spring for turntable leak Fit new brake pads 2nd steer both side | 07/23/2020 |
| CRACK IN FRONT DRIVERS SIDE WINDOW | Fit new windscreen by glass people | 07/23/2020 |
| ENGINE FAN STUCK ON | Inspect fan operation. No fault found | 07/23/2020 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet | 07/07/2020 |
| 18960 - Air horn not working | DIAGNOSE AND REPAIR AIR HORN AND TESTED OK | 06/25/2020 |
| CHECK FIRE EXTINGUISHER | CHECK FIRE EXTINGUISHER | 07/23/2020 |
| MAIN HORN IS NOT WORKING | Horn and main beam all working fine, no fault found | 07/07/2020 |
| MAIN BEAM FAULT LIGHT COMES ON WHEN IN USE | | |
| Volvo Prime Mover (C Service) | Service asset as per attached service sheet | 06/19/2020 |
| 18866 - Need new windscreen | Drop and pick up truck in truck centre | 06/02/2020 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet | 06/02/2020 |
| AIR CON - REPLACE EVAPORATOR | AIR CON - REPLACE EVAPORATOR | 05/04/2020 |
| Volvo Prime Mover (C Service) | Service asset as per attached service sheet | 05/14/2020 |
| Front window cracked | CLOSED AS PER QMAC | 04/01/2022 |
| Replace inter cooler hoses and clamps | Replace inter cooler hoses and clamps | 04/28/2020 |

| | | |
|--|--|------------|
| 413 - Spotter Mirror Air blower Tie rod and ball joint | 413 - Spotter Mirror Air blower Tie rod and ball joint | 04/29/2020 |
| 18548 - Intercooler hose rip, driver side air bag suspension leaking | Fit 2nd hand bottom inter cooler hose Fit new driver side air bag | 04/28/2020 |
| Air conditioning still not working, Blowing hot air | Repaired by O Briens | 04/29/2020 |
| Exhaust break leaking | Repaired/check by Randy | 04/28/2020 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet Replace all intercooler hose, header tank. both 2nd ster tie rod end joint and left hand spotter mirror glass | 04/29/2020 |
| Air con blowing hot air | Repaired by Obrians | 04/29/2020 |
| Truck overheating | Clean out radiator and intercooler | 04/29/2020 |
| Volvo Prime Mover (C Service) | Service asset as per attached service sheet 20K Top set Fit new oil spinner Fit new rear trail shaft uni | 04/07/2020 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet Fi tnew steering oil pipe and hose and male fittings Fit new uni joint front Fit new wiper left hand side | 03/16/2020 |
| Volvo Prime Mover (E Service) | Service asset as per attached service sheet | 02/25/2020 |
| 20692 - Rattle under cab, driver concerned that fan or pulley going to come off and cause damage | Inspect for rattle, found oil spinner requires replacement. Order for next service. Is safe to continue work until then | 02/15/2020 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet Serviced, repair left hand washer pipework and replaced wiper fit right hand back up light and replaced burnt wiring. Fit eyewash bottle and fit mudflap to position 1, washed out radiator and intercooler | 02/06/2020 |
| 20667 - Flat tyre | Bring truck into workshop slowly Remove steer tires and replace | 01/23/2020 |
| 20648 - Headlight keeps cutting out | Check for dirty connections and clean Replace left globe and test | 01/09/2020 |

| | | |
|---|---|------------|
| Volvo Prime Mover (C Service) | Service asset as per attached service sheets | 01/14/2020 |
| 20529 - TRAILER MODULE AIR LINE CONNECTION U/S | - REPLACED ELBOW AND AIR FITITNG | 12/24/2019 |
| 20293 - Bald tyre | Spare tyre fitted position 3 | 12/19/2019 |
| 2009342 - CODE WARNING TRAILER BRAKE PERFORMANCE REDUCED | DRIVER (COREY) CARRIED OUT BRAKE PEDAL TEST AND FAULT CLEARED. BRAKES OPERATING CORRECTLY. TESTING FOR RE-FAULT 8AM | 12/17/2019 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheets | 12/24/2019 |
| 20724 - Air leak | Fix air leak Travel to Greenlands road | 12/14/2019 |
| Volvo Prime Mover (C Service) | Service asset as per attached service sheet Repaired LH washers | 12/05/2019 |
| 20444 - Water pump leaking | Replaced leaking waterpump | 11/18/2019 |
| 20093 - Air con not blowing cold air | Test air conditioner. Must have been done at earlier date as operating correctly | 11/18/2019 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet Replaced left hand wiper head 646323 km (can't enter in place of mt data readings) | 11/18/2019 |
| Check SRS code U300064 is active | Check SRS code U300064 is active | 11/18/2019 |
| 20360 - Engine low power | Diagnose and repair. Found exhaust muffled clogged. Fit new muffled tested ok | 10/22/2019 |
| 2009341 - AIRCON NOT BLOWING COLD AIR MAY NEED RE GASSING | Test air conditioner. Must have been done at earlier date as operating correctly | 11/22/2019 |
| Volvo Prime Mover (C Service) | Service asset as per attached service sheet Fit new steering hose nipple and coupling Fix grease line Fit new wiper blade left hand side Carry out topset and measure valve height | 10/28/2019 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet REPLACE MISSING WIND FLAP AND REFLECTOR FIT NEW SIDE REFLECTORS REPLACE BLOWN 12 V SOCKET FUSE | 10/07/2019 |

| | | |
|---|--|------------|
| 2009340 - MUDFLAP MISSING REAR PASSENGER END, NO 12 VOLT POINTS WORKING/AVAILABLE | REPLACED MISSING MUD FLAP AND REFLECTOR FIT NEW SIDE REFLECTORS REPLACE BLOWN 12V SOCKET FUSE WORK COMPLETED DURING SERVICE ON WO-QBP-023-281 | 10/07/2019 |
| 20152 - Clutch malfunction | Plug laptop in run diagnostics, clutch unserviceable | 09/25/2019 |
| 20332 - Oil leak | Retighten oil spinner housing Tested - okay | 09/22/2019 |
| Volvo Prime Mover (E Service) | Service asset as per attached service sheet | 09/13/2019 |
| 20104 - Cab filter unserviceable, air compressor flex hose leaking oil, EBS cable chaffing on exhaust | Changed out cab filter Hose masters to repair Spiral guard EBS cable | 08/28/2019 |
| 22445 - Beacon light not working | REPAIR BEACON LIGHT AND TESTED OKAY | 08/26/2019 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet | 08/28/2019 |
| Volvo Prime Mover (C Service) | Service asset as per attached service sheets | 08/01/2019 |
| 22276 - Trailer ABS faults | Diagnose and repair fault Found backing wire, repair and test | 07/15/2019 |
| 22164 - ABS fault | Assess ABS fault on dash Find source of problem Set-up temporary fix | 07/14/2019 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet | 07/17/2019 |
| 22259 - ABS trailer plug power supply faults | Diagnose and repair ABS trailer faults Found fuse blown Fit new fuse and test | 07/04/2019 |
| 22212 - No EBS cable fitted, scales not working on trailer | Install EBS cable Assist Mick and drive with scale operation | 07/04/2019 |
| 22256 - Crankcase pressure sensor faults | Fit new sensor and tested okay | 07/02/2019 |
| 22126 - Air slow build up | Clean out carbon from blocked line at air drier housing, replace air drier cartridge and re-set | 06/27/2019 |
| 22205 - Not building up air, stuck in Alcoa Kwinana *loaded* | Load work ute and travel to Alcoa Truck managed to get outside gate Check compressor output - seems okay Take driver back to yard Pick up 287 and go back to Alcoa, travel back to yard and unload tools | 06/27/2019 |

| | | |
|--|--|------------|
| 22125 - Air compressor broken, exhaust manifold blowing | Replaced air compressor and removed/deconed compressor steel pipework Replace blowing exhaust gasket | 06/27/2019 |
| 22202 - Low coolant alarm | Load tools and coolant into ute Take spare sensor with me Investigate fore leaks - none found Re-fill radiator, run up truck, follow truck around overpass until stopped again - wouldn't build up air Tried to pump air into tanks, not enough supply Truck still not building up air, check compressor hot pipe, no air coming out Arrange for tow truck and another truck to collect the trailer Remove drive shaft, assist for truck to hook up, follow truck to flat ground Unhook prime movers from trailers, hook up spare truck and follow back to yard Help tow truck pump prime mover into workshop and | 06/26/2019 |
| 17710 - Broken right hand mirror | Replace right hand mirror assembly | 06/24/2019 |
| 2009339 - LOUD TURBO SCREAMING NOISE STILL APPARENT WHEN DRIVING UNDER LOAD OR USING THE EXHAUST BRAKE | Replace exhaust flexi pipe to reduce leak noise | 06/19/2019 |
| 21946 - 12V outlet not working. Noise from turbo/exhaust. Starter motor failing. | Find problem with outlet - replace fuses. Replace exhaust flexi pipe to reduce leak noise. Fit new starter motor. | 06/18/2019 |
| Volvo Prime Mover (C Service) | Service asset as per attached service sheets | 06/18/2019 |
| 2009338 - AIR ISSUES (BRAKE AIR PRESSURE) NOT HOLDING, FAULT COMES UP WITH AIR COMPRESSOR FAULT | FIND AIR LEAK, REPLACE LEAKING PART & TEST | 06/18/2019 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheets | 05/31/2019 |
| 21834 - Finished off radiator replacement | Re-fit gearbox radiator hoses Re-fill coolant and test | 05/14/2019 |
| 21830 - Radiator replace | Fit new radiator Re-fit associate parts Washed intercooler and A/C condensor | 05/13/2019 |
| 21832 - Right hand tail light smashed | Fit new tail light lens | 05/13/2019 |
| 21783 - Coolant leak | Find coolant leak so can order new parts | 05/09/2019 |

| | | |
|---|--|------------|
| 2009336 - RIGHT HAND TAIL LIGHT SMASHED (NOTICED ON PRE START) | Fit new tail light lens | 06/13/2019 |
| 21812 - Heater hose split | Fit new heater hose Drain and re-fill coolant | 04/30/2019 |
| 21634 - Noise under cab when driving, wiper arm broken, POS 3 brake booster broken, right hand rear mudflap split, clearance light not working, ex cylinder leaking | Replace worn right hand front cab mounting bearings Replace left hand wiper arm Replace corroded/broken brake booster POS 3 Replace split right hand rear mudflap and marker board Repaired clearance light wiring Replace exhaust cylinder | 04/30/2019 |
| Volvo Prime Mover (C Service) | Service asset as per attached service sheet | 04/30/2019 |
| 21587 - Air compressor line blown. | Travel to Alcoa. Change air compressor line - tested ok. | 04/22/2019 |
| 21584 - Coolant leak. | Fix coolant leak. Make up a hose. | 04/20/2019 |
| 2009332 - NO CLEARANCE/PARK LIGHTS | REROUTE, TIE UP EL LEAD TO STOP DISCONNECTION | 04/17/2019 |
| 21548 - Knocking sound from cab when hits bumps | Locate knocking sound - cab mount Go over all leaf spring and other cab mounts, check wheel bearings and king pin | 04/16/2019 |
| 21625 - Engine derate problem | Replace faulty nox sensor | 04/16/2019 |
| 2009331 - BAD CLUNK FROM CAB SHOCKS, POSSIBLY SUSPENSION, NEEDS TO BE LOOKED AT. | REQUIRES RH CAB MOUNT, ORDER ON 16/04/2019. TO BE REPLACED ON SERVICE | 04/16/2019 |
| 21536 - Air dryer need replacing and compressor over working, comes up on dash (driver says), not building up fill air pressure | Check over for any air leaks Check for fault codes on dash and computer Reset air dryer filter/compressor/date system Test truck build full air pressure | 04/12/2019 |
| 21555 - top set due. Electrical faults. Air drier need reset. | Carried out top set. Fix rear side lights and fit new both sides. Reset air drier. | 04/03/2019 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet | 03/13/2019 |
| FAULT WITH APM | REPAIRED BY TRUCK CENTRE WA INVOICE \$2263.65 - 6043856-000002 | 02/28/2019 |
| 2009330 - STILL LOSING AIR PRESSURE, LOW AIR IS COMING UP ON DASH | REPAIRED BY TRUCK CENTRE WA | 02/28/2019 |

| | | |
|---|--|------------|
| 21162 - Seatbelt wont pull down. | Inspected seatbelt. Disassembled seatbelt from seat. Blew out with air. Removed all debris caught in retractable port. Put back together - tested. | 02/11/2019 |
| 21113 - 1) Wiper blades unserviceable. 2) Roof clearance light out. 3) Fire exit out of date. | 1) Replaced worn wiper blades. 2) Replaced orange roof light. 3) Replaced fire exit in cab. | 02/08/2019 |
| 21009 - Engine malfunction | Diagnose and repair short circuit found engine oil control valve faulty Fit new control valve test ok invoice \$200.77 - 5068952-000002 | 01/29/2019 |
| Volvo Prime Mover (E Service) | Service asset as per attached service sheet New drives. INVOICE \$577.75 - 5069218-000002 INVOICE \$105.16 - 5069220-000002 | 02/08/2019 |
| ELECTRONIC FAULTS, CHECK POWER STEERING HOSES, INSTRUMENTATION, SUBLET SPARKY | WORK DONE BY TRUCK CENTRE WA INVOICE \$9614.13 - 6043175-000002 | 01/30/2019 |
| 21002 - Electrical faults. | Diagnose and repair electrical faults. Found wiring short circuit, repair wire and tested - ok. | 01/24/2019 |
| 20897 - Engine malfunction. | Diagnose and repair electrical faults, found cooling actuator short circuit intermittently, Fit in oil cooling actuator - tested ok. INVOICE \$200.59 - 5068871-000002 | 01/22/2019 |
| 2009324 - EXHAUST BRAKE IS TEMPERAMENTAL, GOES ON AND OFF BY ITSELF ON POSITION AND ENGAGED, SOMETIMES DOESN'T GO ON AT ALL | Repaired. | 02/08/2019 |
| FMC - DSSi fault in truck PRM00413 the fault reported = Vibration motor fault detected | Checked 21/02/2019 | 02/21/2019 |
| 20877 - Faulty brake booster right hand 2nd steer. | Repair brake booster. Tested ok. Inspect brake calliper. | 01/15/2019 |

| | | |
|--|---|------------|
| 20846 - Mud guards rubbing on fuel tanks. | Cut rubber pads and sikaflex to fuel tank to prevent wear. | 01/03/2019 |
| 20746 - Electrical faults | Diagnose electrical fault found RDCIOM faulty Send truck to VOLVO for RCIOM to replaced | 12/27/2018 |
| 20780 - Electrical issues non start and breaks applying on their own | Called out to Pinjarra, electrical issues Brakes wont release, got vehicle back to yard and swapped out | 12/26/2018 |
| Volvo Prime Mover (A Service) | Complete INVOICE \$889.76 - 5068744-000002 | 01/03/2019 |
| 20823 - Window wiper scraping window. | Fit new wiper. | 12/20/2018 |
| 20724 - Exhaust brake malfunction, compressor overuse warning, losing air | Test all - no brakes fault | 12/13/2018 |
| 20548 - APM fault. | Test APM and wires, no faults found. | 11/26/2018 |
| 20550 - Electrical fault | Inspect wiring harness for CC10M, found CC10M power supply plug loose, secure plug and test | 11/27/2018 |
| 20664 - Autogreaser line broken | Re-fit grease line with new nut and drive | 11/27/2018 |
| 2009318 - ELECTRICAL FAULT WARNING - TRUCK DERATING, SCREEN SHOWING APM FAULTS | SENT TO TRUCK CENTRE FOR REPAIR/DIAGNOSE | 11/27/2018 |
| 20654 - Electrical malfunctions. Comes on when hit bumps. | Connect computer and look for faults. Check over wiring harness, found plug not locking in properly. Remove/clean pins, fit back together and secure in place. Test drive around yard to see if faults come back. No faults. | 11/23/2018 |
| Volvo Prime Mover (C Service) | Service asset as per attached service sheet reset air dryer. | 11/27/2018 |
| 20540 - Air dryer faults and trailer light fault. | Test trailer lights - all good. | 11/20/2018 |
| 20536 - Electrical faults. | Diagnose and repair. Found window switch driver side faulty - fitted new switch. Tested ok. | 11/16/2018 |

| | | |
|---|---|------------|
| 200930 - 2009323. Fit new air-con fan. Replace air filter and reset V/cads. | Fit new air-con fan and tested - ok. Replaced air filter and reset V/cads. | 11/15/2018 |
| 2009322 - AIR CON NOT WORKING | Fit new air-con fan and tested - ok. Replaced air filter and reset V/cads. INVOICE \$754.319 - 5067855-000002 | 11/15/2018 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet | 11/07/2018 |
| APM FAULT, IGNITION LOOP | WORK DONE BY TRUCK CENTRE INVOICE \$2589.80 - 6042650-000002 | 10/26/2018 |
| 18304 - Seatbelt unserviceable. | Replaced drivers seatbelt. | 10/05/2018 |
| 20217 - Leaking coolant pipes. | Assist Alex remove broken pipes and fit new ones. | 10/04/2018 |
| 20024 - Seatbelt fault. | Reassembled seat belt assembly and diagnosed. Faulty pretensioner. | 10/04/2018 |
| 20023 - Heater crossover pipe leaking. | Stripped down parts around the radiator and replaced crossover pipe. | 10/04/2018 |
| Volvo Prime Mover (C Service) | Service asset as per attached service sheet INVOICE \$218.58 - 5067143-000002 INVOICE \$247.03 - 5067195-000002 INVOICE \$398.65 - 5067214-000002 Puncture repair outer position 8. | 10/04/2018 |
| FMC - DSSi fault in truck PRM00413 the fault reported = Buzzer fault detected | Tested by O'Briens electrics - no faults INVOICE \$184.80 - 00068780 | 10/03/2018 |
| FMC - DSSi - Camera Misaligned - Trk, PRM00413 - South West - Bulk - South West Transport Rockingham - 06:41 Fri 21 Sep 18 (AWST) | Re-aligned camera. | 10/04/2018 |
| AIRCON NEEDS ATTENDING | REPAIRED BY OBRIENS AUTO ELECTRICS INVOICE \$2195.03 - 00068550 | 09/03/2018 |

| | | |
|--|--|------------|
| 20251 - Left hand rear indicator inoperable, rear clearance lights inoperable | Repaired wiring faults at rear of trailer and filled missing reflectors | 09/05/2018 |
| 20105 - Low air pressure | APU test and no faults found | 09/03/2018 |
| 2006610 - Diagnoses and repair APU faults | Diagnoses and repair APU faults. Carried out test APU - no fault found | 09/03/2018 |
| 18248 - Loosing air fault. | Checked air system for operation and leaks. Checked all trailers for air leaks and reset air drier. | 08/30/2018 |
| 18199 - Wrong suzi coil. | Fit 2 new suzi coil and wrap up in conduit. | 08/24/2018 |
| 18133 - Suzi coil melted on work light. | Replaced red suzi coil at Coburn cement. | 08/23/2018 |
| 18194 - SCR faults. | Diagnose and repair SCR faults. Found dosing unit faulty, fit new dosing unit - tested okay. | 08/22/2018 |
| 18233 - Emissions, adblue sensor and wiring faults. | Replaced nox sensor, checked adblue dosing pump operation and checked/repairs wiring fault. | 08/21/2018 |
| 18174 - APM faults. | Reset APM cartridge and air leak - tested okay. | 08/10/2018 |
| Volvo Prime Mover (A Service) | Service asset as per attached service sheet Flip position 2 and 4. INVOICE \$898.55 - 5066443-000002 INVOICE \$137.50 - 6042191-000002 INVOICE \$827.70 - 5066471-000002 | 08/16/2018 |
| 18081 - ABS/EBS fault. | Connect computer, check wiring and connectors. Found nothing (getting sent to Volvos for further inspection.) | 08/07/2018 |
| 18076 - Air pressure dropping off. | Connect computer follow diagnostic procedure. Reset air drier and clear faults. | 08/06/2018 |
| 18073 - Not holding air pressure. | Inspect to see where leak coming from looks to be air regulator. | 08/05/2018 |
| 18055 - Top work light not working. Batteries over charge date. Camera facing wrong direction on desk. | Replace rear facing work light. Replace batteries. Fix camera to dash facing correct position. | 07/24/2018 |

| | | |
|--|---|------------|
| Volvo Prime Mover (C Service) | Service asset as per attached service sheet INVOICE \$122.53 - 1650077593 Flip position1 and 3, spare drive set. INVOICE \$3992.42 - 5065905-000002 & 5065909-000002 | 07/24/2018 |
| 2009310 - REPLACE WINDSCREEN WIPER BLADES, MANUAL BUTTONS FROM SHIFTER ARE OFF, SWITCH FOR BUNDIX BRAKES LOOSE | Replaced windscreen wipers Fixed manual button gear selector lever Fix bundix switch covers Fix grease line | 06/26/2018 |
| 2009307 - RADIATOR FAN STAYS ON FULL TIME PLASTIC COVER FOR MANUAL GEAR STICK IS MISSING | Replaced fan hub assembly all fan and alternator belts and tensioners. Replaced alternator, re-filled with coolant. Plastic cover on gear cover already replaced. | 08/16/2018 |
| 2009306 - LIGHTS (PARK SIDE) ON TRAILER WENT OUT, TRUCK SAID FAULT ON SCREEN. | Clean out plug and check fuses - test Everything worked fine | 07/24/2018 |
| Volvo Prime Mover (A Service) | 10,000km Service | 06/26/2018 |
| 17512 - Fridge loose. Rear work light inoperable. Lighting plug broken. | Secured fridge mount. Repaired work light. Fitted new lighting plug. | 05/17/2018 |
| Volvo Prime Mover (C Service) | 20,000km Service | 05/17/2018 |
| 08591 - Nox sensor fault. | Removed sensor. Tapped thread out in the muffler. Installed new sensor. | 04/24/2018 |
| Volvo Prime Mover (A Service) | 10,000KM SERVICE. New positon1, 2, 3, and 4. | 04/20/2018 |
| 08584 - Turn table handle seized. | Lubed and cleaned handle. | 04/16/2018 |
| 2009304 - Excessive steering shudder when bobtail 80kmh +. | REPLACED ALL STEERS. | 04/20/2018 |
| 08448 - Top set due. | Carried out top set. | 03/21/2018 |
| Volvo Prime Mover (E Service) | 100,000KM SERVICE. Flip position 1, 3 and 4. | 03/21/2018 |
| 08531 - Left hand cab mount unserviceable and grease line broken. | Assisted Keith to change left hand front cab mount. Fix grease line and put new olives and fittings. | 03/06/2018 |
| Dssi Camera Realignment | Adjusted camera. | 03/06/2018 |
| Volvo Prime Mover (A Service) | 10,000KM SERVICE. | 03/06/2018 |

| | | |
|--|---|------------|
| FRONT CAB MOUNTS REQUIRE REPLACEMENT | Replaced left hand front cab mounting. | 03/06/2018 |
| Shudder & banging under cab getting worse | After inspection found slight play in left hand front cab mounting bush/bearings - Serviceable. | 02/15/2018 |
| 08386 - Flat tyres left hand 2nd steer. | change tyres left hand 2nd steer. | 02/10/2018 |
| Volvo Prime Mover (C Service) | 20,000KM SERVICE. Spare drive set. | 02/15/2018 |
| Left hand tail light on PRM00413 not working | REPAIRS COMPLETED ON WO-QBP-013-794 | 01/25/2018 |
| Volvo Prime Mover (A Service) | 10,000KM SERVICE. | 01/25/2018 |
| P1009398 - ENGINE FAN MALFUNCTION. ABS ACTIVE. L/H BRAKE LIGHT OUT. CAB VIBRATION. | NO ENGINE FAULTS FOUND. NO ABS FAULTS FOUND. REPLACED LIGHT. INSPECTED CAB, ALL OK. | 01/25/2018 |
| P1009398 - CAB TILT UNLOCKED. ENGINE WILL DE-RATE IN 24HRS. | Fit new nox sensor. Bypass CAB sensor. | 01/19/2018 |
| REPLACE CYLINDER HEAD. REPLACE TURBO AND MANIFOLD FITTING KIT. | REPLACE CYLINDER HEAD. REPLACE TURBO AND MANIFOLD FITTING KIT. CARRY OUT SUMMER CLEAN. OIL FILLER CAP SPLIT. STEERING PIPE INTO BOTTOM OF STEERING BOX LOOSE. STEERING OIL COOLER PIPE LEAKING. WORK COMPLETED BY TRUCK CENTRE WA AS PER INVOICE NUMBER: 6039932 - 000002 | 01/05/2018 |
| Volvo Prime Mover (C Service) | 20,000KM SERVICE. OIL TO BE REPLACED BY VOLVO. | 01/04/2018 |
| 07991 - UNI BROKEN | REPLACED UNI | 12/11/2017 |
| Volvo Prime Mover (A Service) | 10,000KM SERVICE. | 12/14/2017 |
| WA Mainroads Accreditation Roadworthiness Checklist | COMPLETED AS PER MAINROADS ACCREDITATION ROADWORTHINESS CHECKLIST. | 11/23/2017 |
| Volvo Prime Mover (C Service) | 20,000KM SERVICE. FITTED NEW TYRE TO POS 1 | 11/23/2017 |
| Replace, regroove + rotate tyres as required | NEW 295 STEER TYRE FITTED TO P2 | 11/13/2017 |
| TRUCK OVERHEATING A LOT WHEN LOADED ON HOT DAYS. TRUCK SHAKES BADLY WHEN EMPTY (WHEELS/TYRES/STEERING). WORK REQUEST: P1009395 | WASHED/CLEANED RADIATOR AND INTERCOOLER. TYRES REPLACED. | 11/23/2017 |

| | | |
|--|--|------------|
| COOLANT PUMP LEAKING. RFW FORM: 07910 | DRAIN AND FILL COOLANT. CHANGE COOLANT PUMP. WASHED FRONT OF ENGINE. | 11/02/2017 |
| Volvo Prime Mover (A Service) | 10,000KM SERVICE. | 11/02/2017 |
| BLUETOOTH NOT WORKING PROPERLY. CAN HEAR AUDIO BOOK AND SELECT TO MAKE A CALL. AS SOON AS YOU CALL A NUMBER SOUND IS LOST. PHONE WORKS ON OTHER TRUCKS. WORK REQUEST: P1009394 | TESTED. NO FAULT FOUND. ALSO SPOKE TO USUAL DRIVER. NO FAULTS NOTED. | 10/20/2017 |
| FIX GREASE LINE | FIX GREASE LINE | 09/29/2017 |
| Volvo Prime Mover (C Service) | 20,000KM SERVICE. | 10/12/2017 |
| Volvo Prime Mover (A Service) | 10,000KM SERVICE. TOP SET. CLEAN FCIOM PLUGS. HELPED RANDY WITH TOP SET. CHECKED TYRES. | 09/27/2017 |
| TRAVEL TO HENDERSON DIAGNOSE STARTING FAULTS RESET ECU, INSPECTED PLUGS AND FUSES. | TRAVEL TO HENDERSON DIAGNOSE STARTING FAULTS RESET ECU, INSPECTED PLUGS AND FUSES. | 09/22/2017 |
| CRASH ALERT MECHINISIMS NOT WORKING. | ALL WORK COMPLETED BY TRUCK CENTRE AS PER INVOICE # 6039277 - 000002 | 09/18/2017 |
| Volvo Prime Mover (C Service) | 100,000KM SERVICE COMPLETED | 09/05/2017 |
| DENT IN PASSENGER DOOR ALONG WITH SCRAPE MARKS. | CHECKED AND SERVICABLE | 09/08/2017 |
| Volvo Prime Mover (A Service) | 10,000KM SERVICE, CHECKED TYRES. | 08/15/2017 |
| Volvo Prime Mover (C Service) | 20,000KM SERVICE. TYRES: CHECKED | 07/25/2017 |
| SQUEAKY WHISTLE SOUND WHEN EXHAUST BRAKE IS ON AND WHEN TRUCK IS UNDER LOAD. | CLEANED OUT BLOCKED FUEL BREATHERS. REPLACED LEAKING NO 1+2 EXHAUST MANIFOLD GASKETS AND LEAKING AIR TEST POINT VALVE. | 07/25/2017 |
| Volvo Prime Mover (A Service) | 10,000KM SERVICE, FITTED X2 NEW TYRES TO P1 AND P2, SWAPPED P1 TO P3 AND P3 AND P4 | 07/04/2017 |
| CALIBRATE AIR DRYER RESET FAULT CODES | CALIBRATE AIR DRYER RESET FAULT CODES | 04/19/2017 |
| Volvo Prime Mover (C Service) | 10,000KM SERVICE | 06/13/2017 |
| DIAGNOSE CHECK ENGINE LIGHT FAULTS AND FOUND NOX SENSOR FAULTY - CLEARED CODES | DIAGNOSE CHECK ENGINE LIGHT FAULTS AND FOUND NOX SENSOR FAULTY - CLEARED CODES | 06/06/2017 |
| DRIVERS DOOR INSIDE HANDLE BROKEN. | REPLACED RIGHT HAND SIDE DOOR HANDLE CLIP. | 06/13/2017 |
| Volvo Prime Mover (A Service) | 10,000km service | 05/23/2017 |

| | | |
|--|---|------------|
| RESET AIR DRYER | RESET AIR DRYER | 05/10/2017 |
| Volvo Prime Mover (C Service) | 20,000km service, repaired left hand clearance lights. | 05/02/2017 |
| PRM00413 LEFT HAND FUEL TANK NOT DRAINING ACROSS TO RIGHT SIDE. | REMOVED AND CHECKED BREATHER AND FILTER, CHECKED BOTH FUEL TANKS TAPS, ALL OK CLEAR AND NO FAULTS FOUND. REPLACED P4 BRAKE HOSE, REMOVED 2ND STEER GUARDS AND TRIMMED BACK EDGE, LUBBED UP TURNTABLE. | 04/13/2017 |
| ENGINE RADIATOR FAN STAYING ON CONSTANTLY ALL THE WAY UP THE FREEWAY, TRUCK EMPTY. | CHECKED FAN HUB FOR CONDITION AND OPERATION, NO FAULT FOUND. | 04/13/2017 |
| Volvo Prime Mover (A Service) | 10,000KM SERVICE | 04/13/2017 |
| POWER MODE ON GEAR BOX NOT WORKING, PASSENGER DOOR HAS NO INTERNAL HANDLE TO OPEN FROM INSIDE. CHECK ENGINE WARNING LIGHT ON CONSTANTLY, SAYING ENGINE DERATE IN 30 HOURS. | Fitted new pass door latch and cable, fitted new nox sensor. Fitted new filler cap, top set. | 03/23/2017 |
| Volvo Prime Mover (E Service) | 100,000km service top set, fitted new passenger door catch and cable, fitted new nox sensor. Checked tyres. | 03/23/2017 |
| PRM00413 check engine, dash display reduced pulling lower. | CHECKED ENGINE LIGHT NO FAULT FOUND. RE-SET FAULT CODES 15/8/17 A TATTON | 02/28/2017 |
| Volvo Prime Mover (A Service) | 10,000km service REPAIRED AIE LEAK L/H CHASIS REPLACED DAMAED REFLECTOR CHECK TYRES CONNECT LAPTOP DIAGNOSE FAULT REPLACE NOX SENSOR | 02/28/2017 |
| Prime Mover, Volvo, B/INTERMEDIATE-Service | 20,000KM SERVICE, repaired right hand washer pipe, adjusted turntable, secured front rego plates and replaced fire extinguishers, split up and grease turntable. Fitted new tyres to P1 and P2, flipped P1 and P3 tyres and flipped P2 and P4. | 02/09/2017 |
| Clutch warning malfunction | Sent to Truck Centre for warranty repair. | 01/17/2017 |
| Prime Mover, Volvo, A/MINOR-Service | 10,000km service, | 01/20/2017 |
| Prime Mover, Volvo, B/INTERMEDIATE-Service | COMPLETED B SERVICE CHECKED TYRES RESET AIR DRIER | 12/29/2016 |

| | | |
|---|---|------------|
| Prime Mover, Volvo, A/MINOR-Service | 10,000km service, replaced drive tyres and took truck to Volvo's. | 12/08/2016 |
| Carried out diagnostic and repair for SCR system. Plug v-cards read fault code and found nox sensor faulty. Change nox sensor and clear fault codes, all tested ok. | Carried out diagnostic and repair for SCR system. Plug v-cards read fault code and found nox sensor faulty. Change nox sensor and clear fault codes, all tested ok. | 11/16/2016 |
| Prime Mover, Volvo, B/INTERMEDIATE-Service | 20,000km service, split and grease turn table. Fitted x2 new tyres to P1 and P2, swapped tyres from P1 to P3 and P2 to P4. | 11/18/2016 |
| emissions derate 36 hours-vehicle message | Carried out diagnostic and repair for SCR system. Plug v-cards read fault code, found NOX sensor faulty. Change NOX sensor and clear fault codes, all tested ok. | 11/16/2016 |
| PRM00413 no windscreen washer, right hand side dash board failure | REPAIRED WINDSCREEN WASHER FAULT NO FAULT FOUND WITH DASHBOARD ALL WORKING FINE AT TIME OF SERVICE | 10/27/2016 |
| Prime Mover, Volvo, A/MINOR-Service | COMPLETED A SERVICE ROTATE POS 3 REMOVE T/T AND SWAP OUT BOTTOM PLATE | 10/27/2016 |
| Prime Mover, Volvo, B/INTERMEDIATE-Service | 20,000km service, checked tyres | 10/07/2016 |
| Prime Mover, Volvo, A/MINOR-Service | 10,000KM SERVICE RESET AIR DRYER, CHECKED TYRES. | 09/15/2016 |
| Prime Mover, Volvo, B/INTERMEDIATE-Service | 20,000km service, removed dash board to retrieve fuel card, repaired broken mud guard trim. | 08/25/2016 |
| Replace, regroove + rotate tyres as required | FLIP TYRES ON P3 | 07/14/2016 |
| repaired adblue fault | repaired adblue fault | 07/05/2016 |
| TAKE TO VOLVO | TAKE TO VOLVO | 08/04/2016 |
| INSPECT FUSE BOX RE-ROUTE ABS BRAKE WIRES ADJUST T/T | INSPECTED FUSE BOX RE-ROUTED ABS BRAKE WIRES ADJUSTED T/T | 07/14/2016 |
| Prime Mover, Volvo, A/MINOR-Service | 10,000km service. CHECK TYRES | 08/04/2016 |
| Prime Mover, Volvo, B/INTERMEDIATE-Service | COMPLETED B SERVICE | 07/14/2016 |
| Run out of air, charge air system up. | Run out of air, charge air system up. | 07/11/2016 |
| Call out to no tail lights on trailers, inspect plugs, wiring, suzi leads and isolate truck | Call out to no tail lights on trailers, inspect plugs, wiring, suzi leads and isolate truck. | 07/08/2016 |
| PRM00413 air dryer requires service | Reset percentage on laptop. | 06/23/2016 |
| TRAILER/DOLLY MINOR SERVICE | 7,000km service, checked tyres | 06/23/2016 |

| | | |
|--|---|------------|
| Prime Mover, Volvo, B/INTERMEDIATE-Service | 20,000km service, checked tyres. | 06/10/2016 |
| Blue tooth connection not working | Repaired connection | 06/10/2016 |
| Repair electrical lighting fault | Repair electrical lighting fault | 05/20/2016 |
| TRAILER/DOLLY MINOR SERVICE | 7,000km service, checked tyres. | 05/16/2016 |
| Flipped tyres on P1 and P2 | Flipped tyres on P1 and P2 | 04/28/2016 |
| Prime Mover, Volvo, B/INTERMEDIATE-Service | 20,000km service Tightened all coolant hoses, intercooler pipes and tightened exhaust bolts. | 04/28/2016 |
| PRM00413 transmission faults, P+ mode not working | Soft ware has been set this way by Volvo, not on fault | 04/28/2016 |
| Flip tyres on P3 | Flip tyres on P3 | 04/07/2016 |
| PRM00413 Re-adjust jaws on turntable | checked ok, First aid kit is in the truck | 04/05/2016 |
| Right hand side fuel tank leaks, check ABS | Repaired by Volvo under warranty | 04/04/2016 |
| PRM00413 Right hand fuel tank leaking from fuel line | Measured 150mm length advised Dennis to pursue Main roads permit. | 04/04/2016 |
| Secured several hoses/wiring along chassis and under cab, fit fire extinguisher bag. Also truck was taken taken to Volvo. | Secured several hoses/wiring along chassis and under cab, fit fire extinguisher bag. Also truck was taken taken to Volvo. | 04/04/2016 |
| Prime Mover, Volvo, A/MINOR-Service | 7,000km service | 04/04/2016 |
| Re-tightened jaws on turn table | Adjusted turntable. | 03/17/2016 |
| ABS fault light keeps coming on disengaged engine brake, have to keep shutting down the truck with the isolation procedure to clear fault. | Repaired by Truck Centre under warranty. | 03/11/2016 |
| Adjusted turn table and measure length of road train. | Adjusted turn table and measure length of road train. | 03/10/2016 |
| Prime Mover, Volvo, A/MINOR-Service | 7,000km service, also first service done at Volvo. | 03/10/2016 |

