

Description	Work Done	Completed
A Service - Prime Mover	As per work order	08/26/2024
Air Dryer Filter Replacement - Prime Mover	As per work order	08/04/2024
Topset - Prime Mover	As per work order	08/04/2024
Diff Oil Replacement - Prime Mover	As per work order	08/04/2024
B Service - Prime Mover	As per work order	07/23/2024
Repair battery isolator lockout cover		
MT Data tracking unit to be replaced	As per work order	08/07/2024
Front RH indicator not working		
TCWA - washer reservoir ordered by Bonza.	TCWA - washer reservoir ordered by Bonza.	07/01/2024
Diff Lock Diaphragms - Prime Mover	As per work order	06/12/2024
A Service - Prime Mover	As per work order - Yaka Team	06/12/2024
B Service - Prime Mover	As per work order	04/27/2024
A Service - Trailer Set	As per work order	03/05/2024
A Service - Prime Mover	As per work order	03/02/2024
Humming bird system	Humming bird system	02/26/2024
CHECK ENGINE LIGHT	DEFECT RECTIFIED AT TRUCK CENTRE GERALDTON	01/23/2024
Defects	DEFECTS RECTIFIED AT TRUCK CENTRE GERALDTON	01/23/2024
CHECK ENGINE LIGHT	REF WO-GFN-004-702	01/01/2024
End of Life Asset Replacement - Qube Bulk	NOT COMPLETED, NOT REQUIRED AT THIS STAGE	12/15/2023
ELECTRICAL FAULT	FAULT RECTIFIED	12/20/2023
Defects	MAJOR ISSUES WITH HARNESS	
	REF WO-GFN-004-701	01/01/2024
Fan Hub Replacement - Prime Mover	FAN TESTED AND IS FUNCTIONING AS REQUIRED	01/01/2024
Gearbox Oil Replacement - Prime Mover	GEARBOX OIL AND FILTER REPLACED	12/30/2023
C Service - Prime Mover	C SERVICE COMPLETED	01/01/2024
A Service - Prime Mover	REF WO-GFN-004-486 C SERVICE FOR COMPLETION	11/30/2023
A Service - Trailer Set	TRAILER SET REMOVED FROM SERVICE, TICKET RAISED TO SUSPEND RITM0028225	01/01/2024
Defects	REF WO-GFN-004-535 FOR COMPLETION AND ADDITIONAL WORK	12/06/2023

Air Dryer Filter Replacement - Prime Mover	AIR DRYER REPLACED	11/21/2023
Diff Lock Diaphragms - Prime Mover	DIAPHRAGMS REPLACED	11/21/2023
Topset - Prime Mover	TOPSET ADJUSTMENT COMPLETED	11/21/2023
B Service - Prime Mover	SERVICE COMPLETED	11/21/2023
Diff Oil Replacement - Prime Mover	NOT REPLACED, RECENTLY REPLACED	11/21/2023
B Service - Trailer Set	SERVICE COMPLETE	11/21/2023
A Service - Trailer Set	REF WO-GFN-004-197	11/13/2023
A Service - Prime Mover	SERVICE COMPLETED	11/13/2023
Defects	TRANSFERED TO WO-004-535	12/05/2023
A Service - Trailer Set		11/13/2023
Hydraulic leak	Replaced suction + pressure hose from PTO pump	10/10/2023
oil leak around PTO	CLEANED AROUND PTO RAN UP AND TESTED	10/20/2023
Summer Clean - Prime Mover	SECURED HOSE FITTINGS COMPLETED SUMMER CLEAN. BEN AJ	10/20/2023
add blue fault	TEST WIRING, PUMP ACM REPLACE INJECTOR & PUMP, REFIT REQUIRES NEW ACM fitted and programmed new acm	09/13/2023
Volvo Prime Mover (C Service)	completed C Service	09/23/2023
Volvo Prime Mover (A Service)	CARRIED OUT A-SERVICE AS PER CHECK SHEETS.	08/29/2023
A Service - Trailer Set	COMPLETED	08/29/2023
REPAIRS	CHECKED TRAILER BRAKE ACTIVATION SECURED ROAD SIGN CHECKED T/T REPLACED L/H MAIN BEAM REPAIRED ABS FAULT REPAIRED FRIDGE LOCK REPAIRED OIL LEAK AT FRONT TRAILER RESET ENGINE LIGHT	08/29/2023

D2 BRAKES WONT RELEASE	Diagnosed SR3 was sticky on Dolly (2) Replaced SR3 VALVE Test & Checked brakes operations	07/24/2023
Fuel tank leaking	Drained fuel out of Tank Inspected were leak was Moved Tank away from Hydraulic tank to stop rubbing	07/22/2023
Air leak behind Cab	Repair air leak behind cab	07/15/2023
Lock Out Casing Bent	INSPECTED WORKS FINE	08/01/2023
Volvo Prime Mover (A Service)	Service asset as per attached service sheet completed at flex	07/07/2023
A Service - Trailer Set	as per WO-GFN-003-342	07/14/2023
DEFECTS	REPAIRED AIR LEAK	07/16/2023
DEFECTS	REPLACED DIFF LOCK DIAPHRAM AND ADJUSTED P/D FITTED NEW DRAG LINK AND TIE ROD ENDS 2ND STEER REMOVED HYDRAULIC TANK FOR REPAIRS.	06/25/2023
Air Bag Malfunction on Dash	Completed - No active codes returned	07/14/2023
Fan Hub Replacement - Prime Mover	Replace Fan Hub	07/14/2023
Air Dryer Filter Replacement - Prime Mover	Replace Air Dryer Filter	07/14/2023
Gearbox Oil Replacement and Sampling - Prime Mover	Replaced Oil & Filter Sampled Oil	07/14/2023
Diff Lock Diaphragms - Prime Mover	Replace Diff Lock Diaphragms	06/24/2023
Topset - Prime Mover	TOP SET DONE RECENTLY	07/14/2023
Volvo Prime Mover (E Service)	Service asset as per attached service sheet	07/14/2023
Diff Oil Replacement and Sampling - Prime Mover	Replaced Oil + Sampled	07/14/2023
B Service - Trailer Set	Carried Out Fortnightly Service as per attached Service sheet	07/14/2023
Steering Wheel Shaking	New steer tyres fitted	06/01/2023
Steering Shaking	Fit 4 new steer tyres, weld up seam tube on trailer	06/02/2023
Broken Mudguard	Straighten + weld mudguard bracket back on	06/01/2023
A Service - Trailer Set	as per WO-GFN-003-342	07/15/2023
Air Bag Malfunction on Dash	NEW WO	06/21/2023

Air Leak	Replaced compressor Hot pipe	05/24/2023
Defects	Weld bent A Trailer mud guard bar (rear)	05/30/2023
Volvo Prime Mover (A Service)	Service asset as per attached service sheet	05/30/2023
A Service - Trailer Set	Carry Out Fortnightly Service as per attached Service sheet	05/30/2023
3rd Trailer Wiring Plug Broken	fit new plug	05/12/2023
no diff locks or cross locks	fix plugs on solinoid valves	04/25/2023
A Service - Trailer Set	Carry Out Fortnightly Service as per attached Service sheet Replaced pos L/S wheel bearing Multiple air leaks Track rod bush	05/09/2023
Volvo Prime Mover (A Service)	Service asset as per attached service sheet	05/08/2023
Volvo Prime Mover (C Service)	Service asset as per attached service sheet	04/26/2023
TABLET NOT WORKING	REPAIR MI-DATA - Working CHECK AIRBAG FAULT - HYDRAULIC OIL LEAK UNDER TANK - welded AIR LEAK 3RD TRAILER - new valve fitted INTERMITANT STEERING WOUBLE - checked ok	04/26/2023
NO TAIL LIGHTS ON TRAILERS	FOUND SHORT IN REAR TRAILER WIRING. REMOVED DAMAGED WIRES AND REPLACED WITH NEW TESTED CIRCUIT - ALL FINE	03/30/2023
tipping issue t3	replaced broken air lines under cab test tipped	03/18/2023
Air Dryer Filter Replacement - Prime Mover	Replace Air Dryer Filter	03/15/2023
Diff Lock Diaphragms - Prime Mover	Replace Diff Lock Diaphragms	03/15/2023
Topset - Prime Mover	Carry Out Top Set Adjustment	03/15/2023
Diff Oil Replacement and Sampling - Prime Mover	Replace the oil and filter in all Diff housings and take on oil sampling for analysis.	03/15/2023

BRAKE MALFUNCTION	CONNECTED LAPTOP FOUND SHORT FAULT FOR TREDDLE VALVE TO CONTROLLER. LOCATED AND REPAIRED SHORT.	02/22/2023
T3 NOT TIPPING	TESTED FUNCTION TRAVEL TO ROM LOCATE AND REPAIR AIR LEAK	01/15/2023
over heating	CHECK OPERATION replaced worn fan clutch	01/12/2023
Volvo Prime Mover (A Service)	Service asset as per attached service sheet CLEANED BATTERY TERMINALS	01/26/2023
tire blow out	REPLACED BOTH CABIN POLLEN FILTERS REPLACED BOTH PASSENGER SIDE MIRRORS REPLACED ADD BLUE CAP REPLACED ADD BLUE BREATHER REPAIRED MUD GUARD	01/07/2023
pre start list	CHECKED TOE IN ADJUSTED ALL TRAILER BRAKES CARRIED OUT CALIBRATION ON SUSPENSION REPLACED FIRST DOLL GUARD PUT FIRST AIDE KIT IN CAB	01/26/2023
WA Mainroads Accreditation Roadworthiness Checklist	completed	01/05/2023
Volvo Prime Mover (A Service)	Service asset as per attached service sheet	12/29/2022
Volvo Prime Mover (A Service)	DOUBLE UP WO 002-235	12/26/2022

Volvo Prime Mover (B Service)	Service asset as per attached service sheet 4 x suspension airbags 1st diff output flange nut secured.	12/17/2022
Volvo Prime Mover (B Service)	DOUBLE UP WO	12/15/2022
Volvo Prime Mover (A Service)	Service asset as per attached service sheet	12/05/2022
Brake Test - Prime Mover	Perform Brake test and record results.	11/25/2022
brakes dragging	replaced damaged booster pos 6	11/13/2022
ICE PACK FAULT	REFITTED PILFERRED PARTS FROM KALGOORLIE	11/05/2022
AIR LEAKS	REPAIRED TIPPING LINES REPAIRED COMPRESSOR LINES STRAIGHTENED GUARD BRACKETS	11/03/2022
CHECK EBS FAULT	LOCATED AND REPAIRED BROCKEN WIRE. REPLACED AIR DRYER FILTER.	11/08/2022
Volvo Prime Mover (E Service)	Service asset as per attached service sheet repaired add blue fault repaired suspension fault	11/02/2022
Volvo Prime Mover (A Service)	duplicate wo	10/14/2022
Volvo Prime Mover (A Service)	Service asset as per attached service sheet completed on001-964	10/14/2022
connect trailer	connect trailer sorted out air lines cleaned out fittings	10/02/2022
Volvo Prime Mover (D Service)	Service asset as per attached service sheet replaced lhr clearance light replaced wiper blades	10/14/2022
Volvo Prime Mover (A Service)	Service asset as per attached service sheet NOT DUE!	08/25/2022
Volvo Prime Mover (A Service)	NOT DUE	07/08/2022
Volvo Prime Mover (A Service)	COMPLETED	07/17/2022

BRAKE MALFUNCTION	BRAKE MALFUNCTION REPLACED EBS MODULE REPLACED FUEL FILTER REFITTED DASH LOWER PANEL	08/17/2022
POS 1 DRIVE TORQUE ROD BROCKEN.	REPLACED BROCKEN TORQUE ROD. DRIVER DAMAGE WHEN CHANGING TYRES	07/27/2022
Volvo Prime Mover (B Service)	Service asset as per attached service sheet replaced a/c belt ran new can wiring for the treadle valve secured wiring	07/30/2022
AIR LEAK LIGHTING FAULT	REPAIRED AIR LEAK REPAIRED R/H INDICATORS REPLACED 1 X LIGHT PLUG SOCKET.	07/07/2022
DOSING FAULT	REPAIRED POWER FEED TO DOSING UNIT HAD TRANS ECU REPROGRAMMED FOUND POS 7 PLANETRY HUB HAD COME APPART. ORDERED PARTS. REASSEMBLED PLANETRY IN POS 5 SENT BACK TO WORK	07/03/2022
shifting issues	replaced shift lever replaced l/h head light bulb	06/25/2022
AIR LEAK	TRAVELLED TO CLIFFS NO INDUCTION RETURNED TO WKSP REPLACED PLASTIC HOSE CLEANED COMPRESSOR PIPE REPLACED AIR BAG FOR CAB	06/19/2022
air leak at cab air bag	replaced l/h air bag	06/22/2022
Repairs	replaced fridge fuses lubricated front cab shock unjammed passengers seat belt from fridge rewelded pin for turn table secured hydraulic pipe on t1 lead door cylinder	06/16/2022
check hydraulics	checked hydraulics flow checked and pressure tested	06/12/2022
HEAD LIGHTS CRACKED	REPLACED BOTH HEAD LIGHT UNITS PROGRAMMED LIGHT BENDING ECU	05/17/2022

BRAKE MALFUNCTION	BRAKE MALFUNCTION DAMAGE AIR BAG fitted new air bag and modulator valve	05/07/2022
Carry out service as per service sheet	Carry out service as per service sheet	05/07/2022
Volvo Prime Mover (B Service)	Service asset as per attached service sheet	05/07/2022
Carry out B service	Carry out B service repaired air leak at cab air bag	04/26/2022
Replace Engine oil filler Hose Replace diff cross locks harness Replace Diff fill plug	Replace Engine Oil Filler Hose Replace Diff Cross locks Harness Replace Diff Fill Plug	04/27/2022
Volvo Prime Mover (B Service)	FUEL LEAK WATER DRAIN ORING. REMOVE REPLAVE AND TESTED DIFF PLUG ROUNDED TACK IN DRIVE AND REMOVE TO FILL DIFF SERVICE TRAILERS COMPLETED BY: WOODS	03/09/2022
Remove drag link & fit to PRM00756	Removed drag link as required.	12/21/2021
Carry out B service as per schedule Replace header tank	Work completed as per work order Adblue injector replaced. Diagnosed Coolant Leak - Parts on Order. Completed by: Ben Wuillemin	11/17/2021
Diff Fault	Drained all diffs and checked oil for particles Checked yokes and seals Filled all diffs with clean oil	10/06/2021
Windscreen	Windscreen replaced by Deans Autoglass	09/24/2021
Volvo Prime Mover (B Service)	Service completed as per paperwork	09/25/2021
FMC - DSSi - Camera Misaligned - PRM00426 - South West Bulk - NiW Northern - 05:55 Thu 26 Aug 21 (AWST)	Camera re-aligned	09/11/2021
Volvo Prime Mover (D Service)	Service completed as per sheet	07/31/2021
1567 - COMPRESSOR HOSE	REPLACE AIR FITTING ON COMPRESSOR DISCHARGE PIPE 1259921 KM 22169 HR	07/18/2021

1561 - WONT BUILD UP AIR	CARRY OUT TEMP REPAIR ON COMPRESSOR DISCHARGE PIPE AND TEST - OK 1259243 KM 22157 HR	07/16/2021
Power steering leak	Rectify power steering fluid leak	07/22/2021
Engine de-rating	Inv. fault, found Nox sensor fault logged. Reset system and tested fault cleared. Road test, all ok	07/11/2021
Transmission - Replace Cab Jack Hose – Replace	Replaced gearbox - replaced air fittings - replaced air cooler duct - replaced cab hose. Work completed by Flex industries	06/17/2021
transmission fault and cab hose blown.	Connect tech tool - Analyse - clutch booster sensor cab jack hose blown - new. Replace gear box	06/14/2021
Check steering vibration, harsh (?) ride	Test drive truck and found vibration. Removed and replaced 4x Front steer shocks. Test drive and return to work.	05/19/2021
Volvo Prime Mover (B Service)	WORK NOT COMPLETED WORK COVERED BY WO-GFN-000-299	06/02/2021
Volvo Prime Mover (B Service)	Carried out service (WO-NGF-001-699).	04/15/2021
Volvo Prime Mover (B Service)	Carried out service.	04/15/2021

<p>Fault codes</p>	<p>Test brake fault, attempt to clear, repair air leak. Remove and replace trailer/electronic relay valve at rear of cab, test and hook up trailer line, charge system. Tie and protect line, move to workshop, check for leak, return to operations</p> <p>Fault on unit archive after night shift, remove sand replace trailer charge relay valve, test, unhook, hook up unit to cover. Move into workshop, test, check air dryer, remove cover, change filter, clean and re-assemble. Run and check, fault intermittent, trailer controls not operating, foot pedal working</p> <p>Air dryer unit required, will fit when arrived.</p> <p>1,186,585km</p> <p>Valve relay 2316653</p> <p>Air dryer filter 22260124</p>	<p>03/14/2021</p>
<p>Dash showing "Air system malfunction", Cabin fridge faulty.</p>	<p>Unit down for service, carry out repairs with unit down</p> <p>1,187,030km</p> <p>Parts</p> <p>1x air drier</p> <p>1x Engal remote fridge</p>	<p>03/19/2021</p>
<p>FMC - MT Data - MDVR Connection Error - PRM00426 - South West - Bulk - NiW Northern -05 Mar 2021</p>	<p>Previously repaired, WO not completed</p>	<p>08/05/2021</p>
<p>FMC - MT Data - MDVR Channel State Error - Trk, PRM00426 - South West - Bulk - Goldfields Northern - 05 Mar 2021</p>	<p>Previously repaired - WO not completed</p>	<p>08/05/2021</p>
<p>FMC - MT Data - MDVR Recording Error - PRM00426 - South West - Bulk - NiW Northern - 05 Mar 2021</p>	<p>Previously repaired - WO not completed</p>	<p>08/05/2021</p>
<p>FMC - MT Data - MDVR Hard Drive State Error - PRM00426 - South West - Bulk - NiW Northern - 05 Mar 2021</p>	<p>Closed due to age - No longer faulting</p>	<p>08/04/2021</p>

Air leak	Load required parts and tools, travel to vehicle on Goldfields highway. Locate air leak, remove and replace failed line, run and check for leaks. Tie and protect hose, check, pack up, return to Leinster work shop 1177618 Km Parts used: 1x Fitting (Volvo 992234) 1x 16mm joiner 2 metres 16 nylon hose	02/27/2021
Volvo Prime Mover (B Service)	B service carried out as per service sheet	03/19/2021
Differential locks bypassing into Diffs.	Refit diff locks 1,173,260km Parts Kit	02/21/2021
Engine fan seldom cutting in and staying engaged at high temperature.	Replaced faulty Engine fan hub assembly & belts. 1151407 km	01/15/2021
Volvo Prime Mover (E Service)	1152313 km Carried out service Parts used: Filter kit Air filter	01/20/2021
Volvo Prime Mover (B Service)	1152313 km serviced	01/20/2021
Volvo Prime Mover (C Service)	1152313 km serviced truck	01/20/2021

<p>Coolant temperature & Turbo boost gauges randomly fluctuating high and low, vehicle torque feels low.</p>	<p>Replaced coolant temperature sensor, level sensor & MAP sensor.</p> <p>Vehicle used by Operations - feedback from operator shows an improvement on performance.</p> <p>1,187,030km</p> <p>Parts Sensor (22422785 x1) Sensor (212271982 x1) Sensor (21521072 x1)</p>	<p>03/17/2021</p>
<p>WA Mainroads Accreditation Roadworthiness Checklist</p>	<p>Mainroad accreditation</p> <p>1,137,055km</p>	<p>12/27/2020</p>
<p>Volvo Prime Mover (B Service)</p>	<p>B Service as per sheet</p> <p>1,137,055km</p>	<p>12/27/2020</p>
<p>Volvo Prime Mover (D Service)</p>	<p>Carry out service</p> <p>Found yoke loose tightened up</p> <p>1,097,418km</p> <p>Parts Filter kit Adblue filter Air drier filter Power steer filter</p>	<p>11/05/2020</p>

Volvo Prime Mover (C Service)	<p>26/8 - C service complete, check, repair lights, remove (3) over tensioned oil filters</p> <p>27/8 - Complete due service, remove belts, check pulleys, idler, check oil leak at gearbox and grease leak at pod (auto)</p> <p>Km 1,039,844km</p> <p>Parts Used Service Kit - 85136742 x1 Air dryer filter - 2326034 x1 Cab filter - 23515346 x1 Cab Filter - 23515329 x1 Air cleaner (in) 20411816 Air cleaner (out) 21716424</p>	06/01/2021
Air Leak	<p>the head required parts, tools, had to the vehicle, check air system leak. carry out repairs with parts, add and check for leaks, pack up, return to Leinster check for leaks at work shop.</p> <p>1026327 km</p>	08/09/2020
Water leak Replace air dryer filter Air leak from cab suspension bag	<p>CHECK WATER LEAK IN LINE FOR SCREEN WASHER, PRIME MOVER SEAL, REASSEMBLE, BY PASS LINE TO LH WASTE MAKE NEW HOSE LOOM, FIT, HE OD PROTECT, FILL BOTTLE CHECK SYSTEM FOR LEAKS</p> <p>CHECK AIR LEAK, LOCATE TO CAB AIR BAG (LH), REMOVE AND REPLACE REPAIR LINE, CHECK FOR LEAKS, TIE AND PROTECT LINE, REMOVE COVER, CHECK AIR DRYER, EXHAUSTION FOR A LONG HIRE. REMOVE AND REPLACE FILTER, REASSEMBLE, TEST, FIT CHASSIS COVER</p>	07/29/2020
Volvo Prime Mover (B Service)	Run and check air leak from exhaust brake cylinder. Parts required. Carry out full service as required	07/19/2020
Dismantle Dash - connect tooling check camera fault code	Test fault with camera 3/4, carried last tool, check settings, adjust, run and check, more info require,return to work	07/08/2020

FMC - MT Data - MDVR Hard Drive State Error - PRM00426 - South West - Bulk - NiW Northern - 10 July 2020	Check camera operation, reboot system and check, carry out adjustment to settings, test, check operation with FMC	07/19/2020
FMC - MT Data - MDVR Recording Error - PRM00426 - South West - Bulk - NiW Northern - 10 July 2020	Check and test operation, reboot system to check. Carry out adjustments test, check operation with FMC	07/19/2020
FMC - MT Data - MDVR Channel State Error - Trk, PRM00426 - South West - Bulk - Goldfields Northern - 22:16 10 July 20 (AWST)	Check camera operation, reboot system. Carry out required adjustments, test. Check operation with FMC	07/19/2020
FMC - MT Data - MDVR Connection Error - PRM00426 - South West - Bulk - NiW Northern - 22:12 Sun 10 July 2020 (AWST)	Check camera operation, reboot system, check operation with FMC and return to operations	07/19/2020
Heater not getting hot	Remove covers, check control at dash and tap assembly. Check circulation, locate bypass hose in system. Fit new hose, make up tap hose to join in. Tie and protect hoses, run and check operation, refit all covers top up coolant.	06/15/2020
Cylinder Head, Trailer brake switch inop, Turbo replace, Rekit steer callipers	Work carried out in Kal by Flex Industries 983,050 km	06/10/2020
Check heater & vent operation. Dismantle dash, remove & replace controller, test operation & reassemble dash	Heater in cab not blowing air. Isolate to possible controller issue. Dismantle dash remove and change out controller. Re-assemble dash, test operation, further investigation required. Return unit to work	06/13/2020
Volvo Prime Mover (C Service)	Carry out C service	06/05/2020
Replace brake sensors (wear) Change dryer filters Change brake relay valve	DIAGNOSE FAULTS WITH 3 WHEEL WEAR SENSORS REPLACE LEFT REAR STEER AXLE WEAR SENSOR FIT NEW RELAY VALVE, REPLACE DRYER FILTER AND CLEAN OUT PRESSURE VALVE IN APM	05/31/2020
Remove and replace exhaust manifold test drive	REMOVE ALL COMPONENTS TO REMOVE EXHAUST MANIFOLD CLEAN UP SIDE OF HEAD TO FIT NEW GASKETS AND MANIFOLD	05/31/2020
FMC - MT Data - MDVR Hard Drive State Error - PRM00426 - South West - Bulk - NiW Northern - 6 May 2020	Check unit operation, check and adjust settings, check unit operation with FMC, unit available to return to work	07/19/2020
FMC - MT Data - MDVR Channel Error - PRM00426 - South West - Bulk - NiW Northern - 6 May 2020	Test operation, reboot system and check, adjust, check operation with FMC, unit available for operation	07/19/2020

FMC - MT Data - MDVR Recording Error - PRM00426 - South West - Bulk - NiW Northern - 6 May 2020	Test operation, reboot system and check, adjust. Check unit operating with FMC, return unit to operation	07/19/2020
FMC - MT Data - MDVR Connection Error - PRM00426 - South West - Bulk - NiW Northern - 06:29 Sun 03 May 2020 (AWST)	Test operation of cameras, reboot system and check. Carry out adjustments to setting, test, check with FMC on unit operation	07/19/2020
Volvo Prime Mover (B Service)	B Service	04/28/2020
Volvo Prime Mover (A Service)	AS PER WO NGF-001-056 MOVE TO WORKSHOP CARRY OUT SERVICE AND CHECKS CHECK OPERATION OF BRAKES, ISOLATE TO POSSIBLE RELAY VALVES BEHIND CAB, ORDER REQUIRED PARTS TO FIT	04/15/2020
WA Mainroads Accreditation Roadworthiness Checklist	Complete accreditation AS PER NGF 000 893	01/24/2020
Check trailer brake system	Strip out steering column to check connections to hand piece for trailer brakes, replaced 2 valves behind cab, trace air lines to valves in chassis.	04/18/2020
A - service and repairs	Carried out A service as per sheet attached. Start to check fault in hand operation lever of trailer brake.	04/17/2020
Air leak	Diagnose bad air leak from rear of prime mover, lift air tank back into locating saddle, strap up with temporary strap. Re-insert air pipe, build up air and check for leaks.	04/10/2020
Volvo Prime Mover (B Service)	Carry out B Service as service sheet attached.	03/01/2020
Check charge rate	Replace batteries (overheated / Leaking) Check charge rate - found fault in charge circuit. Test all wiring / fault found in E stop circuit. Bypassed - checked / Pass. Parts used Alternator 2 x batteries	03/30/2020

FMC - MT Data - MDVR Connection Error - PRM00426 - South West - Bulk - NiW Northern - 16:31 Thu 26 Mar 20 (AWST)	Check camera operation, reboot system. Check and carry out setting adjustments, test. Check with FMC unit operating.	07/19/2020
FMC - MT Data - MDVR Recording Error - PRM00426 - South West - Bulk - NiW Northern - 16:31 Thu 26 Mar 20 (AWST)	Check unit operating, reboot. Check and carry out adjustment to settings, check unit operating with FMC	07/19/2020
FMC - MT Data - MDVR Hard Drive State Error - PRM00426 - South West - Bulk - NiW Northern - 16:27 Thu 26 Mar 20 (AWST)	Check camera operation, reboot system, adjust settings, check operation with FMC and return to work	07/19/2020
REPLACE LEAKING WATER PUMP	REPLACE LEAKING WATER PUMP	03/13/2020
Volvo Prime Mover (A Service)	Service asset as per attached service sheet	03/04/2020
TAIL LIGHT FAULT	925,023km 868,659Hr 13,850Hr Diagnose lighting fault as internal fault in rear left tail light Replace with second hand light in stock	02/17/2020
INSPECT AND CREATE DEFECT LIST AND ORDER PARTS	INSPECT AND CREATE DEFECT LIST AND ORDER PARTS	02/16/2020
main roads accreditation checklist	main roads accreditation checklist	01/26/2020
Volvo Prime Mover (E Service)	Carried out service as per sheet attached	02/08/2020
Volvo Prime Mover (B Service)	B Service	01/28/2020
Carry out WA Mainroads accreditation Road worthy Checklist	Carry out WA Mainroads accreditation Road worthy Checklist	01/26/2020
FMC - MT Data - Connection Error - Trk, PRM00426 - South West - Bulk - Goldfields Northern - 17 Mar 2020 (updated)	Check camera operation, reboot system and check adjustments. Adjust, check unit operating with FMC	07/19/2020
Repair coolant leak.	replaced coolant bypass pcpe	01/20/2020
Wash out radiator and repair air leak.	Wash out radiator and repair air leak.	01/03/2020
Replace rhs cab air bag, cab height control valve and ac blower motor.	Replace rhs cab air bag, cab height control valve and ac blower motor.	12/31/2019
Volvo Prime Mover (C Service)	Carried out C service as per sheet attached.	12/08/2019
repaired wiring to trailers	repaired wiring to trailers	11/29/2019

Gear box temperature going up too high.	Travel to truck location, hook up computer found out inactive fault code saying gear box temperature goes up to high. Found active code saying that the coolant level is to low. Add coolant to proper level but code remains active, check for coolant hoses going to the gear box if there is kink hose. Cannot find any . Delete the fault code.	11/23/2019
Volvo Prime Mover (A Service)	Carried out A service as per sheet attached.	11/15/2019
Volvo Prime Mover (B Service)	Service asset as per attached service sheet carried out by Flex industries	10/31/2019
FMC - MT Data - MDVR Recording Error - Trk, PRM00426 - South West - Bulk - Goldfields Northern - 18:00 Wed 16 Oct 19 (AWST) - Site to moderate as required	fix dss issues and mt data issues by contractor	11/27/2019
FMC - MT Data - MDVR Connection Error - Trk, PRM00426 - South West - Bulk - Goldfields Northern - 18:00 Wed 16 Oct 19 (AWST) - Site to moderate as required	fix dss issues and mt data issues by contractor	11/27/2019
Not starting, Air leak at front diff, oil leak at centre diff	Started the truck so it can be emptied before doing repairs. Replaced front diff power divider actuator, replace front diff lock diaphragm. Replaced middle diff out put yoke oil seal. find and rectify problem in starting system wiring.	10/09/2019
diff lock air leak	Removed power divider plate to fix but need seal kit	10/07/2019
repair defects as per work request attached	repair defects as per work request attached	09/30/2019
Volvo Prime Mover (B Service)	Carried out B service as per sheet attached.	09/30/2019
No start	travelled to breakdown found starter motor failed used jump wire to get going starter motor needs replacing	09/08/2019
FMC - MT Data - MDVR Hard Drive State Error - Trk, PRM00426 - South West - Bulk - Goldfields Northern - 23:00 Thu 05 Sep 19 (AWST) - Site to moderate as required	fix dss issues and mt data issues by contractor	11/27/2019
Replace pos1 & 2 steer tyres and pos4 steer	Replaced front axle wheels and 2nd axle RHS.	09/05/2019

FMC - MT Data - IR pods not active- Trk, PRM00426 - South West - Bulk - Goldfields Northern - 09:25 Wed 04 Sep 19 (AWST) - Site to moderate as required	fix dss issues and mt data issues by contractor	11/27/2019
Volvo Prime Mover (D Service)	Service asset as per attached service sheet	09/03/2019
Batteries failed and replaced	replace batteries in prime mover	08/31/2019
FMC - MT Data - MDVR Hard Drive State Error - Trk, PRM00426 - South West - Bulk - Goldfields Northern - 09:25 Mon 26 Aug 19 (AWST) - Site to moderate as required	fix dss issues and mt data issues by contractor	11/27/2019
FMC - MT Data - MDVR Recording Error - Trk, PRM00426 - South West - Bulk - Goldfields Northern - 09:25 Mon 26 Aug 19 (AWST) - Site to moderate as required	fix dss issues and mt data issues by contractor	11/27/2019
Air Leak	Find out where air leak is coming from, found that its from front diff lock hose connector. Replaced the connector.	08/25/2019
Coolant leak	travelled to breakdown found that the top hose fitted had failed. could see that the hose was for the heater system so bypassed and sent back to work tested all ok.	10/18/2019
Coolant leak	Pressure tested system and drained coolant. Hose was replaced, coolant topped up.	08/17/2019
Volvo Prime Mover (A Service)	Carried out A service as per sheet attached.	08/17/2019
FMC - MT Data - MDVR Connection Error - Trk, PRM00426 - South West - Bulk - Goldfields Northern - 10:10 Tue 13 Aug 19 (AWST) - Site to moderate as required	fix dss issues and mt data issues by contractor	11/27/2019
Volvo Prime Mover (B Service)	Carried out B service as per sheet attached	08/02/2019
Replace flex pipe	Remove old pipe and install new flex pipe	07/24/2019
replace all uni joints	Removed drive shaft and both jack shafts, cut all uni joints using oxy to be able to remove them. Replaced all uni joints then put all back again.	07/18/2019
air leak	Repaired air leak and recut end of hose	06/25/2019
reweld trun pin back on	All repairs done by drage	06/25/2019
Volvo Prime Mover (C Service)	SERVICE AS PER SHEET	06/19/2019

Volvo Prime Mover (B Service)	DONE ON C SERVICE - WO/ 101-183	06/28/2019
WR 02361 02839 07967 Documnet holder broken Front tyre on other VDR chopping out Driverside headlight globe blown	Replace doc holder and headlight	06/27/2019
WR07314 Gearbox overheats when under load	WORK DONE BY FLEX	06/12/2019
swap reman tramission and repair old tramission	Complete	06/01/2019
POS 2 brake booster airline require repositioning POS 2-4 calliper has excessive movement Uneven brake pad wear fault	Complete	06/25/2019
Oil leak at front of 2nd drive (pinion bearing cover plate gasket) Oil leak around bottom RHS of bell housing (engine oil) Engine turning tool bung missing and replace clutch	Complete	05/30/2019
RHS & LHS rear horizontal cab shockie leaking/sweating Heat shield RH rear airbag requires replacing (cab susp) Exhaust brake cylinder leaking Crack on exhaust pipe at dosing valve adapter	Complete	05/30/2019
RHS fog light n/w L/H aux high beam n/w L/H mirror light n/w Air system fault on dash R/H fire extinguisher bag torn POS 4 mudguard bracket cracked POS 9 & 10 mudflaps da	Complete	05/30/2019
W/R 2849 diss system goes on off and for no reason	CHECK WITH SUPERVISOR AND OHS OFFICER HAVE NO REPORT IN FMC MAY BE GUNK IN THE EYE	05/23/2019

VDR 2841,07310,7306,7309&2832 sunviser will stay down brake pad wear fault air system malfunction - air leak	Completed.	06/27/2019
VDR1759.7303&7313 truck wheel alignment check front end report of wheel shakasing	Completed.	06/27/2019
Volvo Prime Mover (C Service)	Work done as per WO-SGF-010-183	06/19/2019
vdr 07308 supply small jack and tools	ORDER AND SUPPLY SMALL TOOLS FOR TRUCK	04/26/2019
to remove all wheel nut indicators and re-torque all wheel nuts and refitted wheel nut indicators	RETORQUE	04/05/2019
drop off headlight globes	Grab headlight globe form workshop and drop off to parking bay along Goldfields Highway near Leinster Road.	04/02/2019
Volvo Prime Mover (B Service)	Annual service as per maintenance schedule	04/05/2019
replace front winscreen	Completed.	03/18/2019
engine cly head valve nosey	Completed.	03/18/2019
engine oil leak	call flex and they when murruy mine site and repair oil leak oil filter they found the engine cly head valve nosey tow prm510 to site swap out with prm426 and tow 426 to flex	03/15/2019
Volvo Prime Mover (B Service)	ALL WORK DONE BY FLEX	03/09/2019
head light out LS	REPLACE LH LIGHT	03/08/2019
VDR 07166	Fix by flex	03/02/2019
VDR 02817	sevrice at flex 11/12/18 shoud be completed SEE NOT ON THE VDR	12/11/2018
VDR 02829	Checked and couldn't locate ticking noise.	03/18/2019
VDR 08604	ALL DONE BY FLEX	03/01/2019
VDR 02831 02832 02826 misc repair	air dryer need servicing flex to fix at sevrice air bag malfunction flex to fix at sevrice COMPLETE	03/18/2019

FMC - DSSi fault in truck PRM00426 the fault reported = GPS detected but no signal	TEST SYSTEM FOUND ALL WORK OK USE TECH SUPPORT THEY SAD IT WORKS OK SEE MAIL	02/14/2019
supply adblue cap	Supply new adblue cap.	01/21/2019
Volvo Prime Mover (B Service)	Old WO job was done by flex	02/17/2019
spot light not working	REPLACE BLOWN FUSE FOR SPOT LIGHT	01/12/2019
Repair air leak from test port P/M	Locate test port on line - unserviceable. Remove and replace fitting.	01/08/2019
WA Mainroads Accreditation Roadworthiness Checklist	Carry out Accreditation as per paperwork	02/08/2019
Volvo Prime Mover (E Service)	EMAIL TO FLEX FLEX TO DO THE SERVICE	02/07/2019
Volvo Prime Mover (D Service)	DONE ON WO/ 008 - 593	02/07/2019
08551 - Repairs	No air leak found Air leak and the dolly repaired	12/18/2018
Replace missing fuel cap	Replace missing cap.	12/22/2018
Check over heating issue	CHECK FOR PROBLEM IN COOLNG SYSTEM. CHECK UP BELTS AND FAN HUB AND CLEAN RADIATOR	12/14/2018
02811 - TRUCK GOT TO NEARLY RED MARK ON TEMP GAUGE	- REPLACED ELECTRICAL FAN - 30/11/18 SEAL MINOR COOLANT LEAK	11/30/2018
FMC - DSSi fault in truck PRM00426 the fault reported = Camera fault detected, IR pods not active, Speaker fault detected	Remove old dash cam and replace with new	01/14/2019
B/Down - Compressor discharge pipe failure	OLD WO BY MW JOB DONE FLEX	03/01/2019
B/Down - Alternator failure	ALTERNATOR WAS REMOVED FOR 426 FLEX SUPPLY NEW ALTERNATOR	12/01/2018
Investigate and repair Electric fan failure	ALL WORK DONE BY FLEX	11/30/2018
FMC - DSSi - Camera Misaligned - Trk, PRM00426 - South West - Bulk - Goldfields - 05:46 Mon 26 Nov 18 (AWST) - Site to moderate as required	AS ABOVE	01/14/2019
Replace batteries	REMOVE OLD BATTERIES AND FIT NEW BATTERY	11/23/2018

FMC - DSSi - GPS Not Detected - Trk, PRM00426 - South West - Bulk - Goldfields - 06:00 Tue 06 Nov 18 (AWST)	DONE ON WO 008-606	02/17/2019
power steering leaks	ONE TO FIX	09/06/2018
Volvo Prime Mover (B Service)	Complete	09/07/2018
Volvo Prime Mover (C Service)	D SERVICE - FLEX	05/15/2018
Volvo Prime Mover (B Service)	B SERVICE - FLEX	07/24/2018
Call out. Alt belt broken	TRAVEL TO BREAKDOWN. FOUND BELT MISSING. CHECKED PULLEY AND BEARINGS - OK FIT NEW BELT - TEST OK	08/03/2018
Volvo Prime Mover (E Service)	E Service at 400358km	03/02/2018
Repair driving light	Removed old driving light. Fit new light. Rewire and test. All OK	06/27/2018
06493 - When unhitched from TLB00008 from set found air was still at the supply line cupping. Check cob found pork brake light is on when the truck.trailer park up I hear the brakes blow off.	still at the supply line cupping. Check cob found pork brake light is on when the truck.trailer park up I hear the brakes blow off. mark call Felx to come out and fix	05/17/2018
inspect overheating complaint	Inspect coolant level Inspected cooling system Blew out radiator cooler Suspect operator error	04/07/2018
Breakdown middle diff oil leak	Wash and inspect found diff lock switch leaking on mid diff Found bolts loose, removed and cleaned then re-sealed. Sealed threads on bolts, add 12L Volvo dif foil Just came out of Flex for diff reseal	03/31/2018
Volvo Prime Mover (B Service)	B Service	11/07/2017
Volvo Prime Mover (B Service)	B Service	09/13/2017
Truck' DSS system hasn't been reporting for the last 4 days. The truck has been used in the past two weeks, as login history has been checked.	DONE ON WO 008-606	02/17/2019
Volvo Prime Mover (B Service)	Service asset as per attached service sheet	08/15/2017
Volvo Prime Mover (B Service)	Completed Service as per service sheet Completed by Volvo	07/19/2017

Volvo Prime Mover (B Service)	Contract Maintenance service completed by Flex Industries	03/29/2017
Volvo Prime Mover (B Service)	Contract Maintenance service completed by Flex Industries	02/22/2017
Non Starter B/Down call out	Non Starter B/Down call out, Travel to break down, jump start, requires batteries replacing in Kal.	04/04/2017
WA Mainroads Accreditation Checklist	Carry out Accreditation as per paperwork attached Completed by Flex Industries	01/30/2017
Reposition turntable	Flex Industries re-positioned turntable, replaced 2 bolts as required.	05/02/2016
Supply & Fit DSS system	Done	04/21/2016
Supply & Fit DSS system	Done	04/21/2016
Supply & Fit fleet numbers	Done	04/21/2016
Fit spotlights	Fit spotlights in Kalgoorlie before commissioning	04/19/2016

