

Description	Work Done	Completed
A Service - Prime Mover	a servers completed found a exhorts leak from turbo and manifold all looks to be ok	09/29/2024
electrical faults faults	coolant temp sensor replaced exhaust temp sensor replaced fault cleared on tech tool	09/11/2024
C Service - Prime Mover	C service carried out as per survey	09/17/2024
A Service - Prime Mover	A service as per qube check list	09/07/2024
IVMS Faults	Complete new system fitted by Beau	08/05/2024
B Service - Prime Mover	B service as per qube check list	08/24/2024
A Service - Prime Mover	A service as per qube check list	08/08/2024
Check engine light up on dash Exhaust brake inefficient	completed in esperance	07/28/2024
B Service - Prime Mover	Service completed, replaced bump stops on rear suspension, replaced 1x drive shock	07/24/2024
A Service - Prime Mover	A service completed in Esperance with repairs	07/12/2024
Mainshaft & Rear Most Jack Uni Joints Replacement - Prime Mover	Shafts not changed ,monitor as required till signs of wear	07/11/2024
C Service - Prime Mover	Carry out C service, valve set, replaced diff oils, cab filters, checked air cleaners. KOTECN report:	06/28/2024
Repair A/C system	<p>Check AC system</p> <p>Run vehicle. Pipe freezing up between orifice tube and TX valve, reclaim gas, 120 grams reclaimed</p> <p>Pressure test system, was holding pressure.</p> <p>Strip dash to access evaporator with camera, evaporator oily and has green die in box</p> <p>Evaporator ordered.</p> <p>21/6 - REMOVE AND REPLACE EVAPORATOR AND DRIER, PRESSURE TEST 'OK'</p> <p>VAC DOWN, RE GAS AND PERFORMANCE TEST 'OK'</p>	06/21/2024

No tail light	<p>rotech report.</p> <p>Electrical fault  NO TAIL LIGHT DUE TO MISSING PWR SUPPLY B TO RIO-  CHASSIS MODULE.  CUSTOMER REMOVED MODULE AND CHANGED 1X FUSE  AND TERMINAL. FOUND  1 MORE CORRODED FUSE IN PWR DISTRIBUTION BOX.  REPLACED WITH NEW  TERMINAL, REASSEMBLE AND TEST - OK.  REPLACED MULTIPLE CORRODED TERMINALS, MIDI FUSES  AND SEALED IN  TERMINAL PROTECTOR IN BOX TO PREVENT FROM  FURTHER FAULTING DUE TO  HIGH SALINE ENVIRONMENT.</p> <p>(Quote attached to this work order)</p>	06/17/2024
A Service - Prime Mover	Carry out service	06/27/2024
Topset - Prime Mover	Valve set complete	06/27/2024
Diff Oil Replacement - Prime Mover		06/28/2024
B Service - Prime Mover		06/28/2024
IVMS Faults	Needs further investigation	07/02/2024
A Service - Prime Mover	A service as per qube check list	05/29/2024
B Service - Prime Mover	Carry out service as per service sheet	05/17/2024
A Service - Prime Mover	Carry out service as per service sheet	05/08/2024
MT Data not working	Will need further investigation	07/02/2024
C Service - Prime Mover	Carry out service as per service sheet.	04/21/2024
Air Dryer Filter Replacement - Prime Mover	Remove and replace air drier and recalibrate	04/21/2024
window wiper fault	Remove and replace wiper stalk. all ok at time off test	04/21/2024
Corrective maintenance	Rectified stretch guard. Re tightened stretch guard pole. Remove and replace wiper stalk. Replace Exhaust brake actuator. Replace cooling ring bolts as per missing. Rectified exhaust brake arm bush. all work completed	05/13/2024
A Service - Prime Mover	Carry out service as per service sheet.	04/07/2024

using coolant	Esperance completed	03/20/2024
Radiator Inspection and Clean - Prime Mover	Radiator removed bottom of radiator leaking Intercooler pressure tested found 3 major leaks Ordered intercooler from kip and Steve's	03/26/2024
B Service - Prime Mover	Service complete Coolant leak on radiator	03/26/2024
A Service - Prime Mover	Carry out service as per service sheet.	03/12/2024
seat u/s	repaired seat back rest	05/26/2024
A Service - Prime Mover	Carry out service as per service sheet.	03/12/2024
AD blue faults	replaced ad blue harness	02/20/2024
B Service - Prime Mover	Carry out service as per service sheet	02/24/2024
corrective maintenance	Found top radiator hose to be burst removed and replaced. All ok at time of test	02/05/2024
corrective maintenance	Coolant rectified replaced seal in header tank cap. Resecured rear number plate. Rectified brake light. Rectified head light. Door card parts fitted. Fire Extinguisher is in date.	03/13/2024
A Service - Prime Mover	Carry out service as per service sheet.	02/07/2024
IVMS Faults	check rec state check cameras not faults found monitor	02/17/2024
IVMS Faults		07/02/2024
work order defects	Drivers side mirror fitted. Trailers not fitted with ebs so not required as off road trailers. Hydraulic tank secured.	02/07/2024
A Service - Prime Mover	Carry out service as per service sheet	01/25/2024
C Service - Prime Mover	C service carried out as per qube check list	01/28/2024
Remove and replace,Ad Blu pump, dosage valve and NOX sensor.	Checked vehicle found ad blue pump to have an internal short, also found dosage valve to have an internal short and leaking, found wiring harness connector to be damaged, resecured cleared all faults, performed ad blue pump pressure test all ok. Carried out test drive no faults present.	01/15/2024

EWR 0517	Check air leak, drove truck onto pit built up air found air tank drain to be leaking. Rectified fault. All ok at time of test	12/19/2023
Replace inner Air Filter	Remove and replace inner air filter	02/07/2024
Visual inspection	Carry out visual inspection of asset as per request.	12/16/2023
A Service - Prime Mover	completed with B Service	12/12/2023
B Service - Prime Mover	completed service survey	12/12/2023
A Service	Carry out A service as per service sheet	12/06/2023
EWR1108 - Air Conditioning not blowing cold Air	out sourced by rotech	01/29/2024
Transmission not engaging gear	repaired transmission	01/28/2024
B Service - Prime Mover	carry out service as per request	11/17/2023
A Service - Prime Mover	carry out a service as per request	11/03/2023
Supply and fit new Windscreen	Supply and fit new Windscreen	01/08/2024
Fit Turntable and ballrace assy	Turntable no longer required due to different task. Turntable has been credited back to Qube.	02/07/2024
Broken LH mirror	Remove and replace broken LH mirror	11/10/2023
Emission Derate	Check DTC, NOX sensor not available. Repair wiring and retest OK	11/10/2023
No trailer lights	Replace trailer plug	11/01/2023
A Service - Prime Mover	Completed on WO-FNO-000-007	11/03/2023
IVMS Faults	All ok time of test	11/21/2023
Tarp buttons faulty	Check and rectify tarp buttons, found to have been pushed back through dash console. removed dash reinserted control switch bank. tested all ok.	11/04/2023
Cabin Filter	Remove and replace internal and external cabin filters.	11/03/2023
A Service	Carry out A Service	11/03/2023
Replace Starter Motor	Locate and fit replacement starter	10/29/2023
check over	Check over before going to site, fit intake pipe ect ordered during last service	10/24/2023
Replace APM	Replaced apm	09/12/2023
IVMS Faults	Tested system tracked and checked OK	11/10/2023
Check clearance light fault and replace fuel pickup	Replaced injector tubes and filter head	08/29/2023

Isolator broken	carried out by Rotech  isolator broken remove old isolator fit new isolator re-fit lockable bracket as mounting bolts caused old isolator to fail fit new lever as was previously broken trying to turn isolator that didn't turn test "good"	06/29/2023
Prime Mover - B Service	Service as per schedule Needs lower rear eye bushes in leaf springs Projector light faults	08/21/2023
Low Power	Clean supply and return lines ,blow out all filter housing lines ,check tank contamination,fault trace through tech tool,test drive .	05/15/2023
<del>FMIC - IMI Data - MDVR Not Reporting - PRIM00451 - SWI - QB Esperance - 07:27 Fri 21 Apr 23 (AWST)</del>	No issue found	06/21/2023
11648 - Truck down on Power	COMPLETED BY KIP&STEVES  LOW FUEL PRESSURE - BLOCKAGE IN FUEL LINE TO FILTER. CONNECT LAPTOP AND CHECK FAULT CODES, REMOVE FUEL LINE TO FILTER HEAD, FOUND BLOCKAGE IN NON RETURN VALVE, CLEAN VALVE IN PIPE, REFIT PIPE TO TRUCK, DELETE FAULT CODES AND TEST DRIVE. TRUCK IS GETTING 100% FUEL DELIVERY PRESSURE NOW	03/29/2023
Fire Extinguisher out of Date	Replace fire extinguisher and repair clamp and bracket	05/25/2023
6 Monthly Radiator Clean	Radiator clean completed by Kip and Steve's 24.03.2023	03/24/2023
Belt Tensioner Replacement	Supply and fit fan belt, tensioner and idler. Supply and fit alt belt and tensioner	11/17/2023
Prime Mover - B Service	Service carried out by Kip&Steves  1209583 KM	03/24/2023

FMC - MT Data - MDVR Channel State Error - PRM00451 - SWT - QB Esperance - 12:00 Fri 24 Feb 23 (AWST)	Inspected, no fault found	03/21/2023
FMC - MT Data - MDVR Channel State Error - PRM00451 - SWT - QB Esperance - 14:32 Tue 17 Jan 23 (AWST)	Inspected vehicle found fault in Passenger side camera. Replaced as required and ran new harness. Tested all ok.	02/16/2023
Prime Mover - B Service	Service completed	01/12/2023
Power divider not working Steering wheel trim loose	Tighten mount screws ,replace power divider diaphragm front drive axle	01/12/2023
WA Mainroads Accreditation Roadworthiness Checklist	Carried out Roadworthiness Checklist	12/20/2022
Prime Mover - B Service	Service completed replaced fuel hose from head to fuel pump	12/07/2022
Low fuel pressure	Travel to BD replace primary fuel filter ,tighten fuel stalk ,clean up spill ,travel home	11/14/2022
Air Con doesn't work	Has been sent to rote house and repaired	11/08/2022
Low oil pressure	Replaced oil filters Rear oil filter seal was broken and leaking oil Topped oil up 14 litres	11/03/2022
Prime Mover - B Service		10/31/2022
KL611644 - Hole in Exhaust, Low Fuel Pressure Alert on Dash	Replace HP fuel pump ,replace fuel filter housing	12/09/2022
Prime Mover - C Service	Service completed	03/01/2023
Clutch Fault	CARRIED OUT BY KIP&STEVES CLUTCH FAULT - CLUTCH ACTUATOR FAULTY. REMOVE GEARBOX, CHANGE CLUTCH ACTUATOR BRAKE SEALS, GEARBOX INPUT SHAFT SEAL, OIL COOLER COOLANT HOSE, AIR PIPE, CRANKSHAFT SEAL AND FLYWHEEL. REPLACE REAR ENGINE MOUNTS. PUT GEARBOX BACK IN TRUCK, FILL WITH COOLANT, CALIBRATE CLUTCH, DELETE FAULT CODES AND CHECK AFTER TEST DRIVE	10/04/2022
Spot lights not working	Fixed electrical fault	09/13/2022
Spot lights not working	Fixed electrical fault	09/14/2022
Replace 3x v stays	Replace v stays	09/05/2022

KL11643 - No Level Control, Truck Brake Malfunction, Trailer Park Brake	Replace rear chassis harness	09/05/2022
KL11641 - Tarp Switches pushing into Dash	Remove dash,repair switches	09/07/2022
Prime Mover - C Service	Serviced	09/01/2022
Replace Air Bags & Diagnostic Plug	Replace airbags and diagnostic plug	09/06/2022
KL11640 - No Spill Kit		10/05/2022
KL11640 - Steering Wheel Air Bag not fitted properly	Check air bag fittment	09/05/2022
KL11639-Fuel Pressure Low Message	No issue found	09/05/2022
6 Monthly Radiator Clean	Radiator Exchange carried out by Kip&Steves INV. 00087204	08/08/2022
Volvo Prime Mover (B Service)	Service ,new head light	08/05/2022
Belt Tensioner Replacement	Replace belts and tensioners	09/05/2022
FMC - MT Data - MDVR Channel State Error - PRM00451 - SWT - QB Esperance - 18:50 Sat 09 Jul 22 (AWST)	Enter dss system with screen check all working all ok no problems. Check with main office all ok no problems.	08/08/2022
Auto ride height fault	Replaced rciom harness	07/15/2022
Volvo Prime Mover (B Service)	Complete service	07/06/2022
Replace Batteries	Replace 2x n200 batteries	06/01/2022
Volvo Prime Mover (C Service)	Service and repairs	06/01/2022
Carry out all Volvo Updates	CARRY OUT ALL REQUIRED SOFTWARE UPSATES  CARRIED OUT BY KIP&STEVES INV 85962 1129879 km	05/10/2022
Air leak		05/11/2022
ESP 2565 - FRIDGE BROKEN	FRIDGE WAS REPLACED  1127732 KMS	04/27/2022
ESP 2564 - CAB JACK HOSE	REPLACE CAB JACK HOSE  LH CAB JACK HOSE	04/26/2022
ESP 2606 - FOOT PEDAL FAULT	- DIAG FOOT PEDAL FAULT - SWAP PEDAL TO GET TRUCK GOING  1122978 KMS	04/14/2022

ESP 2559 - POWER STEERING LEAK BOOST LEAK REAR CAB SHOCK	REPLACE BOOST HOSE REPLACE POWER STEERING PRESSURE HOSE SUCTION HOSE REPLACE REAR CAB SHOCK  1116063 KMS	04/08/2022
FMC - MT Data - MDVR Channel State Error - PRM00451 - SWT - QB Esperance - 07:37 Thu 31 Mar 22 (AWST)	INTERNAL ISSUE WITH MT DATA NO FAULTS FOUND	04/21/2022
ESP 2603 - AIR LEAK	- AIR BAGS NO STAYING UP - DIFFICULTY LOADING BECAUSE OF WEIGHT SHIFT - ORGANISE JOB WITH FLEX 1110708 KMS	03/29/2022
11633 - Buttons on steering wheel need to be replaced	REPLACE BUTTONS ON STEERING WHEEL  1127728 KMS  LH BUTTON ASSEMBLY	04/21/2022
11129 - Wheel bearing Failure		06/01/2022
FRIDGE NOT WORKING	AS PER WORK PLAN.  1093845 KMS	02/21/2022
Carry out Uni Joint Replacement	AS PER WORK PLAN ABOVE  1093845 KMS	03/02/2022
Volvo Prime Mover (B Service)	AS PER INVOICE 84925 SERVICE  1116063 KMS  40L ENG OIL AD BLUE FILTER, FILTER KIT CABIN FILTERS 2X AIR DRYER	04/08/2022

Air Con Issues	checked pressure with gauges - "OK" plugged into with cando - P064515 - A/C clutch relay control circuit, code active put power to ac clutch, didnt engage. recover gas from system. supply and replace compressor. replaced drier. pressure test system - "OK" vac and gas - "OK"	03/13/2022
11024 - CHANGED HEADER TANK CHANGED 4 X HYDRAULIC TANK LASHES FIXED PTO SIGNAL LINE	11024 - CHANGED HEADER TANK CHANGED 4 X HYDRAULIC TANK LASHES FIXED PTO SIGNAL LINE  1069298 KMS 18569 HRS	01/17/2022
Volvo Prime Mover (C Service)	Service as above	01/14/2022
Belt Tensioner Replacement	Replaced Tensioner, Replaced Belts, Replaced idler pulley	01/14/2022
6 Monthly Radiator Clean	COMPLETED BY FLEX INDUSTRIES, WITH INTERCOOLER.  1069298 KMS	01/17/2022
Carry out Turbo Replacement	REPLACED TURBO IN KAMBALDA  1063335 KMS	01/01/2022
Spinner/Breather Hi Oil Consumption	FLEX REPLACED SPINNER BREATHERS  1063335 KMS	01/02/2022

Turbo Replacement	<p>CALL TO UNIT INSPECT FOUND SEALS IN TURBO LEAKING, ALLOWING OIL INTO AIR INTAKE SYSTEM. REMOVED INTAKE PIPE OFF TURBO AND CHECKED PLAY IN SHAFT, SMALL MOVEMENT.</p> <p>REMOVED CCV AND SPUN MANUALLY TO ENSURE NO FAULT, REMOVE AND REPLACE TURBO WITH NEW AND FILLED ENGINE OIL</p> <p>1062460 KMS 18460 HRS</p> <p>TURBO RETURN GSK, TURBO DRAIN SEAL, CONNECTOR, TURBO BASE GASKET, CCV GASKET, TURBO FEED GASKET, EXCH TURBO 16L</p>	01/19/2022
Repairs and Maintenance		06/01/2022
11445 - ENG DE RATING	<p>REPLACE BOOST PRESSURE SENSOR</p> <p>1060811 KMS</p>	12/27/2021
Volvo Prime Mover (B Service)	<p>COMPLETE B SERVICE</p> <p>1318835.40 KMS</p> <ul style="list-style-type: none"> <li>- 40L 15W40</li> <li>- FILTER KIT</li> <li>- ZIP TIES</li> <li>- GREASE</li> </ul>	12/04/2021
Dropped Booster	<p>DRIVE TO TRUCK</p> <p>REPLACE BOOSTER</p> <p>PARTS USED:</p> <p>1X BOOSTER</p> <p>1037685 KM</p>	11/21/2021
Dropped Booster	<p>REPLACE BOOSTER DRIVE TO FRASER RANGE</p> <p>1037685 KMS</p> <p>1 X BOOSTER</p>	11/21/2021

KLG 11607 - HYDRAULIC OIL LEAK FROM COUPLING - RHS SUPPORT 3 OR FOR RUBBER GUARD MISSING	KLG 11607 - HYDRAULIC OIL LEAK FROM COUPLING - RHS SUPPORT 3 OR FOR RUBBER GUARD MISSING  S.G REPLACED SEAL KIT IN HYD COUPLING  1027098 KMS	10/26/2021
Tipping Fault	DIGG ISSUE "MODED TO MAKE WORK"  1,025,576 KMS ROPE	10/25/2021
Replace Fan/Coolant Ring and Brake Components	AS ABOVE  1,030,204 KMS	11/02/2021
Volvo Prime Mover (B Service)	AS PER INVOICE 83289 AS WORK PLAN ABOVE  1030204 KMS	11/01/2021
11004 - Fit new 9kg fire extinguisher bracket	AS PER INVOICE 83265  Fit new 9kg fire extinguisher bracket	10/20/2021
Fire Extinguisher Bracket repair and install	Replace fire extinguisher bracket on truck 9kg  1,021,848 km  Part 9kg fire extinguisher bracket 4x M10 bolts, nuts, moslers	10/21/2021
Diagnose and Repair Throttle Issue	DIGG / REPAIR  1019135 KMS  1 X THROTTLE PEDAL	10/12/2021

Fit Bullbar	Fit bull bar to truck Hook up lights  1006452 Km  Parts used: Zip ties Grease	09/15/2021
replace cylinder head	As per invoice 82493 and work plan above  1,006,476	09/10/2021
Headlights	REPLACED HEADLIGHTS  1006452KMS  1xleft headlight 1x right headlight cable ties	09/08/2021
Volvo Prime Mover (C Service)	C Service, LH Rear say bar 4 removed rocker assembly and put it back on  1006452  Service Kit Engine oil Diff oil Trans oil	09/09/2021
replace drivers seat belt	1011051 SEAT BELT REPLACED	09/20/2021
Diff lock light	Diagnose flashing diff lock symbol Adjust sensor contact Replace rear diff locker sensor  1,000,767 km  Parts Diff lock switch sensor 1x Thread sealant	09/06/2021

as work request	Remove and replace sun visor Remove and replace coolant hoses to air comp  1,000,767 kms  Parts 1x feed coolant line to air comp 1x return coolant line to air comp 1x sun visor (reuse coolant)	09/03/2021
exhaust leak	replace exhaust brake valve  reading 1000767	08/30/2021
air con	Replace cab blower fan  1,000,767 kms  parts Blower fan	09/02/2021
coolant leak	Diagnose/locate coolant leak remove, replace expansion tank refill coolant, wash & test  reading: 1000767	08/30/2021
Multiple Repairs	Replace header tank and refill Replace exhaust brake Replace starter motor Repair air leak  1,000,767 km  Parts Exhaust brake Starter motor Expansion tank Coolant Cable ties	08/30/2021

Exhaust manifold repair	Remove and replae exhaust manifold  1,000,767 kms  Parts EXH manifold Gaskets Studs/bolts Replace headlight groves	08/28/2021
Headlight Globes Non-functional + Other faults	Set pre load on Ex Brake Diagnose lights issue Diagnose Ex leak Diagnose compressor malfunction  990895 Km  Parts used: Turbo manifold gasket New air drier <del>2x HL 34w 40w globes</del>	08/16/2021
10919 - COOLANT LEAK	REPLACED THERMOSTAT DRAW DOWN PIPE  967666 KM	07/11/2021
10918 - DROPPED AIR, NO START	TRAVEL TO JOB, SORT OUT AIR LEAK GET COMPRESSOR TO CHARGE AIR TANKS START TRUCK, FOUND EXHAUST LEAK GET TRUCK MOVING, FOLLOW TO YARD VALVE TEST BOLT ON CLAMP  965072 KM	07/08/2021

<p>Volvo Prime Mover (B Service)</p>	<p>Service asset Coolant leak from heater hose Needs air dryer Air compressor leaking oil from head Head lights not dipping Uneven brake wear Replaced dip stick</p> <p>984,543 kms</p> <p>Parts Filter kit Adblue filter 2x cabin filters 40L engine oil Grease Replace batteries</p>	<p>07/28/2021</p>
<p>Hard starting</p>	<p>970,928 km</p> <p>Parts 2x batteries</p>	<p>07/13/2021</p>
<p>Exhaust manifold Replacement</p>	<p>Replace exhaust manifold</p> <p>960,176 km</p> <p>Part Exhaust manifold Exhaust brake actuator 24x exhaust manifold bolts and spacers 4x exhaust manifold to turbo bolts and spacer</p>	<p>06/17/2021</p>

Volvo Prime Mover (B Service)	<p>Complete service Output on gearbox has little movement</p> <p>960,176 kms</p> <p>Parts 40L engine oil Filter kit Adblue filter</p>	06/17/2021
After hours breakdown , electrical charging system fault	carried out by flex industries replaced damaged wiring harness to alternator	06/09/2021
Volvo Prime Mover (C Service)	<p>As per work plan</p> <p>940,746 kms</p>	05/22/2021
Volvo Prime Mover (B Service)	<p>B Service Replaced right hand side side cab air bag</p> <p>925,910 km</p> <p>Parts 1x filter kit 1x adblu filter</p>	04/30/2021
Windscreen Wiper non-functional	<p>Remove and repiace the wind screen wiper mechanical assembly Test all - okay</p> <p>889,125 km</p> <p>Parts Wiper motor + bracket assembly Zip ties Grease</p>	04/12/2021
Replacing Windscreen	<p>906934 KM</p> <p>COMPLETED BY ESPERANCE SMASH REPAIRS</p>	03/30/2021

REPLACE ISOLATOR SWITCH	REPLACED ISOLATOR SWITCH  PARTS USED: NEW ISOLATOR ISOLATOR LOCK OUT KIT  906726 KM	03/25/2021
Volvo Prime Mover (B Service)	Service as per attached service sneets  906726 Km  Parts used: 40L Engine oil 1x Filter kit 1x Adblue Filter 1x in line adblue Filter Cable ties Grease	03/25/2021
FMC - DSSi - Camera Misaligned - PRM00451 - South West Bulk - Esperance - 08:21 Sat 27 Feb 21 (AWST)	Assess camera position and adjust  989,272 kms	03/09/2021
0622 - A/C BLOWING HOT AIR	COMPLETED	02/09/2021
Volvo Prime Mover (C Service)	Carry out service as per work plan  882708 km	01/11/2021
Fit Mt Data Rear facing side mounted cameras	Fit rear facing external cameras and 1x TBSSD  898,280 kms  Parts 2x cameras 1x TBSSD	03/11/2021

REPLACE ALTERNATOR	<p>15026 hr</p> <p>Test alternator charge rate and fault  Found issue with batteries supply and install new batteries  New charge fault detected  Replace alternator (Qube supplied)  Test - ok  Next day follow up check  Find loose starter lead, tighten and test - ok  Replace blown globe</p> <p>Parts used:  Qube supplied alternator  Rotech supplied 2x 8D-1300RHD and 1x GE585214</p>	12/10/2020
Volvo Prime Mover (B Service)	B service complete	11/13/2020
2015314 - A/C NOT WORKING, PLEASE FIX	carried out by rotech	10/07/2020
FMC - MT Data - MDVR Hard Drive State Error - Trk, PRM00451 - South West - Bulk - Esperance - 5 Nov 20	Reformat card 854694	11/11/2020
FMC - MT Data - MDVR Recording Error - Trk, PRM00451 - South West - Bulk - Esperance - 5 Nov 2020	Reformat card 854694	11/11/2020
FMC - MT Data - MDVR Channel State Error - Trk, PRM00451 - South West - Bulk - Esperance - 5 Nov 2020	Removed card 854694	11/11/2020
OIL LEAK	<p>DIAGNOSE LEAK</p> <p>851515 KM</p> <p>PARTS USED:  FUEL RETURN LINE</p>	10/31/2020
FMC - MT Data - MT Data GPS Error - PRM00450 - South West - Bulk - Esperance - 27 October 2020	Reformat card 854694	11/11/2020

R&R RADIATOR	replaced radiator pressure test and clean intercooler Clean trans cooler  849968 Km  Parts used: 43 L VCS Coolant	10/27/2020
DIFF FAILURE	Remove diff with recon and replaced through shaft  849,739km  Parts 1x recon diff 1x through shaft	10/19/2020
A/C NOT WORKING	Cab fan replace  847552km  Parts Used 1x cab fan	10/09/2020
FMC - MT Data - MT Data GPS Error - PRM00450 - South West - Bulk - Esperance - 10 October 2020	Works fine  847,532km	10/05/2020
400,000km Volvo Turbo Change Out	REPLACED TURBO  843596 KM  PARTS USED: 1X TURBO AND GASKET KIT	10/01/2020
800,000 Volvo Wheel Bearing & Engine Main Bearing Replacement	Complete as per work plan  838,065km	09/25/2020
Volvo Prime Mover (B Service)	as per service sheets  838,065km	09/22/2020
REPAIR BOOST LEAK	Found intercooler hose leaking	08/26/2020
0619 - HYD OIL LEAK - PTO, BEHIND TRAILER 2	0619 - HYD OIL LEAK - PTO, BEHIND TRAILER 2 - DONE	07/26/2020

REPLACE WASHER LEVEL SENSOR, AV VALVE & FIT AIR DRYER MUFFLER	Complete all of work plan	08/13/2020
Volvo Prime Mover (C Service)	SERVICE  TRANS FILTER POWER STEERING FILTER AD BLUE IN LINE FILTER 20L TRANSMAX MANUAL 40 75L SYNTRAX UNIVERSAL PLUG 75 WORLD	08/07/2020
24162 - PTO LEAK	DRIVE TO KAMBALA - CHECK OVER HYD LEAK AT PTO, RESEALED PLUG-ON SIDE BUT BACK CASING IS LEAKING. PTO NEEDS REPLACING	08/06/2020
oil leaks	Replaced PTO pump and oil cooler lines	08/07/2020
23992 - STARTER MOTOR U/S CHECK AIR LEAKS	REPLACED STARTER MOTOR REPAIRED AIR LEAK	07/19/2020
Volvo Prime Mover (B Service)	B Service, serviced asset as per attached service sheet	08/07/2020
Volvo Prime Mover (B Service)	complete B service	07/17/2020
REPLACE DRIVE TYRES, WINDSCREEN WIPER BROKEN, CHECK A/C AND CLEAN	Tyres good Wipes replace and motor/linkags all fine and disinfected	06/02/2020
Volvo Prime Mover (B Service)	B Service complete	06/02/2020
10622 - AIR LEAK	FOUND FAULTY AIRLINE, REPLACED WITH NEW FITTINGS AND HOSE	05/25/2020
0616 - WORN DRIVE TYRES - WHEEL SLIP BROKEN LHS WIPER ARM	ALL WORK COMPLETED	05/25/2020
lights fault	Diagnosed and repaired lights fault	08/07/2020
FMC - MT Data - MDVR Camera Connection Error - PRM00451 - South West - Bulk - Esperance - 10:48 Fri 17 Apr 20 (AWST)	ASSES FAULT AND REPLACE PARTS IF REQUIRED FOUND CAMERA 2 TO BE FAULTY REPLACED AND TESTED - ALL OK	04/29/2020
Volvo Prime Mover (C Service)	SERVICE AS PER SHEET	04/14/2020
FMC - MT Data - MDVR Channel State Error - Trk, PRM00451 - South West - Bulk - Esperance - 10 APR 2020	ASSESS FAULT REPLACE PARTS IF REQUIRED FOUND CAMERA 2 TO BE FAULTY. REPLACED AND TESTED - ALL OK	04/29/2020
Volvo Prime Mover (B Service)	B Service	03/20/2020

engine temp hot	Work carried out as work plan	01/31/2020
HAND BRAKE/DOOR ALARM	BRAKE ALARM WORKING	04/14/2020
10462 - Fixed lighting plug on truck	Fixed lighting plug on truck	01/17/2020
Volvo Prime Mover (B Service)	SERVICED AS PER SHEETS	01/19/2020
0612 - Aircon needs attention, not cool enough	Repaired air con	01/05/2020
REPLACE ALL DRIVE LINE UNIS	As per work plan complete	12/24/2019
Volvo Prime Mover (C Service)	Service New isolation switch	12/06/2019
Volvo Prime Mover (B Service)	complete as per WO-ESP-002-642 - used those service sheet	12/06/2019
0608 - Air leak left hand side back axle of airbag air line leaking	Complete as per above	10/17/2019
Volvo Prime Mover (B Service)	Service asset Cracked manifold Leaky cab lock in mech	11/01/2019
Volvo Prime Mover (C Service)	C Service Exhaust manifold cracked Right hand cab air bag leaking Header tank level sensor and plug damaged	10/04/2019
FMC - MT Data - MDVR Hard Drive State Error - Trk, PRM00451 - South West - Bulk - Esperance - 09:57 24 Sep 19(AWST)	all completed by Esperance communications all cameras fixed on site October all cameras repaired	10/03/2019
FMC - MT Data - MDVR Connection Error - Trk, PRM00451 - South West - Bulk - Esperance - 09:57 24 Sep 19 (AWST)	all completed by Esperance communications all cameras fixed on site October all cameras repaired	10/03/2019
FIT OUT TARP SWITCHES	Complete as per plan, done by Rotech electrical	09/17/2019
Volvo Prime Mover (B Service)	Service asset	09/05/2019
0605 - Left hand indicator not working on trailer, prime mover leaking water front of motor, cracked windscreen	Complete	08/08/2019
0604 - Windscreen cracked, MTData holder missing	Complete repairs	07/31/2019
Volvo Prime Mover (B Service)	Service Fit heater hoses as metal pipe were split	08/06/2019
10477 - Coolant leak	Found broken radiator hose, replace with new	07/04/2019
Volvo Prime Mover (C Service)	Complete	07/23/2019

FMC - DSSi - Facial Features Obscured - Trk, PRM00451 - South West - Bulk - Esperance - 01:00 Fri 12 Jul 19 (AWST) - Site to moderate as required	No fault found	07/23/2019
0656 - BATTERIES DEAD - PLEASE REPLACE TRUCK IS LOCATED ABOUT 4-5 KMS INTO NOVA HAUL RD PUNGARN RD KEYS LOCATED UNDERNEATH DRIVERS TOOL BOX BEHIND TRUCK CAB	BATTERIES DEAD - PLEASE REPLACE TRUCK IS LOCATED ABOUT 4-5 KMS INTO NOVA HAUL RD PUNGARN RD KEYS LOCATED UNDERNEATH DRIVERS TOOL BOX BEHIND TRUCK CAB	05/31/2019
0503 - DERATE ENGINE LIGHT ON AD BLUE LEAK EXHAUST CLAMP TO MUFFLER BROKE OFF	DERATE ENGINE LIGHT ON AD BLUE LEAK EXHAUST CLAMP TO MUFFLER BROKE OFF	06/04/2019
TAIL LIGHTS	REPLACED REAR TAIL LIGHTS AND INSTALLED NEW NUMBER PLATE LIGHT	06/18/2019
spotlights out	Found spotlight unserviceable. Replace with new pair.	06/10/2019
Volvo Prime Mover (B Service)	SERVICE AND CHECK OVER TRUCK AS PER SERVICE SHEET	06/07/2019
Volvo Prime Mover (B Service)	B Service	05/10/2019
truck wont start	replaced starter motor and ordered replacement baterys incase required	04/14/2020
Volvo Prime Mover (E Service)	e service	04/16/2019
Volvo Prime Mover (B Service)	FOUND MISSING DRIVE SHAFT BOLT RE-TORQUED REPLACEMENT R/H HEADLIGHT ASSEMBLY	03/22/2019
FAN STUCK ON	REMOVE AND REPLACE FAN AND HUB ASSEMBLY	03/07/2019
Volvo Prime Mover (C Service)	C Service Replaced turntable horse shoe	03/07/2019
Volvo Prime Mover (B Service)	Serviced by Kip & Steve	02/25/2019
0322 - Right hand steer tyre damaged, fault comes up for headlight	Complete	01/15/2019
FMC - MT Data - MDVR Channel State Error - Trk, PRM00451 - South West - Bulk - Esperance - 09:57 Sun 10 Feb 19 (AWST)	Complete as per receipt	03/12/2019
Volvo Prime Mover (B Service)	Serviced	02/25/2019
0317 - PTO switch does not stay on	complete	01/07/2019

FMC - DSSi fault in truck PRM00451 the fault reported = Camera Misaligned	Re-adjust camera test ok Rescrewed so camera don't move again	03/07/2019
a/c not working	ROTECH DRIVE TO NORSEMAN TO REPLACE AC FAN MOTOR AND RETURN TO ESPERANCE PARTS BOUGHT OUT OF BUNBURY BY ROTECH \$200 CALL OUT FEE \$67.73 RESISTOR \$416.88 FAN MOTOR PLUS ROTECH CHARGE TO NOSEMAN AND RETURN	12/27/2018
Volvo Prime Mover (C Service)	C Service Replace wiper blades Secure rubbing hoses and wiring Replace right hand headlight globe	01/10/2019
Replace cylinder head, choofing sound coming from exhaust	REPLACED CYLINDER HEAD KIP AND STEVES	12/08/2018
De-rate fault - Kalgoorlie	REMOVED AD BLUE HOSES RUN CLEAN WATER REFIT HOSES ETC START UP AND TEST PUMP NOT WORKING FLEX CHECK WITH LAPTOP FOUND PUMP U/S C/O PUMP - ALL OK	11/26/2018
Volvo Prime Mover (B Service)	B Service	12/20/2018
Repair headlight, air dryer and fuel filter fuel fault	complete	11/13/2018
Volvo Prime Mover (B Service)	B SERVICE	11/15/2018
Replace muffler	Muffler replaced by Kip & Steves	11/27/2018
Replace blown turbo	COMPLETE	11/13/2018
0223 - Power steering hose leaking and howling	Complete	10/26/2018
Volvo Prime Mover (B Service)	Service	11/01/2018
Replace Evaporator	Complete by Rotech	05/07/2018
Volvo Prime Mover (D Service)	As per service sheets	10/18/2018
Volvo Prime Mover (B Service)	As per service sheets	09/13/2018
FMC - MT Data - MT Data Camera Not Operational - Trk, PRM00451 - South West - Bulk - Esperance - 10:11 Mon 03 Sep 18 (AWST)	Completed.	07/10/2018

0163 - Windscreen cracked from top to bottom	Replaced windscreen.	10/09/2018
Volvo Prime Mover (C Service)	C Service	08/22/2018
Volvo Prime Mover (B Service)	As per service sheets	08/22/2018
FMC - DSSi fault in truck PRM00451 the fault reported = Unit not reporting, for 192 day/s	Completed.	08/09/2018
04681 - C/O NEW STARTER MOTOR	TRAVEL TO SITE, CHECK BATTERY, FOUND ONE U/S C/O BATTERY BUT STILL NOT STARTING - JUMP START START ENGINE - UNHOOK - DRIVE BACK TO KAL C/O NEW STARTER MOTOR	07/30/2018
FMC - DSSi fault in truck PRM00451 the fault reported = Unit not reporting, for 177 day/s	Swapped out unit	11/09/2018
Volvo Prime Mover (D Service)	D Serviced Remove and repair left hand side high beam Fit 6mm joiner air line left hand side rear	07/24/2018
Volvo Prime Mover (B Service)	20,000km Service Right hand horizontal cab shocky leaking Left hand rear clearance lights Air leak repaired	06/27/2018
Volvo Prime Mover (B Service)	20,000km Service Right hand horizontal cab shock leaking Adblue injector leaking around injector A/C filter blocked POS 3 brake lining sensor Fan short 255 times new fan ordered	06/11/2018
FMC - DSSi fault in truck PRM00451 the fault reported = Unit not reporting, for 133 day/s	Swapped out unit	11/09/2018
Volvo Prime Mover (C Service)	Volvo Prime Mover (C Service)	05/23/2018
Coolant Leak	Deliver Truck to TCWA Kewdale for Warranty Repair. Cooling Pack Replaced. - trans cooler Truck brought back to Chandala Hook up Tronox SET01	05/16/2018
Volvo Prime Mover (A Service)	Volvo Prime Mover (A Service)	05/14/2018
Volvo Prime Mover (B Service)	Volvo Prime Mover (B Service)	05/01/2018
09221 - Exhaust leak	Replace gasket and base muffler	04/20/2018

09221 - EXHAUST LEAK.	09221 - EXHAUST LEAK. REPLACED GASKET AT BASE OF MUFFLER.	04/20/2018
DSS system not reporting 83 days  FMC - DSS - Vehicle Not Reporting - Truck, PRM00451 - South West (Region) - South West Transport Chandala (SCRIMS) -Rockingham (MT Data Fleet) - 12:00 Sun 22 Apr 18	DSS system not reporting - System Tested and working	05/23/2018
Replace, regroove + rotate tyres as required	5 X TYRES FITTED BY SLIMS TYRE SERVICE.	04/09/2018
09178 - DIFF LEAK	HAYDEN - DROVE TO MINE - CLEANED BREATHER AND FILLED OIL  GRANT - ORGANISED PARTS AND VOLVO WARRANTY REPAIR	03/29/2018
Volvo Prime Mover (A Service)	Volvo Prime Mover (A Service)	04/04/2018
Volvo Prime Mover (E Service)	Volvo Prime Mover (E Service)	03/21/2018
Replace, regroove + rotate tyres as required	2 X TYRES REPLACED BY SLIMS TYRES.	03/09/2018
Steer & Drive Tyres	Replace Steer Tyres. Replace 1st & 2nd Drive Axle Tyres.	03/07/2018
In cabin MDVR camera from MTData is not functioning. Unable to perform an Audit.	In cabin MDVR camera from MTData is not functioning	03/08/2018
Volvo Prime Mover (A Service)	Volvo Prime Mover (A Service)	03/08/2018
Volvo Prime Mover (B Service)	Volvo Prime Mover (B Service)	02/21/2018
09074 - Hook up trailers	Unhook PRM000324 then hook up PRM00451 to Tronox Set01	02/08/2018
Volvo Prime Mover (A Service)	Volvo Prime Mover (A Service)	02/08/2018
09033 - CAB air bag leaking.	Replace right rear CAB air bag.	01/23/2018
Volvo Prime Mover (D Service)	Volvo Prime Mover (D Service)	01/23/2018
08982 - 1st axle drive tyres unserviceable	Replace all 4 tyres on 1st drive axle	01/09/2018
08946 - brake failure on dash	Hook up laptop and check all fault codes Test all brake systems and calibrate	12/27/2017
Volvo Prime Mover (A Service)	Volvo Prime Mover (A Service)	01/09/2018
Brake pad thickness	Brake pads and discs inspected - No Fault Found.	01/09/2018
UNI JOINTS REPLACED. MAIN SHAFT REAR UNI REPLACED. BATTERIES REPLACED BY TRUCK CENTRE.	UNI JOINTS REPLACED. MAIN SHAFT REAR UNI REPLACED. BATTERIES REPLACED BY TRUCK CENTRE.	12/27/2017
Volvo Prime Mover (C Service)	Volvo Prime Mover (C Service)	12/27/2017

DSS camera is misaligned. see screenshot for details	Camera adjusted	12/11/2017
Volvo Prime Mover (A Service)	Volvo Prime Mover (A Service)	12/12/2017
Volvo Prime Mover (B Service)	Volvo Prime Mover (B Service)	11/30/2017
Volvo Prime Mover (A Service)	Volvo Prime Mover (A Service)	11/21/2017
ABS/EBS Fault.Starting Fault. Radio Fault	ABS/EBS Fault. Starting Fault. Radio Fault. TRUCK CENTRE WA WARRANRY WORK	11/16/2017
Replace Belt & Tensioner	Replace Belt & Tensioner	11/21/2017
08875 - Air systems malfunction	Plug in - inspect active faults Replace air dryer cartridge Re-calibrate air dryer Clean fault	11/08/2017
Volvo Prime Mover (D Service)	Volvo Prime Mover (D Service)	11/08/2017
Volvo Prime Mover (A Service)	Volvo Prime Mover (A Service)	10/20/2017
Cab Tilt Sensors	Cab Tilt Sensors	10/05/2017
Volvo Prime Mover (C Service)	Volvo Prime Mover (C Service)	10/09/2017
Volvo Prime Mover (A Service)	Volvo Prime Mover (A Service)	09/22/2017
ASSET DERATING. TRUCK CENTRE CALLED OUT.	ASSET DERATING. TRUCK CENTRE CALLED OUT.	08/31/2017
UNHOOK TRUCK FROM TRAILERS FOR ASSET TO GO TO TRUCK CENTRE FOR REPAIRS.	UNHOOK TRUCK FROM TRAILERS FOR ASSET TO GO TO TRUCK CENTRE FOR REPAIRS.	09/05/2017
Volvo Prime Mover (B Service)	Volvo Prime Mover (B Service)	09/05/2017
Volvo Prime Mover (A Service)	Volvo Prime Mover B Service carried out - WO-QCD-001-567	09/05/2017
Volvo Prime Mover (A Service)	Volvo Prime Mover (A Service)	08/24/2017
Blown Hydraulic Hose	Blown Hydraulic Hose. Enzed Called out.	08/17/2017
WHEEL ALIGNMENT.	WHEEL ALIGNMENT - COMPLETED BY SLIMS TYRE SERVICE.	08/09/2017
MT Data GPS	Diagnose MT Data Fault. GPS Antenna not receiving satellite signal - MT Data.	08/11/2017
Volvo Prime Mover (D Service)	Volvo Prime Mover (D Service)	08/11/2017
INSPECT FAULTS INCLUDING RADIO FAULTS. RESET.	INSPECT FAULTS INCLUDING RADIO FAULTS. RESET.	08/07/2017
HOOK UP TO TRONOX SET01.	HOOK UP TO TRONOX SET01.	07/31/2017

INSPECT AIR BAG FAULT. CALLOUT TRUCK CENTRE FOR WARRANTY - BREAKDOWN REPAIR.	INSPECT AIR BAG FAULT. CALLOUT TRUCK CENTRE FOR WARRANTY - BREAKDOWN REPAIR.	07/26/2017
CLEAR EBS/ABS FAULTS - RESET COMPUTER.	CLEAR EBS/ABS FAULTS - RESET COMPUTER.	07/26/2017
Replace Coolant Pipes	Replace Coolant Pipes. TCWA Kewdale.	07/31/2017
Initial Top Set	Carry out Valve Adjustment - Top Set. TCWA Kewdale.	07/31/2017
Volvo Prime Mover (A Service)	Volvo Prime Mover (A Service)	07/31/2017
PTO Hose	Replace PTO Hose with upgraded 4 wire 250bar hose	07/19/2017
Volvo Prime Mover (C Service)	Volvo Prime Mover (C Service)	07/19/2017
REFILL HYDRAULIC OIL.	REFILL HYDRAULIC OIL.	07/12/2017
Volvo Prime Mover (A Service)	Service asset as per attached service sheet Completed By Flex Industries	05/13/2017
Volvo Prime Mover (A Service)	Service asset as per attached service sheet	05/01/2017





















































