

Description	Work Done	Completed
Demobilised FOR AUCTION	Completed	10/30/2024
Demobilise	Completed	11/06/2024
A Service - Trailer Set		10/23/2024
A Service - Prime Mover	Not Required - Asset to be demobilised	10/21/2024
Air Dryer Filter Replacement - Prime Mover	Not Required - Asset to be demobilised	10/21/2024
Headlights dull window glass needs replacing	Not required - asset to be demobilised.	10/21/2024
Snapped wheel stud	Replaced hub and rotor installed new brake thickness sensor torqued hub and calliper to spec re checked work and replaced brake pads on p3 and p4	09/09/2024
Tyre wants rotating	Flipped position 3	09/09/2024
Broken wheel stud on steer	Load Ute and travel to site Remove wheel and inspect hub - unit cannot be repaired on site needs to come back to workshop Re fit wheel and follow truck back to yard Park up in workshop awaiting repairs	09/07/2024
Snapped wheel stud	Drive to chemiman jack up truck inspect snapped stud saw it was welded bolted wheel back on tensioned and told trivet to park it in the workshop	09/07/2024
P1,2 Brake pads low Power steering leak	Replaced brake pads1,2 And steering hose assembly	09/02/2024
First Aid Kit Inspection		08/30/2024
B Service - Trailer Set	29/8/24 done 30k	08/30/2024
B Service - Prime Mover	Carried out 30k	08/30/2024
Tyres	New tyre fitted to position 4 Recapped drive tyres fitted	07/25/2024
A Service - Trailer Set	Completed	07/24/2024
Topset - Prime Mover	Completed	07/24/2024
A Service - Prime Mover	Completed	07/24/2024
Flat tyre	Spare outer tyre fitted to position 8	07/19/2024
Fire Suppression Systems Inspection	Check Fire Suppression system and Fire extinguishers are operational and stamp for compliance. CARRIED OUT BY WA FIRE PROTECTION	06/28/2024
B Service - Trailer Set	C/O z, D, j	06/25/2024
Diff Oil Replacement - Prime Mover		06/25/2024

C Service - Prime Mover		06/25/2024
Gearbox Oil Replacement - Prime Mover		06/25/2024
Truck bogged	Explain to driver over 2 way that the diff lock and first gear should walk them out of soft sand Driver said it's not working Go to truck put on the diff lock and select first gear and drive out of soft sand Show and explain to driver that the diff lock has 2 stages	06/10/2024
Steering wheel adjuster broken	Completed	06/05/2024
Rebuild turn table	Completed	05/22/2024
Selector Gear stick Broken	Replaced Selector Gear	05/21/2024
Air Dryer Filter Replacement - Prime Mover	Completed	05/21/2024
Engine Won't Start	Gear shifters turn on , and broken repaired And stuck on Gear position	05/21/2024
A Service - Trailer Set	Carried out 15k 21/5/24	05/22/2024
Carbon Burn - Prime Mover	Completed	05/21/2024
A Service - Prime Mover	Completed	05/22/2024
stater motor not working	Completed	04/29/2024
Springs broken on turn table jaws	completed	04/29/2024
Tie rod ends worn Drag link ends worn	Completed	04/23/2024
Diff seal leaking	Completed	04/23/2024
B Service - Trailer Set		04/23/2024
B Service - Prime Mover	Completed	04/23/2024
Pulling Reduce Power check Engine light on	Diagnosed and Scanned Replaced Nox Sensor Replaced Add blue Main Filters and Inlet Filter	03/27/2024
Change new calliper ,brake pads p3 ,brake sensor and brake pads p4	Change new calliper assembly, brake pads p3, brake sensor and brake pads p4 rear drive axle,	03/21/2024
Replaced headlights	Completed	03/21/2024
A Service - Trailer Set		03/21/2024
A Service - Prime Mover		03/21/2024
Tyres	New tyre fitted to position 1 2 3 Position 3 moved to position 4	02/21/2024

Repair trailer brake faults Reset air dryer Test SCR system	Completed	02/22/2024
B Service - Trailer Set	Perform service on trailer set as per attached service sheets on each individual step.	02/21/2024
B Service - Prime Mover	Minor service which includes: Engine oil and filter change, Fuel filter change,	02/21/2024
Coolant pump and hoses leaking	Completed Replaced blown globe and door switches	02/07/2024
Fan Hub Replacement - Prime Mover	Replaced fan hub and fan replaced all belts and tensioners	02/02/2024
Transmission lock in gears	Completed	02/02/2024
Air Dryer Filter Replacement - Prime Mover	Replace air dryer filter	02/07/2024
Replaced front drive axle brake pads Replaced belts and tensioners and fan hub.	Completed	01/29/2024
RHS window not sealing CWR7425	Replaced door seal	02/02/2024
Windscreen badly scratched hard to see out of CWR7425	Replaced windscreen Completed by TCWA spearwood	02/28/2024
A Service - Trailer Set	Carried out service	01/25/2024
A Service - Prime Mover	Carried out service	01/25/2024
Trailers Set LH indicator not working	Diagnosed wiring and replaced 7 Pin Plug metal	01/17/2024
Check addblue hand pump not working and missing magnet filter @ tank	Check addblue hand pump not working and missing magnet filter @ tank	01/15/2024
Change new driver set belt	Change new driver set belt	12/29/2023
Check and repair driver seatbelts stock up @ ALCOA Kwinana site.	Check and repair driver seatbelt @ALCOA set, need new one set belt	12/27/2023
Fire Suppression Systems Inspection	Check Fire Suppression system and Fire extinguishers are operational and stamp for compliance. CARRIED OUT BY WA FIRE PROTECTION	12/21/2023
Refit sensor bracket Replaced APM silencer Tighten up tail shaft bolts Secure battery cable	Jobs completed	12/12/2023
Ad blu magnet missing	Steal Ad blu magnet from 417 Fit ad blu magnet to tank	12/11/2023

Brakes system malfunction @ ALCOA Wagerup , coming back @ chememan to check and repair brakes system	Check and repair brakes malfunction, prime mover and trailer set	12/11/2023
B Service - Trailer Set	Inspection carried out by Ryan Mador Group	12/08/2023
B Service - Prime Mover	Completed by Randy	12/08/2023
Batteries solution Leaked	Replacement Battery 2x And Fuel Bowl	11/10/2023
Coolant Leaking Fuel water separator Circuit open Trigger some Faults code	Replaced Rad Upper hose and Clamps 2x Cleaned up Fuel Filter separator Diagnosed and Cleared codes	11/06/2023
Full down radiator for cleaning and change some bypass hoses coolant leaking,	Full down radiator for cleaning and change some bypass hose coolant leaking	11/03/2023
A Service - Trailer Set	Perform service on trailer set as per attached service sheets on each individual step. Done 9/11//23	11/13/2023
Fan Hub Replacement - Prime Mover	Replacement Fan hud Done	11/10/2023
Carbon Burn - Prime Mover	Remove Compressor Pipes and burn out Carbon from all steel pipes from air compressor to air dryer Replacement FLIXI PIPE	11/10/2023
A Service - Prime Mover	Visual inspection of asset and grease.	11/10/2023
Change new muffler assembly, dosage valve,air dryer and coolant header tank w/ hoses set.	Change new muffler assembly,dosage valve,air dryer and coolant header tank w/ set hoses.	11/01/2023
Engine Bearing Roll - Prime Mover	Not Completed	08/04/2022
Mainshaft & Rear Jack Uni Joints Replacement - Prime Mover	Not Completed	05/05/2023
Call out seat belt not working correctly	Drive to alcoa found seat belt not working able to free up and unjammed it sent back to yard for repair	10/06/2023
Truck locked in gear and can't start	Travel to site and find truck Fill up rear air tank and jack up position 7 to release tension on diff Select neutral gear and isolate truck In isolate truck and start engine build up air Diagnose air leaks on trailers - advise unit to return to yard for trailer repairs	09/27/2023
Wiper Blade with Arms 2pcs Front Fog light malfunction Right Auxiliary high beam malfunction	Replaced Wiper Arms 2pcs Replaced 2pcs Globes Use Tech.Tool and Diagnosed/Clear codes	09/22/2023

Tyres	New tyre fitted to position 3 New drive tyres fitted	09/21/2023
C Service - Prime Mover	Major service which includes: Engine oil and filter change, Fuel filter change, Diff and Transmission oil change, Adjusting engine valve clearances	09/21/2023
Flat tyre	New tyre fitted to position 4	09/14/2023
A Service - Prime Mover	Replaced with WO-PTT-006-510 C Service	09/20/2023
Topset	TOPSET Done 20/09/2023	09/21/2023
B Service - Prime Mover	Not Required - Replaced with C service WO-PTT-006-510	09/08/2023
Flat Tyre P4+ 6	Change Tyre P6 P4 low Air and Add Pressure Tyre	09/05/2023
A Service - Trailer Set	Visual inspection of asset and grease.C/O H. TPN00037 serviced 07/08/23 TPN00036 and DOL00659 to be serviced still	08/08/2023
A Service - Trailer Set	Visual inspection of asset and grease.	07/13/2023
A Service - Prime Mover	Visual inspection of asset and grease. C/O H.	08/08/2023
Flat tyre	Change flat tyre	07/31/2023
transmission failure.	travel to CCL. pump air into the truck to put the gearbox in neutral. start the truck all ok.	07/24/2023
Tyres	Flipped position 3	07/13/2023
Change front cab shock leaking LHS and install new mounting fire extinguisher w/ full fire extinguisher		07/13/2023
B Service - Prime Mover	Minor service which includes: PRM 494=1028743km F.M Engine oil and filter change, Fuel filter change, ODR Download from EBS module	07/13/2023
Change LHS mirror crack	Change LHS mirror crack	06/29/2023
A/c fan not working.	Fit new a/c fan	06/29/2023

Truck hard to start Engine malfunction	plug TT run diagnostic Replaced engine speed sensor Fit new exhaust back pressure sensor plug.	06/01/2023
A Service - Prime Mover	Visual inspection of asset and grease.	06/01/2023
Tyres	New tyres fitted to position 3 and 4 Flipped position 2	05/05/2023
Hard start up	Replaced oil spinner seal and replaced overflow valve on fuel system	05/05/2023
B Service - Prime Mover	Minor service which includes: Engine oil and filter change, Fuel filter change, ODR Download from EBS module	05/05/2023
A Service - Prime Mover	Visual inspection of asset and grease. 995701km	03/03/2023
drop the trailer at the back end of the prime mover.	hook up the prime mover to the trailer.	02/20/2023
Batteries leaking	Removed leaking batteries and clean acid off truck and install new batteries	02/17/2023
Tyres	Position 3 flipped and moved to position 4 Position 4 flipped and moved to position 3	01/17/2023
B Service - Prime Mover	Minor service which includes: Engine oil and filter change, Fuel filter change, ODR Download from EBS module	01/17/2023
A Service - Trailer Set	Visual inspection of asset and grease.	01/17/2023
WA Mainroads Accreditation Roadworthiness Checklist	Complete Mainroads "Accreditation Road Worthiness Checklist" for Western Australian Heavy Vehicle Accreditation	01/17/2023
A Service - Prime Mover	Visual inspection of asset and grease.	01/17/2023
TRUCK NOT STARTING	Found faulty GSU. Repair wirings	12/28/2022
No trailer lights.	Travel to site. Repair wirings	11/23/2022
A Service	Visual inspection of asset and grease.	10/28/2022
Wiper blades worn out.	Replaced wiper blades.	10/27/2022
Tyres	New drive tyres fitted	10/26/2022
A Service - Prime Mover	Visual inspection of asset and grease.	10/26/2022
Damage guard	Position 8 mudguard replaced	10/26/2022

FMC - MT Data - MDVR Hard Drive State Error - PRM00494 - SWT - QB Southwest Transport Rockingham - 09:43 Wed 28 Sep 22 (AWST)	ATTEND TO MT DATA DVR ERRORS. REPLACED DVR TRAY AND HD DRIVE AS IT WAS MISSING. SUPPLIED BY QUBE. CARRIED OUT BY O'BRIEN	10/25/2022
FMC - MT Data - MDVR Recording Error - PRM00494 - SWT - QB Southwest Transport Rockingham - 09:43 Wed 28 Sep 22 (AWST)	ATTEND TO MT DATA DVR ERRORS. REPLACED DVR TRAY AND HD DRIVE AS IT WAS MISSING. SUPPLIED BY QUBE. CARRIED OUT BY O'BRIEN	10/25/2022
FMC - MT Data - MDVR Channel State Error - PRM00494 - SWT - QB Southwest Transport Rockingham - 09:43 Wed 28 Sep 22 (AWST)	ATTEND TO MT DATA DVR ERRORS. REPLACED DVR TRAY AND HD DRIVE AS IT WAS MISSING. SUPPLIED BY QUBE. CARRIED OUT BY O'BRIEN	10/25/2022
Driver side door hatch cable comes out Driver side seat belt ripped	Fix the cable Replaced seat belt	09/12/2022
Faulty right hand side taillight assembly	Replaced faulty taillight assembly	07/29/2022
B Service - Prime Mover	Minor service which includes: Engine oil and filter change, Fuel filter change, ODR Download from EBS module	07/28/2022
C Service - Prime Mover	Major service which includes: Engine oil and filter change, Fuel filter change, ODR Download from EBS module Diff and Transmission oil change, Adjusting engine valve clearances	07/28/2022
Left side head light blown globe	Replaced globe	07/20/2022
Gear box pressure low	Pump air by compressor	07/19/2022
air leak	Replaced p7 brake booster	07/18/2022
truck lock in gears. unable to start.	Travel to site. Charge air into the truck.	07/18/2022
driver side window not working.	Replaced motor	07/13/2022
B Service - Prime Mover	Minor service which includes: Engine oil and filter change, Fuel filter change, ODR Download from EBS moduleJ.A	07/04/2022
WA Mainroads Accreditation Roadworthiness Checklist	Complete Mainroads "Accreditation Road Worthiness Checklist" AS PER C SERVICE	02/08/2022
Tyres	New tyres fitted to position 3 and 4	06/15/2022

Topset	Topset	06/14/2022
A Service - Prime Mover	Visual inspection of asset and grease.	06/14/2022
Puncture	Spare outer tyre fitted to position 8	06/08/2022
Air con fan not working		05/30/2022
Tyres	New tyres fitted to position 1 and 2	05/26/2022
Muffler flexible pipe broken,ABU valve crack		05/26/2022
Air conditioner not blowing correctly	Replace blocked air conditioner filters	05/24/2022
B Service - Prime Mover	Minor service which includes: Engine oil and filter change, Fuel filter change, ODR Download from EBS module	05/25/2022
Left side rear cabin air bag leak		05/18/2022
P8 brake booster leaking		05/16/2022
A Service - Prime Mover	Visual inspection of asset and grease.	05/17/2022
B Service - Prime Mover	Minor service which includes:	04/27/2022
Coolant connecting pipe leaking Oil spinner hose leaking P3 and 4 brake pads low.	Replaced coolant pipe Fit new oil spinner oring seal Replaced brake pads	04/10/2022
Finish off inter cooler installation Left hand window regulator unserviceable Brake pads worn out	finished installing intercooler Replaced left hand window regulator Replaced brake pads position 3 and 4	04/10/2022
Hole in the charge air cooler	Replaced charge air cooler and hoses	04/10/2022
Turbo boost leak	Diagnose fault, found charge air cooler leaking	04/06/2022
Boost leak		04/05/2022
A Service - Prime Mover	Visual inspection of asset and grease.	04/07/2022
Broken passenger window regulator	Fit new window regulator.	03/23/2022
B Service - Prime Mover	Minor service which includes:	03/24/2022
R/h dip beam not working.	Replaced head light ECU.	03/15/2022
Windscreen wipers not working	Free up r/h pivot shaft.	03/03/2022
A Service - Prime Mover	Visual inspection of asset and grease.	03/02/2022
Both door leaking		02/11/2022
A/c not working		02/11/2022
Engine coolant low level alarm,temp sensor not working,2nd axle tyre steer,		02/11/2022

C Service - Prime Mover	Major service which includes:	02/11/2022
B Service - Prime Mover	Minor service which includes:	02/08/2022
CWR1877-BOTH LHS & RHS DOOR LEAKING FROM RUBBER		02/11/2022
CWR1876-A/C NOT BLOWING COLD AIR		02/11/2022
CWR1875-ENGINE COOLANT ALARM, TEMP SENSOR, BRAKE FAULT, 2ND AXLE STEER		02/11/2022
Top radiator hose swollen.	Replaced top radiator hose.drain and refill coolant.	01/13/2022
Coolant low level, passenger side door leak	Completed	01/07/2022
A Service - Prime Mover	Visual inspection of asset and grease.	01/13/2022
Coolant leak	Replaced radiator and clean intercooler.	12/29/2021
Volvo Prime Mover (C Service)	Service asset as per attached service sheet 1X FUEL FILTER 1X BYPASS FILTER 2X OIL FILTERS	12/21/2021
27421 - TRAILER EBS FAULTS	CHECK WIRING, ASSISTED ELECTRICIAN FOR FAULT TRACING AND TESTED	12/01/2021
Volvo Prime Mover (A Service)	Service asset as per attached service sheet FLIP P3 8X NEW DRIVE TYRES	11/30/2021
Cabin filter block outer and inner	Replaced cabin filters	11/17/2021
CWR1871-TEMP OF TRUCK GETTING HOT UNDER LOAD, A/C NOT WORKING DRIVER'S SIDE	REMOVED RADIATOR & WASHED, REFIT & FILL UP COOLANT CHANGED ENGINE FAN REPLACED COOLANT THERMOSTAT REPLACED EXHAUST BACK PRESSURE REPLACED CABIN FILTERS	11/23/2021
Volvo Prime Mover (C Service)	Service asset as per attached service sheet DIAGNOSE ABS FAULTS HOOK UP & UNHOOK FROM OTHER TRAILERS 3X OIL FILTERS 1X FUEL FILTER	11/08/2021
CWR1870-A/C NOT WORKING PROPERLY	CHECKED A/C, IT'S WORKING	11/08/2021
27374 - ABS FAULTS AND TRUCK BRAKE MALFUNCTION INTERMITTENTLY	DIAGNOSE FAULTS, TEST EVERY PLUG ON THE TRAILERS, TRUCK STILL DRIVEABLE, ADVISE THE OPERATOR TO SWAP THE UNIT TO OTHER TRAILERS FOR ISOLATION OF THE FAULTS	10/19/2021

27312 - LEAD TRAILER NO LOAD RANGE	CHANGE LEAD	10/18/2021
CWR1869-TRUCK BRAKE MALFUNCTION	CHECKED WIRES REPLACED TRAILER MODULATOR BRAKE VALVE	10/11/2021
27361-ABS 1 FAULT	ABS 1 FAULT DIAGNOSED	10/08/2021
FMC - MT Data - MDVR Connection Error - PRM00494 - South West - Bulk - South West Transport Rockingham - 17:14 Thu 30 Sep 21 (AWST)	The dvr in the truck was cutting on and off and unable to work over the air so I replaced the dvr and it all worked with support CARRIED OUT BY MTDATA TECH	10/07/2021
FMC - MT Data - MDVR Recording Error - PRM00494 - South West - Bulk - South West Transport Rockingham - 17:14 Thu 30 Sep 21 (AWST)	The dvr in the truck was cutting on and off and unable to work over the air so I replaced the dvr and it all worked with support CARRIED OUT BY MTDATA TECH	10/07/2021
FMC - MT Data - MDVR Hard Drive State Error - PRM00494 - South West - Bulk - South West Transport Rockingham - 17:14 Thu 30 Sep 21 (AWST)	The dvr in the truck was cutting on and off and unable to work over the air so I replaced the dvr and it all worked with support CARRIED OUT BY MTDATA TECH	10/07/2021
FMC - MT Data - MDVR Channel State Error - PRM00494 - South West - Bulk - South West Transport Rockingham - 17:14 Thu 30 Sep 21 (AWST)	The dvr in the truck was cutting on and off and unable to work over the air so I replaced the dvr and it all worked with support CARRIED OUT BY MTDATA TECH	10/07/2021
Volvo Prime Mover (A Service)	Service asset as per attached service sheet REPLACED LHS TAIL LIGHT REPLACED PIN LIGHT PLUG WELD HOLE ON THE MUFFLER NEW TYRES P1 & P2	10/07/2021
27237-PULLING POWER REDUCED	CHANGED NOX SENSOR CHANGED ADBLUE INJECTOR	09/24/2021
CWR1867-DRIVER DOOR LEAKING	PUSH IN & FIX THE DOOR RUBBER	09/15/2021
Volvo Prime Mover (C Service)	Service asset as per attached service sheet 3X OIL FILTERS 1X FUEL FILTER	09/15/2021
CWR1866-L/H LOW BEAM NOT WORKING	TEST THE L/H HEADLIGHT - NFF	09/10/2021

Volvo Prime Mover (A Service)	Service asset as per attached service sheets SECURE SUZI COIL REPLACED R/H LED PARK LIGHT REPLACED HIGH BEAM GLOBE R/H SECURE SEEING MACHINE VIBRATOR REPAIR WIPER WASHER LINE 1X NEW TYRE P4	09/01/2021
26897 - PUNCTURE	FIT NEW TYRES TO P3	08/24/2021
Volvo Prime Mover (C Service)	Service asset as per attached service sheet CHANGED 2X BATTERIES L/H AIR BAG CAB SHOCKY FLIP P1 3X OIL FILTERS 1X FUEL FILTER	08/11/2021
CWR1863-DRIVER'S DOOR LEAKING AIR/WATER	ADJUST DRIVER SIDE DOOR	07/29/2021
Volvo Prime Mover (A Service)	Service asset as per attached service sheet	07/29/2021
CWR1861-FAULTY SENSOR ALERTS FOR CAB TILT & ENGINE FAN	BRIDGE THE CAB TILT PLUG TEST ENGINE FAN - NFF INSPECT AIR CYLINDER UNIT, FAULTY FIT NEW AIR CYLINDER	07/29/2021
26871 - TREAD FLAPPING	NEW TYRE FITTED P4	07/06/2021
27009 - ACTIVATOR BY-PASS VALVE LEAKING	REPLACE ACTIVATOR BY-PASS VALVE	07/05/2021
CWR1852-ELECTRICAL MIRROR CONTROL NOT WORKING		03/24/2022
CWR1860-A/C FAN NOT BLOWING DRIVER'S SIDE, PARTIAL BLOCK L/S	CHANGED 2X CABIN FILTERS	07/08/2021
Volvo Prime Mover (E Service)	Service asset as per attached service sheet 1X NEW TYRE P3 ALL FILTERS	07/08/2021
CWR1858-ABS #1 LIGHT ON DASH	TEST ABS #1 - NFF	06/23/2021
CWR1856-MAIN BEAM MALFUNCTION	CHECK LIGHT, ALL WORKING	06/23/2021
CWR1855-AIR DRYER REQUIRES SERVICE	RESET AIR DRYER	06/23/2021
CWR1857-RIGHT DAYLIGHT RUNNING LIGHT MALFUNCTION	CHECK ALL LIGHTS ARE WORKING	06/23/2021
CWR 1851 - AIR CON NOT WORKING	CHANGED THE A/C FAN	06/23/2021

Volvo Prime Mover (A Service)	Service asset as per attached service sheet CHANGED A/C FAN CHANGED REAR DRAG LINK	06/23/2021
26813 - DOOR LOCKED ITSELF	DRIVE TO ALCOA WAGERUP, UNLOCK THE DOOR	06/01/2021
26688 - PUNCTURE	SPARE OUTER TYRE FITTED P2	05/24/2021
Volvo Prime Mover (C Service)	Service asset as per attached service sheet 100K NEW DRIVES, FLIP P2 L/H ENGINE MOUNT REPLACED (A.M.) SECURE FRONT GRILL 8X NEW TYRES	05/26/2021
CWR1847 - DRIVERS SIDE WINDOW NOT GOING UP OR DOWN	CHANGED THE REGULATOR	05/18/2021
26681 - R/H WINDOWS REG U/S	REMOVE AND REPLACE WINDOW REG AND TEST	05/18/2021
CWR1846-DRIVER'S DOOR WINDOW BROKEN WINDER, SAFETY BELT RETRACT BROKEN.	REPLACED R/H WINDOW REGULATOR	05/26/2021
26778 - BATTERY ISOLATION SWITCH SNAPPED OFF	TRAVEL TO ALCOA PINJARRA, REPLACE ISOLATION SWITCH	05/09/2021
Volvo Prime Mover (A Service)	Service asset as per attached service sheet FLIP P3	05/12/2021
19906 - checking vehicle for air leaks	Re-check vehicle and trailers for air leaks	02/19/2021
19788- Lost air got stuck in gear	fill up air tanks	02/18/2021
19459 - Inspect for air leak	Inspect for air leak, all good, no air leak	02/19/2021
26659-DRIVER'S SIDE A/C VENT NOT PUMPING AIR	REPLACED A/C FILTERS CHECKED VENTS FOR BLOCKAGES CHECKED PIPING FOR DISCONNECTION	04/27/2021
CWR1840-A/C NOT BLOWING PROPERLY DRIVER'S SIDE	COULD NOT FAULT A/C VENT	04/20/2021
CWR1843-L/H WINDSCREEN WIPER CLIPS BROKEN	REMOUNT CLIP BACK ONTO WIPERS	04/20/2021
Volvo Prime Mover (C Service)	Service asset as per attached service sheet FILTERS	04/20/2021
25154-NOX SENSOR MALFUNCTION	CHANGED NEW NOX SENSOR	03/25/2021
19493-HOLE IN EXHAUST PIPE	WELD 2X HOLES ON EXHAUST PIPE	03/23/2021
Volvo Prime Mover (A Service)	Service asset as per attached service sheet REPLACED R/H REAR CAB SHOCK ABSORBER REPLACED TURNTABLE INSERT PADS WELD R/H BOTTOM STEP BRACKET	03/31/2021

CWR1836 - Clutch fan stuck on.	PULL CAB & CLEAR CODES INSPECT & CLEAN CLUTCH FAN	03/31/2021
Volvo Prime Mover (C Service)	Service asset as per attached service sheet Filters	03/08/2021
19681 - AIR CON NOT WORKING	CHANGE A/C FAN 643406 KM	01/25/2021
19767 - PINCH VALVE SWITCH NOT WORKING	REPLACE PINCH VALVE SWITCH 641405 KM	01/20/2021
19883 - air con fan not working	fit on A/C fan tested ok	02/02/2021
19958 - 2nd steer tyres worn on left shoulder, Transmission gear stick cover faulty	Work Request Form 19958 work completed as part of WO-QBP-030-368	02/16/2021
Volvo Prime Mover (A Service)	Service asset as per attached service sheet replace turntable spring replace reflector inspect & lube up axle king pin and steer transmission cooler coolant hose replace drain and refill coolant new steers	02/16/2021
1828 - ENGINE FAN KEEPS RUNNING	PLUG VCAB & CLEAR THE CODES INSPECT & CLEAN THE ENGINE FAN CABLE PLUG.	03/31/2021
Volvo Prime Mover (E Service)	Service asset as per attached service sheets PARTS USED - 3X OIL FILTER, 1X FUEL FILTER, 1X WATER SEPARATOR, 1X ADD BLUE FILTER, 1X TRANS FILTER, 1X AIR DRYER FILTER, 2X CAB FILTER, 1X AIR CLEANER FILTER, 1X AC FAN,1X STEERING FILTER CURRENT READING - 643406	01/25/2021
1823 - AIR CON NOT WORKING	ATTEND TO AIR CON - REMOVED FILTERS AND CLEANED WORK DONE BY O'BRIEN ELECTRICS PO-QBP-012-947 634676 km	12/15/2020

Volvo Prime Mover (A Service)	Service asset as per attached service sheet CHECK TYRES FIT NEW STARTER MOTOR CURRENT READING - 634676	12/15/2020
19618 - CWR 1822 - CAB MOUNTS SUSPECTED WORN	19618 - CAB MOUNTS SUSPECTED WORN CHECK ALL THE CABMOUNTS - TESTED OK CURRENT READING - 624057	11/27/2020
Volvo Prime Mover (C Service)	Service asset as per attached service sheet NEW DRIVES 20K BELTS & TRENDIONERS REPLACE REPLACE R/H BLIND SPOT MIRROR CURRENT READING - 624252	11/27/2020
19271 - AIR LEAK AND CLUNK NOISE UNDER CAB	CHECK CAB MOUNTS, STEERING COMPONENTS, ENGINE MOUNTS FOR CLUNK, NO FAULTS FOUND AT TIME OF INSPECTION 587820 KM	09/24/2020
765, 1820 - air con fan not working	CHANGE A/C FAN CURRENT READING 616741	11/04/2020
Volvo Prime Mover (A Service)	Service asset as per attached service sheets FLIP P3&P2, REPLACE/REMOVE STUD P3 CHANGE A/C FAN PARTS USED X1 STUD, X1 NUT X1 A/C FAN CURRENT READING 610741 587820 KM	11/04/2020
19271 - AIR LEAK AND CLUNK NOISE UNDER CAB	CHECK CAB MOUNTS, STEERING COMPONENTS, ENGINE MOUNTS FOR CLUNK NO FAULTS FOUND AT TIME OF INSPECTION	09/24/2020
19310 - ENGINE DERATING, SUSPECTED AIR LEAK	DIAGNOSE AND REPAIR FAULT FOUND NOX SENSOR SHORTING FIT NEW SENSOR TESTED OK CHECK FOR AIR LEAK NO AIR LEAK FOUND	09/07/2020

Volvo Prime Mover (C Service)	Service asset as per attached service sheet CHECK TYRES 20K ADJUST TURN TABLE TIDY UP AIR LINES L/H SIDE CHASSIS CURRENT READING - 599849	10/12/2020
1813 - R/H/S BOTTOM MIRROR BROKEN	REPAIRED ON LAST SERVICE WO-QBP-028-893	11/04/2020
1812 - AIR DRYER FAN SHROUD RING LEAKING AIR TURBO HAS A LEAK UNDER LEAD	REPLACED ENGINE FAN SHROUD RING REMOVE & REFIT ASSOCIATE PARTS - TESTED OK RESET AIR DRYER W/VCADS INSPECT AND RETIGHT TURBO CLAMPS AND INTERCOOLER HOSES CURRENT READING - 599849	10/12/2020
Volvo Prime Mover (A Service)	Service asset as per attached service sheets CHECK TYRES REPLACE WINDOW REGULATOR AND TEST PARTS USED 1X WINDOW REGULATOR	09/24/2020
1809 - DRIVERS MIRROR CRACKED FRIDGE BROKEN	587820 KM ALREADY REPAIRED PRIOR TO INSPECTION Service asset as per attached service sheets	09/24/2020
Volvo Prime Mover (C Service)	New tyres POS 3 and POS 4 574,712km Parts Used 2x new tyres 3x oil filter 1x fuel filter 1x fuse for fridge	09/03/2020
FRIDGE NOT WORKING	587820 KM REPLACE FRIDGE AND TEST PARTS USED : 1X FRIDGE	09/24/2020

1803 - FRIDGE NOT WORKING	587820 KM REPLACE FRIDGE AND POWER UP TO SEE WORKS PARTS USED : 1X NEW FRIDGE	09/24/2020
Volvo Prime Mover (A Service)	Service asset as per attached service sheet DIAGNOSE FRIDGE FAULT - FOUND FUSE BLOWN REPLACED ALL BLOWEN COURTESY LIGHT TOP UP COOLANT	08/18/2020
18938 - Wheel nuts loose	Tension. all wheel nuts	07/03/2020
18938 - Wheel nuts loose	Tension all wheel nuts	07/03/2020
MT DATA CHARGER CRADLE NOT CHARGING TABLET	MT DATA CHARGER CRADLE NOT CHARGING TABLET	07/31/2020
Volvo Prime Mover (C Service)	Service asset as per attached service sheet REPAIR AIR LEAKS - REPLACE TABLET CHARGER REPAIR TRAILER PLUG - RESET AIR DRYER	07/31/2020
Volvo Prime Mover (A Service)	Service asset as per attached service sheet BLOW OUT WINDOW WASHER SPRAYERS FIT MISSING REFLECTOR AND TAIL LIGHT ASSEMBLY	07/13/2020
2016099 - FAULTS WITH MEDIA PLAYER PHONE CONTACTS NOT UPLOADING	Test media player with own phone, once phone connected all contacts appeared and was working correctly	07/13/2020
TRUCK TOWE FROM PINJARRA TO QUBE YARD- SWAN TOWING	TRUCK TOWE FROM PINJARRA TO QUBE YARD- SWAN TOWING - 27/6/20	06/27/2020
MT DATA TABLET GLITCHING AFTER TAKING FATIGUE BREAK - FLAGGED DRIER WAS FATIGUED EVEN THO BREAK WAS;NT DUE FOR 2 HOURS	Spoke with Philip and had system reset	07/13/2020
2016069 - AIR CONDITIONER FAN NOT WORKING	Test AC fan throughout day multiple times. Working properly all day at time of service / inspection	07/13/2020
18962 - Electrical faults	Diagnose and repair electrical faults Found data link wire broken Repair broken wire tested ok	06/29/2020
2016095 - WARNING ALARMS HEADLIGHT TURNING ON AND OFF	Connect computer and check for faults as none showing on dash, clear all previous faults and run lights for majority of day to see if go out. Wriggle wiring to lights. No faults at time of inspection	07/13/2020

Volvo Prime Mover (E Service)	Service asset as per attached service sheet Alas welded cracked exhaust, repaired broken POS2 guard bracket, clearance light and seized wiper spindle	06/24/2020
2016093 - REPLACE R/H/S STEER TYRE PULLING LEFT AND RIGHT	Replace front steers with new ones Torqued up second steers correctly as they were left loose	06/24/2020
Volvo Prime Mover (A Service)	Service asset as per attached service sheet - 10K Weld crack in the muffler Lube all hinges	06/12/2020
Volvo Prime Mover (C Service)	Service asset as per attached service sheet SERVICED, REPLACED LEAKING STEERING, HOSE AND FITTINGS, WELDED EXHAUST	05/19/2020
Volvo Prime Mover (C Service)	Service asset as per attached service sheet	05/05/2020
Volvo Prime Mover (A Service)	Service asset as per attached service sheet Replace left hand rear mudflap and split wiper blade	04/28/2020
18702 - Wipers inoperable and slow puncture position 3	Repaired seized wiper spindle Replaced position 3 tyre with secondhand part worn	04/20/2020
FMC - MT Data - MDVR Connection Error - PRM00494 - South West - Bulk - South West Transport Rockingham - 09:16 Sun 19 Apr 20 (AWST)	FMC - MT Data - MDVR Connection Error - PRM00494 - South West - Bulk - South West Transport Rockingham - 09:16 Sun 19 Apr 20 (AWST)	04/28/2020
Volvo Prime Mover (C Service)	Advised by FMC 28/04/20 - no longer faulting Service asset as per attached service sheet 20 k repair exhaust bridge cab shock switch inspect passenger door winder	04/01/2020
Drivers side light not working	Repair globes in right hand interior light	03/18/2020
20493 - Heater fan unserviceable	Replace faulty fan blower assy	03/06/2020
Volvo Prime Mover (A Service)	Service asset as per attached service sheet	03/18/2020
2016083 - Cab tilt sensor U/S, Did Temp repair	2016083 - Cab tilt sensor U/S, Did Temp repair	08/18/2020
18442 - Speed sensor wiring fault	Diagnose and repair found wire screen repair wire and test ok	02/24/2020
18440 - Speed sensor faults	Diagnose and repair Found speed sensor fault fit new sensor. Test drive all good	02/23/2020

20693 - Fault codes	Check fault codes whilst already in yard, found starter relay over heated, short to battery, NOX exceedence, Both codes inactive at time of inspection, clear codes and send to work	02/15/2020
Volvo Prime Mover (C Service)	Service asset as per attached service sheets 20K Secure front grill Secure air compressor pipe Fit new rear mudflaps and sign	02/21/2020
20685 - Window on passenger side not going up	Manually put window back up, disconnect button so cannot be put back down until service day and can be repaired	02/07/2020
2016080 - PASSENGER WINDOW MOTOR NOT WORKING	Inspect window operation Clean side runners tested ok	02/21/2020
20794 - Top set due	Carried out top set, record engine valve height	02/03/2020
Volvo Prime Mover (A Service)	Service asset as per attached service sheets SECURE AERIAL	02/03/2020
20464 - Nox sensor, broken wiper arm	Replace nox sensor Replace broken wiper arm and repaired pipe	01/13/2020
20766 - Steering column unserviceable	Fit new steering column Tested - okay	01/09/2020
FMC - DSSi - Camera Misaligned - Trk, PRM00494 - South West - Bulk - South West Transport Rockingham - 06:52 Fri 10 Jan 20 (AWST)	FAULT IS DUE TO THE DRIVER HAVING THE STEERING WHEEL TOO HIGH, HAVE ADVISE DRIVER TO COMPLY WITH CAMERA RULES AND HAVE STEERING WHEEL LOWER	01/28/2020
20532 - Coolant leak	Replace colant pump	01/02/2020
Volvo Prime Mover (E Service)	Service asset as per attached service sheet 100K Fit new driver side window regulator Weld exhaust pipe Fit new turn table pads	01/08/2020
20629 - Exhaust manifold leaking	Replace manifold gaskets	12/18/2019
Volvo Prime Mover (A Service)	Service asset as per attached service sheets	12/18/2019
20717 - A/C fan not working	Fit new	12/06/2019

Volvo Prime Mover (C Service)	Service asset as per attached service sheets Replace burst cab hydraulic hose and weld up crack in exhaust muffler	12/02/2019
Volvo Prime Mover (A Service)	Service asset as per attached service sheet Replaced left hand wiper assembly Tensioned all steer tyres wheel nuts (383633 Km - Can't enter in place of MT Data readings)	11/12/2019
Check SRS code U300064 is active	Check SRS code U300064 is active No code active (383633 Km can't enter in place of MT Data reading)	11/12/2019
FMC - DSSi - Camera Misaligned - Trk, PRM00494 - South West - Bulk - South West Transport Rockingham - 11:30 Wed 23 Oct 19 (AWST) - Site to moderate as required	FAULT NO LONGER AN ISSUE	11/01/2019
Volvo Prime Mover (C Service)	Service asset as per attached service sheet	10/21/2019
20346 - Truck locked in gear	Pump air to the truck to get out of the gear Start truck - all good	10/06/2019
FMC - DSSi - Facial Features Obscured/Camera Misaligned - Trk, PRM00494 - South West - Bulk - South West Transport Rockingham - 06:00 Fri 11 Oct 19 (AWST) - Site to moderate as required	Blocked view due to individual drivers positioning on steering wheel, further discussion on relocating camera to prevent problem	10/21/2019
20412 - Power outlets not working in cab, air build up slow	Replace blown fuses and refit disconnected wiring plug Check air system for leaks and reset compressor	09/18/2019
Volvo Prime Mover (A Service)	Service asset as per attached service sheets RE ATTACH RNR MUD FLAP	09/26/2019

Volvo Prime Mover (C Service)	Service asset as per attached service sheet REPLACE BATTERY NOTE - AIRBAG MALFUNCTION WARNING - JACK SHAFT UNI JOINT CAPS CRACKED - COMPRESSOR HEAD OIL LEAK - SOLENOID LEAKING OIL ON OIL HEAD	09/06/2019
Volvo Prime Mover (A Service)	Service asset as per attached service sheets Also adjusted headlight, replace right hand glove and adjust turntable jaws	08/21/2019
22383 - Tail lights getting close to hitting trailer	Remove bar from trailer Moved bracket for tail lights back 1 bolt hole\ Tighten up and test clearance	08/07/2019
22287 - Top set due, headlights need adjusting, seat cushion driver side rip	Carried out top set and record valve height Adjust head light Fit new cushion	07/24/2019
22313 - Replace left hand rear light fault	Replace corroded burnt out light unit	07/19/2019
22239 - Turntable wear pads damaged/torn off	Changed out wear pads on turntable	07/21/2019
22303 - Right hand h/l inoperable	Replace hid h/l globe	07/12/2019
Volvo Prime Mover (E Service)	Service asset as per attached service sheet	07/24/2019
FMC - DSSi - Facial Features Obscured - Trk, PRM00494 - South West - Bulk - South West Transport Rockingham - 01:18 Thu 19 Jul 19 (AWST) - Site to moderate as required	FAULT NO LONGER AN ISSUE	08/06/2019
2016053 - LH REAR TAIL LIGHT + BLINKER NOT WORKING	Complete	07/24/2019
2016054 - L/H/S REAR TAIL INDICATOR NOT WORKING	Completed on WO-QBP-021-923	07/24/2019
22064 - Belts, tensioners and idlers due for replacing	Replace belts, tensioners and idlers	07/02/2019
Volvo Prime Mover (A Service)	Service asset as per attached service sheet	07/02/2019
2016051 - 'AIR DRYER REQUIRES SERVICE' ON DASH	Air dryer due to be done in next 20K	07/02/2019
2016050 - Air con not working	Replace A/C fan and test.	06/11/2019
2016049 - Left hand head light low beam not working	Changed out hydraulic globe.	06/11/2019
22029 - Truck driver door locked up.	Travel to Col, help driver unlock the door.	06/12/2019

21933 - A/C fan not blowing.	Replace A/C fan and test.	06/11/2019
21973 - Left hand headlight not working.	Changed out hydraulic globe.	06/11/2019
Volvo Prime Mover (C Service)	Service asset as per attached service sheets	06/11/2019
21849 - left hand side head light low beam not working	Inspect headlight no fault found	05/27/2019
Volvo Prime Mover (A Service)	Service asset as per attached service sheet	05/21/2019
FMC - DSSi - Camera miss aligned - Trk, PRM00494 - South West - Bulk - South West Transport Rockingham - 21:36 13 Feb 19 (AWST)	Check cam alignment, was directly looking at my face as was in driving position	05/21/2019
21770 - Air leak out back of cab, check cab air bags	Inspect cab airbags for leaks Found exhaust flexi pipe leaking Fit new one	05/02/2019
Volvo Prime Mover (C Service)	Service asset as per attached service sheet	05/02/2019
FMC - DSSi fault in truck PRM00494 the fault reported = Unit not reporting, for 3 day/s	FAULT NO LONGER AN ISSUE	04/29/2019
2016041 - AIRCON BLOWING WARM AIR	Evaporator replaced - O'Briens	04/15/2019
21472 - Position of outlet tyre flat.	Change out flat tyre. repaired puncture.	03/28/2019
21237 - Spare tyre needs replacing.	Re-fit original tyre.	03/29/2019
Volvo Prime Mover (A Service)	Service asset as per attached service sheet EVAPORATOR MAY NEED ATTENTION	04/12/2019
Volvo Prime Mover (C Service)	Service asset as per attached service sheet	03/26/2019
21299 - Top set	Top set Measured and rebuild engine valve height	03/08/2019
Volvo Prime Mover (A Service)	Service asset as per attached service sheet	03/08/2019
2016033 - RIGHT HAND FUEL TANK NOT DRAINING, NO FUEL FLOWING THROUGH BLOCKED BREATHER?	Fix fuel tank breather	03/08/2019
Volvo Prime Mover (E Service)	Service asset as per attached service sheet INVOICE \$455.69 - 5069290-000002	02/18/2019
FMC - DSSi - Facial Features Obscured - Trk, PRM00494 - South West - Bulk - South West Transport Rockingham - 14:23 Fri 01 Feb 19 (AWST)	FAULT NO LONGER AN ISSUE	03/05/2019

FMC - DSSi - Camera miss aligned - Trk, PRM00494 - South West - Bulk - South West Transport Rockingham - 05:25 Fri 01 Feb 19 (AWST)	FAULT NO LONGER ANN ISSUE	03/05/2019
21008 - Clean sunroof seal, check multi media - no fault found, refit DSS and found power supply wire faulty	Clean sunroof seal, check multi media - no fault found, refit DSS and found power supply wire faulty then repaired	01/29/2019
Volvo Prime Mover (A Service)	Service asset as per attached service sheet INVOICE \$69.91 - 5068954-000002	01/29/2019
2016030 - WARNING SIGN ON DASH, REDUCED PULLING POWER IN 36 HOURS	volvo repair faults under warranty	01/29/2019
20919 - engine de-rate fault. EBS fault.	investigation - plugged laptop in. determined to be ad blue system fault. Cleared fault. Build air up, dumped brakes a few times, built air up and fault corrected itself.	01/19/2019
2016029 - MTDATA NOT CHARGING, CHARGE SYMBOL APPREARS BUT NO CHARGE	CHARGING NO FAULT FOUND	01/29/2019
20954 - Glad hands leaking. Suzi coil wrap wearing.	Fit new suzi coil conduit. Fit new glad hand seals.	01/09/2019
FMC - DSSi fault in truck PRM00494 the fault reported = Unit not reporting, for 38 day/s	Checked with FMC. All working - no fault	02/18/2019
Volvo Prime Mover (C Service)	Service asset as per attached service sheet	01/09/2019
20774 - 1) Turntable play. 2) Air-leak SVC line.	1) Adjust turntable. 2) Replaced all glad-hand seals.	12/20/2018
2016027 - REQUEST FOR AN AIR-GUN FOR THE TRUCK	INVOICE \$55.76 - 5068407-000002 Fit air blower and hose.	12/20/2018
2016028 - ELECTRICAL ISSUES AFFECTING USB PORTS AND MEDIA PLAYER	Check all the operation - no fault found. Reset air dryer - air leak. Check for faults W/vcads and clear.	12/20/2018
FMC - DSSi fault in truck PRM00494 the fault reported = Unit not reporting, for 17 day/s	FAULT NO LONGER AN ISSUE	01/04/2019
Volvo Prime Mover (A Service)	Service asset as per attached service sheet	12/20/2018

FMC - DSSi fault in truck PRM00494 the fault reported = Unit not reporting, for 10 day/s	FMC - DSSi fault in truck PRM00494 the fault reported = Unit not reporting, for 10 day/s. Unit sent away for warranty appraisal 'pending'. Email was sent notifying all.	12/14/2018
20668 - No start, electrical system failure	Test batteries Drive to Kewdale to get new batteries Fit new batteries Ram truck	12/02/2018
20604 - Puncture	Replace tyre INVOICE \$2772.00 - 2134688	11/27/2018
Volvo Prime Mover (C Service)	Service asset as per attached service sheet INVOICE \$671.00 - 1565975-000001	11/27/2018
FMC - DSSi - Vehicle not reporting - Trk, PRM00494 - South West - Bulk - South West Transport Rockingham - 23:00 Fri 16 Nov 18 (AWST) - Site to moderate as required	O'Briens electrics checked DSS unit unserviceable Waiting on replacement invoice \$308.00 - 00069237	11/27/2018
Volvo Prime Mover (A Service)	Service asset as per attached service sheet	11/08/2018
20043 - Rear lights too close to the trailer.	Modified tail lights and brackets to move lights back. Tested - ok.	10/18/2018
Volvo Prime Mover (C Service)	Service asset as per attached service sheet	10/19/2018
20028 - Drivers door let go in the wind.	Bent door back to shape.	10/05/2018
Volvo Prime Mover (A Service)	Service asset as per attached service sheet	10/05/2018
20140 - Rear checker plat coming off.	Drill a hole and fit bolts and nuts to secure.	09/19/2018
Volvo Prime Mover (C Service)	Service asset as per attached service sheet INVOICE \$660.00 - 2132114	09/11/2018
FMC - DSSi - Camera miss aligned - Trk, PRM00494 - South West - Bulk - South West Transport Rockingham - 07:56 Wed 05 Sep 18 (AWST)	re align camera move down a bolt hole	09/11/2018

Volvo Prime Mover (A Service)	Service asset as per attached service sheet Flip position 2 and position 4.	08/28/2018
2016017 - SEAT BELT NOT RETRACTING INTERMITTENTLY PASSENGER SIDE	Seat jammed in back position. Unjammed seat belt all okay.	08/28/2018
18117 - Modify Adblue cover.	Chopped cover in half for easy access.	08/08/2018
FMC - DSSi - Camera miss aligned - Trk, PRM00494 - South West - Bulk - South West Transport Rockingham - 01:33 Thu 08 Aug 18 (AWST)	Realigned camera.	08/28/2018
Volvo Prime Mover (E Service)	Service asset as per attached service sheet INVOICE \$435.84 - 5066096-000002 INVOICE \$34.43 - 5066100-000002	08/08/2018
Volvo Prime Mover (A Service)	Service asset as per attached service sheet	07/23/2018
FMC - DSSi - Camera miss aligned - Trk, PRM00494 - South West - Bulk - South West Transport Rockingham - 11:31 Thu 12 Jul 18 (AWST)	Secure camera to dash so cannot move out of position	07/23/2018
2016015 - DRIVER'S MIRROR CRACKED FROM TOP TO BOTTOM.	Fit new driver side mirror Carry out topset	08/08/2018
2016016 - AIRCON FAN NOT WORKING (FUSE?) GLAD HAND RUBBERS LEAKING ON LEAD TRAILER, REPLACE.	Aircon fan working Replaced 2x glad hand seals	07/23/2018
17692 - Fault codes setting off alarms	Check electrical faults	06/26/2018
Volvo Prime Mover (C Service)	20,000km Service	07/04/2018
17833 - Electrical faults	Diagnose and repair electrical faults Found left hand door wiring harness faulty Repair faults and tested INVOICE \$280.72 - 5065345-000002	06/26/2018
Volvo Prime Mover (A Service)	Completed.	06/20/2018
17558 - Brake malfunction.	Carried out brake pedal test. Plug vcards - clear all codes.	05/10/2018
Volvo Prime Mover (C Service)	20,000KM SERVICE.	05/29/2018

2016011 - Check electrical charge on 12 volt charger. Electrical short in trailers at the time.	Checked 12 volt supply reads 12V, driver needs to read 12V sign not 24V. No short found on trailers.	06/20/2018
Volvo Prime Mover (A Service)	10,000km Service	05/08/2018
Volvo Prime Mover (C Service)	20,000KM SERVICE.	04/17/2018
Volvo Prime Mover (A Service)	10,000KM SERVICE.	04/04/2018
S&F: UHF RADIO LOAD INDICATOR PARK BRAKE ALARM SPEED LIMIT TO 98KM/HR SIGN WRITING	S&F: UHF RADIO LOAD INDICATOR PARK BRAKE ALARM SPEED LIMIT TO 98KM/HR SIGN WRITING WORK COMPLETED BY TRUCK CENTRE WA AS PER INVOICE NUMBER: 8730852 - 000008	02/22/2018
Mt Data fault	ADJUSTED CAMERA BACK	03/14/2018
Volvo Prime Mover (A Service)	10,000KM SERVICE.	03/14/2018
CARRY OUT 1ST WARRANTY SERVICE	CARRY OUT 1ST WARRANTY SERVICE @ 10,472KMS CHANGE OIL AND FILTERS. TOP OF DRIVERS DOOR LEAKING. ADJUST STRIKER PLATE. WASHER JET NOT WORKING. ADJUST PIPE. RADIO KEEPS JUMPING THROUGH STATIONS. CHECK ELECTRICAL WIRES AND CONNECTIONS. WORK COMPLETED BY TRUCK CENTRE WA AS PER INVOICE NUMBER: 6040593 - 000002	03/07/2018
2016004 - Drivers door leaking at top. Water from wash bay coming in. Check stereo wiring - volume fades in and out. Check antenna - loses stations when driving.	WORK COMPLETED AT FIRST WARRANTY SERVICE BY TRUCK CENTRE ON WO-QBP-014-536	03/07/2018
2016003 - Please fit air con to truck to blow out dust from cab. Please fit seat protection to driver seat to protect seat.	NO BLOWER REQUIRED FOR TRUCK NO SEAT COVER REQUIRED FOR TRUCK	03/14/2018
Volvo Prime Mover (A Service)	10,000KM SERVICE.	02/22/2018

<p>CUT EXHAUST TO 3.8M FIT REAR TREAD PLATE FIT FULL LENGTH PLATE FIT EYEWASH LEFT HAND SIDE MODIFY FIRE EXT BRACKET</p>	<p>CUT EXHAUST TO 3.8M FIT REAR TREAD PLATE FIT FULL LENGTH PLATE FIT EYEWASH LEFT HAND SIDE MODIFY FIRE EXT BRACKET WORK COMPLETED BY TRUCK CENTRE WA AS PER INVOICE NUMBER: 8733761 - 000008</p>	<p>02/15/2018</p>
<p>SERVICE CALL TO FIT GUARDIAN SYSTEM</p>	<p>FITTED CAMERA AND GUARDIAN SYSTEM. PROGRAMMED AND CHECKED OK ON COMPLETION. FITTED CRUISE CONTROL. CUT OUT WIRE, CHECKED OK. WORK COMPLETED BY O'BRIEN AUTO ELECTRICS AS PER INVOICE NUMBER: 00025401</p>	<p>02/16/2018</p>
<p>08418 - Truck needs to be ready for work.</p>	<p>Dog bowls removed, all wheel nuts checked and linked. Turntable bolt checked and painted. Conduit applied to Suzi coils. Mud guard checked and painted. Grease jaws.</p>	<p>02/15/2018</p>

