

Description	Work Done	Completed
Carbon Burn - Prime Mover	N/A	09/24/2024
C Service - Prime Mover	OFF SITE	10/26/2024
A Service - Prime Mover	COMPLETING MAJOR SERVICE	09/04/2024
Smoke Bomb Cab Test	N/A	09/04/2024
IVMS Faults	OFF SITE	10/26/2024
Drive shaft	Drive shaft	08/26/2024
B Service - Prime Mover	As per work order	09/17/2024
Smoke Bomb Outcome Repair - Minimal Leak	Replace RHS (driver side) door seal.	08/26/2024
Multiple defects	Inspected below faults -No faults Found Inspect/repair engine mounts = Newly replaced - LHS/RHS inspect/repair front steer wheel bearings = Minimal Movement inspect/repair LH side steer hub leak =No leak present Inspect/repair Vibration =Engine Mounts Tight	07/31/2024
Air Dryer Filter Replacement - Prime Mover	completed	09/04/2024
Topset - Prime Mover	OFF SITE	10/26/2024
Final Drive Oil Replacement - Prime Mover	OFF SITE	10/26/2024
Gearbox Oil Replacement - Prime Mover	OFF SITE	10/26/2024
A Service - Prime Mover	completed 2 A services per day	08/19/2024
B Service - Prime Mover	performed B Service	07/31/2024
BREAKDOWN REPAIRS	REPLACED DAMAGED STACK & BRACKETS REPLACED HYD FILTER MOUNT & FILTER TOP-UP HYDRAULIC OIL	05/14/2024
Cummins PRM646 04/07/24 Gear Flywheel Ring	Completed	07/08/2024
A Service - Prime Mover	COMPLETED	07/16/2024
brake shoes	ordered	07/01/2024
Replace steering drag link	done - closed out - part was used on 945	08/01/2024

Smoke Bomb Cab Test	smoke bomb in cab (minimal leak at the bottom of the drivers side door)	07/31/2024
Defects from service	As per work order	06/27/2024
Inspection of clutch operation	complete	06/27/2024
Rebuild a pair of sisu hubs	Rebuild a pair of sisu hubs at Maxi parts	06/21/2024
Carbon Burn - Prime Mover	complete	06/26/2024
C Service - Prime Mover	as per work order	06/26/2024
A Service - Prime Mover	Completed Service	06/17/2024
Defects From Service	Repaired Defects	05/29/2024
Air Dryer Filter Replacement - Prime Mover	Replaced Air Dryer	05/28/2024
Topset - Prime Mover	COMPLETED	06/06/2024
Final Drive Oil Replacement - Prime Mover	Replaced Final Drive Oil	05/28/2024
Gearbox Oil Replacement - Prime Mover	Replaced Filter (Oil Still Fresh)	05/28/2024
B Service - Prime Mover	Carried Out Service	05/28/2024
Smoke Bomb Cab Test	Awaiting Parts	05/28/2024
A Service - Prime Mover	completed	05/31/2024
Smoke Bomb Cab Test	COMPLETE WITH NEW	05/25/2024
Defects from service	Defects completed in accordance to work plan	05/08/2024
C Service - Prime Mover	carried out C service as per assigned survey	05/07/2024
FIT NEW AUSTART TURBINE STARTER	FIT NEW AUSTART TURBINE STARTER	02/22/2024
KIT TIE ROD X 4 - PART OF ASSEMBLY	KIT TIE ROD X 3 RECIEVED KIT TIE ROD X 1 RECIEVED ON B/O	04/02/2024
C Service - Prime Mover	COMPLETED WITH NEW WO-YAK-023-308	04/30/2024
A Service - Prime Mover	completed	03/27/2024
post flooding inspections	Completed post flooding inspection on all assets. all oils P/Mover all trailer hubs/retorqued wheel nuts Completed A service on assets Repaired as necessary.	03/15/2024
Gearbox replacement	Completed	04/17/2024
Exchange 18 Speed Reman Transmission, Clutch Kit, Clutch Install/Input Kit MAXI Parts PRM646 7/3/24	Completed	03/08/2024

Carbon Burn - Prime Mover	Completed	04/17/2024
C Service - Prime Mover	COMPLETED WITH NEW	04/09/2024
repairs and return to work inspection	done	03/25/2024
A Service - Prime Mover	Completed	02/28/2024
C Service - Prime Mover	COMPLETED WITH WO-YAK-022-282 AFTER STATIC LEAN INSPECTION	02/02/2024
B Service - Prime Mover	COMPLETED WITH WO-YAK-022-282 AFTER STATIC LEAN INSPECTION	02/02/2024
Carbon Burn - Prime Mover	old work order when it was out of action	01/31/2024
A Service - Prime Mover	completed	01/31/2024
B Service - Prime Mover	Not working	02/07/2024
A Service - Prime Mover	Complete	01/22/2024
A Service - Prime Mover	Complete	01/22/2024
FLYWHEEL CHANGE	done	03/04/2024
INSTALL ROPS	completed	03/26/2024
A Service - Prime Mover	suspended asset	10/25/2023
B Service - Prime Mover	suspended	10/25/2023
A Service - Prime Mover	suspended	10/25/2023
Smoke Bomb Cab Test	suspended	10/25/2023
Air Dryer Filter Replacement - Prime Mover	suspended	10/25/2023
Topset - Prime Mover	suspended	10/25/2023
Final Drive Oil Replacement - Prime Mover	suspended	10/25/2023
A Service - Prime Mover	suspended	10/25/2023
B Service - Prime Mover	suspended	10/25/2023
A Service - Prime Mover	suspended	10/25/2023
Carbon Burn - Prime Mover	complete	09/22/2023
C Service - Prime Mover	completed as per service paperwork by nezar and angelo	09/22/2023
B Service - Prime Mover	Complete Work Plan requirements	09/01/2023
Smoke Bomb Cab Test	Complete Work Plan requirements	09/01/2023
A Service - Prime Mover	AS PER B SERVICE WO-YAK-020-633	09/01/2023
REPAIRS	Complete Work Plan requirements	09/01/2023
B Service - Prime Mover	AS PER B SERVICE WO-YAK-020-633	09/01/2023

Smoke Bomb Cab Test	Smoke bomb cab and reseal if required.	08/01/2023
Kenworth Prime Mover (B Service)	Service asset as per attached service sheet	08/01/2023
Kenworth Prime Mover (B Service)	AS PER WO-YAK-020-243	07/28/2023
NO ENGINE EXHAUST BRAKE	REPLACED EXHAUST BRAKE VALVE	07/06/2023
Kenworth Prime Mover (B Service)	as per WO-YAK-020-197	07/23/2023
DEFECTS	complete	08/01/2023
Kenworth Prime Mover (B Service)	as per WO-YAK-020-143	07/13/2023
repairs with service	Reseal 1st Diff Output Reseal 3rd Diff Input Reseal lay shaft cover	07/02/2023
Replace Air Dryer Filter	Replaced Air Dryer Filter	06/30/2023
Replace Final Drive Oil	Replace Final Drive Oil	06/30/2023
Replace Gearbox Oil & Filter	Replaced Gearbox Oil	06/30/2023
Carry out C Service as per every 1,000 hours.	Carried out C Service as per every 1,000 hours.	06/30/2023
Kenworth Prime Mover (B Service)	Complete AS PER C-SERVICE WO-YAK-019-775	06/30/2023
Smoke Bomb Cab Test	Smoke Bomb Cab Test	06/30/2023
DEFECTS	Fixed wiring on cab light re tightened bull bar mounting bolts refilled washer fluid	07/02/2023
Kenworth Prime Mover (B Service)	Completed with WO-YAK-019-669	05/28/2023
Kenworth Prime Mover (B Service)	Complete Service	05/28/2023
2way fault	Replaced 2 way hand mic	05/22/2023
T2 Brakes wont Release	Re-arrange SR3 Valve air leaks Inspect SR3 Valve Install P6 brake hose chamber / booster Test air charging Machine test	05/18/2023
Rock Damage	Major rock damage to middle axle + rear bar on T2 R+R Pos 3 + 4 Booster Cut out + Replace Pos 3 Booster plate Bend + Weld rear bar Replace blown dash bulb x9	05/14/2023
HOT HUBS	R+R slack adj on Pos 1 for T3 Readjust brake	05/15/2023

Speedo / Defects	Checked sensor and gauge Checked wiring found short in wiring. Plug along chassis rail cut out damaged wiring and replaced Replaced dolly 2 pos 1 T-Rod mounting belt Repair T3 Pos 1 Hot Hub Top up hydraulic oil	05/10/2023
Hot Hub	T4 BROKEN BOOSTER BRACKET REMOVED BOOSTER AND WELDED BRACKET BACK ON	05/10/2023
Repairs	Complete all defects	05/28/2023
Kenworth Prime Mover (B Service)	Service asset as per attached service sheet	05/01/2023
Dolly / Trailer leak repairs	Repair all defects	05/28/2023
MT Tablet not charging	Check fault - No fault found	05/28/2023
Rectify ripe height fault	Rectify ripe height fault	04/30/2023
Hydraulic Leak - T3 wont tip	Damaged hose fitting Removed hose and made new hose at W/S Fitted new hose and called service truck	04/30/2023
LONG RIVET TRAILER SET	2nd DOLLY HOT HUBS	05/10/2023
Diff lock U/S	Repair diff lock	05/28/2023
Replace Air Dryer Filter	Parked up since the 19/2/23	03/19/2023
Replace Final Drive Oil	Parked up since the 19/2/23	03/19/2023
Replace Gearbox Oil & Filter	Parked up since the 19/2/23	03/19/2023
Carry out C Service as per every 1,000 hours.	Parked up since 19/2/23	03/19/2023
Kenworth Prime Mover (B Service)	Parked up since the 19/2/23	04/16/2023
SMOKE TEST REPAIRS	REPLACE BOTH DOOR SEALS REPLACE REAR WINDOW SEAL deans REPLACE GEAR BOOT	06/06/2023
Kenworth Prime Mover (B Service)	completing on a different WO	04/05/2023
Kenworth Prime Mover (B Service)	completing on a different WO	03/20/2023
Kenworth Prime Mover (B Service)	Parked up since 19/2/23	04/05/2023
Kenworth Prime Mover (B Service)	Completed	02/20/2023
Diff lock U/S	Parked up since 19/2/23	03/07/2023
Kenworth Prime Mover (B Service)	Completed on WO-YAK-018-882	02/17/2023
Axle and gear box temp gauge not working	CLOSING - OLD WORK ORDER	03/29/2023

oil leak on engine side tank	Completed	01/25/2023
Small fuel tank needs fixing	Completed	01/25/2023
FUEL GAUGE NOT WORKING	Tested - appears to be working	02/20/2023
FMC - MT Data - Unit not Tracking - PRM00646 - SWT - QB Yakabindie - 06:58 Tue 24 Jan 23 (AWST)	completed	04/24/2023
Kenworth Prime Mover (B Service)	Completed	01/25/2023
Replace Air Dryer Filter	Completed	01/07/2023
Inspect and Clean Radiator	Completed	01/25/2023
Replace Final Drive Oil	Completed	01/07/2023
Replace Gearbox Oil & Filter	Completed	01/07/2023
Carry out C Service as per every 1,000 hours.	Completed	01/07/2023
Kenworth Prime Mover (B Service)	completed	12/19/2022
FMC - MT Data - Unit not Tracking - PRM00646 - SWT - QB Yakabindie - 09:50 Mon 12 Dec 22 (AWST)	Found fault in tracking unit power supply, Replaced Connector.	01/19/2023
Air Con stopping and starting all day	completed	12/18/2022
FMC - MT Data - MDVR Channel State Error - PRM00646 - SWT - QB Yakabindie - 15:42 Fri 25 Nov 22 (AWST) Channel 3 is not connected.	Inspected device, Found error in camera 3 Cable. Replaced camera cable and tested. Found power fault and earth fault in MDVR harness and Truck 12v plug. Tested device. all ok.	01/19/2023
Fuel Leak - FORM# YAK 2704	Noted hole in fuel tank, Pull cross over tank hose off, Cable tied fuel hose Parts noted: Hose end caps, Zip ties completed 05/11/22	11/05/2022
Kenworth Prime Mover (B Service)	completed service as per sheet	11/28/2022

Kenworth Prime Mover (A Service)	Completing due to planning of B Service on 19/11 - WO-YAK-018-046	11/11/2022
FMC - MT Data - Unit not Tracking - PRM00646 - SWT - QB Yakabindie - 16:00 Mon 07 Nov 22 (AWST)	Replaced tracking unit as required. Tested all ok.	11/20/2022
MT Data not recording - Camera faults	Completed WO-YAK-017-804	10/27/2022
Kenworth Prime Mover (C Service)	Completed	10/25/2022
Passenger wiper arm defect	replace wiper assembly	10/25/2022
FMC - MT Data - MDVR Channel State Error - PRM00646 - SWT - QB Yakabindie - 15:23 Thu 06 Oct 22 (AWST)	Inspected found channel 3 and 4 not fitted. No fault in unit.	11/20/2022
Carry out B Service as per every 300 hours.	Completed	09/27/2022
Defects	Replace both rear axle air bags Replace dash light fuse	09/15/2022
Defect Mine radio U/S L/H sun visor Stereo fault	repaired the following Mine radio U/S L/H sun visor Stereo fault	10/25/2022
Defect MT data not working	Completed WO-YAK-017-804	10/27/2022
Defect Trailer lights	Repair trailer wiring	09/08/2022
Brakes locking on	Replaced T1 SR3 Valve, T1 drain cock, and repaired all air leaks found.	09/04/2022
Kenworth Prime Mover (B Service)	Work Completed	09/11/2022
Drivers seat worn and lumber support not working.	Replaced Drivers seat and base	09/11/2022
Kenworth Prime Mover (C Service)	Service asset as per attached service sheet	08/23/2022
Replace Gearbox Oil & Filter	Work completed during C service	08/23/2022
Replace Final Drive Oil	Work completed during C service	08/23/2022
Replace Diff Oil and filters	Work completed during C service	08/23/2022
Inspect & Replace Belt Tensioner & Drive Belts as required	Work completed during C service	08/23/2022
Replace Air Dryer Filter	Work completed during C service	08/23/2022
Repair windscreen wipers and washers	Work completed during C service	08/23/2022
Repair engine temp gauge not working	repair wiring	10/25/2022

Repair trailer lights	Work completed	09/11/2022
Carry out C Service as per every 1,000 hours.	double up	07/10/2022
Kenworth Prime Mover (B Service)	double up	07/10/2022
Kenworth Prime Mover (A Service)	double up	07/10/2022
Replace Belt Tensioner & Drive Belts	not needed	07/08/2022
Replace Air Dryer Filter	not required	07/08/2022
Carbon Burn	not required	07/08/2022
Replace Final Drive Oil	not required	07/08/2022
Replace Gearbox Oil & Filter	not required	07/08/2022
Replace Diff Oil	not required	07/08/2022
Kenworth Prime Mover (A Service)	completed as per B service	07/08/2022
Kenworth Prime Mover (B Service)	C Service due	08/23/2022
Kenworth Prime Mover (A Service)	completed as per B svc	07/08/2022
Replace stereo speakers	Work completed during C service	08/23/2022
Kenworth Prime Mover (B Service)	Service asset as per attached service sheet	06/20/2022
HAZZARD CARD - SUSPENSION ON CAB ROUGH/HARD	REPLACE LEAKING CAB AIR BAG ADJUST CAB SUSPENSION RIDE HEIGH	06/07/2022
A/C BLOWING HOT AIR	Completed	07/19/2022
No dash lights L/H low beam not working	Repair shorted wire, replace fuse for dash lights Replace low beam bulb	06/03/2022
Prime mover electrical repairs	Completed	07/19/2022
Brake Test - Prime Mover	done as part of the service	06/03/2022
Mid- Life Refurbishment	double up	05/31/2022
Kenworth Prime Mover (B Service)	Service asset as per attached service sheet	06/02/2022
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	05/28/2022
Kenworth Prime Mover (A Service)	double up	05/21/2022
Defects	Replace leaking (holed) air tank Replace worn universal joint - 2nd Replace all flange bolts at 3rd universal joint	05/18/2022
Mid- Life Refurbishment	double up	05/31/2022
Kenworth Prime Mover (A Service)	as per work plan	05/10/2022
Kenworth Prime Mover (A Service)	as per work plan	04/30/2022

Kenworth Prime Mover (A Service)	as per work plan	04/23/2022
Replace uni joint & Side step	Completed	07/19/2022
FMC - MT Data - MDVR Recording Error - PRM00646 - SWT - QB Yakabindie - 10:46 Sat 30 Apr 22 (AWST)	as per work plan. Inspected vehicle found no fault in MDVR . continue to monitor.	06/16/2022
FMC - MT Data - MDVR Channel State Error - PRM00646 - SWT - QB Yakabindie - 10:46 Sat 30 Apr 22 (AWST)	as per work plan No fault found, no issues on history of MDVR reports.	06/16/2022
FMC - MT Data - MDVR Connection Error - PRM00646 - SWT - QB Yakabindie - 10:46 Sat 30 Apr 22 (AWST)	as per work plan. No fault found	06/16/2022
No speedo, No washer, only one wiper, seat belt, speedo and tacko need, axle temp gauge, fire extinguisher, oil leak on gear box, Trailer 646-649 rear push bar, lights, mudflaps, dry pins	Fixed dash wiring for dash lights and wipers. Replaced rear cab window Welded mud guard on trailer Replaced leaf pack on trailer Replace fire extinguisher	05/13/2022
mudguards, spring tower stop on trailer, wire ropes, bin condition, only one wiper, axle temp gauge, no fire extinguisher	as per work plan	06/21/2022
Axle Temp Gauge, Seat belt cutting, speedo, trailers 646+649 rear pull bar, mudguards, lights, pins dry	Completed	07/19/2022
Replace Belt Tensioner & Drive Belts	double up not needed	05/03/2022
Replace Air Dryer Filter	double up not needed	05/03/2022
Carbon Burn	double up not needed	05/03/2022
Replace Final Drive Oil	double up not needed	05/03/2022
Replace Gearbox Oil & Filter	double up not needed	05/03/2022
Replace Fan Hub	double up not needed	03/25/2022
Replace Diff Oil	as part of service	05/01/2022
Carry out C Service as per every 1,000 hours.	Carry out C Service as per every 1,000 hours.	04/16/2022
Trailer bin sides cracked	Work completed	06/02/2022
defect	adjust clutch secure tail shaft flange	04/20/2022
defect	replace 3 x trailer kicker springs	04/21/2022
defect	weld in turntable packers	04/20/2022

defect	replace turntable bush	04/22/2022
Replace torque rod	Replace torque rod	04/01/2022
Inspect for no dash lights	Inspected fuses in vehicle Found fuse missing in dash light slot Fit new fuse	04/04/2022
Inspect for lights not working	Inspected fuse Inspected wiring Found rubbed wiring on bull bar Replaced wiring and secured properly	04/15/2022
e-stop fire extinguisher hook up	e-stop fire extinguisher hook up	04/15/2022
Replace King Pins	Jack vehicle up Remove left and right hand steer tyres Remove left and right wheel ends Remove old king pin bushes and replace with new stemco kits Refit hubs Adjust wheel bearings Fill with oil Adjust Brakes Torque wheel nuts and fit re-torque card in vehicle	04/04/2022
front king pins	rekitted front king pins	03/31/2022
Kenworth Prime Mover (A Service)	double up not needed	05/03/2022
Kenworth Prime Mover (B Service)	Service asset as per attached service sheet	03/23/2022
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	03/23/2022
defect	re-crimp alternator connection re-seal oil pressure manifold	03/06/2022
defect	replace shifter and top plate on gearbox repair air leaks	03/15/2022
defect	as per work plan	05/13/2022
wipers, washers, virbration, clutch, rear cab window, diff lockd, mud guard on trailer, light on, leaf broken L/H	Fixed dash wiring for dash lights and wipers. Replaced rear cab window Welded mud guard on trailer Replaced leaf pack on trailer	05/04/2022
Wipers-washers-vibration-clutch free play-rear cab window-diff locks-mudguards on trailers-light on trailers-trailers one leaf brokenLH side	Completed	07/19/2022

carry out tasks	completed	02/24/2022
carry out tasks	completed	02/24/2022
carry out tasks	completed	02/24/2022
leaking safety valve	fitted new safety valve	02/02/2022
no drive without power diver engaged	inspected issue through shaft incorrect size fitted correct through shaft refilled oils	02/02/2022
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	02/08/2022
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	02/08/2022
wheel bearings on middle axle	wheel bearings on middle axle	02/02/2022
repairs	replaced all wheel bearings replaced brake bearings reshimmed hubs replaced j-arms repaired pto	01/26/2022
FMC - MT Data - Unit not Tracking - PRM00646 - SWT - QB Yakabindie - 14:00 Fri 21 Jan 22 (AWST)	Inspected asset found to be tracking fine.	02/16/2022
Carry out C Service as per every 1,000 hours.	Service asset as per attached service sheet	02/01/2022
Change out pos 3-4 j-arms	Change out pos 3-4 j-arms	01/19/2022
leaking air valves	removed and replaced leaking valve	01/14/2022
replace leaking break booster	replace leaking break booster	01/14/2022
PTO not engaging properly	PTO not engaging properly	01/15/2022
Drivers door not closing not sealing noise and dust issues+drivers seat air bags not fully inflated no lumber support truck leaning to one side when cornering at speed	Drivers door not closing not sealing noise and dust issues+drivers seat air bags not fully inflated no lumber support new seat..... truck leaning to one side when cornering at speed checked blocks ok	01/26/2022
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	01/15/2022
brakes	stripped and inspected brakes after very hot hubs	01/06/2022
tipping lines	tipping lines fixed and tested repaired electrical faults on trailers	12/31/2021
1st drive j-arms	1st drive j-arms replaced with 2 x new arms	12/24/2021

drive fault	replaced centre diff fitted second hand unit from 643	12/29/2021
Replace Compressor	carry out replace compressor	01/05/2022
Kenworth Prime Mover (B Service)	Service asset as per attached service sheet	12/31/2021
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	01/02/2022
flat battery's	fitted new battery's	12/09/2021
air leak at tractor protection valve	air leak at tractor protection valve fitted valve off 643	12/02/2021
defects	no window washers trailer lights diff lock to operate check adjust ride height check trailer spring packs check movement in PM turntable!	12/15/2021
Replace Belt Tensioner & Drive Belts	Carry out replacement of Belt Tensioner and Drive Belts	12/14/2021
Replace Air Dryer Filter	Carry out replacement of Air Dryer Filter	12/14/2021
Carbon Burn	no needed on this truck	12/14/2021
Replace Jackshaft Uni Joints	Carry out replacement of Jack Shaft Unis	12/08/2021
Replace Final Drive Oil	Carry out replacement of Final Drive Oil	12/14/2021
Replace Gearbox Oil & Filter	Carry out replacement of Gearbox Oil & Filter	12/14/2021
Replace Gearbox Oil & Filter	double up the truck is parked up with suspension issues	12/13/2021
Replace Fan Hub	Carry out replacement of Fan Hub	12/14/2021
Replace Diff Oil	Carry out replacement of Diff Oil	12/14/2021
Hydraulic hose burst	replaced burst hose	12/06/2021
Replace Compressor	not to be carried out on this truck	12/07/2021
Replace Unit Injectors	N/A for this truck	12/02/2021
Replace Belt Tensioner & Drive Belts	N/A for this truck	12/02/2021
Replace Exhaust Manifold	N/A for this truck	12/02/2021
Replace Turbo	N/A for this truck	12/02/2021
Replace Air Dryer Filter	not to be carried out on this truck	12/07/2021
Carbon Burn	N/A for this truck	12/02/2021
Inspect and Clean Radiator	Carry out inspection and clean of Radiator	12/02/2021
Replace Jackshaft Uni Joints	Carry out replacement of Jack Shaft Unis	12/02/2021

Replace Final Drive Oil	not to be carried out on this truck	12/07/2021
Replace Gearbox Oil & Filter	not to be carried out on this truck	12/07/2021
Replace Fan Hub	Carry out replacement of Fan Hub	12/02/2021
Replace Diff Oil	not to be carried out on this truck	12/07/2021
Replace Diffs	not to be carried out on this truck	12/07/2021
Replace Transmission	not to be carried out on this truck	12/07/2021
Replace Cylinder Head	N/A for this truck	12/02/2021
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	12/01/2021
refit drivers step	refit drivers step	11/24/2021
drivers seat gear lever boots	replace drivers seat fir pass seat replace gear lever boots repaired bent lower drivers step	11/27/2021
Replace Air Dryer Filter	Carry out replacement of Air Dryer Filter	11/26/2021
Replace Final Drive Oil	Carry out replacement of Final Drive Oil	11/26/2021
Replace Gearbox Oil & Filter	Carry out replacement of Gearbox Oil & Filter	11/26/2021
Replace Diff Oil	Carry out replacement of Diff Oil	11/26/2021
Kenworth Prime Mover (B Service)	Service asset as per attached service sheet	11/26/2021
DEFECTS	repaired window washers checked diff lock operation ok adjusted speedo senders replaced engine oil temp sensor replaced cross member gusset reattached drivers door card repaired trailer lights	11/26/2021
Carry out C Service as per every 1,000 hours.	Carry out C Service as per every 1,000 hours.	11/26/2021
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	11/26/2021
0672 - Ring gear von fly wheel	Remove gear box clutch fly wheel.	11/03/2021
Replace Ring Gear As Truck Wont Start	Remove Driveshaft,gearbox,clutch,flywheel Fit new flywheel Refit clutch,gearbox, drive shaft Replace starter motor as gear is broken	11/07/2021
0656 - no start	remove starter to find starter gear u/s and ring gear on fly wheel u/s, needs new fly wheel and starter 751798 km	10/21/2021

REPLACE DRIVE SHAFT CARRY OUT REPAIRS	REPLACED DAMAGED DRIVE SHAFT CARRIED OUT DEFECT REPAIRS REPLACED 1ST DIFF OUTPUT SEAL REPLACED 1ST DIFF C/O 2ND DIFF INPUT SEAL C/O CAB SHOCK C/O CAB AIRBAG AIR LINES REMOVE AND OVER HAUL COOLING PACK	10/19/2021
0441 - DIFFERENTIAL ISSUE	FIT DIFFERENTIAL	10/10/2021
0520 - draw bar	replaced lead draw bar 740410 km 35032 hr	09/29/2021
Kenworth Prime Mover (A Service)	Carry out a service as per service sheet	11/09/2021
0421 - Radiator leaking	Pull in/out radiator 355,439 kms	09/29/2021
Replace Belt Tensioner & Drive Belts	AS PER SERVICE SHEET	09/28/2021
Replace Air Dryer Filter	AS PER SERVICE SHEET	09/28/2021
Carbon Burn	AS PER SERVICE SHEET	09/28/2021
Replace Final Drive Oil	AS PER SERVICE SHEET	09/28/2021
Replace Gearbox Oil & Filter	AS PER SERVICE SHEET	09/28/2021
Replace Fan Hub	AS PER SERVICE SHEET	09/28/2021
Replace Diff Oil	AS PER SERVICE SHEET	09/28/2021
Kenworth Prime Mover (B Service)	carry out service and in for major repairs	09/28/2021
Kenworth Prime Mover (A Service)	AS PER SERVICE SHEET	09/28/2021
Kenworth Prime Mover (A Service)	AS PER SERVICE SHEET	09/28/2021
Kenworth Prime Mover (A Service)	AS PER SERVICE SHEET	09/28/2021
0410 - cab air bag hole and aircon belt snap	replaced cab air bag replaced a/c belt 744685 km	09/14/2021
0407 - recover from Yaka breakdown	replace/crimp hydraulic hose replace airline fittings x3 746814 km	09/15/2021
YAK 0415 - SNAP ROPE WIRE T3 BACK & FRONT	REPLACED ROPE WIRE X 2 T3 9471362	09/19/2021

YAK 0414- AIR STARTING ISSUE	RELEASED SOLENOID 746927 KMS	09/18/2021
1524 - BROKEN WHEEL STUDS	CHANGE WHEEL STUDS ON T21054 745383 KM 35215 HR	09/16/2021
0840 - Radiator hose leaking	Replaced radiator hose 943,022 km	09/09/2021
1631 - Uni joints	Replace uni joints middle to front diff 741,966 km 35,086 hours	09/08/2021
0942 - Blown out drive air bag (left hand) front	Replace drive air bag left hand front 743,338 km	09/12/2021
0089 - Ride height	Repair bent ride height rod and adjust 740,410 km 35,032 hour	09/05/2021
Torque Rod and AC Belt	Repair/ Weld torque rod 2nd dolly pos 2 fix AC Belt	09/05/2021
Gearbox Replacement	Fitted new gearbox	08/28/2021
Blown Hydraulic Filter	Bypass hydraulic filters Filter blew due to return tap hit closed from rock	08/30/2021
Cracked Door Hinge	Weld and brace door hinge	09/03/2021
S Cam Damage	Cut, Straighten, Re-weld S-Cam Bracket	09/02/2021
0081 - Cracked door hinge	Weld + brace door hinge 739,009 km 84,981 hours	09/03/2021
0078 - Bent S cam - rock damage	Cut, straighten + reweld S cam bracket 738,539 km 34,962 hours	09/02/2021

0073 - Blown hydraulic filter	Bypass hydraulic filter Filter blew due to return tap hit closed from rock 735,872 km	08/30/2021
0069 - Gearbox replacement	Finish fitting gearbox 735,872 km	08/28/2021
FMC - MT Data - MDVR Channel State Error - PRM00646 - South West - Bulk - Yakabindie - 18:53 Fri 27 Aug 21 (AWST)	Inspected and found camer 3 dropping out, replaced drivers rear facing camera lead as required. Tested all ok.	10/05/2021
Rocker Box	Replaced rocker box Pos 4 - T2	08/24/2021
1207 - SECURE D SHAFT	SECURED D SHAFT 735870 KM 34852 HR	08/24/2021
1201 - OIL LEAK FILTER HOUSING	SECURED END BUNG ON OIL SENDER MANIDOLF REPAIR OIL GAUGE (?) WIRING PARTS NEEDED: COOLANT LEAK COOLING PACK 735880 KM	08/25/2021
1205 - 10X BROKEN WHEEL STUDS POS 6	REPLACED LEAD TRAILER POS 6 HUB 735870 KM	08/24/2021
1627 - REPLACE BOOSTER	REPLACE BOOSTER PARTS NEEDED: BOOSTER 734693 KM 34812 HR	08/22/2021
Broken Rim	Remove and Replaced broken rim on 2nd trailer hub POS 5	08/25/2021
D Shaft	Secured D Shaft	08/24/2021
Oil Leak Filter	Secured end bung on oil sender manifold Repair oil gauge housing	08/25/2021
Broken Wheel Studs	Replaced Hubs on lead trailer POS 6	08/24/2021
Kenworth Prime Mover (B Service)	Carry out B Service	09/15/2021
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	08/23/2021
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	08/17/2021
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	09/15/2021

FMC - MT Data - MDVR Hard Drive State Error - PRM00646 - South West - Bulk - Yakabindie - 15:05 Fri 13 Aug 21 (AWST)	Inspected asset found no issue with Hard drive state.	10/05/2021
1513 - BROKEN SPRING PACK	CHANGE SPRING PACK X1 34515 HR	08/08/2021
0220 - BROKEN BIN PIN	REPAIR BIN PIN REPLACE DOOR KICKER 34494 HR	08/06/2021
WOR - 2958 AC, MINE RADIO, PASSENGER DOOR & WINDSCREEN WIPERS	works completed	08/04/2021
0826 - Hydraulic leak 1st dolly	Replace hydraulic hose on dolly Test okay 34,413 hours	08/02/2021
0823 - Exhaust leak/steering	Replace broken exhaust Replaced steering column unserviceable Located air leak NO ODO	08/01/2021
0821 - Ride height - D line vibration	Re-set ride height 34,397 hours	07/31/2021
0205 - Broken exhaust causing air lines to blow	Repair air leaks Finish off after Andy repaired exhaust Change tyres Replace booster 34,410 hours	07/31/2021
0819 - Front D-snap, rear bolts snapped	Replace snapped bolts Replaced damaged oil pipe 34,388 hours	07/30/2021

0812 - Steering knock, radiator support stats	Secured loose spring hangers on steer axle Remove both radiator support stats Replace bushes and straightened 34,363 hours	07/29/2021
0807 - Trailer lights	Repair wiring short to dog trailer 34,334 hours	07/28/2021
0807 - TRAILER LIGHTS	REPAIR WIRING SHORT TO DOG TRAILER 34334 HR	07/28/2021
1293 - STUCK ON ROCK, BUSTED DRIVE SHOCK	REMOVE ROCK FIX AND REPLACE SHOCK 715673 KM	07/23/2021
1591 - BRAKE DRAG	CHECK TRAILER SET, ADJUST BRAKES AND TEST - OK 34309 HR	07/26/2021
Replace Belt Tensioner & Drive Belts	COMPLETED	08/04/2021
Replace Air Dryer Filter	COMPLETED	08/04/2021
Carbon Burn	COMPLETED	08/04/2021
Replace Final Drive Oil	COMPLETED	08/04/2021
Replace Gearbox Oil & Filter	COMPLETED	08/04/2021
Replace Fan Hub	COMPLETED	08/04/2021
Replace Diff Oil	COMPLETED	08/04/2021
Carry out C Service as per every 1,000 hours.	COMPLETED	08/04/2021
Kenworth Prime Mover (A Service)	COMPLETED	08/04/2021
FMC - MT Data - MDVR Channel State Error - PRM00646 - South West - Bulk - Yakabindie - 14:25 Mon 26 Jul 21 (AWST)	COMPLETED	08/04/2021
1261 - HYD LEAK AND RETORQUE	34088 HR REPAIR HYD LEAK ON REAR OF DOG TRAILER RETORQUE TRAILER SET	07/15/2021

1272 - COOLANT LEAK	HEATER TAP BROKE FITTING OFF TURN TAPS OFF AND TOP UP COOLANT 34153 HR	07/18/2021
1269 - LOOSE ROPES	TENSION 2X ROPES 34130 HR	07/17/2021
1256 - BLOWN HYD HOSE	REMOVE AND REPLACE HYD HOSE MAKE NEW HYD HOSE 34069 HR	07/14/2021
0389 - Dog trailer rear bar damage, lights, chassis crack 1st dolly	Construction new rear bar for dog trailer, fit and wire new tail lights and test ok. Weld crack in chassis brace at rear of dog trailer Fit new turntable packer to 1st dolly 33,974 hours	07/09/2021
0383 - Wiper Fault	Replace wiper switch Repair wiring to wiper motor Repair left hand wiper arm 33,974 hours	07/07/2021
0394 - Air bags 2x	Replace 2x rear air bags 34,020 hours	07/11/2021
Carry out C Service as per every 1,000 hours.	Completed C Service	07/26/2021
Kenworth Prime Mover (B Service)	Carried out B Service	07/26/2021
Kenworth Prime Mover (A Service)	COMPLETED	08/04/2021
Kenworth Prime Mover (A Service)	COMPLETED	08/04/2021
0124 - TAIL SHAFT	33973 KM FIT NEW TAIL SHAFT	07/03/2021

02954 - REAR LIFT CYLINDER LEAKING BADLY (395), REAR LIFT CYLINDER LEAKING SLIGHTY (396?), CAB SHOCKY UNDER CABLE AIR BAG	Completed	05/17/2021
03129 - REPLACE WHEEL HUB ON DOG TRAILER POS 3 TST644	Completed	05/27/2021
03204 - SERVICE AND REPAIRS	REPLACE T2 POS 5 BOOSTER EXHAUST HEAT WRAP REPLACED 33772 HR	05/26/2021
02952 - SEE WORK PLAN	ALL WORK COMPLETED 699953 KM 33604 HR	05/26/2021
02951 - SEE WORK PLAN	ALL WORK COMPLETED 699953 KM 33604 HR	05/26/2021
WR 03021 - SEE WORK PLAN	Completed	05/25/2021
02605 - REMOVE DRIVER SIDE HAND RAIL FOR REPAIRS	REMOVE DRIVER SIDE HAND RAIL FOR REPAIRS 33814 HR 337754 KM	06/02/2021
WR 02608	COOLANT DRAIN TAP WORKED ITS WAY OPEN REFILL COOLANT 705394 KM 33824 HR	06/03/2021
02807 - REPLACED HYDRAULIC PUMP, LOW FLOW AT 1200 PSI	REPLACED HYDRAULIC PUMP, LOW FLOW AT 1200 PSI 13922 HR	06/14/2021
0256 - PTO PRESSURE	REPLACE SUCTION WIRE 33918 HR	06/13/2021
02773 - Replace power steering pump, replace hydraulic fan pump, replace interior plate	Replace power steering pump, replace hydraulic fan pump, replace interior plate 33,908 kms	06/10/2021

02774 - Fit tail shaft bolts, fit new brake booster to #2 trailer pos 4	Fit tail shaft bolts, fit new brake booster to #2 trailer pos 4 707,558 kms 33,910 hours	06/11/2021
02952 - See work plan	Bolt on chassis rail behind cab D/S, top row behind tool box not tightened up Need eyelets welded on bull bar bolts or change so can do it pre-start without wasting time chasing spanner or socket Drive line vibration. Start at 6km/h 7th direct, becomes more prominent 7th OD 62+km/h. Continues 8th direct. Runs out 83-84km/h. Can be felt through clutch only under accelerator. Snapped rope front bin, front rope Pully needs grease	06/15/2021
02951 - See Work Plan	COMPLETED	08/04/2021
02954 - Rear lift cylinder leaking badly, rear lift cylinder leaking slightly, cab shockie unserviceable air bag	Completed	05/27/2021
03204 - Replace T2 POS 5 booster, exhaust heat wrap replaced	Replace T2 POS 5 booster, exhaust heat wrap replaced 33,772 hours	05/26/2021
WR 03021	HOOK UP TO SET FIT NEW BEARINGS, RELINE BRAKES, WELD BOOSTER BRACKET. FIT NEW BOOSTER, UNSEIZE SCAMS, FIT NEW SCAM AND TUBE ON DOL496 REPLACE ROPE PULLEY ON TST645 33772 HR	05/25/2021
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	07/11/2021
02946 - MOVED CAB RIDE HEIGHT VALVE ARM, ADJUSTED LINKAGE	MOVED CAB RIDE HEIGHT VALVE ARM, ADJUSTED LINKAGE 700853 KM 33646 HR	05/12/2021

00071 - CHANGE FLEXI EXHAUST PIPE, FIX AIR LEAKS FOR GEAR SELECTOR	CHANGE FLEXI EXHAUST PIPE, FIX AIR LEAKS FOR GEAR SELECTOR	05/14/2021
03091 - VERBATION IN DRVE LINE	WENT FOR DRIVE COULDN'T FAULT CHECK DIFF/AIRLINE/TAILSHAFT/JACK SHAFTS FIED AIR BAGS 700618 KM 33636 HR	05/11/2021
Kenworth Prime Mover (B Service)	Service asset as per attached service sheet	05/17/2021
FMC - MT Data - MDVR Channel State Error - PRM00646 - South West - Bulk - Yakabindie - 22:45 Mon 17 May 21 (AWST)	replaced driver side rear face cable	07/07/2021
03119 - REPLACE AIR BAG POS 6	33600 HR WORKS COMPLETED	06/02/2021
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	07/11/2021
03119 - REPLACE AIR BAG POS 6	33600 HR	05/01/2021
WR 02915	33586 HR CARRIED OUT B SERVICE REMOVED TURNTABLE REPLACED MISSING REAR CROSS MEMBER BOLTS REPLACED MISSING BOLT FROM POS 3 SHOCK POS 7 AIR BAG LOWER BOLT REPLACED INFLATED LH AIR BAGS AS FOLDED OVER REPAIRED LOWER STEP DRIVERS SIDE REFITTED/REWIRED RH SPOT LIGHT REPAIRED RHF INDICATOR WIRING REPAIRED HYDRAULIC TANK CAP	04/23/2021
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	04/29/2021

00106 - Brake lock on yard release block/stitch unblocked - all okay, Frijz(incomprehensible) back of brakes to get to work shop	Brake lock on yard release block/stitch unblocked - all okay, Frijz(incomprehensible) back of brakes to get to work shop 689,001	03/28/2021
02545 - Brake lock up hard boost bypassing booster	Brake lock up hard boost bypassing booster 687,666km	03/26/2021
00830 - Remove gearbox and clutch	Remove gearbox and clutch 33,584km	03/30/2021
01328 - Cracked over gearbox for structure in gear clutch faultline not releasing properly	Cracked over gearbox for structure in gear clutch faultline not releasing properly 33,582 hours 399,552 km	03/30/2021
01546 - Replace rope, replace 2x kicker springs	Replace rope, replace 2x kicker springs 698,421 km	03/27/2021
02529 - Coolant leak, no filter	Coolant leak, no filter 695,000km	06/02/2021
Kenworth Prime Mover (B Service)	Service asset as per attached service sheet	04/08/2021
WR 01314	REMOVED GEARBOX REMOVED TOP COVER FOUND BRASS FILLING IN BOTTOM 694032 KM 33361 HR	03/16/2021

WR 01315	694032 KM 33361 HR SWAPPED OVER PARTS FROM OLD BOX TO NEW CLEANED OLD GEARBOX FOR RETURN FITTED NEW GEARBOX TO VEHICLE ADJUSTED CLUTCH STRAIGHTENED FUEL TANK CROSS BRACE REPAIRED AIR LEAKS AT SPLIT RANGE REPLACED SEIZED CLUTCH LINKAGE PIVOT BOLT UNSEIZED CLUTCH PIVOT SHAETS	03/17/2021
WR 02504	1ST DOLLY WELD PACKER ON RHS OF TURNTABLE FIT NEED NEW HEADLIGHT HIGH BEAM SPOTLIGHT, CASING BROKEN 694827 KM	03/19/2021
02509 - ROCK REMOVAL AND BLOWN HYDRO FILTER	695443 KM 33414 HR	03/21/2021
02514 - KEEPS BLOWING FILTER. CHECK FINE FROM FILTER TO TANK ALL OK. CHECK OLD FILTER HOUSING U/S. CAUSE BY HEAT	KEEPS BLOWING FILTER. CHECK FINE FROM FILTER TO TANK ALL OK. CHECK OLD FILTER HOUSING U/S. CAUSE BY HEAT 69544 KM 33415 HR	03/22/2021
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	03/31/2021
01533 - WELD TURNTABLE	690534 KM WELD TURNTABLE	03/08/2021
01201 - SEE WORK PLAN	WELD SCAM BRACKETS X2, BRAKE BOOSTER BRACKETS X3, REPLACED 3X BRAKE BOOSTERS AND 3X SPRING PACK ON TST660 X1, DOLLY 522 X2 686064 KM	02/27/2021

00387 - WELD TURN TABLE SPACERS	WELD TURN TABLE SPACERS 690734 KM	03/12/2021
01305 - B SERVICE. RESECURED S CAM MOUNT TO AXLE ON 2ND DOLLY POS 3	691292 KM 33270 HR	03/10/2021
00817 - FIX CAB AIR BAG LEVER VALVE	FIX CAB AIR BAG LEVER VALVE 33102 HR	02/22/2021
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	03/07/2021
00336 - cab air bag valve, lights, windscreen wipers	32911 hr cab air bag valve, lights, windscreen wipers	02/16/2021
00334 - NOT HOLDING AIR BOOSTER, FIX WINDSCREEN WIPERS	NOT HOLDING AIR BOOSTER, FIX WINDSCREEN WIPERS 32901 HR	02/15/2021
00338 - FREE UP YOKE SHAFT AND ADJUST CLUTCH - GREASE THROUGHOUT BEARING AND LINKAGES	FREE UP YOKE SHAFT AND ADJUST CLUTCH - GREASE THROUGHOUT BEARING AND LINKAGES 682591 KM	02/18/2021
00330 - AIR CON	FITTED FANS AND COOLER - DIAGNOSE AIR CON AND RE-GASED 679707 KM	02/13/2021
Carry out D Service as per every 2,000 hours.	Carry out D Service as per every 2,000 hours.	02/20/2021
Kenworth Prime Mover (C Service)	Service asset as per attached service sheet	03/01/2021
Carry out D Service as per every 2,000 hours.	Service asset as per attached service sheet	02/16/2021
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	02/16/2021
Kenworth Prime Mover (A Service)	asset parked up for repairs	01/05/2021
Kenworth Prime Mover (C Service)	Service asset as per attached service sheet	01/06/2021
Kenworth Prime Mover (A Service)	asset parked up for repairs	01/05/2021
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	12/09/2020

Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	12/01/2020
Kenworth Prime Mover (B Service)	Service asset as per attached service sheet	11/20/2020
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	11/24/2020
23781 - Clevis snapped off back trailer	Refurbish clevis back on	09/25/2020
Kenworth Prime Mover (A Service)	carry out service as per service schedule	11/10/2020
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	10/31/2020
23092 - No prime mover brakes	Adjust brakes 667,600km	10/06/2020
23617 - Yoke broken in driveshaft, hydraulic hose broken TST649	Yoke broken yoke/uni 1x Replaced hydraulic hose	02/06/2021
Kenworth Prime Mover (B Service)	Service asset as per attached service sheet	10/24/2020
FMC - DSSi - Vehicle not reporting more than 3 days - Trk PRM00646 Goldfields Mt Keith - 18 Oct 2020	Found vehicle reporting all okay 671242km	10/29/2020
fab and weld new rear guard bracket	fab and weld new rear guard bracket	10/14/2020
Kenworth Prime Mover (A Service)	Carry out service	10/16/2020
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	10/13/2020
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	10/13/2020
Kenworth Prime Mover (C Service)	carry out service as per attached	09/27/2020
22938 - Bag keep dropping on right hand side tipping hazard	Fix air leak Fit two new ride height valves rehose 31943km	09/06/2020
22923 - A/C not working	Wire out of compressor pulled out Reconnected wire, reset circuit breaker 31761km	09/03/2020
23774 - Getting hot loaded, alarm	Run fan hub test Fit new fan hub, run another test and check	09/15/2020
23776 - A/C not blowing	Clean evaporator extinguisher, hook vents up 657,491km	09/15/2020
22768 - Broken rope wire	Carry out repairs Repaired/replaced wire ropes 65,749km	09/15/2020

23757 - Steering hard to turn	Replace steering ram and drag link, replace steering box Pull steering pump off, accessory drive was worn, replace accessory drive and steering pump 32,022Hr	09/11/2020
22946 - Booster been smacked off	Remove booster Re-fit new booster Got track back into workshop and bent boost bracket back Adjusted brakes 318,531km Pasrt Used 1x 30/30 booster	09/08/2020
Kenworth Prime Mover (A Service)	Carry out A service	09/21/2020
22923 - A/C not working	Wire out of compressor pulled out. Reconnected wire reset circuit breaker	09/03/2020
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet Remove diff yoke, get rest of broken yoke out	09/15/2020
22869 - Front diff yoke snapped in diff	Kms/Hours 651,254km 31,704Hr Parts Used New diff yoke	08/28/2020
22910 - Hot brake	carry out repairs	11/30/2020
Kenworth Prime Mover (A Service)	Complete km 704,000km	09/07/2020
23015 - Booster 2x	Remove and replace damaged boosters, check for operation	08/21/2020
23029 - Not starting	Truck not starting on weighbridge, start truck and move off bridge	08/23/2020

Kenworth Prime Mover (B Service)	truck has been parked up this week for repairs	08/30/2020
Kenworth Prime Mover (A Service)	truck parked up for hungry boards	08/18/2020
Kenworth Prime Mover (A Service)	Completed service	08/08/2020
Kenworth Prime Mover (B Service)	Carry out service	08/01/2020
Kenworth Prime Mover (A Service)	trucked and trailers parked up due to engine problems	07/27/2020
Kenworth Prime Mover (A Service)	truck has had engine issues after rebuild from cummins and has gone back for repairs service and oil change etc is being covered in the repairs	07/21/2020
Kenworth Prime Mover (A Service)	A Service and repairs	07/10/2020
FMC - DSSI - vehicle not reporting more than 5 days - TRK PRM00646 Goldfields Mt Keith - 04 Jul 2020	truck was in cummins Kalgoorlie turned off getting engine work done	07/25/2020
Kenworth Prime Mover (C Service)	Service asset as per attached service sheet	07/04/2020
repairs as per work request	CLUTCH ADJUSTED SR3 TRAILER BRAKE VALVE REPLACED DRIVING LIGHT WIRING REPAIRED AIR BAG SWITCH REPLACED	07/27/2020
no beacons and fuse blown and fix electrical fault	no beacons and fuse blown and fix electrical fault	06/27/2020
Kenworth Prime Mover (A Service)	Complete	06/29/2020
FMC - DSSI - Camera misaligned - PRM00646 - South West Bulk - Yakabindie - 14:57 Tue 23 Jun 20 (AWST)	Repairs carried out by contractor from Guardian	06/23/2020
Kenworth Prime Mover (A Service)	B Service, top up wheel ends, P/S fluff diff, service fire extinguisher, grease to 1x booster bracket snapped	06/21/2020
Kenworth Prime Mover (B Service)	B SERVICE	06/11/2020
FMC - DSSI - Camera Misaligned - PRM00646 - South West Bulk - Yakabindie - 18:45 Tue 09 Jun 20 (AWST)	realign camera	06/15/2020
Kenworth Prime Mover (A Service)	A Service complete	06/07/2020
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	05/28/2020
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	05/25/2020
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	05/16/2020
Kenworth Prime Mover (B Service)	Service asset as per attached service sheet	05/16/2020
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	05/13/2020
Kenworth Prime Mover (A Service)	Service complete	05/03/2020

FMC - DSSi - Camera Misaligned - PRM00646 - South West Bulk - Yakabindie - 09:15 Fri 24 Apr 20 (AWST)	repair fault	05/15/2020
Kenworth Prime Mover (A Service)	Service asset as per attached service sheet	04/28/2020
Brake Inspections	Carry out brake audit	04/18/2020
Kenworth Prime Mover (C Service)	Service asset as per attached service sheet	04/17/2020
Repair centre trailer spring pack wear plates, repair king post pivot mounts on dollies, repair torque rod mount chassis	Carry out repairs	05/26/2020
Repair centre trailer spring pack, wear plates, repair king post pivot mounts on dollies, repair torque rod mount chassis	CARRY OUT REPAIRS TO TRACK	05/26/2020
Repair fuel tank bracket, straighten damaged mud guard	cARRY OUT REPAIRS	05/26/2020
Air leak on rom	REPAIR AIR LEAK ON PLATE	05/26/2020
repairs as per work request	repairs as per work request	05/26/2020
22813 - Air leak	Replace U/S air fitting on lead trailer	04/13/2020
Kenworth Prime Mover (A Service)	Carry out service	04/11/2020
Hubs damaged	REPLACE DAMAGED UNSERVICEABLE	05/26/2020
22808 - Trailer rope roller failed	Replace 3x roller, front of lead trailer	04/05/2020
22651 - Right hand door window full of oil	Fix with super glue	04/02/2020
22802 - Hydraulic leak	Removed hydraulic feed hose between 2nd and lead trailer, made new hose. Refit	04/02/2020
Kenworth Prime Mover (C Service)	Service asset as per attached service sheet	04/17/2020
wheels fell off remove and replace and refit new wheels	wheels fell off remove and replace and refit new wheels	03/21/2020
fit new ride height control	fit new ride height control Removed air lines. Removed old ride height control valve and fit new valve	03/22/2020
ride height valve remove and replace	ride height valve remove and replace Inspected cab air bags and found no air supply to bags. Removed ride height valve and found to be faulty. Plumbed up airline to damaged bags until parts arrive	03/22/2020

airbag spilt	airbag spilt Jacked up cab - Removed split bag and shock. Fit new shock air bag and stabilizer bar	03/22/2020
light bar broken off rewelded	light bar broken off rewelded	03/22/2020
Kenworth Prime Mover (B Service)	B SERVICE	03/26/2020
FMC - DSSI - Camera misaligned - PRM00646 - South West - Bulk - Yakabindie - 04:30 Thu 19 Mar 20 (AWST)	Realigned camera + test	05/08/2020
Not tipping	Pull out hydraulic pump, check pressure and replaced other hydraulic pump from other truck	03/12/2020
Loss of drive	Load tools, travels to MT Keith, inspect ubit drive loss. Return to work hop for parts, yolk on gearbox damaged. Remove yoke from s/hand gear box to get unit going Task take over by contact filter	03/11/2020
Kenworth Prime Mover (A Service)	B SERVICE	03/13/2020
fit new air bag to left middle axle	fit new air bag to left middle axle	03/08/2020
FMC - MT Data - MDVR channel state Error - PRM00646' - South West - Bulk - Yakabindie	fixed by aidan	03/15/2020
Replace torque rod	Replaced 1x drive torque rod	03/02/2020
Fix compressor cooling line	FIX COMPRESSOR INC MAKE NEW HOSES	05/26/2020
Kenworth Prime Mover (A Service)	COMPLETE AS PER YAK-003-812 TO ERASE DUPLICATES	03/05/2020
Replace clutch	Replace clutch, remove tailshat, centre bearing, fuel tank support brackets, gear stick. Remove gear box, clutch, fit new clutch, clutch broke, unzeized selector fork cross shaft. Refit tailshaft, fuel tank support brackets. Refit gearstick carried out clutch adjustment, tagged up gearbox oil. Top up hydraulic oil	02/24/2020
FMC - DSSI - Vehicle not reporting - PRM00646' - South West - Bulk - Yakabindie - 15:15 Thu 27 Feb 20 (AWST)	fixed by Aidan	03/15/2020
installation of steering coloum	installation of steering coloum	02/24/2020
FMC - MT Data - MDVR Connection Error - PRM00646' - South West - Bulk - Yakabindie - 19:10 Wed 19 Feb 20 (AWST)	FIXED BY AIDAN	03/15/2020

Kenworth Prime Mover (A Service)	A Service	03/05/2020
Kenworth Prime Mover (A Service)	COMPLETE AS PER YAK-003-812 TO ERASE DUPLICATES	03/05/2020
Repair Work - bushing replacement	Pressed out bushes and pressed new ones in Started removing tapered pin, remove block and press rest of the way	08/08/2019
Repair Work - Broken Torque bolts	Replaced pos 1 airbag Front diff snapped torque rod bolts causing diff to walk side to side	08/02/2019
Repair Work - replace Torque rod assembly and repair air leaks	Replaced Torque rod assembly Repair multiple air leaks	08/06/2019
FMC - DSSi - GPS Not Detected - Trk, PTK754 - South Australia - Bulk - Whyalla - 06:51 Tue 06 Aug 19 (AWST) - Site to moderate as required	Checked all connections and equipment. all connections, fuses, lights working at time of inspection. Checked both antenna's	08/08/2019
FMC - MT Data - MDVR Connection Error - Trk, PTK754 - South Australia - Bulk - Whyalla - 19:45 Mon 05 Aug 19 (AWST) - Site to moderate as required	Checked all connections and equipment. all connections, fuses, lights working at time of inspection. FMC to update firmware	08/08/2019
FMC - MT Data - MDVR Recording Error - Trk, PTK754 - South Australia - Bulk - Whyalla - 19:45 Mon 05 Aug 19 (AWST) - Site to moderate as required	Checked all connections and equipment. all connections, fuses, lights working at time of inspection. FMC to update firmware	08/08/2019
Repair work - Drive tyres required, Swap prime mover	Replaced drive Tyres and torque all wheel nuts greased drive line Swapped out PTK747 and put PTK754 under trailers Fixed Air bag ride height valve leak	07/17/2019
Repair work - Air bag leak	Replaced leaking Air bag on rear axle due to hole from rock	07/21/2019
FMC - DSSi - Speaker fault - Trk, PTK754 - South Australia - Bulk - Whyalla - 10:50 Fri 26 Jul 19 (AWST) - Site to moderate as required	Checked all connections, mounts antenna's cables	08/06/2019
Repair work - Splitter valve replacement	Fit new Splitter valve to the top of gearbox	05/30/2019
Repair work - Air leak, broken head light, broken working light	Repaired Air leak Replaced broken head light cover Fitted new Right side working light	05/27/2019

Repair work - HYD fitting and filter	Fit new HYD fittings and filter Blank of air tank to gearbox and old trailer plug	05/15/2019
Repair Work - Gear box splitter and cab airbag	Fit air valve to back of gearbox and fittings Fit all air pipes and fittings back on airtank Fit cab air bag Fit water tank Replace pipes and fitting to foot brake valve	05/13/2019
Repair Work - Gear box issues	Jack up cab to fit top splitter valve refit air pipes to splitter valve Refit bottom splitter valve with air fittings and pipes	05/08/2019
Repair Work - Air Bag Issue	Remove old air bag Replace 1 x new air Bag	05/07/2019
Kenworth Prime Mover (C Service)	As per service sheet	07/19/2019
Repair Work - Cab Air bag issue	Remove Cab Airbags and fit to PTK752	04/16/2019
Repair Work - Replace coolant 5L Replace Top radiator hose 500mm x 75mm Change over Trailer - HYD, air lines disconnect and reconnect	Replace Top radiator hose 500mm x 75mm Change over Trailer - HYD, air lines disconnect and reconnect	04/12/2019
Repair Work - Gearbox splitter issue and PTO	Remove top Splitter switch on Gearbox Remove PTO Switch	04/18/2019
Repair Work - removed Tyre's	removed Tyre's and fitted to PTK753	04/13/2019
Repair Work - Adjust A/C Belt Fitted hose clamp tighten Bottom hose clamp replaced air fitting on air tank re tension hyd filter	Adjust A/C Belt Fitted hose clamp tighten Bottom hose clamp replaced air fitting on air tank re tension hyd filter kms 599428 hrs 28600	04/11/2019
Commissioning work	Site Commissioning and associated repair work DSS Install MTData Install	04/10/2019

