



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

PO Box 4300
Hwy 3 & 864 Secondary
Taber, AB T1G 2E5
Tel (403) 223-2333
Fax (403) 223-1515
Toll Free 1-855-763-1427

K01-1
INVOICE

Ship to:
Invoice to:

IN STORE PICKUP

Branch		*REPRINT* CANNYY	
Date	Time	Page	
02/02/24	16:18:06 (R)	01	
Account No	Phone No	Reference No	
[REDACTED]	[REDACTED]	P70373	
Ship via	Order		
PHILLIP	BOURG/BOOKING		
	G.S.T. No		
	79759 4660 RT0001		
Credit Card No	Salesperson		
	J96		

Parts Description

ORDER#: 141224

** Need a quick update on your Parts, Service or Sales Status?
Text messaging is now available with RME!
Please text your local branch main phone number.

Part#	Description	Bin	ORD	ISS	SHP	B/O	UTTTT	Price	Amount
<i>lots 252, 253, 254, 255</i>									
2115-30	BRG CONE LM6704	352D-2	368	368	368		*	13.07	4809.76
2115-31	BRG CUP LM67010	352D-1	368	368	368		*	8.28	3047.04
2200-11-01	HUB SEAL 33	352J-3	184	184	184		*	9.77	1797.68
2200-11-02	HUB WEAR SLV SE	352J-4	184	184	184		*	3.90	717.60
2200-36-03	WSHR TANG 1 INC	396G-3	184	184	184		*	1.73	318.32
6367-71-50	CNVR BELT LACIN	396A-1	2	2	2		*	124.61	249.22
MRKDIS	MARKETING DISC	9999	1-	1-	1-		*	3044.50	3044.50CR
6718-55-01	SCPR CBD LONG S	51RACKG	92	92	92		*	52.49	4829.08
2301-67	packer	HOOPFLR	100	100	100		*	98.52	9852.00
6367-71-72	BELT ASSY	T066890	1	1	1		*	3306.65	3306.65
6367-71-50	CNVR BELT LACIN	396A-1	1	1	1		*	124.61	124.61
6367-71-50	CNVR BELT LACIN	396A-1	1-	1-	1-		*	124.61	124.61CR

12% discount for early booking parts

SUB TOTAL==> 25882.85
GST 797594660 1294.13
TOTAL CHARGE 27176.98

PAYMENT TERMS: NET 30

Repair kit Done
Mid Row Bander Hub's
One of Four Drill's

Signature

Date


ALL CLAIMS AND RETURNED GOODS MUST BE ACCOMPANIED BY THIS INVOICE.
NO RETURNS ON ELECTRICAL OR SPECIAL ORDER PARTS.
NO RETURNS AFTER 30 DAYS
25% RE-STOCK CHARGE ON ALL RETURNED PARTS.
\$25.00 CHARGE ON ALL NSF CHEQUES.

DISCLAIMER OF WARRANTY

Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

[illegible]

14597 - 2200 - 42 - 10000.



Mid Row Bander (MRB)

Lot#:
VG - Date

MRB III/FHB III - Hub Parts Breakdown

#	PART #	DESCRIPTION	QTY	Note
1	1209-12	NUT 1 SLOTTED UNS THIN BLACK	1	
2	1350-17	WASHER MACHINE 1-1/4X2.20 OUTER DIAMETER X.21	1	
3	1500-10	PIN COTTER 3/16X1-1/2 PLD	1	
4	2115-30	BEARING CONE LM67048 NTN	2	
5	2200-11-01	SEAL TRIPLE LIP	1	
6	2200-36	HUB ASSEMBLY 3710/MRBIII CUPS SLEEVE	1	[1]
7a	2200-36-02	DUST CAP DC33 2200-42-02	1	[2]
7b	2200-42-02	DUST CAP 2200-42 2200-44-02	1	[3]
7c	2200-44-02	DUST CAP 2200-44	1	[4]
8a	2200-41-01	SPINDLE 3720/MRB3 2200-42-01	1	[5]
8b	2200-42-01	SPINDLE 3720/MRB3 2200-44-01	1	[6]
8c	2200-44-01	SPINDLE 3720/MRBIII/FHBIII	1	[4]
9	2115-31	BEARING CUP LM67010 NTN	2	
10	2200-11-02	WEAR SLEEVE SE33-1	1	
11	2010-33	FITTING GREASE STRAIGHT 1/4-28	1	

PART NOTES:

- [1] - C/W Items # 9, 10 11
- [2] - Black Dust Cap
Part was replaced: 2200-36-02 --> 2200-42-02 --> 2200-44-02
- [3] - Nickel Plated Dust Cap
Part was replaced: 2200-42-02 --> 2200-44-02
- [4] - Used on CSElite hub.
- [5] - Used on GKN hub.
Part was replaced: 2200-41-01 --> 2200-42-01 --> 2200-44-01
- [6] - Used on ADR hub.
Part was replaced: 2200-42-01 --> 2200-44-01



Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is “sold as is” no warranties made or implied

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture