



JOHN DEERE

Ship To: [REDACTED]

Invoice To: [REDACTED]
[REDACTED]
[REDACTED]

Branch TABER, AB			*REPRINT*		
Date 11/28/25	Time 23:56:09 (B)	Page 01			
Account No UNRUH002	Phone No [REDACTED]	Inv No W37486			
Ship Via	Purchase Order				
Tax ID No	Agrimart				
					Salesperson 481

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
10052527	9770 STS COMBINE	2054	1H09770SKA0738988	11/20/11	
	9770	1471		11/19/15	1250 P

ST No. 103596318

Visit www.westernttractor.ca to sign up for your secure access to WT Mobile.
For more information, at your convenience.

SEGMENT# 1 C 1662 STS 10/01/25 10/01/25

AG Inspection - STS Combine Performax

AG Inspection - STS Combine Performax

Check over on combine and header.
Threshing elements, rotor, and beaters
Check concave condition and level concave.
All bearings checked for play.
Belt, chains, major drives checked for alignment and Condition
Hyd operation, hoses, and cylinder
Monitors, harness, and electrical switch adjustments
Wheel bearings, steering operation
Grease machine
Check fluids and filters.
Safety shields
Decals and hardware
Remove chaffer and sieve elements. Inspect frame for cracks.
note the labor discount to reduce the performax price is Applied to the misc total.

TY22062	HY-GARD 10L	1	79.50	79.50
3664	ENV FEE 9.46L	1	1.80	1.80
	PARTS			81.30
	LABOR			3145.00

CONTINUED ON PAGE 02

X

Received By

Lethbridge, AB Ph: 403-327-5512 Fax 403-328-2599
Burdett, AB Ph: 403-833-3811 Fax: 403-833-2069
Medicine Hat, AB Ph: 403-526-4450 Fax: 403-527-8569

165043 - Highway #3 • PO Box 4177 • Taber, AB T1G 2C6

Ph: 403-223-3588 • Fax: 403-223-2273

Toll Free: 1-877-666-9300

www.westernt tractor.ca



JOHN DEERE

Ship To: SAME AS BELOW

Invoice To: BRENT UNRUH
PO BOX 14
ROXBALL AB T0K 2K0

Branch TABER, AB		
Date 11/28/25	Time 23:56:09 (B)	Page 02
Account No UNRUH002	Phone No [REDACTED]	Inv No W37486
Ship Via	Purchase Order	
Tax ID No	Agrimart	
		Salesperson 481

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	
00052527	9770	STS COMBINE	2054 1H09770SKA0738988	11/20/11	
	9770		1471	11/19/15	1250 P
10906002				SEGMENT TOTAL==>	3226.30

SEGMENT# 2 C 1662 HAULING 10/01/25 10/21/25
Semi Hauling & Misc Charges (Office Use Only)
Hauled in Sept 29th \$450, to be hauled home
10906002

SEGMENT# 3 C 1662 WASH	11/03/25	11/25/25			
Wash And Clean Unit					
			LABOR		350.00
10906002			SEGMENT TOTAL==>		350.00

SEGMENT# 4 C 1662 DECLINED 11/03/25 11/06/25
Repairs Declined By Customer

SEGMENT# 5 C 1662 QUALITYCHECK 11/03/25 11/17/25
Quality Check, - No Charge
Segment has been billed on work order W37979 - 01

SEGMENT# 6 C 1662 113	11/03/25	11/03/25			
R&R FH drive chain					
Remove and replace chain.					
Check alignment with new chain.					
AH206701	60H CHAIN AS		1 M	312.50	312.50
				PARTS	312.50
				LABOR	92.50
10906002			SEGMENT TOTAL==>		405.00

SEGMENT# 7 C 1662 NA 11/03/25 11/03/25
R&R FH Backshaft bearing

CONTINUED ON PAGE 03

X

Received By



JOHN DEERE

Ship To: SAME AS BELOW

Invoice To: **[REDACTED]**
[REDACTED]
[REDACTED]

Branch TABER, AB		
Date 11/28/25	Time 23:56:09 (B)	Page 03
Account No UNRUH002	Phone No [REDACTED]	Inv No W37486
Ship Via	Purchase Order	
Tax ID No	Agrimart	
		Salesperson 481

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	
00052527	9770	STS COMBINE	2054 1H09770SKA0738988	11/20/11	
	9770		1471	11/19/15	1250 P
AH231479		BEARING WITH	1	348.71	348.71
		Bearing With Housing			
				PARTS	348.71
				LABOR	185.00
10906002				SEGMENT TOTAL==>	533.71

SEGMENT#	C	1662	111.5	11/03/25	11/03/25	
						R&R Reverser Oil
						Drain and fill with oil. Ensure feederhouse raised all the way.
						TY26408 HD460 SYN 1L 1 46.02 46.02
						3659 ENV FEE -1L OIL 1 .18 .18
						PARTS 46.20
						LABOR 120.25
10906002						SEGMENT TOTAL==> 166.45

SEGMENT#	C	1662	117.5	11/03/25	11/03/25	
						R&R Header Latch Pin Cable
						Remove cable.
						Check operation.
						Adjust cable. Ensure latch pins are free
						AH207405 PUSH PULL 1 512.50 512.50
						PARTS 512.50
						LABOR 231.25
10906002						SEGMENT TOTAL==> 743.75

SEGMENT#	C	1662	NA	11/03/25	11/03/25	
						Rear bulkhead bolts
						Remove and replace left 2 bolts.
						H174755 BOLT 2 3.18 6.36
						CONTINUED ON PAGE 04

X

Received By



Ship To: SAME AS BELOW

Invoice To: **[REDACTED]**
[REDACTED]
[REDACTED]

Branch TABER, AB		
Date 11/28/25	Time 23:56:09 (B)	Page 04
Account No UNRUH002	Phone No [REDACTED]	Inv No W37486
Ship Via		Purchase Order
Tax ID No		Agrimart
		Salesperson 481

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	
00052527	9770	STS COMBINE	2054 1H09770SKA0738988	11/20/11	
	9770		1471	11/19/15	1250 P
14M7296		10MM FLANGE	2	1.88	3.76
				PARTS	10.12
				LABOR	92.50
10906002				SEGMENT TOTAL==>	102.62

SEGMENT#11 C 1662 122.001 11/03/25 11/05/25

R&R Concave (STS) Per Concave (Two Or More)

DOES NOT INCLUDE LEVELING

Remove dust shields from left front left side of separator.

Open concaves fully.

Remove pins from eyebolts on concave support.

Unbolt concave support from concaves and remove.

Remove and install concaves.

Install concave support.

Install shields.

10906002

LABOR 508.75
SEGMENT TOTAL==> 508.75

SEGMENT#12 C 1662 122.21 11/03/25 11/05/25

Level And Calibrate Concave

Place rotor gearcase in neutral.

Remove shields.

Remove 1 separator grate to spin rotor.

Adjust concave all the way up.

Back off stop bolts.

Adjust eyebolts til threshing elements tick on concaves

(front and back) then back off one full turn (2mm clearance)

Set stop bolts.

Assemble and calibrate concave clearance.

CONTINUED ON PAGE 05

X

Received By

Lethbridge, AB Ph: 403-327-5512 Fax 403-328-2599
Burdett, AB Ph: 403-833-3811 Fax: 403-833-2069
Medicine Hat, AB Ph: 403-526-4450 Fax: 403-527-8569

165043 - Highway #3 • PO Box 4177 • Taber, AB T1G 2C6

Ph: 403-223-3588 • Fax: 403-223-2273

Toll Free: 1-877-666-9300

www.westerntractor.ca



JOHN DEERE

Ship To: SAME AS BELOW

Invoice To: [REDACTED]
[REDACTED]
[REDACTED]

Branch TABER, AB		
Date 11/28/25	Time 23:56:09 (B)	Page 05
Account No UNRUH002	Phone No [REDACTED]	Inv No W37486
Ship Via	Purchase Order	
Tax ID No	Agrimart	
		Salesperson 481

SERVICE INVOICE

TK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	
10052527	9770	STS COMBINE	2054	1H09770SKA0738988	11/20/11
	9770		1471		11/19/15
					1250 P
					LABOR
10906002					323.75
					SEGMENT TOTAL==>
					323.75

SEGMENT#13 C 1662 133.15 11/03/25 11/03/25

R&R Grain Tank Cross Auger Bearings (Both)

CORRECTION:

- Loosed off chain.
- Removed pulley.
- Removed locking collar.
- Removed plate.
- Removed bearing.
- Installed new bearing.
- Installed plate.
- Installed locking collar.
- Installed pulley.
- Removed locking collar on R/H side.
- Removed and replaced bearing.
- Installed locking collar.
- Same procedure on other cross auger.
- Installed chain.
- Ran and checked operation.

ADDITIONAL DESCRIPTION:

LEFT SIDE:

- Remove chain
- Remove sprocket
- R&R bearing
- Assemble, check sprocket alignment.

RIGHT SIDE:

- R&R bearing.

AH133191 LOCK COLLAR 4 26.74 106.96

CONTINUED ON PAGE 06

X

Received By



JOHN DEERE

Ship To: SAME AS BELOW

Invoice To: [REDACTED]
[REDACTED]
[REDACTED]

Branch TABER, AB		
Date 11/28/25	Time 23:56:09 (B)	Page 06
Account No UNRUH002	Phone No [REDACTED]	Inv No W37486
Ship Via	Purchase Order	
Tax ID No	Agrimart	
		Salesperson 481

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	
0052527	9770	STS COMBINE	2054 1H09770SKA0738988	11/20/11	
	9770		1471	11/19/15	1250 P
		Eccentric Locking Collar			
H141123		NUT	6	2.04	12.24
JD39104		BALL BEARI	4	59.50	238.00
				PARTS	357.20
				LABOR	740.00
10906002				SEGMENT TOTAL==>	1097.20

EGMENT#14 C 1662 NA 11/03/25 11/03/25

Left rear gull-wing door light not working

CORRECTION:

Wires were corroded.

Replaced bulb.

Replaced pins in connector.

Tested light everything worked.

ADDITIONAL DESCRIPTION:

Replace bulb.

AXE16948		BULB 862	2	29.72	59.44
R78059		SEAL	2	.56	1.12
		Electrical Connector Assy			
57M7297		TERMINAL	2	1.41	2.82
		Elec. Connector Terminal			
57M7344		ELEC. CONNEC	1	8.53	8.53
		Elec. Connector Housing			
				PARTS	71.91
				LABOR	64.75
10906002				SEGMENT TOTAL==>	136.66

EGMENT#15 C 1662 ENG SERVICE 11/03/25 11/03/25

Engine Service

Change engine oil and filter

CONTINUED ON PAGE 07

X

Received By



JOHN DEERE

Ship To: SAME AS BELOW

Invoice To: [REDACTED]
[REDACTED]
[REDACTED]

Branch TABER, AB		
Date 11/28/25	Time 23:56:09 (B)	Page 07
Account No UNRUH002	Phone No [REDACTED]	Inv No W37486
Ship Via	Purchase Order	
Tax ID No	Agrimart	
		Salesperson 481

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS		
00052527	9770	STS COMBINE	2054	1H09770SKA0738988	11/20/11	
	9770		1471		11/19/15	1250 P
Change fuel filters						
Change engine air filters						
Change cab filters						
AH168783		AIR FILTER	1	138.48		138.48
AH212295		AIR FILTER	1	256.19		256.19
AH222225		AIR FILTER	1	308.39		308.39
H220870		AIR FILTER	1	86.65		86.65
RE509672		OIL FILTER	1	48.79		48.79
RE523785		BOWL	1 M	118.09		118.09
RE525523		FUEL F KIT	1	193.40		193.40
TY26675		15W40+50II/10L	3	83.64		250.92
	Plus-50 II Oil	15W40 CK4/SN				
3661		ENV FEE-8"+JD	1	1.25		1.25
3662		ENV FEE-8"-JD	1	.55		.55
3664		ENV FEE 9.46L	3	1.80		5.40
		PARTS				1408.11
		LABOR				462.50
10906002		SEGMENT TOTAL==>				1870.61

SEGMENT#16 C 1662 21 11/03/25 11/03/25

Adjust Valves (9L)

CORRECTION:

- Removed shields.
- Removed harness.
- Removed valve cover.
- Removed fuel filter to get at engine flywheel.
- Used tool to turn engine over to TDC #1.
- Adjusted all specified valves.
- Turned engine over 360 degrees to TDC #6.
- Adjusted all specified valves.

CONTINUED ON PAGE 08

X

Received By

Lethbridge, AB Ph: 403-327-5512 Fax 403-328-2599
Burdett, AB Ph: 403-833-3811 Fax: 403-833-2069
Medicine Hat, AB Ph: 403-526-4450 Fax: 403-527-8569

165043 - Highway #3 • PO Box 4177 • Taber, AB T1G 2C6

Ph: 403-223-3588 • Fax: 403-223-2273

Toll Free: 1-877-666-9300

www.westerntractor.ca



JOHN DEERE

Ship To: SAME AS BELOW

Invoice To: [REDACTED]
[REDACTED]
[REDACTED]

Branch TABER, AB		
Date 11/28/25	Time 23:56:09 (B)	Page 08
Account No UNRUH002	Phone No [REDACTED]	Inv No W37486
Ship Via	Purchase Order	
Tax ID No	Agrimart	
		Salesperson 481

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
00052527	9770 STS COMBINE	2054	1H09770SKA0738988	11/20/11	
	9770	1471		11/19/15	1250 P

- Cleaned area.
- Installed new gasket.
- Installed valve cover.
- Torqued hardware.
- Installed harness.
- Installed shields.
- Installed fuel filter.
- Ran and checked operation.

ADDITIONAL DESCRIPTION:

- Remove shields and covers from engine.
- Remove rocker arm cover.
- Adjust valves.
- Assemble in reverse order.
- Test run and check operation.

DZ128866	Gasket	1	87.76	87.76
			PARTS	87.76
			LABOR	980.50
10906002			SEGMENT TOTAL==>	1068.26

EGMENT#18 C 1662 NA 11/03/25 11/03/25

- Repair chaffer bent louver
- Chaffer louver bent.
- Repair and install chaffer.

AE23539	LINK CHAIN	1	85.28	85.28
			PARTS	85.28
			LABOR	92.50
10906002			SEGMENT TOTAL==>	177.78

EGMENT#19 C 1662 NA 11/03/25 11/03/25

- R&R Upper Clean Grain Elevator Bearings And Sprocket

CONTINUED ON PAGE 09

X

Received By



JOHN DEERE

Ship To: SAME AS BELOW

Invoice To: [REDACTED]
[REDACTED]
[REDACTED]

Branch TABER, AB		
Date 11/28/25	Time 23:56:09 (B)	Page 09
Account No UNRUH002	Phone No [REDACTED]	Inv No W37486
Ship Via	Purchase Order	
Tax ID No	Agrimart	
		Salesperson 481

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	
00052527	9770	STS COMBINE	2054 1H09770SKA0738988	11/20/11	
	9770		1471	11/19/15	1250 P
AH133191		LOCK COLLAR	2 O	26.74	53.48
		Eccentric Locking Collar			
H228385		CHAIN SPROCK	1	119.90	119.90
H84026		HOOK	10	.93	9.30
JD39104		BALL BEARI	2	59.50	119.00
				PARTS	301.68
				LABOR	925.00
10906002				SEGMENT TOTAL==>	1226.68

SEGMENT#	DESCRIPTION	START DATE	END DATE	HRS	AMOUNT
20	C 1662 126.15	11/03/25	11/03/25		
	R&R Tailings Drive Chain				
	Remove and replace chain.				
	Check alignment.				
AH231461	FINGER			2	42.94
HXE123427	Bolt			14	2.56
H86248	FINGER			14	3.80
N10217	LOCK NUT			14	1.02
					PARTS 189.20
					LABOR 92.50
10906002					SEGMENT TOTAL==> 281.70

SEGMENT#	DESCRIPTION	START DATE	END DATE	HRS	AMOUNT
21	C 1662 4.2	11/03/25	11/04/25		
	Add Coolant				
	Add coolant.				
TY26575	CGII PREMIX 4L			1	27.03
					PARTS 27.03
					LABOR 55.50
10906002					SEGMENT TOTAL==> 82.53

SEGMENT#	DESCRIPTION	START DATE	END DATE
22	C 1662 NA	11/03/25	11/03/25

CONTINUED ON PAGE 10

X

Received By

Lethbridge, AB Ph: 403-327-5512 Fax 403-328-2599
Burdett, AB Ph: 403-833-3811 Fax: 403-833-2069
Medicine Hat, AB Ph: 403-526-4450 Fax: 403-527-8569

165043 - Highway #3 • PO Box 4177 • Taber, AB T1G 2C6

Ph: 403-223-3588 • Fax: 403-223-2273

Toll Free: 1-877-666-9300

www.westerntractor.ca



JOHN DEERE

Ship To: SAME AS BELOW

Invoice To: BRENT UNRUH
PO BOX 441
VALHALL AB T0K 2K0

Branch TABER, AB		
Date 11/28/25	Time 23:56:09 (B)	Page 10
Account No UNRUH002	Phone No [REDACTED]	Inv No W37486
Ship Via	Purchase Order	
Tax ID No	Agrimart	
		Salesperson 481

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
00052527	9770	STS COMBINE	2054	1H09770SKA0738988
	9770		1471	11/20/11
				11/19/15 1250 P

Header repairs

CORRECTION:

Topped up air on air bags and tires.

Replaced 2 broken rods.

Replaced all broken fingers.

ADDITIONAL DESCRIPTION:

Kirks Tire PO#T8913 \$56.34

-Top-up air bags

-Check LH air bag leaks

-Top-up tires

-Replace broken windscreen hold finger (2)

-Replace broken belt pick-up plastic fingers (14)

AN202547	VALVE	1	59.64	59.64
HXE123427	Bolt	26	2.56	66.56
H86248	FINGER	26	3.80	98.80
N10217	LOCK NUT	30	1.02	30.60
SUBLETAG	TIRE REPAIR	1	56.34	56.34
TY26575	CGII PREMIX 4L	1	27.03	27.03
	PARTS			282.63
	LABOR			1295.00
	SUBLET			56.34
10906002	SEGMENT TOTAL==>			1633.97

EGMENT#23 C 1662 NA 11/03/25 11/04/25

Replace Chopper Drive Belt Idler

AH210837	IDLER	2	405.55	811.10
	PARTS			811.10
	LABOR			92.50
10906002	SEGMENT TOTAL==>			903.60

CONTINUED ON PAGE 11

X

Received By

Lethbridge, AB Ph: 403-327-5512 Fax 403-328-2599
 Burdett, AB Ph: 403-833-3811 Fax: 403-833-2069
 Medicine Hat, AB Ph: 403-526-4450 Fax: 403-527-8569

165043 - Highway #3 • PO Box 4177 • Taber, AB T1G 2C6

Ph: 403-223-3588 • Fax: 403-223-2273

Toll Free: 1-877-666-9300

www.westerntractor.ca



JOHN DEERE

Ship To: SAME AS BELOW

Invoice To: [REDACTED]
 [REDACTED]
 [REDACTED]

Branch TABER, AB		
Date 11/28/25	Time 23:56:09 (B)	Page 11
Account No UNRUH002	Phone No [REDACTED]	Inv No W37486
Ship Via		Purchase Order
Tax ID No		Agrimart
		Salesperson 481

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
00052527	9770 STS COMBINE	2054	1H09770SKA0738988	11/20/11	
	9770	1471		11/19/15	1250 P

***** WORK ORDER TOTALS *****

PARTS	4933.23
LABOR	9849.75
SUBLET	56.34
PMI HAUL DISC	450.00-
PMI LABOR DISC	1550.00-
PMI PARTS DISC	493.32-
SERV SUPPLIES	375.00
T SEMI DELIVERY	900.00
VINTAGE DISC	1447.60-
SUB TOTAL==>	12173.40
GST No. 103596318	608.75
TOTAL CREDIT CARD	12782.15

09554J

I agree to pay above total amount according to card issuer agreement (Merchant agreement if credit voucher).

X

Received By