



SLICK
INSPECTION LTD.
403-581-9887
Medicine Hat, AB

GSY OILFIELD TECHNOLOGIES INC.
226 VISTA CLOSE S.E.
MEDICINE HAT, AB. T1B 0C4
TEL: 403-866-6888

SLICK INSPECTION LTD.
2038 12th AV, N.W.
MEDICINE HAT, AB. T1C 2A7
TEL: 403-581-9887

FILE NO.: GED-26-6671

ENGINEERING CERTIFICATION

EQUIPMENT: PICKER TRUCK
MAKE: HIAB
MODEL: 166B-3 CLX
SERIAL: 16606356
OWNER: WHISELL EQUIPMENT
OWNER UNIT #: 52-771
CERTIFIED DATE: June 6, 2026


Based on thorough inspections performed by Slick Inspection Ltd. on June 1, 2026 described in Slick Equipment Inspection Report No. 26-550, I certify that the critical structural, mechanical and control components of the inspected equipment are safe for continued use in accordance with CSA Z150-11 Section 5.3.2.2 which requires an annual inspection, complete inspection if damaged or disassembled, and telescopic boom magnetic particle inspection every five years.

Equipment must be maintained in accordance with manufacturer's recommendations, operated in safe procedure without exceeding rated capacity. This certification is not transferable to new owner. This certification is valid for a maximum period of one year from the inspection date. The unit is to be reinspected if it sustains damage to a structural area and under any approved repairs.

GSY OILFIELD TECHNOLOGIES INC.



APEGA ID: 83361
June 6, 2026



APEGA ID: 83361

Xiang Gao, P.ENG.



SLICK
INSPECTION LTD.
403-581-9887
 Medicine Hat, AB

GSY OILFIELD TECHNOLOGIES INC.
 226 VISTA CLOSE S.E.
 MEDICINE HAT, AB, T1B 0C4
 PH: 403-866-6888
SLICK INSPECTION LTD.
 2038 12th AV, N.W.
 MEDICINE HAT, AB, T1C 2A7
 PH: 403-581-9887

EQUIPMENT INSPECTION REPORT

Report: **26-550**

CLIENT: Whissell Equipment		DATE: June 1 2026	
EQUIPMENT IDENTIFICATION: Picker Truck		UNIT #: 52-771	
MAKE: Hiab	MODEL: 166B-3 CLX	S/N: 16606356	
CODES: OHSA, CSA Z150-98 & W59-18		LOCATION: Lethbridge Shop	

MAGNITIZATION		PARTICAL		PROCEDURE	
Method:	Yoke S.N 4483	Medium:	Magnaflux	Technique:	MT-3
Current:	Alternating (AC)	Type:	Grey Powder	Surface Cond:	Sand Blasted
Field:	Continuous	Application:	Bottle Puffer	Demagnification:	ASME V Art. 7
				Post cleaning:	Ardrox Cleaner

A full length inspection was conducted on the picker ans outriggers. No indications were found at time of inspection. A certification sticker was placed on the unit after inspection.



INSPECTOR: Brent Ahrens

SIGNATURE: 

Inspector's Stamp
Brent Ahrens CGSB Level II RT MT ASNT Level II RT MT REG. # 5607



SLICK
INSPECTION LTD.
403-581-9887
 Medicine Hat, AB

GSY OILFIELD TECHNOLOGIES INC.
 226 VISTA CLOSE S.E.
 MEDICINE HAT, AB, T1B 0C4
 PH: 403-866-6888
SLICK INSPECTION LTD.
 2038 12th AV, N.W
 MEDICINE HAT, AB, T1C 2A7
 PH: 403-581-9887

EQUIPMENT INSPECTION CHECKLIST

COMPONENTS	DEFECTS	OK	DEFECT IDENTIFICATIONS
Picker Model, S/N on Structure		✓	
Load Rating Chart		✓	
Load Indicator Device (LID)		✓	
Boom Angle Indicator		✓	
Boom Length Indicator		✓	
Outrigger Vertical Rams		✓	
Outrigger Boxes		✓	
Outrigger Extensions		✓	
Outrigger Pads		✓	
Outrigger Welds		✓	
Main Boom		✓	
1st Extension		✓	
2nd Extension		✓	
3rd Extension		✓	
4th Extension		✓	
Boom Rest Hook		✓	
Boom Section Wear Pads		✓	
Boom Head Sheaves		✓	
Rotating Frame Welds		✓	
Structure Members between outrigger box's		✓	
Deck		✓	
Holding Nuts and Bolts		✓	
Visual Control Elements		✓	
Other:			
Other:			

COMMENTS:



Disclaimer

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is “sold as is” no warranties made or implied

Brennan LeBlanc
Divisional Operations Manager
Western Canada Agriculture