

K200

Date	Service	Description	Completed By	Odometer
26/2/2021	repair	new windscreen	A1 Windscreens	N/A
21/4/2021	repair	2 new steer tyres + 2 drive tyres	Browns Tyre Service	223489
31/5/2021	service	Carried out a major service. Changed the engine oil, oil filter, fuel filters, greased & checked the vehicle over	Craig Walsh Mobile Mechanical Repairs	228996
1/7/2021	repair	Check & repair low oil pressure light coming on. Fitted a new sensor as required. Checked operation	Craig Walsh Mobile Mechanical Repairs	234906
21/2/2021	repair + Service	Removed the tappet cover, adjusted all inlet, valves, exhaust valves & Jake brakes as required. Fitted a new Jake brake wiring harness (charged at last service). Fitted the new style stud & nut to locate the wiring harness. Refitted the tappet cover & checked operation of the engine. Changed various parameters in the ECM For PTO & idle timer. Carried out a minor service. Greased & checked the vehicle over	Craig Walsh Mobile Mechanical Repairs	217574
31/8/2021	repair	Check & repair speedo not reading. Removed the speedo head & had it checked at New England instruments. (ok). Swapped the plugs over at the rear of the transmission & test drove. Found that the bottom sensor was at fault. Tried to remove the sensor. the sensor broke off. Had the drill & tap the thread out & fitted a new sensor. adjusted the sensor as required. Test drove the vehicle & checked operation (ok).	Craig Walsh Mobile Mechanical Repairs	243756
1/10/2021	repair	Remove and replace K200 Kenworth Cooling Package and service. Supply and fit new heavy duty core to Radiator, flush engine block and service and test Intercooler. Fit new mounts, hoses and clamps.	GUNRAD	N/A
1/10/2021	repair	Test A/C System on K200. Supply and fit new compressor and drier and TX and fit new H/P Hose. Flush system and regas.	GUNRAD	N/A

K200

15/11/2021	service + repairs	Carried out a major service. Changed the engine oil, oil filter, fuel filters, greased & checked the vehicle over. Check & repair the check engine light on. Found that the exhaust gas pressure sensor was at fault. Checked the plug & the wiring. Fitted a new sensor as required. checked operation & cleared all codes. Cleaned the inlet pressure sensor & the EGR differential pressure sensors as required.	Craig Walsh Mobile Mechanical Repairs	251966
29/3/2022	Service	Carried out a major service. Changed the engine oil, oil filter, fuel filters, greased & checked the vehicle over.	Craig Walsh Mobile Mechanical Repairs	274248
16/5/2022	repair	Replaced 3 hoses for cab ram made new & ends & bled system checked ok.	Brown & Hurley Tamworth	N/A
18/7/2022	repair	Steering Box leaking Oil	Brown & Hurley Tamworth	283029
12/10/2022	repair	Check & repair oil leak. Found that the oil pressure sensor was at fault. Fitted a new sensor as required. (had to removed the fuel filter & the sensor for the gauge to gain access to engine oil pressure sensor). Washed down, checked operation & checked for oil leaks.	Craig Walsh Mobile Mechanical Repairs	N/A
12/1/2023	repair	Truck speedo fault, repaired Fitted new suzi coil and necessary fittings.	Brown & Hurley Tamworth	291108
27/11/2023	repair	4x drive tyres	Browns Tyre Service	296716
17/1/2024	repair	Suppled & fitted a new steering column, Checked operation & positioned the steering wheel in the centre.	Craig Walsh Mobile Mechanical Repairs	297170
14/12/2023	repair	Inspect A/C System in K200 Kenworth. Condenser and Cooling Package blocked externally. Pressure clean components, recheck A/C and add UV Dye.	GUNRAD	N/A

K200

5/3/2023	service	service completed	Namoi Ag and Earthmoving Mobile Mechanics	N/A
----------	---------	-------------------	---	-----

Trucks are serviced every 25,000kms either in house or by contracted mechanic.

** As this was a “back up truck” when it was going to be used, full checks were completed before use.