
DAIMLER



VEHICLE RECALL LOOKUP

ENTER VIN

SUBMIT

1FUJHPDVXKLKA0398

Make : FTL

Model : PE116064S T

Model Year : 2019

1 Unrepaired Recalls
associated with this VIN

FL958-A

-

Nov 01,2022

Nhtsa Recall Number 22V817000

Recall Status 11

Safety Risk

Brakes that pull to one side during an ACC braking event may cause a sudden change in vehicle direction, increasing the risk of a crash.

Remedy

Dealers will inspect and replace the front brake modulator valves, as necessary. Some vehicles will have a software update which will alert driver when a replacement is required. All repairs will be performed free of charge. Owner notification letters were mailed beginning October 16, 2023. DTNA's number for this recall is FL-958. This recall expands and replaces previous recall 20V-390. All vehicles previously repaired under recall 20V-390 will need to have the new remedy performed.

Transport Canada Recall

2022-626

Copyright © 2022 Daimler Trucks North America LLC. [Privacy Statement, Legal Notices and Terms.](#)
(<https://securestage.freightliner.com/accessfreightliner/docs/public/applications/privacy.asp>). All rights reserved.

Daimler Trucks North America LLC is a Daimler company.

Recalls in the U.S. and Canada from January 1, 2005, and later are displayed. For questions about a recall on your vehicle, contact the Daimler Trucks North America location of your choice.