

Triple Threat Diesel

7002 96 Street
 Clairmont, AB T8X5B3, CA
 accounting@triplethreatdiesel.com
 (587) 259-4432

Invoice: **INV-27307**Date: **5/22/2026**

Bill To
 Bonnetts Energy Corp. **
 65007 Highway 43
 Grande Prairie, AB, CA
 P: 780-830-9414

Remit Payment To
 Triple Threat Diesel
 7002 96 Street
 Clairmont, AB T8X5B3, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
SO-14696	COD	5/22/2026	Richard	187690	Knight, Amanda	1057

Item	Description	Quantity	Rate	Amount
Complaint: CVIP				
Cause: Annual Inspection Type: Preventive maintenance				
Labor	Correction: Chassis / Chassis / Perform CVIP inspection. Make up list of repairs, once repairs are completed sticker unit. CV8678067 - Completed: 5/22/2026	1.00000	\$505.00	\$505.00
			Subtotal	\$505.00

Complaint: Replace 4 Air Bags**Cause:** Worn **Type:** Unscheduled repair

(Inspection)

Labor	Correction: Chassis / Suspension / Lifted the truck in the air and put frame stands under the frame so the air bags would be as far apart as possible. Once I had the truck in the air, I unbolted both outer nuts on the top and the bottom nut, removed the air lines and the extensions that go to the bag fill ports. Once I got them out, I had to use a torch to remove the nut that goes around the air fill port. Trimmed off the outer stud for easier removal, took some time to remove the air bags. Once the air bags were out, I cleaned off the pedestals where the air bags sit and installed the new ones. Once they were in, I cleaned and applied thread tape to the air line extension tubes and installed them on the new bags and then tightened them down along with all of the nuts that hold the air bags in position. I then reconnected the air lines and had to cut a new piece of air line for between the two air bags because they were seized into the quick-coupler fittings. - Completed: 5/21/2026	5.00000	\$154.50	\$772.50
Parts	AIR BAGS - 57QL329AM	4.00000	\$338.96	\$1,355.84
			Subtotal	\$2,128.34

Complaint: Install Fire Extinguisher Bracket/Mount- Install First Aid Kit, Fire Extinguisher, and Triangle Set**Cause:** Missing **Type:** Unscheduled repair

(Inspection)

Item	Description	Quantity	Rate	Amount
Labor	Correction: Chassis / Chassis / Installed the fire extinguisher bracket next to the driver seat then put the fire extinguisher in the bracket and put the triangle set behind the passenger seat and put the first aid kit in the front of the glove box - Completed: 5/20/2026	1.00000	\$154.50	\$154.50
Parts	5LB ABC FIRE EXTING - SFFIRE5	1.00000	\$99.01	\$99.01
Parts	TRIANGLE FLARE KIT - FLA-50434-10	1.00000	\$32.50	\$32.50
Parts	FIRST AID KIT - DEN81CSA-0002-2	1.00000	\$25.26	\$25.26
			Subtotal	\$311.27

Complaint: Replace Reflective Tape

Cause: Missing **Type:** Unscheduled repair

(Inspection)

Labor	Correction: Chassis / Chassis / Cut and stuck reflective tape to the rear of the cab. - Completed: 5/19/2026	0.50000	\$154.50	\$77.25
Parts	REFLECTIVE TAPE RED/SILVER - 41160	10.00000	\$0.75	\$7.50
			Subtotal	\$84.75

Complaint: Wheel Seals Leaking

Cause: Leaking **Type:** Unscheduled repair

(Inspection)

Labor	Correction: Chassis / Chassis / Removed the second and third axle tires on the LH side and jacked them into the air, removed the axle nuts and had to beat the center of the axle and use a chisel to remove the cones that center the axle on the lug nut studs, as they were seized in place. Once I finally got the cones out, I drained the hub, removed the outer nut, then the lock washer, spacer washer, and inner nut. I then removed the outer bearing and finished draining the hub. Once I had the outer bearing out and the hub fully drained, I removed the hub from the spindle and began removing both seals from the hub and spindle. After getting the seals off, I cleaned all the nuts and bearings in the parts washer. While they were washing, I installed the seal on the spindle. Then I retrieved the bearings and installed the inner bearing after pre-lubing it. I then installed the hub on the spindle and filled it with oil. After the hub was pre-filled with oil, I installed the outer bearing, then installed the inner nut and performed the proper torque procedure. After that, I installed the spacer washer and lock washer, then installed the outer nut and secured it in place with the lock washer. Finally, I installed the new axle gasket, reinstalled the axle, and tightened everything up. I then repeated this procedure for the third axle. - Completed: 5/20/2026	5.00000	\$154.50	\$772.50
Parts	AXLE DRIVE GASKET - 5/8" HOLES - 3303111	2.00000	\$4.03	\$8.06
Parts	75W90 GEAR OIL - BULK - 550026918	2.00000	\$15.23	\$30.46
Parts	WHEEL SEAL, Drive Axle - 3929131	2.00000	\$75.13	\$150.26
			Subtotal	\$961.28

Complaint: Replace Missing Diff Vents

Cause: Missing **Type:** Unscheduled repair

(Inspection)

Item	Description	Quantity	Rate	Amount
Labor	Correction: Chassis / Chassis / Used vice scrips to remove old vent that were plugged off and broken I then screwed in the new vents and tightened them down. - Completed: 5/20/2026	0.50000	\$154.50	\$77.25
Parts	DIFF VENTS - 8235-KIT2902	2.00000	\$19.40	\$38.80
			Subtotal	\$116.05

Complaint: Install Tail Light/Reverse Light Assembly

Cause: Missing **Type:** Unscheduled repair

(Inspection)

Labor	Correction: Chassis / Lighting & Electrical / Install Tail Light/Reverse Light Assembly. Wire in tail lights, back up lights and back up alarm. - Completed: 5/22/2026	4.00000	\$154.50	\$618.00
Parts	RIGHT ANGLE PIGTAIL 3 WIRE - 94993	4.00000	\$2.37	\$9.48
Parts	MM, BLK PVC GROMMET - 91950	1.00000	\$4.09	\$4.09
Parts	4" ROUND RED S/T/T LAMP - 4050	2.00000	\$23.70	\$47.40
Parts	BACK UP LED LAMP - 4060C	2.00000	\$64.58	\$129.16
Parts	MM, BLK PVC GROMMET - 91950	3.00000	\$4.61	\$13.83
Parts	TAIL LIGHT BRACKET - A11-2437	1.00000	\$421.79	\$421.79
			Subtotal	\$1,243.75

Complaint: Replace Speedo Tach Glass

Cause: Missing glass and chrome bezel **Type:** Unscheduled repair

(Inspection)

Labor	Correction: Chassis / Cab Hardware / Remove dash panel and take apart speedo, install new glass and chrome bezel, Install into panel and then install panel into dash. - Completed: 5/20/2026	1.00000	\$154.50	\$154.50
Parts	SPEEDO GLASS - SPEEDO GLASS	1.00000	\$1,185.00	\$1,185.00
			Subtotal	\$1,339.50

Complaint: Replace Door Light Cover

Cause: Broken **Type:** Unscheduled repair

(Inspection)

Labor	Correction: Chassis / Chassis / Removed the old light assembly completely and installed a new one two screws and a plug - Completed: 5/20/2026	0.30000	\$154.50	\$46.35
Parts	DOOR LIGHT ASSEMBLY - 24762752	1.00000	\$149.14	\$149.14
			Subtotal	\$195.49

Complaint: Replace Roof Lights

Cause: Burnt Out **Type:** Unscheduled repair

(Inspection)

Labor	Correction: Chassis / Lighting & Electrical / Twisted and unplugged old bulbs then twisted and plugged in new ones. - Completed: 5/20/2026	0.40000	\$154.50	\$61.80
Parts	ROOF LIGHTS - 8413-10276Y	1.00000	\$68.02	\$68.02

Item	Description	Quantity	Rate	Amount
Parts	ROOF LIGHTS - 8413-10279Y	3.00000	\$101.59	\$304.77
			Subtotal	\$434.59

Complaint: Install Mud Flap and Hangers

Cause: Missing **Type:** Unscheduled repair

(Inspection)

Labor	Correction: Chassis / Chassis / Removed mud flap hangers from their box then pre drilled the holes in the mud flaps installed the hangers on the flaps then hung them on the truck. - Completed: 5/21/2026	1.00000	\$154.50	\$154.50
Parts	MUD FLAPS - MDF-CHHD2424	2.00000	\$29.22	\$58.44
Parts	MUD FLAP HANGER W/T - 03100125	1.00000	\$71.75	\$71.75
Parts	VARIOUS SIZES - SAFETY PIN	2.00000	\$1.95	\$3.90
			Subtotal	\$288.59

Complaint: Replace Headlight Switch

Cause: Customer request **Type:** Unscheduled repair

(Inspection)

Labor	Correction: Chassis / Chassis / Removed all bolts from the dash pulled dash uncoiled the plug and clipped the new one in then put the dash back together. - Completed: 5/21/2026	1.00000	\$154.50	\$154.50
Parts	HEAD LIGHT SWITCH - 25169835	1.00000	\$107.72	\$107.72
			Subtotal	\$262.22

Complaint: Install Bolts for Frame

Cause: Customer request **Type:** Unscheduled repair

(Inspection)

Labor	Correction: Chassis / Frame / Installed bolts in holes in frame rails. - Completed: 5/22/2026	1.00000	\$154.50	\$154.50
Parts	5/8x2 BOLT - 5/8x2	19.00000	\$0.89	\$16.91
Parts	5/8 FLATWASHER - 5/8FW	38.00000	\$0.33	\$12.54
Parts	5/8 NYLOCK - 5/8NY	19.00000	\$1.03	\$19.57
			Subtotal	\$203.52

Complaint: Replace Power Steering Lines

Cause: Worn **Type:** Unscheduled repair

(Inspection)

Labor	Correction: Chassis / Steering / Removed and replaced power steering lines. Suction from reservoir and return to reservoir. Zip tied into place. - Completed: 5/22/2026	1.00000	\$154.50	\$154.50
Parts	ATF - KL-TF3040	6.00000	\$13.96	\$83.76
Parts	TRANSPORT HOSE - 206-16-RL	48.00000	\$1.16	\$55.68
			Subtotal	\$293.94

Complaint: Replace missing battery box cover

Item	Description	Quantity	Rate	Amount
Cause: Battery cover missing Type: Unscheduled repair				
(Inspection)				
Labor	Chassis / Chassis / Replace missing battery box cover - Completed: 5/21/2026	0.00000	\$154.50	\$0.00
Parts	BATTERY BOX - 21062832	1.00000	\$648.16	\$648.16
Parts	LATCH - 25157769	1.00000	\$124.18	\$124.18
			Subtotal	\$772.34

Complaint: Remove airlines that are folded over in frame

Cause: Customer request **Type:** Unscheduled repair

(Inspection)

Labor	Correction: Chassis / Chassis / Any line that was plugged off or left open got taken out and plugged off two plugs in the air tank and a quick connect was added to the air shut off because there was an air line there that was left open - Completed: 5/20/2026	1.00000	\$154.50	\$154.50
Parts	1/2 NUT - 1/2NUT	8.00000	\$0.17	\$1.36
Parts	1/4 NPT HEX PLUG - 10HHP-4	1.00000	\$0.92	\$0.92
Parts	3/4 JIC CAP - 60C-8	1.00000	\$1.87	\$1.87
Parts	1/4 UNION COUPLING - PC1462-4	1.00000	\$7.03	\$7.03
			Subtotal	\$165.68

Complaint: Install haldex bushing on left side rear slack adjuster

Cause: Customer request **Type:** Unscheduled repair

(Inspection)

Labor	Chassis / Air Brake / Install haldex bushing on left side rear slack adjuster - Completed: 5/22/2026	0.00000	\$154.50	\$0.00
Parts	PLASTIC BUSHING - 45210125	1.00000	\$3.61	\$3.61
			Subtotal	\$3.61

Complaint: Top up coolant

Cause: Low on coolant **Type:** Unscheduled repair

(Inspection)

Labor	Correction: Engine / Cooling / Put 10 liters coolant in rad. - Completed: 5/22/2026	0.00000	\$154.50	\$0.00
Parts	50/50 BULK COOLANT DIESEL - A/F20 26-839	10.00000	\$3.19	\$31.90
			Subtotal	\$31.90

Unit: 1057 **VIN:** 1M2AG10CX7M063797

2007 Mack CV (Granite)

Chassis: 279 Kilometers

Engine: 55.80 Hours

Labor	\$4,012.15
Parts	\$5,329.67
Shop Supplies	\$361.09
Pre-Charge Subtotal	\$9,702.91
GST (5% of \$9,702.91)	\$485.15
Total	\$10,188.06

Payments & Credits \$0.00

Balance Due \$10,188.06

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above truck to secure the amount of repairs thereto.

I agree to the payment terms of 30 days and agree that any past due accounts that are over 30 days will acquire a 2% interest fee per month that said account is overdue, and that I and/or my company is responsible for the entirety of all payments associated with the work done for us, by Triple Threat Diesel Inc.

Authorized by: _____