

FORMAL STRUCTURAL REPORT

Redneckz Wireline
65007 TWP RD 714
Grande Prairie, AB T8W 5E7

Attention: Mr. Paul Rolfe

Owner: Redneckz Wireline

5-Year Structural Inspection of a McKissick Overhaul Ball and Hook

MODEL: MB07BT200E, SERIAL: 41486733, UNIT: 2035

DATE OF INSPECTION: September 15, 2023

OUR FILE: X05371

Visual examinations and magnetic particle inspections were performed on the above-described equipment in accordance with Kova Engineering Inspection Plan (KSIP-X05371). The load block and hook was disassembled for inspection in compliance with CSA Z150-16, section 5.3.6, regarding the inspection of load blocks and hooks at 5-year intervals. The specific items examined and our inspection findings were as follows:

1. Through Rod - no defects noted.
2. Lifting Ring - no defects noted.
3. Bearing Connection Nut - no defects noted.
4. Pins & Nuts - no defects noted.
5. Hook - no defects noted.

2035

THE EQUIPMENT IS JUDGED STRUCTURALLY SUITABLE FOR ITS INTENDED SERVICE.

Yours very truly,

KOVA ENGINEERING LTD.



the Crane Certification Bureau™



PN: 1001263

Matt Hanes, P. Eng.

MH:cm



Entered on Server

KOVA