

8230	9/25/2025	1E+06	Mechanic entered - Body Other Please hold sticker damage Beh	replaced	1219079
8230	9/2/2025	1E+06	Fluid Leaks Rear of bus - OAKLEIGH BREAKDOWN VAN ATTENDIN	PUT TOOLS INTO VAN. RECEIVED BREAKDOWN DETAILS . LEFT OAKLEIGH DEPOT TO COMMUTE TO BREAKDOWN SITE . BREAKDOWN CANCELLED . DROVE BACK TO OAKLEIGH DEPOT . UNLOADED MY TOOLS FROM THE BREAKDOWN VAN .	1218950
8230	8/31/2025	1E+06		FIRE EXTINGUISHER TEST & TAG - COMPLETED BY AT5 FIRE	1218950
8230	8/29/2025	1E+06	Consumables		1218950
8230	8/29/2025	1E+06	VALVE SOLENOID 3/2 1/4 24V DOOR CONTROL SURGE SUPP.		1218950
8230	8/29/2025	1E+06		Checked rear door is not operating properly checked for power and ground but all good. Checked terminals and wiring problems between connectors to solenoid but no issue found. Removed the old solenoids and put new ones with diode and put air hoses back to its position. Checked door is functioning normally now an	1218950
8230	8/29/2025	1E+06	Mechanic entered - Body Rear_Door Operation Faulty Rear door	Replaced x2 door open/close solenoid rear door open/close now old solenoid was clicking. Complete	1218950
8230	8/28/2025	1E+06		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Battery positive terminal secured with conduit multiple small wires secured at outside fuse box with cable ties. Carried out fire safety inspection as per checklist. Complete	1218950
8230	8/19/2025	1E+06	Mechanic entered - Fluid Leaks Rear of bus Coolant leaking.	Drained coolant replaced and secured heater hose. Filled coolant and steam cleaned the engine. Drive tested and rechecked coolant level and leaks all ok.	1218997
8230	8/13/2025	1E+06	WIPER BLADE ASSEMBLY 39037 S/5 FROM TX1000		1218950
8230	8/13/2025	1E+06	Workshop Tablet Entered -Wipers and Washers - Wipers Loose	visual inspection found one of the wiper blades had a broken grip tooth and rubber was loose with structuring rails hanging and over extending. ran to check as didnt seem like a driver would notice found other wiper blade mounting was missing a rivet and had spun 180 degrees and was very moving and dragging on scre	1218950
8230	8/7/2025	1E+06	Consumables		1217938
8230	8/7/2025	1E+06	SWITCH DOOR CONTACT (NO) 88V2213 39959		1217938
8230	8/7/2025	1E+06	Body Windows Front opeartion faulty.	Replaced door switch.	1217938
8230	8/4/2025	1E+06	Mechanic entered - Suspension Knee/ Raise	Checked, found suspension and doors are not working. Rectify the faults found signal wire to battery terminal is loose. Replaced terminal and operate doors and suspension all ok.	1217782
8230	8/4/2025	1E+06	Mechanic entered - Air System Air Not Building_Up	Refer to work order 1280504	1217782
8230	7/29/2025	1E+06	Consumables		1217782
8230	7/29/2025	1E+06	Mechanic entered - Body Other Ruist under the wheel chair ra	Assisted Anthony to repair rust	1217782
8230	7/29/2025	1E+06	Mechanic entered - Body Other Ruist under the wheel chair ra	clean rust and painted.	1217782
8230	7/28/2025	1E+06		Filled new hoses and filled coolant in the system. Steam cleaned drive tested and recheked coolant/oil level and lleaks all ok.	1217782
8230	7/28/2025	1E+06	HOSE COOLANT TAPERED 60/70 MERC BENZ 0500LE		1217782
8230	7/28/2025	1E+06		Refitted alternator and fan drive. Drive tested and checked leaks ok.	1217782
8230	7/24/2025	1E+06		Refitted engine breather and alternator mount. Filled 32 liters of engine oil. C/O	1217782
8230	7/23/2025	1E+06		Refitted engine oil sump with new gasket. C/O	1217782
8230	7/22/2025	1E+06	GASKET OIL SUMP 457942 MERC BE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #G391729 Receiving #415645 Date :2025-07-22	1217782
8230	7/22/2025	1E+06		Cleaned parts.	1217782
8230	7/21/2025	1E+06		Removed oil sump and order the parts.C/O	1217782
8230	7/21/2025	1E+06	GASKET OIL PICK UP 0.5MM MERC BENZ 0500LE 44A5709	Drained engine oil and started to remove oil sump. C/O	1217782
8230	7/21/2025	1E+06	BREATHER DIAPHRAGM MERC BENZ OH1830 A0000180133	Drained coolant. C/O	1217782
8230	7/18/2025	1E+06	Mechanic entered - Engine Other Engine oil leak- engine sump	Assisted with Vehicle Safety Inspection. Tensioned all wheel nuts.	1217782
8230	7/18/2025	1E+06	Mechanic entered - Engine Other Bottom radiator hose- leakin	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done.	1217782
8230	7/5/2025	1E+06		VEHICLE SAFETY INSPECTION done	1217782
8230	7/5/2025	1E+06		check air found faulty door open value faulty replaced value air leak ok.	1217500
8230	6/19/2025	1E+06	Driver Tablet Entered-Air System - Air_Leak Front		1217500
8230	6/19/2025	1E+06	BUTTON CLIPPARD DOOR VALVE 11916-2		1217500
8230	6/19/2025	1E+06	VALVE CLIPPARD DOOR OPEN/CLOSE (11916-2) BUTTON		1217500
8230	5/6/2025	1E+06	Deinstall smart track and fit to bus 1690	Completed by bsmart track joe	1217053
8230	5/6/2025	1E+06	Consumables		1217053
8230	5/1/2025	1E+06	FILTER DRYER AIR COND THERMO KING 2750300 DML305FS		1216176
8230	5/1/2025	1E+06	OIL A/C COMPRESSOR AIR CONDITIONING PSR-32		1216176
8230	5/1/2025	1E+06		CARRY OUT A/C - B SERVICE AS PER CHECK LIST Service as per list	1216176
8230	5/1/2025	1E+06		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list	1216176
8230	4/24/2025	1E+06	LAMP CLEAR FRN INDICATOR WRAP-AROUND		1215196
8230	4/24/2025	1E+06	DECAL EMERGENCY EXIT PRESS BUTTON UNDER BUMPER		1215196
8230	4/24/2025	1E+06		fitout front panels replace 2 x burnt bulbs on park lights replace NSF park light fit new decals Mop inside of bus and Dash test lights park bus in yard	1215196
8230	4/23/2025	1E+06		prep and paint	1215196
8230	4/23/2025	1E+06	HARDENER DEBEER 2K AIR DRY 1LTR		1215196
8230	4/22/2025	1E+06		paint primer and sand bumper bars and take to paint shop	1215196
8230	4/22/2025	1E+06		prep work and primed headlight panels cont with prep work.	1215196
8230	4/17/2025	1E+06	BUMPER FRONT N/SIDE CNR VOLGREN CR228		1215196
8230	4/17/2025	1E+06		repair front panel fiberglass bog and sand and take to paint shop	1215196
8230	4/16/2025	1E+06		strip front panel and repair	1215196
8230	4/16/2025	1E+06	*** PHOTOS TAKEN BY GERALD *** Accident # 57896 NEARSIDE	East coast repairing and bus at east coast	1215196
8230	4/16/2025	1E+06	*** PHOTOS TAKEN BY GERALD *** Accident # 57896 NEARSIDE	East coast completed and refer w/o 1259267	1215196
8230	4/12/2025	1E+06		Carried out safety inspection as per check list tensioned all wheel nuts with Zubz. Replaced 2x Wiper blades. Coolant leaking fromboost pump hose clamp tightened clamps. filled coolant road tested rechecked. ok No coolant leaks.	1215196
8230	4/12/2025	1E+06	WIPER BLADE ASSEMBLY 39037 S/5 FROM TX1000	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1215196
8230	4/12/2025	1E+06		Assist Indica with VSA Complete.	1215196
8230	4/4/2025	1E+06		replaced fan drive oil and steam cleaned engine. Checked for leaks ok.	1213817
8230	4/2/2025	1E+06	Consumables		1213281
8230	4/2/2025	1E+06	Consumables		1213281
8230	4/2/2025	1E+06	PTI Tablet Entered -Elec and Light - Exterior Lights passeng	Replaced o/s low beam globe and o/s side indicator globe.	1213281
8230	4/2/2025	1E+06	GLOBE 24V 70W H1 HLC2470		1213281
8230	4/2/2025	1E+06	Workshop Tablet Entered -Elec and Light - Indicators Not Wor	Replaced globe.	1213281
8230	4/1/2025	1E+06	Workshop Tablet Entered -A/C Heating - Not Heating	Run bus up too operating temperature unit heated too set point demisters had a air off at 40C photos off results sent too Ranjith	1213261
8230	4/1/2025	1E+06	Engine replace fan drive oil.		1213261
8230	3/31/2025	1E+06		topup coolant done PTI and park the bus	1213261
8230	3/31/2025	1E+06	WATER PUMP MERC BENZ 0500LE A4	Creditor #:GB-MUL001 MULTISPARES LTD P/O #G384618-1 Receiving #407696 Date :2025-03-31 REPLACEMENT FOR UNIT WITH CRACKED HOUSING	1213261
8230	3/29/2025	1E+06		fitted new water pump with new gasket changed over pulley and thermostat tensioned all bolts to spec JOB c/o and fitted oil lines going into oil filter	1213261
8230	3/28/2025	1E+06	PTI Tablet Entered -Engine - coolant leaking from rear of bu	removed water pump fitted new pump with gasket found coolant leaking from bottom of new pump removed connection and found that water pump housing is cracked new one ordered	1213261
8230	3/28/2025	1E+06		New pump fitted leaking underneath connection to intercooler.Surface of the connecting Area of the pump surface damaged.Worked with Jimmy.cleaned working Area floor.c/o	1213261
8230	3/28/2025	1E+06	WATER PUMP MERC BENZ 0500LE A4	Creditor #:GB-MUL001 MULTISPARES LTD P/O #G384618 Receiving #407537 Date :2025-03-28	1213261
8230	3/28/2025	1E+06		removed water pump C/O	1213261
8230	3/28/2025	1E+06		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Complete CCTV A Service as per check list.	1213261
8230	3/27/2025	1E+06	Consumables		1212847
8230	3/27/2025	1E+06	Driver Tablet Entered -Elec and Light - Exterior Lights	passenger side low beam was not working.find blown globe.re-placed and checked ok.Complete.	1212847
8230	3/27/2025	1E+06	GLOBE 24V 70W H1 HLC2470		1212847
8230	3/25/2025	1E+06		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Replaced boost pump and return air filter medium service as per list	1212847
8230	3/25/2025	1E+06	BOOST PUMP A/C COACH 90LTR 24V CM90P7		1212847
8230	3/21/2025	1E+06	Engine replace fan drive oil.	oil on order.	1212581
8230	3/11/2025	1E+06		CARRY OUT C SERVICE AS PER CHECK LIST completed as per check list but have not done the fan drive oil because no oil in stock. c/o	1211046
8230	3/11/2025	1E+06	FILTER AIR MERC BENZ 0500LE E3 - ES A0040941704		1211046
8230	3/11/2025	1E+06	OIL SAMPLE TEST KIT		1211046
8230	3/11/2025	1E+06	FILTER FUEL/WATER SEPARATOR MERC 0500LE >ES A0004771302		1211046
8230	3/11/2025	1E+06	FILTER POWER STEER SCANIA ALL MODELS 153468		1211046
8230	3/11/2025	1E+06	BREATHER OIL MIST MERC BENZ 0500LE A5410100163		1211046
8230	3/11/2025	1E+06	FILTER OIL MERC BENZ 0500LE ES OH1830 ES A0001801709		1211046
8230	3/11/2025	1E+06	FILTER FUEL MERC BENZ 0500LE -> ES A5410900151		1211046
8230	3/11/2025	1E+06	Consumables		1211046
8230	3/11/2025	1E+06	Consumables		1211046

8230	10/8/2024	1E+06	ANNUAL SAFETY INSPECTION SERIAL #RSI 06S808. PASS. 8/10/2024. WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	1187793
8230	10/8/2024	1E+06	PERFORM CAMPAIGN 11/24 CHECK & ENSURE ALL BUS DRIVE AXLE WHE	checked ok
8230	10/4/2024	1E+06	Consumables	1187793
8230	10/4/2024	1E+06	Consumables	1187050
8230	10/4/2024	1E+06	Consumables	1187050
8230	10/4/2024	1E+06	Drv entered - Body Drivers Seat Controlsdriver seat too high	does lower down driver need more training on how to use the function of the seats.
8230	10/4/2024	1E+06	Carry out final inspection for RSI	carried out final inspection for rsi carried out steam clean
8230	10/3/2024	1E+06	Workshop Tablet Entered -A/C Heating - Not Cooling	Commission tested check heat and cool function A/C work ok
8230	10/2/2024	1E+06	Consumables	1187050
8230	10/2/2024	1E+06		completed repaired the rust
8230	10/1/2024	1E+06	Mechanic entered - Body Other Rust under front and rear door	sand down the rust c/o
8230	9/26/2024	1E+06	Consumables	1187050
8230	9/26/2024	1E+06	GLOBE 24V 70W H1 HLC2470	1186575
8230	9/26/2024	1E+06	PTI Tablet Entered -right hand side headlight not working	replaced os head light globe
8230	9/24/2024	1E+06	Mechanic entered - Wipers and Washers Wipers Loose N/S wiper	Drilled out old rivets and installed new bigger ones wiper no longer loose.
8230	9/24/2024	1E+06	Mechanic entered - Fluid Leaks Rear of bus Oil leak from fro	After extensive steam cleaning in general for RSI took the bus for a road test and found where the gearbox oil was leaking from it was coming out of one loose bolt on the front cover of the gearbox tighten up this bolt and cleaned checked for leaks no more oil coming.
8230	9/24/2024	1E+06	Mechanic entered - Engine Other Tighten up all engine sump b	After extensive cleaning for RSI tighten up all engine sump bolts most of which had about a half turn till tight again.
8230	9/24/2024	1E+06	Mechanic entered - Engine Other ALL Floor hatches off steam	Carried out extensive steam cleaning with floor hatches off on the engine and gearbox. Now clean for RSI.
8230	9/24/2024	1E+06	Consumables	1186554
8230	9/24/2024	1E+06	Mechanic entered - Elec and Light Interior Lights x2 Bus sto	Replaced bus stopping globes and checked after fitment all working.
8230	9/24/2024	1E+06	Consumables	1186554
8230	9/24/2024	1E+06	Consumables	1186554
8230	9/24/2024	1E+06	Mechanic entered - Body Other x1 Priority seating sticker pe	Cheap sticker left all its glue on the window brake cleaned glue off and fit new sticker to N/S.
8230	9/24/2024	1E+06	Mechanic entered - Body Other Plastic duct above rear door c	Created a plate and shaped it to fit in the arch of the panel secured with lock nuts and large washers now holding well above the rear door.
8230	9/24/2024	1E+06	Mechanic entered - Body Front_Door Operation Faulty Left doo	Adjusted sensitive edge with Feda till working.
8230	9/24/2024	1E+06		adjusted the berger switch for sensitive edge with Matt and checked ok.Complete.
8230	9/23/2024	1E+06		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST Completed CCTV service.
8230	9/23/2024	1E+06		PRE ANNUAL SAFETY INSPECTION CHECK Carried out pre RSI as per inspection list reported / repaired any found defects. Tensioned all wheel nuts with Haysun.
8230	9/18/2024	1E+06	Consumables	1185847
8230	9/18/2024	1E+06	PTI Tablet Entered -Elec and Light - Exterior LightsRight f	Replaced globe.
8230	8/29/2024	1E+06		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST
8230	8/29/2024	1E+06		Carry out fire safety inspection as per check list. Complete.
8230	8/29/2024	1E+06		Carry out fire safety inspection as per checklist also secured one of the positive red wire from metal bracket. Complete
8230	8/29/2024	1E+06		COMPLETED BY ATS 20/8/2024
8230	8/24/2024	1E+06		VEHICLE SAFETY INSPECTION
8230	8/24/2024	1E+06		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS completed
8230	8/24/2024	1E+06		completed safety inspection as per check list and tensioned all wheel nuts with indika
8230	8/24/2024	1E+06	Consumables	1181630
8230	8/24/2024	1E+06	Consumables	1181630
8230	8/24/2024	1E+06	Mechanic entered - Body Other rear yellow floor strip missin	fitted new yellow strip 1m
8230	8/24/2024	1E+06	EDGE STEP INSERT YELLOW 40MM P/M ZB10378SER	
8230	8/24/2024	1E+06	Mechanic entered - Body Front_Door Operation Faulty front do	adjusted tested all working
8230	8/21/2024	1E+06	Drv entered - Brakes Foot_Brakes Leaking Air	diagnose air leaks carried out found leaking from air line in service hatch 8mm plastic joiner fitted new brass joiner and straight cut air line and connect build up air pressure. no leaks.
8230	8/21/2024	1E+06	CONNECTOR STRAIGHT BRASS 8MM	
8230	8/20/2024	1E+06		CARRY OUT A SERVICE AS PER CHECK LIST A service completed.
8230	8/20/2024	1E+06	Consumables	1181035
8230	8/20/2024	1E+06	Consumables	1181035
8230	8/20/2024	1E+06	Consumables	1181035
8230	8/1/2024	1E+06	Consumables	1181035
8230	8/1/2024	1E+06	Drivers reported seat is sliding forwards and backwards	Straightened seat adjuster.
8230	7/29/2024	1E+06		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST completed as per check list
8230	7/29/2024	1E+06		Assisted Haysun replace rocker cover gaskets and clean rocker cover surface
8230	7/29/2024	1E+06	GASKET ROCKER CVR MERC BENZ 05	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G369324 Receiving #:391089 Date :2024-07-29
8230	7/29/2024	1E+06	Mechanic entered - CCTV Server Connection	checked the connectivity reported to streamax
8230	7/24/2024	1E+06	PTI Tablet Entered -Elec and Light - two front right and lef	Replaced globes. Fixed issue
8230	7/24/2024	1E+06	Consumables	1177260
8230	7/22/2024	1E+06		1177439
8230	7/22/2024	1E+06	FILTER POWER STEER SCANIA ALL MODELS	1177260
8230	7/22/2024	1E+06		1176687
8230	7/18/2024	1E+06	CORE POWER STEERING PUMP	1176687
8230	7/18/2024	1E+06	PULP POWER STEERING MERCEDES	removed and replaced power steering pump done a complete flush of power steering system tensioned all bolts to spec filled up power steering fluid bleed system and checked for leaks no leaks found and steam clean needs road test
8230	7/17/2024	1E+06	Workshop Tablet Entered -Steering - Steering Wheel Faultyto	Creditor #:GB-WH004 WHITEHORSE TRUCK CENTRE P/O #:G368690 Receiving #:390475 Date :2024-07-18
8230	7/17/2024	1E+06	Workshop Tablet Entered -Steering - Steering Wheel Faultyto	Creditor #:GB-WH004 WHITEHORSE TRUCK CENTRE P/O #:G368690 Receiving #:390475 Date :2024-07-18
8230	7/15/2024	1E+06	Driver Tablet Entered -Brakes - Park_Brake Not Holding	being diagnosing check power steering fluid and filter all good tried turning steering wheel with filter off steering still stiff on idle checked hoses and lines for leaks. all good unable to test pressure in line due to not have proper equipment jacked up bus check steering componets all good came to conclusion that the hydra
8230	7/15/2024	1E+06	Driver Tablet Entered -Brakes - Park_Brake Not Holding	1176000
8230	7/15/2024	1E+06	PERFORM CAMPAIGN 08/24 CHECK AND REPLACE WHERE REQUIRED ACC	1176000
8230	7/11/2024	1E+06	PTI Tablet Entered -front right side head light not working	DVR entered twice
8230	7/11/2024	1E+06	GLOBE 24V 70W H1 HLC2470	Checked the condition of the brake pads both 90 % front and rear brake pads. Brake tested passed.
8230	7/11/2024	1E+06	PTI Tablet Entered -front right side head light not working	DONE
8230	7/11/2024	1E+06	Consumables	Repaired wire and replaced globe.
8230	7/11/2024	1E+06	Consumables	1174918
8230	7/11/2024	1E+06	Consumables	1174918
8230	7/2/2024	1E+06	Vandalism. REPLACE ANTI GRAFFITI FILM-AUDIT 1071 - STAGE 2	1174918
8230	7/2/2024	1E+06	REPLACE ANTI GRAFFITI FILM. A	1174918
8230	6/27/2024	1E+06	CCTV Server Connection - OCC can not view this bus in stre	checked bus with Constat guy and find all wires are ok and connected properly and he mentioned some issue on set up from streamax side through software.Complete.
8230	6/26/2024	1E+06	Mechanic entered - Wheels and Tyres Wheel Nut Retension Rtn	Tensioned wheel nuts position 5 and 6 with Kuma.
8230	6/26/2024	1E+06		Assisted.
8230	6/26/2024	1E+06	Consumables	1173040
8230	6/25/2024	1E+06		1173040
8230	6/25/2024	1E+06		VEHICLE SAFETY INSPECTION
8230	6/25/2024	1E+06		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS
8230	6/25/2024	1E+06		Assisted for wheel nut tensioned.
8230	6/25/2024	1E+06	Mechanic entered - Wheels and Tyres Worn Worn tyres pos.56	Removed and replace with Abraham. Fitted run out tyre Tensioned wheel nuts with Abraham.
8230	6/25/2024	1E+06		Assisted Rene. Fitted orig. runout tyres.
8230	6/25/2024	1E+06	Consumables	1172846
8230	6/25/2024	1E+06		1172846
8230	6/25/2024	1E+06	Mechanic entered - Fluid Leaks Rear of bus Radiator cap miss	Fitted new rad. Cap
8230	6/25/2024	1E+06	CAP RADIATOR 70KPA MERC 0500L A0005014615	
8230	6/4/2024	1E+06	Driver having an issue with the brakes- Dulkhth advised its	r/r the seat with new seat tighten bolts to spec
8230	6/4/2024	1E+06	SEAT DRIVER ISRI 6860/875 NTS LH CONTROLS	
8230	5/13/2024	1E+06		CARRY OUT B SERVICE AS PER CHECK LIST carried out b service as per check list and tensioned all wheel nuts with mark carried out road test steam clean check oil ok.
8230	5/13/2024	1E+06	OIL ENGINE ALL FLEET PLUS E900 15W-40	1165765
8230	5/13/2024	1E+06	OIL SAMPLE TEST KIT	1165765
8230	5/13/2024	1E+06	BREATHER OIL MIST MERC BENZ 0500L A5410100163	1165765
8230	5/13/2024	1E+06	FILTER OIL MERC BENZ 0500LE E5 OH1830 E5 A0001801709	1165765

8230	5/13/2024	1E+06	OIL ENGINE ALL FLEET PLUS E900 15W-40		1165765
8230	5/13/2024	1E+06	OIL ENGINE MOBIL DELVAC MODERN 15W-40 MIN		1165765
8230	5/13/2024	1E+06	Consumables		1165765
8230	5/13/2024	1E+06	Consumables		1165765
8230	5/13/2024	1E+06	Consumables		1165765
8230	5/13/2024	1E+06	Consumables		1165765
8230	4/30/2024	1E+06		VEHICLE SAFETY INSPECTION Completed VSI.	1163972
8230	4/30/2024	1E+06		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned wheel nuts w/ Rene.	1163972
8230	4/20/2024	1E+06	CCTV Hard Drive 1 hour out of synx running fast	adjusted time and checked ok.Complete.	1162058
8230	4/19/2024	1E+06		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST completed as per check list steam clean the bus	1163058
8230	4/19/2024	1E+06	OIL ZF GEARBOX SYNTHETIC ECOFLUID A PLUS		1163058
8230	4/19/2024	1E+06	FILTER ZF ECOMAT GEARBOX 4139-298-038 30980081		1163058
8230	4/19/2024	1E+06	Service		1163058
8230	4/17/2024	1E+06	Driver Tablet Entered -Brakes - Park_Brake Not Holding	CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST completed as per check list steam clean the bus Road test and clean under bus	1162415
8230	4/17/2024	1E+06		Checked brake boosterspark brake valve and Air lines for leaks.all ok checked park Brake for Holding ok. Brake tested passed.	1162415
8230	4/6/2024	1E+06		Assisted.	1161557
8230	4/3/2024	1E+06		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list	1161441
8230	3/30/2024	1E+06	Wheels and Tyres Wheel Nut Retension pos 345&6	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Complete CCTV A Service as per check list.	1161385
8230	3/30/2024	1E+06	Consumables	Carried out all rear wheel nut retension with Matt S	1161385
8230	3/28/2024	1E+06	Mechanic entered - Elec and Light Exterior Lights l/hand fro	Replaced globe.	1161385
8230	3/28/2024	1E+06	Consumables		1161385
8230	3/28/2024	1E+06	BRAKE PADS FRT / RR MERC 0500LE E3+E5 49G7501BERAL		1161385
8230	3/28/2024	1E+06	Ops Entered - Fault - Warning Lights Brakes - Route: - Tak	Assisted and Tensioned wheel nuts with Zubair.	1161385
8230	3/28/2024	1E+06		diagnosed and found rear brakes worn warning light on carried out removing and replacing rear brakes with sateesh and tensioned all wheel nuts with sateesh	1161385
8230	3/22/2024	1E+06	PTI Tablet Entered -Elec and Light - front right park light	Front right indicator lens assembly parklight holder melted need replacement. Removed and replace indicators lens assembly parklight globe and indicator globe.plus replace headlight globe.	1160328
8230	3/22/2024	1E+06	GLOBE 24V 70W H1 HLC2470		1160328
8230	3/22/2024	1E+06	Consumables		1160328
8230	3/21/2024	1E+06	PTI Tablet Entered -Elec and Light - right front park light	Replaced globe.	1160139
8230	3/21/2024	1E+06	Consumables		1160139
8230	3/20/2024	1E+06	Workshop Tablet Entered -Suspension - Knee/ Raise	check and fixed front lavalng sensor road tesed bus ok.	1159612
8230	3/19/2024	1E+06	Workshop Tablet Entered -A/C Heating - Not Cooling	Commission tested check refrigerant levels check air flow across ducts check heat and cool functons unable to fault	1159612
8230	3/19/2024	1E+06	Workshop Tablet Entered -A/C Heating - Not Cooling	Tested ok	1159612
8230	3/19/2024	1E+06	Div entered - A/C Heating Not Cooling		1159612
8230	3/19/2024	1E+06	Ops Entered - Fault - A/C Heating Not Cooling - Route: -		1159612
8230	3/8/2024	1E+06	ALTERNATOR 24V 140AMP MERC BEN	Creditor #GB-ASH001 NAPA AUTO PARTS P/O #G360378RETI Receiving #381358 Date :2024-03-08 INCORRECT PART RETURNED FOR CREDIT	1158103
8230	3/7/2024	1E+06	PTI Tablet Entered -Elec and Light - Exterior Lights front p	Replaced globe.	1157817
8230	3/7/2024	1E+06	Consumables		1157817
8230	3/6/2024	1E+06		PASS	1157646
8230	3/5/2024	1E+06		replaced alternator repair all damage wires road tested bus ok.	1157582
8230	3/4/2024	1E+06	ALTERNATOR 24V 140AMP MERC BEN	Creditor #GB-MUL001 MULTISPARES LTD P/O #G360538 Receiving #380850 Date :2024-03-05	1157582
8230	3/1/2024	1E+06	Vandalism REPLACE ANTI GRAFITTI FILM L4 MODESTY	DONE BY GLASSPROTECH 29/02/2024 POW G360386	1157582
8230	3/1/2024	1E+06	REPLACE ANTI GRAFITTI FILM L4	Creditor #GB-GLA010 GLASSPROTECH MELBOURNE P/O #G360386 Receiving #380894 Date :2024-03-05	1157582
8230	2/29/2024	1E+06	ALTERNATOR 24V 140AMP MERC BEN	Creditor #GB-ASH001 NAPA AUTO PARTS P/O #G360378 Receiving #380634 Date :2024-02-29 7962922	1157582
8230	2/29/2024	1E+06	Engine Warning Light	check fault short wire to chargin system c/o removed alternator back cover and found short wire removed alternator to fit new alternator. found wrong alternator. c/o	1157582
8230	2/28/2024	1E+06	VIBRASORBER SUCTION SCREW TYPE (O RING 33-1785)		1157270
8230	2/23/2024	1E+06	A/C Heating Air Conditioning not working	Replaced failed suction hose pressure test vac and charge system tested ok	1157055
8230	2/15/2024	1E+06		Assisted	1155465
8230	2/15/2024	1E+06		Retensioned wheel nuts pos 1 and 2.	1155465
8230	2/14/2024	1E+06	BUSH FRT & RR SWAY BAR 70MM MERC BENZ 0500LE A6283220050		1155128
8230	2/14/2024	1E+06	LINK SWAY BAR NSF MERC 0500LE A6283201089		1155128
8230	2/14/2024	1E+06	Mechanic entered - Suspension Noisy Near side sway bar link	removed and replaced n/s/f sway bar link	1155128
8230	2/14/2024	1E+06	Mechanic entered - Suspension Noisy Near side sway bar link	removed and replaced n/s/f sway bar link	1155128
8230	2/14/2024	1E+06	BOLT FRT SWAY BAR BUSH MTG MER	Creditor #GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #G359324 Receiving #379475 Date :2024-02-14	1155411
8230	2/14/2024	1E+06	Mechanic entered - Suspension Other Sway bar bush worn need	Remove front tyres to replace front sway bar bushes	1155128
8230	2/14/2024	1E+06	Mechanic entered - Suspension Other Sway bar bush worn need	Assisting removed tyre POS 12 removed and replaced sway bar bushes and removed seized bolt and replaced with new bolt cleaned all bolts with die and wire wheel refitted all nuts bolts and bushes with nevsn and tensioned all wheelnuts with nevsn	1155128
8230	2/14/2024	1E+06	Mechanic entered - Engine Noisy or Rattling Engine clicking	checked over with nevsn and road tested engine all good	1155128
8230	2/14/2024	1E+06	Mechanic entered - Engine Noisy or Rattling Engine clicking	checked over and road tested engine all good	1155128
8230	2/14/2024	1E+06	WHEEL ARCH BRUSH 2.5M LENGTH 12065		1155128
8230	2/14/2024	1E+06	Mechanic entered - Body Other o/s/f wheel arch brush broken	removed and replaced o/s/f wheel arch brush	1155128
8230	2/14/2024	1E+06	Consumables		1155128
8230	2/10/2024	1E+06		VEHICLE SAFETY INSPECTION Completed .	1155128
8230	2/10/2024	1E+06		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Haysun.	1155128
8230	2/10/2024	1E+06	O-RING KIT LARGE VOSS A6739970145		1155128
8230	2/10/2024	1E+06	Mechanic entered - Air System Air_Leak Rear Circuit protecti	Removed o ring and fitted new o-ring kit for fittings. Found out as well air compressor hose unloader leaking. Check found out loose retightened fitting. Checked for leak all ok.	1155128
8230	2/9/2024	1E+06	PERFORM CAMPAIGN 01/24 REMOVAL OF OLD NO SMOKING DECALS	COMPLETED	1155128
8230	2/5/2024	1E+06	PTI Tablet Entered -Elec and Light - Exterior Lights front	Replaced globe.	1154057
8230	2/5/2024	1E+06	PTI Tablet Entered -Elec and Light - Exterior Lights parkli	same defect.	1154057
8230	2/5/2024	1E+06	Consumables		1154057
8230	1/31/2024	1E+06		assist guri changing the air filter system	1152981
8230	1/31/2024	1E+06	SEAL AIR DRYER - CIRCUIT PROT VALVE MERC BENZ 0500LE		1152981
8230	1/31/2024	1E+06		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST complete as per check list check the steal pipes for carbon deposit it was clean and fitted back the same ones.	1152981
8230	1/31/2024	1E+06	AIR DRYER ASSY MERC 0500LE A0004302915		1152981
8230	1/31/2024	1E+06	CONDENSOR C/W DRAIN VALVE MERC BENZ 0500LE A0054327401		1152981
8230	1/17/2024	1E+06		tensioned POS 56 with kumara	1151086
8230	1/17/2024	1E+06		assisted	1151086
8230	1/16/2024	1E+06	Mechanic entered - Wheels and Tyres Damaged Pos.5 damaged th	Fitted orig. runout tyre pos.5 and tensioned wheel nuts w/ Jimmy.	1150898
8230	1/16/2024	1E+06	Consumables		1150898
8230	1/16/2024	1E+06		CARRY OUT A SERVICE AS PER CHECK LIST A service completed.	1150898
8230	1/16/2024	1E+06	Consumables		1150898
8230	1/16/2024	1E+06	Consumables		1150898
8230	1/9/2024	1E+06	WHEEL ARCH BRUSH 2.5M LENGTH 12065		1149852
8230	1/9/2024	1E+06	PTI Tablet Entered -Wheel arch brash has Damaged(right hand	removed o/s/f wheel arch brush and replaced with new and refitted	1149852
8230	1/9/2024	1E+06	Consumables		1149852
8230	1/4/2024	1E+06	PERFORM CAMPAIGN 10/23 POSITIONING OF 2024 PTV FARES	COMPLETED	1149565
8230	#####	1E+06	CCTV FIT XS DVR		1149482
8230	#####	1E+06	CCTV FIT XS GS DVR	fitted and commisioned DVR	1149482
8230	12/6/2023	1E+06		Replaced r/n/s U bolts. Tensioned nuts to spec.	1146547
8230	12/6/2023	1E+06		tensioned POS 34 with nick and assisted tensioning n/s ubolts	1146547
8230	12/5/2023	1E+06	U BOLT RR AXLE MERC BENZ 0500L	Creditor #GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #G355592 Receiving #374925 Date :2023-12-05	1146547
8230	12/5/2023	1E+06	NUT U BOLT RR AXLE MERC BENZ 0	Creditor #GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #G355592 Receiving #374925 Date :2023-12-05	1146547

8230	12/5/2023	1E+06	WASHER TO SUIT U-BOLT REAR MER	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G355592 Receiving #:374925 Date :2023-12-05	1146547
8230	12/1/2023	1E+06		VEHICLE SAFETY INSPECTION Completed safety service.	1146547
8230	12/1/2023	1E+06		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1146547
8230	12/1/2023	1E+06	Mechanic entered - Suspension Other N/S/R axle u-bolt broken	Ordered parts.	1146547
8230	12/1/2023	1E+06	Mechanic entered - Body Other O/S/F wheel arch brush missing	Replaced wheel arch brush for O/S/F.	1146547
8230	12/1/2023	1E+06	WHEEL ARCH BRUSH 2.5M LENGTH 12065		1146547
8230	12/1/2023	1E+06	RUBBER WHEEL ARCH 41294 2.5		1146547
8230	#####	1E+06	Driver Tablet Entered - Engine - Low Power use has trouble ac	Rectify fault found exhaust battery get jammed Removed exhaust and repaired battery shaft. Refitted drive tested and checked the performance of the engine ok.	1145843
8230	#####	1E+06	Elec and Light Two Way Radio Emergency Alarm is being acti	checked 2 way system and found that duress alarm button had been incorrectly wired causing bus to always alarm corrected wiring and rang OCC to test duress button was correctly working tested ok	1144233
8230	#####	1E+06		checked two way radio and inspected for duress button and wiring and find out wiring for duress button is incorrect and find out wire is incorrect. swap over and checked it working ok. call OCC ad di duress button test tested ok. Complete.	1144233
8230	#####	1E+06	Consumables		1144233
8230	#####	1E+06		Retensioned wheel nuts pos 3 and 4.	1143867
8230	#####	1E+06		Assisted	1143867
8230	#####	1E+06	Mechanic entered - Wheels and Tyres Flat or Leaking Pos 3.	Fitted new COOPER tyre pos 3. (note; tyres damage by bolt) Tensioned wheel nuts with Jimmy.	1143825
8230	#####	1E+06	TYRE 295/80R22.5 NEW		1143825
8230	#####	1E+06	Consumables		1143825
8230	#####	1E+06	Driver Tablet Entered - Gearbox Driveline - Rough Gear Change	Drive tested and checked the operation of the transmission ok.	1143825
8230	#####	1E+06		check gearbox oil level fluid low topped up 5l of eco-life oil road tested by nick gears changing and no smoke rechecked oil level all good	1143825
8230	11/3/2023	1E+06	Workshop Tablet Entered - Brakes - Foot_Brakes Pulling	Checked brake pads and any leaks air system ok. Checked suspension and tyres then adjust rear suspension. Brake roller test and road test for check pulling and reater operation all ok.	1142394
8230	#####	1E+06	Consumables		1140666
8230	#####	1E+06	PTI Tablet Entered - Elec and Light - Exterior Lights. right	Replaced globe.	1140666
8230	#####	1E+06	SEAL CRANKSHAFT FRONT MERCEDES 0500LE 4	PART NOT FITTED	1140063
8230	#####	1E+06	Consumables		1140063
8230	#####	1E+06	PTI Tablet Entered - Elec and Light - Exterior Lights. right	Replaced globe	1140063
8230	#####	1E+06		VEHICLE SAFETY INSPECTION	1137962
8230	#####	1E+06		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1137962
8230	#####	1E+06		ANNUAL SAFETY INSPECTION SERIAL # RSI 052418 - PASS - 10.10.2023 WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLE SAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	1137962
8230	#####	1E+06		Assisting completed rsi.	1137962
8230	#####	1E+06		Assisted Zubair to adjusting the right vehicle height	1137962
8230	#####	1E+06	CARRYOUT ANNUAL INSPECTION	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G352260 Receiving #:372858 Date :2023-11-02 BUS 8230 - RWC -10.10.2023	1142103
8230	#####	1E+06	Service	waiting ECU	1137962
8230	10/9/2023	1E+06	Consumables		1137962
8230	10/9/2023	1E+06	Consumables		1137962
8230	10/9/2023	1E+06	Mechanic entered - Elec and Light Other	adjust safety edges. complete	1137962
8230	10/9/2023	1E+06	Mechanic entered - Elec and Light Other	checked high coolant temp warning light replaced temp sensor with spare from up stairs fault still was showing checked plug for ecu and found to be full of dirt and excessive amount of grease applied cleaned plug and refill test drove bus around yard and left running to warm up fault has been fixed warning light no longer	1137962
8230	10/9/2023	1E+06	Consumables		1137962
8230	10/9/2023	1E+06	Carry out final inspection for RSI	completed	1137962
8230	10/9/2023	1E+06		carried out assist	1137962
8230	10/6/2023	1E+06	Drv entered - Suspension Knee/ Raise	Operate knee/raise working ok. (note: to kneeling or raising the bus needs to close both front and rear doors.)	1137682
8230	9/28/2023	1E+06	Mechanic entered - Wipers and Washers Other Wiper blades U/S	replaced both wipers blade	1136648
8230	9/28/2023	1E+06	WIPER BLADE ASSY 1000MM N102		1136648
8230	9/28/2023	1E+06	Consumables		1136648
8230	9/28/2023	1E+06	Consumables		1136648
8230	9/28/2023	1E+06	Consumables		1136648
8230	9/28/2023	1E+06	PTI Tablet Entered - Elec and Light - Exterior Lights right p	replaced front blown park globe and teste tested ok.	1136648
8230	9/28/2023	1E+06	Mechanic entered - Elec and Light Other N/S head light dull.	checked and cleaned headlight lenses headlights tested ok	1136648
8230	9/28/2023	1E+06	Mechanic entered - Elec and Light Interior Lights Dash switc	replaced al blown dash light globes and tested tested ok	1136648
8230	9/28/2023	1E+06	Mechanic entered - Body Other Steam dean under the bus for	completed	1136648
8230	9/28/2023	1E+06	Mechanic entered - Body Other Front n/s and o/s wheel arc wo	replaced O/S wheel arch Sathees changed N/S	1136648
8230	9/28/2023	1E+06	WHEEL ARCH BRUSH 12065		1136648
8230	9/28/2023	1E+06	SEAT CUSH SINGLE CEN CVR RA		1136648
8230	9/28/2023	1E+06	SEAT CUSH DBL CEN 680 CVR - CL		1136648
8230	9/28/2023	1E+06	Mechanic entered - Body Passenger Seat Torn	replaced the seat	1136648
8230	9/28/2023	1E+06		Assisted.	1136648
8230	9/28/2023	1E+06	Mechanic entered - Brakes Other Brake paddle rubber worn	replaced the rubber	1136648
8230	9/28/2023	1E+06	PEDAL RUBBER BRAKE PAD FLAT MERC 500LE A110291018201		1136648
8230	9/28/2023	1E+06	VALVE BOTTOM DOOR SWITCH REG/GREEN		1136648
8230	9/28/2023	1E+06	Mechanic entered - Air System Air_Leak Front of the bus.	Repair air leak	1136648
8230	9/26/2023	1E+06		PRE ANNUAL SAFETY INSPECTION CHECK Completed	1136636
8230	9/26/2023	1E+06		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	1136636
8230	9/26/2023	1E+06		Replaced swab bar D bushes.	1136636
8230	9/26/2023	1E+06	BUSH FRT & RR SWAY BAR MERC BE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G351544 Receiving #:370173 Date :2023-09-26	1136396
8230	9/25/2023	1E+06	Driver Tablet Entered - Suspension - Noisy	check& found Front Dbus noisy luricated & check still noisy parts on order.	1135615
8230	9/15/2023	1E+06	Workshop Tablet Entered -very loud continuous noise while	check noise come thure rear speakers found wire lose conection fixed wire road tested bus ok.	1135615
8230	9/15/2023	1E+06	Ops Entered - Fault - Engine Belts_Loose Nisys Missing - Ro	check ok.	1135615
8230	9/14/2023	1E+06		Repair damage wire harnes clear all fault codes road tested bus ok.	1135615
8230	9/13/2023	1E+06		check fuel unit injector pump wire harnes pin 50 short sercuite c/o	1135615
8230	9/11/2023	1E+06	Fault#:38860 - Ops Entered - Fault - Breakdown Not Starting	Attend to B/down start bus drive to depot conect Actia check fault cant; find any still bus stop engine it self c/o	1135585
8230	9/8/2023	1E+06			1135585
8230	9/8/2023	1E+06	OIL DIFFERENTIAL SYNGEAR 75W-140 CALTEX		1135585
8230	9/8/2023	1E+06	Consumables		1135585
8230	9/8/2023	1E+06	Consumables		1135585
8230	9/8/2023	1E+06	Consumables		1135585
8230	9/8/2023	1E+06		CARRY OUT A SERVICE AS PER CHECK LIST carried out a service as per check list and tensioned all wheel nuts with feda.	1134792
8230	9/5/2023	1E+06		Retensioned wheel nuts pos 3 and 4.	1134792
8230	9/5/2023	1E+06		Assisted	1134281
8230	9/1/2023	1E+06	Consumables		1134281
8230	9/1/2023	1E+06	PTI Tablet Entered - Tyres No3 Worn out	Fitted new COOPER tyre pos 3 and 4. Tensioned wheel nuts to spec. (old tyre pos 4 back to rack)	1134281
8230	9/1/2023	1E+06	TYRE 295/80R22.5 NEW		1134281
8230	9/1/2023	1E+06		Assisted	1134168
8230	8/31/2023	1E+06		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST complete fire safety inspection as per check list	1133371
8230	8/28/2023	1E+06	PROGRAM ENGINE ECU FOR FAN SPE	Creditor #:GB-ABTC001 AUSTRALIAN BUS & TRUCK CARE P/O #:G349717 Receiving #:368074 Date :2023-08-28	1133150
8230	8/25/2023	1E+06	GASKET OIL SEPARATOR MERC BENZ 0500LE	PART NOT REQUIRED	1133132
8230	8/24/2023	1E+06	Workshop Tablet Entered - Engine - Noisy or Rattling loud hig	After carrying out the sump gasket repairs were we had disconnected the batteries and removed alternator and starter motor we had put it all back together and made some repairs to a ignition wire the loud high pitch sound the bus used to make has now stopped no more unusual noise.	1133132
8230	8/24/2023	1E+06		Found out why the bus had no ignition a small wire terminal came off the battery wires repaired the terminal. Now bus cranking the belt was miss aligned for water pump and A/C had to straighten the pulley to line it up. Engine now running took for long road test and check on pit on return no more oil leaks all clear. Oil try to start check and found that one off the wire broken on battery terminal fitted new wire connector and attached to the battery terminal. start the bus and A/C belt comes off because it was miss aligned removed all the belts fitted back A/C belt and aligned properly Fitted all other belts. Start the bus check all the after road test check the heater tap no coolant leak now .all ok	1133132
8230	8/24/2023	1E+06		Road test bus after Guri had repaired the heater tap no more coolant leaks.	1133132
8230	8/24/2023	1E+06	Consumables		1133132
8230	8/24/2023	1E+06	Mechanic entered - Elec and Light Flat Batteries more than 3	Found a small wire had broken off that does ignition repaired that wire now bus starting and cracking.	1133132
8230	8/23/2023	1E+06	BELT MICRO V SERPENT 9 RIB 2120mm LNG		1133132

8230	8/23/2023	1E+06	Fit back the starter motor alternator breaket and wiring fit new coolant pipes fit the new dip stick tube fit new belts and tensioned the crank dampner to 270nm standard M16 10.9. Topped up 33L of engine oil and put back drained coolant. Went to start the bus but batteries are soo dead not even getting ign.	1133132
8230	8/23/2023	1E+06	fitted breather engine oil dipstick oil level sensor . fitted alternator fan pulley all the belts . topped up coolant and engine oil. tighen all nuts and bolt according to the Merc. specs.	1133132
8230	8/22/2023	1E+06	Installed the seal runner and new front main seal with Guri installed the front cover with new gasket. Installed the sump with new gasket and silcon just over the corners where other gaskets meet. Tensioned all bolts to 35Nm.	1133132
8230	8/22/2023	1E+06	received the parts fitted front crank seal runner fitted crank seal and front cover tighten the cover bolt to 35 Nm fitted sump gaskit and sump back tighten the bolt to 35 nm.	1133132
8230	8/22/2023	1E+06	RUNNER FRT CRANK SEAL 457942 M	1133132
8230	8/21/2023	1E+06	SEAL CRANKSHAFT FRONT MERCEDES	1133132
8230	8/18/2023	1E+06	GASKET OIL SEPARATOR MERC BENZ	1133132
8230	8/18/2023	1E+06	SCREW OIL SUMP 457954 MERC BENZ	1133132
8230	8/18/2023	1E+06	received the parts while fitting the cranksaft front seal check and found that seal is wrong. So ordered the correct seal . getted out the sump from hot wash cleaned the old gaskit and selcon from the sump.	1133132
8230	8/18/2023	1E+06	OIL SEPARATOR BREATHER	1133132
8230	8/18/2023	1E+06	TUBE DIPSTICK MERC BENZ 0500LE	1133132
8230	8/18/2023	1E+06	GASKET OIL FILLER NECK MERC BE	1133132
8230	8/18/2023	1E+06	CARRY OUT FIRE EXTINGUISHER TEST & TAG completed by ATS.	1133132
8230	8/17/2023	1E+06	Assisting	1133132
8230	8/17/2023	1E+06	removed the engine sump cleaned the surface on block drain the oil from sump cleaned in the hot wash. removed the front crank seal and cover cleaned the cover and surface on the block. Ordered the parts. /o	1133132
8230	8/17/2023	1E+06	removed leaking coolant tap removed all connection cleaned all the thread puttred new thread tap and puttred together all fittings back. C/o	1133132
8230	8/17/2023	1E+06	Assisted Guri with removing sump and front engine cover cleaned parts and ordered all new seals and gaskets.	1133132
8230	8/17/2023	1E+06	SEAL CRANKSHAFT FRONT MERCEDES 0500LE 4	1133132
8230	8/17/2023	1E+06	HOSE COOLANT TAPERED 60/70 MERC BENZ 0500LE	1133132
8230	8/17/2023	1E+06	HOSE RADIATOR UPPER / LWR MERC BENZ 0500LE	1133132
8230	8/17/2023	1E+06	SCREW OIL SUMP 457954 MERC BENZ 0500LE	1133132
8230	8/17/2023	1E+06	GASKET OIL SUMP 457942 MERC BE	1133132
8230	8/17/2023	1E+06	GASKET FRT TIMING CVR 457942 M	1133132
8230	8/17/2023	1E+06	PERFORM CAMPAIGN 05/23 POSITIONING OF NO SMOKING NO VAPING	1133132
8230	8/16/2023	1E+06	Mechanic entered - Engine Other Engine sump leak	1133132
8230	8/16/2023	1E+06	Mechanic entered - Engine Other Coolant valve fitting leak ne	1133132
8230	8/16/2023	1E+06	Job fixed yesterday.	1133132
8230	8/12/2023	1E+06	VEHICLE SAFETY INSPECTION completed	1132524
8230	8/12/2023	1E+06	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS done with Feda	1132524
8230	8/12/2023	1E+06	assist sstl to do safety inspection as per check list. Complete.	1132524
8230	8/12/2023	1E+06	O-RING KIT LARGE VOS5 A6739970145	1132524
8230	8/10/2023	1E+06	Drv entered - A/C Heating Not Heating	1132382
8230	8/10/2023	1E+06	Run bus up to operating temperature demisters had a iroff at 40c A/C sat at set point 22c unable to fault	1132382
8230	8/9/2023	1E+06	Workshop Tablet Entered -ERROR - Fault type not set ramp ho	1132382
8230	8/7/2023	1E+06	A0025403624 ENGINE ECU	1132065
8230	8/1/2023	1E+06	Service	1131348
8230	8/1/2023	1E+06	Try to programe engine cooling fan by Actia can't do with Actia don't have option	1131348
8230	7/28/2023	1E+06	Removed ecu and tested out euro 4 adblue ecu first to read the fault codes saved in that one then replaced that ECU with the new Euro 3 ECU programmed for this bus all fitted in nice. Started the bus and checked for fault codes no more codes in the system Washed the engine bay as well and took for long road test bus	1131307
8230	7/28/2023	1E+06	Assisted Matt. Received ECU checked and recorded all codes. Removed ECU and replaced with new.	1131307
8230	7/21/2023	1E+06	Ops Entered - Fault - Warning Lights Coolant - Route: 900v	1130679
8230	7/21/2023	1E+06	HOSE ENG - G/BOX OIL COOLER MERC BENZ 0500LE 50N0547G	1130679
8230	7/21/2023	1E+06	Continue job fitted new transmission hose and top-up coolant. Steam cleaned transmission and engine. Roadtest check operation heater ok. No light on dash. After roadtest re check for leak ok no leak coolant level ok.	1130679
8230	7/18/2023	1E+06	ECU ENGINE MERC BENZ 0500LE E3	1130175
8230	7/18/2023	1E+06	CONNECTOR STRAIGHT BRASS 6MM	1130175
8230	7/18/2023	1E+06	REDUCER 4MM X 6MM METAL	1130175
8230	7/18/2023	1E+06	Air System Air Not Building_Up	1130175
8230	7/7/2023	1E+06	PERFORM CAMPAIGN 02/23 POSITIONING OF 2023 PTV FARES	1128278
8230	7/4/2023	1E+06	LAMP LED AMBER 177 X 100	1127579
8230	7/4/2023	1E+06	Workshop Tablet Entered -Elec and Light - Indicators Not Wor	1127579
8230	7/4/2023	1E+06	Consumables	1127579
8230	7/4/2023	1E+06	PERFORM CAMPAIGN 13/22 CONSAT VEHICLE INSTALLATION - VOLGRE	1127579
8230	7/4/2023	1E+06	PERFORM CAMPAIGN 13/22 CONSAT VEHICLE INSTALLATION - VOLGRE	1127579
8230	6/30/2023	1E+06	Myki 4G antenna need install	1127486
8230	6/30/2023	1E+06	Consumables	1127486
8230	6/27/2023	1E+06	REPROGRAMMING ECU	1126900
8230	6/16/2023	1E+06	carried out thorough steam clean	1125120
8230	6/13/2023	1E+06	Removed faulty Ecu and Fitted new ecu. road tested ok.	1124224
8230	6/9/2023	1E+06	Mechanic entered - Fluid Leaks Rear of bus Coolant leaks fro	1124172
8230	6/7/2023	1E+06	ECU ENGINE MERC BENZ 0500LE	1124172
8230	6/1/2023	1E+06	Engine Low PowerDriver reported very low power did not	1124172
8230	6/1/2023	1E+06	carried out checking turbo and exhaust brake butterfly turbo turbine spinning freely and exhaust brake butterfly opened removed exhaust flexing pipe to see if muffler was blocked muffler all good checked to see if exhaust brake was getting air exhaust brake getting air	1124172
8230	6/1/2023	1E+06	Completed	1124172
8230	5/30/2023	1E+06	VEHICLE SAFETY INSPECTION Completed safety service.	1124172
8230	5/30/2023	1E+06	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1124172
8230	5/30/2023	1E+06	Steam cleaned engine and gear box replace a clamp for O/S pipe hose. Ordered 2 taper hoses. Keep monitoring oil leaks. Coolant hose in stock.	1124172
8230	5/24/2023	1E+06	Used diagnose activa tool found ECU faults for exhaust gas after treatment which this euro 3 Merc does not have fitted in the first place. ECU is programmed wrong with euro 4 and up settings. Road tested bus was able to get to 80km but yes takes awhile to get there.	1124020
8230	5/24/2023	1E+06	Assisted Matt. Ran diagnostic scan and only found exhaust code. test driven still low power.	1124020
8230	5/10/2023	1E+06	Ops Entered - Fault - Engine Low Power - Route: 900v - Stud	1123862
8230	5/5/2023	1E+06	Ops Entered - Fault - Engine Low Power - Route: 802 - Chish	1123360
8230	5/2/2023	1E+06	PROGRAM ECU	1123042
8230	4/21/2023	1E+06	GLOBE HEADLAMP 24V 70W H7 HLC2470 48728 13972	1122206
8230	4/21/2023	1E+06	Elec and Light Exterior Lights- Driver reported head light	1122206
8230	4/21/2023	1E+06	Consumables	1122206
8230	4/20/2023	1E+06	Engine Low PowerDriver reported low power and especiall	1121905
8230	4/18/2023	1E+06	CARRY OUT A/C - B SERVICE AS PER CHECK LIST service as per list no oil in stock	1121531
8230	4/18/2023	1E+06	FILTER DRYER AIR COND THERMO KING 2750300 DML305R	1121531
8230	4/18/2023	1E+06	CARRY OUT A/C - A SERVICE AS PER CHECK LIST Service as per list	1121531
8230	4/11/2023	1E+06	Driver Tablet Entered -Body - Front_Door Operation Faulty fr	1121531
8230	4/11/2023	1E+06	Consumables	1121531
8230	4/4/2023	1E+06	A0025403624 ENGINE ECU	1120625
8230	4/3/2023	1E+06	CARRY OUT CTV - A SERVICE AS PER CHECK LIST Complete as per Check list.	1120625
8230	4/3/2023	1E+06	CARRY OUT C SERVICE AS PER CHECK LIST completed	1120625
8230	4/3/2023	1E+06	FILTER FUEL MERC BENZ 0500LE -> E5 A0004771302	1120625
8230	4/3/2023	1E+06	FILTER FUEL MERC BENZ 0500LE -> E5 A5410900151	1120625
8230	4/3/2023	1E+06	FILTER P/STRG MERC SCANIA VOLVO(0153468)(349619)	1120625
8230	4/3/2023	1E+06	OIL SAMPLE KIT AMPOL	1120625
8230	4/3/2023	1E+06	BREATHER OIL MIST MERC BENZ 0500LE A5410100163	1120625
8230	4/3/2023	1E+06	FILTER OIL MERC BENZ 0500LE ES OH1830 ES A0001801709	1120625

8230	7/27/2022	1E+06	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1091744
8230	7/27/2022	1E+06	BUZZER REVERSING 24V 102DB(NR72602)	1091744
8230	7/26/2022	1E+06	HOSE ELBOW MERC BENZ 0500LE	1091744
8230	7/22/2022	1E+06	Consumables	1091192
8230	7/22/2022	1E+06	Ops Entered - Fault - Body Front_Door Operation Faulty - Ro	1091192
8230	7/21/2022	1E+06	Fault#:38277 - Ops Entered - Fault - Breakdown Overheating/C	1091192
8230	7/21/2022	1E+06	Mechanic entered - Engine Other Broken fuel filter Bopwl . (1090998
8230	7/21/2022	1E+06	Mechanic entered - Engine Other Broken fuel filter Bopwl . (1090998
8230	7/21/2022	1E+06	950M/A0020946982 - HOSE (C01 O	1091192
8230	7/20/2022	1E+06	Mechanic entered - Engine Other Broken fuel filter Bopwl . (1090998
8230	7/20/2022	1E+06	AIRBAG FRT - RR MERC BENZ 0500LE E3 - ES OH1830 49Y2200	1090998
8230	7/20/2022	1E+06	HOSE ELBOW MERC BENZ 0500LE	1090998
8230	7/18/2022	1E+06	950M/A4572060211 - Driver Pull	1091192
8230	7/18/2022	1E+06	950M/A4572060011 - Pulley	1091192
8230	7/18/2022	1E+06		1090998
8230	7/15/2022	1E+06	***ACCIDENT***Ops Entered - Fault - Fluid Leaks Rear of bus	1090998
8230	7/15/2022	1E+06	VALVE BALL 1/2 HEATER 20MM	1090998
8230	7/15/2022	1E+06	Mechanic entered - Engine Other Broken fuel filter Bopwl . (1090998
8230	7/15/2022	1E+06		1090998
8230	7/14/2022	1E+06	Accident#53520_Rear	1090998
8230	7/14/2022	1E+06	FOAM TAPE 4MM X 22MM P/M	1090998
8230	7/14/2022	1E+06	REFLECTOR AMBER HELLA 94x44mm	1090998
8230	7/14/2022	1E+06	REFLECTOR RED 94MM X 4MM 84052	1090998
8230	7/14/2022	1E+06	DECAL DO NOT OVERTAKE 100MM X 300MM	1090998
8230	7/14/2022	1E+06	DECAL VENTURA SIDE FOR ROUTEBUS	1090998
8230	7/14/2022	1E+06	DECAL REAR PTV LOGO 300 x 170 mm	1090998
8230	7/13/2022	1E+06	LAMP LED REVERSE RECTANGULAR	1090998
8230	7/13/2022	1E+06	Accident#53520_Rear	1090998
8230	7/13/2022	1E+06	Rear header and side glass re-	1091192
8230	7/12/2022	1E+06	Accident#53520_Rear	1090998
8230	7/12/2022	1E+06	RUBBER W/ARCH EXTRUSION(0400211	1090998
8230	7/12/2022	1E+06	DECAL VENTURA YELLOW DN BLUE 480mm	1090998
8230	7/12/2022	1E+06	PAINT CLEAR COAT	1090998
8230	7/12/2022	1E+06	Accident#53520_Rear	1090998
8230	7/12/2022	1E+06	DIRECT PURCHASE - BODYWORK	1090998
8230	7/12/2022	1E+06	BRUSH WHEELARCH 75mm 2.5M PER METRE	1090998
8230	7/11/2022	1E+06	PAINT CLEAR COAT	1090998
8230	7/11/2022	1E+06	Accident#53520_Rear	1090998
8230	7/11/2022	1E+06	PAINT DEFLEET FAST HARDENER MS	1090998
8230	7/11/2022	1E+06	PAINT SPRAY CAN MATT BACK 400G	1090998
8230	7/11/2022	1E+06	Accident#53520_Rear	1090998
8230	7/8/2022	1E+06	Mechanic entered - Engine Other Broken fuel filter Bopwl . (1090998
8230	7/8/2022	1E+06	Accident#53520_Rear	1090998
8230	7/8/2022	1E+06	Accident#53520_Rear	1090998
8230	7/6/2022	1E+06	Mechanic entered - Engine Other Broken fuel filter Bopwl . (1090998
8230	7/5/2022	1E+06	Accident#53520_Rear	1090998
8230	7/5/2022	1E+06	Mechanic entered - Engine Other Broken fuel filter Bopwl . (1090998
8230	7/5/2022	1E+06	ERAZER WHEEL VINYL ZAPPER	1090998
8230	7/5/2022	1E+06	LCSB002 - D/S Large Lower Grey	1090998
8230	7/5/2022	1E+06	LCSB008 - D/S Black Curve	1090998
8230	7/5/2022	1E+06	Accident#53520_Rear	1090998
8230	7/5/2022	1E+06	D/S LOWER BLACK STRIPES	1090998
8230	7/5/2022	1E+06	LCSB027 - Rear Top Orange	1090998
8230	7/4/2022	1E+06	CLAMP P G/BOX COOLING PIPE MERC 0500LE	1090998
8230	7/4/2022	1E+06	FILTER AIR MERC 0500LE(A0040941704)	1090998
8230	7/4/2022	1E+06	Mechanic entered - Engine Other Broken fuel filter Bopwl . (1090998
8230	7/4/2022	1E+06	Accident#53520_Rear	1090998
8230	7/4/2022	1E+06	H5320T0N - HOSE CLAMP EA S/5 B	1090998
8230	7/1/2022	1E+06	Mechanic entered - Engine Other Broken fuel filter Bopwl . (1090998
8230	7/1/2022	1E+06	Mechanic entered - Engine Other Broken fuel filter Bopwl . (1090998
8230	7/1/2022	1E+06	Mechanic entered - Engine Other Broken fuel filter Bopwl . (1090998
8230	7/1/2022	1E+06	Mechanic entered - Engine Other Broken fuel filter Bopwl . (1090998
8230	7/1/2022	1E+06	Mechanic entered - Engine Other Broken fuel filter Bopwl . (1090998
8230	7/1/2022	1E+06	Mechanic entered - Engine Other Broken fuel filter Bopwl . (1090998
8230	7/1/2022	1E+06	Accident#53520_Rear	1090998
8230	6/30/2022	1E+06	REVERSE LINE 690	1090998
8230	6/30/2022	1E+06	REVERSE LINE 700	1090998
8230	6/30/2022	1E+06	LAMP LED NUMBER PLATE & EXIT LIGHT (250120) (2559)	1090998
8230	6/30/2022	1E+06	CANCEL LINE 20 NOT POSTED	1090998
8230	6/30/2022	1E+06	CANCEL LINE 70 NOT POSTED	1090998
8230	6/30/2022	1E+06	CANCEL LINE 100 NOT POSTED	1090998
8230	6/30/2022	1E+06	CANCEL LINE110 NOT POSTED	1090998
8230	6/30/2022	1E+06	RE-ENTER & POST LINE20	1090998
8230	6/30/2022	1E+06	RE-ENTER AND POST LINE 70	1090998
8230	6/30/2022	1E+06	RE-ENTER AND POST LINE 100	1090998
8230	6/30/2022	1E+06	RE-ENTER AND POST LINE 110	1090998
8230	6/30/2022	1E+06	REVERSE LINE 710	1090998
8230	6/30/2022	1E+06	REVERSE LINE 30 NOT POSTED	1090998
8230	6/30/2022	1E+06	REVERSE LINE 680	1090998
8230	6/29/2022	1E+06	VENT ROOF INTAKE POD	1090998
8230	6/28/2022	1E+06	SIKA SAUSAGE WHITE	1090998
8230	6/27/2022	1E+06	GUSSET LARGE	1090998
8230	6/27/2022	1E+06	Window Cappings - A4 A2 A3 x	1090998
8230	6/24/2022	1E+06	33813 - O/S REAR T/LIGHT CORNE	1090998
8230	6/17/2022	1E+06	SIKA S221 CARTRIDGE	1090998
8230	6/16/2022	1E+06	65x65x5 Angle Steel - 1.1m len	1090998
8230	6/11/2022	1E+06	50N1103 - Radiator mount	1090998
8230	6/11/2022	1E+06	50N0104 - Fan Shroud	1090998
8230	6/10/2022	1E+06	50N0105 - RUBBER SLEEVE RADIAT	1090998
8230	6/9/2022	1E+06	950M/A0025010601 RADIATOR (B98	1090998
8230	6/9/2022	1E+06	950M/A0009872043 RADIATOR RUBB	1090998
			Checked front doors found sensitive edge comes off to the bottom of the door. Refitted and adjust sensitive edge. Checked the operation of the front doors and sensitive edge ok.	
			Attened breakdown found water pump belt shredded fit temporary zipties water pump to crank topped up with water followed bus back to depot. Suspect bad A/C adjustment pulleys. changed date from 9/3/22 to 21/7/ to post wo	
			Received coolant hoses. Drained part of the cooling system and removed the damaged coolant hoses. Fitted new hoses and clamps. Refilled cooling system and started. Roadtested by Nick and no leaks	
			Creditor #EA-WHI004 WHITEHORSE TRUCK CENTRE P/O #EA323228 Receiving #:341669 Date :2022-07-22	
			r/r the air bags O/S/R (C/O)	
			Creditor #EA-WHI004 WHITEHORSE TRUCK CENTRE P/O #EA323228 Receiving #:341670 Date :2022-07-22	
			Creditor #EA-WHI004 WHITEHORSE TRUCK CENTRE P/O #EA325492 Receiving #:341668 Date :2022-07-22	
			Service as per list	
			repaired the the leaks	
			fitted new pulley	
			CARRY OUT A/C - A SERVICE AS PER CHECK LIST Stared service job not completed	
			Completed fit up. Cleaned and delivered to w/shop for their repairs.	
			Creditor #EA-OBRO01 O'BRIENS GLASS INDUSTRIES P/O #EA324881 Receiving #:341613 Date :2022-07-21	
			Replaced osr wheel arch rubber assy. Began fitting decals and lights.	
			fit up corner	
			prep for paint work	
			prep work to rear header n/s roof pod o/s remask and painted silver repainted n/s tail light panel due to not enough primer (shrinkage) and bubbling in filler.	
			prep for priming and painting	
			cleanup steering fluid in paintshop prep work to rear.	
			jump started the bus	
			Complete decal removal and shroud mod.	
			fitted new angle drive pulley refitted alternator drive pulley filled coolant (C/O)	
			Creditor #EA-LAB010 LABEL CONCEPTS P/O #EA324428 Receiving #:341393 Date :2022-07-19	
			Creditor #EA-LAB010 LABEL CONCEPTS P/O #EA324428 Receiving #:341393 Date :2022-07-19	
			Straightened and fit upper & lower radiator shrouding. Fit punch panel and locks. Completed panel mods/holes. Sealed int panels/trimms. Began decals remomoval.	
			Creditor #EA-LAB010 LABEL CONCEPTS P/O #EA324428 Receiving #:341393 Date :2022-07-19	
			Creditor #EA-LAB010 LABEL CONCEPTS P/O #EA324428 Receiving #:341393 Date :2022-07-19	
			fitted the radiator and intercooler pipings tight brackets C/O	
			Removed excess sika from header. Filled/shaped d-mold rivet holes. Weld 1x radiator bracket. Heat/straightened 1x radiator mount. Fit internal pillar access plate and ac vents. Secured wiring. Fit new window capping.	
			Creditor #EA-CBC001 CBC BEARINGS POWER TRANSMISSION P/O #EA324352 Receiving #:341489 Date :2022-07-20	
			Fitted new fuel filter and bowl bleed the system fitted N/S axle tensioned 420nm and drive the bus to eastcoust work shop Fitted N/S Axle and tensioned wheel nuts to 420Nm. Assisted Sisil.	
			Assisted Sisil Tensioned N/S Axle bolts to 420Nm.	
			removed radiator and intercooler and assembled new radiator and intercooler. (C/O) waiting for parts.	
			removed header tank and air box	
			removed the fuel lines and power steering resivor and frame	
			fitted air filter housing fuel filter housing power steering resivor fitted coolant resivor. C/O	
			Weld waist pillar access hole and fill/shape. Fibreglass and filler repair to eng hatch. Fill/shape header and ns bumper damage. Rivet inner eng wall panel. Remove panels for paint and tap new holes.	
			Creditor #EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #EA321230 Receiving #:337767 Date :2022-05-24	
			Creditor #EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #EA323134 Receiving #:340153 Date :2022-06-30	
			Creditor #EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #EA321230 Receiving #:340152 Date :2022-06-30	
			Creditor #EA-DAN001 DANDENONG STEEL P/O #EA323432 Receiving #:339818 Date :2022-06-23	
			Creditor #EA-MUL001 MULTISPARES LTD P/O #EA323229 Receiving #:339369 Date :2022-06-16	
			Creditor #EA-MUL001 MULTISPARES LTD P/O #EA323229 Receiving #:339369 Date :2022-06-16	
			Creditor #EA-MUL001 MULTISPARES LTD P/O #EA323208 Receiving #:339370 Date :2022-06-16	
			Creditor #EA-WHI004 WHITEHORSE TRUCK CENTRE P/O #EA321366 Receiving #:340073 Date :2022-06-28	
			Creditor #EA-WHI004 WHITEHORSE TRUCK CENTRE P/O #EA321366 Receiving #:340073 Date :2022-06-28	

8230	6/9/2022	1E+06	950M/A0025011701 INTERCOOLER O	Creditor #EA-WHI004 WHITEHORSE TRUCK CENTRE P/O #EA321366 Receiving #340073 Date :2022-06-28	1090998
8230	6/9/2022	1E+06	950M/A6295000668 FAN BELT TENS	Creditor #EA-WHI004 WHITEHORSE TRUCK CENTRE P/O #EA321366 Receiving #340073 Date :2022-06-28	1090998
8230	6/9/2022	1E+06	950M/A4572060011 PULLEY	Creditor #EA-WHI004 WHITEHORSE TRUCK CENTRE P/O #EA321366 Receiving #340073 Date :2022-06-28	1090998
8230	6/9/2022	1E+06	950M/A6343104637 CROSS MEMBER	Creditor #EA-WHI004 WHITEHORSE TRUCK CENTRE P/O #EA321366 Receiving #340073 Date :2022-06-28	1090998
8230	6/1/2022	1E+06	FILTER FUEL MERC BENZ 0500LE -> E5 A0004771302		1090998
8230	6/1/2022	1E+06	BOWL CHASSIS FILTER MERC BENZ	Creditor #GR-MUL001 MULTISPARES LTD P/O #G322531 Receiving #338399 Date :2022-06-01	1090998
8230	5/12/2022	1E+06	BUMPER CENTRE CR228L VOLGREN	Creditor #EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #EA321230 Receiving #337767 Date :2022-05-24	1090998
8230	5/12/2022	1E+06	LIGHT LED NO PLATE/REMERG EXIT	Creditor #EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #EA321230 Receiving #337767 Date :2022-05-24	1090998
8230	5/12/2022	1E+06	PLAIN COOLANT HATCH SURROUND 1	Creditor #EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #EA321230 Receiving #337767 Date :2022-05-24	1090998
8230	5/12/2022	1E+06	BUMPER O/S REAR CR228L VOLGREN	Creditor #EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #EA321230 Receiving #337767 Date :2022-05-24	1090998
8230	5/12/2022	1E+06	STRUT GAS STAY 450Nm 700mm	Creditor #EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #EA321230 Receiving #337767 Date :2022-05-24	1090998
8230	5/12/2022	1E+06	29980 - RED/AMBER SIDE MARKER	Creditor #EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #EA321230 Receiving #337767 Date :2022-05-24	1090998
8230	5/12/2022	1E+06	COOLANT DOOR HATCH 1/4 TURN LA	Creditor #EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #EA321230 Receiving #337767 Date :2022-05-24	1090998
8230	5/12/2022	1E+06	O/S RADIATOR PANEL	Creditor #EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #EA321230 Receiving #337768 Date :2022-05-24	1090998
8230	5/12/2022	1E+06	O/S REAR PILLAR	Creditor #EA-VOL001 VOLGREN AUSTRALIA PTY LTD P/O #EA321230 Receiving #337768 Date :2022-05-24	1090998
8230	5/6/2022	1E+06	***ACCIDENT***Fault#:38341 - Ops Entered - Fault - Breakdown	Car hit the bus and bus not driveable. call tow truck and tow bus to east coast for repair	1090998
8230	5/5/2022	1E+06	Tow bus 8230 to Eastcoast	Creditor #EA-EAG001 EAGLE TOWING AND SALVAGE P/O #EA321047 Receiving #337012 Date :2022-05-12	1090998
8230	5/4/2022	1E+06		VEHICLE SAFETY INSPECTION Completed	1090866
8230	5/4/2022	1E+06		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS with Kuma	1090866
8230	5/4/2022	1E+06		Assisting completed safety inspection as per checklist wit nick.	1090866
8230	5/4/2022	1E+06	Consumables		1090866
8230	5/4/2022	1E+06	Mechanic entered - Wheels and Tyres Other tyre no 1got a sc	checked found no nail no leak tyre still holds pressure ok	1090866
8230	5/4/2022	1E+06	Mechanic entered - Gearbox Driveline Other Differential pini	took driveshaft out and re tensioned diff pinion nut to 1000NM with nick ok	1090866
8230	5/4/2022	1E+06	Mechanic entered - Gearbox Driveline Other Differential pini	Assisted.	1090866
8230	5/4/2022	1E+06	Mechanic entered - Engine Other Muffler mount broken.	Repalced 1X muffler mount.	1090866
8230	5/4/2022	1E+06	MOUNT EXHAUST MERC 0500LE(A0004910285)		1090866
8230	5/3/2022	1E+06	PERFORM CAMPAIGN 03/22 QR CODE & SELECTED COVID19 DECAL REM		1090218
8230	4/26/2022	1E+06		CARRY OUT A SERVICE AS PER CHECK LIST Completed check list.	1089411
8230	4/26/2022	1E+06	Consumables		1089411
8230	4/26/2022	1E+06	Consumables		1089411
8230	4/26/2022	1E+06	Consumables		1089411
8230	4/26/2022	1E+06	Consumables		1089411
8230	4/2/2022	1E+06		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST Service complete as per checklist.	1087182
8230	3/18/2022	1E+06	Mechanic entered - Fluid Leaks Interior	Fitted new coolant hose.	1085595
8230	3/16/2022	1E+06	BELT MICRO V SERPENT 9 RIB 2120mm LNG		1085542
8230	3/16/2022	1E+06	PIPE COOLANT VOITH AIR COMP MERC 0500LE		1085542
8230	3/16/2022	1E+06	WASHER VOITH COMP COOL PIPE MERC 0500LE		1085542
8230	3/16/2022	1E+06	Fault#:38286 - Ops Entered - Fault - Breakdown Oil Leak - R	attended to b/down temperally fixed coolant leak from air compresure coolant pipe and fitted main drive belt bus send to depot replaced main drive belt need to change coolant pipe attempted to remove coolant hose off back of compressor	1085542
8230	3/16/2022	1E+06	Fault#:38286 - Ops Entered - Fault - Breakdown Oil Leak - R	Removed and replaced Air compressor coolant plastic pipe. Top up coolant and steam cleaned the engine. Drive tested and checked ccolant level and leaks all ok.	1085542
8230	3/16/2022	1E+06	Fault#:38286 - Ops Entered - Fault - Breakdown Oil Leak - R	Repaired by east coast	1085542
8230	3/16/2022	1E+06	Mechanic entered - Body Other rear bumper is damaged	re fitted idelers and belts tensioned and asjusted belts then built up air all ok.	1085520
8230	3/15/2022	1E+06	Mechanic entered - Body Other engine bay bar across top of e	assisted road tested	1085520
8230	3/15/2022	1E+06	Mechanic entered - Body Other engine bay bar across top of e	stripped old rear bar and fitted up new bars. rewired all rear lights added reflectors and decals	1085520
8230	3/15/2022	1E+06	BODYSHOP - REINFORCE AND WELD RHS HANGER IN ENGINE BAY		1085520
8230	3/15/2022	1E+06	DECAL DO NOT OVERTAKE 100MM X 300MM		1085520
8230	3/15/2022	1E+06	REFLECTOR RED 94MM X 4MM 84052		1085520
8230	3/11/2022	1E+06	BODYSHOP - REINFORCE AND WELD RHS HANGER IN ENGINE BAY	prepare and prime	1085520
8230	3/11/2022	1E+06	PAINTSHOP - PREPARE AND HIFILL REAR BUMPERPREPARE AND PAI	prep and paint parts base coat clear coat	1085520
8230	3/10/2022	1E+06	PULLEY IDLER/ ADJUSTER MERC BENZ 0500LE A0005501833		1085520
8230	3/10/2022	1E+06	BOLT IDLER / ADJUSTER PULLEY 1	Creditor #GB-MUL001 MULTISPARES LTD P/O #G317565 Receiving #333089 Date :2022-03-10	1085520
8230	3/10/2022	1E+06	BODYSHOP - REINFORCE AND WELD RHS HANGER IN ENGINE BAY	Ground the cracked area and welded the crack and reinforced the tube	1085520
8230	3/10/2022	1E+06	BODYSHOP - REINFORCE AND WELD RHS HANGER IN ENGINE BAY	Assisting	1085520
8230	3/10/2022	1E+06	Mechanic entered - Body Other engine bay bar across top of e	fitted intercooler pipe and secured coolant resevoir	1085520
8230	3/10/2022	1E+06	PAINTSHOP - PREPARE AND HIFILL REAR BUMPERPREPARE AND PA	booked out new n/s and centre rear bar removed rear bar pulled out o/s/ bar iron to lineup new bar prefit new n/s and centre bar repaired fibre glass on o/s/ bar corner prefit whole bar to alignn etc removed and primed rear bar.	1085520
8230	3/10/2022	1E+06	BUMPER REAR CENTRE VOLGREN FUTURE BUS		1085520
8230	3/10/2022	1E+06	BUMPER REAR N/SIDE CNR VOLGREN CR228		1085520
8230	3/9/2022	1E+06	BELT MICRO V SERPENT 9 RIB 2120mm LNG		1085520
8230	3/9/2022	1E+06	PULLEY IDLER/ ADJUSTER MERC BENZ 0500LE A0005501833		1085520
8230	3/9/2022	1E+06	Service		1085520
8230	3/9/2022	1E+06	Mechanic entered - Body Other engine bay bar across top of e	removed all mountings to bar and getting bodyshop to weld up.	1085520
8230	3/4/2022	1E+06	Steering (None) Power Steering significantly heavier than	Checked Steering and suspension OK. No leaks on steering lines and gearbox OK. Steering fluid level OK.	1084858
8230	3/4/2022	1E+06	Ops Entered - Fault - BusMinder Unable To Log In - Route:	checked busminder it was working fine.	1084858
8230	3/4/2022	1E+06	Ops Entered - Fault - BusMinder Unable To Log In - Route:	When bus checked busminder working correctly.	1084858
8230	3/4/2022	1E+06	Consumables		1084858
8230	3/2/2022	1E+06	Mechanic entered - Body Drivers Seat Controls height adjuste	remove and replace drivers seat .	1084412
8230	3/2/2022	1E+06	SEAT ASSY ISRI A6008 AIR LUMBAR CHANGE OVER		1084412
8230	2/21/2022	1E+06		CARRY OUT FIRE EXTINGUISHER TEST & TAG	1083200
8230	2/21/2022	1E+06		Completed by ATS	1083200
8230	2/15/2022	1E+06		Retensioned wheel nuts pos 5 and 6.	1082308
8230	2/15/2022	1E+06		Assisted Assisted	1082308
8230	2/14/2022	1E+06		VEHICLE SAFETY INSPECTION Completed VSI	1082178
8230	2/14/2022	1E+06		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Tensioned all wheel nuts w/ Ben.	1082178
8230	2/14/2022	1E+06		completed safety inspection as per checklist.	1082178
8230	2/14/2022	1E+06		Assisted and tensioned wheel nuts w/ Ben.	1082178
8230	2/14/2022	1E+06		Fitted new orig. tyres pos.56.	1082178
8230	1/25/2022	1E+06	Tablet Entered - Warning Lights - EngineMR7109 on dash	Look up fault code on busdoc. Check wiring diagram. Disconnect fan sensor plug check connection and resistance of prop. valves. Remove fan harness and inspect for breaks OK. re-install components and re-run wiring so that there is less strain on plug. Fault code no longer active. Test drive and park. Complete.	1079574
8230	1/25/2022	1E+06	Tablet Entered - Warning Lights - EngineMR7109 on dash	we looked up busdoc on the computer to find the fault code then we disconnected engine fan sensor and checked resistance of valves and then removed harness to inspect for damage. Reconnect and test drive.	1079574
8230	1/7/2022	1E+06	REMOVE OLD 2020 DECAL AND FIT NEW 2022 DECAL POSITION AS ST	Campaign completed	1077764
8230	1/7/2022	1E+06	REMOVE OLD 2020 DECAL AND FIT NEW 2022 DECAL POSITION AS ST	completed	1077764
8230	1/4/2022	1E+06		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST Completedy check list and replace rocker cover gasket.	1077231
8230	1/4/2022	1E+06	GASKET ROCKER CVR MERC BENZ 0500LE A4570160221		1077231
8230	1/4/2022	1E+06	Mechanic entered - Engine - Rocker cover leaking number	Replace rocker cover fitted new.	1077231
8230	1/4/2022	1E+06	COVER ROCKER MERC BENZ 0500LE 50A0023		1077231
8230	#####	1E+06	OIL ENGINE MOBIL DELVAC MODERN 15W-40 (MIN)		1074725
8230	#####	1E+06	Consumables		1074725
8230	#####	1E+06	Consumables		1074725
8230	#####	1E+06	Consumables		1074725
8230	#####	1E+06	Consumables		1074725
8230	#####	1E+06	BREATHER KIT ENGINE OIL MERCEDES 0500LE(A5410100163)		1074608

8230	12/7/2020	939665	Ops Entered - Fault - Air System Air Not Building_Up - Rou	Checked and air building ok. Aior unloading after air system full and driver complain about that and it is normal	1024527
8230	12/3/2020	936485	Air System - Check and repair air leak in the system.	Assisted Ryan with the fitting of air line	1024090
8230	12/3/2020	936485	FITTING		1024090
8230	12/3/2020	936485	Air System check and repair air leak in the system.	Removed and fit air line fittingmodified and weld by Ranjith. Road test and check for leak. No more air leak found	1024090
8230	12/2/2020	936485	VALVE MANUAL DRAIN 22MM VOLVO B7RLE 49G7901		1024090
8230	12/2/2020	936485	Air System check and repair air leak in the system.	Fit air tank fitting and weld it by Ranjithlell leaking C/O	1024090
8230	12/2/2020	936485	O RING AIR TANK - TEST NIPPLE	Creditor #:GB-WH004 WHITEHORSE TRUCK CENTRE P/O #:G288879 Receiving #:301385 Date :2020-12-03	1024090
8230	12/2/2020	936485	THRUST WASHER AIR TANK - TEST	Creditor #:GB-WH004 WHITEHORSE TRUCK CENTRE P/O #:G288879 Receiving #:301385 Date :2020-12-03	1024090
8230	12/1/2020	936485	AIR FITTING AIR TANK - TEST NI	Creditor #:GB-EN201 ENZED DANDENONG P/O #:G288647 Receiving #:302088 Date :2020-12-11 INCORRECT PART RETURNED FOR CREDIT	1025504
8230	#####	930854	WELD CROSS BEAM AT TREAT	Creditor #:GB-EA5002 EASTCOAST TRUCK & BUS SERVICE P/O #:G288489 Receiving #:301035 Date :2020-11-30	1024090
8230	#####	936485	KIT O-RING LARGE VOSS (A6739970145)		1024090
8230	#####	936485	Air System check and repair air leak in the system.	Done by Neil	1024090
8230	#####	936485	VALVE MANUAL DRAIN 22MM VOLVO B7RLE 1081328-5 1581425-4		1024090
8230	#####	936485	Air System - Check and repair air leak in the system.	identified where air leak is coming from air tank to drain valve fitting is cracked. parts have been Ordered C/O	1024090
8230	#####	936556	PERFORM CAMPAIGN 27/20 UPDATED INTERNAL BUS NUMBER DECALS	Done by Neil	1024090
8230	#####	936227	Ops Entered - Fault - Breakdown - Route: 900 - Chadstone	No one attend break down. Operation call to cancel	1023805
8230	#####	933730	PERFORM CAMPAIGN 26/20 REAR EXIT DECAL MAKE YOUR MARK & SER	completed.	1022170
8230	#####	932983	Remove old poster and fit you must wear a face mask when t	Replaced by Refuellers	1021558
8230	#####	932015	PERFORM CAMPAIGN 20/20 VEHICLE TOLLWAY ETAG FITMENT	Fit Etag	1020694
8230	11/9/2020	931477	Ops Entered - A/C Heating - Not Cooling - Route: 900 - Caul	Commission tested unable to fault top up refrigerant tested ok	1020668
8230	11/9/2020	931477	Ops Entered - Fault - A/C Heating Not Cooling - Route: - C	Commission tested unable to fault top up refrigerant tested ok	1020668
8230	11/9/2020	931477	Ops Entered - A/C Heating - Not Cooling - Route: 900v - Wel	Commission tested unable to fault top up refrigerant tested ok	1020668
8230	11/6/2020	931297	Steering Replace steering rod uny joint	replaced	1020668
8230	11/6/2020	930854	Engine - Rear cross member crack	Been welded by east Cost fit back wit new engine mounts	1020668
8230	11/5/2020	930854	Engine - Rear cross member crack	Remove rear crossmember and engine mounts C/O job	1020668
8230	11/5/2020	930854	MOUNT ENGINE MTG REAR MERC BENZ 0500LE 50Y3140		1020668
8230	11/5/2020	930854	NUT M16 X 1.5 RR ENGINE MOUNT	Creditor #:GB-WH004 WHITEHORSE TRUCK CENTRE P/O #:G286984 Receiving #:299393 Date :2020-11-06	1020668
8230	11/4/2020	930549		VEHICLE SAFETY INSPECTION	1020668
8230	11/4/2020	930549		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	1020668
8230	11/4/2020	930549		ANNUAL SAFETY INSPECTION - RWC 035129 - PASSED - 04/11/2020 - WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	1020668
8230	11/4/2020	930549		Assisting	1020668
8230	11/4/2020	931297	STEERING LINK A/ DRIVE TO STRG	Creditor #:GB-WH004 WHITEHORSE TRUCK CENTRE P/O #:G286807 Receiving #:299482 Date :2020-11-09	1020670
8230	#####	929853	Seats located in disabled area are worn out	Repair floor crack under L/H Disable seat - eaats still serviceble	1019937
8230	#####	929803	Carry out final inspection for RSI also take brake report	done	1019937
8230	#####	929803	Carry out final inspection for RSI also take brake report	done	1019937
8230	#####	929803	Consumables	Assisting	1019941
8230	#####	929853	Consumables		1019941
8230	#####	929542	Fit new Myki Decals & refit COVID-19 decals new position fo	completed.	1019937
8230	#####	929542	Fit new Myki Decals & refit COVID-19 decals new position fo	Assist Mark	1019937
8230	#####	929252	Ops Entered - BusMinder - Unable To Log In - Route: 900 - S	Re-boot Bus Minder system and check USB charging. Job complete	1019687
8230	#####	929252	Consumables		1019937
8230	#####	928945	Ops Entered - Body - Front Door Operation Faulty - Route: 9	checked ok.	1019580
8230	#####	928945	Consumables		1019687
8230	#####	926148		Convert comms wire to new type connector on desto connect check and re-assemble. Completed	1018755
8230	#####	927304	Elec and Light - Front destination screen not working		1018755
8230	#####	926148	O20020-O GREEN MALE TERMINAL	Creditor #:GB-MOB002 MOBITEC AUSTRALIA PTY LTD P/O #:G285684 Receiving #:298313 Date :2020-10-20	1018765
8230	#####	926148	O20030 TERMINAL	Creditor #:GB-MOB002 MOBITEC AUSTRALIA PTY LTD P/O #:G285684 Receiving #:298313 Date :2020-10-20	1018765
8230	#####	926148	Mechanic entered - Elec and Light - Exterior Lights dest	completed.	1018755
8230	#####	926148	Consumables		1018765
8230	#####	927304	Consumables		1018765
8230	#####	926871	Engine - Secure coolant tank pipes	Secured	1018755
8230	#####	926871	Elec and Light - Dash light U/S	Replace globes	1018755
8230	#####	926871	Elec and Light - Replace R/H F indicator lens	replaced	1018755
8230	#####	926871	LAMP CLEAR FRNT INDICATOR WRAP-AROUND		1018755
8230	#####	926871	Consumables		1018755
8230	#####	926871	BUTTERFLY AIR VENT 300516		1018755
8230	#####	926871	Body - Secure rear bumper bar	Secured	1018755
8230	#####	926871	Body - Secure rear door moddsty panel	Secured	1018755
8230	#####	926871	Body - Replace driver seat belt	Replaced	1018755
8230	#####	926871	Body - Fix driver damaster vent	Fit new one	1018755
8230	#####	926871	Body - Clean corrosion and paint under front of bus	Repaired	1018755
8230	#####	926871	Body - Secure side panels	secured	1018755
8230	#####	926871	Body - Steam clean all bus	Cleaned	1018755
8230	#####	926871	Consumables		1018755
8230	#####	926847		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST Inspection completed	1018755
8230	#####	926551		PRE ANNUAL SAFETY INSPECTION CHECK	1018755
8230	#####	926551		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST	1018755
8230	#####	926148	Mechanic entered - Elec and Light - Exterior Lights dest	Remove desto cover and the back of destination unit check power supply at unit look for loose wires- all ok. Perform continuity check on communication wires between desto controller and display.- All ok suspected destination display.	1018755
8230	10/7/2020	924788	Drv entered - Wipers and Washers Wipers Not_Clearing Screen	Replaced wiper blade assembly.	1017705
8230	10/7/2020	924788	ASSY WIPER BLADE ASSY 1000mm (TRP1000 is Refill)		1017705
8230	10/7/2020	923971	TANK AIR / PINK TANK MERC BE		1017988
8230	10/5/2020	923971	VALVE DRAIN VALVE CONDENSOR MERCEDES 0500LE A0054327401	Creditor #:GB-WH004 WHITEHORSE TRUCK CENTRE P/O #:G285127 Receiving #:297574 Date :2020-10-08	1017411
8230	10/5/2020	923971	FILTER AIR FILTER CHECK VALVE 22mm CYCLONE		1017411
8230	10/5/2020	923971		Carried out check list Remove and replace air compressor unloader hose and coupling. Remove and replace air line pipe. Replace air line o-ring kit. Test checked for leak all ok. Roadtested ok.	1017411
8230	10/5/2020	923971	KIT O-RING LARGE VOSS (A6739970145)		1017411
8230	10/5/2020	923971	FILTER DRYER SCANIA/VOLVO (1375997) (3090288-6) (49G8704W)		1017411
8230	10/5/2020	923971	HOSE COMPRESSOR TO UNLOADER MERCEDES (A0014292135)		1017411
8230	10/5/2020	923971	COUPLING AIR HOSE - COMP MERC BENZ 0500LE A0089970889		1017411
8230	9/28/2020	922258	OIL DIFFERENTIAL OIL SYNTHETIC FM 75W-140 (3083208)		1016276
8230	9/25/2020	922258	Service	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST Diff service completed.	1016167
8230	9/24/2020	921944	Body - Step Yellow Strips Missing at Rear	fitted new step strips. **PART BOOKED AT E / COAST**	1015456
8230	9/21/2020	921323		Done with Rene.	1015456
8230	9/21/2020	921323		Assisted Saqid.	1015456
8230	9/17/2020	920713		VEHICLE SAFETY INSPECTION Completed check list.	1015456
8230	9/17/2020	920713		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done Assisted by Tayla for wheel nut tension.	1015456
8230	9/17/2020	920734	Mechanic entered - Wheels and Tyres Worn Position 3 tyre wor	Remove pos. 3 Fitted nut on tyre and tension wheel nuts Assisted by Abraham. Steam cleaned rim too much dirt.	1015456
8230	9/17/2020	920734	Consumables		1015456
8230	9/17/2020	920735	Mechanic entered - Brakes Other O/s front brake booster air	Rectify found out clamp bolt loose Retightened bolt and build up air check operation no air leak all ok.	1015456
8230	9/17/2020	920746	KIT O-RING LARGE VOSS (A6739970145)		1015456
8230	9/17/2020	920746	VALVE MANUAL DRAIN 22MM VOLVO B7RLE 1081328-5 1581425-4		1015456
8230	9/17/2020	920746	Mechanic entered - Air System Air_Leak Rear Air tank voss nu	R/r 6 voss nuts o-ring kit air line fittings. Retightened air line pipe nuts and replace air tank drain tap found out faulty as well.	1015456

8230	9/4/2020	918259	Mechanic entered - Gearbox Driveline Other loose pinion diff	Removed tailshaft and re-tightened diff pinion nut.	1013916
8230	9/4/2020	918256		CARRY OUT A SERVICE AS PER CHECK LIST Completed A service and tensioned ll wheel nuts w/Sadid.	1013916
8230	9/4/2020	918256	Consumables		1014027
8230	9/4/2020	918256	Consumables		1014027
8230	9/4/2020	918256	Consumables		1014027
8230	8/25/2020	915982	Ops Entered - Elec and Light - Indicators Not Working - Ro	fixed new stalk and new o/side s indicator	1011752
8230	8/25/2020	915982	COMBINATION SWITCH MERC BENZ 0500LE A0085450124		1011752
8230	8/25/2020	915982	INDICATOR SWITCH MERC BENZ 0500LE A0085450124		1011752
8230	8/25/2020	915982	INDICATOR SIDE INDICATOR R/H		1011866
8230	8/25/2020	915982	Consumables		1011866
8230	8/24/2020	915785	Elec and Light - All External R/H/S Indicators N/W	fixed changed near side indicator outside door globe fixed all working.	1011689
8230	8/24/2020	915785	Consumables		1011689
8230	8/22/2020	913814	REPLACE ANTI GRAFFITI FILM	Creditor #:GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G281711 Receiving #:294339 Date :2020-08-24 REPLACE- L2	1011752
8230	8/14/2020	913814	Vandalism - Replace Anti Graffiti Film - L2	COMPLETED BY GLASSPROTECH	1010324
8230	8/14/2020	913814	Vandalism - Replace Anti Graffiti Film - L2	Assisting - COMPLETED BY GLASSPROTECH	1010324
8230	8/13/2020	913684	Mechanic entered - Elec and Light Exterior Lights Rear numbe	R/R 1 LED light.	1010183
8230	8/13/2020	913684	LAMP LED NUMBER PLATE & EXIT LIGHT (250120) (2559)		1010183
8230	8/13/2020	913684	Consumables		1010324
8230	8/6/2020	913233	Completed by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG	1008951
8230	8/2/2020	910514	Remove old A3 Poster and fit with You can no longer top up	Completed by Refuellers	1008007
8230	7/24/2020	908922		Book back tension done with neven	1006183
8230	7/24/2020	902425	PICK UP FROM PRINCES HWY CLAYT	Creditor #:GB-EAG001 EAGLE TOWING & SALVAGE P/O #:G278284 Receiving #:292126 Date :2020-07-24 BRING TO DEPOT	1006183
8230	7/24/2020	908837	Mechanic entered - CCTV not working no power.	found cctv hdd not locked in.	1006183
8230	7/24/2020	908855	Mechanic entered - Air System Other air fittings leaking nea	Fitted new seals to air fitting checked brake and road tested	1006183
8230	7/24/2020	908855	KIT O-RING LARGE VOSS (A6739970145)		1006183
8230	7/24/2020	908855	Mechanic entered - Air System Other air fittings leaking nea	Checked tayla and found exhaust brake solenoid internally damage thecoiland air leaking to exhaust brake and stall the enging. Replacedexhaust brake solenoid and retarder solenoid. Road tested by Elias all Ok.	1006183
8230	7/23/2020	908225	VALVE SOLENOID EXH BRAKE MERC BENZ 0500LE A0059971236		1006183
8230	7/23/2020	908225	Fault#:37718 - Ops Entered - Fault - Breakdown Not Starting		1006183
8230	7/23/2020	908225	VALVE SOLENOID EXH BRAKE MER	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G280164 Receiving #:292077 Date :2020-07-23	1006183
8230	7/22/2020	908225	Fault#:37718 - Ops Entered - Fault - Breakdown Not Starting	Broken down - Air leaks under bus and and stalling engine - towed back to depot	1006183
8230	7/22/2020	908225	PICK UP FROM OAKLEIGH	Creditor #:GB-EAG001 EAGLE TOWING & SALVAGE P/O #:G280107 Receiving #:292455 Date :2020-07-30 BRING BACK TO DEPOT	1007400
8230	7/21/2020	908065		VEHICLE SAFETY INSPECTION Completed check list.	1006179
8230	7/21/2020	908065	Consumables	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done Assisted by Abraham for wheel nut tension.	1006179
8230	7/21/2020	908076	Mechanic entered - Wheels and Tyres Worn Position 2 tyre wor	Remove position 1 and 2 tyre fitted new. Position 1 return to rack Tensioned wheel nuts with Abraham.	1006179
8230	7/21/2020	908076	TYRE 295/80R22.5 NEW		1006179
8230	7/21/2020	908128	LAMP LED NUMBER PLATE & EXIT LIGHT (250120) (2559)		1006179
8230	7/21/2020	908128	Mechanic entered - Elec and Light Other Number plate light b	Remove and fitted new.	1006179
8230	7/21/2020	908128	Consumables		1006183
8230	7/21/2020	908108	Mechanic entered - Brakes Other Brake pedal rubber worn.	Remove and replace fitted new.	1006179
8230	7/21/2020	908108	PAD BRAKE PEDAL RUBBER MERC BENZ 500LE A1072910182		1006179
8230	7/21/2020	908103	KIT O-RING SMALL VOSS (A0309971748)		1006179
8230	7/21/2020	908103	Mechanic entered - Air System Air_Leak Rear Circuit valve ai	Remove and replace air line o ring kit.	1006179
8230	7/21/2020	908103	KIT O-RING LARGE VOSS (A6739970145)		1006179
8230	7/21/2020	908106	NIPPLE TEST AIR TANK VOLVO B10BLE 30G4500WABCO		1006179
8230	7/21/2020	908106	Mechanic entered - Air System Air_Leak Rear Air tank drain v	Remove and fitted new drain valve.	1006179
8230	7/21/2020	908106	VALVE MANUAL DRAIN 22MM VOLVO B7RLE 1081328-5 1581425-4		1006179
8230	7/1/2020	904190	Consumables		1003117
8230	7/1/2020	904190	Mechanic entered - Elec and Light Other L/H SIDELOW BEAM-OU	Fitted new low beam bulb n/s.	1002832
8230	7/1/2020	904190	GLOBE 24V 70W H1		1002832
8230	6/26/2020	903383	Breakdown Warning Light ON; collant leak ; overheating.	Dandenong bus entered in Moorabbin TIMS	1002313
8230	6/25/2020	902425	Fault#:37654 - Ops Entered - Fault - Breakdown Overheating/C	This job enter twice.	1002027
8230	6/23/2020	902425	Service	R/R coolant hose behind air compressor. Filled up coolant and cleaned the engine. (needs to replace idler pulley drive test and check leaks. C/O	1001676
8230	6/23/2020	902425	PULLEY IDLER/ ADJUSTER MERC BENZ 0500LE A0005501833		1001676
8230	6/23/2020	902425	Fault#:37654 - Ops Entered - Fault - Breakdown Overheating/C	fitted new idler pulley between waterpump and crank as it broke off. adjusted to correct pivot roadtested by Indika and washed to check for leaks Olay	1001676
8230	6/23/2020	902425	Fault#:37654 - Ops Entered - Fault - Breakdown Overheating/C	Fixed.	1001676
8230	6/22/2020	902425	Fault#:37654 - Ops Entered - Fault - Breakdown Overheating/	bus came by tow truck check and found compressor colant hose leak.	1001676
8230	6/22/2020	902425	PIPE COOLANT VOITH COMPRESSOR - BLOCK 0500LE		1001676
8230	6/22/2020	902298	Warning alarm is constantly on	repaired	1001676
8230	6/12/2020	900571	FT A3 Poster in poster frame and fit decals as requested i	Completed	1000122
8230	6/5/2020	899000	uplode new desto pile	done	999220
8230	6/5/2020	898879		CARRY OUT A SERVICE AS PER CHECK LIST	999220
8230	6/5/2020	898879	Consumables	CARRY OUT A SERVICE AS PER CHECK LIST	999220
8230	6/5/2020	898879	Consumables		999220
8230	6/5/2020	898879	Consumables		999220
8230	6/5/2020	898879	Consumables		999220
8230	6/5/2020	898879	Consumables		999220
8230	6/2/2020	898036		CARRY OUT CCTV - A SERVICE AS PER CHECK LIST completed service.	998400
8230	5/22/2020	896178		Assisted	996655
8230	5/22/2020	896178		Retensioned all rear wheel nuts with Nick.	996655
8230	5/22/2020	895909	REPAIR SINGLE SEAT BASE	Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G275964 Receiving #:287501 Date :2020-05-25	996997
8230	5/22/2020	896045	Mechanic entered - Brakes Other O/S/R brakes un-even wear	removed all rear wheels and replaced both side rear brake pads and adjusted tensioned all wheel nuts	996655
8230	5/22/2020	896045	Mechanic entered - Brakes Other O/S/R brakes un-even wear	fit new rear brake pads brake tested ok road tested ok.	996655
8230	5/22/2020	896045	SET DISC PAD SET SCANIA / MERCEDES 0500		996655
8230	5/22/2020	896045	Mechanic entered - Air System Air_Leak Rear	fit new air pipe seals.tested ok.	996655
8230	5/22/2020	896045	Mechanic entered - Air System Air_Leak Rear	replaced air dryer pipe seals and tested all good	996655
8230	5/22/2020	896045	KIT O-RING LARGE VOSS (A6739970145)		996655
8230	5/21/2020	895897		VEHICLE SAFETY INSPECTION Completed safety inspection as per check list.	996655
8230	5/21/2020	895897	Consumables	TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	996655
8230	5/21/2020	895913	Mechanic entered - Suspension Other O/S/R front airbag leaki	Fitted new airbag.	996655
8230	5/21/2020	895913	AIRBAG FRONT+REAR MERC 0405/0500 REAR/VOLVO B10M/B7R REAR		996655
8230	5/21/2020	895907	Mechanic entered - Body Other wheel arch brush worn	Removed and fitted new wheel arch brush and rubber.	996655
8230	5/21/2020	895907	WHEEL ARCH BRUSH 12065		996655
8230	5/21/2020	895907	WHEEL ARCH RUBBER		996655
8230	5/21/2020	895909	Mechanic entered - Body Passenger Seat Torn	Fitted new passenger seat base.	996655
8230	5/21/2020	895910	Mechanic entered - Body Other Rear no smoking decals missing	Fitted 2 new no smoking decals.	996655
8230	5/21/2020	895910	DECAL NO SMOKING GOVERNMENT REGULATIONS 150MM X 80MM		996655
8230	5/19/2020	895355	Drv entered - Elec and Light Exterior Lights	replaced globe n/s front park light.	996194
8230	5/19/2020	895355	Consumables		996557
8230	5/16/2020	894338	PERFORM CAMPAIGN 06/19 DRIVERS SECURITY SCREEN UPGRADE	Completed by ECTB	996153
8230	5/13/2020	894338	PERFORM CAMPAIGN 06/19 DRIVERS SECURITY SCREEN UPGRADE	Sent bus to ECTB	995909

8230	#####	857707	REPLACE ANTI GRAFFITI FILM	Creditor #:GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G263600 Receiving #:275031 Date :2019-12-16 L1	970023
8230	12/5/2019	859069	DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 ROAD SAFETY INSPECTIONS P/O #:G264015 Receiving #:275692 Date :2019-12-23 ANNUAL INSPECTION	971051
8230	12/4/2019	859069		VEHICLE SAFETY INSPECTION	967818
8230	12/4/2019	859069		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	967818
8230	12/4/2019	859069		ANNUAL SAFETY INSPECTION - RWC 017513 - PASSED - 04/12/19WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	967818
8230	12/4/2019	859069		Assisting	967818
8230	12/4/2019	859069		completed.	967818
8230	12/3/2019	858821	A3 Poster Frame Adhesive Decal Campaign please remove old	Completed by ECTB	967560
8230	12/1/2019	826598	CHECK AND REPAIR FULTE CODE ST	Creditor #:GB-WHH004 WHITEHORSE TRUCK CENTRE P/O #:G253049-A Receiving #:275362 Date :2019-12-19	970619
8230	12/1/2019	826598	Consumables		967560
8230	#####	857707	Vandalism - Replace Anti Graffiti Film - L1	Assisting - REPLACED BY GLASSPROTECH	966845
8230	#####	857707	Vandalism - Replace Anti Graffiti Film - L1	REPLACED BY GLASSPROTECH	966845
8230	#####	857565	Final chek for RSI	check for RSI fixed air leak from suspension air reglhator fitted front passanger door valve 2 silenceres done under wash bus ok.	966845
8230	#####	857565	SILENCER DOOR VALVE SILENCER		966845
8230	#####	857565	KIT O-RING SMALL VOSS (A0309971748)		966845
8230	#####	854947	REPAIR SINGLE SEAT BASE		964976
8230	#####	854681	Mechanic entered - Vandalism Vandalism/ Graffiti Interior Pu	Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G262762 Receiving #:272854 Date :2019-11-20	964563
8230	#####	854681	Mechanic entered - Vandalism Vandalism/ Graffiti Interior Pu	done	964563
8230	#####	855304	Engine replace oil filter pipess.	done.	964563
8230	#####	855377	Ops Entered - Fault - Fluid Leaks Rear of bus - Route: - T	Fixed.	964563
8230	#####	855377	RADIATOR CAP 70KPA MERC BENZ 0500LE A0005014615	Correctly coolant leaks found defectice radiator cap. R/R radiator cap and top up coolant. Wash radiator and drive tested ok.	964563
8230	#####	854947	Body - Secure lower skirt panels.	done	964563
8230	#####	855303	Body repair disabale seats	done	964563
8230	#####	855305	Body replace worn seat cushions	Fixed.	964563
8230	#####	855307	steem clean for RSI	Fixed.	964563
8230	#####	854947	KIT O-RING LARGE VOSS (A6739970145)	Completed.	964563
8230	#####	854947	KIT O-RING SMALL VOSS (A0309971748)		964563
8230	#####	855306	Brakes replace 6 way valve.	Fixed.	964563
8230	#####	855308	Brakes replace prake paddle rubber.	Fixed.	964563
8230	#####	855309	Air System repair air leak next air dryer.	Fixed.	964563
8230	#####	854681	REPAIR DISABLED SEAT BACK	Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G262562 Receiving #:272616 Date :2019-11-18	964563
8230	#####	854681	REPAIR DISABLED SEAT BASE	Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G262562 Receiving #:272617 Date :2019-11-18	964563
8230	#####	854947	HOSE OIL FILTER HSG - OIL COOLER MERC BENZ 0500LE 50A0029		964563
8230	#####	854947	HOSE OIL FILTER HSG - OIL COOLER MERC BENZ 0500LE 50A0031		964563
8230	#####	854947	PAD BRAKE PEDAL RUBBER MERC BENZ SOOLE A1072910182		964563
8230	#####	854947	KIT O-RING LARGE VOSS (A6739970145)		964563
8230	#####	854947	VALVE 6 WAY CIRCUIT PROTECTION VALVE		964563
8230	#####	854947	SEAL RING AIR DRYER - FOUR WAY VALVE MERC BENZ 0500LE		964563
8230	#####	854676		PRE ANNUAL SAFETY INSPECTION CHECK done.	964563
8230	#####	854676			964563
8230	#####	854676		CARRY OUT CCTV - B SERVICE AS PER CHECK LIST done.	964563
8230	#####	853270	VALVE PARK BRAKE VALVE MERCEDES BENZ 0500LE (A0034307581)		963965
8230	11/8/2019	853516	Ops Entered - Fault - Body Front_Door Operation Faulty - R	checked and lubricate doors.	963500
8230	11/7/2019	853270	Mechanic entered - Brakes Park_Brake Leaking Air Replace han	R/R hand brake valve. Checked air leaks ok.	963384
8230	11/7/2019	853237	KIT O-RING LARGE VOSS (A6739970145)		963384
8230	11/7/2019	853237	Ops Entered - Fault - Air System Air_Leak Rear - Route: -	repair air leak	963384
8230	11/6/2019	852771	Ops Entered - Fault - Air System Air_Leak Rear - Route: -	Safety Inspection Completed with Abraham and tensioned all wheel nuts	962990
8230	11/6/2019	852771		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Completed vehicle safety inspection and tensioned wheel nuts w/ Ryan	962990
8230	11/6/2019	852771		VEHICLE SAFETY INSPECTION	962990
8230	11/6/2019	852824	MUFFLER MOUNTING (A0004910285)		962990
8230	11/6/2019	852824	Mechanic entered - Body Other Muffler rubber mount worn	Replaced muffler mount	962990
8230	11/6/2019	852923	Mechanic entered - Air System Other Air leaking near 4 way v	fixed air leaks	962990
8230	11/6/2019	852746	Bwere doing ATM	CARRY OUT CCTV - A SERVICE AS PER CHECK LIST	962990
8230	#####	850949	Vandalism (None) - rear passenger side seat base broken.	seat base was removed-re secured it whlist on fire safety inspection	961660
8230	#####	850951	Consumables		961871
8230	#####	850948	Consumables		961871
8230	#####	850951	Mechanic entered - Elec and Light Other battery bridge cable	removed corroded bridge cable and made new one and fitted.	961660
8230	#####	850948	Mechanic entered - Elec and Light Other batt solinoid not se	re secured the battery solinoid to body.	961660
8230	#####	850837	Accident - Rear bumper damage both sides - NIS	Still no acc report from Feb 2019	961660
8230	#####	850945		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST washed under engine and around top and di the fire safety	961660
8230	#####	849460	SEAT FOAM CUSHION PAN DRIVERS SEAT ISRI A6008BASE		959708
8230	#####	849460	Ops Entered - Fault - Body Drivers Seat. no cushion for the	check and fixed seat adjuster replaced cushion bus ok.	959708
8230	9/28/2019	844810	Ops Entered - Fault - Air System Air Not Building_Up - Rou	No fault found	956232
8230	9/20/2019	843493	Consumables		954840
8230	9/20/2019	843493	Consumables		954840
8230	9/20/2019	843493	Consumables		954840
8230	9/20/2019	843493	Consumables		954840
8230	9/20/2019	843493	Consumables		954740
8230	9/20/2019	843493	Consumables		954740
8230	9/13/2019	841758	REPAIR SINGLE SEAT BASE	CARRY OUT A SERVICE AS PER CHECK LIST A Service Completed and tensioned all wheel nuts with Joel	953500
8230	9/11/2019	841746		Creditor #:GB-AUT005 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G257847 Receiving #:267269 Date :2019-09-13	952914
8230	9/11/2019	841746		Assisted Rene.	952914
8230	9/11/2019	841746		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Kumar.	952914
8230	9/11/2019	841746		VEHICLE SAFETY INSPECTION Completed check list and repairs.	952914
8230	9/11/2019	841759	Mechanic entered - Body Other Disability decals ripped.	Remove and replace.	952914
8230	9/11/2019	841758	SINGLE SEAT BASE		952914
8230	9/11/2019	841758	Mechanic entered - Body Passenger Seat Torn	Remove and fitted three(3) new seat base (seat cushion).	952914
8230	9/11/2019	841753	Mechanic entered - Body Other Dis able folded seat backx res	Remove seat pin and secured retightened bolt bracket.	952914
8230	9/11/2019	841760	PLASTIC TRIANGLE HANDSTRAP GREY		952914
8230	9/11/2019	841760	Mechanic entered - Body Other Passenger hand strap worn.	Remove and fitted new eight(8) hand strap.	952914
8230	9/5/2019	840638	HOSE ELBOW RADIATOR MERC 0500LE A0008321794		952096
8230	9/5/2019	840638	Mechanic entered - Warning Lights Coolant leaking count	R/R collant hose. Filled coolant steam cleaned the engine. Drive tested and checked ok.	952096
8230	8/28/2019	838446	Consumables		950326
8230	8/28/2019	838446	LAMP LED SIDE LAMP RED/AMBER PERE (52-98002)		949861
8230	8/28/2019	838446	RHS Rear light not working	Replaced O/S/R marker light	949861
8230	8/22/2019	837243	Consumables		949130
8230	8/22/2019	837243	GLOBE 24V 70W H1		948876
8230	8/22/2019	837243	Mechanic entered - Elec and Light Exterior Lights HEADLIG	Fixed.	948876
8230	8/19/2019	836350		retension pos 3/4 5/6 with Inde.	948057
8230	8/18/2019	838091	Completed by ATS	CARRY OUT FIRE EXTINGUISHER TEST & TAG	948057
8230	8/16/2019	835963	BRAKE CALIPER NSR MERC 0500LE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G255746 Receiving #:264932 Date :2019-08-16	948039
8230	8/16/2019	835963	Mechanic entered - Brakes Park_Brake Not Holding	Checked calipers found N/S/R caliper not self adjuster faulty. Removed caliper and fitted new one. Adjusted brakes and tensioned wheel nuts with Kuma. Brake tested all pass.	948039

8230	#####	787124	Mechanic entered - Body Other rear engine hatch sound damp	East coast replaced Dampening material	913924
8230	12/1/2018	782261	DIRECT PURCHASE - BUS INSPECTI	Creditor #GB-ROA001 ROAD SAFETY INSPECTIONS P/O #G235481 Receiving #245434 Date :2018-12-21	913924
8230	12/1/2018	771009	SUPPLY SERVICE EXCHANGE GEARBO	Creditor #GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #G231584 Receiving #244522 Date :2018-12-12	913794
8230	#####	782789	Steering - NS kingpin faulty	Bus send white horse re repair	913794
8230	#####	782261		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	913794
8230	#####	782261		VEHICLE SAFETY INSPECTION	913794
8230	#####	782261	HELLA 24V REVERSING BUZZER 72602	ANNUAL SAFETY INSPECTION - RWC 015920 - PASSED - 28/11/18WORKSHOP SUPERVISOR/MANAGER NOTE: REDUCE THE VEHICLESAFETY INSPECTION LINE TIME ON THE W/O TO 0.25	913794
8230	#####	782057	ELBOW GMM X 1/4		913794
8230	#####	782057	FILTER PNEUMATIC REGULATOR DOOR RAM (AW20-02H-C)		913794
8230	#####	782057	Folding seat SUPERSLIM PLASTIC BASE Black Cover Mcc		913794
8230	#####	782057	Check over for RSI	replaced pasange seat base replace door regulator	913794
8230	#####	782140		CARRY OUT FIRE EXTINGUISHER TEST & TAG checked o/k	913794
8230	#####	780973	SWITCH DR CONTACT (NORMALLY OPEN) (M22-K10)		912864
8230	#####	780973	Mechanic entered - Body Front_Door Operation Faulty	check door found not shutting.had to press button really hard to work it.So removed and replaced switch and now ok.	912864
8230	#####	780554	SAGE OVERCENTRE LATCH 702LSS		912864
8230	#####	780554	Body - Replace back seat lock	fitted 2 new lock	912864
8230	#####	780553	Body - Adjust rear door sensitive edge	completed	912864
8230	#####	780538	Body - Secure hand rail grabs	completed	912864
8230	#####	780538	Body - Secure hand rail grabs	secured	912864
8230	#####	780959		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST did the fire safety	912864
8230	#####	780532	HOSE P/STEERING HOSE MERCEDE	Creditor #GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #G234743 Receiving #242630 Date :2018-11-20	912864
8230	#####	780532	Steering - Repair power steering oil leak at back of engine	replaced the hose	912864
8230	#####	780532	Steering - Repair power steering oil leak at back of engine	replaced the hose	912864
8230	#####	780380	KIT ENGINE OIL BREATHER KIT MERCEDES 0500LE (EASS00M05)		912864
8230	#####	780380	GASKET OIL SEPARATOR		912864
8230	#####	780380	Mechanic entered - Engine Other Engine breather leak	Ranjith put heli coil fitted back with new filter	912864
8230	#####	780556	Engine - Remove flow hatch steam clean for RSI	completed	912864
8230	#####	780540	Engine - Rekit water separator	Zube did it	912864
8230	#####	780540	Engine - Rekit water separator	rekitted	912864
8230	#####	780540	VALVE DRAIN VALVE CONDENSOR MERCEDES 0500LE		912864
8230	#####	780557	Drv entered - Breakdown Making a Strange Noise	test drive can not find any sound	912864
8230	#####	780537	Body - Replace drivers seat belt	repaired with blade	912864
8230	#####	780537	Body - Replace drivers seat belt		912864
8230	#####	780552	Body - Replace front wheel arch brush	replaced both wheel arch	912864
8230	#####	780535	Body - Bumper bar bolts missing	fitted new one and secured bumper bar	912864
8230	#####	780535	Body - Bumper bar bolts missing	secured	912864
8230	#####	780534	Body - Secure rear door modesty panel	completed	912864
8230	#####	780534	Body - Secure rear door modesty panel	secured	912864
8230	#####	780530	Body - Secure blinds	completed	912864
8230	#####	780552	WHEEL ARCH BRUSH 2.5MTR 12065		912864
8230	#####	780555	Brakes - Replace brake pedal rubber	replaced	912864
8230	#####	780555	Brake Pedal Rubber 0500 Mercedes (A1072910182)		912864
8230	#####	780380	Suspension - Replace NS front airbag	replaced the air bag	912864
8230	#####	780347	AIRBAG FRONT-REAR MERC 0405/0500 REAR/VOLVO B10M/B7R REAR	replaced	912864
8230	#####	780380	Mechanic entered - Engine Other Engine breather leak	removed the breather and try to out the broken bolt	912864
8230	#####	780221	Vandalism - Clean graffiti	Cleaned by fleet support	912150
8230	#####	778767	Service	PRE ANNUAL SAFETY INSPECTION CHECK done.	911390
8230	#####	778767	SINGLE SEAT BACK REST		911390
8230	#####	771009	Breakdown#:35615 - Ops Entered - Breakdown - Breakdown Gear	topped up coolant checked all plugs and went for road test. all good.	911390
8230	11/9/2018	771009	M12 X 1.5 X 30 X 10.9 TORQUE C	Creditor #GB-ECO001 ECONOMY BOLT CO. P/L P/O #G233984 Receiving #241718 Date :2018-11-09	911390
8230	11/8/2018	771009	PROPSHAFT BOLTS DIFF FLANGE	Creditor #GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #G233874 Receiving #241730 Date :2018-11-09	911390
8230	11/8/2018	771009	Breakdown#:35615 - Ops Entered - Breakdown - Breakdown Gear	fit trans and mounts	911390
8230	#####	771009	Breakdown#:35615 - Ops Entered - Breakdown - Breakdown Gear	Went to put new one in but it was wrong one	911390
8230	10/9/2018	771009	SEAL RR MAIN CRANK MERC 0500LE 50A3204		911390
8230	10/9/2018	771009	REAR MAIN SEAL RUNNER SL202		911390
8230	10/9/2018	771009	CRANKSHAFT SEAL REAR		911390
8230	10/9/2018	771009	REAR MAIN SEAL RUNNER SL202		911390
8230	10/9/2018	771009	CRANKSHAFT SEAL REAR		911390
8230	10/8/2018	771009	Breakdown#:35615 - Ops Entered - Breakdown - Breakdown Gear	remove g/box	911390
8230	10/5/2018	765861	VALVE RELAY VALVE RR MERC 05	Creditor #GB-MUL001 MULTISPARES LTD P/O #G229349RET Receiving #238976 Date :2018-10-05 PARTS WARRANTY	911390
8230	10/4/2018	771009	DIRECT PURCHASE - TOWING	Creditor #GB-EAG001 EAGLE TOWING & SALVAGE P/O #G231185 Receiving #238979 Date :2018-10-05 TOW FROM MONASH UNI TO DANDERONG WORKSHOP.	911390
8230	10/4/2018	771009	Breakdown#:35615 - Ops Entered - Breakdown - Breakdown Gear	Arranged tow from Monash Uni.	911298
8230	10/4/2018	770003	Ops Entered - Fault - Gearbox Driveline Rough Gear Change -		911298
8230	10/3/2018	771009	VALVE RELAY VALVE RR MERC 05	Creditor #GB-MUL001 MULTISPARES LTD P/O #G230939 Receiving #238983 Date :2018-10-05	911390
8230	10/2/2018	770003	Gasket sump Ecomat	Creditor #GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #G230625 Receiving #238679 Date :2018-10-02	911298
8230	10/2/2018	770003	SENSOR- INDUCTIVE TURBINE ECOM	Creditor #GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #G230625 Receiving #238679 Date :2018-10-02	911298
8230	10/1/2018	770018		CARRY OUT TRANSMISSION SERVICE AS PER CHECK LIST drain and replace oil filter - top up oil.	911298
8230	10/1/2018	765905	POWER STEERING HOSE	Creditor #GB-HEM001 HEMA'S HOSE SERVICES P/O #G229632 Receiving #238592 Date :2018-10-02	911298
8230	10/1/2018	765999	DIRECT PURCHASE - TOWING	Creditor #GB-EAG001 EAGLE TOWING & SALVAGE P/O #G230809 Receiving #238638 Date :2018-10-02 PICK UP FROM WELLINGTON ROAD TO KNOX	911298
8230	10/1/2018	770003	Ops Entered - Fault - Gearbox Driveline Rough Gear Change -	removed trans sump tested and replaced speed sensor - topped up oil needs roadtest rechecked oil level - mark to road test. all ok.	911298
8230	10/1/2018	770003	FILTER ZF TRANS ECOMAT (1193281-1)(4139 298 038 01)		911298
8230	10/1/2018	770106	CCTV Upgrade Wi-fi not downloading footage.	Completed by Johnny from bwere	911298
8230	10/1/2018	769772	REMOVE AND REPLACE A3 POSTER TO ALL ROUTE VEHICLES	Replaced by Refuellers	911298
8230	9/27/2018	769599	Breakdown#:35602 - Ops Entered - Breakdown - Breakdown Gear	Found no gears reset bus gears started to work. Tried to drive and lost gears again towed bus in	911298
8230	9/21/2018	768372	Consumables		910018
8230	9/21/2018	768372	Elec and Light Repair damaged alternator wirings.	Repaired by Rene.	910018
8230	9/19/2018	767660		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done	909855
8230	9/19/2018	767660		VEHICLE SAFETY INSPECTION Completed.	909855
8230	9/19/2018	765905	BELT MICRO V SERPENTINE BELT 6 RIB 1308mm LONG	Complete flotted new coolant lower hose Re wiring Alternator secured. replace Alternator belt and adjust. Fitted new fan drive shaft and re fit fan drive belt adjust. topped up engine oil coolant and power steering oil. bled power steering Steam clean engine roadtest and check ok no leak.	909855
8230	9/19/2018	765905	Fluid Leaks Replace engine sump gasket.	Fitted new Dip stick pipe fabricate bracket to secured pipe. Fitted new oil low sensor and secured. refit steering pipe secured. Fabricate bracket for heater coolant hose to secured. Refit alternator bracket refit alternator assembly found wire expose need to rewire for safety. c/o.	909855
8230	9/18/2018	765905	Fluid Leaks Replace engine sump gasket.		909855
8230	9/17/2018	765905	UNIT SENDER UNIT OIL LEVEL	Creditor #GB-MUL001 MULTISPARES LTD P/O #G229778 Receiving #237477 Date :2018-09-18	909855
8230	9/17/2018	765905	DIPSTICK TUBE	Creditor #GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #G229588 Receiving #237318 Date :2018-09-17	909855
8230	9/17/2018	765905	Fluid Leaks Replace engine sump gasket.	C/O. Completed sump tensioned all bolts according to specs. Return all wiring brackets secured complete accessories. Remove and replace Alternator mountlob to continue C/o.	909855
8230	9/14/2018	765905	KIT ENGINE OIL BREATHER KIT MERCEDES 0500LE (EASS00M05)		909855
8230	9/14/2018	765905	BUSH ALTERNATOR MTG 12MM X 25MM X 37MM MERC 0500LE		909855
8230	9/14/2018	765905	Fluid Leaks Replace engine sump gasket.		909855
8230	9/14/2018	765905	FAN DRIVE SHAFT MERC 0500LE	Fitted new gasket refit sump assembly job to continue c/o.	909855
8230	9/13/2018	765905	GASKET SUMP 0405NH 447 ENGINE	Creditor #GB-MUL001 MULTISPARES LTD P/O #G229581 Receiving #237206 Date :2018-09-14	909855
				Creditor #GB-MUL001 MULTISPARES LTD P/O #G229521 Receiving #237140 Date :2018-09-13	909855

8230	9/13/2018	765905	HOSE RADIATOR LWR HOSE MERCEDES 0500LE			909855
8230	9/13/2018	765905	Fluid Leaks Replace engine sump gasket.	Remove fan drive shaft bearing worn remove power steering hose leaking oil need replace hose remove alternator assembly and remove sump assembly. Clean parts Job to continue c/o.		909855
8230	9/13/2018	765905	HOSE COOLANT HOSE TAPERED. 60/70 MERCEDES 0500			909855
8230	9/13/2018	765861	VALVE RELAY VALVE RR MERC 05	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G229349 Receiving #:237082 Date :2018-09-13		909855
8230	9/12/2018	765861	Engine oil leak top of engine	Steam washed Engine make sure clean and dry. Roadtested re check for oil leak found sump leaking oil. power steering hose leaking oil and heater coolant hose leaking coolant. Drain coolant drain engine oil and power steering oil. Remove steering pump pipe remove lower coolant pipe and hose. Start to remove sump bc		909855
8230	9/12/2018	765861	KIT O-RING SMALL VOSS (A0309971748)			909855
8230	9/12/2018	765861	KIT O-RING LARGE VOSS (A6739970145)			909855
8230	9/12/2018	765861	Brakes Rear brake relay valve leaks	Check and remove relay valve fitted new relay valve replace all four voss fitting o-ring. Roadtest and check operation ok .		909855
8230	9/12/2018	765888	PERFORM CAMPAIGN 26/18 CHASSIS WASH & UNDER CARRIAGE CHECK	Steam washed and clean done.		909855
8230	9/11/2018	765538	Consumables			909855
8230	9/11/2018	765538	Consumables			909855
8230	9/11/2018	765538	Consumables			909855
8230	9/11/2018	765538	Consumables			909855
8230	9/11/2018	765538	Consumables			909855
8230	9/7/2018	764858	cleaned vandalism as required	CARRY OUT A SERVICE AS PER CHECK LIST		909855
8230	9/7/2018	764858	Vandalism - clean back of seats side wall	Assisting completed		909855
8230	9/1/2018	756020	REPLACE ANTI GRAFFITI FILM	Creditor #:GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G229090 Receiving #:236598 Date :2018-09-07		909855
8230	7/31/2018	756020	Vandalism - Replace anti graffiti film - L2	done by eastcoast		909855
8230	7/31/2018	756173	PERFORM CAMPAIGN 17/18 INTERNAL BUS NUMBERS	Creditor #:GB-GLA010 GLASSPROTECH MELBOURNE P/O #:G225807 Receiving #:236875 Date :2018-09-11 REPLACE L2		909855
8230	7/26/2018	755149	REMOVE OLD POSTER AND REPLACE WITH BUS TIMES ARE CHANGING	REPLACED BY GLASSPROTECH		901815
8230	7/24/2018	754386		Checked by Refuellers and this job has been done		901210
8230	7/23/2018	754211	AIRBAG FRONT+REAR MERC 0405/0500 REAR/VOLVO B10M/B7R REAR	Replaced by refuellers re-tensioned nuts on wheels 3 and 4 with ryan.		900431
8230	7/23/2018	754211	Mechanic entered - Suspension Other O/S/F air bag leaking	Replaced O/S/F air bag		900431
8230	7/23/2018	754211	Mechanic entered - Engine Other Oil leaking from top and but	Steam washed engineroad test and check for leak. Leaking from power steering pipe. Thightened pipe fitting and road test again to check for leak. All Ok		900431
8230	7/20/2018	753718	DECAL GIVE WAY 240x225mm			900431
8230	7/20/2018	753718	DECAL DO NOT OVERTAKE			900431
8230	7/20/2018	753718	FILTER AIR FILTER MERCEDES BENZ			900431
8230	7/20/2018	753718		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		900431
8230	7/20/2018	753718		VEHICLE SAFETY INSPECTION Safety Inspection Completed		900431
8230	7/20/2018	753846	Consumables			900600
8230	7/20/2018	753846	TIRE 295/80R22.5 NEW			900431
8230	7/20/2018	753846	Mechanic entered - Wheels and Tyres Worn Tyres position 3 an	Replaced tyres position 3 and 4 and tensioned all wheel nuts with Hasan		900431
8230	7/20/2018	753849	REFILL WIPER REFILL TO SUIT TX00 / TX90			900431
8230	7/20/2018	753849	Mechanic entered - Body Other Wiper Blade Worn	fit new refills to both wipers. fixed loose blade holder (ns) wiper arm.		900431
8230	7/20/2018	753848	Mechanic entered - Body Other N/S side mirror arm loose	Tightened Side mirror bolt		900431
8230	7/20/2018	753879	Mechanic entered - Body Other Give Way sticker missing	Fit new sticker		900431
8230	7/20/2018	753878	Mechanic entered - Body Other Do Not Overtake Sticker Missin	Fit new sticker		900431
8230	7/17/2018	752971	Consumables			900090
8230	7/17/2018	752971	LAMP STOP/TAIL LED HELLA			900090
8230	7/17/2018	752971	Mechanic entered - Elec and Light Exterior Lights n/s tail l	removed and wired new tail light.		900090
8230	7/17/2018	752970	PERFORM CAMPAIGN 11/18 VENTURA BUS MINDER INSTALLATION	didampaing.		900090
8230	7/7/2018	750941	Mechanic entered - Body Windows Front L/H side windscreen b	put back in place.		988290
8230	7/7/2018	750941	Mechanic entered - Body Windows Front windscreen locking rub	put back in place.		988290
8230	7/6/2018	750638	Consumables			898618
8230	7/6/2018	750638	DOWN LIGHT LED (33041)			898290
8230	7/6/2018	750638	Elec and Light - Centre door step light n/w	replaced faulty light.		898290
8230	6/29/2018	749089	PERFORM CAMPAIGN 16/18 2019 REGISTRATION LABEL REPLACEMENT	Replaced		897106
8230	6/26/2018	748145				896784
8230	6/26/2018	748145	Service	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST		896784
8230	6/15/2018	745777	Mechanic entered - Fluid Leaks Other Need to rectify Engine	Retention all hose clamps steem cleaned Road tested rechecked.no oil leak.		894744
8230	6/13/2018	745177	Consumables			894424
8230	6/13/2018	745177	Consumables			894424
8230	6/13/2018	745177	Consumables			894424
8230	6/13/2018	745177	Consumables			894424
8230	6/13/2018	745177	CONSUMABLES			894315
8230	6/13/2018	745177	FILTER OIL FILTER MERCEDES A0001801709			894315
8230	6/13/2018	745177	FILTER OIL FILTER MERCEDES A0001801709			894315
8230	6/13/2018	745177	KIT ENGINE OIL BREATHER KIT MERCEDES 0500LE (EASS00M05)			894315
8230	6/13/2018	745177		CARRY OUT B SERVICE AS PER CHECK LIST		894315
8230	6/13/2018	745177	Consumables			894424
8230	6/13/2018	745177	Consumables			894424
8230	6/13/2018	745177	Consumables			894424
8230	6/13/2018	745177	Consumables			894424
8230	6/13/2018	745177	Consumables			894315
8230	6/12/2018	744828	PERFORM CAMPAIGN 13/18 VENTURA ROUTE BUS DECAL UPDATE	CARRY OUT A SERVICE AS PER CHECK LIST		894315
8230	6/5/2018	743300	Consumables	completed.		893280
8230	6/5/2018	743300	DOWN LIGHT LED (33041)			893200
8230	6/5/2018	743300	Mechanic entered - Elec and Light Interior Lights drivers li	replaced faulty cab light.		893200
8230	5/21/2018	739875	Drv entered - Brakes Foot_Brakes Leaking Air	check and fixed air leak bus ok.		890620
8230	5/18/2018	739669		Complete with Rene		890620
8230	5/18/2018	739669		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		890620
8230	5/18/2018	739669		VEHICLE SAFETY INSPECTION		890620
8230	5/18/2018	739958	PERFORM CAMPAIGN 15/18 A3 POSTER CHANGE - MYKI AUTO TOP UP	Completed		890620
8230	5/9/2018	737541	Consumables			888930
8230	5/9/2018	737541	Ops Entered - Fault - Warning Lights Batteries - Route: 900	Check battery warning lightcheck ok		888738
8230	5/8/2018	737453	WASHER FUEL PIPE	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G219441 Receiving #:226907 Date :2018-05-09		888885
8230	5/8/2018	737453	COOLANT PIPE COMPRESSOR TO BLO	Creditor #:GB-WHI004 WHITEHORSE TRUCK CENTRE P/O #:G219441 Receiving #:226907 Date :2018-05-09		888885
8230	5/8/2018	737453	Cherck and repair coolant leak	As above		888738
8230	5/8/2018	737453	Fluid Leaks Rear of bus	R/R coolant by pass from air compressor to engine block. Top up coolant and road tested - ok.		888738
8230	5/3/2018	736792	Service	CARRY OUT FIRE EXTINGUISHER TEST & TAG		888333
8230	5/3/2018	736790	PERFORM CAMPAIGN 07/18 RPD DASH MOUNTED OVERRIDE SWITCH INS	Completed by Bwere electrical		888333
8230	5/3/2018	736347		CARRY OUT A/C - A SERVICE AS PER CHECK LIST Replaced return air filter medium		888037
8230	5/1/2018	735887	Consumables			888037
8230	5/1/2018	735887	Mechanic entered - Elec and Light Horn Horn not working	horn working correctly		887374
8230	4/18/2018	733571	PERFORM CAMPAIGN 06/18 REPLACEMENT OF NO ACCESS / PARK BRAK	Been done		885042
8230	4/17/2018	733241	Consumables			885042
8230	4/17/2018	733241	Consumables			885042
8230	4/17/2018	733241	FLURO END POLE TOMBSTONE			884434
8230	4/17/2018	733241	INVERTER 24V 15-36W (KIRG)			884434
8230	4/17/2018	733241	Elec and Light - Saloon fluro light n/w	changed blown fluro tube; replaced blown inverter and melted tube end lamp holder. - saloon light.		884434

8230	4/9/2018	731633	Accident#46689 - Ops Entered - Accident - Bus Hitting Obj	Already been done	882550
8230	4/5/2018	731041		Tensioned front tyres.	882181
8230	4/5/2018	730880	Drv entered - Steering Shakes/ Wobbles	road tested and found wheel woble at 70 kph fitted balanced wheel road tested +pti.	882181
8230	4/5/2018	730880	TYRE 295/80R22.5 NEW		882181
8230	3/29/2018	730088	SILENCER AIR DRYER MERC 0500LE		881515
8230	3/29/2018	730088	AIR DRYER MERCEDES 0500 (49G8505WABCO)		881515
8230	3/29/2018	730088	Mechanic entered - Air System Other Air leak reported didnt	Check air leak found voss fittings leaking rewplace o ring air line pipe leaking retightened and Air dryer faulty change with new Air dryer.	881515
8230	3/29/2018	730089	FILTER DRYER SCANIA / VOLVO (13756997) (49G8704W)		881515
8230	3/29/2018	730089	HALDEX COIL BASE OIL SEPERATOR (49G0031)		881515
8230	3/29/2018	730089	KIT AIR LINE FITTING VOSS 22MM (50Z0114)		881515
8230	3/29/2018	730089	AIR LINE FITTING KIT VOSS 0500LE AIR DRYER SMALL 50Z0115		881515
8230	3/29/2018	730089	KIT PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER		881515
8230	3/29/2018	730089	KIT DRAIN VALVE KIT BOTTOM		881515
8230	3/29/2018	730089	KIT HALDEX CONDENSER KIT TOP (CYCLONE)		881515
8230	3/29/2018	730089	KIT CYCLONE CONDENSER VALVE KIT		881515
8230	3/29/2018	730089			881515
8230	3/29/2018	730089		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST	881515
8230	3/26/2018	729208	Consumables		881210
8230	3/26/2018	729208	Mechanic entered - Wheels and Tyres Flat or Leaking	changed tyre 3 (flat). nuts tensioned with sadid.	880911
8230	3/26/2018	729187	Consumables		881210
8230	3/26/2018	729187	Mechanic entered - Elec and Light Other headlight out	checked working ok.	880911
8230	3/24/2018	729037	Mechanic entered - Steering Other	added power steering fluid - low.	880911
8230	3/24/2018	729038	Mechanic entered - Fluid Leaks Other	added coolant - low.	880911
8230	3/22/2018	728658		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	880730
8230	3/22/2018	728658		VEHICLE SAFETY INSPECTION	880730
8230	3/22/2018	728663	ROCKER COVER 0500LE (50A0023) (1A8502)		880730
8230	3/22/2018	728663	Mechanic entered - Engine Other Number 1 rocker cover cracke	Remove and replace rocker cover and casket.	880730
8230	3/22/2018	728366	Consumables		880911
8230	3/22/2018	728366	INDICATOR LED FRONT TURN LOW FLOOR SQUARE (32983)		880730
8230	3/22/2018	728366	Mechanic entered - Elec and Light Exterior Lights LHS front	replaced faulty (nsf) top indicator light.	880730
8230	3/22/2018	728657	Consumables		880911
8230	3/22/2018	728657	Consumables		880911
8230	3/22/2018	728657	Consumables		880911
8230	3/22/2018	728657	Consumables		880911
8230	3/22/2018	728657		CARRY OUT A SERVICE AS PER CHECK LIST	880730
8230	3/21/2018	728366	Mechanic entered - Elec and Light Exterior Lights LHS front	checked bus lee need to order top lh indicator as no stock	880660
8230	3/14/2018	726549	Air System Air_Leak Rear Air Leak when brakes pedal is pre	check and fixed air leak adjusted park brake air pressure road test bus ok.	878714
8230	3/7/2018	725449	Mechanic entered - Fluid Leaks Rear of bus Coolant leak	Drained coolant, R/R coolant hose. Filled coolant s/yeam cleaned and drive tested. Checked coolant level and leaks OK.	877833
8230	3/2/2018	724019	GASKET ROCKER COVER GASKET MERCEDES 0500LE (50A8515)		877300
8230	3/2/2018	724019		CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST	877300
8230	2/27/2018	722662	Consumables		876741
8230	2/27/2018	722662	GLOBE 24V 70W H1		876184
8230	2/27/2018	722662	Mechanic entered - Elec and Light Exterior Lights	check and replaced os head light globe both conectors	876184
8230	2/27/2018	722944	Please remove any old poster and fit new ones multi choice	Fitted by Refuellers	876184
8230	2/15/2018	719528	Mechanic entered - Fluid Leaks Rear of bus	joined the hose using an elbow fitting, filled coolant; road tested ok	875382
8230	2/13/2018	719528	Mechanic entered - Fluid Leaks Rear of bus	coolant leaking from a rubbed hose above transmission. cut the damaged section and ordered joiner	875382
8230	2/12/2018	718904	Steering wheel vibrates when it goes over 50 km/hHaet como	road testcould not fault either fault.	874339
8230	2/6/2018	717622		Wheel tention carryuot by oakleigh Lindsay and work order 717214	872973
8230	2/4/2018	717214	Consumables		873191
8230	2/4/2018	717214	Mechanic entered - Wheels and Tyres Wheel Nut Retension os	carried out front retorque	872973
8230	2/3/2018	717168	Consumables		873191
8230	2/3/2018	717166	Consumables		873191
8230	2/3/2018	717168	Ops Entered - Fault - Wheels and Tyres Worn - Route: - DIS	all steer tyres already been replaced.	872973
8230	2/3/2018	717166	Mechanic entered - Wheels and Tyres Worn	changed tyres 1 (worn) and 2 (rack). 295's fitted. all steer wheel nuts tensioned with ranjih.	872973
8230	2/3/2018	717166	TYRE 295/80R22.5 NEW		872973
8230	2/2/2018	717128	Consumables		873191
8230	2/2/2018	717114	Consumables		873191
8230	2/2/2018	717128	Wheels and Tyres - front tires worn	bus was transfered back to dandenong depot for tire replacement . as oakleigh does hold the same rim hole size	872973
8230	2/2/2018	717114	Mechanic entered - Wheels and Tyres Worn	BOTH FRONT WHEEL WORN - removed os front and re fitted due to not stocking mercedes alloy wheels. os front has been tienstoend and bus sent to dandenong depot for the front wheels to be replaced	872973
8230	2/2/2018	715510	CLEAN VANDALISM AS REQUIRED	Creditor #GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #G212321 Receiving #220505 Date: 2018-02-08	870261
8230	1/30/2018	716250		Assisting	871995
8230	1/30/2018	716250		Tensioned o/s/r wheels.	871995
8230	1/29/2018	715958	Consumables		871995
8230	1/29/2018	715958	Consumables		871995
8230	1/29/2018	715958	Ops Entered - Fault - Wheels and Tyres Flat or Leaking - Ro	Check all tyres.check Ok	871879
8230	1/29/2018	715807	Suspension - OR drive axle sway bar link noisy & rusty	replaced with Ryan	871879
8230	1/29/2018	715807	SWAY BAR DROP ARM REAR 0500LE		871879
8230	1/29/2018	715807	Suspension - OR drive axle sway bar link noisy & rusty	Removed and fit tyres position 5 and 6 to change O/S/R sway bar link and tensioned all wheel nuts with Alan	871879
8230	1/25/2018	715510	Drv entered - Vandalism Vandalism/ Graffiti Interior	Repaired by ECBT	871879
8230	1/20/2018	714638		VEHICLE SAFETY INSPECTION completed	870261
8230	1/20/2018	714638		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS Done with Ryan	870261
8230	1/20/2018	714638		VEHICLE SAFETY INSPECTION completed	870261
8230	1/16/2018	713723	Perform Campaign 27/17 Positioning of 2018 PTV Fares Decals	Fitted	869267
8230	#####	710668	Consumables		865527
8230	#####	710668	Consumables		865527
8230	#####	710668	Consumables		865527
8230	#####	710668		CARRY OUT A SERVICE AS PER CHECK LIST	865327
8230	#####	707463	REPLACE ANTI GRAFFITI FILM	Creditor #GB-GLA010 GLASSPROTECH MELBOURNE P/O #G209354 Receiving #217239 Date:2017-12-21 REPLACED L1	863668
8230	#####	709305	Vandalism - Replace DOT film on Modesty panel	Replaced	863668
8230	#####	707991	Consumables		862300
8230	#####	707991	Mechanic entered - Elec and Light Exterior Lights N/S headl		861929
8230	#####	707991	GLOBE 24V 70W H1		861929
8230	#####	707991	Drv entered - Elec and Light Exterior Lights	replaced globe.	861929
8230	#####	707463	Vandalism - Replace anti graffiti film - L1	REPLACED BY GLASSPROTECH	861400
8230	#####	707712	MIRROR LEFT HAND BRAZILIAN		861400
8230	#####	707712	Body Left Hand Side Mirror Lens Broken	Removed and replaced broken mirror.	861400
8230	#####	707167	Engine Belts_Loose Noisy Missing	repleaced main belt a/c belt and adjusted s/c compresure road test bus ok.	861400
8230	#####	707167	BELT MICRO V SERPENTINE BELT 6 RIB 1308mm LONG		861400
8230	#####	707167	BELT MICRO V SERPENTINE BELT 9 RIB 2120mm LONG		861400
8230	#####	705718	CLEAN AIR SYSTEM PIPES	Creditor #GB-HMG001 HM GEM ENGINES P/O #G208948 Receiving #216240 Date: 2017-12-11	861400

8230	3/9/2017	649877	Check and repair air won't build up properly	Consulted wiring diagram rectified fault	814380
8230	3/9/2017	649877	Check and repair air won't build up properly	O/Haule air dryer and water separator ordered separator salonoivalverelay Assist Matt to found elektrikal problem	814380
8230	3/8/2017	649877	KIT PURGE VALVE KIT FOR WABCO 49G712W AIR DRYER		814380
8230	3/8/2017	649877	FILTER DRYER SCANIA / VOLVO (1375997) (49G8704W)		814380
8230	3/8/2017	649877	KIT DRAIN VALVE KIT BOTTOM		814380
8230	3/8/2017	649877	KIT HALDEX CONDENSER KIT TOP (CYCLONE)		814380
8230	3/8/2017	649877	KIT CYCLONE CONDENSER VALVE KIT		814380
8230	3/8/2017	649877	Check and repair air won't build up properly	O/Haule air dryer and water separator ordered separator salonoivalverelay C/O job	814380
8230	3/6/2017	649454	Breakdown#33244 - Ops Entered - Breakdown - Breakdown Road	Replace 6 way valve	814283
8230	3/6/2017	649451	KIT AIR LINE FITTING VOSS 22MM (5020114)		814283
8230	3/6/2017	649451	VALVE 4 WAY CIRCUIT PROTECTION VALVE		814283
8230	2/28/2017	605216	CARRY OUT ROLLAWAY SYSTEM	Rcvg #: 194471 (refer Kerrie's email 7/3)	805364
8230	2/24/2017	647540	Consumables		812337
8230	2/24/2017	647540	LED FRONT POSITION MARKER LIGHT		811864
8230	2/24/2017	647540	Elec and Light - Centre door emergency exit light n/w	changed led light	811864
8230	2/17/2017	645733	PERFORM CAMPAIGN 01/17 SMARTRAK DRIVER CONTROL CONSOLE AUDIT	NOT ON CAMPAIGN LIST	810548
8230	2/13/2017	644435	Consumables		809774
8230	2/13/2017	644435	Elec and Light - NSF & centre door exit lights n/w	Replaced	809527
8230	2/13/2017	644435	LED FRONT POSITION MARKER LIGHT		809527
8230	2/6/2017	633175	A/C Heating Not Cooling		808045
8230	2/6/2017	633175	Drv entered - A/C Heating Not Cooling	Replaced all failed fan motors tested ok	808045
8230	2/6/2017	633175	MOTOR EVAPORATOR FAN MOTOR		808045
8230	2/2/2017	633175	Drv entered - A/C Heating Not Cooling		805446
8230	2/2/2017	633175	Drv entered - A/C Heating Not Cooling		805446
8230	2/2/2017	633175	A/C Heating Not Cooling		805446
8230	2/2/2017	633175	Drv entered - A/C Heating Not Cooling		805446
8230	2/2/2017	633175	Drv entered - A/C Heating Not Cooling		805446
8230	2/2/2017	633175	Drv entered - A/C Heating Not Cooling		805446
8230	1/31/2017	633175	AIR CON REFRIDGERANT		806628
8230	1/23/2017	639782		wrong bus	790692
8230	1/23/2017	640400		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	805446
8230	1/23/2017	640400		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	805446
8230	1/23/2017	640400		VEHICLE SAFETY INSPECTION	805446
8230	1/23/2017	633175	EVAPORATOR FAN MOTOR	Creditor #GB-DAN013 DANDENONG RADIATOR SERVICE P/L P/O #:G185251 Receiving #192193 Date :2017-01-23	805446
8230	1/23/2017	633175	Drv entered - Cool & AC Sys	Pressure tested unit found that the discharge pipe had failed repaired section of pipe and tested ok vac and charge unit found evap fans failing near side parts have been ordered secured	790692
8230	1/23/2017	640515	Fluid Leaks - Coolant leaking behind radiator		805446
8230	1/18/2017	639438	Body Windscreen midle rubber comes out	Fitted back	790692
8230	1/17/2017	639368	Mechanic entered - A/C Heating Not Cooling	found a/c n/w clutch not engaging, checked wiring and checked fuses ok.will need test tool to check. ref to w/o 633175	790692
8230	1/17/2017	638691	Consumables		804588
8230	1/17/2017	638691	Elec and Light - Wont start intermittently	assited beuford with his zf checks. began cable tying wiring in bus to secure for roadtest. found wiring being interfered with by electrical hatch closing. secured away from problem area. roastested bus ok. secured steering cover. p.t.i'd fuelled and parked bus.	790692
8230	1/16/2017	638691	SWITCH DOOR BRAKE 0500LE (NBS)		790692
8230	1/13/2017	638691	Elec and Light - Wont start intermittently	assisted beuford. found faulty brake switch that had been shorting out. removed and ordered carry over.	790692
8230	1/12/2017	638476	Breakdown#33132 - Ops Entered - Breakdown - Breakdown Road		790692
8230	1/12/2017	638691	Elec and Light - Wont start intermittently	NBS tracing for fault in DNR circuit c/o	790692
8230	1/12/2017	638476	Breakdown Road Defect Affects ServiceBUS BROKE DOWN ON	Wont start - tried to jump start checked main fuses and fuel couldn't start called and waited for tow truck	790692
8230	1/11/2017	638476	DIRECT PURCHASE - TOWING	Creditor #GB-EAG001 EAGLE TOWING & SALVAGE P/O #:G185201 Receiving #192123 Date :2017-01-23 PICK UP FROM CNR PRINCES HWY & WARRIGUL RD AND RETURN TO DEPOT	805364
8230	1/9/2017	637670	Consumables		804179
8230	1/9/2017	637167	Consumables		804179
8230	1/9/2017	637670	Drv entered - Desto Signs	working ok	790692
8230	1/9/2017	637670	Ops Entered - Fault - Desto Signs - Route: 900 - Monash Uni	fit spare controller	790692
8230	1/9/2017	637670	Ops Entered - Fault - Desto Signs - Route: 900 - Stud Park	replaced desto controller due buttons n/w. fit spare controller working ok.	790692
8230	1/9/2017	637167	Check bus won't start intermittent	completed checking wiring. rerouted wiring to avoid potential trouble spots. repositioned ZF ecu to stop rubbing of loom against support pole. replaced star point/clutch plug. roastested ok. pti and fuelling complete.	790692
8230	1/6/2017	637167	Check bus won't start intermittent	fit new star point. began cable tying up loom. carry over.	804160
8230	1/6/2017	637167	CLUTCH STAR POINT	Creditor #GB-WHI004 WHITEHORSE TRUCKS PTY LTD P/O #:G184747 Receiving #190942 Date :2017-01-06	804160
8230	1/4/2017	636872	Fit New 2107 Large and Small Fares Small Concessionand AO	REPLACED	804160
8230	1/1/2017	605216	Consumables		804160
8230	1/1/2017	605216	CARRY OUT ROLLAWAY SYSTEM	Creditor #GB-BWE001 BWERE ELECTRICS P/O #:G178986 Receiving #192126 Date :2017-01-23	805364
8230	#####	634824	Drv entered - Suspension Knee/ Raise	checked fuses and relay all ok. Found the suspension key in wrong position.	803601
8230	#####	634722		Assisting Tensioned with Shalen.	803601
8230	#####	634722		Tensioned pos 3 & 4 w / nuts with Rene	803601
8230	#####	634283	TYRE 11R22.5N NEW		803601
8230	#####	634283	Mechanic entered - Wheels and Tyres Worn pos34	changed pos 3and 4 tyres and tensioned wheel nut with Mark	803601
8230	#####	634283	Consumables		803915
8230	#####	633533	Mechanic entered - Body Other fire extinguisher expired.	replaced.	790692
8230	#####	633533	Consumables		803378
8230	#####	633175	Consumables		802779
8230	#####	633175	ZF TRANSMISSION SELECTOR	Creditor #GB-EAS002 EASTCOAST TRUCK & BUS SERVICE P/O #:G183558 Receiving #189705 Date :2016-12-14	802779
8230	#####	633139	Warning Lights Enginenot starting	attended yard. batteries o.k. bus finally started. could not move - no transmission. bus towed to workshop for repairs. neven in attendance.	790692
8230	#####	633175	Bus won't start checked gear selector and replace as require	Replaced gear selector with ranjith spare.Went long roady and ok.Order new selector.	790692
8230	#####	633175	Drv entered - Elec and Light Exterior Lights	fitted the fluoro as was not ok now ok.	790692
8230	#####	633176	LABEL PARK BRAKE 8x25mm WHITE/BLACK		790692
8230	#####	633176	SWF SWITCH LABEL SALOON LIGHT WHITE ON GREEN 14x14mm		790692
8230	#####	633176	LABEL HAZARDS 8x25mm WHITE/BLACK		790692
8230	#####	633176	PERFORM CAMPAIGN 17/16 DASH SWITCH LABELLING	Fitted the dash stuff	790692
8230	#####	633176	SWF SWITCH LABEL DRIVERS FAN WHITE ON GREEN 14x14mm		790692
8230	#####	633176	LABEL RADIO 8x25mm WHITE/BLACK		790692
8230	#####	633176	LABEL DURESS BUTTION 8x25mm RED/BLACK		790692
8230	#####	633176	LABEL KNEEL 8x25mm WHITE/BLACK		790692
8230	#####	633176	LABEL LOWER/RAISE 8x25mm WHITE/BLACK		790692
8230	#####	633176	SWF SWITCH LABEL STEP LIGHT WHITE ON GREEN 14x14mm		790692
8230	#####	633176	SWF SWITCH LABEL DEMIST WHITE ON GREEN 14x14mm		790692
8230	#####	633176	LABEL HEADLIGHTS 8x25mm WHITE/BLACK		790692
8230	#####	632981	AXLE SHAFT SCREW	Creditor #GB-WHI004 WHITEHORSE TRUCKS PTY LTD P/O #:G183457 Receiving #189645 Date :2016-12-13	802779
8230	#####	632981	Consumables		802779
8230	#####	632981	Consumables		802779
8230	#####	632981	Consumables		802779
8230	#####	632981	Consumables		802779
8230	#####	632981	Consumables		802625
8230	#####	632981	Consumables		802625
8230	#####	632981	Consumables	CARRY OUT B SERVICE AS PER CHECK LIST	802779
8230	#####	632981	Consumables		802779

8230	#####	632981	Consumables			802779
8230	#####	632981	Consumables			802779
8230	#####	632981		CARRY OUT A SERVICE AS PER CHECK LIST		802625
8230	12/8/2016	631153	DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 Road Safety Inspections P/O #:G182796 Receiving #:189363 Date :2016-12-08		802131
8230	12/8/2016	632153	Consumables			802131
8230	12/8/2016	632153	Check and repair bus won't start	continued checking wiring from selector button. roadtested bus to check. seems to be working ok. parked on fuel bay.		801990
8230	12/7/2016	632153	Check and repair bus won't start	found dmr fuse blowing. got vehicle started to move to workshop. checked wiring leading to dnr switch and to electrical panel. need to dig deeper as fault has rectified itself. carry over.		801990
8230	12/6/2016	631830	DIRECT PURCHASE - TOWING	Creditor #:GB-EGG01 EAGLE TOWING & SALVAGE P/O #:G183062 Receiving #:189779 Date :2016-12-15 FROM JOHN MONASH DRIVE TO DEPOT		802779
8230	12/6/2016	631820	Breakdown#33038 - Ops Entered - Breakdown - Breakdown Road	attend break downstarter fault.tow truck called.		801990
8230	12/5/2016	631538	Drv entered - Ticket Equip	control room		801687
8230	12/5/2016	631628	Drv entered - Steering Excessive Play	checked ok.		801687
8230	12/5/2016	631628	Steering (None) / There is no power steering	checked steering linkagesoil road tested ok.		801687
8230	12/5/2016	631648	Consumables			801990
8230	12/5/2016	631648	Drv entered - Desto Signs	desto works as it should. all ok.		801687
8230	12/5/2016	631509		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST fire safety inspection complete		801687
8230	12/2/2016	631153		ANNUAL SAFETY INSPECTION - RWC008064 - PASSED - 02/12/16		790692
8230	12/2/2016	631244	Consumables			801687
8230	12/2/2016	631244	SPRING RECLINE D/SEAT			790692
8230	12/2/2016	631244	Replace driver seat and fit decal as require	jobs completed		790692
8230	12/1/2016	631018	Consumables			801306
8230	12/1/2016	631018	Mechanic entered - Elec and Light Indicators Not Working	changed blown globe (osf) side indicator.		790692
8230	12/1/2016	631018	GLOBE 24V 21W SINGLE CONTACT (HLR2421)			790692
8230	12/1/2016	623896	Consumables			801306
8230	12/1/2016	623896	SINGLE SEAT BASE			803915
8230	#####	630392	Ops Entered - Fault - Body Front_Door Operation Faulty - Ro	Creditor #:GB-AUT05 AUTOMOTIVE SUNROOF AND TRIMMING SERVICES P/O #:G180029 Receiving #:190264 Date :2016-12-22		790692
8230	#####	630085		repair bumper door switch.		800651
8230	#####	629544	KIT AIR LINE FITTING VOSS 22MM (50Z0114)	re-tensioned all drive wheel nuts. with dulkith.		800651
8230	#####	629544	ECAS LEVELLING VALVE CONTROL 5			800651
8230	#####	629544	Engine - Steamclean engine for RSI	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G182165 Receiving #:188331 Date :2016-11-24		800651
8230	#####	629544	PLASTIC WASHER	cleaned.		800651
8230	#####	629544	BOLT BUMPER BAR BOLT SPECIAL			800651
8230	#####	629544	KIT AIR LINE FITTING VOSS 22MM (50Z0114)			800651
8230	#####	629544	Air System - Repair air leak next air dryer	replaced suspnsion slenid and reseal air lines.		800651
8230	#####	629544	KIT AIR LINE FITTING VOSS 22MM (50Z0114)			800651
8230	#####	629544	Body - OS front corner scratched	fixed.		800651
8230	#####	629544	Body - Adjust rear door sensitive edge	adjusted.		800651
8230	#####	629544	Body - Secure rear door rubber	fixed.		800651
8230	#####	629544	Body - Secure lower skirts panels	retight screws.		800651
8230	#####	628524	SET DISC PAD SET SCANIA / MERCEDES 0500			800651
8230	#####	629356	Suspension - O/S/R sway bar link worn	check ok		800651
8230	#####	628524	Brakes - Replace rear brake disc	replaced r/ brake rotos and b/pads. adjust wheel bearing fit wheel and torque with with phil.		800651
8230	#####	628524	REAR HUB NUT LOCK WASHER			800651
8230	#####	628524	FRONT+REAR DISC ROTOR MERCEDES BENZ 0500			800651
8230	#####	628524	REAR HUB NUT LOCK WASHER			800651
8230	#####	628524	Brakes - Replace rear brake disc	replaced rotos c/o		800651
8230	#####	628703	Consumables			800651
8230	#####	628703	Elec and Light - Engine hatch micro switch u/s	checked working ok.		800651
8230	#####	628524	Brakes - Replace rear brake disc.	start replace rear brake disc.		800651
8230	#####	628206		PRE ANNUAL SAFETY INSPECTION CHECK done.		800325
8230	#####	627952	oil leak from top of the radiator	check top of radeator fixed coolant leak clean bus ok.		800325
8230	#####	626944	Consumables			799388
8230	#####	626944	GLOBE 24V 5W WEDGE INSTRUMENT PANEL (17197)			799088
8230	#####	626944	Elec and Light Flat Batteries	fixed battery wire adjusted alt belt bus ok.		799088
8230	#####	626944	Elec and Light Exterior Lights: right hand headlight very	changed as park light globe and adjusted both head lights		799088
8230	#####	623896	CENTRA CUSHION CLIP RH			795732
8230	#####	623896	CENTRA CUSHION CLIP LH			795732
8230	#####	623896	SINGLE SEAT BASE			795732
8230	#####	623896	CENTRA CUSHION CLIP LH			795732
8230	#####	623898	PAD BRAKE & CLUTCH PEDAL PAD MERCEDES 0500LE			795732
8230	#####	623850				795654
8230	#####	623850		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS		795654
8230	#####	623850		VEHICLE SAFETY INSPECTION		795654
8230	#####	623894	CCTV - Monitor needs securing	Secured monitor		795654
8230	#####	623896	Body - Replace seat cushions	Assisting		795654
8230	#####	623896	Body - Replace seat cushions	R/R seat cushions		795654
8230	#####	623895	Body - N/S modest panel missing screw	Fitted screws		795654
8230	#####	623893	Body - seats loose	Tightened seats		795654
8230	#####	623898	Brakes - Pedal rubber u/s	R/R pedal rubber		795654
8230	#####	623892	SWITCH LOW AIR 0500LE			795654
8230	#####	623892	Air System Air Leak Rear	Locate parts and replaced air switch - ok.		795654
8230	#####	623372	Consumables			795654
8230	#####	623372	Ops Entered - Fault - Elec and Light Exterior Lights - Rout	Replaced OS h/light assembly		790692
8230	#####	623372	HEAD LAMP INSERT HELLA 100MM L/FLOOR 0500 29204			790692
8230	#####	623786	Fit A3 poster to holder either Explore Melbourne or PTV Ap	Fleet Support Replaced		795654
8230	#####	623340	Service	re-tensioned nuts on wheels 3 and 4 with Mark		790692
8230	#####	623340		re-tensioned nuts on wheels 3 and 4 with ranjith.		790692
8230	#####	623201	Consumables			795114
8230	#####	623201	Wheels and Tyres - Tyre 3 worn	changed tyre 3 (worn). nuts tensioned with ranjith.		790692
8230	#####	622996	Consumables			795114
8230	#####	622996	Mechanic entered - Dash Dash_Lights Not Working	changed blown globe gauge light.		794991
8230	#####	622999	HINGE DRIVERS COMPARTMENT 12205 49080			794991
8230	#####	622999	Mechanic entered - Body Other	replaced both broken cab door hinges. replaced broken cab door paddle latch.		794991
8230	#####	622999	PADDLE LATCH DRIVER COMPARTMENT DOOR			794991
8230	#####	622762	Drv entered - Ticket Equip	control room		794345
8230	#####	619661	MUFFLER			792260
8230	#####	620816	Consumables			792260
8230	#####	620788	Consumables			792260
8230	#####	620816	Ops Entered - Fault - Desto Signs - Route: 900 - Chadstone	check ok.		791242
8230	#####	620788	Ops Entered - Fault - Desto Signs - Route: 900 - Stud Park	reset desto unit bus serviceable.		791242
8230	10/7/2016	620453	CENTRA CUSHION CLIP RH			791242
8230	10/7/2016	620453	SINGLE SEAT BASE			791242

8230	10/7/2016	620453	Body - 2 pax seats damaged	replaced damaged seat base cushions and broken cushion clip.	791242
8230	10/6/2016	620283	Mechanic entered - Fluid Leaks Other low coolant.	added coolant.	791242
8230	10/5/2016	620037	Drv entered - Ticket Equip	CONTROL ROOM	791025
8230	10/3/2016	619661	MUFFLER	Creditor #:GB-WHI004 WHITEHORSE TRUCKS PTY LTD P/O #:G173898 Receiving #:184582 Date :2016-10-03	791025
8230	9/27/2016	618398	Consumables		788520
8230	9/27/2016	618398	Ops Entered - Fault - Elec and Light Exterior Lights - Rou	Checked all lights OK	788520
8230	9/27/2016	618398	Consumables		788520
8230	9/27/2016	618398	Body Drivers Seat Belt - BUCKLE SIDE THE CABLE HOLDING IS	Checked has been replaced	788520
8230	9/26/2016	613245	Vandalism - Replace 7 windows- last 3 on N/S and O/S and Re		788520
8230	9/26/2016	613245	Vandalism - Replace 7 windows-	Creditor #:GB-A1W001 A-1 Windscreens P/O #:G176063 Receiving #:183995 Date :2016-09-26	783974
8230	9/22/2016	617485	Drv entered - Ticket Equip	control room	788520
8230	9/14/2016	615789	Consumables		788083
8230	9/14/2016	615789	Consumables		786321
8230	9/14/2016	615789	Consumables		786321
8230	9/14/2016	615789	Consumables		786321
8230	9/14/2016	615789	Consumables		786321
8230	9/14/2016	615789	Consumables		785879
8230	9/14/2016	615789	Consumables		785879
8230	9/7/2016	613522	Supply and apply Smartbus deca	completed	784181
8230	9/5/2016	613522	BODY SHOP SUPPLIES	CARRY OUT A SERVICE AS PER CHECK LIST	777564
8230	9/5/2016	613522	Accident damage - N/S/R - Acc # DAN 43488.	Creditor #:GB-LAB010 LABEL CONCEPTS P/O #:G176272 Receiving #:182689 Date :2016-09-08	777564
8230	9/5/2016	613522	PAINT SUPPLIES	remove n/s decals refit reflector refit n/s/r clearance light	777564
8230	9/5/2016	613522	DECAL VENTURA SIDE FOR ROUTEBUS		777564
8230	9/5/2016	613522	DECAL VENTURA YELLOW ON BLUE 480mm		777564
8230	9/5/2016	613522	DECAL # 5 25mm BLACK		777564
8230	9/5/2016	613522	DECAL # 7 25mm BLACK		777564
8230	9/2/2016	613522	Accident damage - N/S/R - Acc # DAN 43488.	prep work to n/s/r maskup and painted	777564
8230	9/1/2016	607037	Engine Hole in the muffler	rebooked	777564
8230	9/1/2016	611243	CARRY OUT CCTV CHECK OVER	Creditor #:GB-BWE001 BWERE ELECTRICS P/O #:G175285 Receiving #:183651 Date :2016-09-21	787789
8230	8/30/2016	612898	CCTV No audio available on footage	changed audio settings to record audio	783735
8230	8/26/2016	612112		completed with Dulkit pos1/2	782620
8230	8/25/2016	611802	Consumables		783244
8230	8/25/2016	611802	TYRE 11R22.5N NEW		782620
8230	8/24/2016	611684		VEHICLE SAFETY INSPECTION Safety Inspection Completed	782620
8230	8/24/2016	611684		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	782620
8230	8/24/2016	611684		VEHICLE SAFETY INSPECTION Safety Inspection Completed	782620
8230	8/24/2016	611802	Mechanic entered - Wheels and Tyres Worn	Replaced tyres position 1 and 2 and tension wheel nuts	782620
8230	8/24/2016	611802	Mechanic entered - Wheels and Tyres Worn	Replaced tyres position 1 and 2 with Alex and tension wheel nuts	782620
8230	8/22/2016	611243	Check CCTV system function as require	completed by bwere electrical johny	777564
8230	8/16/2016	610141	Consumables		781218
8230	8/16/2016	610136	Consumables		781218
8230	8/16/2016	610141	RADIO AM/FM 12-24VOLT (AV8141)		781155
8230	8/16/2016	610141	Drv entered - Elec and Light AM-FM Radio	fitted	781155
8230	8/16/2016	610141	Drv entered - Elec and Light AM-FM Radio	fitted new radio with elias	781155
8230	8/16/2016	610136	fit diode to rollaway system	Fitted Diode	781155
8230	8/10/2016	607037	Engine Low Power: LOW POWER...WHEN TAKING OFF	check engine bus ok.	779104
8230	8/10/2016	609162	Consumables		779104
8230	8/10/2016	609162	Body - REMOVE TILL TRAY	done.	779104
8230	8/9/2016	607037	Consumables		779104
8230	8/9/2016	607037	DOOR VALVE SILENCER		779104
8230	8/9/2016	607037	Body Rear_Door Operation Faulty: not closing	adjusted rear door and abs switch.	779104
8230	8/2/2016	607037	MOUNT RUBBER EXHAUST VOLVO (6850149-3)(6850149)		777564
8230	8/2/2016	607037	POWER STEERING PUMP O RING 0500LE		777564
8230	8/2/2016	607037	GASKET COMPRESSOR 0500LE (A4571304815)		777564
8230	8/2/2016	607037	Engine - Oil leak at top of engine	Fitted new gasket for air compressor and replaced p/s seal.Road tested ok.	777564
8230	8/2/2016	607037	Engine Turbo fins damaged and leaking oil.	Fitted new turbo and old muffler back to the bus.Road tested - ok.	777564
8230	7/30/2016	607164	CLEANER GRAFFITI REMOVER AMERASE PER LITRE		777564
8230	7/30/2016	607164	HARDENER DELFLEET GRAFFITI RESISTANT PER LITRE		777564
8230	7/30/2016	607164	ANTI GRAFFITI PAINT LIGHT GREY		777564
8230	7/30/2016	607164	ANTI GRAFFITI PAINT DARK GREY		777564
8230	7/30/2016	607164	graffiti interior	painted the bus	777564
8230	7/30/2016	607164	Vandalism Vandalism/ Graffiti Interior / Fleet Support att		777564
8230	7/30/2016	607164	Vandalism Vandalism/ Graffiti Interior		777564
8230	7/29/2016	607037	Engine - Oil leak at top of engine	Washed the engine and road tested. Found oil leaks in the bottom of the air compressor. Drained coolant in the system and removed air compressor and order the parts. C/F	777564
8230	7/29/2016	607037	Engine Turbo fins damaged and leaking oil.	Removed exhaust and muffler. Removed turbo and order the parts. C/F	777564
8230	7/29/2016	607061	Consumables		777564
8230	7/29/2016	607061	Elec and Light Park brake light n/w.	Wrong bus entered	777564
8230	7/21/2016	605216	Consumables		777564
8230	7/21/2016	605216	PERFORM CAMPAIGN 08/16 BUS ROLLAWAY PREVENTION DEVICE (RPD)		777564
8230	7/21/2016	605216	Fit roller way system	fitted roll away system checked and ok	777564
8230	7/20/2016	605079			777444
8230	7/20/2016	605079	GASKET ROCKER COVER GASKET MERCEDES 0500LE (50A8515)	CARRY OUT TUNE-UP SERVICE AS PER CHECK LIST	777444
8230	7/13/2016	603789			777444
8230	7/13/2016	603789	Service	CARRY OUT DIFFERENTIAL SERVICE AS PER CHECK LIST	775820
8230	7/12/2016	603661	PLEASE REMOVE ANY OLD POSTERS & FIT NEW A3 POSTER	Fleet Support	775820
8230	7/9/2016	602912	LAMP LED SIDE LAMP RED/AMBER PERE1 (52-98002)		772620
8230	7/9/2016	602912	fit new nsr side clearance light	fit new led light assembly	772620
8230	7/1/2016	601270			772612
8230	7/1/2016	601270		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	772612
8230	7/1/2016	601270		VEHICLE SAFETY INSPECTION	772612
8230	7/1/2016	601284	Steering Excessive Play - O/S tie rod -end.	Replaced R/H side tie rod balljoint	777564
8230	7/1/2016	607037	TURBO 0500LE	Creditor #:GB-MUL001 MULTISPARES LTD P/O #:G173653 Receiving #:179722 Date :2016-08-02	777564
8230	6/24/2016	599986	Drv entered - Ticket Equip	control room	771501
8230	6/21/2016	599241	KIT DRAIN VALVE KIT BOTTOM		770812
8230	6/21/2016	599241	KIT HALDEX COIL KIT MERCEDES 0500LE (49G0027)		770812
8230	6/21/2016	599241	FILTER AIR FILTER CHECK VALVE 22mm CYCLONE		770812
8230	6/21/2016	599241	KIT CYCLONE CONDENSER VALVE KIT		770812
8230	6/21/2016	599241	KIT HALDEX CONDENSER KIT TOP (CYCLONE)		770812
8230	6/21/2016	599241	HALDEX COIL BASE OIL SEPARATOR (49G0031)		770812
8230	6/21/2016	599241	FILTER DRYER SCANIA / VOLVO (1375997) (49G8704W)		770812
8230	6/21/2016	599241	changed check valve as blocked with dirt	Complete	770812

8230	3/3/2016	579446	Wheels and Tyres - Tyres 56 worn	changed tyres 5 and 6 (worn). nuts tensioned with dulkith.	749650
8230	2/29/2016	577581	Consumables		749280
8230	2/29/2016	577581	GLOBE 24V 21W SINGLE CONTACT HLR2421		748963
8230	2/29/2016	577581	HANDWHEEL KIT FRONT CONTROL		748963
8230	2/25/2016	578109	Steering - Steering wheel very stiff	check steering road test bus serviceble.	748310
8230	2/25/2016	577581	Body Drivers Seat Controls - Please check Functionality	moved driver seat from bus and replaced damage parts with new parts refitted to bus job completed	747514
8230	2/24/2016	577581	GLOBE WEDGE INSTRUMENT 24V 5W 17197		747514
8230	2/24/2016	577581	Mechanic entered - Elec and Light Exterior Lights	changed blown globe (osf) bottom park light.	747514
8230	2/23/2016	577581	LAMP INTERIOR AND REVERSING		747514
8230	2/23/2016	577581	Elec and Light - Reverse light lens missing	removed broken reverse light fitted new unit and globe checked and ok.	747514
8230	2/23/2016	577581	OUTER LEVER ISRI SEAT A6008	Creditor #:GB-ISR002 ISRI SEATS SUNSHINE P/O #G162850 Receiving #1.68689 Date :2016-02-24	748310
8230	2/18/2016	576596	Brakes Park_Brake Not Holding	checked brake padsok checked for air leaksokdoor brake okpark brakeok.	745965
8230	2/15/2016	575879	Consumables		745234
8230	2/15/2016	575879	Elec and Light center door step light n/w	fixed electrical 'no supply' fault.	744589
8230	2/11/2016	575416	The Campaign requires all Bus destinations systems to be in	MOBITEC - MOBITEC ICU400 - 16 X 140 - N/A - N/A	743854
8230	2/10/2016	574943		Wrongly back book	743854
8230	2/2/2016	573709			740983
8230	2/2/2016	573709		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	740983
8230	2/2/2016	573709		VEHICLE SAFETY INSPECTION	740983
8230	2/2/2016	573548	Body DAMAGE OR BROKEN REAR EXIT DOOR OVERHEAD CONSOLE.	Repair interior panels above rear door	740983
8230	2/2/2016	573548	FIRTREE CLIP SIDE PILLAR		740983
8230	2/2/2016	573697	25mm BLACK NO 6		740983
8230	2/2/2016	573697	25mm BLACK NO 7		740983
8230	2/2/2016	573697	Body decal		740983
8230	2/2/2016	572030	AMBER REFLECTOR		740983
8230	2/2/2016	572030	2MM X 1200MM X 2400MM FLAT ALUMINIUM		740983
8230	2/2/2016	572030	BODY SHOP SUPPLIES		740983
8230	2/2/2016	572030	PAINT SUPPLIES		740983
8230	2/1/2016	573548	Body DAMAGE OR BROKEN REAR EXIT DOOR OVERHEAD CONSOLE.	Started repairs	740983
8230	2/1/2016	573548	Body DAMAGE OR BROKEN REAR EXIT DOOR OVERHEAD CONSOLE.	Started repairs	740983
8230	2/1/2016	572030	Accident damage - O/S/M - Acc # DAN 42216. *INTERNAL* *To b	Prepared and painted repairs	740983
8230	2/1/2016	572030	Accident damage - O/S/M - Acc # DAN 42216. *INTERNAL* *To b	Repairs	740983
8230	1/30/2016	573234		retensioned	740983
8230	1/29/2016	573104	Mechanic entered - Wheels and Tyres Worn	changed tyres 3 and 5 (worn). put tyre 4 to position 5. used run out tyres on positions 3 and 4. fitted new valve ext's. all drive nuts tensioned with allan.	740983
8230	1/29/2016	573104	EXTENSION FLEXIBLE TYRE VALVE 180mm LONG		742619
8230	1/29/2016	573104	Consumables		739998
8230	1/19/2016	570961	DECAL PTV METRO MYKI DECAL LARGE 450x330mm		739998
8230	1/19/2016	570961	Campaign 23_15 A3 Poster Change		739381
8230	1/15/2016	570317	Body Drivers Seat Controls	fixed driver seat broken wight adjuster change roller pins.	738004
8230	1/7/2016	568804	Elec and Light AM-FM Radio / SALOON STEREO MID N/W	inspected stereo found out that audio was just playing on the drivers speaker. nowhere else. drivers speaker is fitted behind driver and creates a subwoofer tone. which makes it sound louder. no fault.	738179
8230	1/7/2016	568804	Consumables		738004
8230	1/7/2016	568692	CCTV (None) Audio Recordings Not Working	assisted pascal with checking hdd and camera unit.	738004
8230	1/7/2016	568692	CCTV (None) Audio Recordings Not Working	tested camera fitted to bus and found out that no audio was recording. tested system. changed camera to a new thoreb one by passed old wires and connected new camera to unit. working fine.	738004
8230	1/7/2016	568692	THOREB INT CAMERA		737195
8230	1/6/2016	568371	Mechanic entered - Wipers and Washers Washers Not Working	adjust wiper washers towards screen.	737195
8230	1/6/2016	568646	Wheels and Tyres / Tyres 3 & 5 need replacing (worn)	checked ok	738004
8230	1/6/2016	568646	Consumables		738004
8230	1/6/2016	568527	Consumables		737195
8230	1/6/2016	568646	Elec and Light Park light N/S bottom U/S	checked ok	737195
8230	1/6/2016	568527	24V INVERTER 20W (ACX7096)		737195
8230	1/6/2016	568527	FLURO TUBE 24V 18W 24'		737195
8230	1/6/2016	568527	Mechanic entered - Elec and Light Interior Lights	replaced blown inverter and fluro tube - saloon light (osr).	738004
8230	1/6/2016	568646	Consumables		738004
8230	1/6/2016	568540	Consumables		738004
8230	1/6/2016	568540	Consumables		738004
8230	1/6/2016	568540	Consumables		738004
8230	1/6/2016	568540	Consumables		737195
8230	1/6/2016	568540	Consumables		737195
8230	1/5/2016	568165	BUMPER BOLT SPECIAL		737195
8230	1/5/2016	568165	Mechanic entered - Body Other	replaced missing bumper bar bolt (osr) and tightened all loose rear bumper bar bolts.	735076
8230	#####	567230	Consumables		735076
8230	#####	567230	GLOBE H1 24V 70W HLC2470		733003
8230	#####	567230	Elec and Light - LH side low beam out	REPLACED	733003
8230	#####	566047			733003
8230	#####	566047		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	733003
8230	#####	566047		VEHICLE SAFETY INSPECTION	733003
8230	#####	566040	PERFORM CAMPAIGN 22/15 POSITIONING OF 2016 PTV FARES DECALS	Applied supplied decal	732056
8230	#####	565822	A/C Heating - Requires extra support bracket on discharge p	Secured	725309
8230	#####	558378	AIR CON REFRIGERANT		730004
8230	#####	558378	AIR CONDITIONING REPAIR	Creditor #:GB-23C001 22 CELSIUS P/O #G159655 Receiving #165966 Date :2016-01-07 REPLACE COMPRESSOR	725309
8230	#####	558378	A/C Heating A/C COMPRESSOR BAD OIL LEAK	IN - F072ZC0118 OUT B032ZC0001	725309
8230	#####	558378	A/C Heating A/C COMPRESSOR BAD OIL LEAK	Repaired cracked pipe	725309
8230	#####	558378	Ops Entered - Fault - A/C Heating Not Cooling - Route: 900	Requires extra support bracket on discharge pipe above rear engine door	725309
8230	#####	558378	Need replace A/C compressor	Replaced compressor	725309
8230	#####	564876	Mechanic entered - Fluid Leaks Other	added coolant - low.	731842
8230	#####	564875	Consumables		725309
8230	#####	564875	GLOBE H1 24V 70W HLC2470		725309
8230	#####	564875	GLOBE WEDGE INSTRUMENT 24V 5W 17197		725309
8230	#####	564875	Elec and Light Exterior Lights: LHS headlight#####PLEASE DI	changed blown globes (os) low beam headlight and (osf) bottom park light.	730604
8230	12/8/2015	563745	Body / RIGHT SIDE BODY SCRATCHED.	Alreadt reported	730918
8230	12/7/2015	562326	DIRECT PURCHASE - BUS INSPECTI	Creditor #:GB-ROA001 Road Safety Inspections P/O #G158847 Receiving #164976 Date :2015-12-10	730070
8230	12/4/2015	563017	SILENCEER AIR DRYER		730070
8230	12/4/2015	563017	CHECK VALVE 22MM CYCLONE AIR FILTER		730070
8230	12/4/2015	563017	CYCLONE CONDENSER VALVE KIT		730070
8230	12/4/2015	563017	DRAIN VALVE KIT BOTTOM		730070
8230	12/4/2015	563017	HALDEX CONDENSER KIT TOP(CYCLONE)		730070
8230	12/3/2015	562326		ANNUAL SAFETY INSPECTION - RWC 046240 - PASSED - 04/12/15	725309
8230	12/3/2015	563017		Completed with phil. change check valve blocked replace 9 o rings air lines around air dryer. test check for leaks all ok.	725309
8230	12/3/2015	563017		CARRY OUT AIR SYSTEM SERVICE AS PER CHECK LIST	729668
8230	#####	561645	Consumables		729668

8230	#####	561645	Mechanic entered - Wheels and Tyres Flat or Leaking	replaced front tyre with matching used one as old one was going flat.	728995
8230	#####	561522	DECAL MAKE YOUR MARK		728995
8230	#####	561522	Camapign 20/15 Audit & Update of Safety Decals.Requires a		728995
8230	#####	559933	Ops Entered - Fault - Passenger Doors - Route: 900 - Chadst	check ok.	726100
8230	#####	560164	Remove Old Poster and Fit new All Night Public Transport Po	completed	726100
8230	#####	559643	Body Front_Door Operation Faulty	change switch adjust door ramp. doors ok.	726100
8230	#####	559643	CONTACT BLOCK DOOR PUSH SWITCH		726100
8230	#####	558703	Consumables		725432
8230	#####	558703	Mechanic entered - Elec and Light Other repair starter wirin	repaired starter wiring	725432
8230	#####	558703		CARRY OUT FIRE SAFETY INSPECTION AS PER CHECK LIST did the fire saftey inspection.	725432
8230	#####	558337		Pre Annual Inspection Completed with Sisl	725309
8230	#####	558337		PRE ANNUAL SAFETY INSPECTION CHECK	725309
8230	#####	558394	WIPER REFILL SUIT TX800+TX900		725309
8230	#####	558394	Mechanic entered - Wipers and Washers Wipers Not_Clearing Sc	Replaced wipir blades and adjust wiper arms	725309
8230	#####	558508	Mechanic entered - Engine Other steam clen	completed	725309
8230	#####	558511	Consumables		725432
8230	#####	558396	Consumables		725432
8230	#####	558511	Mechanic entered - Elec and Light Interior Lights exit light	replaced rear exit light	725309
8230	#####	558396	LED FRONT POSITION MARKER LIGHT		725309
8230	#####	558396	Mechanic entered - Elec and Light Interior Lights	Replaced one emergency exit LED light	725309
8230	#####	556193	Gearbox Driveline - Transmission coolant pipe cracked	fit new trans cooler coolant pipe.	723119
8230	#####	556193	P CLAMP G/BOX COOLANT PIPE		723119
8230	#####	556441	Mechanic entered - Engine Other rear coolant pipe clamps bro	fit new P clamps and secure pipes.	723119
8230	#####	556180		VEHICLE SAFETY INSPECTION	723119
8230	#####	556180		CLEAN A/C FILTERS	723119
8230	#####	556180		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	723119
8230	#####	556180		VEHICLE SAFETY INSPECTION	723119
8230	#####	556193	GEARBOX COOLANT PIPE MERCEDES BENZ 0500		723119
8230	#####	556193	Gearbox Driveline - Transmission coolant pipe cracked	c/o	723119
8230	#####	555307	Consumables		722684
8230	#####	555307	Consumables		722684
8230	#####	555307	Consumables		722684
8230	#####	555307		B Service Completed	722684
8230	#####	555207	AIR FILTER MERC 0500LE E491L		722684
8230	#####	555207	OIL FILTER 1725+0500LE		722684
8230	#####	555307		CARRY OUT B SERVICE AS PER CHECK LIST completed	722684
8230	#####	555307	Consumables		722684
8230	#####	555307	Consumables		722684
8230	#####	555307	Consumables		722684
8230	#####	555307	Consumables		722684
8230	#####	555307		CARRY OUT A SERVICE AS PER CHECK LIST completed	722684
8230	#####	554156	Mechanic entered - Fluid Leaks Other	added coolant - low.	720855
8230	10/1/2015	550529	Campaign 11/15. Fit 2 x Supplied Decals to Internal Saloo	Fitted	716719
8230	9/28/2015	549593	Replace A3 poster with Victorian Seniors Festival Poster	Replaced by refuellers	716126
8230	9/18/2015	547827			713009
8230	9/18/2015	547827		CLEAN A/C FILTERS	713009
8230	9/18/2015	547827		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	713009
8230	9/18/2015	547827		VEHICLE SAFETY INSPECTION	713009
8230	9/18/2015	547984	Consumables		713517
8230	9/18/2015	547984	Complete task as instructed in Fleet Campaign 09/15	Checked OK	713517
8230	9/18/2015	547984	Body - Adjust rear door sensors	Adjusted	713517
8230	9/16/2015	547419	Engine Fit remaining radiator brackets and mounts	Completed	713002
8230	9/15/2015	546291	CCTV UPGRADE	Creditor #GB-TH0005 THOREB AUSTRALIA PTY LTD P/O #G155726 Receiving #:161534 Date :2015-09-24	714997
8230	9/15/2015	546291	CCTV UPGRADE	Upgrade done by Volgren	712223
8230	9/9/2015	545815	as per Campaign 08/15Fit Hi Vis Vest DecalFit Coat Hook i		711909
8230	9/8/2015	545815	COAT HOOK DRIVERS WA50004		711909
8230	9/7/2015	545459	CCTV (None) Hard Drive not recording video images.	Cleaned up cameras then went and checked drive ats ops.wasent displaying images properly only audio.Checked back at unit and ips stuck at 50 and cannot change.Unit needs to be changed as 145 had same issue and was changed.	711909
8230	8/20/2015	541431	RADIATOR TOP MOUNT 0500	Creditor #GB-MUL001 MULTISPARES LTD P/O #G155006 Receiving #:160274 Date :2015-08-21	708733
8230	8/20/2015	541431	Engine O/S bottom radiator bracket missing radiator mount.	Assited Riene	708733
8230	8/20/2015	541431	Engine O/S bottom radiator bracket missing radiator mount.	Fitted bottom radiator mounts/o/s bracket renewed.o/s top mount modified with Shalen.	708733
8230	8/20/2015	541431	TOP RADIATOR MOUNT BRACKET	Creditor #GB-WHI004 WHITEHORSE TRUCKS PTY LTD P/O #G155014 Receiving #:160531 Date :2015-08-27	709638
8230	8/20/2015	541431	MERC RADIATOR MOUNT BUSHING		708733
8230	8/20/2015	542771	A3 Poster Change on Route buses for Legacy Week 30/08/15-05	Replaced	708733
8230	8/20/2015	542589	Consumables		708733
8230	8/20/2015	542589	Consumables		708733
8230	8/20/2015	542589	Consumables		708733
8230	8/20/2015	542589	Consumables		708733
8230	8/20/2015	542589	Service		708733
8230	8/20/2015	542589		CARRY OUT A SERVICE AS PER CHECK LIST	708733
8230	8/19/2015	541431	RADIATOR MOUNT LOWER 0500LE	CARRY OUT A SERVICE AS PER CHECK LIST	708733
8230	8/18/2015	541431	RADIATOR LOW MOUNT 0500	Creditor #GB-MUL001 MULTISPARES LTD P/O #G154904 Receiving #:160168 Date :2015-08-19	708733
8230	8/17/2015	541431	RADIATOR LOW MOUNT 0500	Creditor #GB-WHI004 WHITEHORSE TRUCKS PTY LTD P/O #G154901 Receiving #:160166 Date :2015-08-19	708733
8230	8/17/2015	541431	CV JOINT BOLTS FAN DRIVE SHAFT	Creditor #GB-ECC001 ECONOMY BOLT CO. P/L P/O #G154853 Receiving #:160076 Date :2015-08-17	707723
8230	8/17/2015	541431	Engine Radiator motor fan drive shaft has excessive play	Remove hydraulic motor fan tail shaft found one bolt broken remove hydraulic motor tail shaft end and hand tap thread. check and clean found cv joint worn no grease and too much movement. and bolt fitted to tail shaft motor fan side is wrong size of bolt replace bolt. ordered all parts to Lee include radiator mount. ter	707723
8230	8/17/2015	541431	Engine O/S bottom radiator bracket missing radiator mount.		707723
8230	8/5/2015	539459	Mechanic entered - A/C Heating Not Heating	re-attached heater pipe to cab butterfly outlet - fallen off. ran bus and tested heater at outlet - o.k.	705437
8230	7/30/2015	538480	Checked bus in the yard and bring on the pit and found coola	Checkeddn and found leaking from rear heater hose.R/R hose and top up coolant.Road tested - ok.	704498
8230	7/30/2015	538480	Fluid Leaks Rear of bus	Checkeddn and found leaking from rear heater hose.R/R hose and top up coolant.Road tested - ok.	704498
8230	7/30/2015	538266	Complete Campaign 6/15 A3 Marketing Poster Change	Replaced	704498
8230	7/21/2015	536798			703157
8230	7/21/2015	536798		CLEAN A/C FILTERS	703157
8230	7/21/2015	536798		TENSION ALL WHEEL NUTS TO OEM SPECIFICATIONS	703157
8230	7/21/2015	536798		VEHICLE SAFETY INSPECTION	703157
8230	7/17/2015	536198	Consumables		702602
8230	7/17/2015	536198	LED NO PLATE-EXIT LIGHT		702602
8230	7/17/2015	536198	Elec and Light - Exit lights very dull	checked exit lights. replaced front light. rear lights working ok.	702602
8230	7/8/2015	534729	NO 5 WHITE 25MM		700210
8230	7/8/2015	534729	NO 7 WHITE 25MM		700210
8230	7/8/2015	534729	DECAL MAX SAFE CARRY WHITE ON CLEAR		700210
8230	7/8/2015	534729	EMERGENCY PROCEDURE DECAL		700210
8230	7/8/2015	534729	DECAL VIDEO AND AUDIO SURVEILLANCE		700210
8230	7/8/2015	534729	Audit Route buses for correct Decals and positions. Replace		700210
8230	7/6/2015	534199	Consumables		700210

8230	#####	501845	Passenger Doors Not Operating / Front door cannot be close	checked out door and ordered nwe part	667427
8230	#####	501845	SOLENOID VALVE	Creditor #:GB-SMCO01 SMC PNEUMATICS (AUSTRALIA) P/L P/O #:G146553 Receiving #:148515 Date :2014-12-15	667610
8230	#####	501245	BUTTERFLY AIR VENT		667427
8230	#####	501150	A3 Poster Change	Fitted	666884
8230	12/9/2014	500977		Inspect radiator and charge air cooler for dirt - clean complete	666874
8230	12/9/2014	500977		Check oil level in transmission - top up if required complete	666874
8230	12/9/2014	500977		Check and clean cartridge in dry type air cleaner complete	666874
8230	12/9/2014	500977		Replace pre and main fuel filters complete	666874
8230	12/9/2014	500977		Replace air dryer canister clean silence and drain reservoir complete	666874
8230	12/9/2014	500977		Replace angle drive oil complete	666874
8230	12/9/2014	500977		Test coolant level - top up if required to equate to 37C frost protection complete	666874
8230	12/9/2014	500977		Replace power steering filter and check level (Replace oil if required) complete	666874
8230	12/9/2014	500977	FUEL FILTER MERC 0500LE		666874
8230	12/9/2014	500977	FUEL FILTER 0500LE		666874
8230	12/9/2014	500977	FILTER DRYER SCANIA/VOLVO (1375997)(49G8704W)		666874
8230	12/9/2014	500977	POWER STEERING FILTER VOLVO		666874
8230	12/9/2014	500977		complete	666874
8230	12/9/2014	500977		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals complete	666874
8230	12/9/2014	501245	Heat & Demist - Replace air vent	Replaced	666884
8230	12/4/2014	500075	DOOR VALVE SILENCER		666283
8230	12/4/2014	500075	Ops Entered - Fault - Passenger Doors Not Operating - Route	change door air pressure regulator assy and 2 silencers door ok.	666283
8230	12/4/2014	500075	FILTER REGULATOR DOOR RAM		666283
8230	12/4/2014	500075	Consumables		0
8230	12/4/2014	500075	Elec & Light W'ming Light	check fault code can't find any all ok.	666283
8230	#####	499184	Mechanic entered - Eng Cool Coolant Low	added coolant.	665054
8230	#####	498560	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		664453
8230	#####	498560	VALVE 4 WAY CIRCUIT PROTECTION VALVE		664453
8230	#####	498560	Ops Entered - Fault - Brakes Hand Brake - Route: 900 - Cha	Replace 6 way valve and road tested OK	664453
8230	#####	498092	Wipers & Washers - Check wipers playing up	check wipper link and wire wipper ok.	663778
8230	#####	497498	Engine W'ming Light	remove engine control unit clean conector fixed same as road test bus ok.	663078
8230	#####	497757	MANUAL DRAIN VALVE		663556
8230	#####	497757	Ops Entered - Fault - Air System Leaking - Route: 900 - Wel	fixed air leak from wet tank.	663556
8230	#####	496901	Ops Entered - Breakdown - Breakdown Road Defect Unaffected 5	Parked bus	662894
8230	#####	496901	Ops Entered - Breakdown - Breakdown Road Defect Unaffected 5	front passenger door maine shaft pin damage fixed door shaft adjust rear door ramp speed bus ok.	662894
8230	#####	496924	Breakdown - Chadstone shopping centre - OUT 11.30 am BACK 1	Front door pivot lost and dislocated secured the door leaves turned the door brakes off to make it mobile to take back to depot	662894
8230	#####	496480	FITTING STRAIGHT JOINER 6MM 11060000		662206
8230	#####	496480	Mechanic entered - Engine Other Alternator Belt Damage	Replace Alternator Belt	662206
8230	#####	496480	A/C BELT 0500 BENZ		662206
8230	#####	496480	Mechanic entered - Engine Other Alternator Belt Damage	Replace Alternator Belt	662206
8230	#####	496389	Consumables		0
8230	#####	496389	Consumables		0
8230	#####	496389	Consumables		0
8230	#####	496389	Consumables		0
8230	#####	496389		Tension Wheel Nuts To OEM Specification	662206
8230	#####	496389		Grease AC Compressor Clutch Bearing	662206
8230	#####	496389		Clean A/C filter	662206
8230	#####	496389		A Service	662206
8230	#####	496389		A Service	662206
8230	#####	496389	AIR FILTER MERC 0500LE E491L		662206
8230	#####	496389		Clean A/C filter	662206
8230	#####	496389		Grease AC Compressor Clutch Bearing	662206
8230	#####	496389		Tension Wheel Nuts To OEM Specification	662206
8230	#####	495411	Ops Entered - Fault - Passenger Doors Faulty Controls - Rou	adjust front door.	660818
8230	11/8/2014	495337		Re- tension rear wheel nuts	660818
8230	11/7/2014	494892	TYRE NEW 11R22.5N	Creditor #:GB-TYR002 TYRES4U P/O #:G145295 Receiving #:147277 Date :2014-11-10	661233
8230	11/6/2014	494892	VALVE EXTENSION-130mm Metal type		660818
8230	11/6/2014	494892	Whls & Tyres - TYRE 4 47 PSI	changed tyre 3 (worn) and 4 (flat). metal valve ext. fitted. nuts tensioned with dulkith.	660818
8230	#####	493961		re-tensioned nuts on wheels 3, 4; 5 and 6.	659661
8230	#####	493819	Consumables		0
8230	#####	493819	Remove Legacy Poster and replace with See Something Say So	N/A	659661
8230	#####	492796	TYRE NEW 11R22.5N	Creditor #:GB-TYR002 TYRES4U P/O #:G144965 Receiving #:146862 Date :2014-10-28	659215
8230	#####	492770			657959
8230	#####	492770		Tension Wheel Nuts done with rene	657959
8230	#####	492770		Perform & Complete PTVS Bus Safety Inspection completed	657959
8230	#####	492796	Tyre no 3 worn		658404
8230	#####	492796	Whls & Tyres Worn pos 5n & 6 tyres .5wap pos 6 tyre with	Completed	658404
8230	#####	490742	Consumables		0
8230	#####	490741	Consumables		0
8230	#####	490740	Consumables		0
8230	#####	490742	Complete AM/FM radio saloon speaker modification	disconnected saloon speakers	655471
8230	#####	490741	Elec & Light W'ming Light - stop warning light on dash.	checked for warning light road tested could not find anything	655471
8230	#####	490740	Elec & Light Hazard Lights not working.	re secured plug to hazard switch checked and working	655471
8230	#####	490466	Consumables		0
8230	#####	490466	GLOBE INST 24V 2W (17063)		655471
8230	#####	490466	Mechanic entered - Elec & Light Dash Light	changed blown globe.	655471
8230	10/7/2014	489790	Service	Replace Differential oil complete	654938
8230	10/7/2014	489790	SYNTHETIC GEAR LUBRICANT FM 75W-140 (LU27)		654938
8230	10/7/2014	489790	Service		654938
8230	9/24/2014	487455	SIDE INDICATOR L/H		651770
8230	9/24/2014	487455	Mechanic entered - Elec & Light Indicators	replaced (nsf) side lamp - broken.	651770
8230	9/24/2014	487455		Re-kit Air Cyclone Separator Completed	651770
8230	9/24/2014	487455	HALDEX COIL BASE OIL SEPERATOR	Condenser Valve Kit.	651770
8230	9/24/2014	487455	HALDEX COIL KIT 0500LE 49G0027HALDEX	Base	651770
8230	9/24/2014	487455		Coil Kit	651770
8230	9/18/2014	486740	Elec & Light - Outer front door switch n/w	Remove Ping Tank & Steel air Pipes for Cleaning Refit Ping Tank & air Pipes Completed	651770
8230	9/16/2014	485891	Ops Entered - Fault - Passenger Doors Faulty Controls - Rou	There is a 1.3v feed coming up earth wire	651070
8230	9/15/2014	484768	AIR CON REFRIDGERANT	front door cant open from out side no negative to safty switch from park brake solonide switch. bus serviceble.	650150
8230	9/15/2014	484768	COMPRESSOR OIL AIR CON		650150
8230	9/15/2014	484768	FILTER DRIER THERMO KING		650150
8230	9/11/2014	485311	DECAL AUTHORISED OFFICER		649443

8230	5/20/2014	464329	Elec & Light - Bus wont start	Jump started	625710
8230	5/13/2014	462428	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		625515
8230	5/13/2014	462428	FRONT RELAY PROPORTIONAL VALVE 0500LE		625515
8230	5/13/2014	462428	Brakes Proportion valve leaks	Replace valve but still MR 7209 fault cod on dash C/O job	625515
8230	5/9/2014	461990	BATTERY 12V 190 AMP 1000CCA (+ on right side)		625515
8230	5/9/2014	461990	BATTERY 12V 190 AMP 1000CCA (+ on right side)		625515
8230	5/9/2014	461990	Elec & Light Battery Flat replace battery	changed battreys checked out suspection	625515
8230	5/9/2014	462068	Remove Fair Evasion A3 Poster & Replace with MYKI AUTO TOP U	completed	625515
8230	5/8/2014	461733	Mechanic entered - Elec & Light Battery Flat	Jumpstart	625515
8230	5/8/2014	461733	Mechanic entered - Elec & Light Battery Flat	Jumpstart	625515
8230	5/7/2014	461604	Elec & Light Battery Flat	Jump started	625352
8230	5/7/2014	461398	Body & Acc. Floor broom missing	Complete.	625352
8230	5/7/2014	461398	Body & Acc - Check drivers compartment door	Remove door and repaired lock.	625352
8230	5/7/2014	461398	SIDE BIN LOCK PINS		625352
8230	5/7/2014	461398	HINGE DRIVERS COMPARTMENT		625352
8230	5/3/2014	460778	Mechanic entered - Elec & Light Battery Flat	jump started.	623975
8230	4/25/2014	459509	Mechanic entered - Steering Other	added power steering fluid.	621523
8230	4/25/2014	459510	GLOBE H1 24V 70W		621523
8230	4/25/2014	459510	Mechanic entered - Elec & Light Headlights	changed blown globe (ns) low beam headlight.	621523
8230	4/7/2014	456832	Elec & Light - Bus wont start	Jump started bus	617900
8230	4/7/2014	456619	Perform Campaign 1_4 School Bus Light Globe Check Check	No school light on this bus	617566
8230	4/7/2014	456833	Eng Cool - Add coolant	Added	617900
8230	4/7/2014	456618	F/H/LAMP COVER HINGE	Creditor #GB-VOL001 VOLGREN AUSTRALIA P/L P/O #:G137455 Receiving #:139068 Date :2014-04-07	617900
8230	4/7/2014	456618	Body & Acc repair N/S head light cover hingh	Replaced	617566
8230	4/5/2014	456393	Mechanic entered - Elec & Light Battery Flat	jump started.	617566
8230	4/4/2014	455041	0500 COOLANT LOW LEVEL SENDER		617566
8230	4/4/2014	455041	Eng Cool repair coolant leak	Fitted radiator intercoolerangle drive change oil angle drive	617566
8230	4/3/2014	456264	Whls & Tyres - Tyre 2 low tread	Checked OK	617566
8230	4/3/2014	455041	Eng Cool repair coolant leak	Removed intercooler & radiator c/o	617566
8230	4/3/2014	455870	Remove A3 Marketing Poster CATCHING A BUSFit A3 Marketing	completed	617806
8230	3/31/2014	455152		Tension Wheel Nuts	617806
8230	3/31/2014	455152		Perform & Complete PTVS Bus Safety Inspection	617806
8230	3/31/2014	455041	Mechanic entered - Steering Other	added power steering fluid.	617566
8230	3/31/2014	455041	RADIATOR 0500LE	Creditor #GB-MUL001 MULTISPARES LTD P/O #:G137161 Receiving #:138828 Date :2014-04-01	617806
8230	3/31/2014	455041	Eng Cool repair coolant leak	Investigate further coolant leak after header tank had been fitted	617566
8230	3/31/2014	455041	HEADER TANK	Creditor #GB-MUL001 MULTISPARES LTD P/O #:G137106 Receiving #:138767 Date :2014-03-31	617566
8230	3/31/2014	455041	WASHER BOTTLE KIT	Creditor #GB-VOL001 VOLGREN AUSTRALIA P/L P/O #:G137099 Receiving #:138766 Date :2014-03-31	617566
8230	3/31/2014	455041	Eng Cool repair coolant leak	Replaced header tank	617566
8230	3/31/2014	455157	Ops Entered - Fault - Security CCTV System Faulty - Route:	removed hdd. refit and tested ok. the hdd had not been locked.	617806
8230	3/31/2014	454974	Brakes - Front pads low transmission oil leak	Brakes are OK	617566
8230	3/31/2014	455041	Ops Entered - Breakdown - Breakdown Mech Defect Affects Ser	Temp repair fitted drain nipple to top air tank needs a test nipple	617566
8230	3/31/2014	454974	MANUAL DRAIN VALVE		617566
8230	3/30/2014	455050	Eng Cool - Wash engine & top up coolant	Washed & topped up	617806
8230	3/30/2014	455053	Breakdown - Monash Uni - OUT 7.00 pm BACK 8.20 pm - Broken	VAN 619. Temp repair and bring back to w/shop	617806
8230	3/28/2014	453401	Eng Cool Coolant Low radiator cracked please remove for re	R/tested with Andrew & picked up parts from Scania Dandenong	617566
8230	3/28/2014	453401	Eng Cool Coolant Low radiator cracked please remove for re	completed compressor installtopped all fluids uplest drivensteamcleanedmoped	617566
8230	3/28/2014	453401	P/STRG PUMP COUPLING	Creditor #GB-MUL001 MULTISPARES LTD P/O #:G137015 Receiving #:138689 Date :2014-03-28	617566
8230	3/28/2014	453401	AIR DRYER SILENCER SLUIT VOLVO B10BLE		617566
8230	3/28/2014	454829		A Service	617566
8230	3/28/2014	454829		A Service	617566
8230	3/28/2014	454829		Clean A/C filter	617566
8230	3/28/2014	454829		Grease AC Compressor Clutch Bearing	617566
8230	3/28/2014	454829		Tension Wheel Nuts To OEM Specification	617566
8230	3/26/2014	453401	0500LE COMP GASKET KIT SUIT(9	Creditor #GB-MUL001 MULTISPARES LTD P/O #:G136852 Receiving #:138561 Date :2014-03-26	617566
8230	3/26/2014	453401	Eng Cool Coolant Low radiator cracked please remove for r	c/o	617566
8230	3/26/2014	453401	COOLANT PIPE COMPRESSOR TO BLO	Creditor #GB-WHI004 WHITEHORSE TRUCKS PTY LTD P/O #:G136779 Receiving #:138576 Date :2014-03-26	617566
8230	3/24/2014	453401	AIR COMPRESSOR 0500 EURO 3	Creditor #GB-MUL001 MULTISPARES LTD P/O #:G136725 Receiving #:138424 Date :2014-03-24	617566
8230	3/21/2014	453217	Clear unblock all steel pipes between compressor and cyclone	Remove Ping Tank & Steel air Pipes for Cleaning Ref/Ping Tank & air Pipes	617566
8230	3/20/2014	453401	Eng Cool Coolant Low radiator cracked please remove for re	Removed compressor & p/steering removed steel air pipes c/o	617566
8230	3/20/2014	453217	AIR DRYER MERCEDES 0500	Coil kit	617566
8230	3/20/2014	453217	OIL PIPE FILTER TO BLOCK 0500LE	Coil kit	617566
8230	3/20/2014	453217	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)	Coil kit	617566
8230	3/20/2014	453217	HALDEX COIL KIT 0500LE	Coil kit	617566
8230	3/20/2014	453217	DRAIN VALVE KIT BOTTOM	Valve Kit	617566
8230	3/20/2014	453217	HALDEX COIL BASE OIL SEPERATOR	Base	617566
8230	3/20/2014	453217	CYCLONE CONDENSER VALVE KIT	Condenser Valve Kit.	617566
8230	3/19/2014	453217		Re-kit Air Cyclone Separator	617566
8230	3/17/2014	452475	L.E.D SIDE MARKER PERE1 RED/AMBER		617566
8230	3/17/2014	452475	Mechanic entered - Elec & Light Park Lights	replaced smashed (nsr) clearance lamp.	617566
8230	3/14/2014	450612	Eng Cool - Check for coolant leak	Washed and r/tested	617023
8230	3/14/2014	451504	Body & Acc. - Secure rear b/bar	Repaired replaced screws & teflon strip	617023
8230	3/13/2014	451908	SENSITIVE EDGE DOOR SWITCH DW40		616767
8230	3/13/2014	451908	Passenger Doors	checked OK	616767
8230	3/13/2014	451908	Passenger Doors (None)	Changed front door sensitive edges sensors and adjusted door	616767
8230	3/13/2014	451908	Mechanic entered - Eng Cool Coolant Low	added coolant.	616767
8230	3/13/2014	452188	Fit Myki decals as requiredFit Recruitment decal as requi	Replaced	616848
8230	3/11/2014	450612	Ops Entered - Fault - Passenger Doors Faulty Controls - Ro	Fitted new door solenoid checked OK	615053
8230	3/11/2014	450610	Ops Entered - Fault - Passenger Doors Faulty Controls - Rou	Fitted new door solenoid checked OK	615053
8230	3/11/2014	450612	Elec & Light - Interior lights n/w	Replaced old saloon LEDs with new ones	615053
8230	3/11/2014	451448	Elec & Light Interior Lights replace interior lights	Replaced old saloon LEDs with new ones	616335
8230	3/11/2014	450612	FIRTREE CLIP		615053
8230	3/11/2014	450612	Mechanic entered - Eng Cool Coolant Low	added coolant.	616335
8230	3/8/2014	451560	Eng Cool - Add coolant	Added	615917
8230	3/7/2014	450610	FREIGHT	Creditor #GB-SMC001 SMC PNEUMATICS (AUSTRALIA) P/L P/O #:G136098 Receiving #:137749 Date :2014-03-11	616335
8230	3/7/2014	451448	LED INTERIOR ROOF LIGHT	Creditor #GB-MUL001 MULTISPARES LTD P/O #:G136093 Receiving #:137748 Date :2014-03-11	616335
8230	3/7/2014	450610	SOLENOID VALVE	Creditor #GB-SMC001 SMC PNEUMATICS (AUSTRALIA) P/L P/O #:G136098 Receiving #:137749 Date :2014-03-11	616335
8230	3/7/2014	450610	outside door close button not wrking	start to fit solinoid wrong part ordered right part	615053
8230	3/6/2014	450612	Eng Cool coolant leak from header tank	Replace header tank cap and road test	615053
8230	3/5/2014	450612	Eng Cool coolant leak from header tank		615053
8230	3/5/2014	450612	RAD CAP MERC BENZ SIGHT GLASS SIDE		615053
8230	3/5/2014	450612	Eng Cool coolant leak from header tank	Replaced header cap top up coolant and clean engine	615053

8230	3/5/2014	450610	Eng Cool coolant leak from header tank		615053
8230	3/3/2014	450246	RAD CAP MERC BENZ SIGHT GLASS SIDE		614572
8230	3/2/2014	450246	Eng Cool - Replace radiator cap	Replaced cap & topped up coolant	614572
8230	2/27/2014	449740	Mechanic entered - Eng Cool Coolant Low	added coolant.	613575
8230	2/25/2014	449132	HOSE ENG TO G/BOX COOLER MERC 0500LE		612799
8230	2/25/2014	449132	Ops Entered - Breakdown - Breakdown Road Defect Unaffected	??? unaffected	612799
8230	2/24/2014	449132	Mechanic entered - Breakdown Other	take van to wellington rd mulgrave replace coolant hose bring to depot 6.50	612799
8230	2/17/2014	447731		steam clean engine (coolant header tank area).	611544
8230	2/17/2014	447731	Mechanic entered - Eng Cool Coolant Low	added coolant.	611544
8230	2/14/2014	447439	BOSCH REGULATOR 0500LE ALT		
8230	2/14/2014	447439	BEARING ALT MAN 16-240+0500LE		
8230	2/14/2014	447439	AD120689571 70-140AMP ALTERNATOR MERCEDES BENZ 0500LE	Rebuilt alternator	
8230	2/10/2014	446590	Mechanic entered - Eng Cool Coolant Low	added coolant.	609263
8230	2/6/2014	446194	Mechanic entered - Steering Other	added power steering fluid.	608934
8230	2/4/2014	445791	Brakes Replace hand brake valve	TRENT QUINN - Replaced park brake valve & modified plate	607621
8230	2/4/2014	445791	PARK BRAKE VALVE 0500LE		607621
8230	2/3/2014	444914	ANNUAL INSPECTION	Creditor #:GB-ROA001 Road Safety Inspections P/O #:G134447 Receiving #:136449 Date :2014-02-06	609263
8230	2/2/2014	444914	Annual Licence	RWC 676513 - PASSED	607621
8230	2/1/2014	438990	IMAGE RELATED REPAIRS TO BUSES	Creditor #:GB-TRA013 TRANSVAL P/O #:G132548 Receiving #:135197 Date :2014-01-07	603474
8230	1/29/2014	442516		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	603474
8230	1/29/2014	442516		Inspect radiator and charge air cooler for dirt - clean	603474
8230	1/29/2014	442516		Check oil level in transmission - top up if required	603474
8230	1/29/2014	442516		Check and clean cartridge in dry type air cleaner	603474
8230	1/29/2014	442516		Replace pre and main fuel filters	603474
8230	1/29/2014	442516		Replace air dryer cansiter clean silence and drain reservoir	603474
8230	1/29/2014	442516		Replace angle drive oil	603474
8230	1/29/2014	442516		Test coolant level - top up if required to equate to 37C frost protection	603474
8230	1/29/2014	442516		Replace power steering filter and check level (Replace oil if required)	603474
8230	1/29/2014	445252	Engine - Steamclean all bus	5/cleaned	606748
8230	1/23/2014	444353	WHEELCHAIR DECAL		606748
8230	1/23/2014	444353	CENTRA SEAT END CAPS		606748
8230	1/23/2014	444353	EMERGENCY EXIT DECAL 600MM X 80MM		606748
8230	1/23/2014	444353	DO NOT OVERTAKE DECAL		606748
8230	1/23/2014	444353	'GIVE WAY' DECAL 240MM X 225MM		606748
8230	1/22/2014	444240	Comm Equip Faulty. No power	checked two way ok	606748
8230	1/22/2014	444353	Body & Acc - Repair drivers blind	Repaired	606748
8230	1/22/2014	444353	Body & Acc - Secure OS 7 seat frame replace end caps NS 7	Secured	606748
8230	1/22/2014	444353	Body & Acc - Replace interior decals - No Smoking	Replaced	606748
8230	1/22/2014	444353	Body & Acc - Rear step edges replace or fit inserts	Fitted	606748
8230	1/22/2014	444353	Body & Acc - Replace accreditation number decal	Replaced	606748
8230	1/22/2014	444353	Body & Acc - Replace rear window decal	Replaced	606748
8230	1/22/2014	444353	Body & Acc - Replace Do Not Overtake decal - NSR corner b/ba	Replaced	606748
8230	1/22/2014	444353	Body & Acc - Secure all lower skirt panels	Secured	606748
8230	1/22/2014	444353	Body & Acc - Replace Give Way decal - OSR corner window	Replaced	606748
8230	1/21/2014	442516	Mechanic entered - Eng Cool Coolant Low	added coolant.	606493
8230	1/21/2014	442516	Body & Acc - Passenger Seat Cushion. Rear pax seat vadelized	re-fitted seat back and bottom (rear row) n/s.	606493
8230	1/20/2014	442516	GLOBE 24V 2W		606349
8230	1/20/2014	442516	Mechanic entered - Elec & Light Guages	changed blown globe.	606349
8230	1/15/2014	443352	Air Cond Air Conditioner blowing hard	clear fault code clean air returne filter bus ok.	604992
8230	1/11/2014	442216	Ops Entered - Fault - Elec & Light Altern Light - Route:	Alt has been replaced	604310
8230	1/8/2014	442519		Perform & Complete PTVS Bus Safety Inspection complete	603474
8230	1/8/2014	442519		Tension Wheel Nuts complete	603474
8230	1/8/2014	442519		Perform & Complete PTVS Bus Safety Inspection complete	603474
8230	1/8/2014	442516		complete	603474
8230	1/8/2014	442516	FUEL FILTER 0500LE		603474
8230	1/8/2014	442516	POWER STEERING FILTER VOLVO		603474
8230	1/8/2014	442516	AIR DRYER CANISTER VOLVO+ NL202		603474
8230	1/8/2014	442516	FUEL FILTER MERC 0500LE		603474
8230	1/8/2014	442517		Clean A/C filter	603474
8230	1/8/2014	442517		Clean A/C filter	603474
8230	1/8/2014	442517		Grease AC Compressor Clutch Bearing	603474
8230	1/8/2014	442517		Tension Wheel Nuts To OEM Specification	603474
8230	1/7/2014	442216	70-140AMP ALTERNATOR MERCEDES BENZ 0500LE		603474
8230	1/7/2014	442216	Elec & Light Altern Light	checked alternator not charging, removed alternator and began fitting rebuilt alt. had to wait for hydraulic puller to remove pulley and go to economy bolt to allen key bolts to repair rattle gun.	603474
8230	#####	441261	Passenger Doors not opening	changed door solinoid	601826
8230	#####	441261	DOOR VALVE SILENCER		601826
8230	#####	441261	DOOR VALVE SILENCER		601826
8230	#####	441261	PILOT VALVE 5 PORT		601826
8230	#####	441261	Ops Entered - Fault - Passenger Doors Not Operating - Rout	changed door solinoid	601826
8230	#####	440913	Remove A3 Hold On Poster and Fit A3 Catching a bus poster	removed	600934
8230	#####	440621	Mechanic entered - Eng Cool Coolant Low	added coolant.	600701
8230	#####	440416	L.E.D SIDE MARKER PERE1 RED/AMBER		600080
8230	#####	440416	Mechanic entered - Elec & Light Park Lights	REPLACED (NSR) CLEARANCE LIGHT - SMASHED.	600080
8230	#####	438990	Carry out campaign as per Fleet re-branding Procedure.	Rebranded rear only	597907
8230	12/9/2013	438354	Passenger Doors Faulty Controls	REF TO W/O 438201	596918
8230	12/8/2013	438201	Passenger Doors Front door U/S	Replace door switch	596918
8230	#####	436125	SIDEWALL	Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G132202 Receiving #:134045 Date :2013-12-02 SCRAPPED	596035
8230	#####	436126	Whls & Tyres - SCRAP TYRE	WRONG	593067
8230	#####	436125	Whls & Tyres - SCRAP 2 TYRES	SIDEWALL DAMAGED SCRAPPED	593067
8230	#####	435534	Mechanic entered - No Defect Recorded	adjust alt beltrear passanger door pti road test bus ok.	592116
8230	#####	434438	WRON - POS 345 - 11 R22.5 -	Creditor #:GB-BEA001 BEAUREPAIRES P/O #:G131753 Receiving #:133432 Date :2013-11-18 REPLACE WITH NEW	592116
8230	#####	434415	Whls & Tyres - Tyre 3 low		591536
8230	#####	434415	Mechanic entered - Whls & Tyres Worn	fit all rear tyres tension nuts	591536
8230	#####	434438	Whls & Tyres - Replace tyre pos 345 - worn	Replaced	591536
8230	#####	434723	Fit New Myki Decal as Per PTV fitting instructions	Fitted	591536
8230	11/6/2013	433569	LAMP INTERIOR AND REVERSING		589396
8230	11/1/2013	433569	Body & Acc Exterior	Replaced reverse lamp	589396
8230	#####	431429		A Service & Bus Safety Inspection	589011
8230	#####	431429		D-Service & Bus Safety Inspection	589011
8230	#####	431429		Tension Wheel Nuts to Spec	589011

8230	#####	431429	assist to D service.	589011
8230	#####	431429	Replace Engine Oil Breather Kit	589011
8230	#####	431429	ENGINE OIL BREATHER KIT 0500LE (EASS00M05)	589011
8230	#####	431429	Grease AC Compressor Clutch Bearing	589011
8230	#####	431429	AIR FILTER MERC 0500LE	589011
8230	#####	431429	OIL FILTER 1725+0500LE	589011
8230	#####	431429	ENGINE OIL DELD 400LE 15W40	589011
8230	#####	431429		589011
8230	#####	431429	Grease AC Compressor Clutch Bearing	589011
8230	#####	431429	Tension Wheel Nuts To OEM Specification	589011
8230	#####	431429	A Service D Service Completed	589011
8230	#####	431429	Clean A/C filter	589011
8230	#####	431429	Completed by operations	589011
8230	#####	430677	Remove A3 Poster 15/8Fit Poster (HOLD ON) as per Campaign	586391
8230	#####	430762	Diff & Hubs replace diff oil	586391
8230	#####	430356	Perform & Complete PTSV Bus Safety Inspection	586391
8230	#####	430356	Perform & Complete PTSV Bus Safety Inspection	586391
8230	#####	430356	Tension Wheel Nuts	586391
8230	#####	430764	Passenger Doors - Adjust rear door sensitive edge	586391
8230	#####	430035	Diff & Hubs replace diff oil	585794
8230	10/2/2013	428020	Drv entered - Wipers & Washers Worn	583458
8230	9/27/2013	423020	Perform sticker audit on vehicles ensuring that correct stic	578863
8230	9/25/2013	427044	WEDGE GLOBE INSTRUMENT 24V SW	582475
8230	9/24/2013	427044	Elec & Light - Replace globe	582475
8230	9/24/2013	426140	FILTER DRIER THERMO KING	582475
8230	9/20/2013	426270	Mechanic entered - Eng Cool Coolant Low	581756
8230	9/19/2013	426140	added coolant.	581756
8230	9/19/2013	426140	C Service	581756
8230	9/19/2013	426140	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condenser pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	581756
8230	9/19/2013	426140	CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	581756
8230	9/19/2013	426140	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	581756
8230	9/19/2013	426140	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	581756
8230	9/19/2013	426140	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	581756
8230	9/19/2013	426140	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	581756
8230	9/19/2013	426140	DRIVE PULLEYS: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	581756
8230	9/19/2013	426140	DRIVE PULLEYS: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	581756
8230	9/19/2013	426140	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	581756
8230	9/19/2013	426140	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	581756
8230	9/19/2013	426140	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	581756
8230	9/8/2013	424067	Brake Interlock Re-Install to be performed as per Campaign	578863
8230	9/7/2013	423467	Remove A3 Marketing Poster 30/9Fit Marketing Poster 15/8	578863
8230	9/6/2013	423020	Mechanic entered - Body & Acc Passenger Seat Cushion	578863
8230	9/5/2013	423752	Organise Mbenz Recall SM949 to be performed by Whitehorse T	578863
8230	9/4/2013	423020	Ops Entered - Accident - Unreported Accident - Route: - Of	578863
8230	9/4/2013	423020	Ops Entered - Accident - Unreported Accident - Route: - Of	578863
8230	9/3/2013	423020	BY LAW PICKUP/SET DOWN DECAL	578863
8230	9/3/2013	423020	DRIVERS NO DEFECT CHECKLIST DECAL	578863
8230	9/3/2013	423020	WARNING MAXIMUM HEIGHT DECAL	578863
8230	9/3/2013	423020	Perform sticker audit on vehicles ensuring that correct stic	578863
8230	9/3/2013	423020	PLEASE ASSIST DRIVER DECAL	578863
8230	9/3/2013	423020	EMERGENCY PROCEDURE DECAL	578863
8230	9/3/2013	423020	NO SMOKING DECAL	578863
8230	9/3/2013	423020	CCTV SURVEILLANCE DECAL	578863
8230	9/3/2013	423020	BY LAW PICKUP/SET DOWN DECAL	578863
8230	9/3/2013	423020	CUSTOMER ENQUIRY DECAL	578863
8230	9/3/2013	423020	LICENSED TO CARRY DECAL	578863
8230	9/3/2013	423020	CUSTOMER ENQUIRY DECAL	578863
8230	9/3/2013	423020	Ops Entered - Accident - Unreported Accident - Route: - Of	578863
8230	9/3/2013	423475	Mechanic entered - Accident Front MAKEUP NEW COLOUR VARIANTS	578863
8230	9/3/2013	423475	Mechanic entered - Accident Front	578863
8230	9/2/2013	423020	Perform sticker audit on vehicles ensuring that correct stic	578863
8230	9/2/2013	423020	F/GLASS REAR CENTER BUMPER	578863
8230	9/2/2013	423020	Ops Entered - Accident - Unreported Accident - Route: - Of	578863
8230	8/25/2013	421944	WEDGE GLOBE INSTRUMENT 24V SW	577697
8230	8/25/2013	421944	Mechanic entered - Elec & Light Park Lights n/s/f park light	577697
8230	8/22/2013	421402	Perform Campaign as per Instructions Ensure that appropria	577697
8230	8/22/2013	420065	15LTR RUBBISH BINS	577697
8230	8/22/2013	420065	Brakes - Front rotors low - 37mm	577697
8230	8/21/2013	420065	Brakes - Front rotors low - 37mm	577697
8230	8/19/2013	420065	Brakes - Front rotors low - 37mm	577697
8230	8/16/2013	420010	rotors bearings	577697
8230	8/15/2013	420065	Brakes - Front rotors low - 37mm	577697
8230	8/14/2013	420065	WHEEL BEARING	577697
8230	8/14/2013	420065	HUB SEAL FRONT INNER MERCEDES BENZ 0500LE	577697
8230	8/14/2013	420065	HUB SEAL FRONT OUTER MERCEDES BENZ 0500LE	577697
8230	8/14/2013	420065	HUB CAP GASKET 0500LE	577697
8230	8/14/2013	420065	DISC PAD SET SCANIA MB0500	577697
8230	8/14/2013	420065	FRONT+REAR DISC ROTOR MERCEDES BENZ 0500	577697
8230	8/14/2013	420065	Brakes - Front rotors low - 37mm	577697
8230	8/13/2013	420010	ROCKER COVER GASKET 0500LE	577697
8230	8/13/2013	420010	Rocker Cover Gasket	577697
8230	8/9/2013	418362	Replace decals - N/S PANELS -	577697
8230	8/8/2013	418656	Adjust Tappets	577697
8230	8/8/2013	418656	Creditor #:GB-ATT001 ATTITUDE SIGNS P/O #:G127957 Receiving #:129387 Date :2013-08-09	577697
8230	8/8/2013	418656	Re-kit Air Cyclone Separator	577230
8230	8/8/2013	418656	Re-kit Air Cyclone Separator	577230
8230	8/8/2013	419132	A Service	577697
8230	8/8/2013	419132	Tension Wheel Nuts To OEM Specification	577697
8230	8/8/2013	419132	A Service	577697
8230	8/8/2013	419132	Clean A/C filter	577697
8230	8/8/2013	419132	Grease AC Compressor Clutch Bearing	577697
8230	8/6/2013	418362	Accident#37226 - NSR corner panel damage	577230
8230	8/6/2013	418656	Replaced clearance light wired all electrics fitted all tail lights. Replaced reflector decal on b/bar corner N5 fitted NSR bar corner & secured OS bar corner	577230
8230	8/6/2013	418656	Coil Kit	577230
8230	8/6/2013	418656	Valve Kit	577230
8230	8/6/2013	418656	HALDEX COIL BASE OIL SEPERATOR	577230
8230	8/6/2013	418656	Base	577230

8230	8/6/2013	418656	CYCLONE CONDENSER VALVE KIT	Condenser Valve Kit.	577230
8230	8/5/2013	418362	UNREPORTED Accident - Repair NS 3 panel	Removed decals repair panel filler work prep work ready for topcoat	577230
8230	8/5/2013	418362	Accident#37822 - NSF Top corner damage	Filler work prep work masked up for top coat c/o	577230
8230	8/5/2013	418362	Accident#37822 - NSF Top corner damage	Repaired acc dam to NS top front corner and NS rear b/bar corner ready for painting c/o	577230
8230	8/5/2013	418362	Accident#37226 - NSR corner panel damage	Cont repairs on NS tail light panel NSR b/bar corner & NS front top sanded primed painted base coat & clear coat unmasked fitted NS panel 2	577230
8230	8/5/2013	418362	Accident#37226 - NSR corner panel damage	Masked up corner c/o	577230
8230	8/2/2013	418362	UNREPORTED Accident - Repair NS 3 panel	Began repairs to NS 3 panel c/o	577230
8230	8/2/2013	418362	Accident#37822 - NSF Top corner damage	Fibreglass repaired top corner applied body filler c/o	577230
8230	8/2/2013	418362	Accident#37226 - NSR corner panel damage	Dismantled NSR corner panel & repaired c/o	577230
8230	8/2/2013	418362	Accident#37815 - Rear bumper damage	Repaired b/bar	577230
8230	7/30/2013	417360	Drv entered - Passenger Doors Not Operating	no defect - cold morning	576075
8230	7/30/2013	417353	Drv entered - Body & Acc Other	?????	576075
8230	7/29/2013	417780	Eng Cool - Add coolant	Added	576075
8230	7/24/2013	416695	CLIPPARD VALVE DOOR OPEN/CLOSE		573837
8230	7/24/2013	416591	24V INVERTER 20W		573837
8230	7/24/2013	416591	FLURO END POLE TOMBSTONE		573837
8230	7/23/2013	416147			573356
8230	7/23/2013	416147		Tension Wheel Nuts	573356
8230	7/23/2013	416147		Perform & Complete PTSV Bus Safety Inspection	573356
8230	7/23/2013	416695	Passenger Doors - replace front door valve	Replaced	573837
8230	7/23/2013	416591	Elec & Light - OSR interior light n/w	Replaced inverter	573837
8230	7/22/2013	415756	REPL NS GLASS	Creditor #GB-GLA001 GLASS ASSIST PTY LTD P/O #G127223 Receiving #:128450 Date :2013-07-22	573356
8230	7/18/2013	415756	Vandalism. Rock Throwing - NS glass smashed	Knocked out NS glass & cleaned up	572800
8230	7/18/2013	415756	Vandalism. Rock Throwing - NS glass smashed		572800
8230	7/9/2013	414151	Elec & Light - Horn u/s	Checked OK	569676
8230	7/9/2013	414151	Body & Acc - Yellow safety strip missing at rear inside bus	fixed	569676
8230	7/9/2013	414151	Air System - Front door switch leaking air - outside ones	fixed	569676
8230	7/9/2013	414151		Service T - Replace Transmission Oil & Filter	569676
8230	7/9/2013	414151		Bus Safety Inspection	569676
8230	7/9/2013	414151		ZF Transmission Filter	569676
8230	7/9/2013	414151	FILTER TRANSMISSION ZF 4139-298-038E39HD119	ZF Ecofluid A Plus Synthetic Transmission Oil	569676
8230	7/9/2013	414151	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	Service T - Replace Transmission Oil & Filter	569676
8230	7/9/2013	414151			569676
8230	7/8/2013	413970	L E D SIDE MARKER PERE RED/AMBER		569676
8230	7/6/2013	413970	Elec & Light - Replace smashed NSR clearance light	Replaced	569233
8230	7/5/2013	413575	SIDEWALL DAMAGE	Creditor #GB-BEAD01 BEAUREPARES P/O #G126646 Receiving #:127907 Date :2013-07-09 SCRAPPED	569676
8230	7/5/2013	413575	Whls & Tyres - Sidewall damage	Scrapped	569150
8230	6/25/2013	411872	AMBER REFLECTOR		565451
8230	6/24/2013	411559	SIDEWALLFLAT - POS 14 - 11 R	Creditor #GB-BEAD01 BEAUREPARES P/O #G126107 Receiving #:127183 Date :2013-06-25 REPAIR OR REPLACE WITH NEW	565507
8230	6/24/2013	411888	Whls & Tyres - Replace tyres 14	Replaced & torqued w/nuts	565451
8230	6/24/2013	411559	Whls & Tyres - replace tyre pos 14 - sidewall flat	replaced	565000
8230	6/24/2013	411872	Elec & Light - Replace missing OSR amber reflector	Replaced	565451
8230	6/24/2013	411666	BRAKE BOOSTER REAR N/S MB0500LE		565000
8230	6/24/2013	411666	BRAKE BOOSTER REAR O/S MB0500LE		565000
8230	6/21/2013	411666	Brakes - OSR brake booster seems leaking air when foot on b	Fitted new brake booster NS & OS rear fitted & r/tested	565000
8230	6/17/2013	410520	INDICATOR ARM 0500LE		562641
8230	6/17/2013	410520	MUD FLAPS GREEN/AS MFS0X30GRE RED		562641
8230	6/15/2013	410520	Passenger Doors - front door sensitive edge n/w	Checked found OK	562270
8230	6/15/2013	410520	Gearbox - Replace bottom g/box cooler rubber hose	Replaced	562270
8230	6/15/2013	410520	Elec & Light - Replace indicator stork	Replaced	562270
8230	6/15/2013	410520	Eng Cool - Bleed cooling system	Bled & r/tested	562270
8230	6/15/2013	410520	Body & Acc - LHF mudflap torn	Replaced	562270
8230	6/15/2013	410520	Body & Acc Drivers Seat Controls	Repaired	562270
8230	6/15/2013	410519		A Service	562270
8230	6/15/2013	410519		Clean A/C filter	562270
8230	6/15/2013	410519		Grease AC Compressor Clutch Bearing	562270
8230	6/15/2013	410519		Tension Wheel Nuts To OEM Specification	562270
8230	6/11/2013	409481	HOSE LAITE 810M		561158
8230	6/10/2013	409704	Eng Cool - Add coolant	Added	561158
8230	6/8/2013	409481	Breakdown - Carnbourne Station - OUT 4.00 pm BACK 7.00 pm -	Van 619. Could not fit aftermarket merc hose too tight had to cut Volvo hose and make fit OK	560477
8230	6/7/2013	409494	Body & Acc - Secure loose screws on b/bar	Secured	560477
8230	6/3/2013	408521	GLOBE INDICATOR 24V-18W SINGLE CONTACT		558337
8230	5/31/2013	408521	Elec & Light - Replace indicator globe	Replaced	557946
8230	5/29/2013	407988	Eng Cool - Add coolant	Added	557177
8230	5/24/2013	405783	90LTR BOOST PUMP COACH		555614
8230	5/24/2013	405783	FILTER DRIER THERMO KING		555614
8230	5/23/2013	406934	RELAY VALVE		555171
8230	5/23/2013	406934	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		555171
8230	5/23/2013	406934	HALDEX CONDENSER KIT TOP(CYCLONE)		555171
8230	5/23/2013	406934	CHECK VALVE 22MM CYCLONE AIR FILTER		555171
8230	5/23/2013	406934	CYCLONE CONDENSER VALVE KIT		555171
8230	5/23/2013	405783	B - SERVICE	Creditor #GB-22C001 22 CELSIUS P/O #G124756 Receiving #:125438 Date :2013-05-23	555171
8230	5/22/2013	406654		Perform & Complete PTSV Bus Safety Inspection	555045
8230	5/22/2013	406654		Tension Wheel Nuts	555045
8230	5/22/2013	406654	Perform Campaign 01_13 CCTV and GPS AUDIT inspect vehicles	Perform & Complete PTSV Bus Safety Inspection	555045
8230	5/22/2013	406842	Perform Campaign 01_13 CCTV and GPS AUDIT inspect vehicles	Audited	555171
8230	5/22/2013	406934	Eng Cool - Rekit water separator	Rekitted and changed relay valve	555171
8230	5/22/2013	406934	Eng Cool - Rekit water separator	Overhauled cyclonic water separator fitted new pipe union seal fit new relay valve	555171
8230	5/16/2013	405783		B Service	553341
8230	5/16/2013	405783		Replace filter drier	553341
8230	5/16/2013	405783		Replace compressor oil	553341
8230	5/16/2013	405783		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	553341
8230	5/16/2013	405783		CONDENSOR AREA: Clean condensor coils; check bolts/clamps for tension	553341
8230	5/16/2013	405783		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	553341
8230	5/16/2013	405783		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray	553341
8230	5/16/2013	405783		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	553341
8230	5/16/2013	405783		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	553341
8230	5/16/2013	405783		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	553341
8230	5/16/2013	405783		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	553341
8230	5/16/2013	405783		COMPRESSOR DRIVE BELTS: inspect belt wear; Retension belts;	553341
8230	5/16/2013	405783		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	553341
8230	5/16/2013	405783		Clean R/A & F/A filters; inspect and report on condition; Replace filter media	553341

8230	5/11/2013	405056	Suspension - Worn rear LHS sway bar link	Replaced completed r/tested	551547
8230	5/11/2013	405056	Suspension - Worn rear LHS sway bar link	Replaced	551547
8230	5/11/2013	405056	Elec & Light - Repair or replace engine hatch micro switch	Repaired	551547
8230	5/9/2013	404720	AMBER REFLECTOR		551547
8230	5/9/2013	404694	GLOBE 24V 21W SINGLE CONTACT		551547
8230	5/9/2013	404921	Eng Cool - Add coolant	Added	551547
8230	5/8/2013	404694	Elec & Light - Indicators - front left hand bottom	Replaced	551547
8230	5/8/2013	404720	Elec & Light - Replace reflector	Replaced	551547
8230	4/22/2013	402143	Accident #37197# damaged L/H front coner and bumper bar als	u/S Bus due to damage	550623
8230	4/22/2013	402143	Accident #37197# damaged L/H front coner and bumper bar als	ECTB - 22/04/2013	550623
8230	4/16/2013	401573	Body & Acc - Secure exterior mirror	Secured	549798
8230	4/15/2013	401166	Wipers & Washers Wipers U/S	tightened wipers. checked on all speeds ok.	549059
8230	4/8/2013	400056	PADDLE LATCH DRIVER COMPARTMENT DOOR		546945
8230	4/5/2013	399140	WORN - POS 1234 - 11 R22.5	Creditor #BEA001 BEAUREPAIRES P/O #K122280 Receiving #:123226 Date :2013-04-05 REPLACE WITH NEW	546403
8230	4/5/2013	400056	Body & Acc - Replace drivers cab door latch	Replaced	546730
8230	4/5/2013	399805	HINGE DRIVERS COMPARTMENT		546403
8230	4/4/2013	399805	Body & Acc - Replace drivers comp door hinge	Adjusted replaced hinges	546403
8230	4/3/2013	399466	DOOR VALVE SILENCER		546007
8230	4/2/2013	399140	Whls & Tyres - Replace tyres 1234 - worn	replaced	545598
8230	4/1/2013	399466	Passenger Doors - Front door wont open	Fitted silencer on front & rear door checked OK	545598
8230	3/28/2013	398899	RAD CAP MERC BENZ SIGHT GLASS SIDE	A Service	544361
8230	3/26/2013	398899	Eng Cool radiator cap U/S	Replaced	543877
8230	3/26/2013	398548		A Service & Bus Safety Inspection	543877
8230	3/26/2013	398548		Replace Engine Oil Breather Kit	543877
8230	3/26/2013	398548	ENGINE OIL BREATHER KIT 0500LE		543877
8230	3/26/2013	398548		Grease AC Compressor Clutch Bearing	543877
8230	3/26/2013	398548	AIR FILTER MERC 0500LE		543877
8230	3/26/2013	398548	OIL FILTER 1725-0500LE		543877
8230	3/26/2013	398548	ENGINE OIL DELO 400LE 15W40		543877
8230	3/26/2013	398548		Tension Wheel Nuts to Spec	543877
8230	3/26/2013	398548		A Service & Bus Safety Inspection	543877
8230	3/26/2013	398548		D-Service & Bus Safety Inspection	543877
8230	3/26/2013	398548		A Service	543877
8230	3/26/2013	398548		Clean A/C filter	543877
8230	3/26/2013	398548		Grease AC Compressor Clutch Bearing	543877
8230	3/26/2013	398548		Tension Wheel Nuts To OEM Specification	543877
8230	3/23/2013	398768	Whls & Tyres Replace tyres pos 2. 3. 4.	replaced	543547
8230	3/19/2013	396834	SENSITIVE EDGE DOOR SWITCH		541620
8230	3/12/2013	396834	Passenger Doors front sensitive edge switch u/s	Replaced	540037
8230	3/12/2013	396834	Passenger Doors front sensitive edge switch u/s	Replaced assist subu	540037
8230	3/5/2013	394041		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	534797
8230	3/5/2013	394041		Inspect radiator and charge air cooler for dirt - clean	534797
8230	3/5/2013	394041		Check oil level in transmission - top up if required	534797
8230	3/5/2013	394041		Check and clean cartridge in dry type air cleaner	534797
8230	3/5/2013	394041		Replace pre and main fuel filters	534797
8230	3/5/2013	394041		Replace air dryer canister clean silence and drain reservoir	534797
8230	3/5/2013	394041		Replace angle drive oil	534797
8230	3/5/2013	394041		Test coolant level - top up if required to equate to 37C frost protection	534797
8230	3/5/2013	394041		Replace power steering filter and check level (Replace oil if required)	534797
8230	3/5/2013	394041		Replace final drive oil	534797
8230	3/5/2013	394597	ROAD SAFETY INSPECTIONS	Creditor #ROAD01 Road Safety Inspections P/O #:G120822 Receiving #:121889 Date :2013-03-05	538233
8230	3/5/2013	395357	WORNFLAT - POS 56 - 11 R22.5	Creditor #BEA001 BEAUREPAIRES P/O #G121100 Receiving #:121890 Date :2013-03-05 REPAIR OR REPLACE WITH NEW	538233
8230	3/5/2013		Imported Service History	Imported Service History	534797
8230	3/5/2013	395719	HALDEX COIL KIT 0500LE	Re-kit Air Cyclone Separator	538043
8230	3/5/2013	395719	DRAIN VALVE KIT BOTTOM	Coil Kit	538043
8230	3/5/2013	395719	HALDEX COIL BASE OIL SEPERATOR	Valve Kit	538043
8230	3/5/2013	395719	CYCLONE CONDENSER VALVE KIT	Base	538043
8230	3/5/2013	395719		Condenser Valve Kit.	538043
8230	3/4/2013	395632	Whls & Tyres - Replace 56 tyres	Re-kit Air Cyclone Separator	538043
8230	3/4/2013	395357	Whls & Tyres - Replace tyre pos 56 - worn	Replaced & tensioned nuts	538043
8230	3/3/2013	394597	Annual Licence	Replaced	535478
8230	2/27/2013	394817	Passenger Doors Front door wont open from inside	RWC 818494 - Passed	536266
8230	2/21/2013	394044		Adjusted	534797
8230	2/21/2013	394044		Perform & Complete PTSV Bus Safety Inspection	534797
8230	2/21/2013	394044		Tension Wheel Nuts	534797
8230	2/21/2013	394044		Perform & Complete PTSV Bus Safety Inspection	534797
8230	2/21/2013	394041	RPM BORATE EP LUBE 220	Rear Axle Lube	534797
8230	2/21/2013	394041	FUEL FILTER MERC 0500LE		534797
8230	2/21/2013	394041	FUEL FILTER 0500LE		534797
8230	2/21/2013	394041	AIR DRYER CANISTER VOLVO+ NL202		534797
8230	2/21/2013	394041	POWER STEERING FILTER VOLVO		534797
8230	2/21/2013	394194	Complete Campaign 16/12 as required		534969
8230	2/19/2013	390754	ELECTRICAL REPAIR - NON STARTI	Alloy wheels	534021
8230	2/4/2013	391717	Elec & Light - Bus wont start	Creditor #BWE001 BWERE ELECTRICS P/O #G119531 Receiving #:121161 Date :2013-02-19	530711
8230	1/30/2013	390103	ROCKER SWITCH THERMOKING	Jump started by Tullamarine on 25/01 then replaced batteries supplied by GBS on 26/01	529026
8230	1/29/2013	390754	Elec & Light - Battery Flat - at Tullamarine	repaired by Ben Were	528539
8230	1/23/2013	390255	Passenger Doors - Check front door	Checked and adjusted sensitive edge	527985
8230	1/22/2013	390103	Air Cond Switch; Wiring; Relays; Sensors A/C switch is mis	Checked out a/c replace switch fit test box on and tested OK	527985
8230	1/22/2013	389846	GLOBE INDICATOR 24V-18W SINGLE CONTACT		527815
8230	1/22/2013	389907	drivers door wont open	COMPLETED	527815
8230	1/21/2013	389846	Elec & Light - Replace NS indicator globe	Replaced	527815
8230	1/20/2013	389722	Elec & Light - Bus wont start	Jump started	527403
8230	1/17/2013	389184	MERC RADIATOR MOUNT		526142
8230	1/17/2013	389049	AIR FILTER MERC 0500LE		526142
8230	1/16/2013	389188	Passenger Doors - Adjust door sensors	Adjusted front & rear	526142
8230	1/16/2013	389184	Eng Cool - Replace radiator mount	Replaced	526142
8230	1/16/2013	389049		A Service	525940
8230	1/16/2013	389049		A Service	525940
8230	1/16/2013	389049		Clean A/C filter	525940
8230	1/16/2013	389049		Tension Wheel Nuts To OEM Specification	525940
8230	1/16/2013	389049		Grease AC Compressor Clutch Bearing	525940

8230	1/9/2013	388033	switch broken-unable to operate	Tullamarine found loose connection on relay tightened tested OK 03/01/13	523841
8230	1/8/2013	387961	Elec & Light - Bus wont start	Jump started	523841
8230	1/7/2013	387747	Passenger Doors - Tighten and fit missing bolts to front do	Replaced & secured	523626
8230	1/7/2013	387708	Eng Cool - Check coolant leak	Repaired & Topped up	523626
8230	1/5/2013	387603	Eng Cool - Add coolant	Added	523196
8230	1/2/2013	387172	Breakdown - Carrum Downs - OUT 12.15 pm BACK 2.15 pm - Fron	C/O 8390. Temp fix return to depot and adjusted front door	522551
8230	#####	386405	WATER PUMP WITH GASKETS MERCEDES BENZ 0500LE		521261
8230	#####	386405	water pump is leaking	Replaced & topped up coolant	521261
8230	#####	386405	RADIATOR TOP MOUNT 0500		521261
8230	#####	386405	water pump is leaking	Topped up coolant and took out the old radiator mount fitted new one & r/tested	521261
8230	#####	386339	RAD CAP MERC BENZ SIGHT GLASS SIDE		521261
8230	#####	386496	Eng Cool - Add coolant	Added	521261
8230	#####	384140	AIR CON REFRIDGERANT		520809
8230	#####	386339	Breakdown - Springvale Rd Springvale - OUT 4.30 pm BACK 7.3	Van 619. Returned to depot and got radiator cap replaced topped up coolant & returned	520809
8230	#####	384140	air con ineffective	Compressor very oily removed & replaced unloader O rings	516823
8230	#####	386196	CAMPAIGN - Inspect front chassis cracks	no defects found	520810
8230	#####	385989	Passenger Doors - front door not closing properly	Readjusted by Tullamarine 18/12/12	520809
8230	12/7/2012	384365	Passenger Doors - Front door wont close	Adjusted	517500
8230	12/7/2012	383990	SENSITIVE EDGE DOOR SWITCH		516823
8230	12/6/2012	384140	air con ineffective	Checked a/c n/w fault code 10 high pressure cut out	516823
8230	12/6/2012	383990	Passenger Doors Not Operating Front door not working	Subu done job not Phil	516702
8230	12/6/2012	383990	Passenger Doors Not Operating Front door not working	adjusted	516702
8230	12/3/2012	383338	FLOOR HATCH SCREWS		515480
8230	12/3/2012	383636	Brakes/Road test and check for brake problem	R/tested OK	515984
8230	12/3/2012	383142	AIR LINE FITTING KIT 0500LE AIR DRYER 16MM		515480
8230	12/3/2012	383142	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		515480
8230	12/1/2012	383250		Perform & Complete PTSV Bus Safety Inspection	515480
8230	12/1/2012	383250		Tension Wheel Nuts	515480
8230	12/1/2012	383250		Perform & Complete PTSV Bus Safety Inspection	515480
8230	#####	383370	Engine - Steamclean engine	Cleaned	515738
8230	#####	383338	Body & Acc - Replace 2 broken engine cover mounts	Replaced	515738
8230	#####	383142	MODULATION VALVE	Creditor #MUL001 MULTISPARES LTD P/O #G116723 Receiving #:117843 Date :2012-11-30	515738
8230	#####	383142	Air System - Check for air leak	Subu done job not Phil	515480
8230	#####	383142	Air System - Check for air leak	Checked rear axle modulator valve faulty removed new valve fitted air line O ring kit changed all fault code cleared r/tested OK	515480
8230	#####	383139	Breakdown - Springvale Rd Springvale - OUT 4.30 pm BACK 6.3	Van 619. Checked bus & return (replaced rear relay valve)	515480
8230	#####	383142	Air System - Check for air leak	Leaking from rear valve or rear boosters	515480
8230	#####	381849	Test and repair security syste	Creditor #LOND01 LONSDALE ST ELECTRICS P/O #G116846 Receiving #:117561 Date :2012-11-26	514622
8230	#####	381849	Security - Test and repair security system	Adjust date and time - test ok	512315
8230	#####	380007	TINT WINDSCREEN	Creditor #GLA003 GLASSPRO MELBOURNE PTY.LTD. P/O #G116289 Receiving #:117301 Date :2012-11-20	512315
8230	#####	381479	Mechanic entered - Passenger Doors Not Operating	adjust f/door	510895
8230	#####	381086	Security - Check security system	Adjust date time and turn off day light saving - OK	510895
8230	#####	381308	LED FRONT POSITION MARKER LIGHT		511151
8230	#####	381308	Elec & Light - Replace both plate LEDs	Replaced	511151
8230	#####	380666	AIR LINE FITTING KIT 0500LE AIR DRYER 16MM		511151
8230	#####	380666	Steering Steering Whl - replace str wheel	FITTED NEW	510895
8230	#####	380666	Eng Cool - Check for coolant leak		510895
8230	#####	380666	Eng Cool - Cooling pipe bracket broken next to fuel filter		510895
8230	#####	381086	Test security system	Creditor #LOND01 LONSDALE ST ELECTRICS P/O #G116599 Receiving #:117079 Date :2012-11-15	510895
8230	#####	380666	Air System - Replace air line O ring on g/box	Replaced	510895
8230	#####	380655	CYCLONE PACK (SEPARATOR) MERC COMPLETE UNIT		510895
8230	#####	380655	AIR LINE FITTING KIT 0500LE AIR DRYER 16MM		510895
8230	#####	380655	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		510895
8230	#####	380655	CIRCUIT PROTECTION VALVE	Creditor #MUL001 MULTISPARES LTD P/O #G116632 Receiving #:117110 Date :2012-11-15	511151
8230	#####	380655	CIRCUIT PROTECTION VALVE	Creditor #MUL001 MULTISPARES LTD P/O #G116447 Receiving #:117109 Date :2012-11-15	511151
8230	#####	380655	CIRCUIT PROTECTION VALVE	Creditor #MUL001 MULTISPARES LTD P/O #G116447 Receiving #:117085 Date :2012-11-15	511151
8230	#####	380655	EXHAUST BRAKE SOLENOID 0500	Creditor #MUL001 MULTISPARES LTD P/O #G116561 Receiving #:117006 Date :2012-11-14	510895
8230	#####	380655	Air System - Air compressor need to be changed 6Way valve 1	Changed 6way valve air separator exhaust brake solenoid valve 4 x air line O ring cleaned and fitted air pipe	510895
8230	#####	380655	CIRCUIT PROTECTION VALVE	Creditor #MUL001 MULTISPARES LTD P/O #G116478 Receiving #:116988 Date :2012-11-14	510895
8230	#####	380655	CIRCUIT PROTECTION VALVE	Creditor #MUL001 MULTISPARES LTD P/O #G116447 Receiving #:116940 Date :2012-11-13	510895
8230	#####	380655	AIR LINE FITTING KIT 0500LE AIR DRYER(22mm)		510895
8230	#####	380667		Clean A/C filter	510895
8230	#####	380667		Grease AC Compressor Clutch Bearing	510895
8230	#####	380667		Tension Wheel Nuts To OEM Specification done	510895
8230	#####	380667		A Service done	510895
8230	#####	380655	Air System - Air compressor need to be changed 6Way valve 1	Went to KSB checked and filled coolant bought bus back to GBS fitted air line kit ordered parts for 6way valve	510895
8230	11/8/2012	380019	RESEAL SIDE GLASS	Creditor #ELU001 ELITE WINDSCREENS P/O #G116236 Receiving #:116818 Date :2012-11-08	510196
8230	11/7/2012	380007	Vandalism - Replace 8mm safety film to drivers window	Replaced	509777
8230	11/7/2012	380019	Body & Acc Windows - RESEAL SIDE GLASS	ELITE - 07/11/2012	509777
8230	11/5/2012	380069	Eng Cool - Add coolant	Added	509777
8230	11/4/2012	379873	Eng Cool - Add coolant	Added	509326
8230	#####	374209	Side wall damage - Scrap	Creditor #BEA001 BEAUREPARES P/O #G114443 Receiving #:116274 Date :2012-10-26	505909
8230	#####	374209	Side wall damage - Scrap	Creditor #BEA001 BEAUREPARES P/O #G114443 Receiving #:116263 Date :2012-10-26	505909
8230	#####	378139	GLOBE INST 24V 2W		505007
8230	#####	378139	Elec & Light - Replace dash light globe	Replaced	505007
8230	#####	377720	Ops Entered - Fault - Desto Signs - Route: 902 - Eltham Ra	Checked OK	504246
8230	#####	377598	Eng Cool - Coolant leak	Found radiator cap damaged got one from GBS replaced & topped up coolant	504246
8230	#####	376839	Eng Cool - Add coolant	Added	502865
8230	#####	375939	BLADE WIPER 1MTR		500755
8230	10/9/2012	375939	Wipers & Washers - Replace both wiper blades	AReplaced	500755
8230	10/9/2012	375951	Air Cond - Clean a/c filters	Cleaned	500755
8230	10/9/2012	375946	Eng Cool - Add coolant	Tightened hoses and added	500755
8230	10/9/2012	375801	HOSE ENG TO G/BOX COOLER MERC 0500LE		500640
8230	10/8/2012	375801	Breakdown - Doncaster Shopping Centre - OUT 4.00 pm BACK 6.	Van 619. Fitted new coolant hose (thermostat housing) topped up coolant	500640
8230	10/7/2012	375608	Eng Cool - Add coolant	Added	500196
8230	10/6/2012	375598	Eng Cool - Secure coolant hose clamps	Secured	500196
8230	10/4/2012	364843	BUMPER BOLT SPECIAL		499652
8230	10/4/2012	364843	PLASTIC WASHER		499652
8230	10/4/2012	364843	WHEEL ARCH BRUSH 2.5MTR		499652
8230	10/4/2012	364843	PLASTIC WASHER		499652
8230	9/27/2012	370447	Scrap		497760
8230	9/27/2012	374552	No outside display on destination board	Creditor #BEA001 BEAUREPARES P/O #G113198 Receiving #:114882 Date :2012-09-27	498211
				Repaired by Mobitec	

8230	7/25/2012	364843	UNREPORTED - Repair front b/bar	Prep work ready for top coat	481298
8230	7/25/2012	364843	UNREPORTED - Repair front b/bar	Prep work ready for top coat	481298
8230	7/24/2012	365169	A/C BELT 0500 BENZ		481298
8230	7/24/2012	364843	HINGE DRIVERS COMPARTMENT		481298
8230	7/24/2012	364843	UNREPORTED - Repair front b/bar	Prep work repair front bar irons	481298
8230	7/23/2012	365169	Elec & Light - Replace belts	Replaced	481298
8230	7/23/2012	365117	Comm Equip/2 W/AR RADII/ DOES NOT WORK REPORTED BY L.COOL	Checked OK	481298
8230	7/23/2012	364843	Body & Acc - Replace interior decals - priority seating	Replaced	481298
8230	7/23/2012	364843	Body & Acc - Repair & paint till stand	Remove repair refit & painted	481298
8230	7/23/2012	364843	Body & Acc - Replace drivers compartment door hinges	Replaced hinges and adjusted lock catch	481298
8230	7/23/2012	364843	Accident Damaged # 35295 Repair n/s. lower body panels pol	Removed repaired refit NS 7	481298
8230	7/23/2012	364833		A Service	481298
8230	7/23/2012	364833		A Service	481298
8230	7/23/2012	364833		Clean A/C filter	481298
8230	7/23/2012	364833		Grease AC Compressor Clutch Bearing	481298
8230	7/23/2012	364833		Tension Wheel Nuts To OEM Specification	481298
8230	7/19/2012	364720	AMBER REFLECTOR SIDE MOUNT	replaced	480974
8230	7/19/2012	364720	Body & Acc replace amber reflector	replaced	480974
8230	7/15/2012	364005	Suspension Replace front sway bar link both side	Replaced	479611
8230	7/15/2012	364007	Brakes Replace front brake pads	replaced	479611
8230	7/12/2012	363389	Whis & Tyres - Replace tyre pos 1 - puncture	Replaced	478426
8230	7/11/2012	363422	Breakdown - Stud Park Shopping Centre - OUT 10.25 am BACK 1	Van 619. Assisted to change tyre	478426
8230	7/11/2012	363422	Breakdown - Stud Park Shopping Centre - OUT 10.25 am BACK 1	Van 619. Changed front left wheel & tensioned	478426
8230	7/10/2012	362516	Eng Cool/Water pump leaks	Checked OK servicable	477629
8230	7/10/2012	362516	Ops Entered - Fault - Brakes Hand Brake - Route: - Arrive	Checked OK	477629
8230	7/9/2012	362520	SWAY BAR DROP ARM R/H	Creditor #MUL001 MULTISPARES LTD P/O #G110617 Receiving #:111078 Date :2012-07-09	477864
8230	7/9/2012	362520	SWAY BAR DROP ARM L/H	Creditor #MUL001 MULTISPARES LTD P/O #G110617 Receiving #:111078 Date :2012-07-09	477864
8230	7/9/2012	363047	Passenger Doors - Check rear door	Checked OK	477864
8230	7/9/2012	362516	SENSITIVE EDGE DOOR SWITCH		477629
8230	7/9/2012	362516	BRAKE+ CLUTCH PEDAL PAD 0500LE		477629
8230	7/7/2012	362899	Passenger Doors - Rear door wont close	Checked and replaced sensitive switch also under bump switch leak removed from 8235 and fitted to 8230 no part in store also replaced door button switch	477629
8230	7/7/2012	362893	Elec & Light - Bus wont start	Jump started	477629
8230	7/6/2012	362519	ROCKER COVER GASKET 0500LE		477629
8230	7/6/2012	362519	Service	Adjust Tappets	477629
8230	7/6/2012	362520		Tension Wheel Nuts	477629
8230	7/6/2012	362520		Perform & Complete PTSV Bus Safety Inspection	477629
8230	7/6/2012	362520	Mechanic entered - Suspension Noisy		477629
8230	7/6/2012	362516	Engine - Steamclean bus	Cleaned	477629
8230	7/6/2012	362516	Engine - Steamclean engine	Cleaned to do tappets	477629
8230	7/6/2012	362516	NARVA 24V REVERSING BUZZER		477629
8230	7/6/2012	362516	Elec & Light - Replace reverse buzzer	Replaced	477629
8230	7/6/2012	362516	Eng Cool - Cooling pipe bracket broken next to fuel filter		477629
8230	7/6/2012	362516	Body & Acc - OR w/arch brush missing	Replaced	477629
8230	7/6/2012	362516	Body & Acc - OSR w/arch brush strip missing	Replaced	477629
8230	7/6/2012	362516	Body & Acc - Replace w/arch rubber & brush - OS rear	replaced	477629
8230	7/6/2012	362516	Body & Acc - Replace yellow strip inside the bus	Replaced	477629
8230	7/6/2012	362516	SNAP ON SILENCER A/DRYER		477629
8230	7/6/2012	362516	Air System - Replace air dryer silencer	Replaced	477629
8230	7/2/2012	361794	Body & Acc/racked w/screenbus is in row 2-JOP	sent to Elite - 02/07/2012	476541
8230	6/13/2012	359308	Eng Cool - Add coolant	Added	472091
8230	5/29/2012	356842		Service T - Replace Transmission Oil & Filter	467766
8230	5/29/2012	356842	FILTER TRANSMISSION ZF 4139-298-038E39HD119	ZF Transmission Filter	467766
8230	5/29/2012	356842		Bus Safety Inspection	467766
8230	5/29/2012	356842	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	467766
8230	5/29/2012	356842		Service T - Replace Transmission Oil & Filter	467766
8230	5/24/2012	356239		A Service	465887
8230	5/24/2012	356239		A Service	465887
8230	5/24/2012	356239		Clean A/C filter	465887
8230	5/24/2012	356239		Grease AC Compressor Clutch Bearing	465887
8230	5/24/2012	356239		Tension Wheel Nuts To OEM Specification	465887
8230	5/21/2012	355929	Passenger Doors Adjust front ddoor	Adjusted	464946
8230	5/7/2012	353668		Tension Wheel Nuts	459011
8230	5/7/2012	353668	WEDGE GLOBE INSTRUMENT 24V 3W		459011
8230	5/7/2012	353668		Perform & Complete PTSV Bus Safety Inspection	459011
8230	5/7/2012	353668		Perform & Complete PTSV Bus Safety Inspection	459011
8230	5/6/2012	352586	Ventura decals to be supplied fitted to SmartBus		458375
8230	5/4/2012	353894	Breakdown In Stud RD. Dandenong Replace main belt - use B.		459272
8230	5/3/2012	353182	GLOBE H1 24V 70W		459011
8230	5/2/2012	353182	Elec & Light - Headlight out	Fitted new globe	458971
8230	5/2/2012	353195	Eng Cool - Add coolant	Added	458971
8230	5/1/2012	353209	Eng Cool - Add coolant	Added	458971
8230	4/27/2012	352488	Air Cond - Clean a/c filters	Cleaned	458375
8230	4/26/2012	352338	Body & Acc - Fit w/arch brush	Refitted	457923
8230	4/24/2012	351605	Diff & Hubs N/S rear hub seal leaks	R/left side caliper tappet & boot changed	457407
8230	4/24/2012	351605	DISC PAD SET SCANIA MB0500		457407
8230	4/24/2012	351605	BRAKE CALIPER TAPPET KIT 0500(A0004204982)		457407
8230	4/23/2012	351605	Diff & Hubs N/S rear hub seal leaks	Replace NSR hubseal NF	457407
8230	4/23/2012	351605	Diff & Hubs N/S rear hub seal leaks	Removed caliper rotor oil seal sleeve changed new seal fitted hub fitted nut torque given drive shaft fitted caliper boot removed	457407
8230	4/23/2012	351605	Diff & Hubs N/S rear hub seal leaks		457407
8230	4/23/2012	351601	zz105D/Hff & Hubs		457407
8230	4/20/2012	348021	ROAD SAFETY INSPECTIONS	Creditor #ROAD01 Road Safety Inspections P/O #G106085 Receiving #:107433 Date :2012-04-20	457407
8230	4/19/2012	351350	Vandalism - Clean graffiti from NSR	Cleaned	457026
8230	4/7/2012	349893	Eng Cool - Add coolant	Added	452755
8230	4/6/2012	349848	Diff & Hubs - NSR hub oil leak	S/cleaned checked OK	452755
8230	4/1/2012	348021	Annual Licence	- RWC 931470 - Passed	449825
8230	3/27/2012	342680	DISC PAD SET SCANIA MB0500		449825
8230	3/27/2012	348161		Replace Engine Oil Breather Kit	449825
8230	3/27/2012	348161	ENGINE OIL BREATHER KIT 0500LE		449825
8230	3/27/2012	348161		Grease AC Compressor Clutch Bearing	449825
8230	3/27/2012	348161	AIR FILTER MERC 0500LE		449825
8230	3/27/2012	348161		A Service & Bus Safety Inspection	449825

8230	3/27/2012	348161		D-Service & Bus Safety Inspection	
8230	3/27/2012	348161	OIL FILTER 1725+0500LE		449825
8230	3/27/2012	348161	ENGINE OIL DELO 400LE 15W40		449825
8230	3/27/2012	348161		Tension Wheel Nuts to Spec	449825
8230	3/27/2012	348161		A Service	449825
8230	3/27/2012	348161		Clean A/C filter	449825
8230	3/27/2012	348161		Grease AC Compressor Clutch Bearing	449825
8230	3/27/2012	348161		Tension Wheel Nuts To OEM Specification	449825
8230	3/21/2012	347457	Eng Cool - Coolant leaking badly from header tank cap	Checked cap for perished rubber seals all appeared OK left bus running for a period no apparent signs of a leak	448900
8230	3/20/2012	347203	Eng Cool - Add coolant	Added	448017
8230	3/20/2012	347173	Air System - Air not building up	Repaired by Tullamarine 08/03/12 = \$408.91 in gst	448017
8230	3/19/2012	346670	Whls & Tyres - Replace tyre 39 - sidewall damage	Discarded	446235
8230	3/19/2012	346074	Diff & Hubs Leaking - check rear axle oil leak	Rear LHS hub oil leaking tracing problem top up oil breather cleaning and steam washing done	446235
8230	3/15/2012	346348		Inspect bus for RSI	446235
8230	3/15/2012	346348	RPM BORATE EP LUBE 220	Rear Axle Lube	446235
8230	3/15/2012	346348		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	446235
8230	3/15/2012	346348		Inspect radiator and charge air cooler for dirt - clean	446235
8230	3/15/2012	346348		Check oil level in transmission - top up if required	446235
8230	3/15/2012	346348		Check and clean cartridge in dry type air cleaner	446235
8230	3/15/2012	346348		Replace pre and main fuel filters	446235
8230	3/15/2012	346348		Replace air dryer canister clean silence and drain reservoir	446235
8230	3/15/2012	346348		Replace angle drive oil	446235
8230	3/15/2012	346348		Test coolant level - top up if required to equate to 37C frost protection	446235
8230	3/15/2012	346348		Replace power steering filter and check level (Replace oil if required)	446235
8230	3/15/2012	346348			446235
8230	3/15/2012	346348		Replace final drive oil	446235
8230	3/15/2012	346348		Adjust tappets	446235
8230	3/15/2012	346519	Air Cond - Clean a/c filters	Cleaned	446245
8230	3/15/2012	346807	Eng Cool - Add coolant	Added	446245
8230	3/15/2012	346347		Re-kit Air Cyclone Separator	446235
8230	3/15/2012	346347		Water Separator Kit	446235
8230	3/15/2012	346347		Base	446235
8230	3/15/2012	346347		Valve Kit	446235
8230	3/15/2012	346347		Coil Kit	446235
8230	3/15/2012	346347		Inspected	446235
8230	3/14/2012	345973	Annual Body Inspection	Creditor #BEA001 BEAUREPARES P/O #K105381 Receiving #:105922 Date :2012-03-13 Replace with new	446235
8230	3/13/2012	345479	BALD - New 11.00R 22.5 alloy -	Creditor #BEA001 BEAUREPARES P/O #G104661 Receiving #:105841 Date :2012-03-09	445795
8230	3/9/2012	343090	Side wall damage	towed to GBS - 09/03/2012	445795
8230	3/9/2012	345571	Breakdown - 8.30am at Tullamarine B/L - towed to GBS by Ass	Removed from 8261 and fitted to 8230	445814
8230	3/9/2012	346050	Air System - Replace air dryer	Replaced	445430
8230	3/8/2012	345479	Whls & Tyres - Replace 5 and 6 worn	Replaced	445430
8230	3/7/2012	345765	Whls & Tyres - Replace OSR tyres	Disposed	445430
8230	2/29/2012	343090	Whls & Tyres - Sidewall damage - pos 8	Added	443105
8230	2/29/2012	344253	Eng Cool - Add coolant	Added	443105
8230	2/27/2012	343749	Gearbox - Transmission coolant pipe tap leak	Reseal pipe union at tap resealed banjo bolt on top of coolant pipe	443105
8230	2/27/2012	342680	Diff & Hubs - NSR hub oil leaking	repaired	443105
8230	2/22/2012	342680	REAR HUB SEAL KIT 0500LE		443105
8230	2/22/2012	342680	Diff & Hubs - Observed oil leak at hub bearings - NSR	Check for oil leak	443105
8230	2/21/2012	342680	Heat & Demist - Heater n/w	Checked OK	443105
8230	2/21/2012	342680	Diff & Hubs - Excess hub oil leak rear N/side	repaired	443105
8230	2/21/2012	342700	Body & Acc - Apply tint to top of windscreen	Applied = \$ 90 ex gst	443105
8230	2/20/2012	341405	THEIRRY - Assisted		440847
8230	2/20/2012	341405		Perform & Complete PTSV Bus Safety Inspection	440847
8230	2/20/2012	341405		Tension Wheel Nuts	440847
8230	2/19/2012	342700	WINDOW FILM FITTING	Creditor #GLA003 GLASSPRO MELBOURNE PTY.LTD. P/O #G104539 Receiving #:105210 Date :2012-02-23	443105
8230	2/16/2012	342085	Elec & Light - Faulty ignition switch loose contact at times	Changed ind stalk & tightened wiper bolts	442075
8230	2/16/2012	342085	INDICATOR ARM 0500LE		442075
8230	2/16/2012	342075	Replace windscreen	Creditor #ELI001 ELITE WINDSCREENS P/O #G104368 Receiving #:105012 Date :2012-02-17	442727
8230	2/16/2012	342075	Body & Acc Replace chips broken windscrrin	Replaced by Elite W.scrin	442075
8230	2/15/2012	342146	Eng Cool - Add coolant	Added	442075
8230	2/14/2012	342062	Body & Acc - When bus drive uneven place LH middle makes me	Checked found seat noisy lubricated	442075
8230	2/13/2012	342085	Elec & Light - Faulty ignition switch loose contact at time	Replaced indicator switch	442029
8230	2/9/2012	341255	Eng Cool - add coolant	Added	440847
8230	2/7/2012	340721		A Service	439452
8230	2/7/2012	340721		Clean A/C filter	439452
8230	2/7/2012	340721		Tension Wheel Nuts To OEM Specification	439452
8230	2/7/2012	340721		Grease AC Compressor Clutch Bearing	439452
8230	2/7/2012	340721		A Service	439452
8230	2/1/2012	335976	Air Cond - Clean a/c filters	Cleaned	437900
8230	1/20/2012	338753	Air Cond - Clean a/c filter	Cleaned	434386
8230	1/11/2012	336618	POS 2 11R NEW	Creditor #BEA001 BEAUREPARES P/O #K102783 Receiving #:103624 Date :2012-01-11	430862
8230	1/11/2012	336617	POS 1 11R NEW	Creditor #BEA001 BEAUREPARES P/O #K102783 Receiving #:103624 Date :2012-01-11	430862
8230	1/10/2012	336618	Whls & Tyres - Replace tyre pos 2 - low tread	Replaced	430411
8230	1/7/2012	336617	Whls & Tyres - Replace tyre pos 2	Replaced	429989
8230	#####	335455	Elec & Light - Replace OSR reflector	Replaced	427094
8230	#####	333538	POS 3 11R NEW	Creditor #BEA001 BEAUREPARES P/O #K101864 Receiving #:102764 Date :2011-12-16	424557
8230	#####	333538	Whls & Tyres - Replace tyre pos 3 - low and uneven tread we	Replaced	423550
8230	#####	333530	Whls & Tyres - Replace OS rear tyres	Replaced & checked all air pressures	423550
8230	#####	332568	BALD POS 1 11R NEW	Creditor #BEA001 BEAUREPARES P/O #G101478 Receiving #:102508 Date :2011-12-13	423097
8230	#####	333395	Passenger Doors U/S	Checked OK	423097
8230	#####	333369	Eng Cool - Coolant leak	Checked by Dysons 17/11/11 s/cleaned & topped up = \$81.11 ex g.s.t	423097
8230	#####	333206	Diff & Hubs - NR hub sweat	Found oil leak NS rear hub checked underneath no any oil s/clean hub and send on road	421645
8230	12/9/2011	333036		Tension Wheel Nuts	422337
8230	12/9/2011	333036		Perform & Complete PTSV Bus Safety Inspection	422337
8230	12/9/2011	333036		Perform & Complete PTSV Bus Safety Inspection	422337
8230	12/9/2011	333053	Random Vehicle Audit	Inspected	422337
8230	12/9/2011	333037		A Service	422337
8230	12/9/2011	333037		Clean A/C filter	422337
8230	12/9/2011	333037		Tension Wheel Nuts To OEM Specification	422337

8230	12/9/2011	333037		Grease AC Compressor Clutch Bearing		422337
8230	12/7/2011	332752	Whls & Tyres - Replace tyre pos 1	Replaced No 1 tyre tensioned nuts checked pads OK slight leak on NS rear axle		421652
8230	12/7/2011	332752	Whls & Tyres - Replace tyre pos 1	Found that front brake pads are low and n/s hub seal leaking		421652
8230	12/7/2011	332568	Whls & Tyres - Replace tyre pos 1 - side wall damage	Replaced		421652
8230	12/7/2011	332751	Air Cond - Clean a/c filters	Cleaned		421652
8230	12/1/2011	332016	Elec & Light - Repair No plate light wiring	Repaired		419928
8230	#####	331670	Air Cond - Clean a/c filter	Cleaned		419098
8230	#####	329452	Elec & Light - Replace headlight globe	Replaced		414354
8230	#####	329359	Comm Equip - 2way radio n/w	Checked OK		414354
8230	#####	329359	Body & Acc - Mirror bent	Straightened		414354
8230	11/8/2011	328517	Eng Cool - Check for coolant leak	Found all hoses OK tightened clamps and added coolant		412816
8230	#####	326837	GLOBE INST 24V 2W			409737
8230	#####	326837	Elec & Light - Replace dash light globe	Replaced		409737
8230	#####	326851	Eng Cool - Add coolant	Added		409737
8230	#####	326760	Ops Entered - Fault - Eng Cool - Route: - Take a Smart bu	Drained coolant fit new hose top up coolant & r/test had to search for hose none in stock Kumar had a piece		409737
8230	#####	326525	CAMPAIGN - Install retro - reflector tape on rear engine ha	Installed by Attitude signs		409502
8230	#####	326360	Eng Cool - Add coolant	Added		409049
8230	#####	325502	Elec & Light - Focus NS headlight	Focused		407053
8230	#####	325502	Body & Acc - Straighten NS mirror	Straightened		407053
8230	#####	325502	Body & Acc - Tighten front door brush screws	Tightened		407053
8230	#####	324043	COMPRESSOR OIL AIR COV			406263
8230	#####	324043	FILTER DRIER THERMO KING			406263
8230	#####	324913	Body & Acc - Secure windscreen blind rod	Secured		405812
8230	#####	321401	CYCLONE PACK (SEPARATOR) MERC COMPLETE UNIT			404692
8230	#####	324108	Air Cond - Clean a/c filters	Cleaned		404692
8230	#####	324000	Air Cond not working	Repaired		404672
8230	#####	324113	Eng Cool - Add coolant	Added		404692
8230	#####	321401	Removed & replaced	Re-kit Air Cyclone Separator		404672
8230	#####	324043		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation		404672
8230	#####	324043		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension		404672
8230	#####	324043		EVAPORATOR AREA: Clean evaporator coils; check carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills		404672
8230	#####	324043		REFRIGERATION FILTER DRIER: Replace filter dryer; check pump operation;		404672
8230	#####	324043		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose		404672
8230	#####	324043		DRIVE PULLEYS: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear		404672
8230	#####	324043		DRIVE PULLEYS: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;		404672
8230	#####	324043		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;		404672
8230	#####	324043		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)		404672
8230	#####	324043		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media		404672
8230	#####	324000	Air Cond - No a/c at all no power to it	Locate and repair elec fault		404672
8230	#####	323941	CAMPAIGN - Fit covers on retarder switches in electrical cen	Fitted		404672
8230	#####	323999		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension		404672
8230	#####	323999	Ref to w/o 324000	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills		404672
8230	#####	323999		REFRIGERATION FILTER DRIER: Replace filter dryer; check pump operation;		404672
8230	#####	323999		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose		404672
8230	#####	323999		DRIVE PULLEYS: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear		404672
8230	#####	323999		DRIVE PULLEYS: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;		404672
8230	#####	323999		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;		404672
8230	#####	323999		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)		404672
8230	#####	323999		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media		404672
8230	10/6/2011	323058	HOSE ENG TO G/BOX COOLER MERC 0500LE			403593
8230	10/5/2011	323191		Replace Engine Oil Breather Kit		403544
8230	10/5/2011	323191	ENGINE OIL BREATHER KIT 0500LE			403544
8230	10/5/2011	323191		Grease AC Compressor Clutch Bearing		403544
8230	10/5/2011	323191	AIR FILTER MERC 0500LE			403544
8230	10/5/2011	323191	OIL FILTER 1725-0500LE			403544
8230	10/5/2011	323191	ENGINE OIL DELO 400LE 15W40			403544
8230	10/5/2011	323191		Tension Wheel Nuts to Spec		403544
8230	10/5/2011	323191		A Service & Bus Safety Inspection		403544
8230	10/5/2011	323191		D-Service & Bus Safety Inspection		403544
8230	10/5/2011	323191		Clean A/C filter		403544
8230	10/5/2011	323191		Grease AC Compressor Clutch Bearing		403544
8230	10/5/2011	323191		Tension Wheel Nuts To OEM Specification		403544
8230	10/5/2011	323191		A Service		403544
8230	10/3/2011	322783	Eng Cool - add coolant	Added		403043
8230	10/3/2011	323058	Breakdown - Wellington Rd Brandon Park - OUT 4.30 pm BACK 6	Ass Alan		403093
8230	10/3/2011	323058	Breakdown - Wellington Rd Brandon Park - OUT 4.30 pm BACK 6	Used van 619. Found coolant hose burst fitted new and topped up coolant		403093
8230	9/27/2011	321384		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension		400152
8230	9/27/2011	321384		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills		400152
8230	9/27/2011	321384		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray		400152
8230	9/27/2011	321384		REFRIGERATION FILTER DRIER: Replace filter dryer; check pump operation;		400152
8230	9/27/2011	321384		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose		400152
8230	9/27/2011	321384		DRIVE PULLEYS: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear		400152
8230	9/27/2011	321384		DRIVE PULLEYS: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;		400152
8230	9/27/2011	321384		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;		400152
8230	9/27/2011	321384		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)		400152
8230	9/27/2011	321384		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media		400152
8230	9/27/2011	321384		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation		400152
8230	9/26/2011	321572	NARVA 24V REVERSING BUZZER			400152
8230	9/24/2011	321398		Perform & Complete PTSV Bus Safety Inspection		400152
8230	9/24/2011	321398		Perform & Complete PTSV Bus Safety Inspection		400152
8230	9/24/2011	321398		Tension Wheel Nuts		400152
8230	9/24/2011	321398		Perform & Complete PTSV Bus Safety Inspection		400152
8230	9/24/2011	321398		Perform & Complete PTSV Bus Safety Inspection		400152
8230	9/24/2011	321554	Suspension - Kniling operation not working	Checked OK		400445
8230	9/24/2011	321572	Elec & Light - Replace reverse buzzer	Replaced		400445
8230	9/24/2011	321554	Elec & Light - Raise up tilt switch u/s	Rectified		400445
8230	9/24/2011	321538	Fuel gauge defective	Checked OK		400445
8230	9/24/2011	321538	Body & Acc Seat belt jammed	Checked OK		400445
8230	9/23/2011	321339	SEAT BELT R/H			400152

8230	9/23/2011	321339	Body & Acc seat belt not working	Replace seat belt	400152
8230	9/21/2011	291687	check hand brake not holding i	Creditor #WHT001 WHITEHORSE TRUCKS P/O #:G98202 Receiving #:98994 Date :2011-09-21	399247
8230	9/9/2011	318771	DRAIN VALVE KIT BOTTOM		395567
8230	9/8/2011	318771	Water seperator rebuild finished		
8230	9/8/2011	318771	HALDEX CONDENSER KIT TOP(CYCLONE)		395567
8230	9/8/2011	318771	HALDEX COIL BASE OIL SEPARATOR		395567
8230	9/8/2011	318771	WATER SEPARATOR SCANIA+VOLVO+MB (HAL90364)		395567
8230	9/7/2011	318771	Water seperator rebuild not finished		
8230	8/29/2011	317010	Ticket Equip - Ticket machine broken	Given to smart bus co-ord	393139
8230	8/29/2011	316997	Eng Cool - Add coolant	Added	392698
8230	8/29/2011	316806	PRESSURE CAP 78AR 0405+0500LE		392698
8230	8/26/2011	316806	Eng Cool - Check for coolant leak	Cap faulty replaced new & r/tested	392698
8230	8/19/2011	313440	DOWN LIGHT	Creditor #VOL001 VOLGREN AUSTRALIA P/L P/O #:G95661 Receiving #:97714 Date :2011-08-19	390534
8230	8/19/2011	315333	BRAZILLIAN MIRROR L/H		390534
8230	8/19/2011	315333	Body & Acc Driver mirror broken	Replaced mirror	390534
8230	8/18/2011	303710	Replace Grenda decal x 4	Creditor #ATT001 ATTITUDE SIGNS P/O #:G93402 Receiving #:97648 Date :2011-08-18	390130
8230	8/17/2011	315052	Air Cond - Clean a/c filters	Cleaned	390130
8230	8/16/2011	312794	ACCUMULATOR RETARDER VALVE B12BLE		389688
8230	8/15/2011	312794	Brakes - Check for air leak	Ass Dulkhtr replace solenoid valve off accumulator on g/box	388921
8230	8/15/2011	312794	Brakes - Check for air leak	Changed retarder solenoid valve & r/tested	388921
8230	8/15/2011	312794	Brakes - Check for air leak	Changed front brake proportional valve with new air fitting change valve mounting bracket angle	388921
8230	8/15/2011	312794	PROPORTIONAL VALVE A0054297644	Creditor #WHT001 WHITEHORSE TRUCKS P/O #:G96114 Receiving #:97471 Date :2011-08-15	388921
8230	8/11/2011	312794	Brakes - Check for air leak	Replaced proportional valve but s/s part went to w/horse to check other parts they did not have part	388921
8230	8/10/2011	311691	POS 5-6 11R NEW FIT GBS TYRES	Creditor #BEA001 BEAUREPARES P/O #:G95879 Receiving #:97287 Date :2011-08-10	389442
8230	8/9/2011	313440	Replace down light on drivers locker with swivel down light	Replaced	389442
8230	8/8/2011	313237	AMBER REFLECTOR SIDE MOUNT		389442
8230	8/5/2011	313237	Body & Acc - Replace yellow strip on rear floor	Replaced	389442
8230	8/5/2011	313021	AIR FILTER MERC 0500LE		389442
8230	8/5/2011	313021		Clean A/C filter	389442
8230	8/5/2011	313021		Grease AC Compressor Clutch Bearing	389442
8230	8/5/2011	313021		Tension Wheel Nuts To OEM Specification	389442
8230	8/5/2011	313021		A Service	389442
8230	8/5/2011	313021		A Service	389442
8230	8/4/2011	312794	Brakes - Check for air leak	Removed front brake proportional valve but new valve air line fitting is different fixed old valve again	388921
8230	8/3/2011	312794	Brakes - Check for air leak	Took bus 8298 to KSB depot and returned with 8230. found front brake proportional valve leaking ordered parts refer 311691	388921
8230	8/1/2011	311894	Whls & Tyres Worn - No 5 tyre worn	replaced	388335
8230	7/28/2011	311691	replace worn tyre pos 5-6	Moved bus into w/shop replaced & tensioned w/nuts	388335
8230	7/28/2011	311972	Whls & Tyres - Replace tyres 56	Cleaned	388489
8230	7/28/2011	311863	Air Cond - Clean a/c filters	Job has been fixed	388335
8230	7/27/2011	311744	Body & Acc - Hinges back door came out	Repaired	387882
8230	7/26/2011	311725	Body & Acc - Repair rear door		383535
8230	7/13/2011	309440	SEAT BELT LEFT HAND	Replaced belt stalk & adjusted belt holder	383535
8230	7/12/2011	309440	DVR entered - Seat belt buckle broken	Repaired by Tullamarine	383489
8230	7/7/2011	308752	EL - Battery carrier stuck can't pull out		383489
8230	7/7/2011	308606	MALE ELBOW 6MM		383489
8230	7/7/2011	308606	CLIPPARD VALVE DOOR OPEN/CLOSE		383489
8230	7/7/2011	308606	VALVEBOTTOM DOOR SWITCH+REG/GREEN		383489
8230	7/6/2011	308606	Elec & Light - Replace front door emergency switch	Changed front door emergency switch outside door open switch and fixed air leak from front door air line	383489
8230	7/6/2011	308364	EL - Load test and check charge rate	new batts. fitted by Tullamarine Bus Lines	383489
8230	7/6/2011	308606	Brakes Hand Brake - Air leak h/brake wont engage	Checked parking brake relay valve 2 mnts ago parking brake n/w problem fixed from Whitehorse	383489
8230	7/6/2011	308360	BRK - park brake not holding (intermittently)	Sent to WhiteHorse - 06/07/2011 (refer W/O 91687 - P/O 89092	383489
8230	7/3/2011	308016	Bus wont start	Jump started by the batteries	382963
8230	7/2/2011	307981	Bus wont start	Jump started	382551
8230	7/1/2011	307776	Clean a/c filters	Cleaned	382134
8230	7/1/2011	307791	Bus wont start	Jump started & overhauled idler pulley	382134
8230	7/1/2011	307791	Bus wont start	Jump started	382134
8230	6/30/2011	307568		Tension wheel nuts	381536
8230	6/30/2011	307568		Perform & Complete PTVS Bus Safety Inspection	381536
8230	6/30/2011	307583	PD - Rear door faulty	Repaired door	381536
8230	6/22/2011	306184	BR - Handbrake needs adjustment	Replaced relay valve	378506
8230	6/20/2011	306020	PD - Back door playing up sometimes	Checked works OK	378506
8230	6/17/2011	305850	Secure roof aerial	Fixed aerial	378506
8230	6/13/2011	305034	Bus wont start	Jump started	378055
8230	6/8/2011	303732	COMM - Intermittent reception on 2way radio	Being checked by Sim com	374792
8230	6/8/2011	304383		Clean A/C filter	374792
8230	6/8/2011	304383		Grease AC Compressor Clutch Bearing	374792
8230	6/8/2011	304383		A Service	374792
8230	6/8/2011	304383		Tension Wheel Nuts To OEM Specification	374792
8230	6/8/2011	304383		A Service	374792
8230	6/3/2011	303710	Replace Grenda decals x 4	Replaced	374792
8230	5/30/2011	302951	AIR REGULATOR		373423
8230	5/30/2011	303118	Bus wont start	Jump started	373448
8230	5/30/2011	303118	Bus wont start	Jump started	373448
8230	5/29/2011	302951	Losing air at the front - back door sticking	Replaced door regulator door working OK	373423
8230	5/23/2011	301768		Perform & Complete PTVS Bus Safety Inspection	371001
8230	5/23/2011	301768		Perform & Complete PTVS Bus Safety Inspection	371001
8230	5/16/2011	299734	BATTERY 12V 190 AMP 1000CCA		366582
8230	5/9/2011	299738	Check air dryer	Adjusted alternator belt jump started and fixed air dryer exhaust silencer	366659
8230	5/9/2011	299738	SNAP ON SILENCER A/DRYER		366659
8230	5/6/2011	299734	Replace batteries	emoved batteries to access battery bracket frame sized free from frame and fit new batteries	366659
8230	5/6/2011	299380	AIR DRYER CANISTER VOLVO+ NL202		366647
8230	5/6/2011	299380	WATER SEPARATOR SCANIA+VOLVO+MB (HAL90364)		366647
8230	5/5/2011	298696	a0463500073 lock plate	Creditor #WHT001 WHITEHORSE TRUCKS P/O #:G91777 Receiving #:92855 Date :2011-05-05 8230	366647
8230	5/5/2011	299380	AIR - rear brakes locking on	Rekit air dryer and water seperator - adjust air pressure	366647
8230	5/5/2011	299380	HALDEX CONDENSER KIT TOP(CYCLONE)		366647
8230	5/5/2011	299380	SINGLE WABCO AIR DRYER KIT 0500LE		366647
8230	5/4/2011	297863	ROAD SAFETY INSPECTIONS	Creditor #ROAD01 Road Safety Inspections P/O #:G91529 Receiving #:92838 Date :2011-05-04	366647
8230	5/4/2011	298696	a0149970546 hub seal	Creditor #WHT001 WHITEHORSE TRUCKS P/O #:G91777 Receiving #:92815 Date :2011-05-04 8230	366647
8230	5/4/2011	298696	a0139973546 hub seal	Creditor #WHT001 WHITEHORSE TRUCKS P/O #:G91777 Receiving #:92815 Date :2011-05-04 8230	366647
8230	5/3/2011	298696	AXL - check rear hub seals for leaks	Replaced seal	366139
8230	5/2/2011	298696	AXL - check rear hub seals for leaks	Start strip parts	366139

8230	5/1/2011	297863	Annual License -	RWC 583108	366139
8230	4/29/2011	296379	REPAIR W/SCREEN	Creditor #KNIO01 KNIGHTS WINDSCREEN REPAIRS P/O #G91706 Receiving #92648 Date :2011-04-29	366139
8230	4/29/2011	298634	Polish windscrin	Polished	366139
8230	4/29/2011	296379	50F3339 REAR ROTORS	Creditor #MUL001 MULTISPARES LTD P/O #G90864 Receiving #92584 Date :2011-04-29	366139
8230	4/28/2011	298696	SUS - Rear stabilizer ball joint - OS top worn	Fit new one	366139
8230	4/27/2011	298470	Fit rear wheels and torque nuts	Completed	366139
8230	4/27/2011	298474	Clean griffity	Cleaned	366139
8230	4/21/2011	296379	ACC - # - rear brakes overheated - replace discscali	Completed	366139
8230	4/20/2011	296379	DISC PADS SCANIA L94+0500 MERC		366139
8230	4/20/2011	296379	ACC - # - rear brakes overheated - replace discscali	Fit boots to callpers and torque nuts to hubs	366139
8230	4/15/2011	296379	AG283201489 SWAY BAR LINK	Creditor #WHT001 WHITEHORSE TRUCKS P/O #G91202 Receiving #92047 Date :2011-04-15 8230	366139
8230	4/15/2011	296379	ABSK010604 REAR CALIPER DUST B	Creditor #WHT001 WHITEHORSE TRUCKS P/O #G90860 Receiving #92023 Date :2011-04-15	366139
8230	4/15/2011	296379	ACC - # - rear brakes overheated - replace discscali	Completed NS rear need to fit brake pads	366139
8230	4/14/2011	296379	ACC - # - rear brakes overheated - replace discscali	Fitted rear rotor & hubs to bus	366139
8230	4/13/2011	296379	ACC - # - rear brakes overheated - replace discscali	Fit rotors to hubs	366139
8230	4/12/2011	296379	AD149970546 REAR HUB SEALS	Creditor #WHT001 WHITEHORSE TRUCKS P/O #G90860 Receiving #91891 Date :2011-04-12	366139
8230	4/12/2011	296379	AD139973546 REAR HUB SEALS	Creditor #WHT001 WHITEHORSE TRUCKS P/O #G90860 Receiving #91891 Date :2011-04-12	366139
8230	4/12/2011	296379	ACC - # - rear brakes overheated - replace discscali	Fitted fuel filters & start to fit rotors	366139
8230	4/11/2011	296379	VALVE BALL 1/2 HEATER		366139
8230	4/8/2011	296379	ACC - # - rear brakes overheated - replace discscali	Drain power steering oil put new oil & filter & fit air dryer canister	366139
8230	4/8/2011	296379	ACC - # - rear brakes overheated - replace discscali	Drain coolant & fit tap	366139
8230	4/8/2011	296379	ACC - # - rear brakes overheated - replace discscali	Strip and ordered parts	366139
8230	4/7/2011	296379	ACC - # - rear brakes overheated - replace discscali	Strip rear rotor & callpers	366139
8230	4/6/2011	295803	SINGLE WABCO AIR DRYER KIT 0500LE		365715
8230	4/6/2011	296379	ACC - # - rear brakes overheated - replace discscali	Start to strip rear axle & rotors	366139
8230	4/5/2011	295993		Replace final drive oil	365715
8230	4/5/2011	295993		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	365715
8230	4/5/2011	295993		Inspect radiator and charge air cooler for dirt - clean	365715
8230	4/5/2011	295993		Check oil level in transmission - top up if required	365715
8230	4/5/2011	295993		Check and clean cartridge in dry tyre air cleaner	365715
8230	4/5/2011	295993		Replace pre and main fuel filters	365715
8230	4/5/2011	295993		Replace air dryer canister clean silence and drain reservoir	365715
8230	4/5/2011	295993		Replace angle drive oil	365715
8230	4/5/2011	295993		Test coolant level - top up if required to equate to 37C frost protection	365715
8230	4/5/2011	295993		Adjust engine valve clearances 0.4MM INLET 0.6MM EXHAUST SONM TORQUE AFTER ENG HAS COOLED FOR 30 MIN.	365715
8230	4/5/2011	295993		Replace power steering filter and check level (Replace oil if required)	365715
8230	4/5/2011	295993	FUEL FILTER MERC 0500LE		365715
8230	4/5/2011	295993	FUEL FILTER 0500LE		365715
8230	4/5/2011	295993	AIR DRYER CANISTER VOLVO+ NL202		365715
8230	4/5/2011	295993	POWER STEER FILTER B10M		365715
8230	4/5/2011	296032	ANN - Annual Body Inspection	Inspected	365715
8230	4/5/2011	295927	FUSE BLADE 10AMP		365715
8230	4/5/2011	295927	EXTINGUISHER FIRE 2.2K REFILL		365715
8230	4/5/2011	291687	check handbrake not holding	Creditor #WHT001 WHITEHORSE TRUCKS P/O #G89092 Receiving #91580 Date :2011-04-05	365715
8230	4/5/2011	295803	AIR - air dryer leaking	Check and found air dryer leaking removed strip and fit kit start to bit to bus	365715
8230	4/4/2011	295803	COM - 2way radio speaker very crackly	same job	365715
8230	4/4/2011	295803	COMM - radio does not transmit	same job	365715
8230	4/4/2011	295803	COM - 2 way - cell call n/w	same job	365715
8230	4/4/2011	295803	COMM - FM/AM radio n/w	Repaired wiring at radio and replaced fuse	365715
8230	4/4/2011	295803	BOD - Fire extinguisher bottle needs refilling	Replaced	365715
8230	4/4/2011	295803	AIR - air dryer leaking	same job	365715
8230	4/4/2011	295835		Bus Safety Inspection	365715
8230	4/4/2011	295835	FILTER TRANSMISSION ZF 4139-298-038E39HD119	ZF Transmission Filter	365715
8230	4/4/2011	295835	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	365715
8230	4/4/2011	295835		Service T - Replace Transmission Oil & Filter	365715
8230	4/4/2011	295834		Clean A/C filter	365715
8230	4/4/2011	295834		Grease AC Compressor Clutch Bearing	365715
8230	4/4/2011	295834		Tension Wheel Nuts To OEM Specification	365715
8230	4/4/2011	295834		A Service & Bus Safety Inspection	365715
8230	4/3/2011	295927	Breakdown - Wells Rd Frankston - OUT 5.30 pm BACK 7.15 pm -	C/O bus 8297. Return to workshop (Need to repair air leak on air dryer and check brake calliper)	365715
8230	3/31/2011	295572	WIPER REFILL SUIT TX800+TX900		365265
8230	3/30/2011	295572	Replace wiper blade	Replaced	365265
8230	3/21/2011	294070	A/C not working	Tested found that the power supply to a/c from battery cable burnt back from solenoid make up new cable and replace solenoid tested bus all OK	361411
8230	3/16/2011	293685	BODY - cage driver door opens on a bump	Adjust drivers door	360681
8230	3/11/2011	293023	WHEEL NUT SQUIRREL		358987
8230	3/10/2011	293023	Replace missing squirrel from OSR # 56 wheels	Replaced	358987
8230	3/2/2011	289666	POS 5-6 11R NEW	Creditor #BEA001 BEAUREPARES P/O #G88526 Receiving #90100 Date :2011-03-02	358696
8230	3/2/2011	289666	POS 5-6 11R NEW	Creditor #BEA001 BEAUREPARES P/O #G88526 Receiving #90100 Date :2011-03-02	358696
8230	3/2/2011	291999	Check rear door sensitive edge	Replaced & adjusted rear door sensitive edge	358696
8230	3/1/2011	291687	Drv entered - Brakes Hand Brake [See printed defect for mor	same job	358696
8230	3/1/2011	291687	BR - Check hand brake not holding	Repaired at Whitehorse	358696
8230	2/26/2011	291381		Perform & Complete PTVS Bus Safety Inspection	356676
8230	2/26/2011	291381		Perform & Complete PTVS Bus Safety Inspection	356676
8230	2/26/2011	291526	BOD - rear seat slashed	Replaced	358696
8230	2/26/2011	291526	COOL - Check for coolant leak	Check fixed	358696
8230	2/18/2011	290340	BROOM HEAD (09803211)		356676
8230	2/17/2011	290340	Replace broom	Replaced	356676
8230	2/15/2011	289666	replace worn tyre pos 5-6	replace worn tyre pos 5-6	355836
8230	2/15/2011	289893	ENG C - check cooling system	Road tested cant fault system bus back on road.	356037
8230	2/15/2011	289833	Add coolant	Added	356037
8230	2/15/2011	289892	BREAK - Breakdown Caulfield Station. Bus overheating. Out	Took 619 topped up coolant.	356037
8230	2/15/2011	289575	SINGLE WABCO AIR DRYER KIT 0500LE		355601
8230	2/15/2011	289575	AIR DRYER CANISTER VOLVO+ NL202		355601
8230	2/14/2011	289570	Replace OS rear tyres	Replaced	355836
8230	2/14/2011	289570	Replace missing nut on cooling pipe clamp	Replaced	355836
8230	2/14/2011	289570	COOL - coolant leak at trans	Repaired coolant leak on heater hoses	355836
8230	2/14/2011	289575	COOL - Water seperator needs rekitting		355836
8230	2/14/2011	289570	BOD - Front wheel arch brush missing	Replaced	355836
8230	2/14/2011	289570	Overhaul leaking air dryer	Overhauled	355836
8230	2/14/2011	289574	AIR FILTER MERC 0500LE		355601
8230	2/14/2011	289574	OIL FILTER 1725+0500LE		355601

8230	2/14/2011	289574	ENGINE OIL DELO 400LE 15W40		355601
8230	2/14/2011	289574		Tension Wheel Nuts to Spec	355601
8230	2/14/2011	289574		A Service & Bus Safety Inspection	355601
8230	2/14/2011	289574		D-Service & Bus Safety Inspection	355601
8230	2/14/2011	289574		Replace engine oil breather kit	355601
8230	2/14/2011	289574	ENGINE OIL BREATHER KIT 0500LE		355601
8230	2/14/2011	289574		Grease AC Compressor Clutch Bearing	355601
8230	2/14/2011	289575	HALDEX COIL KIT 0500LE	Coil kit	355601
8230	2/14/2011	289575	DRAIN VALVE KIT BOTTOM	Valve Kit	355601
8230	2/14/2011	289575	HALDEX COIL BASE OIL SEPERATOR	Base	355601
8230	2/14/2011	289575	WATER SEPERATOR SCANIA+VOLVO	Water Separator Kit	355601
8230	2/14/2011	289575	Rekitted	Re-kit Air Cyclone Separator	355601
8230	2/14/2011	289575	Assemble water sep	Re-kit Air Cyclone Separator	355601
8230	2/14/2011	289574		Clean A/C filter	355601
8230	2/14/2011	289574		Grease AC Compressor Clutch Bearing	355601
8230	2/14/2011	289574		A Service & Bus Safety Inspection	355601
8230	2/14/2011	289574		Tension Wheel Nuts To OEM Specification	355601
8230	2/11/2011	289426	Add coolant	Added	355601
8230	2/10/2011	289159	Clean a/c filter	Cleaned	355275
8230	2/7/2011	288629	Breakdown - Stud Rd - Scorsby - OUT 7.00 am BACK 8.00 am -	C/O bus 8279. Bus is slow building up air	354273
8230	2/4/2011	288308	Add coolant	Added	353345
8230	2/4/2011	288542	Breakdown - Ringwood Station - OUT 9.20 pm BACK 10.40 pm -	Used 27. Topped up checked for leaks OK	353756
8230	2/3/2011	287530	AIR CON REFRIDGERANT		353023
8230	2/2/2011	282269	70-140AMP ALTERNATOR MERCEDES BENZ 0500LE		352252
8230	2/2/2011	282269	70-140AMP ALTERNATOR MERCEDES BENZ 0500LE		352252
8230	2/2/2011	288071	Breakdown - Springvale Rd - OUT 12.00 pm BACK 1.30 pm - Low	C/O bus 8259. Filled coolant returned & topped up coolant r/tested NO leaks found	353023
8230	2/1/2011	287664	BOD - drivers door sticking	same job	352252
8230	2/1/2011	287664	BOD - drivers door sticking	ref to w/order # 286717	352252
8230	1/31/2011	287530	AC - AC nw	Commission tested found unit low on refrigerant 1kg and return air filter blocked	352212
8230	1/31/2011	287622	Add coolant	Added	352252
8230	1/31/2011	287698	Water leak from reservoir 2 filter	Drained coolant s/cleaned tank its not leaking	352252
8230	1/22/2011	286717	PD - Drivers door keeps opening while driving	adjusted door	349690
8230	1/22/2011	286717	COM - speakers very crackly	checked ok	349690
8230	1/22/2011	286717	Drv entered - Body & Acc Security Door	adjusted door	349690
8230	1/22/2011	286717	BOD - drivers door sticking	adjusted door	349690
8230	1/22/2011	286717	BOD - rear seat slashed	replaced cushions	349690
8230	1/12/2011	285448	PD - doors sticking	adjust sensitive edges	346130
8230	1/12/2011	285355	COOL - top up coolant	topped up	346130
8230	1/10/2011	284898	BOSCH REGULATOR 0500LE ALT		344132
8230	1/10/2011	284898	rebuild alternator	Overhauled alt finished	344132
8230	1/10/2011	284898	rebuild alternator	rebuild alternator bus 8230 refer to w/o 282269	344132
8230	1/7/2011	284920	2 way radio n/w	checked 2way & connections OK	344132
8230	1/6/2011	284687	The drivers door is not closing prop	ref to w/order # 284456	343795
8230	1/5/2011	284460	Fill wiper washer	Filed	344352
8230	1/5/2011	284456	Drivers door is nor closing prop	Checked OK	344352
8230	1/5/2011	284456	Air leaking from valve behind RHR axle	Needs water seperator rekitted	344352
8230	1/5/2011	278975	F/GLASS REAR O/S BUMPER CORNER		337113
8230	#####	283108	Add coolant	Added	339285
8230	#####	282269	RELAY HOIST 24V 30-40AMP		338601
8230	#####	282269	EL - batt light staying on	Checked alt wiring found relay sticking replaced OK	338601
8230	#####	282269	BELT BOTTOM ALTERNATOR MERC 0500LE		338601
8230	#####	282269	70-140AMP ALTERNATOR MERCEDES BENZ 0500LE		338601
8230	#####	278903	EMERGENCY EXIT BUITTON PULL COVER		337113
8230	#####	282510	SCREW TORX 8 X 20MM SIDE PANEL		338601
8230	#####	278903	SCREW TORX 8 X 20MM SIDE PANEL		337113
8230	#####	278903	PLATE CLAMPING SIDE PANEL		337113
8230	#####	282174	Inspected	Perform & Complete PTVS Bus Safety Inspection	338601
8230	#####	278903	WHL - NSF tyre only 5mm	Replaced front wheels	338601
8230	#####	278903	WHL - NSF tyre only 5mm	Replaced front wheels & cleaned	338601
8230	#####	282269	EL - batt light staying on	Checked alts	338601
8230	#####	278903	Replace yellow floor strips	Replaced	338601
8230	#####	282311	Air leak at Tullamarine bus lines	Repaired by TBL on 24/11/10(Fixed air leak from base of air dryer)	338601
8230	#####	282173	Service	A Service & Bus Safety Inspection	338601
8230	#####	282173	Service	Tension Wheel Nuts To OEM Specification	338601
8230	#####	282173	Service	A Service & Bus Safety Inspection	338601
8230	#####	282173	Service	Clean A/C filter	338601
8230	#####	282173	Service	Grease AC Compressor Clutch Bearing	338601
8230	#####	278903	ENG - radiator leaking	Assemble radiator inter cooler and related parts. Fixed rear brake relay valve.	337113
8230	#####	278903	ENG - radiator leaking	Fit radiator fill with coolant fit air relay valve.	337113
8230	#####	282510	Secure b/bar	Secured	338601
8230	#####	278903	ENG - radiator leaking	Fitted fan shroud	337113
8230	#####	278903	ENG - radiator leaking	Assemble radiator and fan together	337113
8230	#####	275353	muffler	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G85217 Receiving #:87138 Date :2010-12-13	338601
8230	#####	281665	Change relay valve	Changed	338601
8230	12/6/2010	280001	TOW BUS TO DEPOT FROM TULLAMAR	Creditor #:ASS001 ASSOCIATED TOWING P/O #:G85505 Receiving #:86835 Date :2010-12-06	338601
8230	12/6/2010	278975	COM - No radio speakers for passengers (Checked 18/06/1024	Looks like head unit faulty ordered parts	337113
8230	12/6/2010	278975	COM - No radio speakers for passengers (Checked 18/06/1024	Looks like head unit faulty ordered parts	337113
8230	12/3/2010	278903	ENG - radiator leaking	Removed radiator intercooler & related parts	337113
8230	12/3/2010	278975	COM - No radio speakers for passengers (Checked 18/06/1024	Checked signal to speakers from radio NO signal	337113
8230	12/3/2010	278903	CAMP - fit wheeel arch locks	Fitted	337113
8230	12/1/2010	280001	Towed bus from Tulamarrine to grendas depot	Towed	338601
8230	12/1/2010	278975	radiator cowlng (side) plasti	Creditor #:VOL001 VOLGREN AUSTRALIA P/L P/O #:G85150 Receiving #:86661 Date :2010-12-01 8230 - TRY CMV	337113
8230	#####	279661	Add coolant	Added	338317
8230	#####	279717	Add coolant	Added	337909
8230	#####	266863	AIR FILTER MERC 0500LE		337113
8230	#####	279587	WEDGE GLOBE INSTRUMENT 24V 3W		337419
8230	#####	279587	Replace park light globe	Replaced	337419
8230	#####	266863		Removed muffler from 8261 and fitted r/tested & fixed driver door lock	337113
8230	#####	266863	4 WAY PROTECTION VALVE BARREL SEALS (MB 0500LE)		337113
8230	#####	278975	AC - A/c n/w (Checked on 24/09/10 servicable HKS)	Checked OK	337113
8230	#####	266863		Removed exhaust muffler clean by s/clean and degreaser checked again turbo and air inlet line and clean burn oil in exhaust muffler r/tested but still smoke need to clean again	337113

8230	9/3/2010	268626	Replace filter drier	323529
8230	9/3/2010	268626	Replace compressor oil	323529
8230	9/3/2010	268626	COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	323529
8230	9/3/2010	268626	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	323529
8230	9/3/2010	268626	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	323529
8230	9/3/2010	268626	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	323529
8230	9/3/2010	268626	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler stop & bush for wear	323529
8230	9/3/2010	268626	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	323529
8230	9/3/2010	268626	REFRIGERATION FILTER DRYER: Replace filter drier; check pump operation;	323529
8230	9/3/2010	268626	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray	323529
8230	9/3/2010	268626	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condenser motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condenser fan grills	323529
8230	9/3/2010	268626	CONDENSOR AREA: Clean condenser coils; check bolts/clamps for tension	323529
8230	9/3/2010	268626	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condenser pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	323529
8230	9/2/2010	268534	Changed & r/tested	323207
8230	9/2/2010	268534	Changed	323207
8230	9/2/2010	268683	Completed fit body panel found radiator top up coolant & found not charging	323207
8230	9/2/2010	268528	C/O bus 8608. Battery light also on dash returned to depot and checked defects (Repaired alternator wiring)	323207
8230	9/1/2010	268683	Fitted radiator & fan fill coolant & fit inter cooler hoses fit fan drive with belts	323207
8230	8/31/2010	268683	Fit cooler to radiator fit fan completed started to fit to bus	323207
8230	8/30/2010	268683	Fit fan to frame & clean parts	323207
8230	8/27/2010	267639	Finished removing alts & cleaned up area	323207
8230	8/27/2010	268683	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G81319 Receiving #:82629 Date :2010-08-27	323207
8230	8/26/2010	267639	Take off alt wiring	323207
8230	8/25/2010	268683	Strip & cleaned fan ordered parts	323207
8230	8/25/2010	268683	Fit gas stays	323207
8230	8/24/2010	268683	Remove radiator and inter cooler c/o need to strip fan	323207
8230	8/24/2010	268683		323207
8230	8/24/2010	268683	GAS STAY 450N 710MM EXT LENGTH	337113
8230	8/23/2010	268683	Radiator fan angle drive bearing noise	323207
8230	8/23/2010	268683	A6344600025 STEER ANGLE DRIVE	323207
8230	8/19/2010	266692	Pick bus up from Dysons	323207
8230	8/19/2010	266692	Pick bus up from Dysons	323207
8230	8/12/2010	265566	GLOBE HIGH BEAM 24V70W H1	320148
8230	8/11/2010	265566	Replace OSP headlight globe	320148
8230	7/30/2010	264056	EL - Speedo does not give true reading past 50 kmh	317396
8230	7/22/2010	262922	Add coolant	315487
8230	7/22/2010	262922	Add coolant	315487
8230	7/21/2010	262718	Add coolant	315100
8230	7/21/2010	262718	Add coolant	315100
8230	7/16/2010	262146	Add coolant	313723
8230	7/16/2010	262146	Add coolant	313723
8230	7/15/2010	262037	Drv entered - Passenger Doors Door Brakes	313723
8230	7/13/2010	261488	SIDE INDICATOR R/H	312243
8230	7/12/2010	261488	Drv entered - Elec & Light Cab Light	312243
8230	7/12/2010	261488	Replace damaged LHS indicator lamp	312243
8230	7/12/2010	261488	COOL - Radiator fan bearing noisy	312243
8230	7/12/2010	261527	Replace screws in drivers blind	312243
8230	7/12/2010	261488	Check handbrake	312243
8230	7/5/2010	260718	Add coolant	310785
8230	7/5/2010	260718	Add coolant	310785
8230	7/1/2010	259985	EL - alt not charging	310289
8230	7/1/2010	259985	EL - alt not charging	310289
8230	7/1/2010	259985	EL - alt not charging	310289
8230	7/1/2010	259985	BEARING ALT MAN 16-240	310289
8230	7/1/2010	259985	BOSCH REGULATOR	310289
8230	6/30/2010	259985	EL - alt not charging	310289
8230	6/29/2010	259985	Ops Entered - Fault - Elec & Light - Route: 901 - Kirkham	310289
8230	6/28/2010	251148	RETURN SCRAPPED TYRE	309966
8230	6/28/2010	250513	RETURN SCRAPPED TYRE	309966
8230	6/28/2010	259704	BRK - brakes shuddering	309966
8230	6/22/2010	259180	BOD - Seat belt n/w	308174
8230	6/21/2010	259018	ENG C - top up coolant	307652
8230	6/21/2010	259018	ENG C - top up coolant	307652
8230	6/18/2010	258732	CUSHION EXHAUST PIPE	307484
8230	6/18/2010	258808	EL - Speedo needs checking out needle not accurate past 40	307484
8230	6/18/2010	258732	GLOBE INST 24V 2W	307484
8230	6/18/2010	258732		307484
8230	6/18/2010	258732		307484
8230	6/18/2010	258732		307484
8230	6/18/2010	258732	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL	307484
8230	6/18/2010	258732	OIL FILTER 1725-0500LE	307484
8230	6/18/2010	258732	AIR FILTER MERC 0500LE	307484
8230	6/18/2010	258732		307484
8230	6/18/2010	258732	ENGINE OIL BREATHER KIT 0500LE	307484
8230	6/18/2010	258732		307484
8230	6/18/2010	258732	Replace engine oil breather kit	307484
8230	6/18/2010	258732	A Service & Bus Safety Inspection	307484
8230	6/18/2010	258732	Tension Wheel Nuts To OEM Specification	307484
8230	6/18/2010	258732	Grease AC Compressor Clutch Bearing	307484
8230	6/18/2010	258732	Clean A/C filter	307484
8230	6/16/2010	258532	Adjusted door	306918
8230	6/15/2010	255796	Road Safety Inspections P/O #:G77872 Receiving #:79854 Date :2010-06-15	306625
8230	6/7/2010	257361	Replace headlight globe	304522
8230	6/4/2010	257127	Add coolant	303495
8230	5/30/2010	256346	Annual Inspection - BC 119752	302145
8230	5/30/2010	255796	inspect for rsi	301396
8230	5/28/2010	256071	PDOWER STEER FILTER 810M	301663
8230	5/28/2010	256071		301663
8230	5/28/2010	256071	Replace final drive oil	301663
8230	5/28/2010	256071	Replace angle drive oil	301663
8230	5/28/2010	256071	Adjust engine valve clearnaces 0.4MM INLET 0.6MM EXHAUST 50NM TORQUE AFTER ENG HAS COOLED FOR 30 MIN.	301663
8230	5/28/2010	256071	Replace power steering filter and check level (Replace oil if required)	301663
8230	5/28/2010	256071	FUEL FILTER MERC 0500LE	301663

8230	5/28/2010	256071	FUEL FILTER 0500LE		301663
8230	5/28/2010	256071	AIR DRYER CANISTER VOLVO+ NL202		301663
8230	5/28/2010	256071		Replace air dryer cansiter clean silence and drain reservoir	301663
8230	5/28/2010	256071		Test coolant level - top up if required to equate to 37C frost protection	301663
8230	5/28/2010	256071		Replace pre and main fuel filters	301663
8230	5/28/2010	256071		Check and clean cartridge in dry tyre air cleaner	301663
8230	5/28/2010	256071		Remove disassemble and clean air cyclone seperater (Apply water repellant grease to electrical connection) Check drainage function for leaks	301663
8230	5/28/2010	256071		Check oil level in transmission - top up if required	301663
8230	5/28/2010	256071		Inspect radiator and charge air cooler for dirt - clean	301663
8230	5/28/2010	256007	OVERFLOW VALVE 0500LE		301663
8230	5/27/2010	256040	ENG C - top up coolant	topped up	301663
8230	5/26/2010	256007	ENGI - replace overflow valve	completed	301396
8230	5/26/2010	256007	ENGI - steam clean bus	completed	301396
8230	5/26/2010	255950	BODY - adjust rear door sensors	adjusted	301396
8230	5/24/2010	255427	COOL - G/box cool pipe leaking		300945
8230	5/24/2010	255427	COOLANT PIPE EXP TANK MERC 0500LE		300945
8230	5/24/2010	255427	COOL - G/box cool pipe leaking	radiator auxillary tank makeup line removed new fitted. Road test done.	300945
8230	5/24/2010	255427	COOL - G/box cool pipe leaking	complete.	300945
8230	5/21/2010	254269	GEARBOX COOLANT PIPE MERCEDES	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G77590 Receiving #:79087 Date :2010-05-21 8230	299766
8230	5/19/2010	254931	RSI - inspect for RSI	completed	299362
8230	5/19/2010	254931	RSI - inspect for RSI	completed	299362
8230	5/19/2010	254747	BOD - Secure drivers compartment door lock	secured	299362
8230	5/19/2010	254747	BOD - Paint till stand	paintned	299362
8230	5/19/2010	254747			299362
8230	5/19/2010	254747	BOD - Clean graffiti - floor seats & side walls	cleaned	299362
8230	5/19/2010	254747	ANTIBURST LOCK STRICKER PLATE		299362
8230	5/19/2010	254747	BOD - Replace interior decal - priority seating	replaced	299362
8230	5/19/2010	254747	BOD - replace exit only on rear doors	replaced	299362
8230	5/19/2010	254747	BOD - Rear step edges replace or fit inserts	replaced	299362
8230	5/19/2010	254747	BOD - Paint door handles - front/rear	adjusted front door and touch up	299362
8230	5/19/2010	254747	BOD - Clean air condition filter secure vents	cleaned	299362
8230	5/19/2010	254747	BOD - safety triangles and decals - replace	replaced	299362
8230	5/19/2010	254747	BOD - polish exterior panels/headers & touch up paint work	polished and touched up	299362
8230	5/19/2010	254747	BOD - Paint exterior mirrors and arms	paintned	299362
8230	5/19/2010	254747	BOD - Accreditation number decal		299362
8230	5/19/2010	254747	BOD - Secure all lower skit panels	secured	299362
8230	5/19/2010	254747	BOD - Paint till stand	paintned	299362
8230	5/19/2010	254747	BOD - Grenda's name address & weight - OSF No 1 panel	removed and polished	299362
8230	5/19/2010	254747	BOD - No cover on BDC - reflecting on windscreen		299362
8230	5/19/2010	254747	BOD - Replace front door - entry only decal	replaced	299362
8230	5/19/2010	254747	BOD - Replace emergency exit decals with safety hammers - r	replaced	299362
8230	5/19/2010	254747	BOD - Replace safety triangle decal - on d/shield new buses	replaced	299362
8230	5/19/2010	254747	BOD - Replace visual check list decal	replaced	299362
8230	5/19/2010	254747	BOD - Replace drivers seat decal	replaced	299362
8230	5/19/2010	254747	Drv entered - Accident		299362
8230	5/19/2010	254747	Ops Entered - Accident - Vehicle ran into Bus - Route: 900		299362
8230	5/19/2010	254747	Ops Entered - Accident - Bus Hit Stationary Object - Route		299362
8230	5/19/2010	254747	Accident damaged # 21387 Polish & touch-up n/s/r. lower pan		299362
8230	5/19/2010	254747	Accident Damaged #30996 R/R. n/s. lower panel reflectors		299362
8230	5/17/2010	254587	ELE - install e tag	installed	298654
8230	5/14/2010	254263	INSTRUMENT GLOBE		297423
8230	5/13/2010	254132	32MM LOOSE WHEEL NUT INDICATOR		297423
8230	5/13/2010	254263	Remove graffiti	Removed	297423
8230	5/13/2010	254269	GB - G/box cooler pipe leaking	Removed transmission cooling line after brazing line fitted fitted all removed parts & filled coolant	297488
8230	5/13/2010	254269	GB - G/box cooler pipe leaking	Repair to coolant pipe at rear of transmission	297488
8230	5/13/2010	254263	Replace stopping sign globe	Replaced	297423
8230	5/13/2010	254132		A Service & Bus Safety Inspection	297423
8230	5/13/2010	254132		Clean A/C filter	297423
8230	5/13/2010	254132		Grease AC Compressor Clutch Bearing	297423
8230	5/13/2010	254132		Tension Wheel Nuts To OEM Specification	297423
8230	5/13/2010	254132		A Service & Bus Safety Inspection	297423
8230	5/12/2010	254058	Add coolant	Added	297017
8230	5/11/2010	253861	Clean a/c filter	Cleaned	296762
8230	5/11/2010	253861	Add coolant	Added	296762
8230	5/11/2010	253897	COMM - 2way radio is n/w properly	checked ok	296762
8230	5/10/2010	253653	ANN - carry out annual inspection	Inspected	296686
8230	5/10/2010	253590	Ticket machine n/w	Checked by joe	296686
8230	5/6/2010	253322	Add coolant	Added	295447
8230	5/5/2010	253370	EL - LH headlight n/w	Checked OK	295914
8230	5/5/2010	253370	BOD - Drivers seat belt n/w	Checked OK	295914
8230	4/29/2010	251423	0500 COOLANT LOW LEVEL SENDER		293123
8230	4/28/2010	250513	POS 1-2 11R225 NEW	Creditor #BEA001 BEAUREPAIRES P/O #:G76389 Receiving #:78263 Date :2010-04-28	293123
8230	4/28/2010	251148	POS 3 11R225 NEW	Creditor #BEA001 BEAUREPAIRES P/O #:G76590 Receiving #:78268 Date :2010-04-28	293123
8230	4/28/2010	252295	Add coolant	Assisted Alan to drain the coolant & changed the coolant level sensor	293123
8230	4/28/2010	252295	Add coolant	Added	293123
8230	4/28/2010	252423	Breakdown - Monash Uni - OUT 5.00 pm BACK 7.00 pm - Coolant	Used van 619. Followed bus back to depot & changed coolant level sensor	293123
8230	4/27/2010	252156	Clean a/c filter	Cleaned	292837
8230	4/22/2010	251792	Add coolant	Added	292106
8230	4/21/2010	251719	Left mirror broken	Assisted	290918
8230	4/21/2010	251719	Left mirror broken	Fitted new mirror	290918
8230	4/20/2010	251387	BROOM HANDLE (8232715)		290313
8230	4/20/2010	251387	BROOM HEAD (09803211)		290313
8230	4/19/2010	251148	Replace tyre pos 3 - puncture	Replaced	290313
8230	4/19/2010	251287	Clean a/c filter	Cleaned	290313
8230	4/19/2010	251387	BOD - No broom in bus	Replaced	290313
8230	4/18/2010	251274	Change pos 3 tyre	Changed	289972
8230	4/16/2010	250827	BROOM HANDLE (8232715)		289120
8230	4/16/2010	250827	BROOM HEAD (09803211)		289120
8230	4/14/2010	250827	BOD - Bus has no broom	Replaced	289120
8230	4/13/2010	250513	replace worn tyres pos 1-2	Replaced	289120
8230	4/8/2010	249613	REPLACE W/SCREEN	Creditor #ELI001 ELITE WINDSCREENS P/O #:G76287 Receiving #:77820 Date :2010-04-08	288309

8230	4/6/2010	249806	Change o/s rear tyres	Changed rear tyres	288309
8230	4/6/2010	249806	Repair water leak	Repaired	288309
8230	4/6/2010	249613	ACC - replace window 3 LHS	Replaced by Elite	288309
8230	4/6/2010	249524		Bus Safety Inspection	288044
8230	4/6/2010	249524	WING NUT BRASS BATTERY TERMINAL POSITIVE		288044
8230	4/6/2010	249524		Service T - Replace Transmission Oil & Filter	288044
8230	4/6/2010	249524	FILTER TRANSMISSION ZF 4139-298-038E39HD119	ZF Transmission Filter	288044
8230	4/6/2010	249524	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	288044
8230	4/6/2010	249524	AIR FILTER MERC 0500LE		288044
8230	4/6/2010	249524		A Service & Bus Safety Inspection	288044
8230	4/6/2010	249524		Clean A/C filter	288044
8230	4/6/2010	249524		Grease AC Compressor Clutch Bearing	288044
8230	4/6/2010	249524		Tension Wheel Nuts To OEM Specification	288044
8230	4/1/2010	249464	Add coolant	Added	288044
8230	3/29/2010	249088	Add coolant	Added	285980
8230	3/26/2010	248879	Clean a/c filter	Cleaned	285250
8230	3/26/2010	248888	Add coolant	Added	285250
8230	3/19/2010	246770	POS 3 11R225 NEW FLAT	Creditor #BEA001 BEAUREPAIRES P/O #G75437 Receiving #77223 Date :2010-03-19	284354
8230	3/19/2010	248235	A/S - Air leak past back door	Air leak from g/box r/valve replaced O ring	284354
8230	3/18/2010	248102	Clean a/c filter	Cleaned	283989
8230	3/11/2010	247219	Add coolant	Added	282363
8230	3/9/2010	246899	Change tyre 3	Changed	281658
8230	3/9/2010	246899	Change tyre 3	Changed	281658
8230	3/9/2010	246770	Replace tyre pos 3 - worn	Replaced	280636
8230	3/9/2010	246770	Ops Entered - Fault - Whls & Tyres - Route: 901 - Dandenong	Replace Pos.3 tyre	280636
8230	3/9/2010	246899	Change tyre 3	Changed	281658
8230	3/1/2010	363889	PUNCTURE - POS 1 - 11 R22.5 -	Creditor #BEA001 BEAUREPAIRES P/O #G110831 Receiving #11290 Date :2012-07-16 REPAIR OR REPLACE WITH NEW	479611
8230	3/1/2010	246047	Clean a/c filter	Cleaned	279357
8230	3/1/2010	361794	REPL WINDSCREEN	Creditor #ELI001 ELITE WINDSCREENS P/O #G110350 Receiving #110830 Date :2012-07-03	476776
8230	2/23/2010	245401	TOP ALT BELT MERC 0500+FAN BELT A/C ARTIC		277739
8230	2/22/2010	245401	Remove graffiti from rear of bus	Removed	277739
8230	2/22/2010	245401	Replace top alt belt	Replaced	277739
8230	2/22/2010	245401	Water leak near radiator	Repaired hose clamp	277739
8230	2/22/2010	245315	TINT WINDOW	Creditor #TIN001 TINT FX P/O #G75041 Receiving #76472 Date :2010-02-22	277739
8230	2/22/2010	245206		A Service & Bus Safety Inspection	277543
8230	2/22/2010	245206		Clean A/C filter	277543
8230	2/22/2010	245206		Grease AC Compressor Clutch Bearing	277543
8230	2/22/2010	245206		Tension Wheel Nuts To OEM Specification	277543
8230	2/22/2010	245206		A Service & Bus Safety Inspection	277543
8230	2/20/2010	245315	Supply and install window tint	Installed by Tint FX	277613
8230	2/16/2010	244693	Clean a/c filter	Cleaned	276561
8230	2/9/2010	243876	Clean a/c filter	Cleaned	274038
8230	2/5/2010	241959	POS 1-2 11R225 NEW	Creditor #BEA001 BEAUREPAIRES P/O #G74197 Receiving #76013 Date :2010-02-05	272971
8230	2/4/2010	243240	Needs a wheel alignment	Tyres checked OK	272747
8230	2/4/2010	243242	Stereo u/s	Checked repaired drivers mic switch	272747
8230	2/4/2010	243240	No 1 air tank sills on 9 PSI	Checked all OK	272747
8230	1/25/2010	242190	Clean a/c filter	Cleaned	269860
8230	1/25/2010	242207	GLOBE INST 24V 2W		269860
8230	1/25/2010	242207	Replace dash light globe	Replaced	269860
8230	1/22/2010	241959	replace worn tyres pos 1-2	Replaced	269264
8230	1/21/2010	241964	Change front tyres & clean	Changed tyres & cleaned rim front & o/s rear	269264
8230	1/21/2010	241964	Change front tyres & clean	Changed tyres & cleaned rim front & o/s rear	269069
8230	1/21/2010	241964	Replace g/box heater hose	Replaced hose copper washer r/tested & checked for leaks	269069
8230	1/21/2010	241807	WASHER OIL LINE INJ PUMP		269069
8230	1/21/2010	241807		Clean A/C filter	268700
8230	1/21/2010	241807		Grease AC Compressor Clutch Bearing	268700
8230	1/21/2010	241807		Tension Wheel Nuts To OEM Specification	268700
8230	1/21/2010	241807		A Service & Bus Safety Inspection	269264
8230	1/21/2010	241807		A Service & Bus Safety Inspection	268700
8230	1/20/2010	241762	Add coolant	Added	268700
8230	1/20/2010	241762	Clean a/c filter	Cleaned	268700
8230	1/14/2010	239974	W/ARCH STRUT P/N 290115	Creditor #VOL001 VOLGREN AUSTRALIA P/L P/O #G73619 Receiving #75450 Date :2010-01-14 230	267161
8230	1/13/2010	240366	POS 4 11R NEW	Creditor #BEA001 BEAUREPAIRES P/O #G73742 Receiving #75398 Date :2010-01-13	266793
8230	1/13/2010	240366	POSS 11R NEW	Creditor #BEA001 BEAUREPAIRES P/O #G73742 Receiving #75398 Date :2010-01-13	266793
8230	1/11/2010	240790	clean a/c filters	cleaned filters	266131
8230	1/11/2010	240476	GEARBOX COOLANT PIPE MERCEDES	Creditor #WHT001 WHITEHORSE TRUCKS P/O #G73492 Receiving #75320 Date :2010-01-11 230	266131
8230	1/11/2010	240814	jump start bus	jump started bus	266425
8230	1/11/2010	240814	jump start bus	jump started bus	266131
8230	1/11/2010	240814	jump start bus	jump started bus	266131
8230	1/10/2010	240772	2 way radio is not clear crackling noise	checked radio ok.	266131
8230	1/8/2010	240601	clean graffiti	cleaned	265567
8230	1/8/2010	240601	clean graffiti	cleaned	265567
8230	1/8/2010	240476	bunny hops going down gear between 4-3 when pressing brakes.	replaced 2 way valve seam and air dryer air kit road tested its ok.	265567
8230	1/8/2010	240476	leaking gearbox coolant pipe	replaced g/box coolant pipe coolant and road tested	265567
8230	1/8/2010	240476	4 WAY PROTECTION VALVE BARREL SEALS (MB 0500LE)		265567
8230	1/8/2010	240476	SNAP ON SILENCER A/DRYER		265567
8230	1/8/2010	240476	SINGLE AIR DRYER KIT 0500LE		265567
8230	1/7/2010	240519	change tyres pos 4 & 5	changed.	265567
8230	1/7/2010	240519	change tyres pos 4 & 5	changed.	265567
8230	1/7/2010	240519	change tyres pos 4 & 5	changed.	265567
8230	1/6/2010	240366	tyre worn position 4 & 5	replaced	265240
8230	1/2/2010	239966	WATER SEPARATOR SCANIA+VOLVO		264301
8230	1/2/2010	239966	HALDEX COIL BASE OIL SEPARATOR		264301
8230	1/2/2010	239966	HALDEX COIL KIT 0500LE		264301
8230	1/2/2010	239966	re kit water separator	re kitted water separator	264301
8230	1/2/2010	239974	air leak front left panel will not close cause the strut is	remove broken panel holder.	264301
8230	#####	239609	Add coolant	Added	263217
8230	#####	239524	Replace radiator cap	Replaced cap & filled coolant	262611
8230	#####	239335	O/S washer hose needs repair	Replaced washer motor & repaired washer hose	262511
8230	#####	239335	PUMP WIPER-WASHER 24 VOLT		262511
8230	#####	239335	O/S washer hose needs repair	Repaired	262511

8230	#####	238960	Clean a/c filter	Cleaned	260838
8230	#####	239049	1 passenger seat slashed	Repaired slashed seat	261091
8230	#####	238806	remove graffitti	removed graffitti	260538
8230	#####	238622		Tension Wheel Nuts to Spec	260186
8230	#####	238622	Service	A Service & Bus Safety Inspection	260186
8230	#####	238622	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		260186
8230	#####	238622		D-Service & Bus Safety Inspection	260186
8230	#####	238622	AIR FILTER MERC 0500LE		260538
8230	#####	238622		Grease AC Compressor Clutch Bearing	260186
8230	#####	238622	OIL FILTER 1725+0500LE		260186
8230	#####	238622		Tension Wheel Nuts to OEM Specification	260186
8230	#####	238622		A Service & Bus Safety Inspection	260186
8230	#####	238622		Clean A/C filter	260186
8230	#####	238622		Grease AC Compressor Clutch Bearing	260186
8230	12/2/2009	237309	Clean a/c filter	Cleaned	256369
8230	#####	235630	Add coolant	Added	252341
8230	#####	235332	Random vehicle audit	Completed at service	251343
8230	#####	235249		Clean A/C filter	250978
8230	#####	235249		A Service & Bus Safety Inspection	250978
8230	#####	235249		Tension Wheel Nuts to OEM Specification	250978
8230	#####	235249		Grease AC Compressor Clutch Bearing	250978
8230	11/4/2009	234440	rear inside roof need to be cleaned	cleaned.	248975
8230	11/4/2009	234326	Remove graffitti	Removed	248725
8230	11/4/2009	234439	door wont open	door top bolt came out. fixed.	248725
8230	11/4/2009	234438	Breakdown Kirkhams Rd Dandenong door wont open.	c/o bus 229. door top bolt came out.	248725
8230	#####	233447	Clean a/c filter	Cleaned	245866
8230	#####	231721	HEAD LIGHT GLOBE 24V 70/75W		243497
8230	#####	231721	change headlight globe	changed headlight globe	243089
8230	#####	231245	Battery saver light on	Found short in cannon plug and repaired	242679
8230	#####	231487	coolant leak from boost pump top connection& near transmis	Checked OK	242540
8230	#####	231659	check coolant leak	checked the coolant leak - ok	243089
8230	10/9/2009	77898	the right front side head light is not working	changed globe	242540
8230	10/9/2009	231245	Battery saver light on	Remove relays fuse section found the short in a/c	242540
8230	10/8/2009	231245	Battery saver light on	Repair alternator wires and check electrical system	242540
8230	10/8/2009	231245	Battery saver light on	Check fuse blowing -	242540
8230	10/8/2009	231613	Sand l/bar	Sand l/bar	242540
8230	10/7/2009	231126	battery light red	ok.checked.	241862
8230	10/7/2009	231487	coolant leak from boost pump top connection& near transmis	checked oil separator OK. Removed alternator cover. Found faulty wire carry over.	242540
8230	10/6/2009	231187	GLOBE S/CONTACT 24V-10W		242540
8230	10/5/2009	231245	Battery saver light on	Check electrical system disconnect air separator	242540
8230	10/5/2009	231245	Battery saver light on	Check electrical system	242540
8230	10/5/2009	231188	GLOBE INDICATOR 24V-18W SINGLE CONTACT		242540
8230	10/5/2009	231188	Replace o/s/l indicator globe	Replace globe	242540
8230	10/5/2009	231188	Replace o/s/l indicator globe	Replace globe	242540
8230	10/5/2009	231187	Replace interior light globe	Replace globe	242540
8230	10/5/2009	231110		A Service & Bus Safety Inspection	242540
8230	10/5/2009	231110		Clean A/C filter	242540
8230	10/5/2009	231110		Grease AC Compressor Clutch Bearing	242540
8230	10/5/2009	231110		Tension Wheel Nuts to OEM Specification	242540
8230	10/5/2009	231110		A Service & Bus Safety Inspection	242540
8230	9/22/2009	228462	FILTER DRIER THERMO KING		239042
8230	9/8/2009	228462		C Service	233895
8230	9/8/2009	228462		B Service	233895
8230	9/8/2009	228462		Replace filter drier	233895
8230	9/8/2009	228462		Replace compressor oil	233895
8230	9/8/2009	228462	Serviced as per list	UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	233895
8230	9/8/2009	228462		CONDENSOR AREA: Clean condensor coils; check bolts/clamps for tension	233895
8230	9/8/2009	228462		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	233895
8230	9/8/2009	228462		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray	233895
8230	9/8/2009	228462		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	233895
8230	9/8/2009	228462		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	233895
8230	9/8/2009	228462		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	233895
8230	9/8/2009	228462		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	233895
8230	9/8/2009	228462		COMPRESSOR DRIVE BELTS: Inspect belt wear; Retension belts;	233895
8230	9/8/2009	228462		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	233895
8230	9/8/2009	228462		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	233895
8230	9/7/2009	228394	Add coolant	Added	233895
8230	8/18/2009	226412	Accident damage #30114# Damaged L/H/S bumper barwindscrrin	Repaired by Volgren	233560
8230	8/17/2009	226367	Water leak above drivers window when raining	Checked for water leaks used pressure cleaner & bus wash NO water coming in	233560
8230	8/17/2009	226316		A Service & Bus Safety Inspection	233560
8230	8/17/2009	226316		Clean A/C filter	233560
8230	8/17/2009	226316		Grease AC Compressor Clutch Bearing	233560
8230	8/17/2009	226316		Tension Wheel Nuts to OEM Specification	233560
8230	8/17/2009	226316		A Service & Bus Safety Inspection	233560
8230	8/8/2009	225456	Drivers comparnent door lock need adjusting	Adjusted	230849
8230	8/4/2009	224007	ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #:G68953 Receiving #:70827 Date :2009-08-04	229717
8230	8/3/2009	224988	GEARBOX COOLANT PIPE MERCEDES BENZ 0500		229717
8230	8/3/2009	224988	CUSHION EXHAUST PIPE		229717
8230	8/3/2009	224988	G/Box oil leak at bell housing		229612
8230	8/3/2009	224988	Angle drive for radiator fan leaking oil (warranty)	S/cleaned & checked OK	229612
8230	8/3/2009	223947		S/cleaned & checked OK	229612
8230	8/3/2009	223947		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	227637
8230	8/3/2009	223947		Check oil level in transmission - top up if required	227637
8230	8/3/2009	223947		Test coolant level - top up if required to equate to 37C frost protection	227637
8230	8/3/2009	223947			229612
8230	8/3/2009	224988	Unblock and aim washer jets	Cleaned & aimed	229612
8230	8/3/2009	224988	Adjstut front doors	Adjusted	229612
8230	8/3/2009	224988	Transmission coolant pipe coolant leak		229612
8230	8/3/2009	224988	Split rear outer muffler mount	Replaced	229612
8230	8/3/2009	224988	Loose indicator stalk	Checked OK	229612
8230	8/3/2009	224911	Add coolant	Added	229612
8230	8/3/2009	224988	Coolant leak at heater tap next to radiator	Repaired	229612

8230	8/3/2009	224988	Replace large coolant pipe on N/S g/box	Replaced	229612
8230	8/3/2009	224988	Coolant leak at tap near g/box	Fixed	229612
8230	8/3/2009	224988	Coolant leak around boost pump	Fixed	229612
8230	8/3/2009	224988	Replace front reg plate	Replaced	229612
8230	8/3/2009	224988	Fit security camera decal on n/s window	Checked OK	229612
8230	8/3/2009	224988	Rear door modresty panel loose	Secured	229612
8230	8/3/2009	224988	Replace brake pedal rubber	Replaced	229612
8230	8/3/2009	224988	Air leaking from retarder oil accumulator air supply fitting	Checked OK	229612
8230	8/3/2009	224988	Air leak on accumulator elbow	Fixed	229612
8230	7/31/2009	224764	Add coolant	Added	229249
8230	7/28/2009	223947	WATER SEPERATOR SCANIA+VOLVO		228482
8230	7/28/2009	223947		Remove disassemble and clean air cyclone seperater (Apply water repellent grease to electrical connection) Check drainage function for leaks	227637
8230	7/28/2009	223947		Replace pre and main fuel filters	227637
8230	7/28/2009	223947		Replace angle drive oil	227637
8230	7/28/2009	223947		Adjust engine valve clearnaces 0.4MM INLET 0.6MM EXHAUST 50NM TORQUE AFTER ENG HAS COOLED FOR 30 MIN.	227637
8230	7/27/2009	224241	Add coolant	Added	227928
8230	7/26/2009	224007	Annual inspection - BC 133737	Annual inspection - BC 133737	227928
8230	7/24/2009	223947		Inspection on bus	227637
8230	7/24/2009	223947		Replace final drive oil	227637
8230	7/24/2009	223947		Inspect radiator and charge air cooler for dirt - clean	227637
8230	7/24/2009	223947		Check and clean cartridge in dry tyre air cleaner	227637
8230	7/24/2009	223947		Replace air dryer canister clean silence and drain reservoir	227637
8230	7/24/2009	223947		Replace power steering filter and check level (Replace oil if required)	227637
8230	7/24/2009	223947	AIR DRYER CANISTER VOLVO+ NL202		227637
8230	7/24/2009	223947	POWER STEER FILTER B10M		227637
8230	7/24/2009	224147	Full steamclean	Cleaned	227928
8230	7/20/2009	223487	Add coolant	Added	226545
8230	7/14/2009	222955		A Service & Bus Safety Inspection	224549
8230	7/14/2009	222955		Clean A/C filter	224549
8230	7/14/2009	222955		Grease AC Compressor Clutch Bearing	224549
8230	7/14/2009	222955		Tension Wheel Nuts To OEM Specification	224549
8230	7/14/2009	222955		A Service & Bus Safety Inspection	224549
8230	7/13/2009	222840	Add coolant	Added	224180
8230	7/12/2009	222802	TOP ALT BELT MERC 0500+FAN BELT A/C ARTIC		224180
8230	7/12/2009	222802	A/C BELT 0500 BENZ		224180
8230	7/12/2009	222802	Change main water pump belt	Changed & changed top alt belt	224180
8230	7/2/2009	221919	Add coolant	Added	221579
8230	7/1/2009	221837	Add coolant	Added	221153
8230	6/25/2009	212206	DIRECT PURCHASE ACCIDENT	Creditor #VOL001 VOLGREN AUSTRALIA P/L P/O #:G65338 Receiving #:69771 Date :2009-06-25 Accident damage no 17749 - N/S/F top fibre glass corner	229268
8230	6/20/2009	220834	Lights shining in car mirrors need to lower	Adjusted mirrors	218189
8230	6/16/2009	219910	POS 3-4-5 11R225 NEW	Creditor #BEAD01 BEAUREPAIRES P/O #:G67683 Receiving #:69466 Date :2009-06-16	216740
8230	6/11/2009	219910	Replace tyre pos 345 - worn	Replaced	215328
8230	6/10/2009	219915	Change tyres 345	Changed	215328
8230	6/10/2009	219915	Change tyres 345	Changed	215179
8230	6/10/2009	219915	Change indicator globe	Replaced	215179
8230	6/10/2009	219873		D Service & Bus Safety Inspection	215179
8230	6/10/2009	219873		Grease AC Compressor Clutch Bearing	215179
8230	6/10/2009	219873	AIR FILTER MERC 0500LE		215179
8230	6/10/2009	219873	OIL FILTER 1725+0500LE		215179
8230	6/10/2009	219873	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		215179
8230	6/10/2009	219873	GLOBE 5/CONTACT 24V-10W		215328
8230	6/10/2009	219873			215179
8230	6/10/2009	219873		Tension Wheel Nuts to Spec	215179
8230	6/10/2009	219873		A Service & Bus Safety Inspection	215179
8230	6/10/2009	219873		Tension Wheel Nuts To OEM Specification	215179
8230	6/10/2009	219873		A Service & Bus Safety Inspection	215179
8230	6/10/2009	219873		Clean A/C filter	215179
8230	6/10/2009	219873		Grease AC Compressor Clutch Bearing	215179
8230	6/2/2009	219158	front blind broke	Repairs to locking mechanism	213060
8230	5/28/2009	218816	BLADE WIPER 1MTR		212005
8230	5/28/2009	218816	Left wiper missing blade retainer thus the wiper blade is h	Bring bus to workshop & replace wiper blade	211680
8230	5/22/2009	218195	Add coolant	Added	210279
8230	5/15/2009	217674	Reset rear door sensor	Set	208076
8230	5/14/2009	217405	Drivers sun visor/blind faulty (when down keeps going up)	Refitted cord on side blind	207409
8230	5/14/2009	217405	Drivers sun visor/blind faulty (when down keeps going up)	Checked OK	207409
8230	5/11/2009	217171	Back door closes very slowly	Checked OK	206962
8230	5/11/2009	217171	TCO 1000	Checked OK	206962
8230	5/11/2009	217171	Drivers area needs a mop	Checked OK	206962
8230	5/11/2009	216989		A Service & Bus Safety Inspection	207043
8230	5/11/2009	216989		Clean A/C filter	206962
8230	5/11/2009	216989		Grease AC Compressor Clutch Bearing	206962
8230	5/11/2009	216989		Tension Wheel Nuts To OEM Specification	206962
8230	5/11/2009	216989		A Service & Bus Safety Inspection	206962
8230	5/7/2009	216781	Add oil	Added	205944
8230	5/5/2009	216532	No light on top of till very dark cannot see coins	There is 2 standard LED downlight in the front which are working OK	205231
8230	5/4/2009	216432	Add coolant	Added	204905
8230	4/28/2009	215777	Ops Entered - Fault - Wipers & Washers - Route: 901 - Kirk	Cleaned out washers	202901
8230	4/28/2009	215777	New section of pipe and elbow need replacing	Checked OK	202901
8230	4/28/2009	215777	Need oil dip stick	Replaced	202901
8230	4/28/2009	215777	F/R door sensor n/w	Checked OK	202901
8230	4/28/2009	215777	Front blind will not stay down	Checked OK	202901
8230	4/28/2009	215777	Sunvisor wont stay down	Checked OK	202901
8230	4/27/2009	215659	BROOM HANDLE (8232715)		202552
8230	4/27/2009	215659	BROOM HEAD (09803211)		202552
8230	4/27/2009	215659	No broom to sweep with	Added	202552
8230	4/24/2009	215548	The l/s wiper needs tightening	Tighten wiper nut adjust wire lines	202063
8230	4/24/2009	215513	Add coolant	Added	202063
8230	4/21/2009	215213	Dash needs to be adjusted	Removed dash checked fault codes- reset still no goodReadjusted dash	201458
8230	4/21/2009	215213	Dash needs to be adjusted	Removed dash checked fault codes- reset still no good	201458
8230	3/23/2009	212206	Accident damage no 17749 - Replace n/s mirror mirror arm (Repaired by Volgren	201458
8230	3/23/2009	212206	Accident damage no 19675 - Replace n/s mirror m/arm (Repla	Repaired by Volgren	201458
8230	3/23/2009	212206	Accident damage no - 20116 - Front of bus and n/s rear panel	Repaired by Volgren	201458

8230	3/22/2009	212295	Ops Entered - Fault - Vandalism - Route: 901 - Dandenong S	Cleaned graffiti	201458
8230	3/16/2009	211466	Recall for fuel line upgrade SM730	Completed by w/horse	200176
8230	3/16/2009	211569	Replace headlight	Replaced	200176
8230	3/16/2009	211569	GLOBE HIGH BEAM		200176
8230	3/16/2009	211569	Add coolant	Added	200176
8230	3/5/2009	210627	Top alt belt cracked	Replaced belt & adjusted a/c belt tensioner and r/tested	197642
8230	3/5/2009	210470		A Service	197642
8230	3/5/2009	210470	DIP STICK MERCEDES 0500LE		197966
8230	3/5/2009	210470	TOP ALT BELT MERC 0500+FAN BELT A/C ARTIC		197642
8230	3/5/2009	210470		A Service	197642
8230	3/5/2009	210470		Grease AC Compressor Clutch Bearing	197642
8230	3/5/2009	210470		Tension Wheel Nuts To OEM Specification	197642
8230	2/23/2009	209473	Speedo defective showing slower speed than actual real spe	Road test ok	194366
8230	2/20/2009	209353	Add oil	Added	193184
8230	2/18/2009	209184	Repair front blind	Repaired	192430
8230	2/16/2009	208891	Need water in washers (wiper blades)	Wiper washer top up	191741
8230	2/16/2009	209049	Change mirror	Changed	191741
8230	2/9/2009	208288	Add coolant	Added	189724
8230	2/8/2009	208252	Clean a/c filter	Cleaned	189724
8230	2/6/2009	208148	Air con n/w	Pressure test system look for leak found on inside off suction elbow repair leak vac & gas NOTE: temp repairs to get bus on road new section off pipe and elbow need replacing	189077
8230	2/5/2009	208148	AIR CON REFRIDGERANT	Added	189355
8230	2/4/2009	207818	Add oil	Added	188491
8230	2/3/2009	207642	No alternator belt	Replaced broken alternator bolts	188300
8230	2/3/2009	206759	Drv entered - Body & Acc Drivers Seat Controls	Checked OK	184742
8230	2/3/2009	207684	FILTER TRANSMISSION ZF 4139-298-038E39HD119	ZF Transmission Filter	188300
8230	2/3/2009	207684	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	188300
8230	2/3/2009	207684		Service T - Replace Transmission Oil & Filter	188300
8230	2/3/2009	207684		Grease AC Compressor Clutch Bearing	188300
8230	2/3/2009	207684		Tension Wheel Nuts To OEM Specification	188300
8230	2/3/2009	207684		A Service	188300
8230	1/22/2009	206800	Replace tyre pos 12 - flat spots	Replaced	184831
8230	1/21/2009	206668	Replace flywheel	Replaced	184742
8230	1/21/2009	206668	Add oil	Added	184742
8230	1/21/2009	206668	Top alternator mount 1 bolt broken	Replaced	184831
8230	1/21/2009	206668	Drv entered - Engine Leaking	R/tested OK	184831
8230	1/21/2009	206668	Drv entered - Engine Leaking	R/tested OK	184831
8230	1/21/2009	206668	Top alternator mount 1 bolt broken	Removed & replaced	184742
8230	1/21/2009	206668	Drv entered - Engine Leaking	S/cleanedchecked	184742
8230	1/21/2009	206668	Very light oil leak around bell housing	Checked OK	184742
8230	1/21/2009	206668	Very light oil leak around bell housing	S/cleaned r/tested checked OK	184831
8230	1/21/2009	206668	MOUNTING BOLT - ALTERNATOR MERCEDES		184742
8230	1/21/2009	206668	DISC PADS SCANIA L94+0500 MERC		184742
8230	1/21/2009	206668	Drv entered - Brakes Noisy	Replaced	184328
8230	1/21/2009	206668	Drv entered - Brakes	Replaced all brake pads	184831
8230	1/21/2009	206668	Drv entered - Brakes Losing Air	Checked OK	184742
8230	1/21/2009	206668	Drv entered - Brakes	Replaced all brake pads	184742
8230	1/19/2009	206523	Refill coolant	Refilled	183964
8230	1/9/2009	205153	POS 3+4 11R225 NEW	Creditor #BEA001 BEAUREPAIRS P/O #:G63135 Receiving #:65085 Date :2009-01-09	181075
8230	1/9/2009	205756	Adjust rear door	Adjusted	180711
8230	1/5/2009	205153	Replace tyre pos 34 - bald	Replaced	179351
8230	1/2/2009	205117	Change N/S/R tyres	Changed	178978
8230	1/2/2009	205117	The raise and lower bus button doesn't work properly	Checked OK	178978
8230	1/2/2009	205091		A Service	178978
8230	1/2/2009	205091		Grease AC Compressor Clutch Bearing	178978
8230	1/2/2009	205091		Tension Wheel Nuts To OEM Specification	178978
8230	1/2/2009	205091		A Service	178978
8230	#####	204842	No water in wipers	Topped up water	178240
8230	#####	204842	No water in wipers	Topped up water	178240
8230	#####	204540	A/C button defective	Wire in new A/C button	176686
8230	#####	204540	The A/C button is broken cant use it customers complain		176686
8230	#####	204367	TOP ALT BELT MERC 0500+FAN BELT A/C ARTIC		176024
8230	#####	204367	Replace belt	Replaced	176024
8230	#####	204367	Replace belt	Replaced	176024
8230	#####	204387	Refill coolant	Refilled	176024
8230	#####	202941	CLEARANCE LIGHTS 250106	Creditor #VOL001 VOLGREN AUSTRALIA P/L P/O #:G62371 Receiving #:64372 Date :2008-12-11 230	172978
8230	#####	203466	Graffiti on window floor & seat of bus	Cleaned graffiti on seats window & floor	172755
8230	12/4/2008	202941	Ops Entered - Wipers & Washers	Checked OK	171174
8230	12/4/2008	202941	Front clearance lights dull	Replaced front clearance lights	171174
8230	12/3/2008	202887	Ops Entered - Wipers & Washers	Replaced windscreen washer motor	170850
8230	12/3/2008	202887	PUMP WIPER-WASHER 24 VOLT		170850
8230	#####	202527	Annual Random Audit	Completed	169883
8230	#####	202427	AIR FILTER MERC 0500LE		169883
8230	#####	202427	OIL FILTER 1725+0500LE		169883
8230	#####	202427	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		169883
8230	#####	202427		Tension Wheel Nuts to Spec	169883
8230	#####	202427		A Service	169883
8230	#####	202427		D-Service	169883
8230	#####	202427		Tension Wheel Nuts To OEM Specification	169883
8230	#####	202427		A Service	169883
8230	#####	202170	Warning light came up on dash twice TCO 1000	Checked all connections on dash computer	169192
8230	#####	202170	Warning light came up on dash twice TCO 1000	Checked out warning codes checked dash and computers ordered parts for lights	169192
8230	11/7/2008	200258	Wiper hanging off	secured wipers mounting	163360
8230	11/6/2008	182516	REPLACE SCREEN	Creditor #ELI001 ELITE WINDSCREENS P/O #:G61468 Receiving #:63361 Date :2008-11-06	163159
8230	11/5/2008	182516	Broken windscreen	Replaced by Elite	162887
8230	11/4/2008	200049	LED CLEARANCE LIGHT (RED AMBER)		162887
8230	11/4/2008	200049	Replace LED clearance R/H	Replaced	162887
8230	#####	182125	Windscreen washer needs water	Filled	162039
8230	#####	182125	G/box cool pipe leaks small hole	Checked OK	162039
8230	#####	182125	BRAZILIAN MIRROR L/H		162039
8230	#####	182125	Replace N/S mirror	Replaced	161976
8230	#####	182125	Clean graffiti	Cleaned	162039

8230	#####	182125	Clean graffiti	Cleaned	161976
8230	#####	182038	AIR FILTER MERC 0500LE		162039
8230	#####	182038		A Service	162039
8230	#####	182038		Tension Wheel Nuts to OEM Specification	161976
8230	#####	182038		A Service	161976
8230	10/8/2008	176135	COOLANT PIPE	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #G59440 Receiving #:62577 Date :2008-10-08	155970
8230	10/3/2008	178232	COMPRESSOR OIL AIR CON		154836
8230	10/3/2008	178232	FILTER DRIER THERMO KING		154836
8230	10/1/2008	179549	BELT BOTTOM ALTERNATOR MERC 0500LE		154090
8230	10/1/2008	179549	TOP ALT BELT MERC 0500+FAN BELT A/C ARTIC		154090
8230	10/1/2008	179549	Replace fan belt	Replaced	154090
8230	10/1/2008	179625	Breakdown - Stud Rd - OUT 7.00 am BACK 7.45 am - No belts	C/O bus 234. Returned and replaced belts & aligned pulleys	154090
8230	9/23/2008	178972	Replace pole bolt f/door	Replaced	152392
8230	9/23/2008	178972	Replace rear bumper bolt & tighten	Replaced	152392
8230	9/23/2008	178881		A Service	152608
8230	9/23/2008	178881		Tension Wheel Nuts to OEM Specification	152392
8230	9/23/2008	178881		A Service	152392
8230	9/19/2008	178737	Replace booster hose	R/tested and fitted hose	151165
8230	9/18/2008	178400	Air conditioning filter needs replacing	REPLACED	150925
8230	9/18/2008	176135	Service	REPLACED BOTH LEAKING COOLANT PIPES	151165
8230	9/18/2008	176135	Service		151165
8230	9/16/2008	178232		B Service	150489
8230	9/16/2008	178232		Replace filter drier	150489
8230	9/16/2008	178232		Replace compressor oil	150489
8230	9/16/2008	178232		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	150489
8230	9/16/2008	178232		CONDENSOR AREA: Clean condensor coils; check boltsclamps for tension	150489
8230	9/16/2008	178232		INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condensor motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condensor fan grills	150489
8230	9/16/2008	178232		EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check boltsclamps & fittings; clean condensate drains; clean drip tray	150489
8230	9/16/2008	178232		REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	150489
8230	9/16/2008	178232		COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	150489
8230	9/16/2008	178232		DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	150489
8230	9/16/2008	178232		DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	150489
8230	9/16/2008	178232		COMPRESSOR DRIVE BELTS: inspect belt wear; Retension belts;	150489
8230	9/16/2008	178232		FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	150489
8230	9/16/2008	178232		Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	150489
8230	9/7/2008	177600	Drv entered - Engine Lacking Power	R/tested OK	148549
8230	9/5/2008	177475	Ticket machine needs full service does not give end portion	Checked OK	147804
8230	8/22/2008	176135	Same pipe coolant leak near heater tap	filled with coolant and checked pipe	144914
8230	8/21/2008	176144	Replace indicator lamp	Replaced	145125
8230	8/21/2008	176144	INDICATOR LAMP SUIT B12BLE		144914
8230	8/21/2008	176144	GLOBE INDICATOR 24V-18W SINGLE CONTACT		144914
8230	8/21/2008	176144	Replace indicator lamp		144914
8230	8/21/2008	176135	Coolant leak from coolant pipe goes to g/box oil cooler- pi	Replaced	144914
8230	8/21/2008	175770	Direct Purchase - BODYWORK	REPLACED BOTH PIPES	144914
8230	8/20/2008	176121	L/H MIRROR ARM LONG (PM8844-1)	Creditor #:TIN002 TINT FX P/O #G59289 Receiving #:61253 Date :2008-08-21 Tint front windscreen and front doors	144914
8230	8/20/2008	176121	L/ mirror taken off		144914
8230	8/20/2008	176121	L/ mirror taken off	Replaced mirror	144674
8230	8/16/2008	175731	Inspect for driveline warranty - Due on 1/8/08	Assist. with mirror	143559
8230	8/16/2008	175770	Tint windscreen & front door glasses.	Completed	143882
8230	8/13/2008	175513	Remove graffiti	Completed by Tint FX	143063
8230	8/13/2008	175423		Removed	143063
8230	8/13/2008	175423	WEDGE GLOBE INSTRUMENT 24V 3W	A Service	143063
8230	8/13/2008	175423			143063
8230	8/13/2008	175423		A Service	141403
8230	8/7/2008	175006	GLOBE HIGH BEAM	Tension Wheel Nuts to OEM Specification	141403
8230	8/7/2008	175006	Replace headlight	Replaced	141403
8230	7/30/2008	161456	DECALS	Creditor #:ATT001 ATTITUDE SIGNS P/O #G53317 Receiving #:60661 Date :2008-07-30	139744
8230	7/28/2008	174123	GLOBE HIGH BEAM		138999
8230	7/28/2008	174123	Drivers side headlight	Replaced	138637
8230	7/10/2008	172843	Replace wiper blades	Replaced	133849
8230	7/10/2008	172697	WIPER REFILL SUIT TX800+TX900		133978
8230	7/10/2008	172697		A Service	133849
8230	7/10/2008	172697		Tension Wheel Nuts to OEM Specification	133849
8230	7/8/2008	172528	Replace park light globe	Replaced	133204
8230	7/8/2008	172528	LED CLEARANCE LIGHT (RED AMBER)		133204
8230	7/8/2008	172542	L/back clearance light is broken	Replaced broken side light	133204
8230	7/2/2008	170831	TOW BUS TO DEPOT	Creditor #:ASS001 ASSOCIATED TOWING P/O #G57377 Receiving #:50900 Date :2008-07-02	131290
8230	7/1/2008	170280	POS 3+4+5	Creditor #:BEA001 BEAUREPARES P/O #G57145 Receiving #:50846 Date :2008-07-01	130964
8230	6/23/2008	171360	Door not closing properly	Set sensitive edge	128069
8230	6/18/2008	170980	AIR DRYER REPAIR KIT MAN NL202		127608
8230	6/18/2008	170980	Rekit air dryer	Rekitted air dryer adjusted front door sensitive edge	127339
8230	6/17/2008	170831	Breakdown - Oakleigh Station - OUT 8.30 pm BACK 1.00 am - N	C/O bus 237. Air leaking out of air dryer. Towed bus back to depot	127339
8230	6/12/2008	149066	AIR CONDITIONING REPAIR	Creditor #:SOL005 SOUTHERN STATES THERMO KING P/O #G49087 Receiving #:50348 Date :2008-06-12	126261
8230	6/12/2008	169163	ROAD SAFETY INSPECTIONS	Creditor #:ROA001 Road Safety Inspections P/O #G56489 Receiving #:50346 Date :2008-06-12	126261
8230	6/11/2008	170376	Tyres have flat spots	Changed rear tyres pos 3-4-5-6	125937
8230	6/11/2008	170280	Replace tyres pos.34 & 5 - worn & flat spots.	rep. tyres pos. 34 & 5 worn & flat spots	125937
8230	6/11/2008	170376	Replace N/S rear side light	Replaced	125937
8230	6/10/2008	170232	Check gearbox overheating.	R/tested could not find fault not over heating checked coolant and with testman not any fault code	125744
8230	6/10/2008	170232	LED CLEARANCE LIGHT (RED AMBER)		125937
8230	6/10/2008	170232	Replace LED	Replaced	125937
8230	6/6/2008	169994	Repair rear door sensitive edge-not working.	Adjusted rear door sensor	124934
8230	6/6/2008	169994	Could you please fit ticket light above till	checked o/k	125348
8230	6/6/2008	169994	Could you please fit ticket light above till	checked o/k	125348
8230	6/6/2008	169991	AIR FILTER MERC 0500LE		124934
8230	6/6/2008	169991	OIL FILTER 1725+0500LE		124934
8230	6/6/2008	169991	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		124934
8230	6/6/2008	169991		Tension Wheel Nuts to Spec	124934
8230	6/6/2008	169991		A Service	124934
8230	6/6/2008	169991		D-Service	124934
8230	6/6/2008	169991		Tension Wheel Nuts to OEM Specification	124934
8230	6/6/2008	169991		A Service	124934

8230	6/4/2008	140680	Warranty	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G44397 Receiving #:50092 Date :2008-06-04 Fault code - INS 0508	124480
8230	6/4/2008	137192	WARRANTY	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G41811 Receiving #:50094 Date :2008-06-04 COOLANT LEAK AT SENSOR HEADER TANK	124480
8230	6/4/2008	137192	WARRANTY	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G41811 Receiving #:50094 Date :2008-06-04 Top alternator bracket cracked	124480
8230	6/4/2008	126415	5000KLM WARRANTY SERVICE	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:36351 Receiving #:50069 Date :2008-06-04	124480
8230	6/4/2008	140367	EXP TANK SENDER LEAKING	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G44191 Receiving #:50076 Date :2008-06-04	124480
8230	6/1/2008	169163	Road Safety Inspections BC 107480	Road Safety Inspections BC 107480	122886
8230	5/31/2008	169574	Please check the speedo	R/tested and checked OK	123741
8230	5/28/2008	169121	A/C BELT 0500 BENZ		122886
8230	5/28/2008	169121	TOP ALT BELT MERC 0500+FAN BELT A/CARTIC		122886
8230	5/28/2008	169121	Engine oil leak (checked on 16/08/07 servicable HKS)	Checked OK	122886
8230	5/28/2008	169121	Drv entered - Whls & Tyres Foreign Body	R/tested cleaned tyres	122886
8230	5/28/2008	169121	Boost pump leak	Repaired	122886
8230	5/28/2008	169121	Steamclean all bus	Cleaned	122517
8230	5/28/2008	169121	WATER SEPERATOR SCANIA+VOLVO		122886
8230	5/28/2008	169121	Replace angle drive oil	Replaced	122886
8230	5/28/2008	169121	Clean & rekit oil seperator	Rekitted	122886
8230	5/28/2008	169121	Remove charge air cooler and clean radiator	Completed	122886
8230	5/22/2008	166962	POS 6	Creditor #:BEAD001 BEAUREPAIRES P/O #:G55291 Receiving #:49653 Date :2008-05-22 NEW	121662
8230	5/22/2008	168599	Paint exterior mirrors and arms	Painted	121662
8230	5/22/2008	168599	Replace interior decals - N/S disabled eat or drinking	Replaced	121662
8230	5/22/2008	168599	Clean air condition filter secure vents	Cleaned	121662
8230	5/22/2008	168599	Secure replace passenger seats arm rest & hand grips N/S 8	Secured	121662
8230	5/22/2008	168599	Replace secure seat cushions - rear seat	Replaced	121662
8230	5/22/2008	168599	Hand rails secure rivet N/S/F 1 floor	Rivetted	121662
8230	5/22/2008	168599	Wheel chair ramp - operation and clean - hits front door ha	Cleaned	121662
8230	5/22/2008	168599	Replace air supply decal	N/A	121662
8230	5/22/2008	168599	Replace safety triangle decal - on d/shield new buses	Replaced	121662
8230	5/22/2008	168599	Replace visual check list decal	N/A	121298
8230	5/22/2008	168599	AMBER REFLECTOR SIDE MOUNT		121847
8230	5/22/2008	168599	SAFETY TRIANGLE DECAL		121847
8230	5/22/2008	168599	Replace dash warning light decal	N/A	121662
8230	5/22/2008	168599	Paint till stand	Painted	121662
8230	5/22/2008	168599	Safety triangles and decals - replace	Replaced	121662
8230	5/22/2008	168599	Paint door handles - front touch up	Painted	121662
8230	5/22/2008	168599	Polish exterior panels/headers - N/S/R O/S 6-7-8	Polished	121662
8230	5/22/2008	168599	Replace side reflectors (even no's) - N/S	Replaced	121662
8230	5/22/2008	168599	Secure all lower skit panels	Secured	121662
8230	5/22/2008	168599	Secure front door seals No 1	Secured	121662
8230	5/22/2008	168599	O/S/F bar - damaged N/S/R glass rubber top - N/S/R side i	Replaced	121662
8230	5/13/2008	167839		R5i inspection	119337
8230	5/13/2008	167839		Remove disassemble and clean air cyclone seperater (Apply water repellent grease to electrical connection) Check drainage function for leaks	119337
8230	5/13/2008	167839		Check and clean cartridge in dry tyre air cleaner	119337
8230	5/13/2008	167839		Replace pre and main fuel filters	119337
8230	5/13/2008	167839		Replace air dryer canister clean silence and drain reservoir	119337
8230	5/13/2008	167839		Replace angle drive oil	119337
8230	5/13/2008	167839		Test coolant level - top up if required to equate to 37C frost protection	119337
8230	5/13/2008	167839		Adjust engine valve clearances 0.4MM INLET 0.6MM EXHAUST SONM TORQUE AFTER ENG HAS COOLED FOR 30 MIN.	119337
8230	5/13/2008	167839		Replace power steering filter and check level (Replace oil if required)	119337
8230	5/13/2008	167839	FUEL FILTER MERC 0500LE		119337
8230	5/13/2008	167839	FUEL FILTER 0500LE		119337
8230	5/13/2008	167839	AIR DRYER CANISTER MAN NL202+VOLVO		119337
8230	5/13/2008	167839	POWER STEER FILTER B10M		119337
8230	5/13/2008	167839		Replace final drive oil	119337
8230	5/13/2008	167839		Electrical - Batteries - Check fluid level (leave air gap when topping up) Cables - Check cables connection are firm with good contact on all battery terminals	119337
8230	5/13/2008	167839		Inspect radiator and charge air cooler for dirt - clean	119337
8230	5/13/2008	167839		Check oil level in transmission - top up if required	119337
8230	5/13/2008	167805	Annual body check list.	Completed	119337
8230	5/13/2008	167713	LED CLEARANCE LIGHT (RED AMBER)		119337
8230	5/12/2008	167713	Left clearance light	Replaced light	119337
8230	5/6/2008	167317	Annual random vehicle audit.	Cancelled not due till December	117315
8230	5/6/2008	167287		Tension Wheel Nuts To OEM Specification	117315
8230	5/6/2008	167287		A Service	117315
8230	5/2/2008	166962	Replace tyre pos 6 - flat	Replaced	116185
8230	5/1/2008	166815	WATER SEPERATOR SCANIA+VOLVO		116185
8230	5/1/2008	166815	O RING OIL SEPERATOR VOLVO+SCANIA		116185
8230	5/1/2008	166815	O RING REAR HUB+BOTTOM KING PIN		116185
8230	5/1/2008	166815	Replace lower alternator pulley and belt to suit 6PK	Overhauled seperator valve fit at w/horse	116185
8230	5/1/2008	166815	Replace lower alternator pulley and belt to suit 6PK	Replaced by Whitehorse	116185
8230	5/1/2008	166905	No broom	Fitted	116185
8230	4/30/2008	166696	Interior lights not working	Checked OK	115856
8230	4/30/2008	166696	Interior lights not working	Checked OK	115856
8230	4/28/2008	166495	GLOBE FESTDOON 24V 3W		115569
8230	4/28/2008	166495	Replace emergency exit globe	Replaced by Abdul	115241
8230	4/27/2008	166484	Adjust door sensitive edge	Adjusted	115241
8230	4/22/2008	163164	Something stuck in a tyre - thump thump	Replaced	113921
8230	4/22/2008	163164	Drv entered - Whls & Tyres Foreign Body	Replaced tyre	113921
8230	4/22/2008	163164	Rear door sensor needs adjusting	Adjust rear door	113921
8230	4/22/2008	163164	Rear door sensor needs adjusting	Adjusted	113921
8230	4/22/2008	163164	Adjust alternator belt	Adjusted	113921
8230	4/11/2008	165259	WEDGE GLOBE INSTRUMENT 24V 3W		111036
8230	4/11/2008	165259	Front L/H parking light not working	Changed headlight globe	110957
8230	4/7/2008	163164	BROOM HANDLE (8232715)		109862
8230	4/7/2008	163164	BROOM HEAD (09803211)		109862
8230	4/7/2008	163164	No broom	Fitted broom	109535
8230	3/31/2008	164177	Service	A Service	107703
8230	3/31/2008	164177		Tension Wheel Nuts To OEM Specification	107551
8230	3/31/2008	164177	Service	A Service	107551
8230	3/22/2008	163164	Fuel guage faulty. Code INS 0508	Replaced fuel tank sender	105821
8230	3/22/2008	163164	Fuel guage faulty. Code INS 0508	Replaced fuel tank sender	104042
8230	3/17/2008	163164	FUEL TANK SENDER	Creditor #:WHT001 WHITEHORSE TRUCKS P/O #:G53846 Receiving #:47827 Date :2008-03-17 230	104280
8230	3/14/2008	163164	Fuel guage faulty. Code INS 0508	Checked out fuel gauge ordered parts	104042

8230	3/5/2008	162519	Accident damaged No 16117 Replace o/s. lower panels No6 & N	Repaired & repainted Ref. o/n. 161450	102404
8230	2/25/2008	161819	TOP ALT BELT MERC 0500+FAN BELT A/C ARTIC		100576
8230	2/25/2008	161819	TOP ALT BELT MERC 0500+FAN BELT A/C ARTIC		100576
8230	2/25/2008	161819	Breakdown - Monash University - OUT 6.30 am BACK 7.00 am - Service	C/O bus 231. Replaced belt and returned polished out runs	100576
8230	2/25/2008	161456	Service	refitted w/airc brush& cleaned up.	100640
8230	2/22/2008	161456	Service	Repainted repaired panels	100576
8230	2/20/2008	161456	Accident damaged Replace o/s/r lower panel & o/s/r.w/a	Manufacture & refit panels	100576
8230	2/20/2008	161456	Accident damaged Replace o/s/r lower panel & o/s/r.w/a		100576
8230	2/20/2008	161456	SCREW TORX 8 X 15MM SIDE PANEL		100576
8230	2/19/2008	161456	Accident damaged Replace o/s/r lower panel & o/s/r.w/a	Panel repair	100576
8230	2/19/2008	161456	Accident damaged Replace o/s/r lower panel & o/s/r.w/a		100576
8230	2/18/2008	161287	TOP ALT BELT MERC 0500+FAN BELT A/C ARTIC		100576
8230	2/18/2008	161287	Bus wont start	Jump started	100576
8230	2/18/2008	161287	Replace alternator belt	Replaced	100576
8230	2/18/2008	161456	Accident damaged Replace o/s/r lower panel & o/s/r.w/a	removed all damaged panelsstart to repair hinge section	100576
8230	2/18/2008	161456	Accident damaged Replace o/s/r lower panel & o/s/r.w/a	removed all damaged panelsstart to repair hinge section	100576
8230	2/17/2008	161277	Replaced top alternator belt	rep. top alternator belt	100576
8230	2/7/2008	158191	WARRANTY CHECKG/BOX	Creditor #EAS002 EASTSIDE TRUCK & BUS SERVICE P/O #G52891 Receiving #46978 Date :2008-02-07	98437
8230	2/1/2008	160055	NARVA 24V REVERSING BUZZER		97479
8230	2/1/2008	160055	Replace reversing buzzer	Replaced	97479
8230	2/1/2008	150067	FILTER DRIER THERMO KING		97695
8230	2/1/2008	160000	Service	A Service	97479
8230	2/1/2008	160000	Service	Tension Wheel Nuts To OEM Specification	97479
8230	2/1/2008	160000	Service	A Service	97479
8230	1/18/2008	159049	Gearbox drops into neutral driving along power off to rest	Repairs done under warranty fromEastcoast	96171
8230	1/18/2008	159049	Gearbox drops into neutral driving along power off to rest	rchecked with technician from Eastcoast truck still unable to locate fault with r/needsneedsto repairs to g/box valve body.	96171
8230	1/14/2008	158191	WARRANTY CHECK G/BOX	Creditor #EAS002 EASTSIDE TRUCK & BUS SERVICE P/O #G52040 Receiving #46291 Date :2008-01-14	95940
8230	1/9/2008	158176	A/C. Fault light on.	Unit had no refrigerant pressure tested leak in engine bay	95665
8230	1/9/2008	158191	Check transmission faults come up - AGN 2712 loses gears.	Checked for not selecting gears but couldn't find fault cleaned connector plug	95757
8230	1/9/2008	158191	Check transmission faults come up - AGN 2712 loses gears.	Repaired by Eastside	95757
8230	1/8/2008	158210	Breakdown - Monash University - OUT 12.00 noon BACK 12.45 p	C/O bus 231. Returned to depot	95665
8230	1/7/2008	158097	Driver complain when bus stops will not move again	Cleaned the front ramp road tested OK	95416
8230	1/5/2008	157923	Fault light comes up on dash (A G L 2712)	R/Tested all systems o/r.	95259
8230	#####	157151	ADJUST TOP ALTERNATOR BELT.	adjust top alk belt	92122
8230	#####	156115	POS 4+5+6	Creditor #BEAD01 BEAUREPAIRES P/O #G51439 Receiving #45780 Date :2007-12-19	91310
8230	#####	156115	Replace tyre pos. 5 6 & 4 - Worn	Rep. tyres pos.45 & 6 Worn	88719
8230	#####	156130	O/S/R inner tyre needs replacing (No tyres left in stock -	Checked ok	88719
8230	#####	156130	Replace rear tyres 645	Replace tyres	88719
8230	#####	156130	LED CLEARANCE LIGHT (RED AMBER)		88821
8230	#####	156130	My CD stuck in the player - can you remove it	Checked ok	88719
8230	#####	156130	Radio pushed inside the dash	Checked ok	88719
8230	#####	156041		Service T - Replace Transmission Oil & Filter	88821
8230	#####	156041	FILTER TRANSMISSION ZF 4139-298-038	ZF Transmission Filter	88719
8230	#####	156041	ZF SYNTHETIC GEARBOX OIL ECO FLUID A PLUS	ZF Ecofluid A Plus Synthetic Transmission Oil	88719
8230	#####	156041		Service T - Replace Transmission Oil & Filter	88719
8230	#####	156041		A Service	88821
8230	#####	156041		Tension Wheel Nuts To OEM Specification	88719
8230	#####	156041		A Service	88719
8230	12/9/2007	156090	Rep. l.e.d light n.s/r.	rep. l.e.d light n/s/r.	88414
8230	12/8/2007	154400	PUNCTURE POS1	Creditor #BEAD01 BEAUREPAIRES P/O #G50825 Receiving #45521 Date :2007-12-08	88031
8230	#####	153598	Direct Purchase - TYRES	Creditor #BEAD01 BEAUREPAIRES P/O #G50518 Receiving #45189 Date :2007-11-27 Pos 3	84756
8230	#####	154867	Fault code on = F R 1125 (LOST BELTS ON FRIDAY BREAKDOW	Repaired broken wire on alternator	84497
8230	#####	154867	Fault code on = F R 1125 (LOST BELTS ON FRIDAY BREAKDOW	Checked out alternator	84497
8230	#####	154856	TOP ALT BELT MERC 0500+FAN BELT A/C ARTIC		84497
8230	#####	154856	Breakdown Jacksons Rd. Mulgrave a/c. belts off.Left at 5.30	C/O. BUS & RETURNED TO DEPOT & REPLACED ALTERNATOR BELTS.	84497
8230	#####	154400	Replaced tyre pos. 1 - Puncture (flat)	Rep. tyre pos. 1 - flat	82561
8230	#####	154444	rep. o/s/r. tyre (punctured)	rep.o/s/r. tyre	82561
8230	#####	153977	GLOBE INDICATOR 24V-18W SINGLE CONTACT		81591
8230	#####	153977	INDICATOR LAMP SUIT B12BLE		81591
8230	#####	153977	Side front indicator lens broken	Replaced broken flasher light	81264
8230	11/7/2007	153520	MIRROR TOP BRAZILLIAN GLASS		80138
8230	11/7/2007	153520	Service		80138
8230	11/7/2007	153598	Replace pos 3	Replaced	80138
8230	11/7/2007	153610	Replace N/S/R outer tyre	Replaced	80138
8230	11/7/2007	153610	Replace N/S/R outer tyre	Replaced	80138
8230	11/7/2007	153561	AIR FILTER MERC 0500LE		80138
8230	11/7/2007	153561	OIL FILTER 1725+0500LE		80138
8230	11/7/2007	153561	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL		80138
8230	11/7/2007	153561		Tension Wheel Nuts to Spec	80138
8230	11/7/2007	153561		A Service	80138
8230	11/7/2007	153561		D-Service	80138
8230	11/7/2007	153561		Tension Wheel Nuts To OEM Specification	80138
8230	11/7/2007	153561		A Service	80138
8230	#####	152978	Retarder lights on dash	Replaced cover on switch for retarder	78388
8230	#####	152523	MOVE SCREEN	Creditor #VOL001 VOLGREN AUSTRALIA P/L P/O #G50188 Receiving #44512 Date :2007-10-24	77903
8230	#####	152523	Move driverscreen		77903
8230	#####	151858	Replace top alt belt	Replaced	75452
8230	#####	151928	FAN BELT A/C ARTIC	C/O..BUS & REPLACED A/C. BELTS ON SITWELLINGTON RD.	75801
8230	#####	151928	A/C BELT 0500 BENZ	C/O..BUS & REPLACED A/C. BELTS ON SITWELLINGTON RD.	75801
8230	#####	151928	Breakdown - A/C. belts split Wellington Rd.left at 10.30a	C/O..BUS & REPLACED A/C. BELTS ON SITWELLINGTON RD.	75801
8230	#####	151858	Replace top alt belt	Replaced	75452
8230	#####	151657	GLOBE HIGH BEAM		74465
8230	#####	151657	L/H headlight out	Replaced globe	74465
8230	10/3/2007	150888	CD/Radio not working	Ass Greg with fixing radio in position	71751
8230	10/3/2007	150888	CD/Radio not working	Repaired wires on radio refit in dash	71751
8230	9/25/2007	150268		A Service	69753
8230	9/25/2007	150268		Tension Wheel Nuts To OEM Specification	69753
8230	9/25/2007	150268		A Service	69753
8230	9/24/2007	150067	Service as per list	Trace fault light back to worn wire on comp	69543
8230	9/24/2007	150067	FUSE BLADE 10AMP		69753
8230	9/24/2007	150067		UNIT PERFORMANCE TEST: Run unit & check gas charge; check condensor pressure switches; check evaporator auto fan speed; check de-ice cut out/in; check operation of fresh air ram; check electrical centre connections lights and operation	69543

8230	9/24/2007	150067	CONDENSOR AREA: Clean condenser coils; check bolts/clamps for tension	69543
8230	9/24/2007	150067	INSPECT MOTORS & BRUSHES: Blow out carbon dust on all evaporator & condenser motors; check brush wear; check blower motor wheels & clean; check mounting brackets; check electrical connections; check condenser fan grills	69543
8230	9/24/2007	150067	EVAPORATOR AREA: Clean evaporator coils; check water valves & pipes; check bolts/clamps & fittings; clean condensate drains; clean drip tray	69543
8230	9/24/2007	150067	REFRIGERATION FILTER DRYER: Replace filter dryer; check pump operation;	69543
8230	9/24/2007	150067	COMPRESSOR: Carry out efficiency test; check unloader control; check L/P switch operation; check H/P switch operation; check suction hose; check discharge hose	69543
8230	9/24/2007	150067	DRIVE PULLEY'S: IDLER PULLEY - inspect idler bearings; inspect idler pulley for wear; inspect idler post & bush for wear	69543
8230	9/24/2007	150067	DRIVE PULLEY'S: CLUTCH - inspect clutch bearing; inspect clutch pulley for wear; inspect clutch air gap;	69543
8230	9/24/2007	150067	COMPRESSOR DRIVE BELTS: inspect belt wear; Retension belts;	69543
8230	9/24/2007	150067	FUNCTION TEST A/C: Check heat & cool modes; Check set point (21.5 C)	69543
8230	9/24/2007	150067	Clean R/A & F/A filters; Inspect and report on condition; Replace filter media	69543
8230	9/17/2007	145682	BRAZILLIAN MIRROR RH	69052
8230	9/17/2007	145682	Broken driver mirror	68845
8230	9/14/2007	149428	LED CLEARANCE LIGHT (RED AMBER)	68845
8230	9/14/2007	149428	Replace LED lamp	68393
8230	9/13/2007	149371	GLOBE HIGH BEAM	68393
8230	9/13/2007	149371	O/S headlight blown	68393
8230	9/10/2007	149066	Air con not working	66476
8230	9/10/2007	149066	Drv entered - Air Cond Cooling Fault Light	66476
8230	9/1/2007	148493	Reverse buzzer not working	65127
8230	8/24/2007	147777	A/C Fault light	64005
8230	8/23/2007	147835	Check belts.	63833
8230	8/21/2007	147492	LED CLEARANCE LIGHT (RED AMBER)	63253
8230	8/21/2007	147492	Rear left side blinker cracked	63253
8230	8/20/2007	147436	Rear left side blinker cracked	62869
8230	8/20/2007	147336	Check clearance lenses	62869
8230	8/16/2007	147077		61628
8230	8/16/2007	147077		61628
8230	8/16/2007	147077		61628
8230	7/22/2007	144977	Radio is not working	55877
8230	7/17/2007	144659	Breakdown - Stud Rd - OUT 4.30 pm BACK 5.45 pm - L/H mirror	54192
8230	7/12/2007	144290	Secure N/S/R mirror	52955
8230	7/10/2007	144078	FUSE BLADE 10AMP	52578
8230	7/10/2007	144078	A/C. Fault light stays on.	52578
8230	7/10/2007	144072		52578
8230	7/10/2007	144072		52578
8230	7/10/2007	144072		52578
8230	7/3/2007	143466	Coolant leak near O/S/R air tanks	50889
8230	6/7/2007	141612	Check for air leaks at rear - middle front of diff	45710
8230	6/6/2007	140905	ROAD SAFETY INSPECTIONS	45329
8230	6/3/2007	140905	Annual Inspection - BC 106344	44772
8230	5/31/2007	141164	Polish front bumper bar	44772
8230	5/31/2007	141164	Put new yellow strip in back	44772
8230	5/30/2007	140880	Oil leak around bell housing(warranty)	44772
8230	5/30/2007	140880	Replace A/C belt	44670
8230	5/30/2007	140880	A/C BELT 0500 BENZ	44772
8230	5/30/2007	140880	Missing bolt in exhaust manifold shield	44772
8230	5/30/2007	140880	Oil leak near bellhousing	44772
8230	5/30/2007	140880	Full steamclean	44772
8230	5/30/2007	140880	Coolant leak behind balancer dripping down	44772
8230	5/30/2007	140880	Coolant leak from tap near gearbox cooler	44772
8230	5/30/2007	140880	Coolant leak near O/S/R air tanks	44772
8230	5/30/2007	140880	Coolant leak on heater tap behind gearbox	44772
8230	5/30/2007	140875	Replace Safety School Crossing decal	44772
8230	5/30/2007	140875	POWDER COATED NOTICE BOARDS	44772
8230	5/30/2007	140875	Replace front door - Entry Only decal	44772
8230	5/30/2007	140875	Safety triangles and decals - behind drivers m panel	44772
8230	5/30/2007	140875	Replace Visual Check List decal	44772
8230	5/30/2007	140875	Replace Do Not Overtake decal - N/S/R corner door	44772
8230	5/30/2007	140880	Replace Exit Only on rear doors	44772
8230	5/30/2007	140957	Paint exterior mirrors and arms	44772
8230	5/30/2007	140957	Clean air condition filter secure vents	44772
8230	5/30/2007	140957	secure drivers compartment door catch	44772
8230	5/30/2007	140875	DO NOT OVERTAKE TURNING DECAL	44772
8230	5/30/2007	140875	SAFETY TRIANGLE DECAL	44772
8230	5/30/2007	140875	Replace Give Way decal - O/S/R corner window	44772
8230	5/30/2007	140875	Replace Safety Triangle decal - on d/shield new buses	44772
8230	5/30/2007	140875	Replace Drivers Seat decal	44772
8230	5/30/2007	140875	Replace Fleet Number on dash - in yellow	44772
8230	5/30/2007	140957	Secure all lower skit panels	44772
8230	5/30/2007	140875	Paint till stand	44670
8230	5/30/2007	140875	GIVE WAY SIGN (SMALL)	44772
8230	5/30/2007	140957	Paint & repair front bumper bar	44772
8230	5/30/2007	140957	Polish out scrape marks No 1 N/S panel & replace rear of fr	44772
8230	5/30/2007	140957	Repair & repaint rear bumper bar - refit N/S/R clip in strip	44772
8230	5/30/2007	140957	Polish & touch up O/S lower panel No5 & No6	44772
8230	5/26/2007	140680	INS 0508 fault code comes on when the fuel gauge drops to e	44342
8230	5/24/2007	140620	FAN BELT A/C ARTIC	44342
8230	5/24/2007	140620	Fan belt off	44300
8230	5/22/2007	140447	FAN BELT A/C ARTIC	44271
8230	5/22/2007	140447	Ops Entered - Engine	44271
8230	5/22/2007	140367	Repair/replace sender on header tank leaks coolant - Warr	44271
8230	5/18/2007	140207	DRIVERS SUN BLIND FRONT LEFT UPPER SUPPORT ARM IS U/S.	43739
8230	5/16/2007	139901	RSI inspection	43535
8230	5/16/2007	139901	Electrical - BATTERIES: check fluid level (leave air gap when topping up) CABLES: check cable connections are firm with good contact on ALL battery terminals	43535
8230	5/16/2007	139901	Inspect radiator & charge-air cooler for dirt - clean if required	43535
8230	5/16/2007	139901	Check oil level in transmission & top-up if required	43535
8230	5/16/2007	139901	Remove disassemble & clean cyclone separator (apply water repellant grease to electrical connections) check drainage function for leaks	43535
8230	5/16/2007	139901	Check & clean filter cartridge in dry-type air cleaner	43535
8230	5/16/2007	139901	Check power steering oil level	43535
8230	5/16/2007	139901	Change pre and main fuel filter	43535
8230	5/16/2007	139901	Change air drier cannister; clean silencer & drain air reservoir	43535

8230	5/16/2007	139901	Change oil in fan angle drive	43535
8230	5/16/2007	139901	Top-up coolant level (must equate to -37C frost protection)	43535
8230	5/16/2007	139901	Adjust Engine Valve Clearance	43535
8230	5/16/2007	139921	Annual body check	43654
8230	5/15/2007	139892	Completed	43654
8230	5/15/2007	139892	A Service	43535
8230	5/15/2007	139892	Tension Wheel Nuts To OEM Specification	43535
8230	5/14/2007	139784	Repaired by Thermoking	43441
8230	5/14/2007	139784	Drv entered - Air Cond Air Conditioner	43441
8230	5/14/2007	139784	Air conditioner not working.	43441
8230	5/14/2007	139865	AM/FM radio has slipped down into the dash board	43441
8230	5/7/2007	139199	Removed and refitted	42881
8230	5/7/2007	139199	Fit new front door sensor and adjust	42881
8230	5/7/2007	139199	Fuel gauge not working	42881
8230	5/7/2007	139199	Checked OK	42881
8230	5/7/2007	139199	Coolant leak at heater tap beside radiator/fan shroud	42881
8230	5/7/2007	139199	Retarter light on not going off	39812
8230	4/24/2007	138329	No broom	36561
8230	4/10/2007	137192	Coolant leaks at bottom of header tank from sensor	36561
8230	4/10/2007	137192	Top alternator mounting bracket cracked	36561
8230	4/10/2007	137191	Replaced by Whitehorse	36561
8230	4/10/2007	137191	Replace top alternator bolts x3 realign belt and tension	36561
8230	4/10/2007	137191	Replaced alternator mount bolts and replaced broken one	36561
8230	4/10/2007	137191	Cleaned	36561
8230	3/31/2007	136671	Steam clean engine	35565
8230	3/28/2007	136391	Please check speedo. Speedo showing lower than it seems	34753
8230	3/28/2007	136391	Replace engine bay lamp light globes	34753
8230	3/28/2007	136391	Replaced	34753
8230	3/28/2007	136340	GLOBE INDICATOR 24V21W SINGLE CONTACT	34753
8230	3/28/2007	136340	D-Service	34753
8230	3/28/2007	136340	A Service	34753
8230	3/28/2007	136340	Tension Wheel Nuts to Spec	34753
8230	3/28/2007	136340	ENGINE OIL DELO 400 15W-40 MULTIGRADE/ NEW OIL	34753
8230	3/28/2007	136340	OIL FILTER 1725+0500LE	34753
8230	3/28/2007	136340	AIR FILTER MERC 0500LE	34753
8230	3/28/2007	136340	AIR FILTER MERC 0500LE	34753
8230	3/28/2007	136340	A Service	34753
8230	3/28/2007	136340	Tension Wheel Nuts To OEM Specification	34753
8230	3/22/2007	135903	Repaired by Thermoking	33066
8230	3/22/2007	135903	A/C not working	33066
8230	3/22/2007	135903	Ops Entered - Air Cond	33248
8230	3/22/2007	135903	Ops Entered - Air Cond	33066
8230	3/22/2007	135903	FAN-HUB BELT SCANIA 12.5X1330MM & Lower 0500 Benz	33248
8230	3/22/2007	135989	Breakdown - Springvale Rd & Wellington Rd - OUT 5.00 pm BAC	33066
8230	3/22/2007	135916	LED CLEARANCE LIGHT (RED AMBER)	33066
8230	3/22/2007	135916	Replace N/R marker light	33066
8230	3/13/2007	135112	Replaced	30412
8230	3/13/2007	135112	Replace side marker	30412
8230	3/13/2007	135112	LED CLEARANCE LIGHT (RED AMBER)	30412
8230	3/9/2007	134932	Repaired by Thermoking	30412
8230	3/9/2007	134932	Drv entered - Air Cond Cooling Fault Light	30412
8230	3/9/2007	134932	Air conditioning system is faulty & red warning light is on.	29595
8230	3/6/2007	134603	Retarter light on not going off	29595
8230	3/6/2007	134603	Retarter light on not going off	29595
8230	3/3/2007	134371	Road tested no fault found	28886
8230	3/3/2007	134371	Retarter light on not going off	28886
8230	3/3/2007	134371	Drv entered - Air Cond Cooling Fault Light	28886
8230	3/3/2007	134371	Air conditioner is u/s.	29256
8230	2/28/2007	134093	Checked OK	29256
8230	2/28/2007	134066	A Service	29256
8230	2/28/2007	134066	Tension Wheel Nuts To OEM Specification	29256
8230	2/28/2007	134066	A Service	29256
8230	2/16/2007	133158	Adjusted & roadtested OK	25862
8230	2/16/2007	130657	Adjust front door sensors	25862
8230	2/16/2007	130657	Retarter light on not going off	25862
8230	2/16/2007	133158	Retarter light on not going off	25862
8230	2/15/2007	133105	Covered retarder switch made up cover and fitted	25536
8230	2/15/2007	133105	Replace alternator belt	25536
8230	2/15/2007	133105	FAN BELT A/C ARTIC	25536
8230	2/5/2007	132181	Replaced	22576
8230	1/30/2007	130657	Retighten coolant hose clamp next to heater taps. Topped up coolant road tested	21872
8230	1/18/2007	131133	Creditor #VOL001 VOLGREN AUSTRALIA P/L P/O #G37818 Receiving #37990 Date :2007-01-30 BUS230	19965
8230	1/16/2007	130876	Repair crack in discharge pipe at reducer vac gas & clean filter fuel & park bus	19296
8230	1/16/2007	130875	Complete	19296
8230	1/16/2007	130875	A Service	19296
8230	1/16/2007	130875	A Service	19296
8230	1/16/2007	130875	Tension Wheel Nuts To OEM Specification	19296
8230	1/12/2007	130678	Tok Van 203 and adjusted sensitive door edge	18487
8230	1/11/2007	130657	Fit new and adjust	18361
8230	1/11/2007	130658	Fit new front door sensor and adjust	18361
8230	1/11/2007	130638	Road tested and checked OK	18361
8230	1/11/2007	130588	C/O bus 235. Returned to depot	18101
8230	1/10/2007	130473	Adjusted	18101
8230	1/10/2007	130473	FAN BELT 12.5X1325MM MERC BOTTOM ALT	18101
8230	1/10/2007	130473	A/C BELT 0500 BENZ	18101
8230	1/10/2007	130473	Replace lower alternator belt & a/c. Belt.	18101
8230	1/10/2007	130466	Left hand mirror	18101
8230	1/10/2007	130466	Left hand mirror keeps moving	14306
8230	#####	129315	Adjusted front and rear doors	14306
8230	#####	129294	Adjusted door sensors	14306
8230	#####	129294	Check/repair front or rear doors not closing properly	13241
8230	#####	128595	C/O bus 235. Left bus for Merc to pick up (warranty)	11237
8230	12/6/2006	128093	Repaired by Thermo King	10803
8230	12/4/2006	127920	Water hammer check and replace elbows as required fit insu	10530
8230	12/2/2006	127860	Doors opens when you push button to shut hold	10530
8230	12/2/2006	127860	Drv entered - Passenger Doors Require Adjusted	9526
8230	#####	127303	Adjust f/door brake	9526
8230	#####	127303	Fitted	9526
8230	#####	127303	Fit wheel nut indicators	9526
8230	#####	127303	32MM LOOSE WHEEL NUT INDICATOR	9526
8230	#####	127303	Checked OK	9526
8230	#####	127303	Drv entered - Air Cond Air Conditioner	9526
8230	#####	127303	Checked OK	9526
8230	#####	127293	A Service	9526
8230	#####	127293	Tension Wheel Nuts To OEM Specification	9526
8230	#####	127293	A Service	9526
8230	#####	126415	Done by whitehorse	6792
8230	#####	126496	Put sikaflex on radio head to secure	6792
8230	#####	126496	Radio needs attention	6792
8230	11/6/2006	125651	Cleared fault code	4274
8230	#####	125207	Tightened both alt belts & top mount plate	2836
8230	#####	124554	New Registration - DN 100820	1200

