
Component Serial Number

VIN

329131

473909C0612236

W1T96342420499866

YEAR

MAKE

MODEL

IN SERVICE

2020

MB

96342422-XAU30

09/07/2021

Vehicle Notes :

Component Serial Number

VIN

329131

473909C0612236

W1T96342420499866

YEAR

MAKE

MODEL

IN SERVICE

2020

MB

96342422-XAU30

09/07/2021

Repair Order History

AmtPriceExtended

SlId : RA971000260:01 Total : \$2,401.52 Date Invoice : 06/29/2022 OdomIn: 222,197 OdomOut: 222,197

Sold Operations

OpsId : 1 Job : 00 Check and report on start hesitation (possible starter motor)

Cause :

Correction : Checked and confirmed starting operation intermittent.

1.00 **STARTER MOTOR** 1,666.66 1,666.66

OpsId : 2 Job : 60 Check and report on front grill broken clips

Cause :

Correction : Fit new front grill

1.00 **FRAME SEGMENT** 117.51 117.51

OpsId : 3 Job : 00 Change air filter as per telligent print out

Cause :

Correction : CARRIED OUT AIR FILTER AS REQUIRED.

1.00 **RS FILTER ELEMENT** 315.54 315.54

1.00 **WORKSHOP SUNDRIES** 0.01 0.01

SlId : RA920029291:02 Total : \$0.00 Date Invoice : 12/24/2024 OdomIn: 627,551 OdomOut: 627,561

Sold Operations

OpsId : 2 Job : 00 PART ADDED TO JOB THAT IS NOT RELATING TO REPAIR AND NO ME

Cause :

Correction :

0.00 **BATTERY SENSOR** 567.93 0.00

SlId : RA920029291:01 Total : \$1,405.82 Date Invoice : 12/19/2024 OdomIn: 627,551 OdomOut: 627,561

Sold Operations

OpsId : 1 Job : 99 OIL LEAK FROM SPINNER

Cause : DEFORMITY OF MATERIAL CAUSING TUBE TO SPLIT FROM TOP AND BYPASS OIL

Correction : Inspected oil spinner

1.00 **OIL SEPARATOR** 1,141.96 1,141.96

1.00 **ELASTOMER METAL SEAL** 13.68 13.68

1.00 **SCREW IN FITTING** 37.50 37.50

0.00 **AARONS DESK** 0.00 0.00

0.00 **AARONS DESK** 0.00 0.00

-1.00 **Adjust Parts Price [[Warranty Only]]** 1.82 -1.82

SlId : RA920027300:01 Total : \$312.52 Date Invoice : 10/09/2024 OdomIn: 591,536 OdomOut: 591,536

Component Serial Number

VIN

329131

473909C0612236

W1T96342420499866

YEAR

MAKE

MODEL

IN SERVICE

2020

MB

96342422-XAU30

09/07/2021

Sold Operations

OpsId : 1 Job : EA AC not working - turns off every 20 minutes-diagnose and advise

Cause :

Correction : C: Signal line for AC compressor had short circuit causing intermittent operation

1.00 **Wiring & terminals for ac wiring repairs** 6.52 6.521.00 **R134A AC GAS** 90.00 90.00

SIsId : RA920026312:01 Total : \$1,002.98

Date Invoice : 08/29/2024

OdomIn: 582,000

OdomOut: 582,003

Sold Operations

OpsId : 1 Job : 83 A/C not activating at all.

Cause : DONE - HP

Correction : COMPLAINT:

OpsId : 2 Job : 99 WIRING REPAIRS TO THE ALTERNATOR

Cause : DONE - HP

Correction : COMPLAINT:

1.00 **ADHESIVE TAPE(ROLL)** 52.98 52.980.00 **stgaging room** 0.00 0.00

SIsId : RA920025153:01 Total : \$1,023.02

Date Invoice : 07/26/2024

OdomIn: 553,991

OdomOut: 553,991

Sold Operations

OpsId : 6 Job : 13 Air tank bracket stripped, PLEASE REF BRENDAN PALMER FOR PAYME

Cause : DONE

Correction : C: Air tank strap stripped on removal, Nut on clamp bolt rounded and spinning in holsters

1.00 **TENSIONING STRAP** 37.99 37.991.00 **TENSIONING STRAP** 37.99 37.990.00 **BAY 4** 0.00 0.00

OpsId : 10 Job : 43 LEAKING BOTH STEER AXLE AIR BRAKE HOSES ON VEHICLE, PLEASE

Cause : DONE

Correction : C: Seals in end fittings on both brake hoses deteriorated due to brake heat

1.00 **BRAKE HOSE** 292.49 292.491.00 **BRAKE HOSE** 282.49 282.494.00 **RETAINING SCREW** 28.89 115.56

SIsId : RA920024651:02 Total : \$871.88

Date Invoice : 07/19/2024

OdomIn: 553,991

OdomOut: 553,991

Sold Operations

OpsId : 9 Job : 14 CRACKED AND DAMAGED HEAT SHEILDS

Cause : DONE

Correction : CRACKED AND DAMAGED HEAT SHEILDS

1.00 **SCREENING PLATE** 287.07 287.071.00 **SCREENING PLATE** 353.81 353.81

SIsId : RA920024651:01 Total : \$13,141.20

Date Invoice : 07/18/2024

OdomIn: 553,991

OdomOut: 553,991

Component Serial Number

VIN

329131

473909C0612236

W1T96342420499866

YEAR

MAKE

MODEL

IN SERVICE

2020

MB

96342422-XAU30

09/07/2021

Sold Operations

OpsId : 7 Job : 18 ENGINE PRESSURIZING

Cause : DONE

Correction : ENGINE PRESSURIZING

2.00	ALM TEST KITS SYDNEY NZ	49.39	98.78
1.00	SET PROTECTIVE COVERS	5.31	5.31
1.00	SET PROTECTIVE COVERS	6.93	6.93
1.00	SET PROTECTIVE COVERS	13.15	13.15
1.00	SET PROTECTIVE COVERS	37.79	37.79
1.00	SET PROTECTIVE COVERS	68.86	68.86
0.00	HCV BAY #4/5 - ZAC S	0.00	0.00
1.00	CYLINDER HEAD GASKET	743.21	743.21
1.00	SEAL	130.03	130.03
1.00	SEAL	130.03	130.03
6.00	SEAL	16.48	98.88
1.00	SEAL	47.64	47.64
1.00	SEAL	46.67	46.67
1.00	METAL SEAL	96.81	96.81
10.00	SEALING RING	4.23	42.30
8.00	SEALING RING	3.46	27.68
8.00	SEALING RING	4.07	32.56
2.00	HIGH PRESSURE LINE	316.26	632.52
0.00	ex dealers	0.00	0.00
3.00	HIGH PRESSURE LINE	192.23	576.69
3.00	HIGH PRESSURE LINE	212.35	637.05
6.00	METAL SEAL	32.01	192.06
1.00	SEAL CYLINDER HEAD COVER	106.97	106.97
1.00	CIRCUMFERENTIAL SEAL	74.16	74.16
6.00	O RING	6.50	39.00
6.00	O RING	7.87	47.22
6.00	O RING	15.66	93.96
6.00	SEALING RING	10.67	64.02
6.00	BIHEXAGONAL SCREW	3.98	23.88
1.00	SCREW PLUG	41.76	41.76
1.00	PARTS KIT FILTER PACKAGE	80.02	80.02
4.00	HEX HEAD SCREW W FLANGE	20.27	81.08
1.00	SEAL	9.28	9.28
0.00	staging room	0.00	0.00
1.00	LATE OIL FILTER KIT	55.28	55.28
1.00	SCREW PLUG	41.76	41.76
39.00	ENGINE - ALLIANCE PRIME ENGINE GLOBAL 10W40 (1000L) - QABP AFM498:	7.46	290.94
-3.00	Adjust Parts Price [[Warranty Only]]	1.00	-3.00

Component Serial Number

VIN

329131

473909C0612236

W1T96342420499866

YEAR

MAKE

MODEL

IN SERVICE

2020

MB

96342422-XAU30

09/07/2021

Sold Operations (Cont.)

OpsId : 8 Job : 14 EGR COOLER LEAKING EXHAUST
 Cause : DONE
 Correction : EGR COOLER LEAKING EXHAUST

1.00	EXH GAS RECIRC COOLER	3,677.68	3,677.68
0.00	ex dealers	0.00	0.00
2.00	CONNECTING PIPE	53.53	107.06
1.00	SEAL	78.59	78.59
0.00	ex melb	0.00	0.00
1.00	SEAL	78.59	78.59
0.00	ex melb	0.00	0.00

SIsId : RA920024201:03 Total : \$0.00

Date Invoice : 07/06/2024

OdomIn: 553,972

OdomOut: 553,972

Sold Operations

OpsId : 6 Job : 00 DUPLICATED PARTS
 Cause :
 Correction :

0.00	SEALING RING	11.31	0.00
0.00	SEALING RING	31.75	0.00
0.00	SEALING RING	6.19	0.00
0.00	SEALING RING	10.01	0.00
0.00	SEALING RING	5.38	0.00
0.00	SEAL RING	5.70	0.00
0.00	CAP TRANSMISSION HOUSING	314.59	0.00
0.00	SEALING RING	3.92	0.00

SIsId : RA920024201:02 Total : \$2,154.74

Date Invoice : 07/06/2024

OdomIn: 553,972

OdomOut: 553,972

Sold Operations

OpsId : 4 Job : 32 BOTH L/H AND R/H ENGINE MOUNTS SPLIT / TORN
 Cause : Mounts Torn due to constant torsional stress
 Correction : Removed DPF covers and removed dpf securing bolts, dpf mounts and removed DPF unit to acces

2.00	ENGINE MOUNT	524.46	1,048.92
------	--------------	--------	----------

OpsId : 5 Job : 99 L/H SIDE BATTERY BOX BRACKET SNAPPED
 Cause : Battery box bracket snapped due to torsional stress from chassis movement
 Correction : Removed adblue tank

1.00	HOLDER	575.82	575.82
------	--------	--------	--------

SIsId : RA920024201:01 Total : \$26,992.30

Date Invoice : 06/29/2024

OdomIn: 553,972

OdomOut: 553,972

Component Serial Number

VIN

329131

473909C0612236

W1T96342420499866

YEAR

MAKE

MODEL

IN SERVICE

2020

MB

96342422-XAU30

09/07/2021

Sold Operations

OpsId : 1 Job : 27 GEARBOX BROKEN
 Cause : FOUND CASE HARDENING DETERIORATION ON K1 GEAR CAUSING MULTIPLE TEETH ON S
 Correction : Brought vehicle into workshop

0.00	CORE MUST BE CLEANED AND RETURNED IN ORIGINAL PACKAGING	0.00	0.00
1.00	TRANSMISSION	21,776.01	21,776.01
1.00	CORE - TRANSMISSION	5,356.02	5,356.02
0.00	CORE MUST BE CLEANED AND RETURNED IN ORIGINAL PACKAGING	0.00	0.00
1.00	SEALING RING	10.71	10.71
1.00	SEALING RING	33.69	33.69
1.00	SEALING RING	6.57	6.57
1.00	SEALING RING	10.62	10.62
1.00	SEALING RING	5.10	5.10
1.00	SEAL RING	6.17	6.17
1.00	CAP TRANSMISSION HOUSING	333.88	333.88
1.00	SEALING RING	3.71	3.71
-1.00	CORE - TRANSMISSION	5,356.02	-5,356.02
12.00	GEAR OIL - ALLIANCE PRIME TRANS PLUS MB 75W90 (205L) - QABP AFM430	21.03	252.36
1.00	Adjust Parts Price [[Warranty Only]]	16.48	16.48

OpsId : 3 Job : 26 QUOTE FOR REPLACEMENT OF TRANSMISSION
 Cause :
 Correction :

-1.00	MISC SHOP SUPPLIES	34.98	-34.98
-------	--------------------	-------	--------

SlId : RA920022458:02 Total : \$608.00 Date Invoice : 06/29/2024 OdomIn: 517,559 OdomOut: 517,559

Sold Operations

OpsId : 6 Job : 60 MERCEDES GOODWILL HAVE COVERED PARTS COST ONLY
 Cause :
 Correction : C: Cab pump motor inop

SlId : RA920022458:01 Total : \$1,795.00 Date Invoice : 06/27/2024 OdomIn: 517,559 OdomOut: 517,559

Sold Operations

OpsId : 5 Job : EA Cab pump motor inop
 Cause :
 Correction : C: Cab pump motor inop

1.00	HYDRAULIC PUMP	1,795.00	1,795.00
------	----------------	----------	----------

SlId : RA920022457:01 Total : -\$3,520.00 Date Invoice : 04/19/2024 OdomIn: 447,918 OdomOut: 447,923

Component Serial Number

VIN

329131

473909C0612236

W1T96342420499866

YEAR

MAKE

MODEL

IN SERVICE

2020

MB

96342422-XAU30

09/07/2021

Sold Operations

OpsId : 5 Job : 60 Cab pump motor inop

Cause :

Correction : C: Cab pump motor inop

-1.00	HYDRAULIC PUMP	2,950.00	-2,950.00
-------	----------------	----------	-----------

SIsId : RA920018239:03 Total : \$3,520.00

Date Invoice : 12/06/2023

OdomIn: 447,918

OdomOut: 447,923

Sold Operations

OpsId : 5 Job : 60 Cab pump motor inop

Cause :

Correction : C: Cab pump motor inop

1.00	HYDRAULIC PUMP	2,950.00	2,950.00
------	----------------	----------	----------

SIsId : RA920018239:02 Total : \$2,295.50

Date Invoice : 12/02/2023

OdomIn: 447,918

OdomOut: 447,923

Sold Operations

OpsId : 2 Job : 99 Engine hunting (rough idle)

Cause :

Correction : QCV valve sticking causing inaccurate amount of fuel;

1.00	FUEL METERING UNIT	940.18	940.18
------	--------------------	--------	--------

0.00	bay 10	0.00	0.00
------	--------	------	------

OpsId : 4 Job : 47 Rail pressure sensor reading incorrect, preventing QCV test from being cal

Cause :

Correction : CAUSE;

1.00	PRESSURE SENSOR	975.82	975.82
------	-----------------	--------	--------

0.00	HCV BAY #10	0.00	0.00
------	-------------	------	------

SIsId : RA920018239:01 Total : \$2,081.95

Date Invoice : 11/30/2023

OdomIn: 0

OdomOut: 447,923

Component Serial Number

VIN

329131

473909C0612236

W1T96342420499866

YEAR

MAKE

MODEL

IN SERVICE

2020

MB

96342422-XAU30

09/07/2021

Sold Operations

OpsId : 1 Job : 83 A/C NOT WORKING INTERMITTENTLY, MISTING

Cause :

Correction : C:TX valve intermittently sticking causing A/C to freeze and mist

OpsId : 3 Job : 83 REPAIRS REQUIRED TO A/C SYSTEM

Cause :

Correction : C: TX valve externally bypassing refrigerant

1.00	EXPANSION VALVE	190.99	190.99
1.00	REFRIGERANT DRIER	352.49	352.49
1.00	FULL FACE GASKET	17.99	17.99
1.00	FULL FACE GASKET	17.09	17.09
1.00	DUST FILTER	105.99	105.99
1.00	R134A AC GAS	90.00	90.00
1.00	HAZ WASTE & ENVIRO DISPOSAL	27.50	27.50
1.00	SECTIONAL SEALING RING	28.19	28.19
1.00	SECTIONAL SEALING RING	16.71	16.71

SIsId : RA920011224:01 Total : \$1,104.05

Date Invoice : 04/06/2023

OdomIn: 302,578

OdomOut: 302,578

Sold Operations

OpsId : 1 Job : EA LEFT REAR ON FRONT DIFF AIRBAG HAS HOLE IN IT

Cause : LH REAR FRONT DRIVE AXLE AIR BAG DELAMINATED INTERNALLY

Correction : Short test

1.00	SCREW PLUG	52.99	52.99
1.00	SPRING SHEET METAL LOCK	3.67	3.67
0.00	Staging room please	0.00	0.00
1.00	AIR SSP. BELLOWS, RA	847.49	847.49
1.00	SPRING SHEET METAL LOCK	1.90	1.90
0.00	SMALL CLIP - BOTTOM	0.00	0.00
0.00	EXPRESS 1	0.00	0.00

SIsId : RA920011223:01 Total : -\$1,104.03

Date Invoice : 04/06/2023

OdomIn: 302,578

OdomOut: 302,578

Component Serial Number

VIN

329131

473909C0612236

W1T96342420499866

YEAR

MAKE

MODEL

IN SERVICE

2020

MB

96342422-XAU30

09/07/2021

Sold Operations

OpsId : 1 Job : EA LEFT REAR ON FRONT DIFF AIRBAG HAS HOLE IN IT
 Cause : LH REAR FRONT DRIVE AXLE AIR BAG DELAMINATED INTERNALLY
 Correction : Short test

-1.00	SCREW PLUG	52.99	-52.99
-1.00	SPRING SHEET METAL LOCK	3.67	-3.67
0.00	Staging room please	0.00	0.00
-1.00	AIR SSP. BELLOWS, RA	847.49	-847.49
-1.00	SPRING SHEET METAL LOCK	1.90	-1.90
0.00	SMALL CLIP - BOTTOM	0.00	0.00
0.00	EXPRESS 1	0.00	0.00
1.00	Adjust Parts Cost [[Warranty Only]]	0.02	0.02

SIId : RA920011110:01 Total : \$1,104.03 Date Invoice : 04/06/2023 OdomIn: 302,578 OdomOut: 302,578

Sold Operations

OpsId : 1 Job : EA LEFT REAR ON FRONT DIFF AIRBAG HAS HOLE IN IT
 Cause : LH REAR FRONT DRIVE AXLE AIR BAG DELAMINATED INTERNALLY
 Correction : Short test

1.00	SCREW PLUG	52.99	52.99
1.00	SPRING SHEET METAL LOCK	3.67	3.67
0.00	Staging room please	0.00	0.00
1.00	AIR SSP. BELLOWS, RA	847.49	847.49
1.00	SPRING SHEET METAL LOCK	1.90	1.90
0.00	SMALL CLIP - BOTTOM	0.00	0.00
0.00	EXPRESS 1	0.00	0.00
-1.00	Adjust Parts Cost [[Warranty Only]]	0.02	-0.02

SIId : RA920011109:01 Total : -\$1,004.21 Date Invoice : 04/04/2023 OdomIn: 302,578 OdomOut: 302,578

Sold Operations

OpsId : 1 Job : EA LEFT REAR ON FRONT DIFF AIRBAG HAS HOLE IN IT
 Cause : LH REAR FRONT DRIVE AXLE AIR BAG DELAMINATED INTERNALLY
 Correction : Short test

-1.00	SCREW PLUG	41.09	-41.09
-1.00	SPRING SHEET METAL LOCK	2.95	-2.95
0.00	Staging room please	0.00	0.00
-1.00	AIR SSP. BELLOWS, RA	777.14	-777.14
-1.00	SPRING SHEET METAL LOCK	1.55	-1.55
0.00	SMALL CLIP - BOTTOM	0.00	0.00
0.00	EXPRESS 1	0.00	0.00
1.00	Adjust Parts Cost [[Warranty Only]]	0.02	0.02

SIId : RA920008191:01 Total : \$1,004.21 Date Invoice : 12/21/2022 OdomIn: 302,578 OdomOut: 302,578

Component Serial Number

VIN

329131

473909C0612236

W1T96342420499866

YEAR

MAKE

MODEL

IN SERVICE

2020

MB

96342422-XAU30

09/07/2021

Sold Operations

OpsId : 1 Job : EA LEFT REAR ON FRONT DIFF AIRBAG HAS HOLE IN IT
 Cause : LH REAR FRONT DRIVE AXLE AIR BAG DELAMINATED INTERNALLY
 Correction : Short test

1.00	SCREW PLUG	41.09	41.09
1.00	SPRING SHEET METAL LOCK	2.95	2.95
0.00	Staging room please	0.00	0.00
1.00	AIR SSP. BELLOWS, RA	777.14	777.14
1.00	SPRING SHEET METAL LOCK	1.55	1.55
0.00	SMALL CLIP - BOTTOM	0.00	0.00
0.00	EXPRESS 1	0.00	0.00
-1.00	Adjust Parts Cost [[Warranty Only]]	0.02	-0.02

SIsId : RA920004489:01 Total : \$2,400.85

Date Invoice : 08/24/2022

OdomIn: 258,842

OdomOut: 258,842

Sold Operations

OpsId : 1 Job : 00 SERVICE AS PER DATA SHEET - BEST BASIC
 Cause : Done CP
 Correction : Complaint: Carry out service

1.00	FILTER PACKAGE	64.65	64.65
1.00	TS FUEL FILTER	179.80	179.80
1.00	FILTER CARTRIDGE	150.77	150.77
1.00	SCREW PLUG	34.61	34.61
2.00	AIR FILTER	57.83	115.66
1.00	DUST FILTER	86.55	86.55
1.00	TS WIPER BLADE	59.97	59.97
1.00	AIR FILTER ELEMENT	130.54	130.54
2.00	SEALING RING	3.27	6.54
1.00	BULB	71.44	71.44
1.00	WORKSHOP SUNDRIES	43.53	43.53
1.00	HAZ WASTE & ENVIRO DISPOSAL	21.68	21.68
1.00	GREASE - ALLIANCE AFX2 GREASE (450GL) - QABP AFM4215450	5.78	5.78
0.40	COMPLEX GREASE	37.69	15.08
42.00	ENGINE - ALLIANCE PRIME ENGINE GLOBAL 10W40 (1000L) - QABP AFM498:	6.95	291.90
12.20	GEAR OIL - ALLIANCE PRIME TRANS PLUS MB 75W90 (205L) - QABP AFM430	20.80	253.76
-1.59	Adjust Parts Cost [[Warranty Only]]	1.00	-1.59

Rejected Operations

OpsId : 2 Job : 00 Quote parts
 Cause :
 Correction :

1.00	WINDSHIELD	840.15	840.15
0.00	IN STOCK	0.00	0.00

Component Serial Number

VIN

329131

473909C0612236

W1T96342420499866

YEAR

MAKE

MODEL

IN SERVICE

2020

MB

96342422-XAU30

09/07/2021

SlsId : RA920002016:01 Total : \$431.19

Date Invoice : 06/23/2022

OdomIn: 202,596

OdomOut: 202,496

Sold Operations

OpsId : 1 Job : 42 FRONT BRAKE CLIP, DRIVERS SIDE

Cause :

Correction : remove and replace brake hose and voss fitting.

1.00	BRAKE HOSE	186.15	186.15
2.00	UNION SCREW	5.92	11.84

SlsId : RA920000877:02 Total : \$1,459.41

Date Invoice : 05/12/2022

OdomIn: 177,087

OdomOut: 177,087

Sold Operations

OpsId : 1 Job : 10 CARRY OUT SERVICE - BEST BASIC 2026/500K

Cause : Done JB

Correction : 35639 31/2/22

1.00	FILTER PACKAGE	63.39	63.39
1.00	TS FUEL FILTER	176.26	176.26
1.00	FILTER CARTRIDGE	147.83	147.83
2.00	AIR FILTER	54.97	109.94
1.00	DUST FILTER	84.81	84.81
1.00	SCREW PLUG	33.94	33.94
40.00	Engine-ALLIANCE PRIME ENGINE GLOBAL 10W40-PUMP IN	6.45	258.00
1.00	HAZ WASTE & ENVIRO DISPOSAL	16.00	16.00
1.00	MISC SHOP SUPPLIES	27.44	27.44

SlsId : RA920000877:01 Total : \$343.76

Date Invoice : 05/12/2022

OdomIn: 177,087

OdomOut: 177,087

Sold Operations

OpsId : 2 Job : 43 BRAKE LINE LEAKING (SIDE STEER) - WARRANTY ????

Cause : Done JB

Correction : 35639 31/3/22

1.00	BRAKE HOSE	186.15	186.15
2.00	UNION SCREW	5.92	11.84
1.00	MISC SHOP SUPPLIES	0.02	0.02