

12270421 Canada Inc.

21 Apple Valley Way

Brampton ON L6P 3P8

+16475639578

reeferrepair@gmail.com

GST/HST Registration No.: 717946735RT0001

INVOICE

BILL TO

INVOICE

0176

DATE

06/04/2026

TERMS

Net 30

DUE DATE

06/05/2026

DATE	ACTIVITY	DESCRIPTION	TAX	QTY	RATE	AMOUNT
	PMB C-600	REPLACE FUEL FILTER, OIL FILTER AND AIR FILTER, OIL 13L AND TOP UP COOLANT, TIGHTEN ALL BELT, CLEAN ALL ELECTRIC TERMINAL, FUEL SUMP FROM FUEL TANK. RUN & CHECK, ALL OPERATIONS NORMAL.	HST ON	0	0.00	0.00
	DIAGNOSE	REEFER UNABLE TO START AND HMI SCREEN FLASHING FOUND HMI IS FAULTY.	HST ON	2	92.00	184.00
	090-45-2449	CONTROLLER - HMI SR4 USED	HST ON	1	2,295.34	2,295.34
	REPLACED	HMI SR 4 REPLACED	HST ON	1	1.00	1.00
	Run & Check Operation	Pre Trip Passed all operations normal	HST ON	0	0.00	0.00

R1110
C-600
SR NU 6001335150
EH 8831
TH 19353

SUBTOTAL	2,480.34
HST (ON) @ 13%	322.44
TOTAL	2,802.78
PAYMENT	2,802.78
BALANCE DUE	\$0.00

PAID