

Deard

BF59-1738

Estimate: 2783

9/7/2023

CVI REPAIRS ESTIMATE

HVAC RENTALS



Black Dog

3813 82 Avenue

Leduc, AB T9E 0K2, CA

admin@blackdogoilfield.com

(780) 612-9532

Purchase Order

Unit

Unit: 334 VIN: 1RNF48A26YR006662 2000 Reitnouer Inc Trailers Reitnouer Inc Trailers Current Usage: 0 Miles

Description	Quantity	Rate	Amount
DIAG AND REPAIR FOR ABS LIGHT STAYS ON ***PARTS TO BE ADDED AT TIME FO REPAIR*** ***LABOR MAY CHANGE DEPENDING ON REPAIR***	2	\$155.00	\$310.00
		Subtotal	\$310.00
REPAIR FOR #2 L/H BRAKE HARDWARE WORN OUT REMOVE TIRES, REPLACE HARDWARE KIT REINSTALL TIRES AND TORQUE	1	\$155.00	\$155.00
Q & Q+ BRAKE HARDWARE KIT	0	\$23.66	\$0.00
		Subtotal	\$155.00
REPAIR FOR AIR TANK DRAIN VALVES LEAKING REMOVE AND REPLACE DRAIN VAVLES AND INSTALL CABLE	1	\$155.00	\$155.00
Drain Valve	2	\$16.01	\$32.03
		Subtotal	\$187.03
REPAIR FOR DOT TAPE INCORRECT ON REAR OF UNIT RED HAS TO BE TO OUTSIDE REMOVE AND REPLACE DOT TAPE ON REAR OF UNIT AS REQUIRED ***PARTS TO BE ADDED AT TIME FO REPAIR***	1	\$155.00	\$155.00
		Subtotal	\$155.00
REPAIR FOR SERVICE GLADHAND RUBBER/ SEAL TORN REMOVE AND REPLACE GLADHAND SEALS	.25	\$155.00	\$38.75
PROTECTO GLADHAND SEAL	2	\$2.92	\$5.84
		Subtotal	\$44.59
REPAIR FOR #1 L/H HUB OIL LOW TOP UP HUB	0	\$155.00	\$0.00
HD SYNTHETIC 75W90 OIL BULK	0.5	\$18.54	\$9.27

Description	Quantity	Rate	Amount
		Subtotal	\$9.27
REPAIR FOR #2 R/H AIRBAG LEAKING			
REMOVE AND REPLACE AIRBAG	2.5	\$155.00	\$387.50
PARTS TO BE ADDED AT TIME FO REPAIR			
		Subtotal	\$387.50
REPAIR FOR #2 R/H BRAKE CHAMBER PARK SPRING BROKEN	1.5	\$155.00	\$232.50
3030 SHORT STROKE POT	1	\$129.62	\$129.62
		Subtotal	\$362.12
REPAIR FOR MULTIPLE CRACKS ON TIE DOWN BAR, BOTH ALUMINUM			
WINCH BOXES ON THE FRONT LEFT OF TRAILER, LANDING GEAR			
SUPPORT BRACKET, SUB FRAME ON BOTH SIDES IN FRONT OF #1 AXLE,			
#1 LEFT SIDE AIRBAG PEDESTAL			
REPAIR FOR WHERE AXLE HANGER BRACKETS MOUNT TO FRAME IS			
CORRODED / RUST JACKED OVER 12 MIL			
REPAIR FOR CROSSMEMBER IN FRONT OF #1 AXLE IS BENT PAST SPEC			\$155.00
REPAIR FOR BOLTS IN THE REAR OF TRAILER ARE LOOSE DUE TO RUST			\$0.00
JACKING			
REPAIR FOR MULTIPLE LOOSE BOLTS ON DECKING SUPPORTS			
***CANNOT ESTIMATE THIS AS WE DONT DO MOST OF THESE REPAIR			
HERE, YOU WILL HAVE TO TAKE IT TO A TRAILER REPAIR SHOP FOR AN			
ESTIMATE***			
		Subtotal	\$0.00
		Shop Supplies	\$143.38
		Labor	\$1,433.75
		Parts	\$176.76
		Subtotal	\$1,753.89
		GST	\$87.69
			(5% of \$1,753.89)
			Total \$1,841.58

*: Core charges not included in total. You will be charged for any core that is not in returnable condition. This charge may be applied on a separate invoice.

GST# : 833150998

The details and the estimate for the repairs provided above are based on our first inspection and do not constitute a guarantee that no further work or parts will be required. The estimate is not a guarantee of the final price of the repairs. The total bill of work and final price will be as per the details available on completion of the repairs. Other terms and conditions as applicable. If you authorize us to perform the above repairs, either verbally or in writing, you agree to pay in full for the work performed and parts required.

Customer Signature: _____



PC# 7096
 SOUTH EDMONTON AB POWER & HVAC
 3404 79 AVE
 LEDUC, AB T9E 0Z5
 587-686-7150

Work Order 77986726

Created 1/27/25 Meter at Repair
 Entered By BBOLES Maintained By
 Authorized By
 Opened 1/27/25 Closed
 Terms NET 30

Job Site:
 OUR SHOP

Bill To: Account #
 SOUTH EDMONTON AB POWER & HVAC

Engine Model
 Engine Serial # 89736

Air Reg #
 Air Reg Expires 000000

PO

Job #

Job Loc OUR SHOP

Warranty N Expires

Claim #

Last Cont/Cust 7439660/

Current Meter

Service Call

Mechanic 89736

Date Acquired 9/09/19

Date In Rent 9/09/19

Current Location 7096

Owning Location 7096

Equipment Status N Down <20days

Work Order Description INSPECTION DEFECT ACTION

HOUSE W/O 76553461 NOT CORRECT
W/O TO CLARIFY

** Important Information **

Equip #	Make	Model	Serial #	Description
LF5079	REITNOUER	MAXMI	1RNF48A26YR006662	RENTAL 35'- 53' FLAT

WORK PERFORMED:

PREVIOUS W/O 76553461 NOT CORRECT THIS W/O TO CLARIFY

Trailer needs heavy repair and did not receive a CVIP last year. Estimate to repair more than new trailer. SEND TO AUCTION

Total Amount

GST/HST# R102235256

Comments:

Mechanic Signature

Date