

Fleet #	RT45
Registration	XB75KK
Make	Kenworth
Model	T358
VIN / Chassis #	6F50000008A439648

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
10/09/2025		AIRLEAKS R-2406 NEW COMPRESSOR FITTED	Internal Workshop		\$2,334.12
16/07/2025		INSPECTION R-2358 REPLACED GOVENOR VALVE REPAIRED AIR LEAKS REPAIRED BRAKES REPLACED WATER CONTROL AIR REGULATORS REPLACE DRIVE TYRE AND RIM	Internal Workshop		\$2,248.32
05/12/2024	325,465 kms	fuel filter R-2034 DIAGNOSE ENGINE NO FUEL. REMOVE AND REPLACE FUEL TRANSFER PUMP. REPLACED POSITION SENSORS AND REPAIRED WIRING. CLEAN AREA AND POSITION TRUCK. TEST RUN OK	Internal Workshop		\$3,608.33
31/10/2024	325,465 kms	B - 30000 S-834 CARRY OUT B SERVICE	Internal Workshop		\$584.50
10/09/2024	321,125 kms	INSPECTION R-1501	Internal Workshop		\$444.08
10/01/2024	320,461 kms 213,408 hrs	Battery R-1325 Replaced batteries	Internal Workshop		\$0.00
10/01/2024	320,461 kms	Battery R-1326 Replaced batteries	Internal Workshop		\$558.86
20/12/2023		COI I-92		KNK	\$0.00
04/08/2023	320,461 kms	Air Conditioner R-1108 Remove busted condenser and install new one Found leaking hose at TX valve replace hose Vac out system Gas up system	Internal Workshop		\$264.00
08/11/2022		Registration O-238 Registration Renewal Received emailed to Tamara to follow up COI 13.12.22: emailed COI booking to TMR to open online to allow rego pymnt Paid 12 mths rego.	TMR	4805E2	\$1,314.23
02/11/2022		First Aid Kit R-867 steven hutchinson advised they found mulitple kits and have placed one in the truck	Internal Workshop		\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
25/10/2022	31,211,176 kms 21,647 hrs	Air Bag, Air Conditioner, coolant, wipers R-867	BDS Mechanical, Fabbro Diesel Services		\$0.00
16/09/2022	309,429 kms 21,450 hrs	Air leaks , Radiator R-698 1- Replace air lines 2- Replace blown hose 3- Replace Pos1,2 with 16 ply tyres	Fabbro Diesel Services		\$589.95
12/09/2022		Air Conditioner R-671 marked completed by Robbie	Fabbro Diesel Services		\$0.00
07/09/2022	320,461 kms	B - 30000 S-243 31/10 - robbie - s-243 job was raised - will be due now will schedule within the next week	Fabbro Diesel Services		\$157.54
05/09/2022		COI I-59 COI reminder paperwork received and emailed to Tamara. 13.12.2022: No response to email issued several times requesting information on planned location. Made booking for Innisfail, 17th January, in discussion with Steven Hutchison. If appt ends up needing to be changed, noted that 48 business hrs notice is reqd. Emailed request to TMR compliance to open rego online for payment as COI expired	TMR	1025818591	\$195.33
20/08/2022	313,184 kms	guards, Hoses R-541 fit new actuator repaired air leaks tightened pipe clamp note coolant pipe needs welding up on days off	BDS Mechanical		\$679.25
09/08/2022	320,461 kms	A - 15000 S-186 22/8 mitch advised still waiting for parts for this service 31/10 - robbie advised this is not showing for service but our system shows that it is.	Fabbro Diesel Services		\$0.00
27/07/2022	304,144 kms 21,093 hrs	Leaks, Transmission R-501 leaking from crack in weld for drain bung boss pack Ute, travel from etheridge camp 50KM to job site clean drain tray an drain coolant leaking from weld on coolant drain boss clean weld and surrounding area with wire brush and sandpaper apply epoxy putty and let set for 45min refill cooling system, top up test drive and inspect, no leaks pack up and travel back to camp	Fabbro Diesel Services		\$418.00
11/07/2022		Alternator R-35 jobcard signed as completed test alternator - not charging supply and fit new alternator on site remove and charge / load test starting batteries	Nowland Engineering		\$1,002.30
28/06/2022		Parts Only R-302 Fitter: Robbie Brammer Site: Silkwood Dates: 20/06/2022 - 26/06/2022 Labour - Date: 20/06/2022 Hours: 10.5 Labour - Date: 21/06/2022 Hours: 9.5 Labour - Date: 22/06/2022 Hours: 12.5 Labour - Date: 23/06/2022 Hours: 13.5 Labour - Date: 24/06/2022 Hours: 11.5 Labour - Date: 25/06/2022 Hours: 12.0 Labour - Date: 26/06/2022 Hours: 9	Fabbro Diesel Services		\$1,045.00
21/06/2022		Parts Only R-235 parts only	Brown & Hurley, Powell Industrial Pty Ltd		\$1,130.42
13/06/2022	303,138 kms	B - 30000 S-71 replaced air filter during service	BDS Mechanical Townsville		\$1,359.29
13/06/2022		Registration O-88 Paid GCA card. 6mths rego.	TMR		\$1,300.13

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
03/05/2022		Parts Only R-227 Labour Hire Fitter: Robbie Brammer Site: Townsville Dates: 25/04/22 - 01/05/22 Labour - Date: 25/04/22 Hours: 1 .0 Labour - Date: 26/04/22 Hours: 13 Labour - Date: 27/04/22 Hours: 15 Labour - Date: 28/04/22 Hours: 11.5 Labour - Date: 29/04/22 Hours: 15 Labour - Date: 30/04/22 Hours: 15.5 Labour - Date: 01/05/22 Hours: 14.5 worked out as LV26=3 GR37=47.5 TR34=12 LV11=4 RT45=9.5 GEN=2.5 LV26=1 SCTR?=2 RS22005?=4	Fabbro Diesel Services		\$992.75
03/05/2022		Parts Only R-335 Fitter: Robbie Brammer Site: Townsville Dates: 25/04/22 - 01/05/22 Labour - Date: 25/04/22 Hours: 1 .0 Labour - Date: 26/04/22 Hours: 13 Labour - Date: 27/04/22 Hours: 15 Labour - Date: 28/04/22 Hours: 11.5 Labour - Date: 29/04/22 Hours: 15 Labour - Date: 30/04/22 Hours: 15.5 Labour - Date: 01/05/22 Hours: 14.5	Fabbro Diesel Services		\$522.50
29/04/2022		Air leaks R-351 air leaks repair due to inability to hold air even whilst running replace all 6mm hose to spray heads and battery valve on tank body	Fabbro Diesel Services, Pirtek		\$362.00
09/02/2022	297,390 kms 20,696 hrs	COI R-2	Fabbros Diesel Services		\$11,919.48
30/01/2022		Parts Only R-362 jan- mar parts	Fabbro Diesel Services, MaxiParts, Truckzone		\$4,800.35
19/01/2022	297,390 kms 20,696 hrs	C - 180000 S-3 Complete C service as per attached service sheet. 1. Replace all filters and oils 2. Drain and refill with new coolant 3. Replace all idler bearings 4. Replace fan and alternator belt 5. Replace windscreen wipers	Brown & Hurley, Fabbros Diesel Services , Truckzone		\$692.73
12/01/2022		Battery R-5 Removed and replaced 2x batteries. Checked over and all okay. Job and paperwork completed.	Fabbros Diesel Service Cloncurry	712712	\$561.97
13/12/2021		Truck Annual Inspection I-3	TMR	101893462	\$190.49
12/12/2021		Registration O-14 Paid 6 mths registration with GCA Card.	TMR	F7B9FC	\$1,296.31
25/11/2021		Speed R-57 RO#7 Operator complained truck wouldnt go over 30km/h. plugged in onsite, code 0242, vehicle speed sensor circuit tampering has been detected, inactive, removed sensor plug, which had water in it, contacted, cleaned and blew out, cleared code test drove truck, got to 80km/h easy, also watched data and sensor reading is lining up with speed. do recommend getting fiter kit and oil for alison as needs service	BDS Mechanical Townsville		\$104.50
19/10/2021	291,742 kms	Drop Bar R-104 RO22049 & 22036 LH drop bar wouldnt open. pulled apart and it was chocked up with dirt. cleaned up, made sure everthing is free, reassembled. operator went to take truck, stop engine light came on, checked coolant, it was low, topped up, no visible leaks. cleared code and informed operator to keep a close eye on it. also noticed radiator stay rubbers need replacing asap. 20/11 - LH drop bar wouldnt open again, on inspection found air actuator to be seized this time. swapped out with one from Iveco water truck. tested, all ok	BDS Mechanical		\$888.25

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
12/09/2021		S-Cam R-64 Assemble Pos 3 new s-cam tube to vehicles jack up 2nd axle and remove wheel/drum, brake shoe spring had come adrift as well and s-cam roller, inspect ok and reassemble, remove slack adjuster and found adjuster missing off slack adjuster, require a new one. remove old s-cam tube and replace, refit slack adjuster, boost u/s due to bent shaft, cut shaft and bolt up booster, require new 24/30 booster.	Fabbros Diesel Services		\$0.00
36 Records				Total:	\$41,564.98