



Wajax Limited
123 Queensland Crescent
Red Deer AB T4P 2P6

N41-1
MAY

INVOICE PROPOSAL

1 (8)

Invoice date	Due date	Order number	Your order number	Reference	Order date
06/Jan/2025	05/Feb/2025	TL0-7100318087			28/Oct/2024

Payer C211180

Customer C211180

Payer address

Delivery address

R. BRUCE ERICKSON CONSTRUCTION LTD.
ATTENTION: ALLAN ERICKSON
36145 RR# 43
RED DEER COUNTY AB T4G 0L5

SCOTT & ASSOCIATES INS ADJUSTERS INC
201-O 2435 MANSFIELD DRIVE
COURTENAY BC V9N 2M2

Contact ALAN ERICKSON
Phone 403-638-6401
E-mail aserick.ab@gmail.com

Entered by Wendy Graham
Phone 403-346-8981 , FAX 403-347-3711
E-mail WGraham@wajax.com

Delivery method	Delivery terms	Payment terms	Delivery date
None	Service	Net 30 days	28/Oct/2024

Line	Product / Description	Fleet number	Lot/Serial no	Service
1	870C FELLER BUNCHER Brand TIGERCAT <u>Meters</u> Hours: 11636.00 KM: 0.00 Miles: 0.00		87013098	SHOP
<p>COMPLAINT:</p> <p>UNIT CAUGHTFIRE WHILE ON SITE (THERMAL EVENT)</p> <ol style="list-style-type: none"> 1. UNLOAD UNIT FROM TRAILER (NOT OPERATIONAL) 2. MOVE UNIT INTO SHOP 3. PERFORM INSPECTION TO DETERMINE WHAT REPAIRS ARE REQUIRED 4. SUBMIT TO CUSTOMER AND INSURANCE BROKER TO DETERMINE DIRECTION OF REPAIRS <p>CAUSE:</p> <p>THERMAL EVENT</p> <p>CORRECTION:</p> <p>UNLOAD UNIT FROM TRAILER (NON-OPERATIONAL): REMOVE FINAL DRIVE GEARS TO ALLOW THE UNIT TO BE IN NEUTRAL FOR TOWING. USE OTHER EQUIPMENT AT WAJAX TO ASSIST WITH THE UNLOADING. TOW UNIT INTO SHOP FOR DIAGNOSES.</p> <p>DIAGNOSE CAUSE OF FIRE, HEALTH CHECK TO DETERMINE REPAIRS NEEDED. WASH UNIT/CLEAN THE EFFECTED AREA FOR INSPECTION. INCLUDES MACHINE/ENGINE DOWNLOADS, ENGINE OIL SAMPLE: INSPECT UNIT FOR THERMAL EVENT DAMAGE AND REPAIRS NEEDED.</p>				



Wajax Limited
 123 Queensland Crescent
 Red Deer AB T4P 2P6

INVOICE PROPOSAL

2 (8)

Invoice date	Due date	Order number	Your order number	Reference	Order date
06/Jan/2025	05/Feb/2025	TL0-7100318087			28/Oct/2024

WASH/CLEAN EFFECTED AREA. TECH NEEDED TO ADD WIRING HARNESS (OVERLAY) TO PERFORM THE ENGINE.MACHINE DOWNLOAD. PERFORM AND SUBMIT ENGINE OIL SAMPLE DUE TO TURBO FAILURE. PUT TOGETHER THE PARTS LIST FOR REPAIRS NEEDED.

ENGINE REPAIRS CAUSED FROM THERMAL EVENT:

FOUND DAMAGE/MELTED HARNESSES, ENGINE STARTER HAS SIGNS OF FAILURE (MELTED), EXHAUST DAMAGE (HEAT BLANKET AND MUFFLER), STARTING AND CHARGING CABLES, HEATER COOLANT LINES, DRAIN COOLANT AND FILL WITH NEW COOLANT, HIGH PRESSURE/LOW PRESSURE FUEL LINES. BLOW BY HOSES DAMAGED - REPLACE. ENGINE FIRE WALL WEATHER STRIPPING DAMAGE - REPLACE.

MACHINE REPAIRS CAUSED FROM THERMAL EVENT:

FOUND MELTED MACHINE HARNESS, SENSORS AND SOLENOID ON HYDRAULIC PUMP. FOUND MELTED/DAMAGED HYDRAULIC HOSES AND HYDRAULIC SENSOR CAUSED FROM THERMAL EVENT DAMAGE. REPLACE EFFECTED HARNESSES. REPLACE EFFECTED HYDRAULIC HOSES. TOP UP HYDRAULIC FLUID. FOUND FIRE SUPPRESSION SENSORS, WIRING AND HOSE DAMAGE FROM THERMAL EVENT. PUMP COMPARTMENT PUMP HARNESS, LIGHT HARNESS AND LIGHT DAMAGED FROM THERMAL EVENT. FOUND ADDITIONAL HOSES THAT ARE DAMAGED FROM THERMAL EVENT REQUIRED REPLACEMENT. ADDITIONAL ELECTRICAL REPAIRS TO HARNESSES/WIRING THAT REQUIRED REPAIRS.

FINAL DRIVE REASSEMBLY (CLEAN, ASSEMBLE AND FILL):

CLEAN FINAL DRIVES, ASSEMBLE AND FILL WITH NEW OIL.

ADDITIONAL CLEANING AND PAINT TOUCH UPS CAUSED FROM THERMAL EVENT DAMAGE:

ADDITIONAL UNLNOWN/UNFORESEEN ITEMS FOUND DURING THE REPAIR:

Tr no	Line type	Op/Item / Description	Quantity	U/M	Price	Discount amt	Handling chg	Total
104	Miscellaneous	FREIGHTIN PARTS FREIGHT CHARGES	1.00	EA	1,200.00			1,200.00
4	Material	12033769B Ext Item No 12033769-B MSN CONN FUSE	2.00	EA	4.97			9.94
5	Material	12066614L Ext Item No 12066614-L MSN	4.00	EA	0.97			3.88