


AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

REPAIR REPORT

Site: Meag

C41-13
SEP

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

Unit No: #10B

Hr Meter:

Date: March 18/25

Subcontractor: Iane

Description:

Hours

① Troubleshoot why tailgate locks won't release.
↳ inspect linkages and brake pots
↳ No air going to air valve @ rear of truck. Followed air line from valve to air tank. No kinks. Undo airline @ air tank. Pressure regulator was frozen with water. Replace regulator, all works good.

1 hr

NO.


QNTS.

Parts/Materials

x1 90psi regulator

TRAVEL:

WORK DESCRIPTION




A Division of 848875 Alberta Ltd.
Box 247, Lao La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

Hyd hoses From Sapphire,

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: Unit 10B / Blade

Date: Feb 10 / 25

Hr Meter:

Subcontractor: Shawn

Description:	Hours
- install 2 new tubes	
in new tires for blade	
- install 2 new male	
hyd wing fittings for blade	
hook up and function	
- help Dylan with hyd	
hoses for sand volume	
control cylinder	

NO.	QNTS.	Parts/Materials

1 hr

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysięzny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: Unit 10B

Date: Feb 11/24

Hr Meter:

Subcontractor: Shawn

Description:	Hours
- hook up blade bring into shop	
- install 2 plow tires	
- set blade height	
- hook up hyd lines	
- try to figure out on truck why it wont spread sand	5hrs
- called dealership discussed with technician	
- he will call back	
- install unit # decals	
- clean hood install winter front	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysleżny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Meag

Unit No: #23

Hr Meter:

Date: Jan 27/25

Subcontractor: Low

Description:	Hours
① Replace both shocks on #2 axle	
② Replace both shocks on #4 axle	
③ Remove driveshaft behind transmission ↳ remove midship yoke, please accordingly ↳ Reinstall drivelines	
	(2 hrs)

NO.	QNTS.	Parts/Materials
	x4	shocks
	x1	midship nut
	x1	SPL. strap kit

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieszny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: 10 B

Date: January 10/25

Hr Meter:

Subcontractor: Dylan Bourassa

Description:	Hours
Fixed Broken wires/	
tied up wires in Rear	
Put covers/ Plugs	
Back in for	4.5 hrs
Module Bored in	
Back of Box	-4.5 hrs
Grinded Rust of	
for New side Panels	
helped Shawn try	
to Reset system	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: Unit 10B

Date: Jan 9th /25

Hr Meter:

Subcontractor: Shum

Description:	Hours
- Torque wheels 50lbs	
- Install new custom made tailgate latches	
- remove control panels rear box electronic panels to diagnose electrical issues	
- Build custom side box cover guards	
- Diagnose wiring with Dylaw Onel Tm	

NO.	QNTS.	Parts/Materials

6hrs

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieszny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: Unit 10B

Hr Meter:

Date: Jan 8 WEB/25

Subcontractor: Shawn

Description:	Hours
- build custom arms for tailgate	
- assist Dylan with broken wires in junction box	
- build custom doors for side panels on boxes	6 1/2 hrs
- top up coolant.	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: Unit 10B

Hr Meter:

Date: Jan 7/25

Subcontractor: Shawn

Description:	Hours
- finish install air brake pots	
for tailgate latches latches	
- build custom plate to access	
brake pots for tailgate latches	
- try to repair send dump	
control cylinder	
- put front wheels on.	
- install oil cooler	
- top up coolant.	

NO.	QNTS.	Parts/Materials

5 hrs

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: shop

Unit No: 10B

Hr Meter:

Date: January 7/25

Subcontractor: Dylan Boakassa

Description:	Hours
Cleaned out conveyor	-2.5hrs
Belt/lubricated	
Picked up oil cooler	
seals	
Filled washer	
fluid up	
Cut Break Pot end	
off to open	
tail gate	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: 10B

Hr Meter:

Date: January 6/2025

Subcontractor: Dylan Bournassa

Description:	Hours
Removed oil cooler/ PreP'd to Put Back together	4 hrs
Cleaned debris off of conveyor Belt	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: Unit 10B

Hr Meter:

Date: Jan 6 / 25

Subcontractor: Shawn


Description:	Hours
- install wiring to starter	
- help dylan remove oil cooler	
- help laurence with box panels	

NO.	QNTS.	Parts/Materials

4 hrs

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: 10B

Hr Meter:

Date: January 6/25

Subcontractor: Dylan Bourassa

Description:	Hours
Fixed/Replaced corroded wires/pins on connections that go to control box underneath tail gate Breaker Set Break Breaks tied up wires/hoses	8hrs
Changed licence plate light/fixed wires installed licence plate	
fixed wires for marker light on hood	

NO.	QNTS.	Parts/Materials
		wire connectors
	4	pin connectors (female)
		zip ties

WORK DESCRIPTION

Pin connectors from saphire, other parts from shop supplies,



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: 10B

Hr Meter: 9707 hrs

Date: January 3 2024


Subcontractor: CJ Biegler

Description:	Hours
- Took starter ready	-
Wire out and build	
a new one	
- Took drive side	
brake pot out by tailgate	9 hrs
- Prepped brake pots	
for tailgate	15
- Prepped cylinder for	
box shooft	-

NO.	QNTS.	Parts/Materials
	2	Brake pots
	4	400 fittings

WORK DESCRIPTION

<u>SMR Supplies</u>



REPAIR REPORT

Site: Shop


Date: January 2/25

Subcontractor: Dylan Bourassa

[illegible]

WORK DESCRIPTION

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiężny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: 10B

Hr Meter: 9707 hrs

Date: C5 Biegle 15

Subcontractor: January 2 2024

Description:	Hours
- Mc dylan put	3hrs
hydraulic pump back on	
- Hook it hoses back on	
- Ziptied the loose	
wires	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: 10B

Hr Meter:

Date: December 30/24

Subcontractor: Dylan Bourassa

Description:	Hours
Changed two	3 hrs
hydraulic hoses	
Removed driver step	
to Bend Back /	
Prep too Be welded	

NO.	QNTS.	Parts/Materials
	2	hoses

WORK DESCRIPTION

hyd hoses made at ethos,



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: 10B

Hr Meter: 970 Hrs

Date: December 30 2024

Subcontractor: CJ Biegler

Description:	Hours
- checked all fire	9 Hrs
pressures and added	
air to all of them	
- Took Gps off	
- Added All Gps	
wires took out	
- Started to take	
light rack off	
- Rewired beacon light	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop


Unit No: <u>10B (Plow Truck)</u>		
Hr Meter: <u>9,705</u>		
Description:	Hours	
continued C-VIP	}	
Put front end on		
Jack stands/Removed		
from tires		- 7.5 hrs
Removed hyd pump		- 1.5 hrs
with CT		
changed Junction	}	
Box ON front of		
dump Box		

Date: <u>December 27/24</u>		
Subcontractor: <u>Dylan Baccassa</u>		
NO.	QNTS.	Parts/Materials
	1	Junction Box

WORK DESCRIPTION

Parts from Ethos, ordered oil cooler At smr diesel,

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przyslezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site:

Shop

Unit No:

~~New #~~ 10B Plow Truck

Date:

December 27 2024

Hr Meter:

9707 hrs

Subcontractor:

CJ Biegle

Description:	Hours
- Took cylinder for	8.5 hrs
shoot off	
- capped lines	
- Measured front	
shoes (steer axle)	
- Greased front end	
- Me dylan took	
the hydrolic pump	
out	
-	

NO.	QNTS.	Parts/Materials

WORK DESCRIPTION



A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysiezny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

Site: Shop

Unit No: New ^{Plow} ~~Trac~~ Track 10B

Date: December 23/24

Hr Meter:

Subcontractor: Dylan Boudreau


Description:	Hours
Removed Rear wheels	
Started C-VIP	
Chipped mud outta frame	
Removed Rear drive shaft	
too changed 4-joints/	
Re-installed drive shaft	- 9.5 hrs
Removed First Rear axle	
drums/ shoes	
install New shoes/ drum	
ON Rear Front Passenger	
Side	
Put Rear tires on	
tied up wires	

NO.	QNTS.	Parts/Materials
	2	4-joints Kits
	1	Break shoe Kit
	1	drum

WORK DESCRIPTION

Parts from SMR diesel,

AL'S CONTRACTING



2005 LTD.

A Division of 848875 Alberta Ltd.
Box 247, Lac La Biche, Alberta T0A 2C0

Allan Przysieszny
Ph: (780) 623-2242
Cell: (780) 623-0340

REPAIR REPORT

103

Site:

Shop

Unit No: New Plow Truck

Date: December 23 2024

Hr Meter:

Subcontractor: CS Biegler

Description:	Hours
- Put wheels on	-
One axle	
- Drums on one (new)	
- New one brake shoe	
Set	
- Checked lights	9hrs
- Changed oil, oil filter,	
fuel filter, air filter	
- Topped off coolant,	
washer fluid	
- Helped dylan with	
driveshaft	
- Checked air line (Brake)	-

NO.	QNTS.	Parts/Materials
	34.9L	oil
		oil filter
		washer fluid
		coolant
		Brake shoe Set
		Brake drum
		Air filter
		Fuel filter

WORK DESCRIPTION

Air filter, fuel filter, oil filter, brake shoe Set, brake drum.
SMR Supplies
oil from UFA
Washer fluid and coolant from Shop