

Vehicle Information
 Svc ID 6748
 ROGATOR RG1300C SP WITH 48M ALUMINIUM BOOM

Stock # 6637N Compliance
 VIN AGCA1300KJNSL1100 Sold 17/12/2018
 Engine No. D68630 Warranty Start 24/04/2019
 Rego # XV94FS Odometer 2621
 Trans.

Client Communication Edit

Vehicle Notes:

History

R/O #	Client Name	Status	Odometer	Date In	Date Out	Job No	Job Code	Job Description	Retail	Warranty	Internal	Trade /	Non-Product	
162624				26/03/2024	26/03/2024	1 C		COOLANT LEAK AROUND RADIATOR	270.00	0	0	0	0	
152906				18/04/2023	20/04/2023	1 C		FIT SOLENOID	375.00	0	0	0	0	View
152357			2,621	15/03/2023	14/04/2023	1 C		CHECK STEERING NOT WORKING	509.30	0	0	1,370.70	0	View
145623			1,743	15/03/2022	7/04/2022	1 C		REPAIR CRACKS IN BOOM & LEVEL	1,408.60	0	0	0	0	View
145166				17/02/2022	28/02/2022	1 C		REPAIRS TO HYDRAULIC RAM	276.50	0	0	0	0	View
145092				14/02/2022	15/02/2022	1 C		DIAGNOSE ESTOP VALVE OPERATION	732.10	0	0	859.60	0	View
142141				27/09/2021	29/10/2021	1 C		CARRY OUT SERVICE ON MACHINE	1,381.50	0	0	3,112.10	0	View
141739				6/09/2021	18/10/2021	1 C		CARRY OUT REPAIRS TO BOOM FOLD CONTROL BOX	211.80	0	0	0	0	View
141583				31/08/2021	31/08/2021	1 C		BOOM WONT FOLD	0	618.75	0	0	0	View
135935			1,230	16/10/2020	21/04/2021	1 W		BULLETIN 20-0111	0	428.51	0	0	0	View
139604				21/04/2021		1 C		COOLANT CHANGE	448.80	0	0	252.10	0	View
136281			1,180	30/10/2020	6/01/2021	1 W		SERVICE BULLETIN - 20-00-24	0	684.15	0	0	0	View
136656			1,163	12/11/2020	10/11/2020	1 W		FAILED BREAKAWAY CABLE	0	900.32	0	0	0	View
135934			1,156	16/10/2020	30/10/2020	1 W		LOADING SPEED ISSUE	0	780.18	0	0	0	View
135998				20/10/2020		1 W		REPLACE LEAKING HYDRAULIC TANK	0	5,267.06	0	0	0	View
						2 C		HYDRAULIC OIL	79.50	0	0	0	0	View
135794			1,124	12/10/2020	26/10/2020	1 W		WELD CRACKS IN ALUMINIUM BOOM	0	391.52	0	0	0	View
134385			1,119	12/08/2020	8/10/2020	1 W		REPLACE NORAC CONTROLLER	0	165.00	0	0	0	View
133882			882	8/07/2020	8/07/2020	1 W		REPLACE TILT CYLINDER BOLTS	0	220.00	0	0	0	View
133849			915	7/07/2020	7/07/2020	1 C		HVAC FAN NOT WORKING	403.00	0	0	0	0	View
133033			785	11/05/2020	26/05/2020	1 W		WELDING REPAIRS TO BOOM	0	280.50	0	0	0	View
131888			713	10/02/2020	11/05/2020	1 W		REPLACE FAULTY E-STOP VALVES	0	1,283.04	0	0	0	View
128245			559	31/07/2019	10/02/2020	1 W		REPLACE PUMP	0	912.02	0	0	0	View
131448				9/01/2020	31/01/2020	1 W		PARK BRAKE SOFTWARE UPDATE PSP2019223	0	220.00	0	0	0	View
130999			555	11/12/2019	9/01/2020	1 W		REPLACE SOLENOIDS	0	632.06	0	0	0	View
128989			493	17/09/2019	30/09/2019	1 W		FIELD CAMPAIGN FC3237 JOYSICK REPLACEMENT	0	2,269.94	0	0	0	View
128848			437	10/09/2019	23/09/2019	1 W		REPAIRS TO ALUMINIUM BOOM	0	341.00	0	0	0	View
128629			430	28/08/2019	4/09/2019	1 W		REPAIRS TO INDUCTION HOPPER MOUNT	0	271.17	0	0	0	View
						2 C		400HR SERVICE	699.60	0	0	52.00	0	View
128367			400	9/08/2019	28/08/2019	1 W		REPLACEMENT REAR REVERSING CAMERA	0	695.96	0	0	0	View
127981				15/07/2019	8/08/2019	1 W		SERVICE BULLETIN	0	546.21	0	0	0	View
127439			151	28/05/2019	27/05/2019	1 W		REPAIR TO FUEL INJECTOR PUMP	0	3,199.26	0	0	0	View
127298				16/05/2019	21/05/2019	1 W		REPLACE WATER PUMP BELT AND AIRCONDITIONER PUMP FAULT	0	2,297.71	0	0	0	View
						2 W		LOSS OF COMMUNICATION WITH NORAC	0	82.50	0	0	0	View
127351			1,314	21/05/2019		1 C		FIRST SERVICE	471.80	0	0	20.70	0	View
126857				2/04/2019	1/05/2019	1 I		PDI UNIT	0	0	6,311.33	0	0	View