

10122 124 AVE
GRANDE PRAIRIE, AB. T8V 0R4
Phone: 780-539-3706 Fax: 587-803-8951
FIXED RIGHT THE FIRST TIME

INVOICE

8471

710694290RT0001

INVOICE

Ref #: 2367

Date: 02/18/2021

GOOD TO GO OILFIELD

11424 97 ST
GRANDE PRAIRIE, AB T8V 7B7
Cellular 780-532-3693 -- Home 780-518-9040 SCOTT

2015 Ford - F-350 Super Duty XLT - 6.2L, V8 (379CI) VIN(6)
Lic # :
Unit # : **GTG 25**
VIN # : 1FT8W3B65 FEA60632
Odometer In : 84821
Odometer Out : 84822

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
MANIFOLD ASY BC3Z 9431 DA	1.00	239.22	239.22	GRANDE PRAIRIE AUTO REPAIR INSPECTION: https://2un.me/9iegxzb8	
GASKET BC3Z 9448 B	2.00	60.07	120.14	COMPLIMENTARY DIGITAL INSPECTION Performed digital inspection	n/c
STUD W714869 S431	8.00	3.45	27.60	DIAG ACTIVE CEL Checked codes had code p0316 misfire on startup, p0442 EVAP	67.50
NUT W714870 S430	8.00	3.45	27.60	system leak detected small leak, p0446 EVAP system vent control circuit. Recommend further diag time.	
STUD W707753 S900	2.00	11.76	23.52	INSPECT FOR BROKEN EXHAUST MANIFOLD Found driver side exhaust manifold to be cracked recommend replacing exhaust manifold.	135.00
NUT - HEX W520514 S440	2.00	8.30	16.60	EXHAUST MANIFOLD - Remove & Replace - Gas/Ethanol Left,w/Single Rear Wheels	356.40
LIC PLATE ASSEMBLY (CP) 60101	2.00	11.13	22.26	Replaced driver side exhaust manifold, started and found no leaks.	
4X4 SERVICE FLUIDS F250/F350 DF F250/F350	1.00	229.43	229.43	SMOKE TEST FOR EVAP LEAK Smoke tested evap system, found smoke to be coming out of vent tube. Plugged vent tube and found no leaks. Recommend replacing carbon cannister and relocating vent valve tube, due to being plugged full of mud causing the vent valve to not fully close.	135.00
REAR BRAKE PADS PGD-1691-M	1.00	157.24	157.24	DIAG FOR MISFIRE CODE Had a code for misfire detected on startup. Pulled spark plugs and found they were original plugs and worn out. Recommend replacing plugs and wires.	67.50
REAR ROTORS 681017fzn	2.00	257.00	514.00	DIAG GAS CAP LIGHT IS ON Smoke tested evap system found smoke coming out of vent tube, plugged vent tube and found no leaks. Gas cap has a good seal, recommend replacing evap cannister and relocating evap vent valve tube. Due to evap cannister sucking in mud and getting clogged not letting vent valve fully close.	67.50
AIR FILTER 49883	1.00	27.69	27.69	DIAG BOTH PLATE LIGHTS - INOP Found the plate lights to be burnt out. Replaced bulbs and lights work properly.	40.50
3 - 7/32" VACUUM TUBING AND CONNECTORS 1	1.00	15.00	15.00	DIAG TPMS LIGHT IS ON - WE DO SEE L/H REAR TIRE IS LOW Found driver side rear tire to be low. Repaired tire and took for road test tpms light did not return.	67.50
Shop Supplies			25.00	REPAIR L/H REAR TIRE Repaired driver side rear tire, rechecked and found no leaks.	35.00
				4X4 SERVICE REMOVE DIFF COVERS, CLEAN, INSPECT, RESEAL AND REFILL AS REQUIRED. ALSO DRAIN AND FILL TRANSFER CASE AS REQUIRED	337.50
				R&R REAR BRAKE PADS, ROTORS AND SERVICE CALIPERS Replaced rear brake pads and rotors as well as serviced calipers due to being 3mm brakes and having siezed pins. Took for road test and found no issues.	270.00
				REPAIR FRONT WHEEL HUB VACUUM LINES	87.75

Visit us on the web: www.gpautorepair.ca

Service Advisor: ANDERSON, LANE, Tech: GEROW, LANE; GROSS, WADE

Email Address: info@gpautorepair.ca



12423 - 100 STREET
GRANDE PRAIRIE, AB T8V 4H2
1-855-642-5823
GST#896127677

INVOICE NO. 01/22/2021 17:32
TRANSACTION NO. 00027-078806
EMPLOYEES 21012200078806
SUM02G MAC03G CAB04

CUSTOMER INFORMATION

Go Oilfield Good To
Grande Prairie, AB T8V 1T5
(780) 532-3693

GOODTOGO L GOOD TO GO OILFIELD SERVICES
UNIT# GTG25
DRIVERS NAME TYLER

VEHICLE INFORMATION

YEAR 2015 LICENSE PLATE AB-BND6795
MAKE FORD ALTERNATE ID
MODEL F-350 PICKUP MILEAGE 81849
ENGINE 8cyl 6.2L FI
VIN# VIN: 1FT8W3B65FEA60632

SERVICE HISTORY

DATE	MILEAGE	SERVICES
01/22/21	81849	FS DPG AF WWF RFD RRD RTC
11/04/20	71134	FS DPG AF RRD RTC RFD ATS ENV

SERVICE CHECKLIST

ITEM	DESCRIPTION
1. BRAKE FLUID	FULL
2. POWER STEERING FLUID	FULL
3. WASHER FLUID	FILLED
4. CABIN AIR FILTER	N/A
5. AIR FILTER	REPLACED
6. BREATHER ELEMENT	N/A
7. PCV VALVE	N/A
8. WIPER BLADES*	APPEARS OK
9. SERPENTINE BELT*	APPEARS OK
10. ENGINE COOLANT	-36 DEGS.C
11. TRANSMISSION*	APPEARS OK
12. REAR DIFFERENTIAL*	REC REPLCD
13. FRONT DIFFERENTIAL*	REC REPLCD
14. TRANSFER CASE*	REC REPLCD
15. EXTERIOR LIGHTS	APPEARS OK
16. WINDOWS/LUBRICATE HING	DONE/DONE
17. UNDER CARRIAGE VISUAL*	APPEARS OK
18. LEAKS*	APPEARS OK
19. TIRE PRESSURE	F70 R80

DESCRIPTION**QTY. PRICE**

DESCRIPTION	QTY.	PRICE
FULL SERVICE OIL CHANGE	1.00	67.99
OF2222 OIL FILTER	1.00	0.00
MOTOSOL 5/20 OIL	6.60	4.19
OIL LEVEL FULL ON ARRIVAL	1.00	0.00
CHASSIS LUBE COMPLETED	1.00	0.00
GREASE FITTINGS LUBED	2.00	0.00
A CHANGE FOR THE BETTER	1.00	0.00
EMAIL SAVINGS PROGRAM-NO	1.00	0.00
ENVIRO/SHOP SUPPLIES FEE	1.00	6.99
GASKET	1.00	2.00
5642 AIR FILTER	1.00	32.99
WINDOW WASHER FLUID	1.00	3.49
REC. FRONT DIFF SERVICE	1.00	0.00
REC. REAR DIFF SERVICE	1.00	0.00
REC. TRANSFER CASE SERV	1.00	0.00

COMMENTS

THANK YOU!
ENGINE LIGHT ON
ON ARRIVAL

SUBTOTAL 117.65
GST (5%) 5.88
TOTAL 123.53
CHARGE 123.53

COPIED FOR
MAINTENANCE
RECORDS

GST#896127677

MESSAGES

Recommend next service on 04/22/2021 or 86849 km.
1
Thank you for supporting an Alberta owned business!

**OIL WARNING!**

If your oil warning light comes on (or your gauge loses pressure) **STOP** your car immediately! **NEVER** operate your engine when the oil warning light is on!

DOING SO WILL VOID WARRANTY!
See Over For Additional Information

X
I have authorized the work to be performed without a written estimate
See reverse of invoice for Personal Information Protection Policy



12423 100 STREET
GRANDE PRAIRIE, AB T8V 4H2
1-855-642-5823
GST#896127677

DATE
INVOICE NO.
TRANSACTION NO.
EMPLOYEES

07/15/2021 8:32
00027-084904
21071500084904
FET01G DUM02G FET01

CUSTOMER INFORMATION

Go Oilfield Good To
Grande Prairie, AB T8V 1T5
(780) 532-3693

GOOD TO GO L GOOD TO GO OILFIELD SERVICES
UNIT# GTG25
DRIVERS NAME ARMON

VEHICLE INFORMATION

YEAR 2015
MAKE FORD
MODEL F-350 PICKUP
ENGINE 8cyl 6.2L FI
VIN# VIN: 1FT8W3B65FEA60632
LICENSE PLATE AB-BND6795
ALTERNATE ID
MILEAGE 91621

SERVICE HISTORY

DATE	MILEAGE	SERVICES
07/15/21	91621	FS DPG AF RDS ADD
01/22/21	81849	ADD WWF
11/04/20	71134	FS DPG AF WWF RFD RRD RTC FS DPG AF RRD RTC RFD ATS ENV

SERVICE CHECKLIST

- | ITEM | STATUS |
|----------------------------|------------|
| 1. BRAKE FLUID | FULL |
| 2. POWER STEERING FLUID | FULL |
| 3. WASHER FLUID | LOW |
| 4. CABIN AIR FILTER | N/A |
| 5. AIR FILTER | REPLACED |
| 6. SKID PLATE | N/A |
| 7. PCV VALVE | N/A |
| 8. WIPER BLADES* | APPEARS OK |
| 9. SERPENTINE BELT* | APPEARS OK |
| 10. ENGINE COOLANT | -36 DEGS.C |
| 11. TRANSMISSION* | APPEARS OK |
| 12. REAR DIFFERENTIAL* | REPLACED |
| 13. FRONT DIFFERENTIAL* | APPEARS OK |
| 14. TRANSFER CASE* | N/A |
| 15. EXTERIOR LIGHTS | APPEARS OK |
| 16. WINDOWS/LUBRICATE HING | DONE/DONE |
| 17. UNDER CARRIAGE VISUAL* | APPEARS OK |
| 18. LEAKS* | APPEARS OK |
| 19. TIRE PRESSURE | F80 R80 |

DESCRIPTION

QTY. PRICE

DESCRIPTION	QTY.	PRICE
FULL SERVICE OIL CHANGE	1.00	67.99
X2222 OIL FILTER	1.00	0.00
MOTOSOL 5/20 OIL	6.60	4.19
OIL LEVEL FULL ON ARRIVAL	1.00	0.00
CHASSIS LUBE COMPLETED	1.00	0.00
GREASE FITTINGS LUBED	2.00	0.00
A CHANGE FOR THE BETTER	1.00	0.00
EMAIL SAVINGS PROGRAM-YES	1.00	0.00
ENVIRO/SHOP SUPPLIES FEE	1.00	6.99
GASKET	1.00	2.00
5642 AIR FILTER	1.00	32.99
SYN. REAR DIFF SERVICE	1.00	109.99
MOTOSOL SYN 75/140	3.80	15.99
ENVIRO/SHOP SUPPLIES FEE	1.00	1.00
XTEND FRICTION MODIFIER	1.00	0.00
XTEND FRICTION MODIFIER	1.00	0.00
WINDOW WASHER FLUID	1.00	21.99
BATTERY TEST PASSED	1.00	2.99

COMMENTS

rear diff service approved
by sir scott

SUBTOTAL 266.12
DISCOUNT (FLT) 26.61
SALE 239.51
GST (5%) 11.98
TOTAL 251.49
CHARGE 251.49

MESSAGES

COPIED FOR
MAINTENANCE
RECORDS

GST#896127677

Recommend next service on 10/13/2021 or 96621 km.
Thank you for supporting an Alberta owned business!



OIL WARNING!

If your oil warning light comes on (or your gauge loses pressure) STOP your car immediately! NEVER operate your engine when the oil warning light is on!

DOING SO WILL VOID WARRANTY!
See Over For Additional Information

X
I have authorized the work to be performed without a written estimate
See reverse of invoice for Personal Information Protection Policy



STANDARD AUTO GLASS-8844
10116 - 124TH AVENUE
GRANDE PRAIRIE AB T8V 0R4
(780)539-3093 Fax:(780)538-9916

Invoice

8844-846221

Date: 2021/12/07

C01

Page: 1

GST/HST#: 895661775RT

PST/TVP#:N

Bill-To:

GOOD TO GO OILFIELD SERV
14424-97 STREET
GRANDE PRAIRIE AB T8V 7B7

(780)532-3693 fax:(780)532-9358

(The "Customer")

Account: +27012870000

JOB ID: 88440000084622

G16 25

Policy:		Vehicle:	2016 FORD F SERIES F350 4 DOOR			
Claim:		Loss Date:				
CSR:	005	PO/RO:	2732	Scheduled Date:	2021/12/07	
Installer:	018	Authorized:	SCOTT			
Unit:	25	Work Order #:	88440000084622			
Products & Services						
				<u>Qty</u>	<u>Labour</u>	<u>Material</u>
DB11203YPY	DOMESTIC BACK GLASS			1.00	100.00	275.00
DISPO	DISPOSAL FEE			1.00	0.00	5.00
KIT2	URETHANE			1.00	0.00	50.00
	123					

I have read the details of this invoice, the sale conditions and warranties on the back of the present invoice. I accept them and recognize being bounded by them.

Customer Signature: _____ Date: _____

	NON INSURED	INSURED	TOTAL
Material:	330.00	0.00	
Labour:	100.00	0.00	
GST/HST:	21.50	0.00	
PST:	0.00	0.00	
Total:	451.50	0.00	

TOTAL PAYABLE BY CUSTOMER: 451.50

Payments: 0.00

Balance: 451.50

451.50

Tempered Glass Installation The warranty is not transferable or redeemable for cash. The installation is warranted against leaks and against manufacturing defects for a period of one year. (See reverse for details of warranty.)

COPIED FOR
MAINTENANCE
RECORDS ©

Division of Belron Canada Inc.

Ver:8.0.6