

Unit #809 - 2010 Caterpillar D8T
S#KPZ04029

809

Date	Hours	Work Performed
Octoer 19, 2011		Flip over blade, install blade onto machine. (Ron B)
October 26, 2011		Complete first service. (Ron B)
Jan 28/14	3725	oil fuel air
May 20, 2014		Finning Inv # 960619798 Machine Troubleshoot in Shop
June 24, 2014	3850	Service - Oil, Both Fuel (DJ)
July 27/14	4104	Service - eng oil, fuel, cab air check both air filters good, work lights, horn, backup alarms, fire ext, battery & cables, coolant, spill kit, belts Ripper tooth needs changed soon operator has tooth and pin coolant leak @ hose for turbo cooling # 6 20" cut (Tim)
Nov. 25/14	4,373	Service - 0W40, eng, fuel, outer air (Amos)
May 7/15	8,600	Service - eng, fuel check finals Grease hard bar (Dean)
Jul. 17/15	5,040	Service - eng, both fuel, both aircab air Grease hard bar (Bob)
sept 24/15	5115	engine and transmission oil check, hydraulic level checked, fuel filter changed, water sep changed, work lights fixed, horn, back alarm, fire ext, all good battery post cleaned coolant good wiper and windshield good, undercarriage good cutting edges good new batteries clean post replace pins on park brake linkage(Bob)
oct 24/15	5294	changed oil and filter, changed fuel, water sep, inner and outer air filters, checked work lights horn and back up alarm, 0w40 (Brian)
Feb18/16	5672	Changed Eng oil+filter, Fuel+water sep inner and outer air filters changed, Greased hard bar, needs small bolts for side window, (Amos+Kevin)
Mar 2/16		Install new screws for side window, (Amos)
feb 27/16	5702	Trouble shoot electrical problems, bad connection behind the seat, swap trans pump coupler from 808, needs Machine harness- engine harness, trans couplers. (Dean)
June 17/17	5758	topped up hydrualic oil, and trans oil, found leaking oring under the floor boards changed and leak stopped (steve) change leaking trans hose
June 23/17	5784	change transmission oil and filter, change hydrolic filters, change transmission oil cooler hoses, change bottom sump hose on torque converter { DJ }
sept 1/17	5913	change cab filter, charge ac [Steve]
sept 3/17	5924	recharge AC, change head light [Steve]

Unit #809 - 2010 Caterpillar D8T
S#KPZ04029

Jan 17/18	6144	Service - 0w40 oil , both fuel , both air , cork machine [Doyle]
Jan 20/18		Replace trans filter hose , replace trans pump drive couplers [Amos]
May 2/18	6357	Change 2 trans hoses , 2 new U-joints , replace A/C compressor & charge system , remove ripper hose block & weld cracks in fuel tank [Charlie] [Amos]
July 5/18	6519	Service - 15w40 oil , check finals [Levi]
Aug 21/18	6842	Service - 15w40 oil , both air [Amos]
Oct 15/18	7032	Change final drive oil's [Amos]
Oct 26/18	7082	Service - 0w40 oil , both fuel , O. air [Doyle]
Feb 22/19	7405	New Hardbar & 3 pin's - hardbar from Finning [Amos]
Mar 5/19	7407	Service - 0w40 oil , both fuel [Doyle]
Dec 7/19	7502	Change trans oil & filter , change hyd filter , change final drive oils , O. air , cab filter , lites [Levi & Doyle]
Feb 7/20	7853	Service - 5w40 oil , both fuel , O. air [Amos]
Mar 25/20	8086	Install new belt & rebearing smooth pulley [Levi]
June1/21	8089	Blade cyl's - RE & RE by Kodiak Chrome - new rods & seals , undercarriage poor - install new segments , NEW cutting edges [Doyle]
Jan18/22	8911	Service - 5w40 oil , both fuel , both air , change tilt hose [Chris C]
Feb 23/22		Service - 5w40 oil , both fuel , both air [Doyle]
July 29/22	9602	Diagnosed and fixed loose wire connection going to AC compressor. Added spill kit into machine. [Clayton]
August 04/22	9614	Changed out bent LH upper wiper arm, both wiper blades. Changed fresh air cab filter. Changed broken sprayer nozzle. Replaced back up alarm. [Clayton]
Oct 12/22	9703	Replaced leaking pivot shaft seal. Refilled pivot shaft resevoir. Replaced hard bar pin LH + Seals. [Clayton + Shawn]
Feb 06/23	9942	Service - 5W40, both fuel, both air. [Braylan]

Unit #809 - 2010 Caterpillar D8T
S#KPZ04029

[illegible]