

sepDate	Hours	Work Performed – Unit G7 Serial # VBD63880	
	250	First service done by Brandt Tractor	
Oct 22/12			
	369	Changed out warranty blade cylinder	
March 6, 2013	584	Install fan reversing solenoid ; and signal light (Dean)	
Aug 21/13	990	Oil fuel air	
Oct 21/13	1164	Oil fuel air	
Dec 5/13	1483	Oil fuel air	
Mar 11/14	1980	Oil fuel air	
Aug.11/14	2677	Service – eng oil, trans, hyd, air, Check oil levels trans, hyd. Check work lights, horn, backup alarm, fire ext, battery & cables, Pos shut off, coolant belts, cutting edges good, attachment good, R/R fender missing, R/R fender bars (Tim)	Check pos. air
Sept. 13/14	2830	Service – eng oil, outlet air, Check work lights horn backup alarm, pos air shutdown, (Doyle)	
Dec. 4/14		Flip snow wing blade (Tim)	
Dec. 24/14	3394	Service – 0W40, eng, both fuel, both air (Doyle)	
Dec. 31/14		Replace hyd. Tube (Doyle)	
Jan. 17/15	3620	Service – eng oil, both fuel, both air Change cutting edge on wing, fan motor Top up air in all tires (Bob)	
Feb. 12/14	3,923	Service – eng, both fuel, both air (Amos)	
Apr. 1/15	4,304	Service – oil, both fuel, both air (Bob)	
Jun. 29/15		Recharge A/C	(Kevin)

Jul. 23/15	4,848	Service – eng, both fuel, both air, cab air Straighten old scafier and install new one
Sept 27/15	5130	Service- eng oil and filter, trans oil and filter changed, diff oil and filter Changed, hydraulic filter changed, fuel, waters sep. inner outerand cab filters Changed, work lights, back up alarm, fire ext. , battery cables are all good, Repair bent fender right rear (Bob)
Oct 9/15		Changed cutting edges replace 4 light bulbs, no power to back lights or tail lights, need to replace some shims in turn table.(Brian)
Nov2/15		Find bad ground and replace tail lights, need to replace one work light (Brian)
Nov 8/15		Replace hose for right front drive wheel, (Brian+bob)
Jan 6/15	5367	Install wing, shim circle, shim side shift, changed wing edges, checked for Leaks, straighten steps,(Amos)
Nov 30/15	5362	Brandt - Install long block engine !! repair oil leak on rite FWD hub Inv # 1923095
Apr25/16	5493	Service – 15 w40 oil , SOS oil , First oil change after Brandt rebuild, (Amos)
August 7, 2016	5711	Replace left front wheel drive hose. Repair right front fender. (Amos)
Aug 16/16	n/a	Brandt - remove motor & reseal bellhousing [warranty]

September 14, 2016	5782	Service – 0w40 oil, both fuel, both air. (Dean)
Aug 29-16	n/a	Alpine - install new windshield
Sept 30/16	5916	Repair small hyd oil leaks [Dean]
Nov 2/16	6161	Service - 0w40 oil , both fuel , replace ripper hose , repair tire chains [Dean]
Nov 9/16	n/a	Fix side window wiper [Amos]
Dec 15/16	6534	Service - 0w40 oil , both fuel , 0.air [Amos]
June 17/17	6757	Water in fuel light coming on after filter change, change filters and drain water in tank unit working well. ADDED 5L ENGINE OIL
June 15/17	6267	Water in fuel changed filter { DJ }
July 22/17	6878	Service- oil change, water sep, both air filters { Doyle }
Nov 11/17	7234	Service – 0W40 Oil, Both Fuel [Doyle]
Nov 15/17	7237	Brandt - Lower Cache - check trans - filter has lots of metal !!! inv # 1927941
Dec 21/17	7265	New alternator [Doyle]
Jan 15/18	7356	Replace sideshift slides , change 3 wear pads , cab filter , lites , fire ext [Steve]
Jan 22/18	7414	Fix step , fix seat air hose , replace broken sandvik pockets [Doyle]

Nov 30/17	7241	Brandt - install reman trans inv # 1928064
Mar 28/18	n/a	Repair air seat , grease machine [Dan L]
May 14/18	7511	Service - 15w40 oil , both fuel , both air , re & re sideshift cyl - new rod from Jalco [Amos]
Sept 15/18	7643	Replace heater water valve , replace 12 – 24 inverter , replace heater motor , change cab filters [Levi]
Feb 15/19	7708	Service - 0w40 oil , both fuel , O. air [Amos]
Feb 25/19	7709	Leaking tandem pivots – Vision Machining repair seal surfaces , new updated seals , new pivot bushings & thrusts , replace RF drive chain [Amos]
Mar 14/19	7715	Replace 3 FWD hoses on LH side , replace fuel rail pressure sensor [Levi]
Apr 8/19	7722	Remove snow wing [Amos]
Apr 16/19	7722	Replace hyd control valve rubber isolaters & bolts [Amos]
June 4/19	7730	Change RH FWD hose , part # AT438313 [Amos]
Nov 7/19	7968	Service - 5w40 oil , both fuel , both air , clean cab filter [Amos]
Nov 12/19		Kal tire - Install 2 new Snowplus tires on LH drive
Dec 17/19	8090	Replace coolant expansion tank hose [Amos]

FEB 7/20	8370	Service - 5w40 oil , both fuel , both air	[Amos]
Mar 10/20	8535	Replace bottom boost hose	[Doyle]
Apr 7/20	8585	Both fuel filters , fix fuel tank vent	[Levi]
June 5/20	8786	Service - 5w40 oil , both fuel , both air , new sandvik boards	[Doyle]
Aug 15/20	9136	Service - 5w40 oil , both fuel , both air , clean cab filter	[Amos]
Nov 9/20	9611	Replace air to air clamp at top of cooler	[Amos]
Nov 12/20	9868	Install new batteries from Brandt , new RH tierod end	[Levi]
Nov 13/20		2 new Maxim steering tires	
Dec 11/20		Replace 2 missing plastic circle slides	[Levi]
Feb 01-21	9820	Needs new front window, glued back in , New hose for lift ram on wing at barrel end (Doyle)	
Feb 02-21	9827	SERVICED-5w-40,filter change on engine and outer air,New retainer for pin on wing. (Doyle)	
March 10/21	9942	Replace circle J-Hook slides and flat slides above J-Hooks	(Doyle)
Mar1/21	9942	New wing edges- Heavy duty from Brandt	(Doyle)
Apr 16/21	10065	Reseal sideshift cyl , replace upper flat circle slides , adjust sideshift slides , remove snow wing	[Doyle]
		Alpine - new front windshield	

May 10/21	10162	Service - 5w40 oil , both fuel , O. air , cab filter	[Doyle]
July 29/21	10568	Service - 5w40 oil, both air	[Doyle]
Aug 31/21		Replace 3 LH AWD hoses	[Levi]
Oct 15/21	10856	Service - trans oil & filter , diff filter , hyd filter , cab filter's , Re & Re circle drive pinion shaft & brg's , new brass gear	[Doyle]
Oct 23/21	10864	Replace trans shift module	[Doyle]
Nov 30/21	10960	Service - 5w40 oil , both fuel , O. air , lites	[Doyle]
Jan 24/22	11185	Install new turbo & EGR cooler , change motor oil filter	[Levi]
Apr 4/22	11131	Service - 5w40 oil , both fuel , both air , cab filters , change trans & diff oil , trans & diff filters , replace 2 tierod ends , replace top sideshift slides , check A/C , install new sandvik boards , remove wing	[Clayton E]
June 01/22		Install all new sandvick bits.	[Levi]
July 15/22	11712	Service - 5W40, both air. Installed new gear selector switch assembly.	[Levi]
Nov 07/22	12134	Service - 5W40, Both fuel, both air.	[Chris]
Dec 08/22	12241	New ends and shims on side shift cylinder. New oil in tandems. Install wing.	[Braylan]
Feb 09/23	12453	Lower side shift shim keeper broken bolts removed.	[Chris]
March 08/23	12539	Service - 5W40, both fuel, both air. Repair keeper on wing pin.	[Chris]

[illegible]