

MAINTENANCE
Unit #T142
2007 Sterling Dump Truck
Serial# 2FZAATDJ27AX68909

Date	Hours	Work Performed
Nov 3/17		New To Fleet Rig-Up, Installed Reverse Lights, Back-up Alarm, Rear Flasher Lights, 2-way Radio, Chain Hangers [Steve]
Jan 8/18	1287	Install 2 vibrators on sanding unit [Steve]
Nov 6/19	1457	Service - 5w40 oil , both fuel , O. air , grease unit [Jacob]
Dec 13/19	1496	Replace sander drive gearbox !! Split open [Jacob]
Jan 2/20	1500	Rebuild sander drive gearbox - gear repaired by Precision Machining , rebuild Idler shaft at front of unit [Jacob]
Feb 27/20	1543	Replace front plow edges [Jacob]
Sept 18/20	1,574	Remove sander, clean out box and re-instal. Replace ratchet straps (Jacob)
Nov 05/20	1,592	Diagnose plow not working. Wrong size fuses in power dist. Box. (Jacob)
Dec 17/20	1642	Repair LH rear sander strobe lite [Jacob]
Feb 02-21	1,680	Built gate for sander, re built gear drive for sander, installed new back up lights . Jalco repaired gear and reduction box. (Jacob)
Mar 20/21	1739	Replace water pump & gasket behind oil filter base [Jacob]
Nov 10/21	1745	Install new batteries [Curtis]
Dec 12/22	27687	Passenger side outer drive tire. Fixed and mounted back on. [Michael]
Dec 15/22		Replace front plow edges [Shawn]
Jan 24/23	2354	Service - 5w40 oil, O. air , grease unit [Jaydan]
May 17/23	2658	#2 L and R brake lining replaced. Added reflective tape to box. License plate light replaced. Left rear marker replaced. Winshield replaced. [Jaydan]
Feb 06/24	2915	Service- 5W40, air filter, both fuel. Repaired valve. Repaired sander floor chain. [Jaydan]
Dec 02/24	3061	Replace power cable battery to starter. Replace trans cooler line. Replace hydraulic suction line. Repair hydraulic tank mounts due to cracks. [Jaydan]