

MAINTENANCE

Unit #328 - 2017 John Deere 470 GLC Excavator
S#!FF470GXTFE471331

328

Date	Hours	Work Performed
February 2018	1420	Purchased From Brandt
Mar 23/18	1570	Service - 0w40 oil , P. fuel , both air [Amos]
Apr 20/18		Hardface cleanup bucket , weld on wear bars from Finning [Doyle]
Apr 24/18		Replace cab filter [Amos]
May 8/18	1914	Flip cutting edge [Doyle]
May 10/18	1934	Service - 15w40 oil , O. air , replace left track adj zerk [Amos]
May 23/18	2032	Replace rite track tensioner valve [Amos]
Aug 9/18	2563	Replace cab filter [Amos]
Aug 27/18	2,658	Service - 15w40oil ,both air [Amos]
Oct 22/18	3033	Service - 0w40 oil , both fuel , both air [Amos]
Dec 20/18	3213	Tighten clamps on mian hyd suction hoses [Amos]
Feb 26/19	3463	Service - 0w40 oil , both fuel , O. air , fix lites [Amos]
Apr 2/19	3605	Both cab filters [Amos]
Nov 7/19	3937	Service - 5w40 oil , both fuel , both air [Amos]
Jan 3/20	4200	New bucket pin & bushings , build up side faces of stick , linebore coupler , new pin & bushings in H - link [Levi] Brg & Hyd did the linebore
Jan 15/20	4206	Service - 5w40 oil , both fuel , both air , cab filters , change final drive & swing oils , change hyd oil & fitters , change both track tensioner nipples , clean out fuel tank , fix lites [Levi]
Feb 5/20		Replace center broken tooth adaptor [Doyle]
Mar 30/20	4622	Service - 5w40 oil , O. air [Levi]
Sept 21/20	4777	Instal new water pump belts (Levi)
July 8/21	5128	Change final drive,s & swing oil's [Doyle]

MAINTENANCE

Unit #328 - 2017 John Deere 470 GLC Excavator

S#!FF470GXTFE471331

Nov 11/21	5388	Service - 5w40 oil , both air [Levi]
Dec22/21	5586	Change final drive & swing oils , change hyd oil & filters [Chris C]
Jan 25/22		Brg & Hyd - line bore stick pin , new pins & brgs Jalco - line bore Q/C & H-link
April 22/22	5730	Serviced Engine , fuel filters + Cab Filter. Repaired boom light RH. [Clayton]
Jan 14/23	6133	Service- 5W40, Hydraulic filters, both fuel, both air. [Russ G]
May 12/23	6558	Service - 5W40, both fuel, both air, both cab. Replace a/c belt and tensioner pulley and assemble. Check ac good. [Chris]
June 26/23	6571	Remove and rebuild water pump. Replace thermostats. Fresh coolant in machine. [Chris]
August 29/23	6602	Over heating issues. Hydraulic and engine coolant. Replaced water pump and thermostats. Replace sensors for hydraulic temp and both coolant sensors. Pull coolers + send to rad shop for acid wash. Re-install and test ok. Replaced RH cross over relief, adjust all pressures. test ok. [Chris]
Oct 10/23		Replace leaking o-ring on RH cross over relief. [Chris]
Oct 25/23	6897	Remove DPF, Get baked at kenworth. Diagnose + Replace coolant temp sensor. Replace alternator o-rings. Replace fan pump suction line coupler. Replace sight glass o-rings. [Jason]
Nov 01/23	6935	Service- 5W40, both fuel, both air. [Jason]
Dec 15/23	7324	Service- 5W40, both fuel, both air. [Chris]
Feb 17/24	7391	Flipped cutting edge. Dissassembled H Link + quick attach for line boring. Re-assemble and shim quick attach and Hlink. [Chris]
March 22/24	7557	Tighten pipeclamps on hydraulic lines. Service finals. Service swing motors. Pump shock line leaking. Replace o-rings and test. [Chris]
Oct 28/24	7710	Service- 5W40, both fuel, both air. [Chris]
Oct 30/24	7730	Bolts installed in car body stump pan. [Chris]
Feb 24/25	7965	Service- 5W40, both fuel, outer air, clean cab filter. [Shannon]
May 26/25		Service- 5W40, Both air filters, cleaned cab filter. Greased . [Shannon]

Unit #328 - 2017 John Deere 470 GLC Excavator
S#!FF470GXTFE471331

[illegible]