

MAINTENANCE
Unit #332 - Volvo 235E
S#T00314588

332

Date	Hours	Work Performed
June 16/21		Install 2-way radio & fire ext. [Jacob]
Nov 30/21	507	Service 5w40 oil , both fuel , both air [Levi]
Dec 17/21		Greatwest Equip - replace DEF pump
Mar 1/22	836	Change both thumb hoses at cyl [Levi]
Mar 4/22	837	Service - 5 w40 oil , O. air [Levi]
March 22/23	1322	Service - 5W40, both fuel, outer air. [Braylan]
July 5/23		Replace leaking flex line on stick cylinder. [Chris]
Nov 25/23	1868	Service - 5W40, secondary fuel, outer air. [Jason]
Feb 22/24		New window installed. [Alpine]
July 09/24	2638	Service - 5W40, both air, both fuel. [Chris]
July 22/24	2,671	Replace serpentine belt and AC V Belt [Chris]
March 21/25	3004	Service - 5W40, both fuel, outer air check over machine and all filters. Set all steps and repair and weld in place. [Shannon]
July 11/25	3291	Install new A/C compressor. Install new heat control as wouldn't auto A/C
Aug 19/25	3294	Remove and replair all broken bolts in upper structure under exhaust. Remove and repair all in hood. Weld supports, straighten under house guards. Remove broken bolts. (N/A)
Sept 4/25	3318	Service - Complete engine service. Oil, fuel, and outer air. Drain, flush and clean final drives. Repair 2-way, test A/C. Adjust belts. Grease. (Shannon)
jan 28/26	3363	def sensor problem, took apart mechine, had to get new armature assy sensor.
April 9/26	3644	Service - 5W40, both fuel, both air. [Ben]