

Moorvale Earthmoving
Asset History Report
KOMATSU HM300-2

Tuesday, 8 October 20

W/O No	Description	Complete
MERD06		
43862	Site intro Grosvenor	23/08/2024
47914	Topped up Trans - Oil leaking out of brake breathers	23/08/2024
48211	Refit seat adjusting lever - Knocked off again over the weekend	23/08/2024
50020	REMOVE VISION LINK READY FOR SALE	23/08/2024
49353	Fire suppression Service	19/07/2024
46347	Fire suppression Inspection Moranbah North	19/07/2024
49195	ARTICULATED (MOXY) DUMP TRUCK 250hr SERVICECompleted by: JustinHours: 11245HDate: 12/07/2024	12/07/2024
47556	REAR BRAKE COOLING TUBES RUSTED THROUGH AND LEAKING. TEMPORARILY PATCHED Replaced with nice new ones.Justin12/07/202411245H	12/07/2024
48631	Brake test - Moranbah NorthJustin13/06/202411159H	14/06/2024
47467	Replace broken front windscreen	23/05/2024
47462	Replace broken tub cables due to a concrete block hitting the tailgateLane 20/05/2024	23/05/2024
47902	Slow to crank - Front battery 8.5V rear 12.5V	13/05/2024
47779	Replace faulty beaconRemoved and replaced beacon 02/05/2024 10992H	2/05/2024
47507	ARTICULATED (MOXY) DUMP TRUCK 1000hr SERVICECompleted by:Hours:Date:17-4-24	18/04/2024
46784	ARTICULATED (MOXY) DUMP TRUCK 1000hr SERVICECompleted by: CLAYTON, TED, JAKEHours: 10943Date: 17/04/24	17/04/2024
47397	2G43ZG Rear brake oil pressure low.Checked kick in and out pressures.Checked and adjusted accumulator pressures.Fault gone tested OK.	12/04/2024

W/O No	Description	Complete
47088	DX12K4 front brake pressure switch faultyReplaced due to stuck normally closed	30/03/2024
46447	ARTICULATED (MOXY) DUMP TRUCK 250hr SERVICECompleted by: JustinHours: 10777HDate: 07/03/2024	7/03/2024
46501	Blown brake charge hose.Jacked the cab and replaced the blown hose. Topped up oil.	29/02/2024
45658	Site intro Moranbah NorthJustin 23/01/2024 10593H	23/01/2024
44071	fire suppression service	2/12/2023
44029	RIM CRACK TESTING	2/12/2023
44600	3 Month brake test Moranbah NorthJustin 23/11/2023 10416H	23/11/2023
44110	Paint machine	23/11/2023
44090	REPLACE BRITTLE/LEAKING HYDRAULIC HOSE UNDER CAB	24/10/2023
42112	Transmission not selecting gearspreviously repaired	15/10/2023
43547	ARTICULATED (MOXY) DUMP TRUCK 250hr SERVICECompleted by: DanHours: 10414Date:14/10/23	14/10/2023
43645	Tipping fault - cleaned cab tip control, detents U/S. Problem still present.12/10 - hoist controller was replaced and tray was still coming up on its own. hoist pilot valve was removed and stripped as per komatsu instructions. solenoids tested fine and valve seemed to be fine on inspection but fault is no longer present	13/10/2023
43582	Complete Level 1 Service - ChubbCompleted: 03/10/2023	13/10/2023
42623	Tub dump knob broken.Replaced but was not the issue	13/10/2023
43546	Flat pos 3 tyre1/10/23 - No run outs in stock - tyrepanic carried out workPos 1 > pos 3Pos 2 > pos 42 new steers fitted now left with 1 good runout	1/10/2023
41855	bottom mirror gone (26-Jun) RHS bottom mirror gone (30-Jun 03-Jul) Replaced Justin 04/08/2023	8/08/2023
41122	ARTICULATED (MOXY) DUMP TRUCK 2000hr SERVICECompleted by: ScheanHours: 10082Date: 11/07/2023	12/07/2023
41174	Replace broken grease nipple on block.	6/06/2023
41030	Carry out brake test.	31/05/2023

W/O No	Description	Complete
40752	12 month fire suppression service	23/05/2023
40276	Blown hose under cab somewhere Schean 22/05/2023 9922H	22/05/2023
38508	Fit Caterpillar GPS unit as required.	3/03/2023
38474	Engine vibration, Damper splines.	3/03/2023
38416	12 month site intro Moranbah North	3/03/2023
38390	air con not working very well (23-Nov 05,06-Dec)	3/03/2023
38362	Repair battery isolator.	3/03/2023
38239	Fire suppression leak	26/01/2023
37881	Blown hose back of cab	26/01/2023
37541	POS1 and POS6 oil leak after being bogged.	26/01/2023
36498	Broken seat (14/09 SMU 9424)	26/01/2023
35978	replace faulty window regulator	26/01/2023
35831	Repair light on Dumpy.	26/01/2023
35170	Replace exhaust elbow and Fuel lines	26/01/2023
35077	1000hr service	26/01/2023
33776	A/C compressor failure	26/01/2023
38091	ARTICULATED (MOXY) DUMP TRUCK 250hr SERVICE Aaron M 03/02/2023 9752H	4/01/2023
37496	Replace Bonnet Cable Aidan 22/11/2022	23/11/2022
37441	Replace leaking oil cooler hose Schean 10/11/2022	11/11/2022
37221	3 Monthly brake test Moranbah North Aaron M 02/11/2022 9610H	3/11/2022
36903	ARTICULATED (MOXY) DUMP TRUCK 500hr SERVICE Aidan M 11/10/22 9534H	11/10/2022
38038	Fire Suppression 6 Monthly InspectionCompleted by: ChubbDate: 29-8-2022	29/08/2022
36059	Replace heater hoses.	24/08/2022

W/O No	Description	Complete
35980	ARTICULATED (MOXY) DUMP TRUCK 250hr SERVICE Darcy 19/08/2022	19/08/2022
35802	Repair coolant leak.	10/08/2022
35696	3 Monthly brake test Moranbah North	4/08/2022
35254	Replace broken grease line.	14/07/2022
34561	ARTICULATED (MOXY) DUMP TRUCK 1000hr SERVICECompleted by: Aaron Marsh Date: 30-06-2022Hours: 9086hrs	30/06/2022
34028	Pre cleaner broken	19/05/2022
33371	Park brake fault	3/05/2022
33295	indicator light replacement, site defects Replace brake cooling hoses	3/05/2022
33221	Replace tyres on poss1/2	3/05/2022
32315	Fire Suppression 6 Monthly Inspection	3/05/2022
31655	Site intro Moranbah North	3/05/2022
31273	Drivers door handle broken	3/05/2022
33210	Glue rear window in	23/03/2022
31527	ARTICULATED (MOXY) DUMP TRUCK 250hr SERVICE	17/02/2022
28853		3/02/2022
30627	Replace Flashing light	16/12/2021
30769	UHF poor range	16/12/2021
30655	F/R indicator blown	16/12/2021
30335	Could use new sight glass for hydraulic oil (13/11, SMU 4400	2/12/2021
29006	Front Brake Accumulator pressure fault	2/12/2021
30052	500hour service	18/11/2021
30404	Brake test for Moranbah North	18/11/2021
30402	Tail lights holder bent (16/11, SMU 8528	18/11/2021

W/O No	Description	Complete
30267	inter axle lock not working	18/11/2021
28472	Seat fault, remove seat from RD05 to install	8/07/2021
28392	upgrade final/wheel end breathers	8/07/2021
28388	LHR tail light assy	8/07/2021
28386	Inspections for M north, defects	8/07/2021
27931	Air con cold but barely any air (22/02 SMU 8022)	8/07/2021
27928	POS 2 final drive leak (17,18/02 SMU 8005)	8/07/2021
27338	Transferring oil from brake cooling to final drives	8/07/2021
26831	MOXY 2000hr SERVICE @ 8,000 Hrs	25/06/2021
28546	Fire sup service,	6/05/2021
27818	Fit GPS system as required.	15/03/2021
27805	Repair fire suppression Fault	15/03/2021
27793	Get Moxy ready for Callide Mine	15/03/2021
27300	Fire Suppression 6 Monthly Inspection	14/12/2020
25925	Air on seat not working (24/09 SMU 7767)	11/11/2020
25995	Top light not working (01,02/10 SMU 7805)	26/10/2020
25754	MOXY 250hr SERVICE @ 7,750 Hrs	1/10/2020
25945	Seat Cushion on back rest u/s send to seat shop for repair	29/09/2020
24850	Seat adjustment broken (16/07 SMU 7463)	24/09/2020
25869	CHECK FIRE SUPPRESSION FAULT	21/09/2020
25439	Tub sensor fault	20/08/2020
25417	BRAKE TEST & SITE PAPERWORK	17/08/2020
24918	Radiator cap leaking on hose (22,23/07 SMU 7519)	6/08/2020

W/O No	Description	Complete
24841	MOXY 500hr SERVICE @ 7,500 Hrs	30/07/2020
24780	Reverse alarm not working (14/07 SMU 7459)	29/07/2020
24681	LHS brake light out (8/07 SMU 7446)	29/07/2020
24800	Repair Auto Greaser change wiper blades	20/07/2020
24718	Reverse alarm not working (10/07 SMU 7453)	14/07/2020
24619	Chair lever broken off (02/07 SMU 7430)	14/07/2020
24308	Auto greaser not working (17/06 SMU 7370)	26/06/2020
24045	Fire Suppression 6 Monthly Inspection	16/06/2020
23348	Seat adjustment forward and back broken (28/05 SMU 7323)	8/06/2020
23347	Seat belt light won't go out (28/05 SMU 7323)	8/06/2020
22314	Some lift rams may not be greasing (20/02 SMU 7059)	8/06/2020
23160	Passout for moranbah north Replace door seals	3/06/2020
23151	Replace Batteries	22/05/2020
23155	Repair right hand hub leak'Replace window switch	21/05/2020
21853	MOXY 250hr SERVICE	30/04/2020
20155	cas cam/ lights / check over	23/03/2020
18307	Repair oil leak on RH front drive flange	4/03/2020
18079	Replace coolant header tank & missing wheel chocks	26/02/2020
17900	Pump fuel up every time to start (18,19,20/12,06/01 SMU 6960)	26/02/2020
17899	Seat won't pump up (12,16,17,18,19,20/12,06/01 SMU 6937)	26/02/2020
19266	replace seat switch	26/02/2020
18879	Window button (23,24,27/01,05/02 SMU: 6997)	26/02/2020
18878	Two way is broken (23,24,27/01,05/02 SMU: 6997)	26/02/2020

W/O No	Description	Complete
19707	Replace Seat slides Replace park brake switchReplace mirror left hand lower	26/02/2020
22312	Fix interior lights	24/02/2020
21512	Mount and wire up millennium radio	21/01/2020
21462	Fit up new coolant over flow bottle	17/01/2020
20521	peabody inspection	15/01/2020
20686	Grease lines	13/01/2020
20654	kick rails	13/01/2020
17105	Fire Suppression 6 Monthly Inspection	13/01/2020
20543	Fuel primers	9/01/2020