

Equipment Maintenance Summary

Caterpillar 259D Tracks SS-15

Timeframe: 01/01/2016 → 04/01/2026

Scope: Both Maintenance and Repair

Generated: April 1, 2026 9:23 AM

Description	Start	End	Hours/KM	Type	Rule	Created
Topped up coolant. Mechanic = Joe	02/28/2018 12:00 AM	02/28/2018 12:00 AM	46/-	Maintenance		03/05/2018 2:56 PM
Changed battery.	02/28/2018 12:00 AM	02/28/2018 12:00 AM	46/-	Repair		03/05/2018 3:10 PM
Drained hydraulic oil, changed filter and refilled tank. (Operator filled with diesel) Mechanic = Colin	04/24/2018 12:00 AM	04/24/2018 12:00 AM	157/-	Repair		04/25/2018 9:07 AM
Change Engine Oil & Filter (11L 10W40 PetroCan Full Synthetic), Air Filter - Greased - Sent engine oil sample to Finning Mechanic = Shawn & Carl	07/06/2018 12:00 AM	07/06/2018 12:00 AM	427/-	Maintenance	Skid Steer - 500 Hour	07/24/2018 11:17 AM
Changed oil in final drives and sampled. Sampled engine oil. Mechanic = Carl	05/30/2018 12:00 AM	05/30/2018 12:00 AM	276/-	Maintenance		02/06/2019 3:53 PM
Finning - Repair Beacon	02/28/2019 12:00 AM	02/28/2019 12:00 AM	685/-	Repair		03/01/2019 9:00 AM
Replace Factory Isolation Switch with Lockable Unit - Check A/C - Wash - Grease Mechanic = Blake	05/17/2019 12:00 AM	05/17/2019 12:00 AM	770/-	Repair		05/24/2019 12:47 PM
Change Engine Oil & Filter (11L 10W40 PetroCan Duron UHP Synthetic), Air Filter, Fuel Filter, Hyd. Filter, Inline Fuel Filter, Cab Air Filters, Final Drive Oil (Cat Synthetic GO SAE 75W-140), Greased - Washed Mechanic = Blake	05/17/2019 12:00 AM	05/17/2019 12:00 AM	770/-	Maintenance	Skid Steer - 500 Hour	05/24/2019 1:07 PM
Change Engine Oil & Filter (11L 10W40 PetroCan Duron UHP Synthetic), Air Filter, Fuel Filter, Hyd. Filter, Inline Fuel Filter, Cab Air Filters, Final Drive Oil (Cat Synthetic GO SAE 75W-140), Greased - Washed Mechanic = Blake	05/17/2019 12:00 AM	05/17/2019 12:00 AM	770/-	Maintenance	Skid Steer - 500 Hour	05/24/2019 1:07 PM

Check GPS - GPS is showing a change in location but is not tracking hours properly. - Last Service at 770 Hours - Removed GPS ESN# 4661206105 Sent to Office	11/14/2019 12:00 AM	11/14/2019 12:00 AM	963/-	Repair		11/14/2019 7:47 AM
				Repair Request Check Over Check GPS - GPS is showing a change in location but is not tracking hours properly. - Last Service at 770 Hours November 12, 2019 12:14 PM by Chris Bildfell		
Replace Beacon Bulb - Repair and Heat Shrink Wires in Door - Wash - Check Lights Mechanic = Mickenzie	11/15/2019 12:00 AM	11/15/2019 12:00 AM	963/-	Repair		11/17/2019 10:02 PM
Replace Engine Air Filter	04/17/2020 12:00 AM	04/17/2020 12:00 AM	1,201/-	Maintenance		05/12/2020 4:35 PM
Change Engine Oil & Filter (11L 10W40 PetroCan Duron UHP Synthetic), Outer Air Filter - Greased - Washed Mechanic = Blake	05/13/2020 12:00 AM	06/12/2020 12:00 AM	1,250/-	Maintenance	Skid Steer - 500 Hour	06/29/2020 10:12 AM
Replaced Cab after Roll Over - Cab Supplied by Finning Caterpillar Mechanic = Blake & Carl	08/14/2020 12:00 AM	08/14/2020 12:00 AM	1,475/-	Repair		12/16/2020 10:31 AM
Replace Cab Door with New Glass Using Old Hardware Mechanic = Jace	12/10/2020 12:00 AM	12/10/2020 12:00 AM	1,708/-	Repair		12/18/2020 2:17 PM
Change Engine Oil & Filter (11L 10W40 PetroCan Duron UHP Synthetic), Inner and Outer Air Filters, Fuel Filter, Hyd. Filter and Breather, Inline Fuel Filter, Cab Air Filters, Final Drive Oil (Cat Synthetic GO SAE 75W-140), Greased - Washed Mechanic = Blake	01/04/2021 12:00 AM	01/04/2021 12:00 AM	1,708/-	Maintenance	Skid Steer - 500 Hour	01/11/2021 3:32 PM

Install Engine Oil Quick Drain Plug - Replaced Front Door Glass and Hardware - Set Stricker on Door - Replaced Block Heater Element (Cord Still OK) - Check Lights, Replaced LHS Front Work Light - Repaired Ground Wire and Replaced Bulb in Rear LHS Work Light - Tighten Connection on Rear Red Light - Check and Adjust Track Tension - Wash Under Cab and Wash Out Engine Bay - Grease - Check Fire Ext Mechanic = Blake and Jace	01/04/2021 12:00 AM	01/04/2021 12:00 AM	1,708/-	Repair	01/11/2021 3:39 PM
Install GPS ESN# 4673430249 - Include Location of Install On Machine Please and Thank You - Installed Under Cab Mechanic = Tanner	05/03/2021 12:00 AM	05/03/2021 12:00 AM	1,748/-	Repair	05/05/2021 10:46 AM
				Repair Request Install GPS Install GPS ESN# 4673430249 - Include Location of Install On Machine Please and Thank You April 30, 2021 1:29 PM by Chris Bildfell	
Check Fluids, Track Tension, Beacon, Lights (Replaced Rear LHS Red Bulb) BU Alarm, Decals, Reflective Tape, Operator Manual, Fire Ext, Seat Belt, Horn, Mirror, Wash, Grease - Re-Install Glow Plug Wires Mechanic = Tanner	05/03/2021 12:00 AM	05/03/2021 12:00 AM	1,748/-	Repair	05/05/2021 10:55 AM
Repaired beacon wiring Replaced fire extinguisher Clean battery posts and apply dielectric grease	N/A	N/A	-/-	Repair	06/08/2021 2:58 PM
Replaced Both Tracks	12/03/2021 12:00 AM	12/03/2021 12:00 AM	1,977/-	Repair	12/03/2021 2:19 PM
- Replace o-ring and tighten hydro line @ track motor - added 16.5L T04+10W - Replaced front right headlight bulb - hardwired beacon - greased machine - Replaced battery - Replaced coolant line from oil cooler to EGR - TANNER	N/A	N/A	-/-	Repair	12/14/2021 7:56 AM

- changed engine oil and filter - changed in line fuel filter and cartridge fuel filter - changed inner and outer air filters - changed cab air filter and fresh air filter - greased machine and tensioned tracks - cleaned dirt out from under the cab - Tanner	N/A	N/A	2,246/-	Maintenance	Skid Steer - 500 Hour	03/25/2022 11:49 AM
- changed 4 hydraulic lines on left hand drive motor, added vibration protection on to the lines for left and right hand side - added weather stripping to the top of the radiator for vibration protection - replaced block coolant drain valve - tested block heater - working - cleaned mud out of the coolant radiator - Tanner	N/A	N/A	2,246/-	Repair		03/25/2022 11:53 AM
Replaced cutting edge on bucket Devin	04/06/2022 12:00 AM	04/06/2022 12:00 AM	2,260/-	Repair		04/06/2022 4:52 PM
Replaced 3 work light bulbs Greased machine Checked over machine Blake, Carter	N/A	N/A	2,358/-	Repair		07/07/2022 10:38 AM
Replace broken hyd fitting on RHS drive motor Devin	09/10/2022 12:00 AM	09/10/2022 12:00 AM	2,491/-	Repair		09/10/2022 2:51 PM
Replace pin on end of quick attach cylinder with bolt Blake, Carter	N/A	N/A	2,519/-	Repair		10/02/2022 3:39 PM
Changed engine oil and filter Changed fuel filter and inline fuel filter Changed inner and outer air filter Changed both cab filters Changed hydraulic breather Changed hydraulic filter Didn't have the gear oil for finals so couldn't do them Carter, Morgan	N/A	N/A	2,741/-	Maintenance	Skid Steer - 500 Hour	06/27/2023 1:58 PM
Changed both final drive fluids that were due at the original 1000hr service -Aidan	10/06/2023 11:00 AM	10/06/2023 12:00 PM	2,788/-	Maintenance		10/06/2023 1:21 PM
Replace Engine with Rebuilt Engine from Parkland Engine Rebuilders in Yorkton, SK	01/23/2025 12:00 AM	01/23/2025 12:00 AM	2,788/-	Repair		01/23/2025 1:58 PM
replaced left side quick attach pin and spring Rylan and Kalan	09/24/2025 12:00 AM	09/19/2025 12:00 AM	2,975/-	Repair		09/19/2025 8:29 AM
Changed engine oil and filter, changed fuel filter and in-line fuel filter,changed air filter,changed cab filter. Clarence	01/23/2026 12:00 AM	01/22/2026 12:00 AM	3,295/-	Maintenance	Skid Steer - 500 Hour	01/22/2026 11:53 AM

Jammed quick attach due to dirt and rust, Clean and lubricate Wiper not functioning - rewire and replaced deutsch connector Clarence	01/21/2026 12:00 AM	01/21/2026 12:00 AM	3,295/-	Repair	01/22/2026 12:00 PM
---	------------------------	------------------------	---------	--------	------------------------