



# THUNDER BAY TRUCK CENTRE, Inc.

WWW.TBTC.CA

EMAIL: MAIL@TBTC.CA



**Peterbilt Thunder Bay**  
 1145 Commerce Street  
 Thunder Bay, ON P7E 6E8  
 (807) 577-5793 or (800) 465-5030  
 Fax: (807) 577-8918

**Peterbilt Fort Frances**  
 505 McIrvine Road  
 Fort Frances, ON P9A 3X7  
 (888) 889-2344 or (807) 274-7936  
 Fax: (807) 274-2813

**Peterbilt Dryden**  
 70 Keith Avenue  
 Dryden, ON P8N 3K8  
 (807) 223-7577 or (844) 223-7577  
 Fax: (807) 223-8482

**Peterbilt Longlac**  
 106 Hamel Ave.  
 Longlac, ON P0T 2A0  
 (807) 876-2687  
 Fax: (807) 876-2570

<b>Sold To:</b>	Number	W3105	<b>REPAIR ORDER NUMBER</b>
	Phone	902 899-2900	<b>DR19954</b>
	P.O. NO.		<b>Inv Date: 10-22-25</b>
	Complete	10-06-25	<b>SVC WRITER</b>
	Open Date	10-06-25	MT*JP

### CUSTOMER INVOICE

Page: 1 of 2

<b>SERIAL NO.</b> 1XPTDPOX1LD638633		<b>UNIT NO.</b> 638633		<b>MILEAGE</b> 525584	
<b>YEAR / MAKE / MODEL /</b> 2020 / Peterbilt / 367				<b>ENG HRS</b> 16027.0	
<b>ENGINE / SERIAL</b> MX-13 / Y191461				<b>LICENSE</b>	
<b>TRANS / SERIAL</b> RTLO18918B / P1248551				<b>CPL/ARRG</b> P011	
<b>RXLS MODEL/SERIAL</b>		D46-170/HN07681624, D46-170/HN07681625			
<b>SELL DLR</b>		<b>DEL DATE</b>	07-11-19	<b>DEL MILE</b>	

1 INSPECT CAUSE OF ENGINE LIGHTS ON. FULL DERATE PRESENT.  
 CAUSE:  
 DEF DOSING VALVE CRACKED. DEF TANK DIRTY AND FILTER PLUGGED.  
 DEF PUMP WEAK.  
 CORRECTION:  
 CONNECT DAVIE AND REVIEW CODES. T/S DEF DOSING VALVE SHORTED CODES.  
 REMOVE STEP AND DOSING VALVE. OHM VALVE-OUT OF SPEC. REPLACE VALVE.  
 TRY TO PRIME-NO PSI. REMOVE TANK. FLUSH TANK AND REPLACE PRE FILTER.  
 INSTALL TANK AND FILL WITH DEF. ATTEMPT TO PRIME-NO GO. REPLACE DEF  
 PUMP. UNIT PRIMED. RUN REGEN TO VERIFY AND CLEAR DERATE.

TOTAL LABOR	787.50
TOTAL PARTS	3,297.78
TOTAL ELECT-TEST	100.00

Qty	Part Number	Description	Unit	Extended
1	2115633PE	INJECTOR, DOSER	1,156.10	1,156.10
1	2192544PE	GASKET, AFTERTREATMENT	85.77	85.77
1	085471WMA	KIT-FILTER REPLACEMENT	32.39	32.39
8	KLF002	KLEENDEF 2.5GAL JUGS	11.66	93.28
1	5506956RXCUM	PUMP,DOSER	1,917.84	1,917.84
2	MP33848MSC	HX HD DRILL SCREW, 1/4-14	1.44	2.88
2	5841001200	RELEASE CLIP-DEF LINE, 5/	4.76	9.52
1	ECT-TEST	ELECT-TEST	100.00	100.00

MISCELLANEOUS SUPPLY 77.18

SLS-SVC CUST LBR TRK	787.50
SLS-SUNDRIES	77.18
SLS-PTS SHOP	3,297.78
ELECTRONIC TESTING	100.00

Customer Print Name: \_\_\_\_\_

Customer Signature: \_\_\_\_\_ Date: \_\_\_\_\_

GST# R105278493

RETURNS: PARTS MUST BE RETURNED WITH 30 DAYS OF PURCHASE, ALL RETURNED ITEMS ARE SUBJECT TO A 10% HANDLING CHARGE WHEN SUPPLIED AS ORDERED AND MUST BE ACCOMPANIED BY OUT PACKING SLIP OR INVOICE.

TERMS: NET 30, 2%PER MONTH 24% PER ANNUM SERVICE CHARGE ON ALL OVERDUE ACCOUNTS.

Work Order  
**DR19954**

**Invoice Date:** 10-22-25  
Page 2 of 2

H.S.T. R105278493  
PLEASE PAY THIS TOTAL

554.12  
4,816.58