

Description	Raised
Conveyor Maintenance - Steel return roller	08/18/2025
Conveyor Maintenance - Fabricate & Supply new Discharge Belt.	08/11/2025
Boltmasters - High tensil threaded Rod andHex Nuts. Split Pins Asstd Sizes	08/07/2025
Lincom - Inspect telemetry system and speed wheel	06/13/2025
Hastings Deering - Mountings, Washer Bolt	05/07/2025
Hastings Deering - Pin	05/07/2025
OMS - Replace feeder hose, replace 2 x hose back controls to RH wing cylinder, replace x cross over hoses between chassus ar head drum of main conveyor, spiral wrap hoses	05/05/2025
GDGU Auto Electrics - Fitted & wired up Jump Start Receptacle & Isolator circuit	04/28/2025
Conveyore Maintenance - poly liner boards 920mm x 180mm 10mm thick	04/15/2025
Lincom - Tail drum	04/14/2025
KG Engineering - Repair Keyway & shaft. Recess holes in plates	03/26/2025
Conveyor Maintenance - Spiral return rollers, steel return rollers, Ubolts, Washers & Nyloc Nuts, Poly strips	03/18/2025
OMS - Remove/lift guarding around engine fan, Make pins for back door hydraulic pin, 2000hr service, fit new alternator pulley & Belts, fit feeder side wings, fit back door feeder	03/12/2025
Lincom - Gear, key, bearing lock washer, nut bearing lock, oring, bearing, Anti-Vib Nordloc washer, hex bolt	03/11/2025
CRD Contracting - Weld in wear plates	03/09/2025
Hastings Deering - Pulley V belts	03/07/2025
Lincom - Hydraulic cylinder, Fluid level/Float Switch, Pressure filter element	03/05/2025
Britrac - Superskirt	03/04/2025
OMS - Fit crusher drive Belts	03/03/2025
Lincom - Filter for service	03/03/2025
Lincom - Hydraulic cylinder	02/28/2025
Southern Qld Steel - Steel plate 8 x 2485 x 8000 400QTP	02/20/2025
Seal Innovations - Reseal Conveyor Left Rams, Oil Seal, Rotary Seal	02/20/2025

Lincom - Relay & Base	02/18/2025
Motion Australia - Taperlock Bushes, Spherical bushing	02/18/2025
Lincom - Pulley	02/17/2025
Motion Australia - Optibelt SK Wedge Belt	02/06/2025
NAPA - Batteries, Battery Master switch, Remote control Batteries	11/29/2024
OMS-Install new seal in Clutch	09/22/2024
OMS- Repare Hose Seelline to oil cooler, recover steel line to hose fitting	09/18/2024
Lincom - Outer seal Kit encl End Plate	09/18/2024
Lincom - Aerial & Modem	08/06/2024
Lincom - Speed Wheel Sensor Assy, Speed Wheel Cable Conveyor	07/22/2024
OMS - Repairs to Guards, Cabinet Filter System, Repair broken harness	07/18/2024
Licom-Fluid Level/ Float Switch, Drive Belt,Toggle Bracket Pin,Sling assy	07/09/2024
Lincom-Hardened Bush, spring adjusting Mounting,	07/09/2024
1 x FC332-10 Hose; 5 x B-P7-06 Joiners Brass; 5 x B-P7-08 Joiners Brass 3 x BTM-BSF-BTM-040404 Taper m/f Swivel - PO 24479 Hosepower	11/23/2023
2 x 8RLA Hose 1/2 FIB/BRA SAE30R2; 2.3 x 12CR2 HOSE 3/4 2Wire SAE 100R2; 1 x SFB-1212 Stem Fitting 3/4 BSPP S/FEM; 1 x SFB90-1212 Stem Fitting 3/4 BSP S/FEM 90'; 2 x FNP-12 Ferrule Body C1T/2AT/C5C - PO 24443 CDM Hydraulics	11/21/2023
1 x Plain Jig Bush; 1 x Drawback Pin - PO 24259 Lincom Pacific	11/02/2023
2 x Hoses & Fittings - PO 24347 RMS	11/02/2023
4 Each 2215-0122 Pin Hex Lock Nut M36-4.0GR8.8; 2215-0024 Nut Hex 36MM; 31.10.0706 Washer Compression AZ496; J54AX1173A Washer Cup Wedge (31.10.0243); 10.0244 Jaw Holder Rubber Washer (J54A; CR021-014-001 Wedge Bolt Fixed; 1 Each CW021-013-MN140 Fixed Jaw Wedge NDS (Supertooth); CW021-015-MN140 Fixed Jaw Wedge DS (Supertooth) - PO 24291 Lincom Pacific	10/26/2023
500hr Service at 8523hrs	10/25/2023
1 x 60526055 Node Block - PO 24093 Lincom Pacific	09/29/2023
2 x 4W1203 Cup; 2 x 4W1204 Cone; 1 x 6V9748 Seal; 1 x 8S1475 Vee Belt Set - PO 24058 Hastings Deering	09/25/2023
1 x 8S1475 V Belt Set - PO 24150 Hastings Deering	09/24/2023
Hydraulic Hoses and Fittings - PO 23681 CDM Hydraulics	07/31/2023
250hr Service @ 8305hrs	07/20/2023
Water Pump - PO 23561 Hastings Deering	07/13/2023
1 x Conveyor Belt 1200mm 4 ply 6/2 covers endless with a Superscrew on Bias - PO 23391 Fenner Dunlop	06/09/2023
Coolant Oil Filters, Air Filters, Fuel Filters - PO 23371 Hastings Deering	06/07/2023
1 x 22% Moving Jaw Liner Sup/Tooth - PO 23266 Lincom Pacific	05/22/2023

Alternator & Parts, Fuses, Multimeter, & Fuse Kit - PO 023265 NAPA	05/19/2023
1000hr Service @ 8037hrs	05/17/2023
1 x Hydraulic hose and fittings - PO 23147 CDM Hydraulics	04/24/2023
250hr Service @ 7834hrs	04/12/2023
Replace Hydraulic Hoses and fittings - PO 22915 Hosepower	03/02/2023
500hr Service @ 7580hrs	02/22/2023
Repairs on site, 2 x Contactor 3P 9A 24VDC Coil, 1 x PLC Safety Controller (PLC), 1 x Programming Software - PO 22849 Lincom Pacific	02/20/2023
Hyd Return Hose U/S, Temp repair, Brendan to order new hose from CDM Kununurra	02/07/2023
Replace Hyd Tank and Fuel tank mounts, 4x 12.09.0082 Mounts, 4x 12.09.1055 Mounts, 8 x Roller Mounts, 8 x U Bolts, 4 x Tracking Rollers - PO 022778 Lincom Pacific	02/07/2023
PC Head Drum nip guard, Main Conv Head Drum Slide Pad under magnet, Slider Pad - PO 022793 Lincom Pacific	02/03/2023
Service filters - PO 22735 Hastings Deering	02/02/2023
500hr Service Kit - PO 022711 Applied Industrial Tech.	01/31/2023
Hydraulic Motor, Main Conveyor Head Drum - PO 22653 Lincom Pacific	01/19/2023
Tail Drum Assembly - PO 22647 Lincom Pacific	01/19/2023
Grizzly Sections to be replaced, Recieved Grizzly sections on site, Boilermaker to hard face before installing - PO 022642 Lincom Pacific	01/18/2023
250hr Service @ 7269hrs	12/07/2022
9 x 100 x 55 x 1550mm Impact bars -PO 22251 Lincom Pacific	11/07/2022
Supply 28 mtres of 12mm wide 4ply 6/2 conveyor belt with ar63 Superscrew Installed - PO 22250 Fenner Dunlop	11/07/2022
1000hr Service @ 6973hrs	10/24/2022
2 x 100 x 55 x 1500mm Impact Bar - PO 21952 Lincom Pacific	09/26/2022
1 x Superskirt 200 x 12 x 15250 1 Roll, 3 x Superscrew 63 900 wide kit - PO 21927 Britrac	09/21/2023
2 each Spherical Roller Bearing, Split Housings, Split Housing Components, Fixing Rings, Sleeves - PO 21916 Applied Ind Tech	09/19/2022
D/Row Spherical, adaptor sleeve, spacer ring, housing cover, seal. - PO 21915 Statewide Bearings	09/19/2022
1 x 22% Fixed Jaw liner Super/Tooth - PO 21875 Lincom Pacific	09/14/2022
1 x Contactor 3P 9A 24VDC Coil - PO 21856 Lincom Pacific	09/12/2022
8 x SPC8000 Belts - PO 21776 Applied Ind Tech	09/05/2022
3 x Hydraulic Hoses & Fittings - PO 21737 CDM Hydraulics	08/29/2023
2 x 6i2509 Filters - PO 21712 Hastings Deering	08/24/2023
2 x N150 Batteries - PO 21703 Battery World Darwin	08/23/2022
14 x Lagging rubber natural diamond 12mm 40m roll, rema sc2000 cement 1.0kg kit 5250980 - PO 21692 Fenner Dunlop	08/22/2022

Housing, D/Row Spherical, Adaptor Sleeve, Housing Cover, Spacer Ring - PO 21651 Statewide Bearings	08/11/2022
500hr Service @ 6533hrs	08/07/2022
500Hr Service Kit - PO 21450 Hastings Deering	07/07/2022
250hr Service @ 6187hrs, Service, change oil in plate feeder & clean - PO 21179 Preventative Maint NQ	05/09/2022
250 Hr Service Kit - PO 21115 Hastings Deering	05/05/2022
HASTINGS DEERING: Fuel water separator & bowl	01/13/2022
BRITRAC: Supply & install new discharge belt. 1200 wide. 4 ply. 10:3 Covers. 28 metres open length.	01/12/2022
BRITRAC: 2 x K-Superskirt 150x12mmx15.2 metres	01/12/2022
Hydraulic oil to be replaced when back at TSV Workshop.	11/23/2021
ISSUES FROM 2000HR SERVICE: Coolant should have been replaced at the 2000hr service - but there was no coolant onsite at Dotswood. The tracks gearbox oil could not be replaced as the tracks were buried. GR requested for the hydraulic oil not to be replaced.	11/20/2021
2000hr service: 6053	11/20/2021
LINCOM: Filter blower assembly 60502468	10/21/2021
500hr service 5,542	08/02/2021
TONKIN: Supply and cut 20mm 400 biz for grizzly bars for ID185 at Oakleigh Quarry. 1 @ Grizzly A - 1100 x 1100 c/w 18 x 250. 1 @ Grizzly B - 1100 x 1100 c/w 23 x 250.	06/28/2021
LINCOM: 4 x snubber rubber	06/24/2021
LINCOM: Supply and install new Clutch	06/21/2021
16 x SPC8000 V Belts from STATEWIDE	06/18/2021
Replace 3 x skirting rubber	06/11/2021
ALLSORTS FABRICATION: Repair cracks and fishplate, remove & replace wing pins, design and fabricate captive washers.	04/28/2021
LINCOM: PT600 Feeder cover	04/20/2021
1000hr service - 5010	11/27/2020
250hr service - 4,722	09/17/2020
STATEWIDE BEARINGS: Bearing housing assemblies with spacer rings	08/10/2020
500hr service - 4,491.8	06/22/2020
BRITRAC: 28 metre x 1200 wide feeder belt. PN800/4 M+ Grade, 10/3 Covers	05/27/2020
BURSON: New Battery	10/08/2019

LINCOM REPAIRS: Clutch seal leaking on the outer seal. Removed drive belts, pulley and cover plate. O Ring hardened. Surfaces marks on the front of the clutch housing and heat marks in the still were noted. Slight scuffing on the inside face of pulley. Bearing tolerance 0.002 inch. Replaced seals, refit pulley. Pulley initially 9.5mm inside shaft end, refit to flush with end of shaft to better Align belts. Refit drive belts. Loose resistor on node 2 - tightened. Disconnected and cleaned 2 into 1 plug for node 1 & 2. Earth isolation points loose - tightened. Node plugs into cabinet full of dust - cleaned out. Cabinet dusty - cleaned out. Rear panel in elec cabinet loose - tightened and put bolt through to secure. Earth lead onto rear panel in cabinet not connected - reconnected. Plug on PLC dusty - cleaned. To access screen frame bolts had to move diverted chute. Due to modifications made by customer had to cut out holes for the bolts on the bottom side of the shaft and remove expand foam. Found bash plate had been welded into where the screen mesh should sit. Loosened of all bolts on vib frame and screen frame, took measurements.	09/20/2018
POLY PROTECTIVE COATINGS: 10 x Conveyor skirt 1530 x 155 x 55mm red urethane	09/04/2018
PRE-START - Emergency stop switches missing from next to crusher, Missing ladder beside crusher.	08/20/2018
PRE-START - Handrails damaged, Pin Bent on feeder wing, Door fallen off control box, Skirt rubber need replacing. REPAIRS: ALECT: Remove and replace 24v Fan motor for control box pressurizer - Test all ok. E Stop Repairs. LINCOM: Outer Dual Seal Kit (includes end plate) PT600 Clutch. 1100x650 Gear. LASERCUT: 16mm bisaloy, feeder floor plate. PRECISION ENGINEERING: Supply shaft for Drum Roller on ID185. Remove & replace shaft in roller 06/02/2018. Repair intake pipe. WULGURU ENGINEERING: 2 x wedges. Weld aluminium housing for ID185. BRITRAC: 1200mm wide superscrew and fit belt Nordev Belt 2nd Hand. Strip & relag head section pulley. PROTEC: Masking tape, 4 litres primer grey, 1 litre T12 diamanta ral 5021. HILLS FABRICATION: Hungry boards on conveyor. Repair 2 x wings, Repair and weld hinge, repair conveyor, fabricate new pins.	08/06/2018
250hr service - 4300	07/31/2018
2000hr service - 4047	07/31/2018
LINCOM: Swing Jaw Liner	07/23/2018
ALECT: E Stop lanyards repaired on conveyor, battery isolator replaced	07/16/2018
BRITRAC: Supply & install 27 metre x 1200 wide 4 ply 6/2 covers for Feeder Belt	07/13/2018
STATEWIDE: 4 x ATSNA512A, 2 x SNK512-610, 4 x 22212KW33C3, 4 x H312-055, 2 x TSNG512 Seals, 2 x UC215 & 2 x P215	07/06/2018
LINCOM: 2 x Pan liners, 2 x Grizzly Sections, Jawstock Protector, Rubber Stop, Sliders Pads	07/05/2018
16 x SPC8000 V Belts from CBC	07/04/2018
LINCOM: Cabinet door hinge	07/03/2018

250hr service - 3836	07/03/2018
500 Hour Service - 3625.1	07/01/2018
Fixed Jaw liner from LINCOM	07/01/2018
500hr service	06/20/2018
10 x SPC8000FEN V Belts from CBC	06/13/2018
8 x Gates C315 V Belts from STATEWIDE	06/07/2018
BRITRAC: 11 x impact bars. 55 x 100 x 1500mm \$189 each.	06/06/2018
LINCOM: Fixed wedge bolts, cups, hex nuts, rubber jaw holder washers, Fixed jaw wedges DS & NDS. Centre / return rollers. Wing Rollers	06/06/2018
250hr service 3325	06/04/2018
1000 Hour Service - 31/05/2018 - 3099	05/31/2018
Product belt from BRITRAC	05/18/2018
ALECT AUTO: Locate starting fault - Tested starting on machine - Could not fault at time of test.	05/17/2018
PRESTART - Belt tracking issues, Fuel Filter issues, Truff roller jamed, Conveyor belt damaged. (2558). PRESTART: Belts Keep burning out, Toggle plate adjuster bent, Need light over jaw so you can see - PRESTART 2451	05/07/2018
Backing plates & jaw liners from LINCOM	05/01/2018
Tail drum bearing blocks from STATEWIDE	04/30/2018
250hr service	04/30/2018
PRECISION ENGINEERING & WELDING: 7 x Machine Pins	04/30/2018
8 x C315 GATES V BELTS FROM STATEWIDE	04/30/2018
PRECISION ENGINEERING: Repair shaft in roller	04/20/2018
Chris Moore Boiler makers.	04/18/2018
250hr service	04/18/2018
Fabricate new guards in TSV Workshop	04/13/2018
500hr service - 2493.50	04/10/2018
LINCOM: Swing backing plate, Fixed backing plate, Moving & fixed liner, Fixed wedge bolts, wedge washer cup, Nut hex, Jaw Holder Rubber Washer, Fixed Jaw Wedge NDS & DS.	04/03/2018
JAYSEL: Eletrical repairs at Ravenswood	03/20/2018

New belt from BRITRAC. 1200mm 4ply 6/2 covers - 27 metres + 1200mm superscrew.	03/20/2018
Pre-Start - LH Side Feeder case damaged, oil leaks around machine.	03/19/2018
250hr service - 2268	03/12/2018
2000hr service - 1967	03/12/2018
PRESTART: Hole in fines chute	03/12/2018
Head drum scraper fixed & Turned swing jaw on 16.03.18	03/12/2018
PRESTART: Top isolator screws broken. High engine oil level on dipstick. Oil cooler hose weeps	03/11/2018
Fixed & Swing Jaw liners. LOWER Cheek plates. Moving Wedge bolts. Nuts, washers and bolts to suit	03/09/2018
Return Rollers from LINCOM. Replaced 16.03.18	03/07/2018
End Cover (gear) from LINCOM	03/02/2018
10 x grouser plates from HONEYCOMBES	03/02/2018
Supply & install a 15 metre insert of the product belt. 4 ply 6/2 covers 1200mm superscrew.	02/08/2018
250hr service - 1804	02/08/2018
24v Starter motor from ASHDOWN	02/05/2018
BRITRAC: Supply & fit feeder belt. 27 metres x 1200 x 4 ply 6/2 Covers	02/05/2018
TSV LASER CUTTING: Supply of material & laser cutting for Feeder Bin	02/01/2018
4 x 2 banded SPC8000 Rex V Belts from STATEWIDE - WRONG ONES DO NOT ORDER ORDER AGAIN	01/30/2018
Fixed & Swing Jaw liners. LOWER Cheek plates. Moving Wedge bolts. Nuts, washers and bolts to suit	01/25/2018
500hr service - 1603	01/22/2018
Main Conveyor tracking roller & Return Roller from Lincom.	01/18/2018
1000hr service - 1223	01/12/2018
New ID & Nordev Stickers from GRACIE SIGNS	01/08/2018
New starter motor from ASHDOWN INGRAM	01/02/2018
Fixed jaw plate with wedge bolts (fixed & moving) from LINCOM	12/27/2017
250hr service - 7823	11/29/2017
Parts for L1376 while on Dry hire at Windfarm	08/16/2017