Description	Raised
Preventative Maintenance - Repair Hydraulic Hoses	06/19/2025
OMS - Remove hydraulic pump, fir seals & motor, replaced damaged bolts, Remove pump, fit seals and end plates, fit pump back on machine	06/05/2025
Lincom - Seal Kit	05/30/2025
Scotts Seals - Seals	05/07/2025
Ausdraulics - Dust Seals	05/07/2025
OMS - Reseal Cylinder	05/05/2025
Lincom - Remote control kit	04/28/2025
Britrac-10mm skirt. 1050 x 10M roll	04/28/2025
DGU Ditted & wired up start isolator sircuit and jump start receptacle	04/23/2025
OMS - Walking fault - remote not walking	04/14/2025
Lincom - Tail conveyor Cylinder Ram	04/01/2025
OMS - Repairs to final drive, dirt belt cylinder, Overside cylinder	04/01/2025
OMS- Remove and make hoses from screenbox motor to screen box valve	03/17/2025
Motion - Gaskets, Orings	03/12/2025
Boltmasters - Socket Head Capscrew	03/11/2025
Conveyore Maintenance - Install new feed belt, LH & RH Fines wing belts	03/10/2025
CRD- Fabricate & Install new Guards	03/09/2025
Motion Australia - Hi Temp Silicon seal	03/05/2025
Statewide Bearings - Dual Seals & Ball Bearings	03/05/2025
Lincom - Spiral Roller, Disc Returnh Roller	03/05/2025
Lincom - RH & LH Wing Roller	03/03/2025
Preventative maintenance - Replace Hydraulic Hoses	03/02/2025
CRD- Welding of weat plates, install track rollers, fabricate new guides, fabricate new guards	03/02/2025
Conveyor Maintenance - Impact bars, T Bolts	02/28/2025
Lincom - Walkway Hinge	02/28/2025
Conveyor maintenance - Sandblast and rubber lag conveyor drive pulleys	02/27/2025
Crusher Spares - Clamping bars, Half moon washers	02/27/2025
Boltmasters - U bolts, Nuts, Washers	02/26/2025
Crusher Spares - Rollers	02/26/2025

CRD - Straighten and fabricate new guards			02/24/2025
Preventative Maintenance - Remove & replace hydraulic hoses			02/23/2025
Boltmasters - Washers, Socket Screw, Tensile hex bolts & Nuts, Nylocnuts, flat washers, threaded rod, black sampson washers			02/19/2025
Preventative Maintenance- Hydraulic Hose Replacement			02/08/2025
OMS- Fit throttle switch to control panel, replace engine filter and oil,			29.10.2024
Lincom - POS Stiches			09/24/2024
OMS- unfold Machine diagnose faulty idle switch , unload screen deck and straighten RHS Walkway			09/18/2024
Bob Parks-Tailpipe with rain cap			09/11/2024
OMS - Fit New Engineto Machine, fit engine guards to machine			09/10/2024
Hastings - New Engine			08/13/2024
OMS-Disconnect and remove engine			08/11/2024
3 x UK211-FYH Bearings, Housings & Sleeves - PO 24435 Applied Ind.			11/15/2023
500hr Service at 2502hrs			10/05/2023
3 x Oil Filters - PO 24109 Hastings Deering			10/04/2023
1 x Starter Motor 3218965 Stg Mot-Elec - PO 24061 Hastings Deering			09/25/2023
2 x P607254 Filters; 1 x FX15-JAP WIR & 1 X UCX15-48-JAP Bearing - PO 23619 Applied Ind Tech			07/21/2023
Replace Side Conveyor Tail Drum & Bearing/Housing Assy - PO 23261 Lincom Pacific			06/14/2023
1 x Seal Kit - PO 23355 Applied Ind Tech			06/02/2023
2 x P780522 Air Filters - PO 23225 Applied Ind Tech		05/11/2023	
Hydraulic hose and fittings for screen box - PO 23189 Hosepower			05/10/2023
Conveyor Belt 1500/3 5:1.5M Grade. Prepped to 13 380mm IC Inc Superscrew 65 on 10dg bias - PO 23145 Britrac Aust			04/27/2023
Service Filters - PO 23121 Applied Ind Tech			04/19/2023
Service Filters - PO 23119 Hastings Deering			04/18/2023
4 x Hydraulic Hoses & Fittings - PO 22989 Hosepower			03/20/2023
1 x Fire Extinguisher - PO 22883 Blackwoods			02/23/2023
V belts for screen box Drive			02/23/2023
2 x Fuel Filters _ PO 22890 Hastings Deering			02/24/2023
2000hr Service Kit 1 each Element Radialseal Primary; Air Filter; Oil Filter; Fuel Filter Water Seperator Spin-on - PO 22882 UKW Spares			02/23/2023
Welded Mesh and RHS	22873	Tonkin Steel	02/20/2023
2 lengths 50 x 50 x 3 Steel Angle	22874	Tonkin Steel	02/20/2023
15nb Med Gal Pipe	22875	Tonkin Steel	02/22/2023
Pins, Screws washers	22848	Boltmasters	02/20/2023
Zinc Guard, Washers, Hex Bolts, Hex Nuts	22878	Boltmasters	02/22/2023

3 x V belts, 1 x Micro V Belt, Cable Ties, 22886 Statewide B	02/23/2023
50 x 50 x 4 Glavanised Weldmesh 22879 Tonkin Steel	02/23/2023
Tools 22876 United Tools	02/22/2023
220,0 0	
900 3 Ply 5+1.5 covers 18344 IC Fittered with superscrew 10 diag. bias Repairs to motors, valves, pumps, Parts & Labour; fuel primer - need to prime before starting - 1 x spare wing conv (to go to Darwin) - check out leaks around valve control banks orings speed valves - replace screen control	02/15/2023
valve - hoses fines conv (bulkhead to motor) - hoses x 4 rear track motors (2 drives, 2 returns) - 2 x seal kits wing conv drive motors (main conv motor ok) - rubber guard - rear chassis - pilot pump off rear engine needs gasket (Brendan to fix) - guarding issues / repairs Gudgy- fines conveyor small - clean down dirt, oil & rocks to access leaking components - numerous hoses were replaced due to being hard & cracking - a lot of hoses were cut to be able to be removed due to the stiffness - reseal 4 x flow controls - reseal 2 x side conveyor motors - remove auxiliary pump, cut new mounting gasket & refit - replace control valve supplied - replace engine fuel line & fittings refit guards - clean down machine. – PO 22922 Ausdraulics Holdings	
5 x Screens. W/Wire mesh screens 40.0mm Apt x 10.1mm. Wire 1220m long x 1890 O/H, 45 deg hooks - PO 022852 Crusher Spares	02/21/2023
Order 3 x Seal Kits for the 3 conveyor drive motors, Ordered through Pirtek. TVS pick up	01/25/2023
Fit new seal kits to Hyd Conveyor Motors x 3 order kits ready for shut down work be sending plant to Bradshaw; Kits have been ordered through Pirtek Townsville 25/01/23 PO 22692, Received 01/02/23, Doug Picked up.	01/25/2023
Replace Control Valve received from Lincom Pacific PO 22641	
Supply 3 hoses and fittings - PO 22608 Ausdraulics Holdings	
1 x 3671817 Connection A - PO 22531 Hastings Deering	
$2 \times r^2$ at 12k hose assembly; $1 \times r^2$ at 16k hose assembly; $2 \times b^2$ bf1-1212f 3/4 bspp fem str 3/4 hose; $2 \times r^2$ reusable ferrule non-skive; $1 \times d^2$ nipple 3/4 bspt male - PO 22466 Pirtek TSV.	12/12/2022
Strip cylinder rod bent at 90 deg. Manufacture new Rod and Reseal - PO 22398 CDM Hydraulics	
1 each Repair Kit 40 Series; Coupling Grp2 1:8 Taper; Spider 65 Series - PO 22354 Alloway Hydraulics	
2 x body 3/4 suits 100r1; 2 x hose 3/4 bsp f ¾; 1 x nipple 3/4 x 1/2 bspt - PO 22353 Ausspray	11/22/2022
4 x UCX10R3 Triple Seal WIR Bearings - PO 22343 Statewide Bearings	11/21/2022
Fit new diesel Starter Switch, Control Valve Bracket & 45Deg Short handle (valve) received from Lincom - Brendan Birt	11/18/2022
1 x Fuel Seperator Filter - PO 22318 UKW Spares	
2 x xn70zzlmf - 12volt 810cca 80ah Exide extreme battery heavy duty - PO 22314 A1 Battery Pro	
Strip and Fit New Starter Motor, Clean up mega fuse, fit 2 new batteries, Wash and flush radiator, Treat fuel tank with additive, Cleaned engine bay - Brendan Birt	11/15/2022
1 x Starter Motor - PO 22309 Hastings Deering	11/15/2022
Air & Oil Filters - PO 22285 UKW Spares	11/14/2022
Hydraulic Hoses & Fittings - PO 22183 CDM Hydraulics	10/28/2022
1 each UC211-32-FYH FYN Bearings, Housings, Sleeves; UC211-FYH FYBN Bearings, Housings, Sleeves - PO 22472 Applied Ind Tech	10/07/2022
2 x Hydraulic Hoses & Fittings - PO 22015 CDM Hydraulics	09/29/2022
Hydraulic Hoses & Fittings - PO 21889 CDM Hydraulics	09/15/2022
1 x 1600mm PN630/4 6x2 Belt. Prepped with a 65 Superscrew to a IC of 14110mm - PO 21809 Britrac	09/06/2022
2 each pillow block housing; ball bearing - wide in; Triple Seal; Dual Seal - PO 21710 Statewide Bearings	08/24/2022
1 Starter Motor - PO 21658 Belcher Diesel Services	08/12/2022
Hydraulic Hoses and Fittings - PO 21624 CDM Hydraulics	08/08/2022

2 x Oil Filters - PO 21616 Hastings Deering	08/08/2022
3 x P780522 Air Filters; 3 x P780523 Air Filters - PO 216153 Applied Ind Tech	08/08/2022
3 x SPB2360 Belts - PO 21613 Applied Ind Tech	08/05/2022
5 x W/Wire Mesh Screens: 45.0mm apt x 8.0mm. Wire: 1220mm long x 1880 O/H, 45 degree hooks; 2 x BIS450 Grade Punch Plates. 80mm Hexagon Holes. 16.0mm thick size - 1890 O/H X 1215mm long, 45 degree hooks -	06/20/2022
1 x 5" Top spin pre cleaner - PO 21358 UKW Spares	06/16/2022
Air Filter AF25618 - PO 21281 UKW Spares	06/01/2022
1 x Air Filter Outer; 3 x Air Filter Inner - PO 21279 Applied Ind Tech	06/01/2022
P606210 Filter - PO 21246 Applied Ind Tech	05/26/2022
Oil Filter - PO 21178 Hastings Deering	05/17/2022
Umbilical Control Kit (6050101) - PO 021135 Lincom Pacific	05/09/2022
Air Filters Outer - PO 21119 UKW Spares	05/06/2022
50 x M20 x 190 Gal 8.8 Cup Head bolts & nuts - PO 21096 Boltmasters	05/04/2022
40 x HALF MOOON WASHERS M20 Zinc Plates Spherical Washer - PO 21093 Crusher Spares	05/04/2022
Service Filters x 4 - PO 20927 Applied Industrial Tech	04/05/2022
2 each P211-FYH FYH Bearings, Housings, Sleeves; UK211-FYH FYH Bearings, Housings, Sleeves; H311 Sleeves; 1 x Grey Maxx Silicone 95G Loctite - PO 20838 Applied Industrial Tech	03/21/2022
Bearing failure on fines discharge belt-final drive leaking	03/14/2022
250hr Service @ 1231hrs	02/28/2022
Air Filters, Inner & Outer - PO 20708 Applied Industrial Tech	02/24/2022
250hr Service kit - PO 20702 Hastings Deering	02/24/2022
2 x 150mm Hex P/Plate W2400 12mm W/String Prot PO 20638 Lincom Pacific	02/14/2022
LINCOM: Fines conveyor rollers	09/24/2021
BRITRAC: Fines Belt. 18100 ic. 900 wide. 3 ply. 5 /1.5 covers. Prepped for cold splice - supply only.	09/09/2021
Both Fines and Midsize conveyors need a number of troff rollers replaced. especially in impact bed zone. fines belt coming apart at cold splice.	09/01/2021
Left hand side wing on feeder bin needs work (bent)	09/01/2021
1000hr service: 954	08/05/2021
Clean out radiator. Air filters. Hydraulic oil coolers.	06/28/2021
LOCKER GROUP: 5 x 16mm apt bottom deck screens. \$223 each. Size 1880 O/H x 1220 mm long, 45 degree hooks	06/25/2021
5 x bottom deck screens are 20.0mm square aperture, 6.3mm wire, 1880 O/H x 1220mm long, 45 degree hooks. 10 x Tensioning bars are 6.0mm thick mild steel 1215mm long blanks.	04/30/2021
STATEWIDE BEARINGS: 2 x UK15R3 bearings + collars, 2 x FX15 housings, sleeves	04/28/2021
ALLSORTS FABRICATION: Supply material & fabricate screen hold down plates. Repair / replace conveyor locating pins & straighten guards and mounting brackets on screen plant	04/28/2021

250hr service - 745	11/27/2020
500hr service - 469	09/17/2020
BRITRAC: Feeder Belt - 10765 ic. 1200 width. 4 ply. 10/3 Cover.	07/17/2020
UKW: Top spin pre cleaner H002433	07/15/2020
STATEWIDE: Bearings & housings for feeder belt. 2 x P215 & 2 x UC215 Dual Sea.	07/03/2020
250hr service - 203	06/22/2020
Repairs before Hervey's Range: 20 x M20 moon washers, service, Bill duct, capping rubber, e stop & wiring repairs, fuel / water separator bowl, Skirting rubber, Mid-fines side conveyor belt. AUSDRAULICS: Replace O Ring on shaft on fine feed valve for conveyor. Remove hydraulic hose on conveyor motor. Remove hydraulic suction hose off hydraulic pump - found hose was clamped on thread of fitting not on hose tail as it should be. Remove leaking discharge. CBC: V Belt for shaker box.	05/22/2020
LOCKER GROUP: 5 x 35mm aperture with a 10.0mm wire diameter in high tensile steel to suit a Warrior 2400 - \$345 each for the bottom deck.	05/19/2020
BRITRAC: Feeder Belt - 10765 ic. 1300 width. 4 ply. 10/3 Cover.	01/21/2020
100hr service - 110	01/07/2020
LINCOM: Screen Drive V Belts (Set of 3)	01/06/2020
V- Belts	01/06/2020
HASTINGS DEERING: New Engine, new e stop. AUSDRAULICS: Make Hoses & supply power hydraulic pack to recover screening plant to transport back to workshop for repairs. LINCOM: New display screen. Coolant,	10/10/2019
1000hr service - 944	08/20/2019
500hr service - 577 (hour meter - reset itself)	05/27/2019
LINCOM - 6 X 4 X 100p/plate half inpact plate. 6 x 4 x 100 P/Plate x 4. Warrior 2400 punch plate hald impact plate. Warrior 2400 Punch plate lead x 4. 12mm Long leg capping Rubber x 20mtrs	05/10/2019
PRE-START - Hydraulic leak, badly damaged feeder belt, transfer belt badly worn	08/20/2018
1000hr service - 3015	08/12/2018
PRE-START - Damage handrail, weeping at oil cooler, Not holding fuel, have tp prime everytime to start - PRESTART NO# 2514	07/30/2018
250hr service - 2723	07/21/2018
PRECISION ENGINEERING & WELDING - Drill Screen Clamp	07/18/2018
ALECT: E Stop wiring that runs below the under carriage damaged and requires a section replaced	07/16/2018
BIRTRAC: Supply belt & Hot Splice belt. 1200 WIDE 10765 IC PN800/4 M+ Grade, 10/3 Covers. THIS MACHINE WOULD NORMALLY TAKE A 1300 WIDE BELT. NONE IN STOCK.	07/13/2018
Fuel Releif for Warrior ordered through Hastings	07/06/2018
BRITRAC: 50 x 130mm x 16mm cup head screen bolts, 2 x poly skirts & 40 metres capping rubber	07/06/2018
HASTINGS DEERING: Supply and replace fuel pump	07/03/2018
LINCOM: Engine Dip stick	07/03/2018
AEG: 4 x punch plates 80.0mm apt x 16mm thick - 4 @ 1215mm long x 1895mm O/H 45 deg hooks. Punch plate 80.0mm apt x 16mm thick - 1 @ 1215mm long x 1895mm O/H 45 deg hooks - Half Blank	07/03/2018

250hr service	07/03/2018
500hr service - 2645	07/02/2018
Fuel / water separator housing & 5 x spare filters from HASTINGS DEERING	06/11/2018
Wing conveyor rollers & wear plates from LINCOM. LH & RH Wera Plates from TSV LASER CUTTING	06/05/2018
250hr service 2332	06/04/2018
2000 Hour Service - 31/05/2018 - 2104	05/31/2018
250hr service	04/30/2018
PRESTART - Injectors need replacing, Fines belt need to be tracked over a bit, Rubber curtains leaking on both sides of screen.	04/30/2018
PRESTART - Needs skirting Rubbers	04/30/2018
500hr service - 1490	04/16/2018
5 x New punch plates from LINCOM	04/03/2018
Pre-Start - Duck Bill wear plates need replacing, Curtain at the end of screen torn(Repaired)	03/26/2018
250hr service - 1261	03/12/2018
1000hr service - 957	03/12/2018
PRESTART: Worn wear plates on chute after POS 5 T/D	03/12/2018
Supply & install feeder belt (10765mm inc x 1200mm 4 ply 10/3 covers BRITRAC	02/08/2018
250hr service - 781	02/08/2018
KG ENGINEERING: SUPPLY AND FABRICATE 2 SKIRT PLATES	02/05/2018
New punch plates from LINCOM	02/02/2018
16 & 20mm moon washers from AEG	01/25/2018
500hr service - 579	01/22/2018
250hr service - 349	01/17/2018
4 x SPB2410 Carlisle Blue Label Power Wedged V Belts from CBC BEARINGS	01/08/2018
ID Stickers, 250hr service kit	01/08/2018
New punch plates from LINCOM	12/15/2017