



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to: IN STORE PICKUP

Invoice to: INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		*REPRINT*
Date	Time	Page
04/01/25	23:06:41 (B)	01
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00814
Ship Via		Purchase Order
		Salesperson
		KK

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
036462AB	JOHN DEERE S690	3621	1H0S690SVB0745512	08/02/13	
	S690	2659	RG6135R000482		1500

Have you heard about MyDealer yet? We have a great new way to help you stay connected to your equipment. Either mobile or laptop - look up parts, order them online, view past purchases, or book a service appointment, you are in control. Ask a parts or service member about MyDealer today!

SEGMENT# 1 C 9662 FIELDREADY 12/12/24 02/10/25
SALES CERTIFIED USED PROGRAM - FIELD READY INSPECTION 22.00 HRS

CHECKLIST NOTING REPAIRS AND WEAR ITEMS AS FOUND.
PLEASE NOTE PRESSURES TAKEN. CONSULT WITH OWNER OF MACHINE
TO WHICH REPAIRS WE RECOMMEND AND WHICH THEY WISH US TO DO.
HAVE SEGMENTED WORKORDER CREATED, FOR WORK TO BE DONE.
THIS DOES NOT INCLUDE ANY MAJOR CLEANING OR BLOWING OF THE
DUST CHAFF OFF.

-ADD ARROWS TO FEEDERHOUSE AND PLATFORM FOR EASE OF
ALIGNMENT AND HOOKING UP

(See Horizon Ag & Turf Combine Certification document for
full details on coverage that comes with this certification)

***** TECHNICIANS COMMENTS *****

*
*Brought unit into the shop and inspected. Composed an
*estimate and forwarded it to the service office. Installed
*all belts, sieve and chaffer. Calibrated. Performed final
checks and adjustments. Popped out dent in the unload auger.
*

10400001	16001001	LABOR	2599.00
SEGMENT TOTAL==>			2599.00

SEGMENT# 2 C 9662 10-000-003 12/12/24

CONTINUED ON PAGE 02

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to:

IN STORE PICKUP

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
04/01/25	23:06:41 (B)	02
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00814
Ship Via	Purchase Order	
	Salesperson	
	KK	

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS
036462AB JOHN DEERE S690 3621 1H0S690SVB0745512 08/02/13
S690 2659 RG6135R000482 1500

TRADE COMBINE- CLEAN AND WASH EXTERIOR TIN WORK ONLY 5.00 HRS
TOUCH UP PAINT ON COMBINE
LUBE ALL CHAINS
GREASE MACHINE ENTIRELY AFTER WASH
PARK IN LINE UP
DETAIL AS NEEDED

***** TECHNICIANS COMMENTS *****
*
*Cleaned unit as per instructions.
*

SEGMENT# 3 C 9662 NA 02/21/25 03/04/25
LHS SEPARATOR RAIL SNAPPED OFF OF BULKHEAD 1.00 HRS

-REPAIR OR REPLACE
-WELD AS REQUIRED
***** TECHNICIANS COMMENTS *****
*
*Disconnected batteries. Set up welder and repaired.
*

LABOR 180.00
10400001 16001001 SEGMENT TOTAL==> 180.00

SEGMENT# 4 C 9627 NA 02/21/25 02/21/25
REPLACE MISSING FRONT BULKHEAD HARDWARE TO FEED RAMP 1.00 HRS

***** TECHNICIANS COMMENTS *****
*
*Replaced missing hardware and torqued to spec.
*

CONTINUED ON PAGE 03

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to: IN STORE PICKUP

Invoice to: INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
04/01/25	23:06:41 (B)	03
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00814
Ship Via	Purchase Order	
	Salesperson	
	KK	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
036462AB	JOHN DEERE S690	3621	1H0S690SVB0745512	08/02/13	
	S690	2659	RG6135R000482		1500

A58549	WASHER	1	5.38	5.38	
03M7192	BOLT-M10 X 30MM	4	1.58	6.32	
14M7296	NUT-10MM FLG HD	4	2.08	8.32	
	PARTS		20.02		
	LABOR		477.00		
10400001	16001001		SEGMENT TOTAL==>	497.02	

SEGMENT# 5 C 9667 NA 02/21/25 03/04/25

RHS HOPPER SUPPORT CRACKED RIGHT THROUGH 3.00 HRS

FISHPLATE SUPPORT AND WELD

***** TECHNICIANS COMMENTS *****

* * *

*Welded combine as required. Prepped unit and repainted. *

* * *

LABOR 540.00

10400001 16001001 SEGMENT TOTAL==> 540.00

SEGMENT# 6 C 9627 NA 02/21/25 02/21/25

DIAGNOSE LEAK ON SPREADER VALVE AND REPAIR AS REQUIRED 2.00 HRS

***** TECHNICIANS COMMENTS *****

* * *

*Cleaned oil from valve block. Operated and could see no *

*leak. Will recheck with combine engaged. Removed the inside *

*rear coil, valve and damaged o ring. Installed new seal and *

*reassembled. *

* * *

51M7047 O-RING 1 7.88 7.88

CONTINUED ON PAGE 04

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO

Ship to:	IN STORE PICKUP
	INTERNAL CUSTOMER Horizon Ag & Turf Lloydminster AB T9V 3A2

Branch ST. PAUL		
Date 04/01/25	Time 23:06:41 (B)	Page 04
Account No. INTER01A	Phone No. 7808754471	Invoice No. W00814
Ship Via		Purchase Order
		Salesperson KK

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
036462AB	JOHN DEERE S690	3621	1H0S690SVB0745512	08/02/13	
	S690	2659	RG6135R000482		1500
				PARTS	7.88
				LABOR	392.40
	16001001		SEGMENT TOTAL==>		400.28

SEGMENT# 7 C 9627 NA	02/21/25 02/21/25	
ROTOR BEARING NOISY AND HAS PLAY		3.00 HRS
-REPLACE BEARING		
***** TECHNICIANS COMMENTS *****		
*Removed shields. Front bearing was seized. Removed and		
*replaced front bearing. Reinstalled shields.		

AXE42868	Bearing With Ho	1 568.69 568.69
	Bearing With Housing	
		PARTS 568.69
		LABOR 585.00
	16001001	SEGMENT TOTAL==> 1153.69

SEGMENT# 8 C 9627 NA	02/21/25 02/21/25	
CLEANING FAN BEARINGS HAVE PLAY		3.00 HRS
-REPLACE FAN BEARINGS		
***** TECHNICIANS COMMENTS *****		
*Removed RHS drive pulleys from shaft and both bearings.		
*Cleaned shaft and installed two new bearings. Reinstalled		
*drive pulley.		

AH139297	BALL BEARING	1 80.93 80.93
CONTINUED ON PAGE 05		

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH (24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,

SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to:

IN STORE PICKUP

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
04/01/25	23:06:41 (B)	05
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00814
Ship Via	Purchase Order	
	Salesperson	
	KK	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
036462AB	JOHN DEERE S690	3621	1H0S690SVB0745512	08/02/13	
	S690	2659	RG6135R000482		1500
AH225510	BEARING	1	50.63	50.63	
AL14674	LOCKING COLLAR	1	29.57	29.57	
	Eccentric Locking Collar				
			PARTS	161.13	
			LABOR	585.00	
10400001	16001001		SEGMENT TOTAL==>	746.13	

SEGMENT# 9 C 9662 NA	02/21/25 02/21/25			
LOW FAN SPEED AND CLEANING FAN BELT STRETCHED	1.00 HRS			
-REPLACE BELT				
***** TECHNICIANS COMMENTS *****				
*Removed cleaning fan belt and replaced with new.				

HXE15594	CLN FAN BELT	1	149.14	149.14
			PARTS	149.14
			LABOR	180.00
16001001			SEGMENT TOTAL==>	329.14

SEGMENT#10 C 9627 NA	02/21/25 02/21/25			
TAILINGS DRIVE CHAIN STRETCHED AND SPROCKETS WORN	1.50 HRS			
-REPLACE CHAIN AND SPROCKETS				
***** TECHNICIANS COMMENTS *****				
*Installed new drive chain, two tensioner sprockets and hub.				

AH89428	Idler Sprocket	2	128.09	256.18
AXE17053	#50 ENDLESS	1	124.56	124.56
CONTINUED ON PAGE 06				

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to: IN STORE PICKUP

Invoice to: INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
04/01/25	23:06:41 (B)	06
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00814
Ship Via		Purchase Order
		Salesperson
		KK

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
036462AB	JOHN DEERE S690	3621	1H0S690SVB0745512	08/02/13	
	S690	2659	RG6135R000482		1500
H114395	SPACER	1	8.08		8.08
H216427	SPACER	1	18.69		18.69
			PARTS		407.51
			LABOR		270.00
	16001001		SEGMENT TOTAL==>		677.51

SEGMENT#11 C 9627 NA 02/21/25 02/21/25

REAR SIEVE HANGERS POUNED OUT 2.00 HRS

-REPLACE BOTH REAR SIEVE ARMS

***** TECHNICIANS COMMENTS *****

* * *

*Removed rear sieve arms and replaced with new. * *

* * *

AH220398	SHAKER ARM	2	196.77	393.54
			PARTS	393.54
			LABOR	360.00
	16001001		SEGMENT TOTAL==>	753.54

SEGMENT#12 C 9627 NA 02/21/25 02/21/25

TAILINGS ELEVATOR AT END OF ADJUSTMENT 4.00 HRS

SPROCKETS LOOSE ON SHAFTS

-REPLACE TAILINGS ELEVATOR CHAIN

-REPLACE SPROCKETS AND KEYS

-REPLACE TOP SHAFT OUTER BEARING

***** TECHNICIANS COMMENTS *****

* * *

*Removed chain connect from link. Found it was in good * *

*shape with the offset link and just at mid adjustment. * *

*Inspected sprockets and they were like new. Reinstalled * *

CONTINUED ON PAGE 07

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to:

IN STORE PICKUP

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
04/01/25	23:06:41 (B)	07
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00814
Ship Via	Purchase Order	
		Salesperson
		KK

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
036462AB	JOHN DEERE S690	3621	1H0S690SVB0745512	08/02/13	
	S690	2659	RG6135R000482		1500
*connect link and set tension.				*	
*				*	

			LABOR		540.00
16001001			SEGMENT TOTAL==>		540.00

SEGMENT#	C	9627	NA	02/21/25	02/21/25	
REPLACE POUNDED OUT PRIMARY GEARCASE MOUNTS						2.00 HRS
***** TECHNICIANS COMMENTS *****						
*Removed header belt tension. Loosened gear box mounting						
bolts and replaced all four rubber washers. Torqued to spec.						

H148132			BUSHING	4 S	28.50	114.00
					PARTS	114.00
					LABOR	360.00
16001001					SEGMENT TOTAL==>	474.00

SEGMENT#	C	9627	NA	02/21/25	02/21/25	
REPLACE LOOSE BACKSHAFT BEARING ON FEEDER DRIVE SHAFT						2.00 HRS
***** TECHNICIANS COMMENTS *****						
*Removed shaft speed wheel and bearing. Installed a new						
*bearing. Reinstalled tone wheel.						

AH231479			Bearing With Ho	1	329.16	329.16
			Bearing With Housing			
					PARTS	329.16
CONTINUED ON PAGE 08						

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to:

IN STORE PICKUP

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
04/01/25	23:06:41 (B)	08
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00814
Ship Via	Purchase Order	
		Salesperson
		KK

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
036462AB	JOHN DEERE S690	3621	1H0S690SVB0745512	08/02/13	
	S690	2659	RG6135R000482		1500
				LABOR	360.00
10400001	16001001			SEGMENT TOTAL==>	689.16

SEGMENT#15 C 9627 NA 02/21/25 02/21/25
AIRSCREEN JACKSHAFT BEARINGS DRY 2.00 HRS
-REPLACE BEARINGS AND BELT
ENGINE SIDE BELT PEELING
-REPLACE

***** TECHNICIANS COMMENTS *****

*
*Removed the drive belt and driven. Removed the shaft and
*pulley assembly from the combine and disassembled. Cleaned
*shaft and reassembled with new bearings and a drive belt.
*

AZ10044	LOCK COLLAR-25M	2	14.93	29.86
	Eccentric Locking Collar			
HXE93567	Ball Bearing	2	71.74	143.48
H238867	BELT R.SCRN.DRV	1	42.39	42.39
	PARTS			215.73
	LABOR			754.20
10400001	16001001			SEGMENT TOTAL==> 969.93

SEGMENT#16 C 9627 NA 02/21/25 02/21/25
RAD SWEEPER BEARING HAS PLAY 1.00 HRS
-REPLACE BEARING AND HUB
***** TECHNICIANS COMMENTS *****
*
*Removed sweeper arm. Removed and replaced bearings and
*hub. Reinstalled arm.

CONTINUED ON PAGE 09

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to: IN STORE PICKUP

Invoice to: INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
04/01/25	23:06:41 (B)	09
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00814
Ship Via	Purchase Order	
	Salesperson	
	KK	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
036462AB	JOHN DEERE S690	3621	1H0S690SVB0745512	08/02/13	
	S690	2659	RG6135R000482		1500

HXE66282	Hub	1	111.67	111.67	
JD29980	Ball Bearing	2	8.79	17.58	
			PARTS	129.25	
			LABOR	279.00	
16001001			SEGMENT TOTAL==>	408.25	

SEGMENT#	DESCRIPTION	DATE	HRS
17	C 9627 NA	02/21/25 02/21/25	
	REPLACE BEARING AND CHANNEL		1.00 HRS
	-UNLOADER TENSION PULLEY BEARINGS SHOT		
	-BELT CHANNEL BENT		
***** TECHNICIANS COMMENTS *****			
	*Removed belt tension pulley and replaced. Straightened the		
	*damaged belt channel.		

AH204389	IDLER 8.5"	1	150.10
			PARTS 150.10
			LABOR 248.40
16001001			SEGMENT TOTAL==> 398.50

SEGMENT#	DESCRIPTION	DATE	HRS
19	C 9627 NA	02/21/25 02/21/25	
	REPLACE BEARING AND BELT		1.00 HRS
	-VACUUM IDLER DRY		
	-BELT CRACKED		
***** TECHNICIANS COMMENTS *****			
	*Removed blower belt idler. Pressed bearing out of the		

CONTINUED ON PAGE 10

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to:

IN STORE PICKUP

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
04/01/25	23:06:41 (B)	10
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00814
Ship Via	Purchase Order	
	Salesperson	
	KK	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
036462AB	JOHN DEERE S690	3621	1H0S690SVB0745512	08/02/13	
	S690	2659	RG6135R000482		1500
*pulley and installed a new one. Reinstalled on combine and *					
*installed a new drive belt. *					
* *					

HXE38073	VACUUM FAN BELT	1	29.82	29.82	
JD8535	BEARING	1	10.02	10.02	
			PARTS	39.84	
			LABOR	451.80	
10400001	16001001		SEGMENT TOTAL==>	491.64	

SEGMENT#20 C 9627 NA 02/21/25 02/21/25
SERVICE: 10.00 HRS

- ENGINE OIL/FILTER
- FUEL FILTERS
- MEG OIL
- HYD OIL
- ALL HYD FILTERS
- ALL AIR FILTERS
- FINAL DRIVES
- PRIMARY
- ROTOR
- REVERSER

***** TECHNICIANS COMMENTS *****

- * *
- *Drained all oils. Changed all air, oil and fuel filters. *
- *Filled with new oil. *
- * *

AH128449	HYDRAULIC FILT	1	134.54	134.54
	Hydraulic Filter			

CONTINUED ON PAGE 11

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO

Ship to:

IN STORE PICKUP

Invoice to:

 INTERNAL CUSTOMER
 Horizon Ag & Turf
 Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
04/01/25	23:06:41 (B)	11
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00814
Ship Via		Purchase Order
		Salesperson
		KK

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
036462AB	JOHN DEERE S690	3621	1H0S690SVB0745512	08/02/13	
	S690	2659	RG6135R000482		1500
AN207368	PRODR. FILTER	1	178.03	178.03	
	Hydraulic Filter				
AR69444	HYGARD 18.9L	6	143.24	859.44	
AXE12964	HYD.RESV.FIL.	1	162.19	162.19	
	Hydraulic Filter				
DZ112918	SEC.FUEL FIL.	1	215.56	215.56	
DZ130550	PRIM FUEL FILT	RETAIL	218.91		
		2	215.54	431.08	
ENVO114	OIL ENVIRO FEE	8	1.14	9.12	
ENV06	OIL ENVIRO FEE	12	.06	.72	
ENV10	ENVIRO CHARGE	17	.10	1.70	
ENV100	ENVIRO CHARGE	7	1.25	8.75	
ENV12	CONTAIN ENV FEE	12	.12	1.44	
ENV227	CONTAIN ENV FEE	8	2.27	18.16	
ENV23	OIL ENVIRO FEE	2	.23	.46	
ENV46	CONTAIN ENV FEE	2	.46	.92	
GL5	GL5 - 85W140	17	11.75	199.75	
HXE11090	AIR FILTER PRM.	1	421.93	421.93	
HXE11091	AIR FILTER SEC.	1	297.72	297.72	
L214634	CAB REC. FILTER	1	45.79	45.79	
RE284091	CAB FILTER	1	111.24	111.24	
RE572785	ENG OIL FILTER	1	138.38	138.38	
TY26408	HD460 SYN.G.OIL	12	44.63	535.56	
TY26673	15W40+50II 3.8L	2	34.15	68.30	
	Plus-50 II Oil 15W40 CK4/SN				
TY26679	15W40+50II 19L	2	154.45	308.90	
	Plus-50 II Oil 15W40 CK4/SN				
			PARTS	4149.68	
			LABOR	1917.00	
10400001	16001001		SEGMENT TOTAL==>	6066.68	

CONTINUED ON PAGE 12

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
 (24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,

SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to:

IN STORE PICKUP

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
04/01/25	23:06:41 (B)	12
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00814
Ship Via		Purchase Order
		Salesperson
		KK

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
036462AB	JOHN DEERE S690	3621	1H0S690SVB0745512	08/02/13	
	S690	2659	RG6135R000482		1500

SEGMENT#21 C 9627 NA 02/21/25 02/21/25

FRONT ROW HAS BROKEN ROTOR ELEMENTS

-REPLACE ROW

***** TECHNICIANS COMMENTS *****

*

*Reinstalled concaves and torqued hardware. Performed

*concave leveling procedure.

*

HXE12610	STRAP	1 M	123.57	123.57
----------	-------	-----	--------	--------

KXE10034	THRES.ELMT.STD	1	757.21	757.21
----------	----------------	---	--------	--------

Threshing Element

PARTS 880.78

LABOR 540.00

10400001	16001001	SEGMENT TOTAL==>	1420.78
----------	----------	------------------	---------

***** WORK ORDER TOTALS *****

	INTERNAL	CUSTOMER
--	----------	----------

PARTS	7716.45	
-------	---------	--

LABOR	11618.80	
-------	----------	--

Shop Supplies	250.00	
---------------	--------	--

INTERNAL TOTAL	19585.25	
----------------	----------	--

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO