



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

S780 JSC TRD(810078)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		*REPRINT*
Date	Time	Page
03/20/25	23:04:19 (B)	01
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W02389
Ship Via	Purchase Order	
	024	
		Salesperson
		KIC

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
152137A	JOHN DEERE S780	1784	1H0S780SCKT810078	08/02/21	
	S780	1394		08/01/25	1250

Have you heard about MyDealer yet? We have a great new way to help you stay connected to your equipment. Either mobile or laptop - look up parts, order them online, view past purchases, or book a service appointment, you are in control. Ask a parts or service member about MyDealer today!

SEGMENT# 1 C 9762 FIELDREADY 11/04/24 01/02/25 03/18/25
SALES CERTIFIED USED PROGRAM - FIELD READY INSPECTION 22.00 HRS
(See Horizon Ag & Turf Combine Certification document for full details on coverage that comes with this certification,
***** TECHNICIANS COMMENTS *****
*
*+Perform Field Ready Inspection
*

LABOR 2599.00
16001001 SEGMENT TOTAL==> 2599.00

SEGMENT# 2 C 9762 NA 11/04/24
WASH AND DETAIL AS NEEDED - WASHBAY TO DO
***** TECHNICIANS COMMENTS *****
*
*+washbay to do
*

SEGMENT# 3 C 9762 10-000-002 11/04/24 01/06/25
CLEAN COMBINE AS NEEDED-BEFORE REPAIR- BLOW OFF WITH 2.50 HRS
YARD COMPRESSOR
***** TECHNICIANS COMMENTS *****

CONTINUED ON PAGE 02

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH (24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

S780 JSC TRD(810078)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
03/20/25	23:04:19 (B)	02
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W02389
Ship Via	Purchase Order	
	024	
		Salesperson
		KIC

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
152137A	JOHN DEERE S780	1784	1H0S780SCKT810078	08/02/21	
	S780	1394		08/01/25	1250
*			*		
*+blow off combine			*		
*			*		

			LABOR		450.00
16001001			SEGMENT TOTAL==>		450.00

SEGMENT# 4 C 9762 NA 11/04/24 02/27/25

COMPLETE SERVICE

CHANGE ENGINE OIL & FILTER

CHANGE FUEL FILTERS

CHANGE ALL AIR FILTERS

CHANGE HYD/TRANS FILTERS

DOUBLE CHECK FLUID LEVELS & GREASE

***** TECHNICIANS COMMENTS *****

*

*+changed engine oil & filter

*+changed fuel filters

*+changed all air filters

*+changed hyd/trans filters

*+double check fluid levels & greased

*

AH128449	HYDRAULIC FILT	1	138.81	138.81
----------	----------------	---	--------	--------

Hydraulic Filter

AN207368	PRODR. FILTER	1	183.69	183.69
----------	---------------	---	--------	--------

Hydraulic Filter

AXE12964	HYD.RESV.FIL.	1	167.34	167.34
----------	---------------	---	--------	--------

Hydraulic Filter

AXE42065	DEBRIS FIL.#2	1	139.41	139.41
----------	---------------	---	--------	--------

CONTINUED ON PAGE 03

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

S780 JSC TRD(810078)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
03/20/25	23:04:19 (B)	03
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W02389
Ship Via	Purchase Order	
	024	
		Salesperson
		KIC

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
152137A	JOHN DEERE S780	1784	1H0S780SCKT810078	08/02/21	
	S780	1394		08/01/25	1250
AXE42066		DEBRIS FIL.#1	1	218.29	218.29
DZ112918		SEC.FUEL FIL.	1	222.42	222.42
DZ130550		PRIM FUEL FILT	1	218.91	218.91
ENVO114		OIL ENVIRO FEE	2	1.14	2.28
ENV100		ENVIRO CHARGE	7	1.25	8.75
ENV114		CONTAIN ENV FEE	2	1.14	2.28
ENV227		CONTAIN ENV FEE	2	2.27	4.54
ENV23		OIL ENVIRO FEE	1	.23	.23
ENV46		CONTAIN ENV FEE	1	.46	.46
ENV57		OIL ENVIRO FEE	2	.57	1.14
HXE11090		AIR FILTER PRM.	1	435.34	435.34
HXE11091		AIR FILTER SEC.	1	307.18	307.18
L214634		CAB FIL.(QTY.2)	1	47.23	47.23
RE572785		ENG OIL FILTER	1	142.78	142.78
TA32591		Air Filter	1	114.77	114.77
TY22062		HYGARD 9.46L	2	77.09	154.18
TY26673		15w40+50II 3.8L	1	34.15	34.15
	Plus-50 II Oil	15W40 CK4/SN			
TY26679		15W40+50II 19L	2	154.45	308.90
	Plus-50 II Oil	15W40 CK4/SN			
			PARTS		2853.08
			LABOR		1080.00
	16001001		SEGMENT TOTAL==>		3933.08

SEGMENT# 5 C 9762 NA 02/28/25 02/28/25
LH REAR DISCHARGE LIGHT DOES NOT WORK - DIAGNOSE & REPAIR

***** TECHNICIANS COMMENTS *****

*
*+Replaced damaged bulb & light works now
*

CONTINUED ON PAGE 04

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

S780 JSC TRD(810078)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
03/20/25	23:04:19 (B)	04
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W02389
Ship Via	Purchase Order	
	024	
		Salesperson
		KIC

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
152137A	JOHN DEERE S780	1784	1H0S780SCKT810078	08/02/21	
	S780	1394		08/01/25	1250

AH208904	BULB 886		RETAIL	37.73	
			1	36.57	36.57
			PARTS		36.57
			LABOR		75.60
	16001001		SEGMENT TOTAL==>		112.17

SEGMENT# 6 C 9762 NA	02/28/25 03/04/25		
UPDATE SOFTWARE			
***** TECHNICIANS COMMENTS *****			
* *			
*+update software *			
* *			

	LABOR	270.00	
16001001	SEGMENT TOTAL==>	270.00	

SEGMENT# 7 C 9764 NA	02/28/25 02/28/25		
FEEDER CHAIN HAS 2 BENT SLATS - REPLACE			
REMOVE 1/2 LINKS FROM FEEDER CHAIN & ADJUST			
***** TECHNICIANS COMMENTS *****			
* *			
*+Replaced slats - removed half links *			
*+Tensioned chains and cleaned up bay *			
*+Corrected bolt on half link direction *			
* *			

HXE42402	SLAT	RETAIL	93.36
		2	90.48
			180.96
14M7517	NUT-10MM NYLOCK	RETAIL	2.13
CONTINUED ON PAGE 05			

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

S780 JSC TRD(810078)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
03/20/25	23:04:19 (B)	05
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W02389
Ship Via	Purchase Order	
	024	
		Salesperson
		KIC

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
152137A	JOHN DEERE S780	1784	1H0S780SCKT810078	08/02/21	
	S780	1394		08/01/25	1250
			8	2.07	16.56
19M7402	#8BOLT-M10X25MM		RETAIL	2.06	
			8	2.00	16.00
			PARTS		213.52
			LABOR		586.80
	16001001		SEGMENT TOTAL==>		800.32

SEGMENT# 8 C 9762 NA 02/28/25 02/28/25
ELEVATOR JACK SHAFT DRIVE BELT IS FAILED - REPLACE
***** TECHNICIANS COMMENTS *****
*
*+Replaced damaged elevator jack shaft drive belt
*

H154723 BELT-C148 RETAIL 137.68
1 133.43 133.43
PARTS 133.43
LABOR 270.00
16001001 SEGMENT TOTAL==> 403.43

SEGMENT# 9 C 9762 NA 02/28/25 02/28/25
CLEAN GRAIN DRIVE BELT IS FAILED - REPLACE
***** TECHNICIANS COMMENTS *****
*
*+Replaced clean grain elevator drive belt
*

H223230 V-BELT DWIDTH RETAIL 393.45
1 381.33 381.33
PARTS 381.33
CONTINUED ON PAGE 06

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

S780 JSC TRD(810078)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
03/20/25	23:04:19 (B)	06
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W02389
Ship Via	Purchase Order	
	024	
		Salesperson
		KIC

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
152137A	JOHN DEERE S780	1784	1H0S780SCKT810078	08/02/21	
	S780	1394		08/01/25	1250
				LABOR	270.00
	16001001		SEGMENT TOTAL==>		651.33

SEGMENT#10 C 9764 NA 02/28/25 02/28/25
FEEDER HOUSE DRIVE CHAIN & SLIP CLUTCH ARE WORN - REPLACE
***** TECHNICIANS COMMENTS *****
*
*+Replaced slip clutch & drive chain - Tensioned chain
*

AXE22402 S.CLUTCH 1300NM RETAIL 1243.23
1 1204.93 1204.93
AXE80366 189 LINKS-#60H RETAIL 266.53
1 258.31 258.31
SW60HOLUS #60H OFFSET LK RETAIL 12.78
2 12.39 24.78
11M7032 COTTER-3/16X2" 1 1.18 1.18
PARTS 1489.20
LABOR 180.00
16001001 SEGMENT TOTAL==> 1669.20

SEGMENT#11 C 9762 NA 02/28/25 03/05/25
ADJUST CLEAN GRAIN & TAILINGS CHAINS
***** TECHNICIANS COMMENTS *****
*
*+Removed a half link on the clean grain chain
*
*+adjusted tension
*
*+Adjusted tailings elevator chain tension as well
*

CONTINUED ON PAGE 07

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

S780 JSC TRD(810078)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
03/20/25	23:04:19 (B)	07
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W02389
Ship Via	Purchase Order	
	024	
		Salesperson
		KIC

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
152137A	JOHN DEERE S780	1784	1H0S780SCKT810078	08/02/21	
	S780	1394		08/01/25	1250
				LABOR	174.60
	16001001		SEGMENT TOTAL==>		174.60

SEGMENT#12 C 9762 NA 02/28/25 02/28/25
ACCELERATOR DRIVE BELT IS FAILED - REPLACE
***** TECHNICIANS COMMENTS *****
*
*+Replaced accelerator drive belt as needed
*

HXE54503 3B/NOTCHED/FEED RETAIL 337.01
1 326.63 326.63
PARTS 326.63
LABOR 147.60
16001001 SEGMENT TOTAL==> 474.23

SEGMENT#13 C 9762 NA 02/28/25 02/28/25
TAILINGS RETURN TROUGH CLEAN OUT DOOR LEAKS - SEAL UP
***** TECHNICIANS COMMENTS *****
*
*+Removed duct tape/glue & old damaged seal on tailings
*
*+cleanout hatch
*
*+Installed new seal
*

L59796 WEATHERSTRIP RETAIL 35.64
1 34.53 34.53
PARTS 34.53
LABOR 347.40
16001001 SEGMENT TOTAL==> 381.93

CONTINUED ON PAGE 08

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

S780 JSC TRD(810078)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
03/20/25	23:04:19 (B)	08
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W02389
Ship Via	Purchase Order	
	024	
		Salesperson
		KIC

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
152137A	JOHN DEERE S780	1784	1H0S780SCKT810078	08/02/21	
	S780	1394		08/01/25	1250

SEGMENT#14 C 9762 NA 02/28/25 02/28/25

SHOE DRIVE BELT FAILED - REPLACE

***** TECHNICIANS COMMENTS *****

* *

*+Replaced shoe drive belt as needed *

* *

HXE102288	V-Belt	RETAIL	858.08	
		1	831.65	831.65
		PARTS		831.65
		LABOR		270.00
16001001		SEGMENT TOTAL==>		1101.65

SEGMENT#15 C 9762 NA 02/28/25 02/28/25

BOTH LOWER CHOPPER BELTS FAILED - REPLACE

***** TECHNICIANS COMMENTS *****

* *

*+Replaced both lower chopper belts *

* *

HXE124869	V-Belt	RETAIL	692.86	
		2	682.20	1364.39
T77858	F/F-ORING #12	1	3.42	3.42
		PARTS		1367.81
		LABOR		424.08
16001001		SEGMENT TOTAL==>		1791.89


SEGMENT#16 C 9762 NA 02/28/25 02/28/25

FRONT ENGINE MOUNT UNDER IS MISSING HARDWARE - REPLACE

CONTINUED ON PAGE 09

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

S780 JSC TRD(810078)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
03/20/25	23:04:19 (B)	09
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W02389
Ship Via	Purchase Order	
	024	
		Salesperson
		KIC

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
152137A	JOHN DEERE S780	1784	1H0S780SCKT810078	08/02/21	
	S780	1394		08/01/25	1250
***** TECHNICIANS COMMENTS *****					
* *					
*+Installed missing hardware from front engine mount *					
* *					

14M7722	M8 FLG PT LNUT	RETAIL	1.58		
		2	1.53		3.06
19M7868	FL/BOLT-M8X30MM	RETAIL	1.76		
		2	1.71		3.42
			PARTS		6.48
			LABOR		149.40
16001001		SEGMENT TOTAL==>			155.88

SEGMENT#17 C 9762 NA		02/28/25 02/28/25			
ROTARY SCREEN DRIVE BELT IS FAILED - REPLACE					
***** TECHNICIANS COMMENTS *****					
* *					
*+replaced rotary screen drive belt *					
* *					

HXE130611	V-Belt	1	83.41		83.41
H221273	BELT RTRYSCRN				2.20-
			PARTS		81.21
			LABOR		225.00
16001001		SEGMENT TOTAL==>			306.21

SEGMENT#18 C 9762 NA		02/28/25 02/28/25			
COOLANT LEAK ON LEFT SIDE OF RADIATOR - DIAGNOSE & REPAIR					
***** TECHNICIANS COMMENTS *****					
* *					

CONTINUED ON PAGE 10

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

S780 JSC TRD(810078)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
03/20/25	23:04:19 (B)	10
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W02389
Ship Via	Purchase Order	
	024	
		Salesperson
		KIC

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
152137A	JOHN DEERE S780	1784	1H0S780SCKT810078	08/02/21	
	S780	1394		08/01/25	1250
*+found coolant leaks				*	
*+washed off residue				*	
*+tightened all hardware				*	
*+tested operation - no more leaks found				*	
*				*	

TY26575	COOLGARDII PMIX	2		24.37	48.74
				PARTS	48.74
				LABOR	450.00
16001001			SEGMENT TOTAL==>		498.74

SEGMENT#19 C 9762 NA 02/28/25 02/28/25

MEG IS COVERED IN OILY CHAFF - DIAGNOSE & REPAIR

***** TECHNICIANS COMMENTS *****

*
*+Washed off residue
*+Found valve body was leaking on top of the MEG
*+Removed all attached lines on MEG valve body
*+Removed valve and cleaned/prepped mounting surface
*+Replaced multiple O-rings on valve fittings
*+Installed valve and all removed components
*+Ran up machine to operating temp to verify repair
*+No more leak present after run up
*

CE30048	Gasket	1 N	78.02	78.02
T77858	F/F-ORING #12	2	3.42	6.84
T77932	F/F-ORING #10	5	3.54	17.70
51M7043	O-RING M18	1	4.07	4.07
51M7045	O-RING M22	1	5.95	5.95

CONTINUED ON PAGE 11

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

S780 JSC TRD(810078)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
03/20/25	23:04:19 (B)	11
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W02389
Ship Via	Purchase Order	
	024	
		Salesperson
		KIC

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
152137A	JOHN DEERE S780	1784	1H0S780SCKT810078	08/02/21	
	S780	1394		08/01/25	1250
51M7047	O-RING M27	2		7.88	15.76
				PARTS	128.34
				LABOR	943.20
	16001001		SEGMENT TOTAL==>		1071.54

SEGMENT#20 C 9762 NA 02/28/25 02/28/25
LOAD AUGER DRIVE HUB WORN OUT - REPLACE
***** TECHNICIANS COMMENTS *****
*
*+Replaced load auger drive as needed
*

HXE84650 Driver RETAIL 174.15
1 168.79 168.79
14M7589 LOCK NUT 16MM RETAIL 5.24
1 5.08 5.08
49M4821 KEY-6X6X32MM RETAIL 4.27
1 4.14 4.14
PARTS 178.01
LABOR 154.08
16001001 SEGMENT TOTAL==> 332.09

SEGMENT#21 C 9762 NA 02/28/25 02/28/25
LOAD AUGER FLIGHTING NEEDS WELDING
UPPER BEARING IS FAILED - REPLACE
***** TECHNICIANS COMMENTS *****
*
*+Pulled lead auger out in hopper & prepper/welded cracked
*
*+flighting
*
*+Replaced top bearing as well
*

CONTINUED ON PAGE 12

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

S780 JSC TRD(810078)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch LLOYDMINSTER		
Date 03/20/25	Time 23:04:19 (B)	Page 12
Account No. INTER01A	Phone No. 7808754471	Invoice No. W02389
Ship Via		Purchase Order 024
		Salesperson KIC

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
152137A	JOHN DEERE S780	1784	1H0S780SCKT810078	08/02/21	
	S780	1394		08/01/25	1250

JD10384	BEARING-30MM		RETAIL	79.97	
			1	77.51	77.51
			PARTS		77.51
			LABOR		768.60
16001001			SEGMENT TOTAL==>		846.11

SEGMENT#22 C 9762 NA	02/28/25 02/28/25
ADJUST PICK -UP AIR BAGS	
***** TECHNICIANS COMMENTS *****	
*+Adjusted air bags as needed	

	LABOR 90.00
16001001	SEGMENT TOTAL==> 90.00

SEGMENT#23 C 9762 NA	02/28/25 02/28/25
ADJUST TABLE AUGER DRIVE CHAIN	
***** TECHNICIANS COMMENTS *****	
*+Adjusted table auger drive chain as needed	

	LABOR 135.00
16001001	SEGMENT TOTAL==> 135.00

SEGMENT#24 C 9762 NA	02/28/25 02/28/25
UPPER CHOPPER BELT IS FAILED - REPLACE	

CONTINUED ON PAGE 13

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

S780 JSC TRD(810078)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
03/20/25	23:04:19 (B)	13
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W02389
Ship Via	Purchase Order	
	024	
		Salesperson
		KIC

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
152137A	JOHN DEERE S780	1784	1H0S780SCKT810078	08/02/21	
	S780	1394		08/01/25	1250
***** TECHNICIANS COMMENTS *****					
* *					
*+Replaced upper chopper belt *					
* *					

HXE124868	BELT 3HC		RETAIL	692.07	
			1	670.75	670.75
			PARTS		670.75
			LABOR		480.60
16001001			SEGMENT TOTAL==>		1151.35

SEGMENT#25 C 9762 NA	02/28/25 02/28/25
DISCHARGE BEATER BELT FAILED - REPLACE	
***** TECHNICIANS COMMENTS *****	
* *	
*+Replaced discharge beater belt *	
* *	

HXE124870	V-Belt
	RETAIL 416.73
	1 403.90 403.90
	PARTS 403.90
	LABOR 158.40
16001001	SEGMENT TOTAL==> 562.30

SEGMENT#26 C 9762 NA	02/28/25 03/03/25
FLIP STATIONARY KNIVES	
***** TECHNICIANS COMMENTS *****	
* *	
*+Flipped knives as needed *	
* *	

CONTINUED ON PAGE 14

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

S780 JSC TRD(810078)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		
Date	Time	Page
03/20/25	23:04:19 (B)	14
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W02389
Ship Via	Purchase Order	
	024	
		Salesperson
		KIC

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
152137A	JOHN DEERE S780	1784	1H0S780SCKT810078	08/02/21	
	S780	1394		08/01/25	1250

			LABOR		270.00
	16001001		SEGMENT TOTAL==>		270.00

SEGMENT#28 C 9762 NA 02/28/25 03/11/25
COOLING PACK NEEDS TO BE WASHED OUT
***** TECHNICIANS COMMENTS *****
* * * * *
*+pressure washed cooling pack * * * * *
* * * * *

LABOR 354.60
16001001 SEGMENT TOTAL==> 354.60

SEGMENT#29 C 9762 NA 02/28/25 02/28/25
CHANGE PRIMARY & REVERSER GEARCASE OILS
***** TECHNICIANS COMMENTS *****
* * * * *
*+Replaced oil in reverser & main gear cases * * * * *
* * * * *

ENV06 OIL ENVIRO FEE 9 .06 .54
ENV12 CONTAIN ENV FEE 9 .12 1.08
TY26408 HD460 SYN.G.OIL 9 44.63 401.67
PARTS 403.29
LABOR 360.00
16001001 SEGMENT TOTAL==> 763.29

SEGMENT#31 C 9762 NA 02/28/25 03/11/25
TROUBLESHOOT CODE 516824.04

CONTINUED ON PAGE 15

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

S780 JSC TRD(810078)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch LLOYDMINSTER		
Date 03/20/25	Time 23:04:19 (B)	Page 15
Account No. INTER01A	Phone No. 7808754471	Invoice No. W02389
Ship Via		Purchase Order 024
		Salesperson KIC

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
152137A	JOHN DEERE S780	1784	1H0S780SCKT810078	08/02/21	
	S780	1394		08/01/25	1250
***** TECHNICIANS COMMENTS *****					
* * *					
*+T/S code 516824.04					
*+Tried calibrating the AYM controller					
*+Code was still present					
*+Swapped front left sensor pad to a different location					
*+The code followed the sensor pad					
*+Replaced sensor pad & verified repair					
* * *					

AXE63845	Sensor	1	2492.99	2492.99	
			PARTS	2492.99	
			LABOR	518.40	
16001001			SEGMENT TOTAL==>	3011.39	

***** WORK ORDER TOTALS *****	
	INTERNAL CUSTOMER
PARTS	12158.97
LABOR	12202.36
Shop Supplies	250.00
Software Connec	50.00
INTERNAL TOTAL	24661.33

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO