

| MAINTANENCE MANAGEMENT RECORD |                      |                                                                                                                                                                                                           |        |
|-------------------------------|----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| BODY TYPE:                    |                      | TRUCK                                                                                                                                                                                                     |        |
| MAKE:                         |                      | MACK                                                                                                                                                                                                      |        |
| YEAR OF MANUFACTURE:          |                      | 2016                                                                                                                                                                                                      |        |
| VEHICLE ID No. (VIN)          |                      | 6FMN12H69GD807320                                                                                                                                                                                         |        |
| ENGINE NUMBER:                |                      | MP8605806                                                                                                                                                                                                 |        |
| LICENSE NUMBER:               |                      | SB77ML                                                                                                                                                                                                    |        |
| CONFIGURATION CODE:           |                      | 3 AXLE TRUCK + 1 TRAILER COMB > 6 AXLES                                                                                                                                                                   |        |
| MASS:                         |                      | 9820                                                                                                                                                                                                      |        |
| LAST SERVICE:                 |                      |                                                                                                                                                                                                           |        |
| NEXT SERVICE DUE:             |                      |                                                                                                                                                                                                           |        |
| NHVAS LABEL NUMBER:           |                      | A143980 (22/02/2017 MASS/MAINTENANCE)                                                                                                                                                                     |        |
| DATE                          | COMPANY              | DESCRIPTION                                                                                                                                                                                               | KM'S   |
| 22/03/2017                    | SOUTH CENTRAL TRUCKS | FIRST SERVICE                                                                                                                                                                                             | 4,783  |
| 29/05/2017                    | SOUTH CENTRAL TRUCKS | BASIC SERVICE - CHANGE ENGINE OIL & FILTERS, CARRY OUT ALL CHECKS & ADJUSTMENTS, CHECK ALL LEVELS & LIGHT OPERATIONS, DRAIN AIR SYSTEMOF CONTAMINATION, GREASE VEHICLE                                    |        |
| 24/07/2017                    | SOUTH CENTRAL TRUCKS | REPLACE TRANSMISSION OIL                                                                                                                                                                                  | 7,834  |
| 14/10/2017                    | SCOTT CHRISTENSEN    | SERVICE TRUCK, DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS GREASE ALL POINTS, CHECK LIGHTS AND BATTERIES, CHECK BRAKES AND STEERING                                                 | 44,744 |
| 20/01/2018                    | SCOTT CHRISTENSEN    | SERVICE TRUCK, DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECKED LIGHTS AND BATTERIES, GREASED ALL POINTS, CHECKED BRAKES, STEER JOINTS, REPLACED FAN BELT, REPLACE WIPER BLADES | 60,503 |
| 24/03/2018                    | SCOTT CHRISTENSEN    | SERVICE TRUCK, DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, GREASE ALL POINTS                                                                           | 70,984 |

|            |                             |                                                                                                                                                                                                                            |         |
|------------|-----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|
| 8/06/2018  | SOUTH CENTRAL TRUCKS        | ANNUAL SERVICE - CHANGE ENGINE,DIFF,GEARBOX AND POWER STEERING OILS AND FILTERS. GREASE ALL POINTS, ADJUST BRAKES CHECK LIGHTS, WHEEL BEARINGSAND TENSION SUSPENSION, CHECK DRIVE BELTS, HOSES, MOUNTS DRAIN AIR TANKS     | 80,187  |
| 20/10/2018 | SCOTT CHRISTENSEN           | SERVICE TRUCK DRAIN AND REFILL ENGINE OIL, CHECK ALL LEVELS, CHANGE ALL FILTERS, CHECK BRAKES AND STEERING JOINTS, GREASE ALL POINTS, CHECK LIGHTS AND BATTERIES, CLEANED CORROSION FROM BATTERIES                         | 100,975 |
| 19/12/2018 | TRUCK POWER AUTO ELECTRICS  | SUPPLY AND FIT WIRELESS REVERSE CAMERA KIT TO TRUCK, PROGRAM CAMERAS TO MONITOR                                                                                                                                            |         |
| 19/01/2019 | SCOTT CHRISTENSEN           | SERVICE TRUCK, DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, GREASE ALL POINTS, CHECK LIGHTS AND BATTERIES                                                                                            | 111641  |
| 5/04/2019  | SCOTT CHRISTENSEN           | SERVICE TRUCK AS PER SERVICE SHEET, TOPPED UP COOLANT HEADER TANK, TOPPED UP POWER STEERING RESERVOIR, REPLACED FRONT UNI IN JACK SHAFT , DRIVE AXLE BRAKE LININGS GETTING LOW                                             | 122,582 |
| 26/07/2019 | MAXITRANS                   | TARP WIRE HAS FALLEN OFFF GUIDE WHEEL<br>*RECTIFY CHECK OPERATION FOUND UNIT KEPT CUTTING OUR IN OPERATION CHECKED SYSTEM, FOUND INTERNAL INTERMITTENT FAULT IN RAZOR CONTROLLER REMOVE & REPLACE CHECK OPERATION - ALL OK | 140,687 |
| 17/08/2019 | CMV TRUCK AND TRAILER PARTS | DECAL-REAR MARKER PLAIN X2 - DECAL-REAR MARKER PRINT X2                                                                                                                                                                    |         |
| 17/08/2019 | SOUTH CENTRAL TRUCK & BUS   | X2 SAFETY VALVE                                                                                                                                                                                                            |         |

|            |                                 |                                                                                                                                                             |         |
|------------|---------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|
| 17/08/2019 | SCOTT<br>CHRISTENSEN            | DRAINED AND REFILLED ENGINE OIL, CHANGED ALL FILTERS, CHECKED ALL LEVELS, CHECKED LIGHTS AND BATTERIES, CHECKED BRAKES, GREASED ALL POINTS                  | 143,574 |
| 22/08/2019 | TRUCK POWER<br>AUTO ELECTRICS   | 1X WEDGE GLOBE KIT - 1X UHF FLEX ANTENNA - 1X UHF COAXIAL JOINER - 2X UHF COAXIAL PLUG                                                                      |         |
| 26/08/2019 | SOUTH CENTRAL<br>TRUCK & BUS    | X2 WIPER BLADE - BASIC                                                                                                                                      |         |
| 20/09/2019 | MAXITRANS                       | FUEL LEAKING FROM TANK. REMOVE TANK. DRAIN TANK. CLEAN TANK OUT. PREP AND WELD UP PATCH AS REQUIRED. REFILL TANK. REFIT TO UNIT. CHECK OPERATION FOR LEAKS. |         |
| 9/10/2019  | SCOTT<br>CHRISTENSEN            | REFITTED DAMAGED HYDRAULIC FITTINGS ON REAR OF TRUCK. REPLACED NUMBER PLATE LIGHT. REPLACED HYDRAULIC FITTING ON TRAILER                                    | 150,851 |
| 11/10/2019 | TRUELINE TRUCK<br>REPAIR CENTRE | CHECK FRONT SUSPENSION AND STEERING COMPONENTS. CHECK ALL WHEEL ALIGN ANGLES AND REST TOE                                                                   | 151,011 |
| 24/10/2019 | MAXITRANS                       | REPLACING BROKEN AIR RAM AND RAM MOUNTING. REPLACE LEAKING PUSH/PULL VALVE                                                                                  |         |
| 28/10/2019 | SCOTT<br>CHRISTENSEN            | REPLACED RINGFEEDER HANDLE AND PIN                                                                                                                          |         |
| 29/10/2019 | SOUTH CENTRAL<br>TRUCK & BUS    | FILTER KITX1. FILTER CARTRIDGE X1                                                                                                                           |         |
| 7/11/2019  | MAXITRANS                       | ADJUST TAIL GATE FINGERS                                                                                                                                    |         |

|            |                            |                                                                                                                                                                                                                                                                                                                                              |         |
|------------|----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|
| 7/11/2019  | SCOTT CHRISTENSEN          | DRAINED AND REFILLED ENGINE OIL. CHASNGED ALL FILTERS. CHECKED ALL LEVELS. CHECKED LIGHTS AND BATTERIES. CHECKED BRAKES. GREASED ALL POINTS. REPLACED X1 BROKEN P CLIP FOR HYDRAULIC HOSE. REMOVED AND REPLACED RINGFEEDER DUE TO BEING DAMAGED. REMOVED AND REPLACED X1 BRAKE VALVE IN CHASSIS. TIGHTENED LOOSE BOLTS NEAR BALL ON TRAILER. | 155,457 |
| 7/11/2019  | SOUTH CENTRAL TRUCK & BUS  | 1X VALVE                                                                                                                                                                                                                                                                                                                                     |         |
| 11/01/2020 | SCOTT CHRISTENSEN          | diagnosed why oil is leaking onto cab floor from hydraulic air controls. Removed and replaced hoist control valve. Swapped over fittings from old valve to new valve. Raised and lowered tipper several times to check operation. Cleaned oil from inside cab floor and air control for hydraulics.                                          | 165,037 |
| 15/11/2019 | SCOTT CHRISTENSEN          | REBUILD RINGFEEDER                                                                                                                                                                                                                                                                                                                           |         |
| 3/12/2019  | TRUCK POWER AUTO ELECTRICS | 1 HR LABOUR. 1X GLOBE KIT. SUPPLY AND FIT NEW HEADLIGHT GLOBES. MODIFY GLOBE HOLDERS TO SUIT. TEST OK.                                                                                                                                                                                                                                       |         |
| 19/12/2019 | SOUTH CENTRAL TRUCK & BUS  | X1 EXPANSION TANK                                                                                                                                                                                                                                                                                                                            |         |
| 19/12/2019 | SOUTH CENTRAL TRUCK & BUS  | X1 HOSE. X1 90 DEGREE FITTING. X1 20LTRCOOLANT                                                                                                                                                                                                                                                                                               |         |
| 19/12/2019 | SCOTT CHRISTENSEN          | REPAIRED HEADER TANK WATER LEAK. REMOVED AND REPLACED RADIATOR HEADER TANK.                                                                                                                                                                                                                                                                  |         |
| 6/01/2020  | SOUTH CENTRAL TRUCK & BUS  | X1 LATCH                                                                                                                                                                                                                                                                                                                                     |         |

|            |                             |                                                                                                                                                                                                                                                             |         |
|------------|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|
| 13/01/2020 | SOUTH CENTRAL TRUCK & BUS   | X1 FILTER KIT                                                                                                                                                                                                                                               |         |
| 18/01/2020 | SCOTT CHRISTENSEN           | drained and refilled engine oil. Changed all filters. Checked all levels. Checked all lights and batteries. Checked brakes. Greased all points. Replaced rh brake booster on front drive axle.                                                              | 166,212 |
| 10/02/2020 | MAXITRANS                   | tarp not functioning. Replaced battery in remote. Repaired faulty wiring.                                                                                                                                                                                   |         |
| 18/02/2020 | MAXITRANS                   | tailgate ram has failed. Remove and replace. Check operation all ok.                                                                                                                                                                                        |         |
| 21/02/2020 | south central truck and bus | parts. Filter kit x1                                                                                                                                                                                                                                        |         |
| 8/03/2020  | HaulMark                    | Removed and replaced starter motor                                                                                                                                                                                                                          | 171,388 |
| 21/03/2020 | adelaide independent bandag | supply and fit to front drive: 11r22.5 bdr-ht stock bandag x4. 11r22.5 stock casing x4. steer: strip and fit own x2. balance powder/beads x2.                                                                                                               | 176,618 |
| 26/03/2020 | south central truck and bus | parts: filter kit x1                                                                                                                                                                                                                                        |         |
| 28/03/2020 | SCOTT CHRISTENSEN           | serviced truck. Drain and refill engine oil. Change all filters. Check all levels. Check lights and batteries. Grease all ponts. Checked brakes and steering joints. Replaced x2 broken p-clamps. Replaced missing grease nipple a bottom of hydraulic ram. | 177,909 |
| 3/06/2020  | South Central Truck and Bus | parts- filter kit x1                                                                                                                                                                                                                                        |         |
| 5/06/2020  | MaxiTRANS                   | TARP STUCK SHUT - WILL NOT OPEN - DIAGNOSED / REPORT / REPAIR. *CHECK MECHANICAL & POWER SUPPLY - BATTERY ETC....ALL OK - CHECKED & FOUND MELTED FUSE HOLDER - *REMOVED AND REPLACED WITH NEW UNIT - CHECK OPERATION - ALL OK                               |         |

|            |                                   |                                                                                                                                                                                                                                                                                                                                                                     |         |
|------------|-----------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|
| 6/06/2020  | SCOTT<br>CHRISTENSEN              | Mechanics Report - drained and refilled engine oil. Changed all filters. Checked all levels. Checked lights, batteries. Checked and adjusted brakes. Greased all grese nipples. Removed oil filters and fitted new ones.                                                                                                                                            | 191,368 |
| 9/06/2020  | adelaide<br>independent<br>bandag | supply and fit to rh steer : 295/80r22.5 att404 haulmax x1. balance powder/beads x1. scrap tyre disposal x1.                                                                                                                                                                                                                                                        | 191,463 |
| 9/07/2020  | adelaide<br>independent<br>bandag | supply and fit to rear drive positions: 11r22.5 bdr-ht bandag (stk) x4. 11r22.5 stock casing x4                                                                                                                                                                                                                                                                     | 200,391 |
| 18/07/2020 | South Central<br>Truck & Bus      | Parts - filter cartridge x1. filter kit x2. seal wheel longlif x1. gasket axle shaft x1                                                                                                                                                                                                                                                                             |         |
| 18/07/2020 | SCOTT<br>CHRISTENSEN              | MECHANICS REPORT : SERVICE TRUCK. REPLACE REAR BRAKES. DRAINED ANF REFILLED ENGINE OIL. CHANGED ALL FILTERS. CHECKED ALL LEVELS. CHECKED LIGHTS AND BATTERIES. CHECKED AND ADJUSTED BRAKES. GREASED ALL NIPPLES. FITTED NEW BRAKE SHOES AND BRAKE DRUMS. REFITTED WHEEL AND TENSIONED NUTS TO 500 FT LBS. PARTS : BRAKE SHOE KIT X4. BRAKE DRUM X4. CONSUMABLES X1. | 201,495 |
| 20/07/2020 | South Central<br>Truck & Bus      | Parts - Kit drive wheel br x1. Bulldog synthetic trans fluid 20L x1.                                                                                                                                                                                                                                                                                                |         |
| 24/07/2020 | SOUTH CENTRAL<br>TRUCK AND BUS    | CHECK AND RECTIFY TRANSMISSION STUCK IN SECOND GEAR. CONNECTED LAPTOP AND FOUND GEARBOX WOULD NOT SELECT 3RD OR 4TH GEAR. CARRIED OUT GEAR SELECTOR TEST WHICH FAILED GEAR RANGE FOR 3RD AND 4TH GEAR. REPROGRAMMED ENGINE AND TRANSMISSION ECU'S. ROADTESTED AND CHECKED OPERATION. ALL OK.                                                                        | 200,008 |
| 8/09/2020  | adelaide<br>independent<br>bandag | FIT 1X NEW TYRE                                                                                                                                                                                                                                                                                                                                                     |         |
| 24/09/2020 | SOUTH CENTRAL<br>TRUCK            | FILTER KIT                                                                                                                                                                                                                                                                                                                                                          |         |

|            |                             |                                                                                                                                                         |         |
|------------|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------|---------|
| 25/09/2020 | SOUTH CENTRAL TRUCK         | FILTER CARTIDGE                                                                                                                                         |         |
| 25/09/2020 | SCOTT CHRISTENSEN           | DRAINED AND REFILLED ENGINE OIL, CHANGED ALL FILTERS, CHECKED ALL LEVELS, CHECKED LIGHTS AND BATTERIES, CHECKED BRAKES, GREASED ALL POINTS              | 211,856 |
| 27/10/2020 | SOUTH CENTRAL TRUCK         | CHECK & RECTIFY ENGINE LIGHT ON DASH, CHECK AND RECTIFY DIFF TEMP SENSOR, REPLACE FAULT HAND PIECE FOR 2 WAY RADIO                                      | 215,641 |
| 27/11/2020 | SCOTT CHRISTENSEN           | SERVICE TRUCK, DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS. CHECKED LIGHTS AND BATTERIES, CHECKED BRAKES AND KING PINS            | 221,707 |
| 14/12/2020 | MAXITRANS                   | LIGHTS FLICKERING - REPLACE ELECTRICAL BASE ON TRUCK AND PLUG ON DOG. CHECK WIRING & FOUND BROKEN EARTH REPAIRD AS REQUIRED. CHECK OPERATION ALL OK     |         |
| 20/01/2021 | TRUCK POWER AUTO ELECTRICS  | TEST FUNCTION OF REVERSE CAMERA SYSTEM, REMOVE & RELACE FAULTY LED BEACON ON ROOF                                                                       |         |
| 1/02/2021  | SCOTT CHRISTENSEN           | Removed and replaced leaking brake boosters LHR drive + parts                                                                                           | 228183  |
| 12/03/2021 | SCOTT CHRISTENSEN           | DRAINED AND REFILLED ENGINE OIL, CHANGED ALL FILTERS, CHECKED ALL LEVELS, CHECKED LIGHTS AND BATTERIES, CHECKED BRAKES, GREASED ALL POINTS              | 233,694 |
| 14/05/2021 | SCOTT CHRISTENSEN           | SERVICED TRUCK-REMOVED AND REPLACED WIPER BLADES                                                                                                        | 244,171 |
| 24/05/2021 | SOUTH CENTRAL TRUCK & BUS   | CHECK & RECTIFY DRIVE AXLE BUSHES WORN - CHECK & RECTIFY STEERING WHEEL BEARING WORN -CHECK & RECTIFY POWER STEERING LEAK-RECT EXHAUST MAINFOLD LEAKING | 244,981 |
| 25/05/2021 | ADELAIDE INDEPENDENT BANDAG | SUPPLY AND FIT STEERS X 2 - WHEEL BALANCE - BALANCE WEIGHT - SCRAP DISPOSAL                                                                             | 245,179 |
| 21/06/2021 | ADELAIDE INDEPENDENT BANDAG | RH STEER-STRIP & FIT X 1-WHEEL BALANCE X 1-BALANCE WEIGHTS X 16.5-ROTATE DRIVE WHEEL X 2-RH REAR INNER X1-REMOVE AND RELACE WHEEL                       | 240,762 |

|            |                             |                                                                                                                                                                                                                                                                 |         |
|------------|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|
| 9/07/2021  | SCOTT CHRISTENSEN           | REPLACED HYDRAULIC FITTING ON REAR OF TRUCK                                                                                                                                                                                                                     |         |
| 14/07/2021 | SCOTT CHRISTENSEN           | OIL & FILTER CHANGE, CHECKED ALL LEVELS, LIGHTS AND BATTERIES, GREASED NIPPLES, REPLACED 2 X BELTS                                                                                                                                                              | 251,575 |
| 28/07/2021 | ADELAIDE INDEPENDENT BANDAG | PUNCTURE REPAIR - 11R22.5 - RH FRONT OUTER                                                                                                                                                                                                                      |         |
| 17/08/2021 | SCOTT CHRISTENSEN           | MECHANICS REPORT: DRAINED AND REFILLED ENGINE OIL, CHANGED ALL FILTERS, CHECKED ALL LEVELS, CHECKED ALL LIGHTS AND BATTERIES, CHECKED AND ADJUSTED BRAKES, GREASED ALL NIPPLES                                                                                  | 250,161 |
| 30/11/2021 | SCOTT CHRISTENSEN           | SERVICE TRUCK, DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECKED ALL LEVELS, CHECKED BRAKES, GREASED ALL POINTS. CHECKED LIGHTS AND BATTERIES. REMOVED AND REPLACED BROKEN BOLTS OPN FUEL TANK CROSS OVER, REMOVED AND REPLACED 2X ROOF LIGHTS.          | 263,162 |
| 31/12/2021 | SOUTH CENTRAL TRUCK & BUS   | REFER TO HYPER LINK FOR DETAILS                                                                                                                                                                                                                                 |         |
| 31/01/2022 | TRUCK POWER AUTO ELECTRICS  | CHECK FAULT WITH A/C NOT WORKING. INSPECT AND FIND MISSING BELT FOR A/C COMPRESSOR AND ALTERNATOR. SOURCE REPLACEMENT BELT AND FIT. RE-CHECK A/C AND CHARGING SYSTEM. OK                                                                                        | N/A     |
| 3/03/2022  | TRUCK POWER AUTO ELECTRICS  | ATTEND JOB AT VIRGINIA (MACKTRANS). CHECK FAULT WITH A/C NOT WORKING. INSPECT AND FIND MISSING BELT FOR A/C COMPRESSOR AND ALTERNATOR. SOURCE REPLACEMENT BELT AND FIT. RE-CHECK A/C AND CHARGING SYSTEMS. OK. *NOTE POSSIBLE FAULT OF BELT TENSIONER ASSEMBLY* | N/A     |
| 25/03/2022 | SCOTT CHRISTENSEN           | REPLACED ALTERNATOR BELT AND BELT TENSIONER                                                                                                                                                                                                                     | N/A     |
| 5/04/2022  | ADELAIDE INDEPENDENT BANDAG | SUPPLE AND FIT RH FRONT INNER                                                                                                                                                                                                                                   | N/A     |

|            |                                   |                                                                                                                                                                                                                                                                    |         |
|------------|-----------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|
| 20/04/2022 | SCOTT<br>CHRISTENSEN              | REMOVED AND REPLACED BRAKE BOOSTER                                                                                                                                                                                                                                 | 272,042 |
| 29/04/2022 | SCOTT<br>CHRISTENSEN              | SERVICE TRUCK, DRAIN AND REFILL ENGINE OIL,<br>CHANGE ALL FILTERS, CHECKED ALL LEVELS,<br>CHECKED LIGHTS AND BATTERIES. CHECKED<br>BRAKES AND STEERING JOINTS, GREASED ALL<br>POINTS                                                                               | N/A     |
| 11/11/2022 | ADELAIDE<br>INDEPENDENT<br>BANDAG | SERVICE CALL ON TRUCK SC77ML: SUPPLY & FIT 2<br>TYRES & STOPCK CASTING ALSO CASING FOR RE-<br>TREADING                                                                                                                                                             | N/A     |
| 5/01/2023  | ADELAIDE<br>INDEPENDENT<br>BANDAG | SERVICE CALL. SUPPLY AND FIT STEERS. BLANCE<br>AND PWEDER/BEADS.                                                                                                                                                                                                   | N/A     |
| 30/01/2023 | ADELAIDE<br>INDEPENDENT<br>BANDAG | RH REAR REPLACEMENT OF 2 TYRES                                                                                                                                                                                                                                     | N/A     |
| 22/03/2023 | SCOTT<br>CHRISTENSEN              | DRAIN AND REFILL ENGINE OIL, CHANGE ALL<br>FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND<br>BATTERIES, CHECK AND ADJUST BRAKES, GREASE<br>ALL GREASE NIPPLES.                                                                                                        | 295771  |
| 23/06/2023 | SCOTT<br>CHRISTENSEN              | REMOVE AND REPLACE STEERING WHEEL,<br>CHECKED AIR LEAK                                                                                                                                                                                                             |         |
| 12/09/2023 | COMPLETE<br>ALIGNMENTS            | REPLACE PIVOT BUSHES AND CENTRE BUSHES ON<br>BOTH DRIVE AXLES, OXY CU TO REMOVE SEIZED<br>ECCENTRICS, REPLACE FIRST AND SECOND DRIVE<br>RHS TORQUE ROD BUSES AT DIFF END USING NEW<br>BOLTS, WHEEL ALIGNMENT                                                       |         |
| 4/09/2023  | SCOTT<br>CHRISTENSEN              | DRAIN AND REFILL ENGINE OIL, CHANGE ALL<br>FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND<br>BATTERIES, CHECK AND ADJUST BRAKES, GREASE<br>ALL NIPPLES, REPLACE 2X BOLTS RH FRONT DRIVE<br>AXLE TO FIT SUSPENSION ARM MOUNT,<br>TIGHTENED LEAKING POWER STEERING HOSE | 308501  |
| 17/11/2023 | adelaide<br>independent<br>bandag | ROTATE TYRES/WHEELS (STEERS) X 2, WHEEL<br>BALANCE X 2, PRESSURE MAINTENANCE TYRE X 8<br>(DRIVES)                                                                                                                                                                  | 311479  |
| 23/11/2023 | SCOTT<br>CHRISTENSEN              | REPLACE WINDSCREEN WIPER MOTOR                                                                                                                                                                                                                                     | 312755  |

|            |                                   |                                                                                                                                                                                                                                                                                                                                                                                                    |         |
|------------|-----------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|
| 11/01/2024 | adelaide<br>independent<br>bandag | SUPPLY AND FIT X 2 LH REAR, 2X STOCK CASING                                                                                                                                                                                                                                                                                                                                                        |         |
| 16/02/2024 | SCOTT<br>CHRISTENSEN              | REMOVE AND REPLACE LH REAR SPRING BRAKE,<br>REPLACED LH REAR AXLE BRAKE BOOSTER                                                                                                                                                                                                                                                                                                                    | 319,929 |
| 23/02/2024 | SCOTT<br>CHRISTENSEN              | DRAIN AND REFILL ENGINE OIL, CHANGE ALL<br>FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND<br>BATTERIES, CHECK AND ADJUST BRAKES, GREASE<br>ALL GREASE NIPPLES                                                                                                                                                                                                                                         | 320,964 |
| 18/04/2024 | SOUTH CENTRAL<br>TRUCKS           | SEE HYPERLINK FOR DETAILS                                                                                                                                                                                                                                                                                                                                                                          | 325,552 |
| 24/04/2024 | adelaide<br>independent<br>bandag | supply and fit to steers 2x neo allroads aeolus,<br>wheel balance, stick on balance weights rh rear 2x<br>bandag customer own casings                                                                                                                                                                                                                                                              | 326441  |
| 23/05/2024 | SCOTT<br>CHRISTENSEN              | REPAIRED DRIVERS SEAT, FIT NEW SEAT BELT,<br>CLEANED BLOCKED DIFF BREATHERS, TIGHTENED<br>TRACK ROD BOLTS ON RH FRONT DRIVE AXLE                                                                                                                                                                                                                                                                   | 329,292 |
| 3/06/2024  | SCOTT<br>CHRISTENSEN              | DRAIN AND REFILL ENGINE OIL, CHANGE ALL<br>FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND<br>BATTERIES, CHECK AND ADJUST BRAKES, GREASE<br>ALL GREASE NIPPLES, REMOVE AND REPLACE<br>TOOLBOX HINGE AND T HANDLE, REPLACED TWO<br>EXHAUST FLEX'S, REPLACED ONE EXHAUST PIPE<br>AND FIVE INCH CLAMP LOOSENED PIPE BACK OF<br>EXHAUST BRAKE, ADJUSTED PIPE OF CHASSIS RAIL<br>AND TIGHTENED PIPE BACK UP | 330,953 |
| 25/09/2024 | adelaide<br>independent<br>bandag | LH REAR OUTER PUNCTURE REPAIR X 1,<br>UNIVERSAL PATCH X 1, REMOVE AND REPLACE<br>WHEELS X 1                                                                                                                                                                                                                                                                                                        | 337414  |
| 4/11/2024  | TRUCK POWER<br>AUTO ELECTRICS     | CHECK AC OPERATION, FIND SYSTEM LOW ON<br>PRESSURES, REMOVE AND REPLACE RECEIVER<br>DRIER, REPLACE O RINGS TO FITTINGS, REPLACE<br>SERVICE VALVE CORES, VAC DOWN SYSTEM,<br>CHECK FOR LEAKS, CHARGE SYSTEM WITH<br>OIL/DYE, CHARGE SYSTEM WITH REFRIDGERANT,<br>CHECK OPERATION, FIND POOR VENT AIR FLOW,<br>REPLACE BLOCKED CABIN FILTER, RECHECK OK                                              |         |

|            |                                   |                                                                                                                                                                                                                                                                       |        |
|------------|-----------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 19/11/2024 | TRUCK POWER<br>AUTO ELECTRICS     | INSPECT AC SYSTEM FOR SIGNS OF LEAK, REMOVE PASSENGER SIDE DASH PANELS TO ACCESS EVAPORATIVE COIL, FIND SIGNS OF UV DYE, CHARGE SYSTEM WITH R134A GAS AND LEAK GUARD/UV DYE SOLUTION, MONITOR SYSTEM PERFORMANCE AND REINSPECT EVAPORATOR FOR FURTHER SIGNS OF UV DYE |        |
| 13/01/2025 | TRUCK POWER<br>AUTO ELECTRICS     | SERVICE AC SYSTEM AFTER EVAPORATOR REPLACEMENT, REPLACE O RINGS AS REQUIRED, REMOVE AND REPLACE RECEIVER DRIER, REPLACE SERVICE VALVE CORES, VAC DOWN AC SYSTEM, CHARGE SYSTEM WITH OIL/DYE, CHARGE SYSTEM WITH REFRIGERANT                                           |        |
| 21/03/2025 | FREIGHTER<br>GROUP                | DIAGNOSE ISSUE WITH TARP NOT MOVING AND RECTIFY, REPLACE BATTERY                                                                                                                                                                                                      |        |
| 5/03/2025  | SCOTT<br>CHRISTENSEN              | TRUCK SERVICE, DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, CHECK AND ADJUST BRAKES, GREASE ALL GREASE NIPPLES                                                                                                      | 352807 |
| 12/03/2025 | SCOTT<br>CHRISTENSEN              | PICKED UP HYDRAULIC HOSE, REMOVE AND REPLACE HYDRAULIC SUCTION HOSE AND CLAMPS, REMOVE AND REPLACE EXHAUST PIPE FLEX                                                                                                                                                  | 352807 |
| 16/04/2025 | TRUCK POWER<br>AUTO ELECTRICS     | SUPPLY AND FIT REVERSE CAMERA KIT TO TRUCK, SUPPLY AND FIT ADDITIONAL CAMERA CABLE AND TRAILER SUZI COIL KIT, SUPPLY AND FIT ADDITIONAL CAMERA AND CABLE TO DOG TRAILER TEST OPERATION OK, REMOVE AND REPLACE BLOCKED CABIN FILTER                                    | 356154 |
| 25/06/2025 | adelaide<br>independent<br>bandag | SERVICE CALL 1h REAR REMOVE REPLACE 2X WHEELS BOLT ON OWN SCRAP TYRE DIS X2                                                                                                                                                                                           |        |
| 25/06/2025 | adelaide<br>independent<br>bandag | SUPPLY FIT LOOSE WHEELS FROM SB77ML FOR SHED STOCK 11R22.5 B729 BANDAG OWN CASINGS                                                                                                                                                                                    |        |

SEE HYPERLINK

20/06/2025 SCOTT  
CHRISTENSEN

364,301

|            |                                   |                                                                                                                                                                                                                                                                                                                             |        |
|------------|-----------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 30/09/2025 | adelaide<br>independent<br>bandag | SERVICE CALL, PUNCTURE REPAIR, REMOVE AND REPLACE WHEELS/TYRES, TORQUE SETTING 650N                                                                                                                                                                                                                                         |        |
| 3/11/2025  | SCOTT<br>CHRISTENSEN              | MECHANICS REPORT: TRUCK SERVICE: DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, CHECK AND ADJUST BRAKES, GREASE ALL GREASE NIPPLES                                                                                                                                          | 374591 |
| 8/12/2025  | SCOTT<br>CHRISTENSEN              | TRUCK SERVICE, DRAIN AND REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS & BATTERIES, CHECK & ADJUST BRAKES, GREASE ALL GREASE NIPPLE, REPLACE & FIT 4 NEW AIR BAGS, REMOVE RUSTED OUT EXHAUST PIECES, FIT NEW EXHAUST ELBOW & FLEX, REMOVE AND FIT RINGFEEDER PAD, REMOVE & REPLACE AIR DRYER FILTER | 385039 |
| 18/12/2025 | TRUCK POWER<br>AUTO ELECTRICS     | LABOUR, BATTERY MASTER SWITCH SUNDRIES                                                                                                                                                                                                                                                                                      |        |
| 09.01.2026 | TRUCK POWER<br>AUTO ELECTRICS     | LABOUR, 18437P, H7 LED GLOVE 2PK SUIT PROJECTOR, 18240BL T 10 5W LED WEDGE 2PK, E72-42ARM -LED SIDE MARKER RED/AMBER                                                                                                                                                                                                        |        |
| 4/02/2026  | adelaide<br>independent<br>bandag | SUPPLY & FIT LH MIDDLE, 11R22.5 RIB TRAC ELITE BANDAG - STK, 11R22.5 STOCK CASING, EPA SCRAP TYRE DISPOSAL - 11R22.5                                                                                                                                                                                                        | 390403 |
| 2/02/2026  | SCOTT<br>CHRISTENSEN              | MECHANICS REPORT - ADJUSTED BRAKES - NOTICE - PLEASE NOTE RADIATOR IS LEAKING                                                                                                                                                                                                                                               | 390388 |

|            |                                   |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |        |
|------------|-----------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| 20/02/2026 | SCOTT<br>CHRISTENSEN              | MECHANICS REPORT - TRUCK SERVICE - DRAIN & REFILL ENGINE OIL, CHANGE ALL FILTERS, CHECK ALL LEVELS, CHECK LIGHTS AND BATTERIES, CHECK AND ADJUST BRAKES, GREASE ALL GREASE NIPPLES. REMOVED BRAKES AND BRAKE DRUMS, FITTED NEW SLACK ADJUSTERS, ORDERED AND PICKED NEW PARTS, FITTED NEW BRAKE SHOES AND DRUMS TO TRUCK, CLEANED OIL AND GREASE FROM LH REAR HUB DUE TO A LEAKING WHEEL SEAL. WELDED BEARING CUP IN LH REAR HUB TO REMOVE OLD CUPS, CLEANED UP HUB & FITTED NEW BEARING CUPS, REFIT LH REAR HUB TO TRUCK WITH NEW BEARINGS, FILLED UP HUB WITH OIL, REFIT ALL WHEELS TO TRUCK AND TORQUED WHEEL NUTS TO SPECIFICATIONS. | 396759 |
| 6/03/2026  | ADELAIDE<br>INDEPENDENT<br>BANDAG | SUPPLY & FIT, RH REAR, 11R22.5 BDR-HT BANDAG - SIX, 11 R22.5 STOCK CASING                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | 396770 |
| 10/03/2026 | adelaide<br>independent<br>bandag | POSITION: LH FRONT, REMOVE AND REPLACE WHEELS/TYRES, NOTE: REMOTE WHEELS FROM LH FRONT AXLE WITH TYRES FROM LH FRONT AXLE OF SY43GM                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | 396805 |
| 14/05/2026 | SCOTT<br>CHRISTENSEN              | DIFF LOCK NOT WORKING -SEE HYPERLINK                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |        |
| 19/05/2026 | adelaide<br>independent<br>bandag | SUPPLY & FIT FRONT DRIVE AXEL                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | 400452 |