

EV21-1

Oct 27 changed out Switch for Signals. finally. Replaced Electrical socket. 770520
New Card 7450 PIN

Nov 13 Chain Rack Installed & Full Service 784655

Next Lube @ 809655 to 814655

Next Service @ 839655 to 844655

December 25 Lube New Wipers blades 811400

2020

Jan 14 New Brass fitting On Hose. ^{TM^{1st}} Valve on Air Dryer 825852
Lid for Power Fluid Replaced Coolant System leak &
Towed to Ottawa Kenworth.

Feb 4 Full Service New Fog Lights Installed 845064

Next Lube @ 870064 to 875064

Next Service @ 900064 to 905064

Check Belt.

Feb 20 Deer/Elk Hit 860593

Re Mount Fog lights Changed Pintle Hook

May 12 Fixed Bumper & Full Service Fixed Rear light. 910112
Replaced windshield.

Next Lube 935112 to 940112

Next Service 965112 to 970112

June 8 Lube Replaced Rear Driver Side Brake Chamber 935789

July 20 Full Service Safety Replace Clutch Actuator? Replaced card 966320
End.

Next Lube @ 991320 to 996320

Next Service @ 1021320 to ~~1021~~ 1026320

Aug 7 2020 DEF Tank Vent unplugged. washer
AC evaporator Due to AC Not working at Times

985100

Aug 27 2020 Lube

999689

September 27 2020 Full Service Right Headlight Changed

1024874

Next Lube @ 1049874 to 1054874

Next Service @ 1079874 to 1084874

October 21 2020 ^{Top} Bottom Nox Sensor replaced.

1043463

~~Plastic~~ ~~steps~~ ^{Highland} Plastic to Steps tightened.

Nov 4 2020 Lube, ^{outlet} Bottom Nox Sensor Replaced

1050026

Cleaned Fan Motor Fixed, Black Heater Plug Fixed
ABS checked out, Batteries replaced

²⁰²⁰
Dec 15 Steering Tires Changed Belts changed
Full Service. Rebrake Jan 1

1081618

Next Lube @ 1106618 to 1111618

Next service @ 1136618 to 1141618


Jan 20 2021 Lube, ^{side} Fender, replaced band filter,
Hood cylinders for opening

1101372

Jan 27 2021 Elmont AB PPF Cleaned Valve Replaced
Derate

1107079

Feb 4 2021 Calgary AB

 Bottom Outlet Nox Sensor

1113264

replaced replaced Air filter, Power Steering Clamps -
EGR Cleaned (???)

March 25 2021 Belt Replaced. Cylinders Redone. 1,123,788³
Full Service. New Radiator. Engine Overhaul. b/c
of Head Gasket Replacement

Next Lube 1,148,788 to 1,153,788
Next Service 1,178,788 to 1,183,788

April 11 2021 1140271
New Starter, New Passenger Wiper blade. New Cabin Filter
(Firewall) & Pre Filter. Rear Right Axle According to John
1 Tire had a nail, Other Valve stem issue.

May 11 2021 Full Service, New Hub Caps. LED Head Lights. 1178059

Next Lube 1,203,059 to 1,208,059
Next Service 1,233,059 to 1,238,059

June 7 2021 New Drive Tires, Bug Screen, Detail Inside. 1191668

July 20 2021 New Windshield New Suspension Components
159324

Sept 02 2021 1244964 - ~~steering~~ replaced
cabin air filters

Sept. 24/21.

YRC. G50

- Grease + Tire check.
- Replaced 5th wheel cylinder
- Inspect 5th wheel function.

1,265,209 Kms.

Sept. 27/21.

YRC. G50.

- Replace 5th wheel bushings
- R+R 5th wheel bushings check - front diff sensor
- Replaced engine air Filters.

1,265,225 Kms.

Sept. 27/21.

YRC. G50.

- Reinstall low beam lights
- Reinstalled original low beams.

1,265,223 Kms.

Oct. 28/21.

NOMAD.

- Replaced water pump
- Replaced King Pin cap on passenger side
- Replaced air dryer cartridge
- Replaced bearings on idler + tensioner pulley on A/c. belt.
- Grease.

1,294,242 Kms.

Nov. 15/21.

NOMAD.

- Fan switch for bunk heater.
- Replaced tensioner + pulley on A/c unit.
- Repaired wiring on rear diff.
- Replaced sensor to rear diff
- Disconnected + taped off Y cable for amp sensor.

1,294,242 Kms.

Nov. 25/21.

Royal Lube

- Full service

Dec. 28/21.

NOMAD

- Grease.
- Replace King pin cap on passenger si.
- installed new hose clamp on webasto water pump.

1,329,581 Kms.

Jan. 25/22.

NOMAD

- Replaced height control valve
- Repaired corroded wiring to rear red cab lights.

1,329,626 Kms.

March 04/22.

NOMAD

- Grease
- Right side rear cab lights repaired
- Replaced bunk HVAC Switch.

1,365,384 Kms.

May 03/22.

NOMAD

- Grease
 - Replaced popo stick
 - Fixed marker light wiring
- 1,403,178 KMS.

May 18/22.

Larry J.

- Replaced intake Nox Sensor.
- 1,420,071 KMS.

May 27/22.
30.

Larry J.

- Grease
 - rebuild 5th wheel.
 - clutch adj.
 - Replaced def Tank.
- 1,424,809 KMS.

July 02/22.

- Steer tires
 - 3 axle alignment
- 1448970 KMS.

July 04/22.

- ~~Thas clutches~~
 - clutch adjusted
- 1,440,081 KMS.

July 16/22. K.W. WPLG.
- Full Service
- replaced blower motor in bunk.
1,447,230 KMS.

July 28/22
- SAFETY
1457858 KMS-

Aug. 03/22. Self
- Grease & Levels
1,459,555 KMS.

Sept. 22/22. Self
- Grease & Levels.
1,494,473 KMS.

Sept. 29/22.

WARD TIRE.

- Patch drive Tire.

1,497,984 Kms.

Sept. 29/22.

SELF.

- Grease
- Replaced Top 4- left CL. lights

1,497,986 Kms.

Oct. 1/22.

- Drive Tire rotation.

Kms.

Oct. 07/22.

C.D.S.

- engine auxillary heater repair -
replaced water pump.

1502269 Kms.

Nov. 15/22.

NORMAN

- Replaced doser.
- Replaced def fluid filter
- blew out doser line from filter housing
to doser.
- Replaced doser valve
- wiring from ecu to doser within spec.
- V clamp for Scr to front section of dpf
not installed correctly - corrected.

1,525,104 Kms.

Oct 21/22.

Royal

- Full service (not fuel filters)
- Grease + levels.

1,507,879 Kms.

Dec. 05/22.

High River. m.

- checked DEF issues
- Load tested batteries
- checked codes for DPF + DEF.
- pressure tested pump + inspected lines + wiring - OK.

1,529,706 Kms.

Nov. 22/22.

CDS.

- Computer diagnosis, check engine light + derating found issue with DEF.
- Exhaust repair.
- Replaced DEF heater lines

1,526,537 Kms.

Dec. 02/22.

Larry J.

- no marker lights on trailer
- check Tractor plug, Fuse fail for Trailer plug - replaced.

1,529,638 Kms.

Dec. 18/22.

Calgary. Peterbilt -

- changed ~~water~~ inner DEF tank filter.

1,531,195 Kms.

Jan. 07/23.

Royal hube
- Grease.

1,543,171 Kms.

RET REPAIRS FOR 159283 FOR MONTH OF JULY 2020

June July 17/20 F/S and Safety @ 966316 Km's @
 56200 Km's Reimer Shop. also replace slave
 since lost cylinder on clutch 2421.41
 F/S.

1/2
 July
 Aug
 Aug
 Aug
 Aug
 Aug.
 Aug.
 Aug.
 Aug 6
 Aug 1
 Aug.
 Aug.
 Aug 2
 Aug 2
 Aug 2
 Aug 3
 Aug 3,

Repairs For 158283 For Month of August

15

Aug 09/20 Repair air conditng & cleaned condenser
of Buys & repair Def Tank leather tube
\$767.83

Sen
Spt
Sept
Sept
Sept
SEPT
SEPT
SEPT
SEPT
SEPT
SEPT
SEPT
SEPT
SEPT
SEPT

Aug 24/20 LUBE @ Reiman @ 999685 L's

98 158

REPAIRS FOR 159283 FOR MONTH OF SEPTEMBER 2020

SEP 28/20 FIS, repair left side steps + check batteries
58554 @ 1024870 km's
last FIS 53

REPAIRS FOR 159283 FOR MONTH OF OCTOBER 2020
OCT15/20 Replace ^{new} rear lens & repair left side
steps, mirror could not be tightened @
Inland Kenworth @ 1042623.4 / hrs
Cost. 1389.78 include GST.

12

00

N

N

P

NO

Ne

No

No

NO

NOV

NOV

NOV

NOV

NOV

REPAIRS FOR 159283 FOR MONTH OF NOVEMBER 2020 159

NOV 4/20 LUBE, ELECTRICAL OUTLET ON BLOCK HEATER

HEATER FAN, LHEUX BATTERIES &

REPLACE 4 NEW CAT BATTERIES & CABLE ENDS

1050016 KWS TOTAL BILL @ Kenworth is \$3763.56

DEC 01

DEC 0

DEC 0

DEC 08

DEC 1

DEC 1

DEC 1

DEC 1

DEC 1

DEC 1

REPAIRS FOR 159283 FOR MONTH OF DECEMBER 2020

Dec 11/20 FSD Reimburse 1081602/L's
Check from belts & idler pulleys ok
Repair right rear fairing
New steering tips @ Denroy new fan
belts

159283, REPAIRS FOR MONTH OF JANUARY 2021

Jan 19/21 LUBE & repair fairing & hood @ 1101369 hrs
and new in cab air filter.

Jan 26/21 Truck derated @ EDT. KENWORTH
@ 1107066 hrs clean out def valve
& DPF filter cleaning, cost 1752.66
469853 hrs since last @ PF cleaning

159283 REPAIRS FOR MONTH OF FEBRUARY 2021

Feb 01/21 @ Great West Kenworth in Calgary.
 Exhaust gas pressure erratic check MAF
 sensor @ 1113240 Km's have to replace
 MAF sensor & F.R sensor repair oil
 leak on power steering & light on fender.
 Replaced Rear MAF sensor Replaced
 Exhaust gas pressure sensor repaired
 power steering leak with new clamps.
 Replaced engine air filter, Ready
 @ Feb 4/21 @ 3 pm, 1113243 Km's

Feb 12/21 Truck Towed From PASS LAKE TO INLAND KENWORTH
 Feb 14/21 in WPG. F/S, new radiator & Engine
 over haul on inframe route is \$25500.00
 @ 1,123,778 Km's TOTAL REPAIR 25313.18

159283 REPAIRS FOR MARCH 2021

F/S done @ Kenworth @ 1123,778 L's

New Radiator + Engine overhaul.

\$25353.00

MARCH 24/21 New idler pulley @ Reiman 1123778 L's

April 11/21 TIS & new window

REPAIRS ON 159283 APRIL 2021

PRIL 9/21 LUBE & NEW STARTER & REPAIR DRIVE TIRE
@ 1140091 KLS

April 25/21 @ Kenworth air cond leak on rad & fix
left side door squeak @ 1160626 KLS
new air cond. condenser & door hinge
stap. 1740.72

REPAIRS ON 159283 FOR MAY 2021

MAY 13/21 F/S @ Reimer @ 4,178,897 LLS
MAY 14/21 Clean truck interior by Roseane.
RV & truck cleaning

REPAIRS FOR 159883 J

JUNE 1/21 New drive tires @ Don
@ 1191654/k's \$3520.44

JUNE 25/21 Repair ABS, LUBE, Rear @
@ 1211464/k's also repl
injector full line @ K

REPAIRS FOR 159283 JULY 2021

JULY 16/21 SAFETY @ 1,230,559 K's