

# Triple S Trucking

403-601-9809

Unit #: 152

Kms 208733

Hrs 6-6111

☐ SERVICE ☒ REPAIR

Work Performance By: \_\_\_\_\_

Location:

Description & Parts Valve cover gasket + 16 bolts  
air bag bolts

Time In: 12:00 PM Time Out: 5:21 PM Time spent on job: \_\_\_\_\_

Signature

# SERVICE & REPAIR

**Triple S Trucking**

Box 210, Longview, AB T0L 1H0

403-601-9809

Date: Dec 4/2023

Unit #: 152 Viper

Kms 141701.8 Hrs 26 117.4

☐ SERVICE

☒ REPAIR

Work Performance By: Shane Spagren

Location: Longview Shop

Description & Parts Drivers Door window went roll up Western Star  
152 fix/install

Inv # 138

Parts R James \$ 227.69 paid for by Shane

Add 1hr for fuel

Time In: 2:45

Time Out: 7:45

Time spent on job: 5hr

# SERVICE & REPAIR

S Triple S Trucking  
Box 210, Longview, AB T0L 1H0  
403-601-9809

2 H B L INC  
c/w s e l o n J A B

Date: Nov 21/23

Unit #: 152 + 152 trailer

Kms 138257 Hrs 26022

☒ SERVICE ☐ REPAIR

Work Performance By: Scott

Location: L.V. Shop

Description & Parts Grease truck & trailer set brakes

Lined area for description and parts details.

Time In: 3:00 pm Time Out: 4:00 pm Time spent on job: 1

[Signature]  
Signature

# SERVICE & REPAIR

~~Triple S Trucking~~

~~Box 210, Longview, AB T0L 1H0~~

~~403-601-9809~~

Date: Oct 24/23.

Unit #: 152 Truck + Trailer License # 6JUL62

Kms 130324.3 Hrs \_\_\_\_\_

241 Bar Inc

Box 44

Carleton Place, AB

TO JOMO

☒ SERVICE ☒ REPAIR

Work Performance By: Mike

Location: Carleton Place

Description & Parts \_\_\_\_\_

- trailer CUP (back 2 axle new brakes/Drum  
new front cl lights.

- truck
- Driving light instal
- new High/Low Head lights (4)
- tighten Headache Buck bolts.
- Replaced oil pressure sensor
- throw 3 sets chains on 2 sets used.

truck / trailer greased

Time In: \_\_\_\_\_ Time Out: \_\_\_\_\_ Time spent on job: \_\_\_\_\_

[Signature]  
Signature

# SERVICE & REPAIR



~~Triple S Trucking~~

~~Box 249, Longview, AB T0L 1H0~~

~~403-601-9809~~

2 H Bar Fnc  
Carleton Place AB.

Date: Oct 12/23

Unit #: 152 Truck

Kms 127100

Hrs 25740

☐ SERVICE ☒ REPAIR

Work Performance By: male

Location: L.V. Shop

Description & Parts replace fan Belt.

Blank lines for additional notes or parts list.

Time In: 18:00 Time Out: 19:00 Time spent on job: 1

[Signature]  
Signature

# SERVICE & REPAIR

5

**Triple S Trucking**

Box 210, Longview, AB T0L 1H0

403-601-9809

Date: Oct 10 123

Unit #: 152 truck

Kms 125 964

Hrs 25715

2 H Bar  
carsland MB

☒ SERVICE ☐ REPAIR

Work Performance By: Scott

Location: L.V.

Description & Parts Grease truck blow out cab

clean Garbage out

PRINTED BY HIGHWOOD PRINTING INC., HIGH RIVER, AB 403-652-3101

Time In: 19:00 Time Out: 13:00 Time spent on job: 1

[Signature]  
Signature

# SERVICE & REPAIR

2 H Bar

**Triple S Trucking**

Box 210, Longview, AB T0L 1H0

403-601-9809

9

Date: OCT 3 / 23

Br 44

carsland AB

Unit #: 152 + trailer 6JU062

Kms 123 850

Hrs 25650

☐ SERVICE ☒ REPAIR

Work Performance By: mate + Scott

Location: carsland shop

Description & Parts Tighten up loose Power steer bolt  
wash off oil, weld wrench on trailer,  
Tighten up air to air clamps

Time In: 15:30 Time Out: 19:00 Time spent on job: 2.50

1 hr Travel

[Signature]  
Signature

# SERVICE & REPAIR

9

**Triple S Trucking**

Box 210, Longview, AB T0L 1H0

403-601-9809

Date: Oct 4/23

Unit #: 152 truck.

Kms 124120

Hrs 25670

2 H Bar

Box 44 Carlsbad 19B.

☐ SERVICE ☒ REPAIR

Work Performance By: mike (Strathmore Heavy)

Location: Strathmore Shop

Description & Parts Five broken crankcase sensor wire.

Blank lines for description and parts.

Time In: 11:00 Time Out: 15:00 Time spent on job: 1

[Signature]  
Signature