

JOB #	DATE	FLEET ID	CODE	STATUS	DESCRIPTION	NOTES
20003393	25-Mar-15	BLL1458	SERV	Complete	A SERVICE - FORM WS13	scania service
20003593	23-Jan-15	BLL1458	ELEC	Complete	RECTIFY HIGH EMISS LIGHT/ENG WARN LIGHT	SCANIA WARRANTY WORK - RECTIFY HIGH EMISSIONS LIGHT AND ENGINE WARNING LIGHT ON. F-HIGH EMISSION LIGHT AND ENGINE CHECK LIGHT UP ON DASH, BLOWING SMOKE. C - FAULTY INET METERING VALVE. R - REPLACE INLET METERING VALVE. CUSTOMER COMPLAINT, FUEL A
20003815	26-Mar-15	BLL1458	CAB	Complete	FIT FIRE EXTINGUISHER BRACKET	EXTERNAL BRACKET FITTED WITH FIRE EXTINGUISHER AS PER REQUEST. LOCATION IS DRIVERS SIDE REAR ON TOOL BOXES
20004026	22-Apr-15	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20004273	27-Jul-15	BLL1458	SERV	Complete	A SERVICE - FORM WS13	SCANIA SERVICE
20004273	27-Jul-15	BLL1458	SERV	Complete	B SERVICE - FORM WS13	SCANIA SERVICE
20004273	27-Jul-15	BLL1458	SERV	Complete	C SERVICE - TRUCK	scania service
20004308	18-Mar-15	BLL1458	ELEC	Complete	RECTIFY FUEL FAULT COMING UP ON DASH	SCANIA REPAIR - FAULT L.O.P AND BLACK SMOKE, FAULT CODES UP ON DASH EMS CAUSE FAULTY FUEL FLOW METERING VALVE, MEASURING OUTSIDE SPEC AS PER SDP3 AND MULTI. REMEDY REPLACED FAULTY FUEL FLOW METERING VALVE.
20004309	15-Jan-15	BLL1458	ENGI	Complete	REPLACE MISSING TANK CAP AND ORING	SCANIA REPAIR - FAULT LEAKING FUEL FROM DIESEL TANK. CAUSE BLANKING CAP AND ORING MISSING ON TOP OF DIESEL TANK. REMEDY REPLACED CAP AND ORING.
20004562	16-Sep-15	BLL1458		Complete	ADMIN ERROR- CLOSED OUT	
20004704	15-Oct-15	BLL1458	TYRE	Complete	PUNCTURE	steer
20004704	15-Oct-15	BLL1458	TYRE	Complete	STRIP AND FIT	4 x drive tyres
20004713	15-Oct-15	BLL1458	TYRE	Complete	STRIP AND FIT STEERS X 2	
20005021	04-Jan-16	BLL1458	TYRE	Complete	1 X PUNCTURE STRIP AND FIT	
20005361	24-Mar-15	BLL1458	CAB	Complete	FUEL FAULT AT DASH	SCANIA REPLACED FAULTY FUEL FLOW METER
20005362	17-Nov-15	BLL1458	SERV	Complete	A SERVICE - FORM WS13	SCANIA
20005363	16-Feb-16	BLL1458	AIR	Complete	AIR CONDITIONER	SCANIA
20005364	17-Mar-16	BLL1458	SERV	Complete	A SERVICE - FORM WS13	
20005364	17-Mar-16	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20005364	17-Mar-16	BLL1458	SERV	Complete	C SERVICE - TRUCK	SCANIA
20005416	13-Apr-16	BLL1458	TYRE	Complete	1X FLIP ON RIM	
20005709	10-Aug-16	BLL1458	CAB	Complete	AIR BLOWER FOR CAB	AIR BLOWER FOR CAB. DONE BY SCANIA ON THE 21/06/2016 REFER TO RO 20005895
20005709	10-Aug-16	BLL1458	ENGI	Complete	RETARDER NOT WORKING	RETARDER NOT WORKING- DONE BY SCANIA AT SERVICE- 21/06/2016. REFER TO RO 20005895
20005709	10-Aug-16	BLL1458	CHAS	Complete	CRACKS IN BOLSTERS NEED WELDIN	CRACKS IN BOLSTERS REQUIRE WELDING
20005709	10-Aug-16	BLL1458	TYRE	Complete	4 X STEER & 8 X DRIVE TYRES	4 X STEER & 8 X DRIVE TYRES REQUIRED. DONE ON THE 8/07/2016- REFER TO 20005884
20005850	08-Jul-16	BLL1458	GATE	Complete	D/S SWINGING GATE CRACKED	D/S SWINGING GATE CRACKED
20005850	08-Jul-16	BLL1458	CHAS	Complete	RING FEEDER WEAR AND LOOSE	RING FEEDER WEAR AND LOOSE
20005850	08-Jul-16	BLL1458	CHAS	Complete	CRACKS IN PINS	CRACKS IN PINS
20005864	08-Jul-16	BLL1458	TYRE	Complete	8X NEW	
20005895	21-Jun-16	BLL1458	SERV	Complete	A SERVICE - FORM WS13	scania service agreement no cost
20006219	07-Sep-16	BLL1458	SERV	Complete	A SERVICE - FORM WS13	
20006219	07-Sep-16	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20006452	27-Jan-17	BLL1458	CHAS	Complete	RINGFEEDER DAMAGE	RINGFEEDER DAMAGE replaced
20006532	27-Jan-17	BLL1458	SERV	Complete	A SERVICE - FORM WS13	
20006532	27-Jan-17	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20006532	27-Jan-17	BLL1458	TYRE	Complete	ROTATED STEER TYRES	
20006718	24-Mar-17	BLL1458	TYRE	Complete	REAR AXLE TYRES NEED REPLACING	REAR AXLE DRIVE TYRES REQUIRE REPLACING replaced 4 with new tyres
20006806	06-Mar-17	BLL1458	BATT	Complete	REPLACE BATTERIES	
20007026	12-May-17	BLL1458		Complete	AC WORKING ON/OFF	AC WORKING ON/OFF
20007026	12-May-17	BLL1458	ENGI	Complete	RETARDER NOT WORKING	RETARDER NOT WORKING.
20007026	12-May-17	BLL1458	ENGI	Complete	WATER TANK	WATER TANK
20007034	04-May-17	BLL1458	SERV	Complete	A SERVICE - FORM WS13	
20007034	04-May-17	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20007034	04-May-17	BLL1458		Complete	C SERVICE - TRUCK	
20007034	04-May-17	BLL1458	SERV	Complete	D SERVICE - FORM WS13	
20007034	04-May-17	BLL1458	AIR	Complete	AIRCON TEMP SENSOR REPLACED	
20007034	04-May-17	BLL1458	CAB	Complete	WELDED VALVE BRACKET	
20007034	04-May-17	BLL1458	ELEC	Complete	HOOK UP LIGHT AT RINGFEEDER	fitted
20007300	07-Sep-16	BLL1458	TYRE	Complete	DRIVE TYRES NEED REPLACING	DRIVE TYRES NEED REPLACING
20007471	17-Jul-17	BLL1458	ELEC	Complete	FITTED RESERVE LIGHTS	
20007471	17-Jul-17	BLL1458	CHAS	Complete	CREATED BRACKET FOR RESERVE LIGHT	HAD TO MOVE PLATE TO FIT RESERVE LIGHT
20007472	17-Jul-17	BLL1458	TYRE	Complete	4X NEW MICHELIN	
20007543	28-Aug-17	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20007543	28-Aug-17	BLL1458	CHAS	Complete	REPLACED TWIST COCKS X2	
20007543	28-Aug-17	BLL1458	CHAS	Complete	MADE BRACKET FOR AIR VALVE	
20007543	28-Aug-17	BLL1458	ELEC	Complete	FITTED REVERSE LIGHT	
20007592	01-Sep-17	BLL1458	CHAS	Complete	FRONT BOLTS ON FRONT SUBFRAME	FRONT BOLTS ON FRONT SUBFRAME LOOSE
20007592	01-Sep-17	BLL1458	AIR	Complete	AC WORK INTERMITTENTLY	A/C WORKS INTERMITTENTLY
20007747	28-Sep-17	BLL1458	AIR	Complete	A/C NOT WORKING	A/C NOT WORKING
20007747	28-Sep-17	BLL1458	TYRE	Complete	2X STEER TYRES	2X STEER TYRES
20007767	07-Sep-17	BLL1458	TYRE	Complete	REPLACE WITH SPARE TYRES	
20007895	28-Sep-17	BLL1458	CHAS	Complete	WHEEL ALIGNMENT	BRETT STEELE LASER ALIGNMENTS
20007949	28-Sep-17	BLL1458	AIR	Complete	AIRCON COMPRESSOR	STEVE ROSS AUTO AIR- 10PV 24V SCANIA COMP- TOP UP OIL, CHECK BELTS & O RINGS. RECHARGE SYSTEM W/ R134A REFRIGERANT

20008019	02-Feb-18	BLL1458	GATE	Complete	L/H GATE LATCH	L/H LATCH IN SPRING REPLACEMENT
20008035	04-Nov-17	BLL1458	SUSP	Complete	REPLACED BOTTOM SHOCKY BUSH & BOLT	
20008051	07-Nov-17	BLL1458	BATT	Complete	REPLACED BOTH BATTERIES	
20008187	11-Dec-17	BLL1458	SERV	Complete	B SERVICE - FORM WS13	SCANIA
20008420	31-Jan-18	BLL1458	TYRE	Complete	ROTATE STEERS	
20008438	26-Feb-18	BLL1458	TYRE	Complete	2X STEER TYRES (BACK AXLE)	2X STEER TYRES (BACK AXLE)
20008614	26-Feb-18	BLL1458	TYRE	Complete	2X CONTINENTAL	
20009050	29-Jun-18	BLL1458	SERV	Complete	A SERVICE - FORM WS13	
20009129	25-Jun-18	BLL1458	SUSP	Complete	FITTED SHOCKY BOLT TO POSITION 3	
20009251	30-Aug-18	BLL1458	SUSP	Complete	D/S SHOCK ADSORBER LEAKING OIL	D/S SHOCK ADSORBER LEAKING OIL
20009251	30-Aug-18	BLL1458	GATE	Complete	P/S GATE LATCH NEEDS REPLACING	P/S GATE LATCH NEEDS REPLACING
20009251	30-Aug-18	BLL1458	TYRE	Complete	4X DRIVE TYRE NEEDS REPLACING	4X DRIVE TYRE NEEDS REPLACING
20009277	12-Jul-18	BLL1458	TYRE	Complete	ROTATE STEER	
20009388	27-Aug-18	BLL1458	TYRE	Complete	TYRES - 4 X NEW STEER	
20009630	20-Oct-18	BLL1458	TYRE	Complete	FIX SPARE TYRE	FIX SPARE TYRE
20009630	20-Oct-18	BLL1458	TYRE	Complete	2X STEER TYRES	2X STEER TYRES
20009644	22-Oct-18	BLL1458	TYRE	Complete	SERVICE CALLOUT	TYRE EVOLUTION
20009715	23-Oct-18	BLL1458	TYRE	Complete	PUNCTURE REPAIR	
20009749	05-Nov-18	BLL1458	TYRE	Complete	2X NEW TYRES AND 4X ROTATE	
20009771	22-Oct-18	BLL1458	BDWN	Complete	CALLOUT RISELY HILL RD	TYRE EVOLUTION
20009968	11-Dec-18	BLL1458	ENGI	Complete	ENGINE WARNING LIGHT	
20009968	11-Dec-18	BLL1458	GEAR	Complete	MAJORLEAKS IN BELLHOUSING	fault = oil leaks in bellhousing c failed rear main and gearbox input shaft seals r detach prop shafts, remove pipes and hoses, electrical connections, remove gearbox, inspected and found input shaft seal leaking from nose cone, rear main seal leak
20010018	28-Feb-19	BLL1458	ELEC	Complete	3 X CLEARANCE LIGHTS	3 X CLEARANCE LIGHTS NOT WORKING
20010018	28-Feb-19	BLL1458	TYRE	Complete	4 X TYRES ON REAR AXLE	4 X TYRES ON REAR AXLE NEED REPLACING
20010207	08-Feb-19	BLL1458	SERV	Complete	A SERVICE - FORM WS13	
20010207	08-Feb-19	BLL1458	SERV	Complete	B SERVICE - FORM WS13	SCANIA
20010207	08-Feb-19	BLL1458	ENGI	Complete	REPLACE IDLERS, TENSIONERS, BELTS	SCANIA
20010207	08-Feb-19	BLL1458	STER	Complete	REPLACED L/H 2ND STEER TRACK ROD	SCANIA
20010207	08-Feb-19	BLL1458	ENGI	Complete	RECTIFY FRONT CRACK SEAL LEAKING	
20010207	08-Feb-19	BLL1458	ENGI	Complete	REPLACE FRONT ENGINE MOUNTS	
20010233	15-Feb-19	BLL1458	TYRE	Complete	4X NEW TYRE	
20010248	28-Feb-19	BLL1458	ELEC	Complete	3X CLEARANCE LIGHTS	3X CLEARANCE LIGHTS
20010248	28-Feb-19	BLL1458	TYRE	Complete	2X STEER TYRES	2X STEER TYRES
20010390	12-Mar-19	BLL1458	TYRE	Complete	2X CONTINENTAL, 2X ROTATE	
20010453	26-Apr-19	BLL1458	SERV	Complete	A SERVICE - FORM WS13	
20010453	26-Apr-19	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20010453	26-Apr-19	BLL1458		Complete	C SERVICE - TRUCK	
20010453	26-Apr-19	BLL1458	SERV	Complete	D SERVICE - FORM WS13	
20010453	26-Apr-19	BLL1458	ELEC	Complete	REPLACE 3 CLEARANCE LIGHTS	
20010453	26-Apr-19	BLL1458	CHAS	Complete	REPLACE 1 SIDE MARKER	
20010453	26-Apr-19	BLL1458	ENGI	Complete	RELACE AIR FILTER	
20010453	26-Apr-19	BLL1458	SUSP	Complete	REBUSH POSITION 3 SHOCKY	
20010453	26-Apr-19	BLL1458	CHAS	Complete	TIGHTEN UP ALL PTO BOLTS	
20010453	26-Apr-19	BLL1458	CHAS	Complete	FIT 1 PTO BOLT TO PTO	
20010705	17-Jun-19	BLL1458	SERV	Complete	A SERVICE - FORM WS13	
20010705	17-Jun-19	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20010705	17-Jun-19	BLL1458	ELEC	Complete	REPLACE REAR NUMBER PLATE LIGHT	
20010767	04-Jun-19	BLL1458	TYRE	Complete	4X ROTATE UP/ 4X ROTATE DOWN	
20011070	05-Aug-19	BLL1458	SERV	Complete	A SERVICE - FORM WS13	
20011070	05-Aug-19	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20011070	05-Aug-19	BLL1458	CAB	Complete	REPLACE CAB BUMP STOPS	
20011070	05-Aug-19	BLL1458	ELEC	Complete	REPLACE REAR BRAKE LIGHT	
20011070	05-Aug-19	BLL1458	SUSP	Complete	REMOUNT BALL JOINT CLAMP ON 2ND STEER AXLE	
20011089	06-Aug-19	BLL1458	WIND	Complete	S/F WINDSCREEN	NORTHSIDE RACQ
20011136	14-Aug-19	BLL1458	AIR	Complete	A/C NOT WORKING	A/C NOT WORKING
20011172	20-Sep-19	BLL1458	SERV	Complete	A SERVICE - FORM WS13	
20011172	20-Sep-19	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20011172	20-Sep-19	BLL1458	EXHA	Complete	REPLACE EXHAUST PRESSURE SENSOR	
20011172	20-Sep-19	BLL1458	AIR	Complete	REPAIR CHARGE AIR COOLER PIPE	
20011172	20-Sep-19	BLL1458	CHAS	Complete	REPAIR EMERGENCY VALVE BRACKET	
20011172	20-Sep-19	BLL1458	ELEC	Complete	REPAIR LEFT INDICATOR LIGHT	
20011262	09-Sep-19	BLL1458	TYRE	Complete	STEER TYRE REPLACEMENT	STEER TYRES NEED REPLACEMENT
20011283	14-Sep-19	BLL1458	AIR	Complete	AIRCON REPAIRS	STEVE ROSS AUTO AIR
20011310	27-Sep-19	BLL1458	ENGI	Complete	CHECK & REPORT OH HIGH EMISSIONS LIGHT ON	SCANIA
20011313	10-Oct-19	BLL1458	ENGI	Complete	REPORT EMISSION FAULT CODE & CLEAR BLOCKED EGR	SCANIA
20011319	20-Aug-19	BLL1458	CRAN	Complete	FLASHING LED LIGHTS	FLASHING LED LIGHTS
20011377	25-Nov-19	BLL1458	SERV	Complete	A SERVICE - FORM WS13	
20011377	25-Nov-19	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20011377	25-Nov-19	BLL1458	ENGI	Complete	REPLACE HOSE CLAMP GOT EGR BOOTST HOSE	
20011377	25-Nov-19	BLL1458	CAB	Complete	REPLACE WIPER BLADES	
20011508	25-Nov-19	BLL1458	TYRE	Complete	1X PUNCTURE REPAIR	
20011574	11-Dec-19	BLL1458	TYRE	Complete	6X NEW TYRES/ 4X ROTATE	
20011593	13-Dec-19	BLL1458	TYRE	Complete	2X STEER (BACK AXLE)	2X STEER TYRES ON BACK AXLE
20011735	23-Jan-20	BLL1458	SERV	Complete	A SERVICE - FORM WS13	
20011735	23-Jan-20	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20011735	23-Jan-20	BLL1458	ENGI	Complete	REPLACE HOSE CLAMPS ON EGR HOSE	
20011735	23-Jan-20	BLL1458	ELEC	Complete	REPAIR CLEARANCE LIGHT BRACKET	
20011735	23-Jan-20	BLL1458	CAB	Complete	REPLACE POS 1 AIRBAG	
20011741	20-Jan-20	BLL1458	CHAS	Complete	TRUCK LOSING AIR O/NIGHT	TRUCK LOSING AIR O/NIGHT
20011813	12-Feb-20	BLL1458	CHAS	Complete	CAB TILT BAR MISSING	CAB TILT BAR MISSING
20011946	11-Mar-20	BLL1458	SERV	Complete	A SERVICE - FORM WS13	
20011946	11-Mar-20	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20011946	11-Mar-20	BLL1458	ELEC	Complete	REPLACE STOP & PARK LIGHT BULBS	
20011946	11-Mar-20	BLL1458	ENGI	Complete	REPLACED EGR COOLER HOSE CLAMPS	

20011946	11-Mar-20	BLL1458	COOL	Complete	AIR LEAK BYPASS AIRDRYER LINE	
20012103	28-Apr-20	BLL1458	SERV	Complete	A SERVICE - FORM WS13	
20012103	28-Apr-20	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20012103	28-Apr-20	BLL1458		Complete	C SERVICE - TRUCK	
20012103	28-Apr-20	BLL1458	SERV	Complete	D SERVICE - FORM WS13	
20012146	05-May-20	BLL1458		Complete	ADMIN CLOSED OUT	
20012236	14-May-20	BLL1458	BATT	Complete	REPLACED 2X BATTERIES	
20012252	22-Jun-20	BLL1458	SUSP	Complete	BOOST LEAK	BOOST LEAK
20012252	22-Jun-20	BLL1458	TYRE	Complete	2X STEER TYRES	2X STEER TYRES BACK AXLE
20012319	29-May-20	BLL1458	EXHA	Complete	EXCESSIVE EXHAUST BLACK SMOKE	EXCESSIVE EXHAUST BLACK SMOKE
20012346	04-Jun-20	BLL1458	SERV	Complete	A SERVICE - FORM WS13	
20012346	04-Jun-20	BLL1458	SERV	Complete	B SERVICE - FORM WS13	SCANIA
20012383	22-Jun-20	BLL1458	TYRE	Complete	2X HANKOOK/ 1X ROTATE	
20012434	19-Jun-20	BLL1458	BATT	Complete	BATTERY BOILING- NEW BATTERY & ALTERNATOR	SCANIA
20012531	27-Jul-20	BLL1458	SERV	Complete	A SERVICE - FORM WS13	
20012531	27-Jul-20	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20012531	27-Jul-20	BLL1458	ENGI	Complete	REPLACED EGR SILICON HOSES	
20012531	27-Jul-20	BLL1458	CHAS	Complete	REPLACED TOW HITCH W/ NEW RING FEEDER	
20012538	27-Jul-20	BLL1458	CHAS	Complete	RING FEEDER NEEDS REPLACING	RING FEEDER NEEDS REPLACING
20012542	21-Jul-20	BLL1458		Complete	ADMIN ERROR- CLOSED OUT	
20012767	17-Sep-20	BLL1458	SERV	Complete	A SERVICE - FORM WS13	
20012767	17-Sep-20	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20012793	17-Sep-20	BLL1458	WIND	Complete	SUPPLY AND FIT WINDSCREEN	
20012829	29-Sep-20	BLL1458	TYRE	Complete	REAR AXLE TYRES	REAR AXLE TYRE COMING UP REPLACEMENT
20012829	29-Sep-20	BLL1458	CAB	Complete	LEAKING REAR AIRBAG	LEAKING REAR AIRBAG
20012857	17-Sep-20	BLL1458	CHAS	Complete	2X MUDFLAPS REPAIRS	2X MUDFLAP REPAIRS- 1X MISSING 1X CRACKED. REPAIRED DURING SERVICE
20013036	16-Nov-20	BLL1458	TYRE	Complete	8X DRIVE TYRE	8X DRIVE TYRES/ 2X STEER TYRE
20013057	13-Nov-20	BLL1458	COOL	Complete	COOLANT LEAK AT HEADER TANK	COOLANT LEAK AT HEADER TANK
20013064	16-Nov-20	BLL1458	TYRE	Complete	8X NEW TYRES	
20013071	16-Nov-20	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20013071	16-Nov-20	BLL1458	SUSP	Complete	REPLACE SWAY BAR BUSHES FIRST STEER	
20013071	16-Nov-20	BLL1458	CHAS	Complete	REPLACE AIR BAG FRIST DRIVE RHS	
20013071	16-Nov-20	BLL1458	STER	Complete	REPLACE DRAG LINK SECOND STEER	
20013207	11-Dec-20	BLL1458	CAB	Complete	CAB MOUNTS & CAB TILT RAM	CAB MOUNTS & CAB TILT RAM NEED REPLACING
20013208	16-Dec-20	BLL1458	ENGI	Complete	REPLACE HOSES	HOSES ON CRANE NEED REPLACING. REPAIRED DURING SERVICE
20013208	16-Dec-20	BLL1458	CAB	Complete	FRONT AIRBAG NEED REPLACING	FRONT AIRBAG NEED REPLACING. REPAIRED DURING SERVICE
20013267	04-Jan-21	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20013267	04-Jan-21	BLL1458	AXLE	Complete	REPLACED 1ST AXLE STEER AIR BAG	
20013267	04-Jan-21	BLL1458	CAB	Complete	REPLACED CAB TILT CYLINDER	
20013267	04-Jan-21	BLL1458	COOL	Complete	REPLACE EGR COOL HOSE CLAMP	
20013344	22-Dec-20	BLL1458	TYRE	Complete	S/F ROTATE ALL DRIVE TYRES	
20013445	16-Mar-21	BLL1458	ELEC	Complete	BATTERY CHARGER	BATTERY CHARGER FPR CRANE REMOTE ONLY WHEN CRANE IN ON. REPAIRED DURING SERVICE
20013450	11-Jan-21	BLL1458	ENGI	Complete	REMOVE, MANUFACTURE & RFIT 2X LEG HOSES	RYCO- Remove, manufacture and refit 2x stabilizer leg hoses, control valve hose and re-end main return lin3 back to cooling fan.
20013537	25-Feb-21	BLL1458	AIR	Complete	A/C NOT WORKING	OS1- 465-VGM Scania 697502 A/c not working Test a/c found the compressor clutch was faulty. Supplied and fitted new compressor and serviced system. re-gased tested all ok.
20013549	04-Mar-21	BLL1458	ENGI	Complete	CHECK & REPORT ON HIGH EMISSIONS LIGHT	SCANIA- CHECK AND REPORT ON HIGH EMISSIONS LIGHT F- Mass flow sensor faults C- Blocked air filter R- Checked operation, checked fault codes. Checked mass flow sensor, checked exhaust gas pressure sensor, checked combination sensor. Checked air fi
20013612	26-Mar-21	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20013663	01-Apr-21	BLL1458	ENGI	Complete	REPLACED ECA UNIT, TORQUE ROD BUSHES & TCM CONTROL	SCANIA- DIAGNOSE AND REPLACE FAULTING ECA UNIT F: Diagnose and replace faulting ECA unit C: Short circuit in ECA unit R: Inspected fault codes and found active faults for short circuit for the ECA, road tested and truck didnt fault, quoted, remov
20013737	27-Apr-21	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20013737	27-Apr-21	BLL1458	SERV	Complete	D SERVICE - FORM WS13	replaced clutch shift sensors thermostats spigot bearing and clutch for assembly sway bar bushes test drove
20013818	04-Oct-21	BLL1458	CAB	Complete	BACK AIR BAG NOT LEVELING	BACK AIR BAG NOT LEVELING
20013818	04-Oct-21	BLL1458	WIND	Complete	CRACK IN WINDSCREEN	CRACK IN WINDSCREEN
20013930	16-Jun-21	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20014166	04-Aug-21	BLL1458	BDWN	Complete	BOOST LEAK UNDER ACCELERATION	TMW QLD- Reports of a boost leak under acceleration. Inspected over the intake and found a worn dive clamp on the intercooler hose had broken. Removed and replace hose clamp with bolt up clamp.
20014186	16-Aug-21	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20014186	16-Aug-21	BLL1458	GATE	Complete	GATES POCKET LATCH REMOVED & REWELDED	
20014186	16-Aug-21	BLL1458	ENGI	Complete	REPLACED ENGINE AIRLINE	
20014186	16-Aug-21	BLL1458	CHAS	Complete	REPLACE REFLECTORS	

20014210	04-Aug-21	BLL1458	SERV	Complete	B SERVICE - FORM WS13	Reports of a boost leak under acceleration. Inspected over the intake and found a worn dive clamp on the intercooler hose had broken. Removed and replace hose clamp with bolt up clamp. Consumables B SERVICE
20014370	24-Sep-21	BLL1458	WIND	Complete	WINDSCREEN CRACKED	WINDSCREEN CRACKED ON DRIVERS SIDE
20014381	24-Sep-21	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20014381	24-Sep-21	BLL1458	TYRE	Complete	REPLACED DRIVE AXLE TYRES (4X)	
20014381	24-Sep-21	BLL1458	ELEC	Complete	REPLACED RESERVE SPOT LIGHT	
20014381	24-Sep-21	BLL1458	ENGI	Complete	REPLACED PVC CLAMPS	
20014506	13-Oct-21	BLL1458	ELEC	Complete	LHS HEAD LIGHT NOT WORKING	LHS HEAD LIGHT NOT WORKING
20014546	04-Nov-21	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20014598	05-Nov-21	BLL1458	TYRE	Complete	X2 MAXI TYRES X2 ROTATE DOWN	
20014723	29-Nov-21	BLL1458	ELEC	Complete	RHS HEADLIGHT NOT WORKING	RHS HEADLIGHT NOT WORKING
20014839	05-Jan-22	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20014839	05-Jan-22	BLL1458	CHAS	Complete	REPLACED HEADER TANK	
20014870	18-Jan-22	BLL1458		Complete	ADMIN- CLOSED OUT	
20014881	16-Jan-22	BLL1458	SERV	Complete	B SERVICE - FORM WS13	CHECK AND RPEORT ON RETARDER LEAKING FROM BLEED PIPE F- Check and report on retarder leaking from bleed pipe C- Accumulator seals leaking and valve psiton seals R- Drained coolent and retarder oil. disconnected retarder cooling pipes and removed r
20014906	- -	BLL1458		In-Complete	TOOLBOX P/S REPLACEMENT	TOOLBOX ON P/S OF TRUCK NEEDS REPLACEMENT
20015335	23-May-22	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20015335	23-May-22	BLL1458	SERV	Complete	D SERVICE - FORM WS13	
20015350	23-May-22	BLL1458	ELEC	Complete	CLEARANCE LIGHT NOT WORKING	CLEARANCE LIGHT ON SUNVISOR LHS NOT WORKING
20015411	20-May-22	BLL1458	TYRE	Complete	2X ROATE/ 10X NEW TYRE	
20015517	18-Jul-22	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20015544	18-Jul-22	BLL1458	CHAS	Complete	REPLACE DAMAGED TOOLBOX	Replace damaged tool box
20015704	02-Sep-22	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20015806	18-Oct-22	BLL1458	BDWN	Complete	BREAKDOWN- ENGINE NOISE. ALTERNATOR LIGHT	ALL ABOUT DIESEL SERVICES
20015858	18-Nov-22	BLL1458	SERV	Complete	B SERVICE - FORM WS13	TREY- 4 HOURS
20015920	25-Nov-22	BLL1458	BDWN	Complete	BREAKDOWN- RADIATOR BLOCKED	MTR- 25/11/2022- Get coolant and water and travel to truck on Toowoomba old range, jack cab over and inspect coolant hose, found radiator to be blocked, top coolant up, tell drive how to use manual mode in truck and return to workshop.
20016020	16-Jan-23	BLL1458	TYRE	Complete	SWAP FRONT STERS WITH BLL1457	
20016090	24-Feb-23	BLL1458	BDWN	Complete	BREAKDOWN- BLOWN COORDINATOR FUSE	BLOWN COORDINATOR FUSE Travel to truck located Bruce Highway Yeppen Roundabout bypass. Start truck, build air. COO fuse blew. Reset fuse and started truck. Blowing fuse for Coordinator. Fuse 21, 20-amp manual circuit breaker. Put scanner on tr
20016139	15-Mar-23	BLL1458	SERV	Complete	B SERVICE - FORM WS13 + OTHER	CONFIRM INJECTOR FAULTS PERFORM "M" SERVICE 3RD AXLE BRAKE IMBALANCE - TO BE ASSESSED FOR BRAKE CHAMBER OR CALIPER FAULT OIL PRESSURE SENSOR LEAKING ENGINE AIR FILTER BLOCKED OIL FILTER BEARING MISSING
20016187	22-Feb-23	BLL1458	BDWN	Complete	TRUCK NOT STARTING- B/DOWN	RCM- 15/02/23 Travelled to Church St and inspected truck not starting. Checked batteries and fuses, found blown fuse for starter lockout. Replaced fuse and blew straight away once ignition was turned on. Lifted up cab and checked wiring, removed
20016198	27-Mar-23	BLL1458	ENGI	Complete	REPLACED ALL INJECTORS	SCANIA- REPLACE ALL INJECTORS - CUSTOMERS REQUEST F: Replace all injetors- customer request C: Customer requested R: Removed rocker covers, removed fuel lines, removed injector and injector pencil, changed injectors refitted injector pencils, ref
20016324	20-May-23	BLL1458	TYRE	Complete	2X NEW (STEER)/ 8X NEW HAULMAX	
20016346	04-Jun-23	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20016346	04-Jun-23	BLL1458	SERV	Complete	D SERVICE - FORM WS13	FEZ= 4.5 HRS PAT= 4.5 HRS
20016400	05-Jun-23	BLL1458	ENGI	Complete	PRESSURE LINE TO PUMP	POWER FLOW- Pressure line to pump
20016401	06-Jun-23	BLL1458	WIND	Complete	REPAIR FRONT	Northside Windscreens
20016580	23-Aug-23	BLL1458	SERV	Complete	B SERVICE - FORM WS13	MAT PITURA
20016580	23-Aug-23	BLL1458	CAB	Complete	FITTED CAB JACK LINE	MATT PITURA
20016580	23-Aug-23	BLL1458	ENGI	Complete	REPLACED RADIATOR	MATT PITURA
20016580	23-Aug-23	BLL1458	CHAS	Complete	FIXED AIR LINE	
20016665	23-Aug-23	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20016730	03-Nov-23	BLL1458	TYRE	Complete	3X NEW TYRE (STEER)	
20016756	16-Oct-23	BLL1458	SERV	Complete	B SERVICE - FORM WS13	
20016817	26-Nov-23	BLL1458	BDWN	Complete	ATTEND BREAKDOWN	SCANIA- ATTEND BREAKDOWN SIMMONS LOGISTICS 80 LEITCHES ROAD, BRENDAL QLD 4500 NEEDS COORDINATOR RE-PROGRAMMING ENGINE LIGHT ON DASH - RENEW PROPORTIONAL VALVE AND T124 POSITION SENSOR F: Check and report on egr fault C: Failed valve block and
20016848	03-Jan-24	BLL1458	TYRE	Complete	1X 2ND HAND TYRE	