



Vehicle History Detail

Fleet #	
Registration	
Make	SCANIA
Model	R620
VIN / Chassis #	YS2R6X40005504246

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
24/07/2026	1,314,215 kms	DECOMMISSION R-65852 Decommissioning- replaced two batteries with new batteries. 1314215km			\$462.00
01/07/2026		SPRING EYE BUSHES, STEER AXLE R-56293 TRUCK HAS BEEN SELECTED TO BE SOLD. TAKEN TO INGLEBURN 1/7/26			\$0.00
01/07/2026		RUNNING HOT R-58194 TRUCK HAS BEEN SELECTED TO BE SOLD. TAKEN TO INGLEBURN 1/7/26			\$154.00
01/07/2026		DTC CODES R-52828 TRUCK HAS BEEN SELECTED TO BE SOLD. TAKEN TO INGLEBURN 1/7/26			\$0.00
01/07/2026		EXHAUST CLAMP R-62106 TRUCK HAS BEEN SELECTED TO BE SOLD. TAKEN TO INGLEBURN 1/7/26			\$77.00
01/07/2026		A/C, FAULT REPORT, HEATER R-48650 TRUCK HAS BEEN SELECTED TO BE SOLD. TAKEN TO INGLEBURN 1/7/26			\$154.00
30/06/2026	1,313,757 kms	A - 10K/90Days S-31205 (A) SERVICE CARRIED OUT BY CHOMBA ISSA SERGIO KMS 1313757			\$308.00
30/06/2026	1,313,757 kms	SWAP TYRES T-17836 TYRE CHANGES ISSA CHOMBA SERGIO KMS 1313757			\$346.50
25/06/2026	1,312,364 kms	EMISSIONS HIGH, STEERING SHAKING R-63692 TRUCK HAS BEEN SELECTED TO BE SOLD. TAKEN TO INGLEBURN 1/7/26			\$731.24
10/06/2026	1,309,577 kms	BATTERIES FAILED R-63686 REPLACED WITH SPARE USED BATTERY			\$154.00
05/06/2026		BROKEN TAIL LIGHT R-62524 REPLACED			\$597.52
04/06/2026		NEW DRIVE TYRES, RUNOUTS T-17400 HD602 X4 - TYRE CHANGES JUSTICE BRETT KMS			\$1,452.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
30/05/2026	1,305,253 kms	RUNOUT T-17328 TYRE CHANGES SERGIO KMS 1305253			\$0.00
30/05/2026	1,305,253 kms	LIGHT INOP R-62673 DUPLICATE			\$1.54
30/05/2026	1,305,253 kms	LIGHT INOP R-62672 REPLACED			\$282.37
27/05/2026	1,304,608 kms	HEADLIGHT BULB R-62483 REPLACED			\$85.87
25/05/2026	1,303,812 kms	B - 20K/180Days S-30553 (B) SERVICE CARRIED OUT BY MICK JUSTICE KMS 1303812			\$345.40
19/05/2026	1,301,617 kms	RUNOUT T-17207 TYRE CHANGES BRETT KMS 1301617			\$231.00
13/05/2026	1,298,909 kms	RUNOUT T-17132 TYRE CHANGES JUSTICE KMS 1298909			\$115.50
06/05/2026	1,296,299 kms	EXHAUST MANIFOLD LEAK R-61112 REPAIRED & REPLACED			\$1,765.76
29/04/2026	1,295,006 kms	RUNOUTS T-16973 REPLACED WITH R/O			\$539.00
29/04/2026	1,295,006 kms	TURNTABLE R-60899 CLEANED			\$154.00
21/04/2026	1,292,148 kms	A - 10K/90Days S-29650 (A) SERVICE CARRIED OUT BY ISSA CHOMBA SERGIO KMS 1292148			\$693.00
21/04/2026	1,292,148 kms	AIR LEAK, CHECK TURNTABLE R-60518 REPAIRED & REPLACED			\$332.16
21/04/2026	1,292,148 kms	TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS I-2856 ANNUAL INSPECTION CARRIED OUT BY SERGIO ISSA CHOMBA KMS 1292148			\$231.00
21/04/2026	1,292,148 kms	TYRE PUNCTURED T-16868 TYRE REPAIRED ISSA CHOMBA SERGIO KMS 1292148			\$115.50
15/04/2026	1,289,738 kms	NEW STEERS T-16890 TYRE CHANGES COOPER KMS 1289738			\$1,335.49
15/04/2026	1,289,738 kms	HEADLIGHT OUT R-60202 REPLACED			\$169.39
02/04/2026	1,284,935 kms	LIGHT BULBS R-59777 REPLACED			\$78.25

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
02/04/2026	1,284,935 kms	RUNOUT, STEER TYRE T-16738 TYRE CHANGES JUSTICE KMS 1284935			\$77.00
31/03/2026	1,284,099 kms	BRAKE LIGHT ISSUE R-59471 NO ACTION REQUIRED.			\$77.00
25/03/2026	1,281,920 kms	BRAKE LIGHT ISSUE R-59287 REPLACED FUSE BRETT KMS 1281920			\$77.00
24/03/2026	1,281,749 kms	B - 20K/180Days S-28950 (B) SERVICE CARRIED OUT BY ISSA CHOMBA SERGIO KMS 1281749			\$460.90
25/02/2026	1,274,196 kms	FOG LIGHT, SPOT LIGHT R-56292			\$594.00
25/02/2026	1,274,196 kms	BROKEN BOLT R-57646			\$77.00
24/02/2026	1,274,190 kms	AIR BAG, CABIN, REPAIRS, SHOCK R-57588			\$2,764.25
23/02/2026	1,274,147 kms	SPRING EYE BUSHES R-57511			\$3,708.35
22/02/2026	1,274,121 kms	BRACKET, CHECK STEERING, DIFF OIL, EXHAUST R-57436			\$924.00
22/02/2026	1,274,121 kms	RUNOUTS T-15758 TYRE CHANGES PAT CHOMBA SERGIO LKMS 1274121			\$346.50
17/02/2026	1,272,010 kms	FLAT TYRE T-15680 REMOVED REPAIRED REFITTED TYRE BRETT KMS 1272010			\$154.00
16/02/2026	1,271,705 kms	RUNOUT T-15682 TYRE CHANGES CHOMBA SERGIO KMS 1271705			\$308.00
16/02/2026	1,271,705 kms	A - 10K/90Days S-28142 (A) SERVICE CARRIED OUT BY CHOMBA SERGIO KMS 1271705			\$308.00
17/01/2026	1,260,277 kms	C - 100K/365Days S-27475 (C) SERVICE CARRIED OUT BY JUSTICE CHOMBA KMS 1260277 CHANGED CAB FILTER AIR FILTER	SCANIA AUSTRALIA 10 - 52157		\$1,461.52
17/01/2026	1,260,277 kms	HEAD LAMP R-55697			\$101.02
17/01/2026	1,260,277 kms	RUNOUT T-15519 TYRE CHANGES JUSTICE CHOMBA SERGIO KMS 1260927			\$346.50
06/01/2026	1,256,582 kms	GREASE TURNTABLE R-55208			\$77.00
02/01/2026	1,256,065 kms	CHECK WIPERS R-54711			\$161.59
18/12/2025	1,252,305 kms	CAB FILTER R-54246			\$107.71
04/12/2025	1,248,959 kms	A - 10K/90Days S-26590 (A) SERVICE CARRIED OUT BY CHOMBA JUSTICE KMS 1248959 REPLACED BLINKER BULBS			\$247.15

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
04/12/2025	1,248,959 kms	RUNOUT T-14886 TYRE CHANGES JUSTICE KMS 1248959			\$77.00
17/11/2025	1,246,806 kms	SPEED SENSOR R-46860 NB replaced spd sensor didn't work, ran truck out to GTR. 23/7			\$7,950.52
17/10/2025		DIPSTICK R-46918	SCANIA AUSTRALIA 10 - 52157		\$250.36
08/10/2025	1,242,839 kms	KNOCKING NOISE R-49161			\$2,901.29
23/09/2025		FIRE EXTINGUISHER R-46993			\$0.00
22/09/2025	1,238,772 kms	B - 20K/180Days S-25049 (B) SERVICE CARRIED OUT BY JUSTICE KMS 1238772 REPLACED LIGHT BULBS - FOG LIGHT, RHS BLINKER			\$751.91
09/09/2025	1,235,433 kms	steering stiff R-49218			\$1,425.60
08/09/2025	1,235,226 kms	STEER TYRES T-13850 INSPECTED TYRES REMOVED AND BALANCED LHS TYRE. RHS TYRE TO BE OUT OF ROUND, REPLACED WITH USED TYRE FROM MQP241 BRETT KMS 1235226			\$154.00
09/08/2025	1,226,195 kms	OBD SOCKET R-49077	GLEN ARTNEY TRUCK REPAIRS PTY LTD - 10		\$360.61
08/08/2025		SUZY AIR FITTING R-47731			\$115.50
23/07/2025		FRONT SHOCKS, GEARBOX MOUNTS, KING PINS, SHACKLE PINS, SPOT LIGHT R-42766			\$2,581.81
23/07/2025	1,225,614 kms	A - 10K/90Days S-23812 (A) SERVICE CARRIED OUT BY MICK, COOPER KMS 1225614			\$385.00
14/07/2025	1,224,868 kms	BROKEN MUDGUARD R-46682			\$314.82
17/04/2025	1,219,104 kms	TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS I-2239 ANNUAL INSPECTION CARRIED OUT BY MICK COOPER			\$0.00
27/03/2025	1,217,988 kms	TRAILER PLUG R-41650			\$77.00
19/03/2025	1,217,784 kms	PARK ALARM R-41553			\$539.00
11/03/2025	1,217,749 kms	CAB AIRBAG R-40801			\$723.75
10/03/2025	1,217,607 kms	CHECK ENGINE LIGHT R-40385 TRUCK TO BE INSPECTED BY SCANIA			\$847.00
05/03/2025	1,216,229 kms	ROTATION T-11693 5/3 - COOP HELPED			\$308.00
05/03/2025	1,216,229 kms	COOLANT LEAK R-39879			\$902.77

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
05/03/2025	1,216,229 kms	B - 20K/180Days S-21029 (B) SERVICE CARRIED OUT BY JUSTICE, COOP. BRETT KMS 1216229 REPLACED SIDE STEP BLINKER RHS REPLACED CAB FILTER			\$914.81
21/02/2025	1,213,441 kms	NEW TYRE, ROTATION T-11627 TYRE CHANGES SHANE KMS 1213441			\$1,458.00
09/02/2025	1,208,319 kms	AIR BAG LEAK R-39020			\$411.03
31/01/2025	1,205,678 kms	RUNOUT T-11409 TYRE CHANGES SHANE KMS 22942			\$154.00
31/01/2025	1,205,678 kms	A - 10K/90Days S-20313 (A) SERVICE CARRIED OUT BY JUSTICE , KMS 1205678 REPLACED FRONT CAB BUMP STOPA X2 FITTED NEW SIDE FLHS INDICATOR BULB			\$505.89
24/01/2025	1,203,588 kms	NEW TYRE T-11203 TYRE CHANGES SHANE KMS 1203588			\$687.00
31/12/2024		CHECK CODES R-37787			\$462.00
23/12/2024	1,193,912 kms	B - 20K/180Days S-19757 (B) SERVICE CARRIED OUT BY JUSTICE AND MICK KMS 1193912 CAMERA OK			\$576.07
18/12/2024	1,192,450 kms	FAULTY SENSOR R-37275			\$1,133.99
20/11/2024	1,183,962 kms	A - 10K/90Days S-19077 (A) SERVICE CARRIED OUT BY MICK, BRETT, JARRAH KMS 1183962 REPLACED CAB BUMP STOPS CAMERA OK..			\$410.52
18/10/2024	1,173,339 kms	B - 20K/180Days S-18438 (B) SERVICE CARRIED OUT BY JUSTICE, BRETT, JARRAH KMS 1173339 PLAY IN LHS STEER AXLE KING PIN			\$961.07
18/10/2024	1,173,339 kms	NEW STEERS, RUNOUTS T-9930 TYRE CHANGES SHANE KMS 1173339			\$1,451.00
15/10/2024	1,171,553 kms	BRAKE ISSUE R-34317 ALL OK			\$154.00
30/09/2024	1,166,838 kms	PANEL LOOSE R-33621			\$231.00
30/09/2024	1,166,839 kms	GEARBOX REAR SEAL R-32968 REPLACED			\$1,765.28
17/09/2024	1,164,189 kms	LIGHT OUT R-33150 REPLACED BULB			\$101.02
13/09/2024	1,163,497 kms	LIGHTS OUT R-33052 REPLACED BULB			\$126.70

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
11/09/2024	1,162,377 kms	A - 10K/90Days S-17696 (A) SERVICE CARRIED OUT BY JUSTICE, MICK, EDWIN KMS 1162377			\$346.50
11/09/2024	1,162,377 kms	TURNTABLE R-32967 REKIT			\$992.08
28/08/2024		BLINKER BULB R-32257 REPLACED BULB			\$53.10
08/08/2024	1,151,973 kms	CHECK ENGINE LIGHT R-26722 FIXED			\$3,427.77
06/08/2024		BRAKE LIGHT R-31112 REPAIRED			\$38.50
06/08/2024	1,151,577 kms	EXHAUST R-31114 REPAIRED			\$231.00
31/07/2024	1,151,114 kms	RETARDER ISSUE R-29972 REPAIRED		57580	\$8,409.89
16/07/2024	1,150,448 kms	B - 20K/180Days S-15953 (B) SERVICE CARRIED OUT BY MICK, JUSTICE KMS 1150448 LHS OUTER FOG LIGHT BULB LHS WASHER BROKEN REPLACED SQUIRTER			\$390.60
07/07/2024	1,148,275 kms	LIGHT OUT R-29998 REPLACED BULB			\$101.02
25/06/2024	1,142,165 kms	ENGINE LIGHT ON R-23196 FIXED UNDER R 26722 AT GTR			\$0.00
17/06/2024	1,139,046 kms	A - 10K/90Days S-15213 (A) SERVICE CARRIED OUT BY BRETT, JARRAH, KMS 1139046 REPLACED BULB FOG LIGHT 48701			\$637.00
27/05/2024	1,132,097 kms	B - 20K/180Days S-14825 (B) SERVICE CARRIED OUT BY EDWIN, BRETT, MICK KMS 1132097 NO ISSUES RAISED			\$576.07
27/05/2024	1,132,097 kms	NEW TYRE, ROTATE TYRES, TYRE FLIP T-8366 TYRE CHANGES STUART KMS 1132097			\$231.00
24/05/2024	1,130,343 kms	HEADLIGHT R-23196 REPLACED BULB			\$74.84
07/05/2024	1,122,143 kms	FUEL LEAK, KING PINS R-23320 REPAIRED			\$2,455.46
07/05/2024	1,122,143 kms	OIL LEAK R-26907 REPAIRED			\$673.09

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
07/05/2024	1,122,134 kms	A - 10K/90Days S-14419 (A) SERVICE CARRIED OUT BY EDWIN, JUSTICE, JARRAH KMS 1122134 FITTED HEADLIGHT HIGH BEAM BULB			\$352.10
18/04/2024	1,112,267 kms	C - 100K/365Days S-14025 (B/C) SERVICE CARRIED OUT BY MICK, DANNY, JUSTICE KMS 1112267 REPLACED FILTERS AND OIL, ENGINE OIL, FUEL FILTERS, AIR CLEANER - GBOX O&F, RETARDER O&F, DIFFS, O&F, ADBLUE FILTER, P.S. FILTER, DRYER FILTER.			\$1,595.53
18/04/2024	1,112,267 kms	TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS I-1540 ANNUAL INSPECTION CARRIED OUT BY MICK KMS 1112267 NO ISSUES RAISED			\$0.00
17/04/2024	1,111,145 kms	REPLACE BATTERY R-26125 REPLACED			\$1,100.22
08/04/2024	1,106,000 kms	OIL LEAK R-25771 FIXED			\$77.00
25/03/2024		KING PIN R-21803 FOUND KING PIN PO MISSING IN REPAIRS ADDED IT IN HERE BP..			\$926.70
25/03/2024	1,101,733 kms	A - 10K/90Days S-13589 (A) SERVICE CARRIED OUT BY MICK RHRSR AIR BAG LEAKING			\$903.98
25/03/2024	1,101,733 kms	NEW TYRE T-7625 TYRE CHANGES STUART KMS 1101733			\$1,104.69
21/03/2024	1,099,778 kms	HEADLIGHT OUT R-25120 fixed			\$104.10
14/03/2024	1,096,238 kms	HEADLIGHT LENS, HEADLIGHT PROTECTOR R-22668			\$509.50
13/03/2024	1,045,349 kms	BRAKE LININGS, DOWN ON POWER R-30193			\$704.17
26/02/2024	1,091,553 kms	B - 20K/180Days S-13093 (B) SERVICE CARRIED OUT BY MICK AND JUSTICE KMS 1091553 CHECK AND CLEAN PLUGS FOR BRAKE CALIPERS NOTED R 23320 -MOVEMENT IN LHS KING PIN -TOP RHS KING PIN NOT TAKING MUCH GREASE - SMALL AIR LEAK FROM CAB RHRSR AIR BAG -FUEL LEAK AT MOTOR			\$576.07
15/02/2024		HOSE R-23564			\$398.98
08/02/2024	1,080,399 kms	A - 10K/90Days S-12737 (A) SERVICE CARRIED OUT BY MICK KMS 1080399 REPLACED LHS CORNER BLINKER BULB			\$399.60
24/01/2024	1,074,216 kms	EMMISSIONS FAULT R-23102	GLEN ARTNEY TRUCK REPAIRS PTY LTD - 16		\$2,146.93
23/01/2024		BREAKDOWN R-24899	TRUCKSMART PTY LTD - 16		\$1,174.62

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
10/01/2024	1,067,418 kms	B - 20K/180Days S-12004 (A) SERVICE CARRID OUT BY EDWIN AND MICK KMS 1067418 FITTED NEW PARK LIGHT ON LHS OF BULLBAR			\$494.40
10/01/2024	1,067,397 kms	FRIDGE, HEADLIGHT R-22192			\$88.73
10/01/2024	1,067,418 kms	RUNOUT T-6461 TYRE CHANGE STUART KMS 1067418			\$38.50
08/12/2023	1,052,722 kms	A - 10K/90Days S-11626 (A) SERVICE CARRIED OUT BY EDWIN AND MICK KMS 1052722 CAB BUMP STOPS X2			\$410.52
23/11/2023	1,043,308 kms	HEADLIGHT BLOWN R-20458			\$61.51
20/11/2023	1,040,969 kms	B - 20K/180Days S-11344 (B) SERVICE CARRIED OUT BY MICK, JUSTICE KMS 1040969 NO ISSUES RAISED			\$417.40
15/11/2023		BREAKDOWN R-20101 WORK CARRIED OUT BY TRUCKSMART -	TRUCKSMART PTY LTD - 10		\$638.33
13/11/2023	1,037,657 kms	WINDSCREEN DAMAGED R-20099	WINDSCREENS OBRIEN (OBRIEN GLASS) - 10		\$1,294.00
06/11/2023	1,034,127 kms	A - 10K/90Days S-10971 (A) SERVICE CARRIED OUT BY MICK, EDWIN KMS 1034127 NO ISSUES RAISED			\$385.00
06/11/2023	1,034,125 kms	BULLBAR BLINKER R-19695			\$149.60
20/10/2023	1,023,438 kms	BRAKE WARNING ON DASH R-19896			\$77.00
10/10/2023	1,018,191 kms	C - 100K/365Days S-10553 (C/B) SERVICE CARRIED OUT BY DANNY, MICK, EDWIN KMS 1018191 NOT DONE - RETARTER HAS JUST BEEN REBUILT			\$1,287.03
20/09/2023		FRONT WHEEL BEARINGS R-17923			\$1,648.57
20/09/2023	1,010,079 kms	A - 10K/90Days S-10319 (A) SERVICE CARRIED OUT BY MICK KMS 1010079 RHS STEER WHEEL BEARING NEEDS DOING "NOISY" R 17923, PO 19058			\$385.00
11/09/2023	1,004,385 kms	KING PIN, TURNTABLE R-16620			\$3,192.20
01/09/2023		RETARDER MALFUNCTION R-18228 GTR CARRIED OUT WORK TO REPLACE RETARDER AND FITTED DRIVE SHAFT TIGHTEN AND TENSIONED WITH NEW BOLTS, TEST DROVE ALL OK	GLEN ARTNEY TRUCK REPAIRS PTY LTD - 16		\$12,490.24
28/08/2023	1,003,801 kms	BROKEN EBS PLUG R-17216			\$204.71
20/08/2023	997,267 kms	B - 20K/180Days S-9680 (B) SERVICE CARRIED OUT BY PAT AND JUSTICE NO ISSUES RAISED			\$1,187.40
16/08/2023	994,253 kms	LIGHTS INOP R-16871			\$130.66

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
15/08/2023		HEATER NOT WORKING R-15403 HURCUM REMOVED AIRCONDITIONER COVERS & HEATER TAP AND CHECK TAP FOR CORRECT OPERATION	HURCUM AUTO ELECTRICS - 16		\$264.00
07/08/2023	987,677 kms	A - 10K/90Days S-9484 (A) SERVICE CARRIED OUT BY MICK AND JUSTICE KMS 987677 STEP BLINKER OUT RHS - FIXED INPUT SHAFT SEAL ON REAR DIFF LEAKING			\$462.00
02/08/2023	984,665 kms	PANEL LOOSE R-16476			\$257.00
17/07/2023	975,737 kms	B - 20K/180Days S-8829 (B) SERVICE CARRIED OUT BY MICK KMS 975737 NO ISSUES RAISED,			\$641.96
13/07/2023		GENERAL REPAIRS R-15882			\$1,235.70
09/06/2023	971,975 kms	HEAD LIGHT R-14945 HEATER NOT WORKING			\$11.73
02/06/2023	956,064 kms	AIR BAG R-16688 ISSUE FIXED BY GTR 2/6/23	GLEN ARTNEY TRUCK REPAIRS PTY LTD - 16		\$1,625.80
29/05/2023	964,200 kms	FUEL LEAK R-13454 SERVICE CARRIED OUT ON 29/5/23 NO ISSUE RAISED IN REGARDS TO THIS	GLEN ARTNEY TRUCK REPAIRS PTY LTD - 10		\$0.00
29/05/2023	964,022 kms	A - 10K S-8107 STARTED 15/5 MICK KMS 956034 AIR BAG LEAK, LHSR & RHSF G/BOX OIL LEAK AIR BAGS RIDE TO HIGH NOT RESETTNG EXCESSIVE MOVEMENT IN KING PIN DID'NT FINISH - HAD WHEEL ALIGNMENT AT JT FOSSEY FINISHED ON 29/5/23 WITH EDWIN AND JUSTICE KMS 964022			\$0.00
15/05/2023		DAMAGED MUDGUARD R-14283			\$945.78
15/05/2023	956,037 kms	WHEEL ALIGNMENT R-14063 STEER AXLE BOTH ENDS OF DRAGLINK HAVE MOVEMENT BOTH TIE ROD ENDS HAVE MOVMENT	BIG WHEELS (** DO NOT USE) TRUCK ALIGNMENT - 10	14213821	\$1,400.00
12/05/2023		TANK STRAP R-15996			\$90.09
24/04/2023	946,282 kms	A - 10K S-7709 (A) SERVICE CARRIED OUT BY MICK ANNUAL INSPECTION - DONE CAB BUMP STOPS R 11862 - DONE			\$462.00
24/04/2023	946,282 kms	TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS I-818 ANNUAL INSPECTION CARRIED OUT BY MICK KMS 946282			\$0.00
24/04/2023	946,282 kms	BUMP STOPS R-11862			\$23.20
18/04/2023	946,259 kms	MANIFOLD LEAKING R-19589			\$154.00
31/03/2023		FUEL STRAP R-12798			\$136.48
24/03/2023	932,379 kms	E S-8315 SERVICE CARRIED OUT BY GTR	GLEN ARTNEY TRUCK REPAIRS PTY LTD - 10		\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
23/03/2023	934,094 kms	A - 10K S-7264 (A) SERVICE CARRIED OUT BY MICK KMS 934094 COOLANT PIPE MOUNT FOR RETARDER REPLACED X2			\$40.39
22/03/2023	922,326 kms	FUEL TANK STRAP R-12447			\$0.00
01/03/2023	922,209 kms	COOLANT LEAK, KING PINS R-10830 24/3 GTR CHECKED OVER AT SERVICE - KING PINS OK NEED TO BOOK IN FOR COOLANT ISSUE - ISSUE NOT RAISED AT SERVICE 01/03/23. NO LONGER AN ISSUE			\$0.00
01/03/2023	920,482 kms	A - 10K S-6947 (A) SERVICE CARRIED OUT BY MICK KMS 920482			\$0.00
22/02/2023	916,800 kms	ALTERNATOR R-11512			\$0.00
17/02/2023	914,195 kms	HEAD LIGHT R-11431			\$0.00
30/01/2023	9,023,025 kms	NEW TYRE T-3309 FITTED NEW DRIVE TYRES X8 PAT AND SHANE KMS 902025			\$0.00
30/01/2023	902,025 kms	A - 10K S-6374 (A) SERVICE CARRIED OUT PAT AND MICK KMS 902025 LHS INNER FOG LIGHT - FIXED MICK .5HRS LHS BULL BAR BLINKER - FIXED MICK .5HRS TIGHTEN MUFFLER BOX MOUNT BOLTS - FIXED PAT AND SHANE TENSION STEER UBOLT LHSR - FIXED MICK .25HRS			\$0.00
30/12/2022	880,301 kms	HEADLIGHT R-10142 REPLACED BULBS, ALL TESTED OK			\$0.00
21/12/2022	874,712 kms	HEADLIGHT, INDICATORS R-9917 FIXED REPLACED ALL OK MICK			\$0.00
16/12/2022	869,850 kms	A - 10K S-5742 (A) SERVICE CARRIED OUT MICK KMS 869850 REMOVED AND REPAIRED EXHAUST PIPE BELL TO MUFFLER			\$0.00
15/12/2022	869,985 kms	EXHAUST PIPE R-9678 REMOVED AND REPAIRED EXHAUST PIPE BELL TO MUFFLER			\$0.00
07/12/2022	864,281 kms	SUZI COIL R-9448 TESTED OK			\$0.00
02/12/2022	861,265 kms	SUZI COIL R-9260			\$0.00
22/11/2022	854,335 kms	A - 10K S-5387 (A)SERVICE CARRIED OUT, MICK, KMS 854335			\$0.00
14/11/2022	853,000 kms	DRAGLINK R-9427 ORDERED DRAGLINK 9/11/22 DAN PICKED UP 14/11/22			\$0.00
08/11/2022	842,908 kms	A - 10K S-5373 (A) SERVICE CARRIED OUT, MICK, KMS 842908 * FRONT DRAG LINK WORN * FIT NEW BULL BAR PARK LIGHT * PARK LIGHT			\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
01/11/2022	838,000 kms	BATTERY R-9419			\$0.00
07/10/2022	828,817 kms	ENGINE, fridge fault, WIPER BLADES R-8825 CHECKED FRIDGE REPLACED FAULTY FUSE COULDNT SOURCE WIPER BLADES TEST DROVE, CHECKED OVER, COULDNT FIND ANY FAULTS DID REPLACE LIGHT BULB INSIDE FRIDGE.			\$0.00
06/10/2022		HEADLIGHTS R-7261 TEST LIGHTS "REPLACE LEFT HAND SIDE HEADLIGHT BULB" FOUND RIGHT HAND SIDE HEADLIGHT LENS BROKEN - REPLACE RIGHT HAND SIDE HEAD LIGHT LENS & BULB "TEST OK" 16.09.22			\$0.00
28/09/2022	673,354 kms	STEER TYRES T-474 REMOVE AND FIT TWO NEW STEER TYRES BALANCE TENSION WHEEL NUTS TO SPEC.			\$0.00
26/09/2022	889,914 kms	A - 10K S-3509 CARRY OUT (A) SERVICE. DONE 12/7/2022.			\$0.00
23/09/2022	777,376 kms	A - 10K S-3452 CARRY OUT (A) SERVICE . DONE 22/6/2022.			\$0.00
22/09/2022	763,850 kms	COOLANT LEAK R-4828 REPLACE RADIATOR CAP SEAL.			\$0.00
22/09/2022		INDICATOR R-6448 BAD CONNECTION.			\$0.00
22/09/2022	813,656 kms	BROKEN MIRROR R-7254 REPLACED 2 RIGHT HAND REAR VISION MIRRORS WITH SECOND HAND ONES 08/09/22			\$0.00
22/09/2022	780,759 kms	GENERAL REPAIRS R-5804 REPLACE CAP STRAINER.			\$0.00
22/09/2022	785,847 kms	HEADLIGHT BULB OUT R-5813 REPLACE HEADLIGHT.			\$0.00
16/09/2022	818,714 kms	HEADLIGHT BULB, HEADLIGHT LENS R-7652 ALL LIGHTS WORKING			\$0.00
10/09/2022	950,623 kms	A - 10K S-5468 (A) SERVICE CARRIED OUT PAT KMS 815335 NOTE: KING PIN WORN L/H STEER, RETORDER LEVEL LOW, GEAR BOX LEVEL HIGH, EXHAUST ASSEMBLY LOOSE			\$0.00
03/09/2022	810,666 kms	NEW TYRES, STEER TYRES T-2341 FITTED 2 NEW STEER TYRES			\$0.00
11/08/2022	801,873 kms	BROKEN TAIL LIGHT R-9118			\$106.25
09/08/2022	801,851 kms	A - 10K S-4259 'A' SERVICE DONE 09.08.22 RHS STEER GUARD PANEL LOOSE 2-3mm MOVEMENT LHS PIN FIT COOLANT PIPE MOUNTTO RETARDER			\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
09/08/2022	801,851 kms	CAB AIR BAGS R-9117 ISSUE FIXED			\$0.00
13/06/2022	950,623 kms	A - 10K S-2857 CARRY OUT (A) SERVICE. ALL CHECKED OK AT TIME OF INSPECTION			\$0.00
13/06/2022	762,954 kms	A - 10K S-2854 CARRY OUT (A) SERVICE. DONE 23/5/2022.			\$0.00
06/06/2022	740,386 kms	A - 10K S-2423 CARRY OUT (A) SERVICE.			\$0.00
22/04/2022	753,159 kms	TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS I-260			
06/04/2022	709,279 kms	HEADLIGHTS R-2448 REPLACE HEAD LIGHT GLOBE.			\$0.00
06/04/2022	703,128 kms	IGNITION KEY R-1995 Check over key and key barrel, tested operation of key, everything was OK at time of inspection			\$0.00
29/03/2022	869,092 kms	A - 10K/90Days S-1610 CARRY OUT (A) SERVICE ALL CHECKED OK AT TIME OF INSPECTION			\$0.00
16/03/2022	729,886 kms	A - 10K/90Days S-1941 CARRY OUT (A) SERVICE.			\$0.00
15/03/2022	693,624 kms	A - 10K/90Days S-1324 Carry out A service Everything was OK at time of inspection			\$0.00
09/12/2021	62,501 kms	A - 10K/90Days S-1103 CARRY OUT (A) SERVICE. Scania maintenance, coolant pipe to retarder needs mounts. Through shaft seal leaking Rest CHECKED OK AT TIME OF INSPECTION			\$0.00
17/11/2021	656,106 kms	New T-290 REPLACE ALL 8 DRIVE TYRES WORN.			\$0.00
15/11/2021	629,234 kms	A - 10K/90Days S-63 COMPLETE A+ SERVICE Repair to RHS Steer 1/4 Guard			
10/11/2021	667,535 kms	A - 10K/90Days S-769 Bar the notes above all CHECKED OK AT TIME OF INSPECTION			
18/10/2021		RUNOUT T-274 Remove RHS Rear Outer Tyre & Replace with Runout Tension All Wheel Nuts & Fit Nut Indicators			\$0.00
08/10/2021	650,185 kms	WINDSCREEN WIPERS R-309 FIT NEW WIPERS			
18/08/2021	626,978 kms	RUNOUT T-124 Removed & Checked, Tyre had side wall damage. Fitted Runout to match.			

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
------	---------	-----------------------	----------	---------	------

205 Records

Total: \$118,608.59